



**TIP TEMPATURE MONITOR
CALIBRATION INSTRUCTIONS
PACE PART NUMBER 8001-0087-P1
MANUAL NUMBER 5050-0557**

1) Tools:


Temperature Calibrator (i.e. Fluke 724, Omega CL351-2A, or Victor VC14)
screwdriver, 9volts battery, Sensor (PACE P/N 1285-0046-P1), multi-functional
meter, DC power,

2) Calibration preparation:

- a) Connect Tip Temp. Monitor with the 9v battery and the sensor. (There is a sensor shipped together with the monitor.) Turn the “C and F switch” on PCB to the “C” position. Then switch the Tip Temperature Monitor on and leave it there for half an hour.

3) Calibration Steps:

- i. Set Temperature Calibrator output at 0°C. Adjust P3 potentiometer until the monitor display shows ambient temperature plus 1°C.
- ii. Turn the “C and F switch” on PCB to “F” position. Adjust P4 potentiometer until the monitor display shows $(1^{\circ}\text{C} + \text{ambient temperature}) \times 1.8 + 32$.
- iii. Set Temperature Calibrator output at 450 Celsius. Adjust P1 potentiometer until the monitor display shows $(450^{\circ}\text{C} + \text{ambient temperature}) \times 1.8 + 32$. ($\pm 6^{\circ}\text{F}$ tolerance)
- iv. Turn the “C and F switch” at PCB board bottom to the “C” position. Adjust P2 potentiometer until the monitor display shows $450^{\circ}\text{C} + \text{ambient}$ ($\pm 3^{\circ}\text{C}$ tolerance).
- v. Repeat above 4 steps until they all reach the requirements
- vi. Turn the monitor power switch to “Check” position. And turn the “C and F “switch on the PCB to “C” position. Adjust P5 potentiometer until the monitor display shows 450°C . Then again turn the “C and F” switch to “F” position. The monitor display should show $810^{\circ}\text{F} \sim 811^{\circ}\text{F}$. If it is not so, slightly adjust the P5 potentiometer so as to make the display shows the above figure. If still it is not reading within the $810^{\circ}\text{F} \sim 811^{\circ}\text{F}$ range, slightly adjust P1 potentiometer so as to make the display shows the above figure.
Please keep it in mind that step i., ii., iii., iv. should be within the range.



C and F exchange rate

°C	°F	°C	°F
1°C	33.8°F	2°C	35.6°F
3°C	37.4°F	4°C	39.2°F
5°C	41°F	6°C	42.8°F
7°C	44.6°F	8°C	46.4°F
9°C	48.2°F	10°C	50°F
11°C	51.8°F	12°C	53.6°F
13°C	55.4°F	14°C	57.2°F
15°C	59°F	16°C	60.8°F
17°C	62.6°F	18°C	64.4°F
19°C	66.2°F	20°C	68°F
21°C	69.8°F	22°C	71.6°F
23°C	73.4°F	24°C	75.2°F
25°C	77°F	26°C	78.8°F
27°C	80.6°F	28°C	82.4°F
29°C	84.2°F	30°C	86°F
31°C	87.8°F	32°C	89.6°F
33°C	91.4°F	34°C	93.2°F
35°C	95°F	36°C	96.8°F
37°C	98.6°F	38°C	100.4°F
39°C	102.2°F	40°C	104°F
41°C	105.8°F	42°C	107.6°F
43°C	109.4°F	44°C	111.2°F
45°C	113°F	50°C	122°F
100°C	212°F	200°C	392°F
300°C	572°F	400°C	752°F
450°C	842°F	500°C	932°F
600°C	1112°F	700°C	1292°F

Notes: In case, the engineer has no Temperature Calibrator at hand, he can use standard voltage as alternative. The data is as follows:

0	0 mV
100	4.095 mV
200	8.137 mV
300	12.207 mV
400	16.395 mV
450	18.513 mV
500	20.64 mV
600	24.902 mV



® PACE Incorporated

9030 Junction Drive
Annapolis Junction,
MD 20701

Tel: (301) 490-9860

PACE Europe Limited

13 Tanners Drive
Blakelands
Milton Keynes