

# Guardian 1000 Series Hipot Testers Instruction Manual

Form 150665/A3

©QuadTech, Inc., 2000  
5 Clock Tower Place, 210 East  
Maynard, Massachusetts, U.S.A. 01754  
October 2002

Telephone	978-461-2100
Sales	800-253-1230
Facsimile	978-461-4295
Website	<a href="http://www.quadtech.com">www.quadtech.com</a>

The material in this manual is for informational purposes only and is subject to change, without notice. QuadTech assumes no responsibility for any error or for consequential damages that may result from the misinterpretation of any procedures in this publication.

## WARNING

Potentially dangerous voltages may be present on front and rear panel terminals. Follow all warnings in this manual when operating or servicing this instrument. Dangerous levels of energy may be stored in capacitive devices tested by this unit. Always make sure the high voltage indicator is **not** on when connecting or disconnecting the device under test.



Product will be marked with this symbol (ISO#3864) when it is necessary for the user to refer to the instruction manual in order to prevent injury or equipment damage.



Product marked with this symbol (IEC417) indicates presence of direct current.



Product will be marked with this symbol (ISO#3864) when voltages in excess of 1000V are present.



---

# Contents

---

<b>Warranty</b>	<b>5</b>
<b>Specifications</b>	<b>7</b>
<b>Accessories</b>	<b>11</b>
<b>Safety Precautions</b>	<b>13</b>
<b>Condensed Operating Instructions</b>	<b>15</b>

## **Introduction - Section 1**

1.1	Unpacking and Inspection	21
1.2	Product Overview	21
1.3	Controls and Indicators	22
1.3.1	Front Panel Controls and Indicators	22
1.3.2	Rear Panel Controls and Connectors	23
1.4	Installation	24
1.4.1	Dimensions	24
1.4.2	Instrument Positioning	24
1.4.3	Power Requirements	24
1.4.4	Safety Inspection	25

## **Operation - Section 2**

2.1	Terms and Conventions	27
2.2	Start-Up	31
2.3	Programming Electrical Safety Tests	31
2.4	Programming a AC Hipot Test	35
2.5	Programming a DC Hipot Test	37
2.6	Programming an Insulation Resistance Test	39
2.7	Programming a Multi-Step Test	41
2.7.1	SMART Key	42
2.8	PRESET Test Parameters	43
2.8.1	PASS HOLD	44
2.8.2	STEP HOLD	44
2.8.3	JUDG. WAIT	44
2.8.4	AC-V FREQ	44
2.8.5	GR CONT.	44
2.8.6	SOFT. AGC	44
2.8.7	AUTO RANGE	44
2.8.8	GFI	45
2.8.9	FAIL CONT.	45
2.8.10	SCREEN	45
2.8.11	PART NO.	45
2.8.12	LOT NO.	45
2.8.13	SERIAL NO.	45
2.9	Storing a Test Setup	46
2.10	Instrument Offset	48
2.11	Connection To Device Under Test	50
2.12	Measurement Procedure	51
2.13	MENU Parameters	52
2.13.1	MEMORY Function	53
2.13.2	SYSTEM Function	53

---

## Contents (Continued)

---

2.13	MENU Parameters (Continued)	
2.13.3	OPTION Function .....	53
2.13.4	CALIBRATION Function .....	54
2.13.5	KEY LOCK Function .....	55
2.13.6	CHANGE PASSWORD Function .....	56
2.13.7	ERROR LOG Function .....	56
2.13.8	PRINT PROGRAM Function .....	57
2.13.9	ABOUT Function .....	57

### Interface - Section 3

3.1	Remote .....	59
3.2	RS232 Interface.....	62
3.2.1	Pin Configuration.....	62
3.2.2	RS232 Specifications .....	63
3.2.3	RS232 Commands .....	63
3.2.4	Sample QuickBASIC Program.....	64
3.3	IEEE-488 Interface.....	66
3.3.1	Pin Configuration.....	66
3.3.2	IEEE-488 Interface Codes and Messages .....	68
3.3.3	IEEE-488 Interface Commands .....	69
3.3.3.1	IEEE-488 Register Assignments .....	69
3.3.3.2	IEEE-488 Register Configurations .....	70
3.3.4	IEEE-488 & SCPI Command Summary .....	72
3.3.5	Error Messages .....	82
3.3.6	Sample QuickBASIC Programs .....	83
3.4	Printer Interface .....	86
3.5	G16 International Power Strip.....	88
3.6	S07 Power Entry Adaptor Cable .....	89
3.7	S03 Corded Product Adaptor .....	90
3.8	S05 Foot Switch .....	91
3.9	S08 Gun Probe .....	92
3.10	S50 Ground Bond Tester .....	93

### Service & Calibration - Section 4

4.1	General .....	95
4.2	Instrument Return.....	95
4.3	Calibration.....	95
4.3.1	Calibration Parameters .....	96
4.3.2	Enable Calibration .....	97
4.3.3	AC Voltage Calibration.....	98
4.3.4	DC Voltage Calibration.....	99
4.3.5	IR Voltage Calibration .....	100
4.3.6	AC Current Calibration .....	101
4.3.7	Real AC Current Calibration .....	103
4.3.8	DC Current Calibration .....	105
4.3.9	ARC Calibration.....	107
4.3.10	IR Resistor Calibration .....	107
4.3.11	Finalize Calibration .....	109

---

## Warranty

---



QuadTech warrants that Products are free from defects in material and workmanship and, when properly used, will perform in accordance with QuadTech's applicable published specifications. If within one (1) year after original shipment it is found not to meet this standard, it will be repaired, or at the option of QuadTech, replaced at no charge when returned to a QuadTech service facility.

**Changes in the Product not approved by QuadTech shall void this warranty.**

**QuadTech shall not be liable for any indirect, special or consequential damages, even if notice has been given of the possibility of such damages.**

**This warranty is in lieu of all other warranties, expressed or implied, including, but not limited to any implied warranty or merchantability of fitness for a particular purpose.**

### **SERVICE POLICY**

QuadTech's service policy is to maintain product repair capability for a period of at least five (5) years after original shipment and to make this capability available at the then prevailing schedule of charges.



# Specifications

## Dielectric Strength

### G 1010, 1030, & 1030S

<b>AC Output Voltage:</b>	Range: 0.05 to 5kV AC, in 1V steps
	Regulation: $\pm$ (1% of setting +5V)
	Frequency: 50/60Hz selectable
<b>Voltage Display:</b>	Accuracy: $\pm$ (1% of reading +5V)
	Resolution: 1V steps
<b>AC Current Display:</b>	Total & Real current
	Range: 0.001mA to 30mA AC, in 1 $\mu$ A steps
	Accuracy: $\pm$ (1% of reading + 5 counts) (Total)
	Accuracy: $\pm$ (5% of reading + 20 counts) (Real)


### G 1030, & 1030S

<b>DC Output Voltage:</b>	Range: 0.05 to 6kV DC, in 1V steps
<b>Voltage Display:</b>	Accuracy: $\pm$ (1% of reading +5V)
	Resolution: 1V steps
<b>DC Current Display:</b>	Range: 0.0001mA to 10mA DC
	3 Ranges: 0.0001mA – 0.3mA; 0.31mA-3mA; 3.1mA-10mA
	Accuracy: $\pm$ (1% of reading + 5 counts)

## Insulation Resistance

### G 1030, & 1030S

<b>Insulation Resistance:</b>	Voltage: 50 - 1000V DC in 1V steps
	Accuracy: $\pm$ (1.5% of reading + 5V)
	Range: 0.1M $\Omega$ - 50G $\Omega$ (voltage dependent)
	Accuracy: 1M $\Omega$ - 1G $\Omega$ , $\pm$ (5% + 10counts) $\geq$ 500V
	1G $\Omega$ - 10G $\Omega$ , $\pm$ (10% + 10counts) $\geq$ 500V
	10G $\Omega$ - 50G $\Omega$ , $\pm$ (15% + 10counts) $\geq$ 500V
	0.1M $\Omega$ - 1G $\Omega$ , $\pm$ (10% + 10counts) $<$ 500V



**Guardian 1000 Series Resistance Range**

---

## Specifications (Continued)

---

### General Features

---

#### ARC Detection

**Detection Current:** Range: 1mA – 15mA AC and 10mA DC

**Pulse Width:** Minimum: 10 $\mu$ s

#### Ground Fault

**Interrupt (GFI):** Shutdown of current imbalance when  $I > 0.5\text{mA}$

**Time:** Test: 0.1sec – 999 sec, Continuous

Ramp: 0.1sec – 999 sec, OFF

**Limits:** HI/LO programmable during Test Time

LO can be set to OFF during Hipot Test

HI can be set to OFF during IR Test

**Indication:** Pass/fail LEDs, audible alarm

**Remote Control:** Inputs: START, STOP

Characteristics: 24V active low, Pulse width  $\cong 20\text{ms}$

Outputs: PASS, FAIL, UNDER TEST

Characteristics: Dry contact relay, Closed if true

120V, 100mA max

Connector: 9 pin male D-series & Terminal Strip

**Setup Storage:** 99 Memory Locations, 99 Steps, Total of 500 Memory Segments

#### Standard

**Interfaces:** RS232 Remote I/O

**Scanner:** 8 Channel HV Internal Scanner (1030S only)

#### Optional

**Interfaces:** IEEE-488 Printer

**Connectors:** Front and Rear Connection (1010 & 1030 instruments)

Front Connection (1030S instrument)

HV OUTPUT: Custom Banana Socket

RTN/LOW: Banana Socket

**Front Panel** 11 Digit Password with or without setup recall

**Lockout:** LED Display: LOCK



---

## Specifications (Continued)

---

### General Features

---

<b>Mechanical:</b>	Bench Mount Dimensions:(w x h x d): 12.80 x 4.20 x 16.00 inches 320 x 105 x 400 mm									
<b>Weight:</b>	30.5 lbs (14 kg) net, 36 lbs (16.5 kg) shipping (1010, 1030) 32.5 lbs (15 kg) net, 38 lbs (17.5 kg) shipping (1030S)									
<b>Environmental:</b>	Specifications: 18°C to 28°C, 70% RH Operating: 0°C to + 40°C, 70% RH Storage: -10°C to + 60°C, 70% RH Warm-up Time: 15 minutes									
<b>Power:</b>	<ul style="list-style-type: none"><li>• 90 - 130V AC</li><li>• 200 - 250V AC</li></ul>	<ul style="list-style-type: none"><li>• 50 or 60Hz</li><li>• 500W max</li></ul>								
<b>Supplied:</b>	<ul style="list-style-type: none"><li>• Instruction Manual</li><li>• Calibration Certificate</li></ul>	<ul style="list-style-type: none"><li>• Power Cable</li><li>• Test Leads</li></ul>								
<b>Ordering Information:</b>	<table><thead><tr><th><u>Description</u></th><th><u>Catalog No.</u></th></tr></thead><tbody><tr><td>AC Hipot Tester</td><td>Guardian 1010</td></tr><tr><td>AC/DC/IR Hipot Tester</td><td>Guardian 1030</td></tr><tr><td>AC/DC/IR/SC Hipot Tester</td><td>Guardian 1030S</td></tr></tbody></table>	<u>Description</u>	<u>Catalog No.</u>	AC Hipot Tester	Guardian 1010	AC/DC/IR Hipot Tester	Guardian 1030	AC/DC/IR/SC Hipot Tester	Guardian 1030S	
<u>Description</u>	<u>Catalog No.</u>									
AC Hipot Tester	Guardian 1010									
AC/DC/IR Hipot Tester	Guardian 1030									
AC/DC/IR/SC Hipot Tester	Guardian 1030S									



---

## Accessories

---

### Accessories Included

Item	Quantity	QuadTech P/N
AC Power Cord	1	4200-0300
Power Line Fuse 5A 250V SB	1	520108
Power Line Fuse 2.5A 250V SB	1	520134
High Voltage Lead Set, 1m with alligator clips	1	S02
Ground Continuity Lead	1	700100
HV Lead Set (8), unterminated 1030S only	1	G40
Instruction Manual	1	150665
Calibration Certificate	1	N/A

### Accessories/Options Available

Item	Quantity	QuadTech P/N
High Voltage Lead Set, high & low, 1m (std. with unit)	1	S02
Corded Product Adaptor, 115V	1	S03
High Voltage Lead Set, high & low, 2m	1	S04
Foot Switch	1	S05
High Voltage Probe	1	S06
Power Entry Adaptor Cable	1	S07
Gun Probe	1	S08
High Voltage Lead, 1m, unterminated	1	S09
High Voltage Lead, 2m, unterminated	1	S10
Gun Probe with Remote Start	1	S11
Load Box, resistive	1	S12
Load Box, custom resistors	1	S14
Interconnection Cable to Sentry 50 Ground Bond Tester	1	S15
Ground Continuity Lead (standard with unit)	1	700100
International Power Strip	1	G16
Corded Product Adaptor, 240V	1	G25
Printer Interface (replaces IEEE-488)	1	G38
IEEE-488 ('GPIB') Interface	1	G39
HV Lead Set (8), unterminated	1	G40



---

## Safety Precautions

---

### WARNING

The Guardian 1000 Series Hipot Tester can provide an output voltage as high as 6000V DC (5000V AC) to the external device under test (DUT). Although the Guardian unit is designed with full attention to operator safety, serious hazards could occur if the instrument is used improperly and these safety instructions are not followed.

1. The Guardian 1000 unit is designed to be operated with its chassis connected to earth ground. The instrument is shipped with a three-prong power cord to provide this connection to ground. This power cord should only be plugged in to a receptacle that provides earth ground. Serious injury can result if the Guardian 1000 is not connected to earth ground.
2. Tightly connect cable(s) to the (blue) **RTN/LOW** terminal. If this is not done, the DUT's casing can be charged to the high voltage test level and serious injury or electrical shock hazards could result if the DUT is touched.
3. Never touch the metal of the High Voltage probe directly. Touch only the insulated parts of the lead(s).
4. Never touch the test leads, test fixture or DUT in any manner (this includes insulation on all wires and clips) when the high voltage is applied and the red **DANGER** light is **ON**.
5. Before turning on the Guardian unit, make sure there is no device (DUT) or fixture connected to the test leads.
6. After each test, press the **[STOP]** (red) button for safety if there is any concern that HV may still be applied to the output terminals.
7. When the red **DANGER** LED is lit or flashing, NEVER touch the device under test, the lead wires or the output terminals.
8. Before touching the test lead wires or output terminals make sure:
  - a) The red **[STOP]** button has been pressed
  - b) The red **DANGER** LED is **OFF**.
9. **In the case of an emergency**, turn **OFF** the **POWER** switch using a "hot stick" and disconnect the AC power cord from the wall. **DO NOT TOUCH THE Guardian 1000 INSTRUMENT.**
10. If the **DANGER** LED does not go **off** when the **[STOP]** button is pressed, immediately stop using the tester. It is possible that the output voltage is still being delivered regardless of the **TEST ON/OFF** control signal.
11. When the Guardian 1000 instrument is used in remote control mode, be extremely careful. The High Voltage Output is being turned on and off with an external signal.



---

# Condensed Operating Instructions

---

## **WARNING**

High Voltage is applied to the white HV Output Terminal anytime the red **DANGER** LED is **ON** or flashing. Always make sure the **DANGER** LED is **OFF** when connecting or disconnecting the device under test (DUT).

## **General Information**

The Guardian 1000 Series Hipot Tester is a measuring instrument for direct readout of hipot output voltage and leakage current and insulation resistance. The voltage applied to the device under test is adjustable from 50V – 5kV AC and 50V to 6kV DC. The trip current limit is programmable from 1uA to 30mA AC in 1uA steps and from 0.1uA to 10mA DC in 0.1uA steps. The output voltage for Insulation Resistance tests is 50V to 1000V DC over a measurement range of 100k $\Omega$  to 50G $\Omega$ .

## **Start-Up**

The Guardian 1000 Series unit can be operated from a power source between 90 and 250VAC at a power line frequency of 50 or 60Hz. The standard Guardian 1000 Series unit is shipped from QuadTech with a 5A fuse in place for AC 90-130V operation. (A 2.5A fuse is included for 200-250V operation). The G1000 unit is shipped with the line voltage selector set for 120V. Refer to paragraph 1.4.3 for instructions on changing the fuse or line voltage selector.

Connect the Guardian 1000 Series unit AC power cord to the source of proper voltage. Operate the G1000 Series instrument with its chassis connected to earth ground. The Guardian 1000 instrument is shipped with a three-prong power cord to provide this connection to ground. This power cord should only be plugged into a receptacle that provides earth ground. Serious injury may result if the G1000 Series instrument is not connected to earth ground.

Press the [POWER] button on the front panel to apply power. To switch the power off, press the [POWER] button again or if measurements are to be made proceed with the Test Parameter Setup in Table COI-1. The G1000 Series instrument should warm up for 15 minutes prior to use.

## **NOTE**

**Please read this instruction manual in its entirety before operating this instrument. These condensed operating instructions are not a substitute for all the information provided in the remainder of this manual.**


## **NOTE**

**Refer to paragraphs 2.3 through 2.5 for a full description of programming test parameters and instruction on how to store the test setup. Test parameters must be set before the G1000 Series instrument can be zeroed.**

# Condensed Operating Instructions (Continued)

There are numerous menus within the Guardian 1000 Series instruments. Familiarize yourself with these menus prior to programming a test. Figure COI-1 illustrates the STAND BY display and lists the functions that can be accessed by pressing the [F1] through [F4] keys.

## "STAND BY" or "Power-Up" Display



F1	F2	F3	F4
<b>PROGRAM</b>	<b>PRESET</b>	<b>MENU</b>	<b>MORE</b>
Insert Delete Program STEP: 1-99 MODE: AC/DC/IR Voltage High Limit Test Time Low Limit ARC Limit Ramp Time REAL Limit Box # Channel Setting	Pass Hold Step Hold Judg. Wait AC-V Freq. GR Cont. Soft AGC. Auto Range GFI Fail Cont Screen Part No. Lot No. Serial No.	<b>Memory</b> Store Recall Delete <b>System</b> Contrast Beeper Volume <b>Option</b> RS232 Baud Rate Parity Flow Control IEEE-488 GPIB Address <b>PRINTER</b> A. Auto Print Pass Fail B. Print Data Part No. Lot No. Serial No. Test Data Result <b>Calibration</b> (Need password to enter) <b>Key Lock</b> (Need password to enter) <b>Change Password</b> (Need password to enter) <b>Error Log</b> <b>About</b> Manufacturer Software version	View Test Steps (Tabular Format) Offset

**Figure COI-1: G1000 Series Menus**

**NOTE:**  
 The function of UP/DOWN depends on the menu. When [F3] = ENTER, the UP/DOWN operation changes the highlighted value and the ENTER operation scrolls through the menu selections. When [F3] = SELECT, the UP/DOWN operation scrolls through the menu selections and the SELECT operation chooses (enters into) the highlighted parameter.



# Condensed Operating Instructions (Continued)

With the Guardian 1000 Series instrument in “STAND BY” (or power-up display) status, follow the steps in Table COI-1 to program an AC, DC and/or IR test.

"STAND BY"  
or  
"Power-Up"  
Display

STEP 1/1	AC	LOW : OFF	PROGRAM	
		ARC : OFF	PRESET	
1.250kV		RAMP: OFF	MENU	
15.00mA		REAL: OFF	MORE..	
3.0s		SCAN : 1 2 3 4 5 6 7 8		
		x x x x x x x x		
STAND BY	RMT	LOCK	OFST	ERR

F1 To enter programming mode.

F2 To view/change preset (initial) test parameters.

F3 To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.

F4 To view the programmed test setups and access offset function.

"PROGRAM"  
Display

STEP 1	AC	LOW : OFF	UP	
		ARC : OFF	MORE..	
VOLT: 0.000kV		RAMP: OFF	ENTER	
HIGH: 0.500mA		REAL: OFF	MORE..	
TIME: 3.0s		SCAN : 1 2 3 4 5 6 7 8		
		x x x x x x x x		
PROCESS STEP	RMT	LOCK	OFST	ERR

F1 To change value in highlighted box.

F2 To delete or insert a test step.

F3 To move highlighted box around display to select parameter to change

F4 To exit programming mode.

**Figure COI-2: “STAND BY” and PROGRAM Displays**

**Table COI-1: Test Parameter Setup**

Step	Test Parameter	AC Hipot	DC Hipot	IR	Range
1	To enter programming mode	[F1] = PROGRAM	[F1] = PROGRAM	[F1] = PROGRAM	
2	Select Test Step	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	1-99
3	Select Test Mode	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	AC, DC or IR
4	Select Test Voltage	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	0.05-5kV AC 0.05-6kV DC 0.05-1kV IR
5	Set High Limit * Set Low Limit (IR)	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	0.001-30mA AC 0.0001-10mA DC 0.1-50000MΩ IR
6	Set Test Time	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	0, 0.1-999s AC 0, 0.1-999s DC 0, 0.1-999s IR
7	Set Low Limit * Set High Limit (IR)	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	0-30mA AC 0-10mA DC 0-50GΩ IR
8	Set ARC Limit	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER		1-15mA AC 1-10mA DC
9	Set RAMP Time	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	[F1] = UP [F3] = ENTER	0-999s AC 0-999s DC 0-999s IR
10	Set REAL Current	[F1] = UP [F3] = ENTER			0-30mA AC
11	Set SCAN Channels (H or L)	[F1] = MOVE [F2] = CHANGE	[F1] = MOVE [F2] = CHANGE	[F1] = MOVE [F2] = CHANGE	Channels 1-8 H, L or X=Off
12a	To program <b>next</b> test step <b>OR</b>	[F3] = ENTER <b>OR</b>	[F3] = ENTER <b>OR</b>	[F3] = ENTER <b>OR</b>	Program next step <b>OR</b>
12b	To <b>exit</b> programming mode	[F4] = EXIT	[F4] = EXIT	[F4] = EXIT	Exit programming

\* Unit will make low limit decision at the end of test.

\* High Limit Decision is made at start of test time unless judgment wait is set.

---

## Condensed Operating Instructions (Continued)

---

### Offset


After setting your test parameters, zero the Guardian 1000 Series instrument by using the automatic offset. With no device connected, connect the appropriate cable (or other fixture) into the front panel OUTPUT connectors. Refer to paragraph 2.9 cable connections based on test to be performed. Test leads for AC hipot and DC hipot should be OPEN.

Prior to performing the OFFSET function:

- Allow the instrument to warm up for 15 minutes.
- Connect the Test cables (or fixture) to the front panel OUTPUT and RTN/LOW connectors.
- Program the test steps.

With the instrument in STAND BY status:

- Press [F4] = MORE
- Press [F3] = OFFSET
- Follow instructions on display: i.e.: connect OPEN across OUTPUT terminal.
- Press green [START] button.
- Wait while instrument gets OFFSET value.
- The **OFST** block at the bottom of the display is now highlighted (back lit).
- Press [F4] = MORE to return to STAND BY status.




**Figure COI-3: Zero/Offset OPEN Configuration**

# Condensed Operating Instructions (Continued)

## Connection to Device under Test (DUT)

Figure COI-4 illustrates the connection of the Guardian 1000 Series unit to a single DUT using the S02 1-meter HV cable set that comes standard with the instrument. The custom white banana plug/red alligator clip is connected between the OUTPUT terminal on the G1000 Series unit and the high side of the device under test. The black banana plug/alligator clip is connected between the RTN/LOW terminal on the G1000 Series unit to the low side of the DUT.



COI-4: Connection to Device under Test

## Measurement Mode

1. Turn [POWER] ON.
2. Allow G1000 Series instrument a 15-minute warm up time.
3. Connect S02 Black ground cable to G1000 Series unit RTN/LOW terminal
4. Connect S02 White/red HV cable to G1000 Series unit OUTPUT terminal.
5. Press [F1] = PROGRAM and enter test parameters. When finished programming, press [F4] = EXIT to return to STAND BY status.
6. Press [F4] = MORE to access Offset function. Press [F3] = OFFSET. Follow Offset instructions. When Offset is complete, press [F4] = MORE to return to STAND BY.
7. Connect device under test (DUT) to test leads.
8. Press [START].
9. Record measurement.
10. Press [STOP].



---

## Section 1: Introduction

---

### 1.1 Unpacking and Inspection

Inspect the shipping carton before opening. If damaged, contact the carrier agent immediately. Inspect the Guardian 1000 Series instrument for any damage. If the instrument appears damaged or fails to meet specifications notify QuadTech (refer to instruction manual front cover) or its local representative. Retain the original shipping carton and packing material for future use such as returning the instrument for recalibration or service.

### 1.2 Product Overview

The Guardian 1000 Series is available in three models, the 1010, 1030 and 1030S, all of which provide AC Hipot testing capability. Additionally, the Guardian 1030 & 1030S provide DC Hipot testing and Insulation Resistance testing. The hipot test can be programmed over a voltage range of 0.05 to 5kV AC and 0.05 to 6kV DC with a min/max leakage current detection range of 0.001 to 30mA AC and 0.0001 to 10mA DC. Insulation resistance measurements are possible to 50G $\Omega$  at programmable DC test voltages between 50 and 1000V. Each instrument comes standard with ground continuity check, internal storage of 99 test setups, remote interface with start/stop inputs & pass/fail outputs and an RS232 interface. An optional IEEE-488 Interface or Printer Interface is available for all three instruments. The Guardian 1030S instrument is equipped with a scan interface and 8 HV front panel connectors for multi-point testing.




**Figure 1-1: Guardian 1030S AC/DC/IR/SC Hipot Tester**

### 1.3 Controls and Indicators

#### 1.3.1 Front Panel Controls and Indicators

Figure 1-2 illustrates the controls and indicators on the front panel of the Guardian 1000 Series AC/DC/IR Hipot Tester. Table 1-1 identifies them with description and function.




**Figure 1-2: Guardian 1030S Front Panel Controls & Indicators**

**Table 1-1: Guardian 1000 Series Front Panel Controls & Indicators**

Reference Number Figure 1-2	Name	Type	Function
1	Power	Green Push Button	Apply AC Power: 1=ON, 0=OFF
2	START	Green Push Button	Initiate Test: HV applied to OUTPUT terminal
3	STOP	Red Push Button	Stop Test: HV terminated at OUTPUT terminal
4	Display	LCD	Program Menu, Test Setup, Measurement Results, Memory Contents, Calibration
5	F1, F2, F3 and F4	Gray Push Buttons	Select Instrument Functions Keys perform different functions under different menus. Right side of display shows corresponding key function.
6	CAL	Recessed P-B	Enable/Disable Instrument Calibration
7	UPDATE	Recessed P-B	Qualified Service Personnel Only
8	PASS	Green LED	When lit, DUT judged as PASS
8	FAIL	Red LED	When lit, DUT judged as FAIL. Output voltage is immediately cut off. Press [STOP] to disable FAIL LED
9	DANGER	Red LED	When lit, high voltage is present at OUTPUT terminals
10	OUTPUT	White Custom Banana Socket	High Voltage (Potential) Terminal
11	RTN/LOW	Blue Banana Socket	RTN: Low voltage reference terminal LOW: Common ground reference terminal
12	CH1-8	8 White Custom Banana Sockets	High Voltage Scan Channels (1030S Only)

### 1.3.2 Rear Panel Controls and Connectors

Figure 1-3 illustrates the controls and connectors on the rear panel of the Guardian 1000 Series AC/DC/IR Hipot Tester. Table 1-2 identifies them with description and function.



**Figure 1-3: Rear Panel Guardian 1000 Series Instrument**

**Table 1-2: Guardian 1000 Series Rear Panel Controls & Connectors**


Reference # Figure 1-3	Name	Type	Function
1	Fan	SF11580AT 115V 50/60Hz 0.10A	Cool Unit: T $\geq$ 50°C = ON, T $<$ 45°C = OFF
2	Remote	Black 11-screw Terminal Strip	Remote Connection: Inputs: Start, Stop, Interlock Outputs: Pass, Fail, Under Test
3	Output	Black 2-position Slide Switch	For 24V Output or Relay contact
4	Remote	Silver 9-pin D-Type Connector	Remote Connection: Inputs: Start, Reset, Interlock Outputs: Pass, Fail, Under Test
5	CONT CHK OPT.	Black banana plug	Connection for Ground Continuity Check
6	GPIB/PRINTER	Blue 24-pin	Optional IEEE-488 Interface or Printer connector
7	N/A	N/A	For unspecified use
8	RS232	Silver 9-pin, D-Type	RS232 Interface connector
9	AC Line Input	Black 3-wire inlet module & fuse holder	Connection to AC power source Fuse Drawer: 6.3A 250V or 3.15A 250V (see #11)
10	1ΩCAL	Black hole	Calibration for Continuity, Qualified Personnel Only
11	VOLTAGE SELECTOR	2 Red 2-position Slide Switches	Select Voltage Level corresponding to AC Source 90V – 110V: 5A 250V Slow Blow 110V – 130V: 5A 250V Slow Blow 200V – 240V: 2.5A 250V Slow Blow 220V – 250V: 2.5A 250V Slow Blow
12 *	RTN/LOW	Blue Banana Socket	RTN: Low voltage reference terminal LOW: Common ground reference terminal
13 *	HV OUTPUT	White Custom Banana Socket	Optional rear panel High Voltage (Potential) Terminal

\* NOTE: The rear panel HV OUTPUT and RTN/LOW terminals are standard on the 1010 and 1030 units. They are NOT on the 1030S unit.

## 1.4 Installation

### 1.4.1 Dimensions

The Guardian 1000 series unit is supplied in a bench configuration, i.e., in a cabinet with resilient feet for placement on a table. Flip feet are provided under the front feet so that the Guardian instrument can be tilted up for convenient operator viewing.



**Figure 1-4: Guardian 1000 Series Instrument Dimensions**

### 1.4.2 Instrument Positioning

The Guardian unit contains one (1) graphic display for direct readout of measured parameters. The optimum angle for viewing is slightly down and about 10 degrees either side of center. For bench operation the front flip feet should always be used to angle the instrument up. In bench or rack mount applications the instrument should be positioned with consideration for ample air flow around the rear panel fan ventilation hole. An open space of at least 3 inches (75mm) is recommended behind the rear panel. Testing should be performed on a non-conductive surface. An ESD mat is not a recommended test platform.

### 1.4.3 Power Requirements

The Guardian can be operated from a power source of 90 to 132V AC or 198 to 250V AC. Power connection is via the rear panel through a standard receptacle. Before connecting the 3-wire power cord between the unit and AC power source, make sure the voltage selection switches on the rear panel (Figure 1-5) are in accordance with the power source being used. For a 90-132V source, use a 5A 250V fuse. For a 198-250V source, use a 2.5A 250V fuse. Always use an outlet that has a properly connected protection ground.




**WARNING**  
**MAKE SURE THE UNIT HAS BEEN DISCONNECTED FROM ITS AC POWER SOURCE FOR AT LEAST FIVE MINUTES BEFORE PROCEEDING.**

### Procedure For Changing A Guardian 1000 Series Fuse

**Remove the fuse drawer, by inserting a flat head screwdriver behind the small tab located just below the 3-prong receptacle, and force outward.**

Once the fuse drawer has been removed from the instrument snap the fuse from the holder and replace. Make sure the new fuse is of the proper rating. Note that the fuse drawer can also be used to store a spare fuse.

Install the fuse drawer back in the inlet module (fuse down) by pushing in until it locks securely in place.



**Figure 1-5: Close-Up of G1000 Series Rear Panel**

#### 1.4.4 Safety Inspection

Before operating the instrument inspect the power inlet module on the rear of the Guardian to ensure that the properly rated fuse is in place, otherwise damage to the unit is possible. Make sure that the voltage selector switches are set in accordance with the power source in use. Refer to paragraph 1.4.3 and Figure 1-5.

The Guardian instrument is shipped with a standard U.S. power cord, QuadTech P/N 4200-0300 (with Belden SPH-386 socket or equivalent, and a 3-wire plug conforming to IEC 320). Make sure the instrument is only used with these cables (or other approved international cord set) to ensure that the instrument is provided with connection to protective earth ground.

The surrounding environment should be free from excessive dust to prevent contamination of electronic circuits. The surrounding environment should also be free from excessive vibration. Do not expose the Guardian instrument to direct sunlight, extreme temperature or humidity variations, or corrosive chemicals.



---

## Section 2: Operation

---

### 2.1 Terms and Conventions

**Table 2-1: Measurement Unit Prefixes**

<u>Multiple</u>	<u>Scientific</u>	<u>Engineering</u>	<u>Symbol</u>
1000000000000000	10 <sup>15</sup>	Peta	P
1000000000000	10 <sup>12</sup>	Tera	T
1000000000	10 <sup>9</sup>	Giga	G
1000000	10 <sup>6</sup>	Mega	M
1000	10 <sup>3</sup>	Kilo	k
.001	10 <sup>-3</sup>	milli	m
.000001	10 <sup>-6</sup>	micro	u
.000000001	10 <sup>-9</sup>	nano	n
.000000000001	10 <sup>-12</sup>	pico	p
.000000000000001	10 <sup>-15</sup>	femto	f

**ARcing:** Sparking or ‘flashing over’ caused by a breakdown of electrical insulation.

**Current:**

**AC:** Alternating Current. AC is an electrical current that has one polarity during part of the cycle and the opposing polarity during the other part of the cycle. Residential electricity is AC.

**DC:** Direct Current. Non-reversing polarity. The movement of charge is in one direction. Used to describe both current and voltage. Batteries supply direct current (DC).

**Charging Current:** An insulated product exhibits the basic characteristics of a capacitor. Application of a voltage across the insulation causes a current to flow as the capacitor charges. This current instantaneously rises to a high value as voltage is applied then exponentially decays to zero as the DUT becomes fully charged. Charging current decays to zero much faster than dielectric absorption.

Dielectric Absorption:	The physical phenomenon in which insulation appears to absorb and retain an electrical charge slowly over time. Apply a voltage to a capacitor for an extended period of time. Then quickly discharge it to zero voltage. Leave the capacitor open circuited for a period of time then connect a voltmeter to it and measure the residual voltage. The residual voltage is caused by the dielectric absorption of the capacitor.
Dielectric Strength:	The ratio between the voltage at which breakdown of the insulating material occurs and the distance between the two points subject to the applied voltage.
Dielectric Withstand Test:	This is the most common electrical safety test performed. A high voltage (either AC or DC) is applied to determine if a breakdown will occur in the insulation of the DUT. Dielectric Withstand is also referred to as a hipot (high potential) test.
Discharge:	The act of draining off an electrical charge to ground. Devices that retain charge should be discharged after an IR test or DC hipot test.
DUT:	Device Under Test. (i.e. the product being tested).
Frequency:	The rate at which current or voltage reverses polarity and then back again completing a full cycle, measured in Hertz (Hz) or cycles/second. AC Line Frequency = 50/60 Hz.
<b>Ground:</b>	
Ground:	The base reference from which voltages are measured, nominally the same potential as the earth. Ground is also the side of a circuit that is at the same potential as the base reference.
Ground Bond Test:	Test to verify that all conductive parts of a product that are exposed to user contact are connected to the power line ground. The ground bond test verifies the integrity of the ground connection using a high current AC signal with current level as high as 30Amps. Ground bond provides a better simulation of how a product will perform under an actual fault condition.
Ground Continuity:	Test to verify that all conductive parts of a product that are exposed to user contact are connected to the power line ground. GC Test normally performed with a low current DC signal that checks to ensure the ground connection has a resistance of $<1\Omega$ .

Insulation Resistance: Measures the total resistance between any two points separated by electrical insulation. The IR test determines how effective the dielectric (insulation) is in resisting the flow of electrical current.

**Interface:**

IEEE-488: General Purpose Interface Bus (GPIB). GPIB is an industry standard definition of a Parallel bus connection for the purpose of communicating data between devices.

RS232: An industry standard definition for a Serial line communication link or port.

Scanner: An electronic device designed to switch or matrix signals.

**Leakage Current (LC):**

Leakage Current: The residual flow of current that flows through the insulation after a high voltage has been applied for a period of time. The leakage current is equal to the applied voltage divided by the insulation resistance. Leakage current is the main measured value for AC hipot and DC hipot.

Applied Part LC Test: A line leakage current test that measures the current that would flow from, to or between applied parts such as sensor and patient leads. This test is the most complicated and time-consuming line leakage test.

Earth LC Test: The most important and most common of the line leakage tests. Earth leakage current is basically the current flowing back through the ground conductor on the power cord. It is measured by opening the ground conductor, inserting a circuit with the simulated impedance of the human body then measuring the voltage across part of the circuit with a true RMS voltmeter.

Enclosure LC Test: A line leakage test that measures the current that flows through the human body if the body had touched the enclosure of the DUT.

Line LC Test: A line voltage leakage current test simulates the effect of a person touching exposed metal parts of a product and detects whether or not the leakage current that flows through the person's body remains below a safe level. Apply power to the product being tested, then measure the leakage current from any exposed metal on the chassis of the product under a fault conditions such as "no ground". A special circuit is used to simulate the impedance of the human body.

**Limits:**

High Limit:

The high limit is the upper value for a test to be considered a pass. If the measured value is higher than the high limit the test is considered a fail. In hipot, leakage current and ground bond test modes a high limit is required.

Low Limit:

The low limit is the lower value for a test to be considered a pass. If the measured value is lower than the low limit the test is considered a fail. In insulation resistance test mode a low limit is required. In an AC or DC Hipot test, the low limit FAIL decision occurs at the end of the programmed test time.

Mode:

The test which is to be performed such as AC Hipot (WAC), DC Hipot (WDC), Insulation Resistance (IR), Ground Bond (GR) or Leakage Current (LC).

RAMPing:

The gradual increase or decrease of voltage or current over a period of time (step).

Step:

The Guardian 1000 Series instrument can perform up to 10 tests in a sequence. The step number indicates in which order the tests will be performed. For example if step 1 is a ground bond test, step 2 an AC hipot and step 3 an insulation resistance measurement then when a test is started the Guardian will perform a ground bond test followed by an AC hipot then an insulation resistance measurement.


**Test Current:**

Real Current:

The real current test is a measure of the resistive current component of the device under test. The resistive component is attributed to the resistance of the device's insulation.

Total Current:

The total current test is a measure of the resistive and reactive current components of the device under test. The reactive component is attributed to the capacitive or inductive components of the circuit



## 2.2 Startup

Check to make sure the Red Voltage Selector Switches on the rear panel agree with the power source available. Depending on the power source the switch positions should be in the up or down positions as shown in Figure 1-5 (Close-Up of G1000 Series Rear Panel).

**WARNING**  
**NEVER TOUCH THE TEST LEADS IN ANY MANNER** (this includes insulation on all wires and clips) when **HIGH VOLTAGE IS APPLIED** and red **DANGER** LED is **ON**.  
  
USE ALL PRECAUTIONS NECESSARY TO **AVOID TOUCHING THE DEVICE UNDER TEST** WHEN THE RED **DANGER** LED IS **ON OR FLASHING**.

Connect the instrument power cord to the source of proper voltage. **The instrument is to be used only with three-wire grounded outlets.**

Power is applied to the Guardian 1000 Series instrument by pressing the green [POWER] switch on the front panel to the ON (1 position). The Guardian 1000 Series unit should warm up for a period of at least 15 minutes prior to use.

**WARNING**  
**DO NOT TURN INSTRUMENT POWER ON OR OFF WITH TEST DEVICES CONNECTED.**

## 2.3 Programming Electrical Safety Tests

The Guardian 1000 Series instrument is capable of performing the tests listed in Table 2-2. A single-step test can be performed on a device and is programmed as described in paragraphs 2.4 – 2.6. When the device under test requires a multi-step test the order of test precedence is important. Refer to paragraph 2.7 for programming a multi-step test.


**Table 2-2: Guardian 1000 Series Electrical Safety Tests**

<b>Test</b>	<b>Software Designation</b>	<b>Programming Instructions Paragraph</b>	<b>G1000 Series Instrument</b>
AC Hipot	AC	2.4	1010, 1030, 1030S
DC Hipot	DC	2.5	1030, 1030S
Insulation Resistance	IR	2.6	1030, 1030S
Multi-Step		2.7	1010, 1030, 1030S

A scan test is programmed in the last step of an AC, DC and/or IR test setup. The Guardian 1030S is equipped with an internal 8 channel HV scanner. The rear panel scan interface is standard on the Guardian 1030S. An external scanner can be used with the Guardian 1000 Series instrument. Refer to paragraph 3.5 for further description of the scan interface.

## Function keys of the STAND BY Display

The function keys on the right hand side of the display allow the operator to access the numerous menus imbedded within the Guardian 1000 Series instrument software. Familiarize yourself with these menus prior to programming a test. Figure 2-1 illustrates the STAND BY display and lists the functions that can be accessed by pressing the [F1] through [F4] keys.




**Figure 2-1: STAND BY Function Key Menus**



Figure 2-2 illustrates the “STAND BY” or ‘Power-Up’ display. Also illustrated in Figure 2-3 are the PROGRAM display and the three test mode displays (AC, DC or IR).

The Guardian 1000 Series instruments have multiple menus or displays that may seem confusing at first glance. In an attempt to clarify the numerous functions of the software, this instruction manual will illustrate these displays in a (hopefully) logical format. The function keys (F1, F2, F3 & F4) perform different tasks depending upon the menu currently shown on the display. Figure 2-2 illustrates the STAND BY display shown upon instrument ‘power-up’.

**"STAND BY" or "Power-Up" Display**



**Figure 2-2: STAND BY Display**

To access the programming function of the G1000 Series instrument in the STAND BY menu, press the [F1] key (PROGRAM). Once in the PROGRAM display, select the test step then the test mode (AC, DC or IR). From here you can program the individual parameters of each test. Refer to Figure 2-3 for an illustration of the “STAND BY” display, the PROGRAM display and the three test mode displays (AC, DC or IR). Paragraphs 2.4, 2.5 and 2.6 illustrate how to program the specific parameters of each of the 3 tests.

The Stand By display as shown when the G1000 instrument is powered up. The box in the lower left hand corner denotes the instrument status. For clarity, a green arrow (◀) is used to denote which function key (F1 – F4) is pressed to get to the next display screen.

"STAND BY" or "Power-Up" Display	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">STEP 1/1</td> <td style="width: 25%;">AC</td> <td style="width: 25%;">LOW : OFF</td> <td style="width: 25%; text-align: right;">PROGRAM</td> </tr> <tr> <td></td> <td></td> <td>ARC : OFF</td> <td></td> </tr> <tr> <td style="text-align: center;">1.250kV</td> <td></td> <td>RAMP : OFF</td> <td style="text-align: right;">PRESET</td> </tr> <tr> <td style="text-align: center;">15.00mA</td> <td></td> <td>REAL : OFF</td> <td></td> </tr> <tr> <td style="text-align: center;">3.0s</td> <td></td> <td style="text-align: center;">1 2 3 4 5 6 7 8</td> <td style="text-align: right;">MENU</td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">STAND BY</td> <td style="border: 1px solid black; text-align: center;">RMT</td> <td style="border: 1px solid black; text-align: center;">LOCK</td> <td style="border: 1px solid black; text-align: center;">OFST</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">ERR</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">MORE..</td> </tr> </table>	STEP 1/1	AC	LOW : OFF	PROGRAM			ARC : OFF		1.250kV		RAMP : OFF	PRESET	15.00mA		REAL : OFF		3.0s		1 2 3 4 5 6 7 8	MENU			SCAN : x x x x x x x x		STAND BY	RMT	LOCK	OFST				ERR				MORE..	<p>F1 ▶ To enter programming mode.</p> <p>F2 ◀ To view/change preset (initial) test parameters.</p> <p>F3 ◀ To view/change system parameters: memory, system, option, calibration, key lock, password, error, &amp; about.</p> <p>F4 ◀ To view the programmed test setups and access offset function.</p>
STEP 1/1	AC	LOW : OFF	PROGRAM																																			
		ARC : OFF																																				
1.250kV		RAMP : OFF	PRESET																																			
15.00mA		REAL : OFF																																				
3.0s		1 2 3 4 5 6 7 8	MENU																																			
		SCAN : x x x x x x x x																																				
STAND BY	RMT	LOCK	OFST																																			
			ERR																																			
			MORE..																																			
"PROGRAM" Display	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">STEP 1</td> <td style="width: 25%;">AC</td> <td style="width: 25%;">LOW : OFF</td> <td style="width: 25%; text-align: right;">UP</td> </tr> <tr> <td></td> <td></td> <td>ARC : OFF</td> <td></td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td>RAMP : OFF</td> <td style="text-align: right;">MORE..</td> </tr> <tr> <td>HIGH: 0.500mA</td> <td></td> <td>REAL : OFF</td> <td></td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td style="text-align: center;">1 2 3 4 5 6 7 8</td> <td style="text-align: right;">ENTER</td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">PROCESS STEP</td> <td style="border: 1px solid black; text-align: center;">RMT</td> <td style="border: 1px solid black; text-align: center;">LOCK</td> <td style="border: 1px solid black; text-align: center;">OFST</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">ERR</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">EXIT</td> </tr> </table>	STEP 1	AC	LOW : OFF	UP			ARC : OFF		VOLT: 0.000kV		RAMP : OFF	MORE..	HIGH: 0.500mA		REAL : OFF		TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER			SCAN : x x x x x x x x		PROCESS STEP	RMT	LOCK	OFST				ERR				EXIT	<p>F1 ▶ To change value in highlighted box.</p> <p>F2 ◀ To delete or insert a test step.</p> <p>F3 ◀ To move highlighted box around display to select parameter to change</p> <p>F4 ◀ To exit programming mode.</p>
STEP 1	AC	LOW : OFF	UP																																			
		ARC : OFF																																				
VOLT: 0.000kV		RAMP : OFF	MORE..																																			
HIGH: 0.500mA		REAL : OFF																																				
TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER																																			
		SCAN : x x x x x x x x																																				
PROCESS STEP	RMT	LOCK	OFST																																			
			ERR																																			
			EXIT																																			
"PROGRAM" Display	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">STEP 1</td> <td style="width: 25%; text-align: center;">▶ AC</td> <td style="width: 25%;">LOW : OFF</td> <td style="width: 25%; text-align: right;">UP</td> </tr> <tr> <td></td> <td></td> <td>ARC : OFF</td> <td></td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td>RAMP : OFF</td> <td style="text-align: right;">DOWN</td> </tr> <tr> <td>HIGH: 0.500mA</td> <td></td> <td>REAL : OFF</td> <td></td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td style="text-align: center;">1 2 3 4 5 6 7 8</td> <td style="text-align: right;">ENTER</td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">SELECT MODE</td> <td style="border: 1px solid black; text-align: center;">RMT</td> <td style="border: 1px solid black; text-align: center;">LOCK</td> <td style="border: 1px solid black; text-align: center;">OFST</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">ERR</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">EXIT</td> </tr> </table>	STEP 1	▶ AC	LOW : OFF	UP			ARC : OFF		VOLT: 0.000kV		RAMP : OFF	DOWN	HIGH: 0.500mA		REAL : OFF		TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER			SCAN : x x x x x x x x		SELECT MODE	RMT	LOCK	OFST				ERR				EXIT	<p>F1 ▶ To move highlighted box around display to select parameter to change</p>
STEP 1	▶ AC	LOW : OFF	UP																																			
		ARC : OFF																																				
VOLT: 0.000kV		RAMP : OFF	DOWN																																			
HIGH: 0.500mA		REAL : OFF																																				
TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER																																			
		SCAN : x x x x x x x x																																				
SELECT MODE	RMT	LOCK	OFST																																			
			ERR																																			
			EXIT																																			
"AC" Test Setup Display	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">STEP 1</td> <td style="width: 25%; text-align: center;">AC</td> <td style="width: 25%;">LOW : OFF</td> <td style="width: 25%; text-align: right;">UP</td> </tr> <tr> <td></td> <td></td> <td>ARC : OFF</td> <td></td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td>RAMP : OFF</td> <td style="text-align: right;">DOWN</td> </tr> <tr> <td>HIGH: 0.500mA</td> <td></td> <td>REAL : OFF</td> <td></td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td style="text-align: center;">1 2 3 4 5 6 7 8</td> <td style="text-align: right;">ENTER</td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">SELECT MODE</td> <td style="border: 1px solid black; text-align: center;">RMT</td> <td style="border: 1px solid black; text-align: center;">LOCK</td> <td style="border: 1px solid black; text-align: center;">OFST</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">ERR</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">EXIT</td> </tr> </table>	STEP 1	AC	LOW : OFF	UP			ARC : OFF		VOLT: 0.000kV		RAMP : OFF	DOWN	HIGH: 0.500mA		REAL : OFF		TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER			SCAN : x x x x x x x x		SELECT MODE	RMT	LOCK	OFST				ERR				EXIT	<p>F1 ▶ To toggle between AC/DC/IR and select test mode</p>
STEP 1	AC	LOW : OFF	UP																																			
		ARC : OFF																																				
VOLT: 0.000kV		RAMP : OFF	DOWN																																			
HIGH: 0.500mA		REAL : OFF																																				
TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER																																			
		SCAN : x x x x x x x x																																				
SELECT MODE	RMT	LOCK	OFST																																			
			ERR																																			
			EXIT																																			
"DC" Test Setup Display	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">STEP 1</td> <td style="width: 25%; text-align: center;">DC</td> <td style="width: 25%;">LOW : OFF</td> <td style="width: 25%; text-align: right;">UP</td> </tr> <tr> <td></td> <td></td> <td>ARC : OFF</td> <td></td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td>RAMP : OFF</td> <td style="text-align: right;">DOWN</td> </tr> <tr> <td>HIGH: 0.500mA</td> <td></td> <td></td> <td></td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td style="text-align: center;">1 2 3 4 5 6 7 8</td> <td style="text-align: right;">ENTER</td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">SELECT MODE</td> <td style="border: 1px solid black; text-align: center;">RMT</td> <td style="border: 1px solid black; text-align: center;">LOCK</td> <td style="border: 1px solid black; text-align: center;">OFST</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">ERR</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">EXIT</td> </tr> </table>	STEP 1	DC	LOW : OFF	UP			ARC : OFF		VOLT: 0.000kV		RAMP : OFF	DOWN	HIGH: 0.500mA				TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER			SCAN : x x x x x x x x		SELECT MODE	RMT	LOCK	OFST				ERR				EXIT	<p>F1 ▶ To toggle between AC/DC/IR and select test mode</p>
STEP 1	DC	LOW : OFF	UP																																			
		ARC : OFF																																				
VOLT: 0.000kV		RAMP : OFF	DOWN																																			
HIGH: 0.500mA																																						
TIME: 3.0s		1 2 3 4 5 6 7 8	ENTER																																			
		SCAN : x x x x x x x x																																				
SELECT MODE	RMT	LOCK	OFST																																			
			ERR																																			
			EXIT																																			
"IR" Test Setup Display	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">STEP 1</td> <td style="width: 25%; text-align: center;">IR</td> <td style="width: 25%;">HIGH : OFF</td> <td style="width: 25%; text-align: right;">UP</td> </tr> <tr> <td></td> <td></td> <td>RAMP : OFF</td> <td></td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td></td> <td style="text-align: right;">DOWN</td> </tr> <tr> <td>LOW: 1.0MΩ</td> <td></td> <td style="text-align: center;">1 2 3 4 5 6 7 8</td> <td style="text-align: right;">ENTER</td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">SELECT MODE</td> <td style="border: 1px solid black; text-align: center;">RMT</td> <td style="border: 1px solid black; text-align: center;">LOCK</td> <td style="border: 1px solid black; text-align: center;">OFST</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">ERR</td> </tr> <tr> <td></td> <td></td> <td></td> <td style="border: 1px solid black; text-align: center;">EXIT</td> </tr> </table>	STEP 1	IR	HIGH : OFF	UP			RAMP : OFF		VOLT: 0.000kV			DOWN	LOW: 1.0MΩ		1 2 3 4 5 6 7 8	ENTER	TIME: 3.0s		SCAN : x x x x x x x x		SELECT MODE	RMT	LOCK	OFST				ERR				EXIT	<p>F1 ▶ To toggle between AC/DC/IR and select test mode</p>				
STEP 1	IR	HIGH : OFF	UP																																			
		RAMP : OFF																																				
VOLT: 0.000kV			DOWN																																			
LOW: 1.0MΩ		1 2 3 4 5 6 7 8	ENTER																																			
TIME: 3.0s		SCAN : x x x x x x x x																																				
SELECT MODE	RMT	LOCK	OFST																																			
			ERR																																			
			EXIT																																			

**Figure 2-3: STAND BY, PROGRAM & Test Mode Displays**

## 2.4 Programming an AC Hipot Test

This test is applicable to the Guardian 1010, 1030 and 1030S instruments. With the instrument in 'stand-by' status, press [F1] = PROGRAM. Follow the green arrows (◀) on the right side of this diagram to program the individual AC hipot test parameters.

"STAND BY" or "Power-Up" Display	<table border="1"> <tr> <td>STEP 1/0</td> <td>AC</td> <td>LOW : OFF</td> <td>PROGRAM</td> <td>F1</td> <td>▶</td> <td>To enter programming mode.</td> </tr> <tr> <td>0.000kV</td> <td></td> <td>ARC : OFF</td> <td>PRESET</td> <td>F2</td> <td>◀</td> <td>To view/change preset (initial) test parameters.</td> </tr> <tr> <td>0.500mA</td> <td></td> <td>RAMP: OFF</td> <td>MENU</td> <td>F3</td> <td>◀</td> <td>To view/change system parameters: memory, system, option, calibration, key lock, password, error, &amp; about.</td> </tr> <tr> <td>3.0s</td> <td></td> <td>REAL: OFF</td> <td>MORE..</td> <td>F4</td> <td>◀</td> <td>To view the programmed test setups and access offset function.</td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>STAND BY</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1/0	AC	LOW : OFF	PROGRAM	F1	▶	To enter programming mode.	0.000kV		ARC : OFF	PRESET	F2	◀	To view/change preset (initial) test parameters.	0.500mA		RAMP: OFF	MENU	F3	◀	To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.	3.0s		REAL: OFF	MORE..	F4	◀	To view the programmed test setups and access offset function.			SCAN : 1 2 3 4 5 6 7 8							SCAN : x x x x x x x x						STAND BY	RMT	LOCK	OFST	ERR	
	STEP 1/0	AC	LOW : OFF	PROGRAM	F1	▶	To enter programming mode.																																											
0.000kV		ARC : OFF	PRESET	F2	◀	To view/change preset (initial) test parameters.																																												
0.500mA		RAMP: OFF	MENU	F3	◀	To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.																																												
3.0s		REAL: OFF	MORE..	F4	◀	To view the programmed test setups and access offset function.																																												
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : x x x x x x x x																																																
	STAND BY	RMT	LOCK	OFST	ERR																																													
"PROGRAM" Display	<table border="1"> <tr> <td>STEP 1</td> <td>AC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>◀</td> <td>To change value in highlighted box.</td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td>ARC : OFF</td> <td>MORE..</td> <td>F2</td> <td>◀</td> <td>To delete or insert a test step.</td> </tr> <tr> <td>HIGH: 0.500mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box around display to select parameter to change</td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td>◀</td> <td>To exit programming mode.</td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>PROCESS STEP</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1	AC	LOW : OFF	UP	F1	◀	To change value in highlighted box.	VOLT: 0.000kV		ARC : OFF	MORE..	F2	◀	To delete or insert a test step.	HIGH: 0.500mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box around display to select parameter to change	TIME: 3.0s		REAL: OFF	EXIT	F4	◀	To exit programming mode.			SCAN : 1 2 3 4 5 6 7 8							SCAN : x x x x x x x x						PROCESS STEP	RMT	LOCK	OFST	ERR	
STEP 1	AC	LOW : OFF	UP	F1	◀	To change value in highlighted box.																																												
VOLT: 0.000kV		ARC : OFF	MORE..	F2	◀	To delete or insert a test step.																																												
HIGH: 0.500mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box around display to select parameter to change																																												
TIME: 3.0s		REAL: OFF	EXIT	F4	◀	To exit programming mode.																																												
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : x x x x x x x x																																																
	PROCESS STEP	RMT	LOCK	OFST	ERR																																													
Select AC Test Mode	<table border="1"> <tr> <td>STEP 1</td> <td>AC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>To select test mode equal to AC</td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td>ARC : OFF</td> <td>DOWN</td> <td>F2</td> <td></td> <td></td> </tr> <tr> <td>HIGH: 0.500mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box to VOLT.</td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>SELECT MODE</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1	AC	LOW : OFF	UP	F1	▶	To select test mode equal to AC	VOLT: 0.000kV		ARC : OFF	DOWN	F2			HIGH: 0.500mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to VOLT.	TIME: 3.0s		REAL: OFF	EXIT	F4					SCAN : 1 2 3 4 5 6 7 8							SCAN : x x x x x x x x						SELECT MODE	RMT	LOCK	OFST	ERR	
STEP 1	AC	LOW : OFF	UP	F1	▶	To select test mode equal to AC																																												
VOLT: 0.000kV		ARC : OFF	DOWN	F2																																														
HIGH: 0.500mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to VOLT.																																												
TIME: 3.0s		REAL: OFF	EXIT	F4																																														
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : x x x x x x x x																																																
	SELECT MODE	RMT	LOCK	OFST	ERR																																													
Set Test VOLTage	<table border="1"> <tr> <td>STEP 1</td> <td>AC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>To enter test voltage in 0.001kV increments</td> </tr> <tr> <td>VOLT: 0.000 kV</td> <td></td> <td>ARC : OFF</td> <td>DOWN</td> <td>F2</td> <td></td> <td></td> </tr> <tr> <td>HIGH: 0.500 mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box to HIGH.</td> </tr> <tr> <td>TIME: 3.0 s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>0.05 - 5kV</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1	AC	LOW : OFF	UP	F1	▶	To enter test voltage in 0.001kV increments	VOLT: 0.000 kV		ARC : OFF	DOWN	F2			HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to HIGH.	TIME: 3.0 s		REAL: OFF	EXIT	F4					SCAN : 1 2 3 4 5 6 7 8							SCAN : x x x x x x x x						0.05 - 5kV	RMT	LOCK	OFST	ERR	
STEP 1	AC	LOW : OFF	UP	F1	▶	To enter test voltage in 0.001kV increments																																												
VOLT: 0.000 kV		ARC : OFF	DOWN	F2																																														
HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to HIGH.																																												
TIME: 3.0 s		REAL: OFF	EXIT	F4																																														
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : x x x x x x x x																																																
	0.05 - 5kV	RMT	LOCK	OFST	ERR																																													
Set HIGH Current Limit	<table border="1"> <tr> <td>STEP 1</td> <td>AC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>To enter high current limit in 0.001mA increments</td> </tr> <tr> <td>VOLT: 1.250 kV</td> <td></td> <td>ARC : OFF</td> <td>DOWN</td> <td>F2</td> <td></td> <td></td> </tr> <tr> <td>HIGH: 0.500 mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box to TIME.</td> </tr> <tr> <td>TIME: 3.0 s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>0.001 - 30mA</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1	AC	LOW : OFF	UP	F1	▶	To enter high current limit in 0.001mA increments	VOLT: 1.250 kV		ARC : OFF	DOWN	F2			HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to TIME.	TIME: 3.0 s		REAL: OFF	EXIT	F4					SCAN : 1 2 3 4 5 6 7 8							SCAN : x x x x x x x x						0.001 - 30mA	RMT	LOCK	OFST	ERR	
STEP 1	AC	LOW : OFF	UP	F1	▶	To enter high current limit in 0.001mA increments																																												
VOLT: 1.250 kV		ARC : OFF	DOWN	F2																																														
HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to TIME.																																												
TIME: 3.0 s		REAL: OFF	EXIT	F4																																														
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : x x x x x x x x																																																
	0.001 - 30mA	RMT	LOCK	OFST	ERR																																													
Set Test TIME	<table border="1"> <tr> <td>STEP 1</td> <td>AC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>To enter test time in 0.1 second increments</td> </tr> <tr> <td>VOLT: 1.250 kV</td> <td></td> <td>ARC : OFF</td> <td>DOWN</td> <td>F2</td> <td></td> <td></td> </tr> <tr> <td>HIGH: 15.0 mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box to LOW.</td> </tr> <tr> <td>TIME: 3.0 s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : x x x x x x x x</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>0, 0.1 - 999s</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1	AC	LOW : OFF	UP	F1	▶	To enter test time in 0.1 second increments	VOLT: 1.250 kV		ARC : OFF	DOWN	F2			HIGH: 15.0 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to LOW.	TIME: 3.0 s		REAL: OFF	EXIT	F4					SCAN : 1 2 3 4 5 6 7 8							SCAN : x x x x x x x x						0, 0.1 - 999s	RMT	LOCK	OFST	ERR	
STEP 1	AC	LOW : OFF	UP	F1	▶	To enter test time in 0.1 second increments																																												
VOLT: 1.250 kV		ARC : OFF	DOWN	F2																																														
HIGH: 15.0 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to LOW.																																												
TIME: 3.0 s		REAL: OFF	EXIT	F4																																														
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : x x x x x x x x																																																
	0, 0.1 - 999s	RMT	LOCK	OFST	ERR																																													

Continue on next page.

## Programming an AC Hipot Test (Continued)

Set LOW Current Limit	STEP 1	AC	LOW : OFF	UP	F1	▶ To enter low current limit in 0.001mA increments
	VOLT: 1.250 kV		ARC : OFF	DOWN	F2	
	HIGH: 15.0 mA		RAMP: OFF	ENTER	F3	▶ To move highlighted box to ARC.
	TIME: 3.0 s		REAL: OFF	EXIT	F4	
			SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X			
	0 - 30mA	0=OFF	RMT	LOCK	OFST	ERR

Set ARC Limit	STEP 1	AC	LOW : OFF	UP	F1	▶ To enter ARC limit in 0.001mA increments
	VOLT: 1.250 kV		ARC : OFF	DOWN	F2	
	HIGH: 1.000 mA		RAMP: OFF	ENTER	F3	▶ To move highlighted box to RAMP.
	TIME: 3.0 s		REAL: OFF	EXIT	F4	
			SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X			
	1 - 15mA	0=OFF	RMT	LOCK	OFST	ERR

Set RAMP Time	STEP 1	AC	LOW : OFF	UP	F1	▶ To enter ramp time in 0.1 second increments
	VOLT: 1.250 kV		ARC : OFF	DOWN	F2	
	HIGH: 15.0 mA		RAMP: OFF	ENTER	F3	▶ To move highlighted box to REAL.
	TIME: 3.0 s		REAL: OFF	EXIT	F4	
			SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X			
	0 - 999s	0=OFF	RMT	LOCK	OFST	ERR

Set REAL Current Limit	STEP 1	AC	LOW : OFF	UP	F1	▶ To enter real current ON or OFF in 0.001mA increments.
	VOLT: 1.250 kV		ARC : OFF	DOWN	F2	
	HIGH: 0.500 mA		RAMP: 10.0 s	ENTER	F3	▶ To move highlighted box to SCAN.
	TIME: 3.0 s		REAL: OFF	EXIT	F4	
			SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X			
	0 - 30mA	0=OFF	RMT	LOCK	OFST	ERR

Set SCAN Channels	STEP 1	AC	LOW : OFF	MOVE	F1	▶ To move underscore cursor to highlight a scan channel 1-8.
	VOLT: 1.250 kV		ARC : OFF	CHANGE	F2	▶ To change status of a scan channel 1-8 as H (high), L (low) or X (OFF).
	HIGH: 15.0 mA		RAMP: OFF	ENTER	F3	
	TIME: 10.0 s		REAL: OFF	EXIT	F4	
			SCAN : H X X X X X X X			
	SELECT BOXS		RMT	LOCK	OFST	ERR

EXIT or Program More	STEP 1	AC	LOW : OFF	MOVE	F1	▶ To move highlighted box to STEP and immediately program another step.
	VOLT: 1.250 kV		ARC : OFF	CHANGE	F2	
	HIGH: 15.0 mA		RAMP: OFF	ENTER	F3	OR ▶ To exit programming mode and return to STAND BY status.
	TIME: 10.0 s		REAL: OFF	EXIT	F4	
			SCAN : H X X X X X X X			
	CHANNEL		RMT	LOCK	OFST	ERR

**END AC Hipot Test Programming.** After selecting the scan channels, one can either press [F3] = ENTER to move the highlighted box to STEP and start programming STEP 2-99 OR one can press [F4] = EXIT to exit programming function and return to STAND BY status.

## 2.5 Programming a DC Hipot Test

This test is applicable to the Guardian 1030 and 1030S instruments. With the instrument in 'stand-by' status, press [F1] = PROGRAM. Follow the **green** arrows (◀) on the right side of this diagram to program the individual DC hipot test parameters. The example illustrated herein shows an AC test as Step 1 and how to program a DC test in Step 2.

"STAND BY" or "Power-Up" Display	<table border="1"> <tr> <td>STEP 1/1</td> <td>AC</td> <td>LOW : OFF</td> <td>PROGRAM</td> <td>F1</td> <td>▶</td> <td>To enter programming mode.</td> </tr> <tr> <td>1.250kV</td> <td></td> <td>ARC : OFF</td> <td>PRESET</td> <td>F2</td> <td>◀</td> <td>To view/change preset (initial) test parameters.</td> </tr> <tr> <td>15.00mA</td> <td></td> <td>RAMP: OFF</td> <td>MENU</td> <td>F3</td> <td>◀</td> <td>To view/change system parameters: memory, system, option, calibration, key lock, password, error, &amp; about.</td> </tr> <tr> <td>3.0s</td> <td></td> <td>REAL: OFF</td> <td>MORE..</td> <td>F4</td> <td>◀</td> <td>To view the programmed test setups and access offset function.</td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : X X X X X X X X</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>STAND BY</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1/1	AC	LOW : OFF	PROGRAM	F1	▶	To enter programming mode.	1.250kV		ARC : OFF	PRESET	F2	◀	To view/change preset (initial) test parameters.	15.00mA		RAMP: OFF	MENU	F3	◀	To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.	3.0s		REAL: OFF	MORE..	F4	◀	To view the programmed test setups and access offset function.			SCAN : 1 2 3 4 5 6 7 8							SCAN : X X X X X X X X						STAND BY	RMT	LOCK	OFST	ERR	
	STEP 1/1	AC	LOW : OFF	PROGRAM	F1	▶	To enter programming mode.																																											
1.250kV		ARC : OFF	PRESET	F2	◀	To view/change preset (initial) test parameters.																																												
15.00mA		RAMP: OFF	MENU	F3	◀	To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.																																												
3.0s		REAL: OFF	MORE..	F4	◀	To view the programmed test setups and access offset function.																																												
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : X X X X X X X X																																																
	STAND BY	RMT	LOCK	OFST	ERR																																													
"PROGRAM" Display	<table border="1"> <tr> <td>STEP 1</td> <td>AC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>◀</td> <td>To change value in highlighted box.</td> </tr> <tr> <td>VOLT: 1.250kV</td> <td></td> <td>ARC : OFF</td> <td>MORE..</td> <td>F2</td> <td>◀</td> <td>To delete or insert a test step.</td> </tr> <tr> <td>HIGH: 15.0mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>◀</td> <td>To move highlighted box around display to select parameter to change</td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td>◀</td> <td>To exit programming mode.</td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : X X X X X X X X</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>PROCESS STEP</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 1	AC	LOW : OFF	UP	F1	◀	To change value in highlighted box.	VOLT: 1.250kV		ARC : OFF	MORE..	F2	◀	To delete or insert a test step.	HIGH: 15.0mA		RAMP: OFF	ENTER	F3	◀	To move highlighted box around display to select parameter to change	TIME: 3.0s		REAL: OFF	EXIT	F4	◀	To exit programming mode.			SCAN : 1 2 3 4 5 6 7 8							SCAN : X X X X X X X X						PROCESS STEP	RMT	LOCK	OFST	ERR	
STEP 1	AC	LOW : OFF	UP	F1	◀	To change value in highlighted box.																																												
VOLT: 1.250kV		ARC : OFF	MORE..	F2	◀	To delete or insert a test step.																																												
HIGH: 15.0mA		RAMP: OFF	ENTER	F3	◀	To move highlighted box around display to select parameter to change																																												
TIME: 3.0s		REAL: OFF	EXIT	F4	◀	To exit programming mode.																																												
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : X X X X X X X X																																																
	PROCESS STEP	RMT	LOCK	OFST	ERR																																													
Select STEP #	<table border="1"> <tr> <td>STEP 2</td> <td>AC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>To change value of highlighted box.</td> </tr> <tr> <td>VOLT: 1.250kV</td> <td></td> <td>ARC : OFF</td> <td>MORE..</td> <td>F2</td> <td>◀</td> <td>To delete or insert a test step.</td> </tr> <tr> <td>HIGH: 15.0mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box around display to select parameter to change</td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td>◀</td> <td>To exit programming mode.</td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : X X X X X X X X</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>PROCESS STEP</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 2	AC	LOW : OFF	UP	F1	▶	To change value of highlighted box.	VOLT: 1.250kV		ARC : OFF	MORE..	F2	◀	To delete or insert a test step.	HIGH: 15.0mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box around display to select parameter to change	TIME: 3.0s		REAL: OFF	EXIT	F4	◀	To exit programming mode.			SCAN : 1 2 3 4 5 6 7 8							SCAN : X X X X X X X X						PROCESS STEP	RMT	LOCK	OFST	ERR	
STEP 2	AC	LOW : OFF	UP	F1	▶	To change value of highlighted box.																																												
VOLT: 1.250kV		ARC : OFF	MORE..	F2	◀	To delete or insert a test step.																																												
HIGH: 15.0mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box around display to select parameter to change																																												
TIME: 3.0s		REAL: OFF	EXIT	F4	◀	To exit programming mode.																																												
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : X X X X X X X X																																																
	PROCESS STEP	RMT	LOCK	OFST	ERR																																													
Select DC Test Mode	<table border="1"> <tr> <td>STEP 2</td> <td>DC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>To change test mode to DC.</td> </tr> <tr> <td>VOLT: 0.000kV</td> <td></td> <td>ARC : OFF</td> <td>DOWN</td> <td>F2</td> <td>◀</td> <td></td> </tr> <tr> <td>HIGH: 0.500mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box to VOLT.</td> </tr> <tr> <td>TIME: 3.0s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td>◀</td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : X X X X X X X X</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>SELECT MODE</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 2	DC	LOW : OFF	UP	F1	▶	To change test mode to DC.	VOLT: 0.000kV		ARC : OFF	DOWN	F2	◀		HIGH: 0.500mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to VOLT.	TIME: 3.0s		REAL: OFF	EXIT	F4	◀				SCAN : 1 2 3 4 5 6 7 8							SCAN : X X X X X X X X						SELECT MODE	RMT	LOCK	OFST	ERR	
STEP 2	DC	LOW : OFF	UP	F1	▶	To change test mode to DC.																																												
VOLT: 0.000kV		ARC : OFF	DOWN	F2	◀																																													
HIGH: 0.500mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to VOLT.																																												
TIME: 3.0s		REAL: OFF	EXIT	F4	◀																																													
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : X X X X X X X X																																																
	SELECT MODE	RMT	LOCK	OFST	ERR																																													
Set Test VOLTage	<table border="1"> <tr> <td>STEP 2</td> <td>DC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>To enter test voltage in 0.001kV increments</td> </tr> <tr> <td>VOLT: 0.000 kV</td> <td></td> <td>ARC : OFF</td> <td>DOWN</td> <td>F2</td> <td>◀</td> <td></td> </tr> <tr> <td>HIGH: 0.500 mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box to HIGH.</td> </tr> <tr> <td>TIME: 3.0 s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td>◀</td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : X X X X X X X X</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>0.05 - 6kV</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 2	DC	LOW : OFF	UP	F1	▶	To enter test voltage in 0.001kV increments	VOLT: 0.000 kV		ARC : OFF	DOWN	F2	◀		HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to HIGH.	TIME: 3.0 s		REAL: OFF	EXIT	F4	◀				SCAN : 1 2 3 4 5 6 7 8							SCAN : X X X X X X X X						0.05 - 6kV	RMT	LOCK	OFST	ERR	
STEP 2	DC	LOW : OFF	UP	F1	▶	To enter test voltage in 0.001kV increments																																												
VOLT: 0.000 kV		ARC : OFF	DOWN	F2	◀																																													
HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to HIGH.																																												
TIME: 3.0 s		REAL: OFF	EXIT	F4	◀																																													
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : X X X X X X X X																																																
	0.05 - 6kV	RMT	LOCK	OFST	ERR																																													
Set HIGH Current Limit	<table border="1"> <tr> <td>STEP 2</td> <td>DC</td> <td>LOW : OFF</td> <td>UP</td> <td>F1</td> <td>▶</td> <td>0.1uA increments and from 0.001mA-10mA in 0.001mA increments</td> </tr> <tr> <td>VOLT: 2.500 kV</td> <td></td> <td>ARC : OFF</td> <td>DOWN</td> <td>F2</td> <td>◀</td> <td></td> </tr> <tr> <td>HIGH: 0.500 mA</td> <td></td> <td>RAMP: OFF</td> <td>ENTER</td> <td>F3</td> <td>▶</td> <td>To move highlighted box to TIME.</td> </tr> <tr> <td>TIME: 3.0 s</td> <td></td> <td>REAL: OFF</td> <td>EXIT</td> <td>F4</td> <td>◀</td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : 1 2 3 4 5 6 7 8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td>SCAN : X X X X X X X X</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td>0.0001 - 10mA</td> <td>RMT</td> <td>LOCK</td> <td>OFST</td> <td>ERR</td> <td></td> </tr> </table>	STEP 2	DC	LOW : OFF	UP	F1	▶	0.1uA increments and from 0.001mA-10mA in 0.001mA increments	VOLT: 2.500 kV		ARC : OFF	DOWN	F2	◀		HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to TIME.	TIME: 3.0 s		REAL: OFF	EXIT	F4	◀				SCAN : 1 2 3 4 5 6 7 8							SCAN : X X X X X X X X						0.0001 - 10mA	RMT	LOCK	OFST	ERR	
STEP 2	DC	LOW : OFF	UP	F1	▶	0.1uA increments and from 0.001mA-10mA in 0.001mA increments																																												
VOLT: 2.500 kV		ARC : OFF	DOWN	F2	◀																																													
HIGH: 0.500 mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box to TIME.																																												
TIME: 3.0 s		REAL: OFF	EXIT	F4	◀																																													
		SCAN : 1 2 3 4 5 6 7 8																																																
		SCAN : X X X X X X X X																																																
	0.0001 - 10mA	RMT	LOCK	OFST	ERR																																													

Continue on next page.

## Programming an DC Hipot Test (Continued)

Set Test TIME	STEP 2	DC	LOW : OFF	UP	F1	To enter test time in 0.1 second increments To move highlighted box to LOW.
	VOLT: 2.500 kV		ARC : OFF	DOWN	F2	
	HIGH: 15.0 mA		RAMP: OFF	ENTER	F3	
	TIME: 3.0 s		SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X	EXIT	F4	
	0, 0.1 - 999s	RMT	LOCK	OFST	ERR	
Set LOW Current Limit	STEP 2	DC	LOW : OFF	UP	F1	To enter low current limit in 0.001mA increments To move highlighted box to ARC.
	VOLT: 1.250 kV		ARC : OFF	DOWN	F2	
	HIGH: 10.0 mA		RAMP: OFF	ENTER	F3	
	TIME: 3.0 s		SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X	EXIT	F4	
	0 - 10mA 0=OFF	RMT	LOCK	OFST	ERR	
Set ARC Limit	STEP 2	DC	LOW : OFF	UP	F1	To enter ARC limit in 0.001mA increments To move highlighted box to RAMP.
	VOLT: 1.250 kV		ARC : OFF	DOWN	F2	
	HIGH: 1.000 mA		RAMP: OFF	ENTER	F3	
	TIME: 3.0 s		SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X	EXIT	F4	
	1 - 10mA 0=OFF	RMT	LOCK	OFST	ERR	
Set RAMP Time	STEP 2	DC	LOW : OFF	UP	F1	To enter ramp time in 0.1 second increments To move highlighted box to SCAN.
	VOLT: 1.250 kV		ARC : OFF	DOWN	F2	
	HIGH: 10.0 mA		RAMP: OFF	ENTER	F3	
	TIME: 3.0 s		SCAN : 1 2 3 4 5 6 7 8 X X X X X X X X	EXIT	F4	
	0 - 999s 0=OFF	RMT	LOCK	OFST	ERR	
Set SCAN Channels	STEP 2	DC	LOW : OFF	MOVE	F1	To move underscore cursor to highlight a scan channel 1-8. To change status of a scan channel 1-8 as H (high), L (low) or X (OFF).
	VOLT: 1.250 kV		ARC : OFF	CHANGE	F2	
	HIGH: 10.0 mA		RAMP: OFF	ENTER	F3	
	TIME: 3.0 s		SCAN : 1 2 3 4 5 6 7 8 H X X X X X X X	EXIT	F4	
	SELECT BOXS	RMT	LOCK	OFST	ERR	
EXIT or Program More	STEP 2	DC	LOW : OFF	MOVE	F1	To move highlighted box to STEP and immediately program another step. To exit programming mode and return to STAND BY status.
	VOLT: 1.250 kV		ARC : OFF	CHANGE	F2	
	HIGH: 10.0 mA		RAMP: OFF	ENTER	F3	
	TIME: 3.0 s		SCAN : 1 2 3 4 5 6 7 8 H X X X X X X X	EXIT	F4	
	CHANNEL	RMT	LOCK	OFST	ERR	

**END DC Hipot Test Programming.** After selecting the scan channels, one can either press [F3] = ENTER to move the highlighted box to STEP and start programming STEP 3-99 OR one can press [F4] = EXIT to exit programming function and return to STAND BY status.

## 2.6 Programming an IR (Insulation Resistance) Test

This test is applicable to the 1030 and 1030S instruments. With the instrument in 'stand-by' status, press [F1] = PROGRAM. Follow the green arrows (◀) on the right side of this diagram to program the individual IR (insulation resistance) test parameters. This example shows an AC test as Step 1, a DC test as Step 2 and how to program an IR test in Step 3.

"STAND BY" or "Power-Up" Display	STEP 1/2	AC	LOW : OFF	PROGRAM	F1	▶	To enter programming mode.
	1.250kV		ARC : OFF	PRESET	F2	◀	To view/change preset (initial) test parameters.
	15.00mA		RAMP: OFF	MENU	F3	◀	To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.
	3.0s		REAL: OFF	MORE..	F4	◀	To view the programmed test setups and access offset function.
	STAND BY	RMT	LOCK	OFST	ERR		
"PROGRAM" Display & Select Step #	STEP 1	AC	LOW : OFF	UP	F1	▶	To change value in highlighted box. (Press twice to go to Step 3).
	VOLT: 2.500kV		ARC : OFF	MORE..	F2	◀	To delete or insert a test step.
	HIGH: 15.0mA		RAMP: OFF	ENTER	F3	▶	To move highlighted box around display to select parameter to change
	TIME: 3.0s		REAL: OFF	EXIT	F4	◀	To exit programming mode.
	PROCESS STEP	RMT	LOCK	OFST	ERR		
Select IR Test Mode	STEP 3	IR	HIGH: OFF	UP	F1	▶	To select test mode equal to IR
	VOLT: 0.000kV		RAMP: OFF	DOWN	F2	▶	To move highlighted box to VOLT.
	LOW: 1.0MΩ		SCAN : X X X X X X X X	ENTER	F3	▶	To move highlighted box to VOLT.
	TIME: 3.0s			EXIT	F4	▶	To move highlighted box to VOLT.
	SELECT MODE	RMT	LOCK	OFST	ERR		
Set Test VOLTage	STEP 3	IR	HIGH: OFF	UP	F1	▶	To enter test voltage in 0.001kV increments
	VOLT: 0.000 kV		RAMP: OFF	DOWN	F2	▶	To enter test voltage in 0.001kV increments
	LOW: 1.0 MΩ		SCAN : X X X X X X X X	ENTER	F3	▶	To move highlighted box to LOW.
	TIME: 3.0 s			EXIT	F4	▶	To move highlighted box to LOW.
	0.05 - 1kV	RMT	LOCK	OFST	ERR		
Set LOW Resistance Limit	STEP 3	IR	HIGH: OFF	UP	F1	▶	To enter low resistance limit in 0.1MΩ increments
	VOLT: 0.500 kV		RAMP: OFF	DOWN	F2	▶	To enter low resistance limit in 0.1MΩ increments
	LOW: 1.0 MΩ		SCAN : X X X X X X X X	ENTER	F3	▶	To move highlighted box to TIME.
	TIME: 3.0 s			EXIT	F4	▶	To move highlighted box to TIME.
	0.1 - 50000MΩ	RMT	LOCK	OFST	ERR		
Set Test TIME	STEP 3	IR	HIGH: OFF	UP	F1	▶	To enter test time in 0.1 second increments
	VOLT: 0.500 kV		RAMP: OFF	DOWN	F2	▶	To enter test time in 0.1 second increments
	LOW: 2.5 MΩ		SCAN : X X X X X X X X	ENTER	F3	▶	To move highlighted box to HIGH.
	TIME: 3.0 s			EXIT	F4	▶	To move highlighted box to HIGH.
	0, 0.1 - 999s	RMT	LOCK	OFST	ERR		

Continue on next page.

## Programming an IR (Insulation Resistance) Test (Continued)

Set HIGH Resistance Limit	STEP 3	IR	HIGH : OFF	UP	F1	▶ To enter high resistance limit in 0.1MΩ increments
			RAMP: OFF	DOWN	F2	
	VOLT: 0.500 kV		1 2 3 4 5 6 7 8	ENTER	F3	▶ To move highlighted box to RAMP.
	LOW: 2.5 MΩ		SCAN : X X X X X X X X	EXIT	F4	
	0 - 50GΩ	0=OFF	RMT	LOCK	OFST	ERR
Set RAMP Time	STEP 3	IR	HIGH : OFF	UP	F1	▶ To enter ramp time in 0.1 second increments
			RAMP: OFF	DOWN	F2	
	VOLT: 0.500 kV		1 2 3 4 5 6 7 8	ENTER	F3	▶ To move highlighted box to SCAN.
	LOW: 2.5 MΩ		SCAN : X X X X X X X X	EXIT	F4	
	0 - 999s	0=OFF	RMT	LOCK	OFST	ERR
Set SCAN Channels	STEP 3	IR	HIGH : OFF	MOVE	F1	▶ To move underscore cursor to highlight a scan channel 1-8.
			RAMP: OFF	CHANGE	F2	▶ To change status of a scan channel 1-8 as H (high), L (low) or X (OFF).
	VOLT: 0.500 kV		1 2 3 4 5 6 7 8	ENTER	F3	
	LOW: 2.5 MΩ		SCAN : H X X X X X X X	EXIT	F4	
	SELECT BOXS	RMT	LOCK	OFST	ERR	
EXIT or Program More	STEP 3	IR	HIGH : OFF	MOVE	F1	
			RAMP: OFF	CHANGE	F2	
	VOLT: 0.500 kV		1 2 3 4 5 6 7 8	ENTER	F3	◀ To move highlighted box to STEP and immediately program another step.
	LOW: 2.5 MΩ		SCAN : H X X X X X X X	EXIT	F4	OR ▶ To exit programming mode and return to STAND BY status.
	CHANNEL	RMT	LOCK	OFST	ERR	
For the sake of this example, we pressed [F4] = EXIT and returned to STAND BY status.						
"STAND BY" or "Power-Up" Display	STEP 1/3	AC	LOW : OFF	PROGRAM	F1	◀ To enter programming mode.
			ARC : OFF	PRESET	F2	◀ To view/change preset (initial) test parameters.
	1.250kV		RAMP: OFF	MENU	F3	◀ To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.
	15.00mA		1 2 3 4 5 6 7 8	MORE..	F4	▶ To view the programmed test setups and access offset function.
3.0s		SCAN : X X X X X X X X				
	STAND BY	RMT	LOCK	OFST	ERR	
For the sake of this example, we pressed [F4] = MORE to view the 3 Test Setups just programmed (AC/DC/IR)						
Test Setups	VOLTAGE MEASURE REAL			UP	F1	
	1	AC	1.250 kV 15.00 mA	DOWN	F2	
	2	DC	2.500 kV 0.500 mA	OFFSET	F3	▶ To enter OFFSET function.
	3	IR	0.500 kV 2.50 MΩ	MORE..	F4	▶ To return to STAND BY status
			1 2 3 4 5 6 7 8			
			SCAN : X X X X X X X X			
	STAND BY	RMT	LOCK	OFST	ERR	


**END IR (Insulation Resistance) Test Programming.** For this specific example, press [F4] = MORE to return to STAND BY status.



## 2.7 Programming a Multi-Step Test

Paragraphs 2.4, 2.5 and 2.6 illustrate the programming of a 3-step test (AC, DC & IR). To program a multiple step test, power-up the G1000 Series instrument so the 'Stand By' display is shown (Figure 2-2). Press [F1] = PROGRAM and enter the test parameters for the first test. After specifying SCAN channels press [F3] = ENTER to enter test parameters for the second test. At this time, do **NOT** press [F4] = EXIT because this will exit you from programming mode. After specifying SCAN channels for the second test press [F3] = ENTER to continue entering test parameters for the third test. Continue this process for up to 99 steps. When finished entering desired number of test steps, press [F4] = EXIT to exit programming mode and return to Stand By status.

In Stand By status, to view the test steps just programmed press [F4] = MORE. Figure 2-4 illustrates the Stand By display and resultant test setup display if the programming example in paragraphs 2.4-2.6 were followed.



**Figure 2-4: View Programmed Test Setups**

To view the test results, press [F4] = MORE to go to the tabular display. Use the UP/DOWN key to scroll to the next page.

**NOTE:**  
Exiting the tabular display will clear your test results.

**NOTE:**  
Instrument **PRESET** values can be programmed and stored for your specific test setup. Therefore **before storing** your tests, program the preset values.

## 2.7.1 SMART Key


Applicable to software version 2.xx or higher, this programming function retains the last ten (10) test parameters previously run. When in program mode and SMART key is ON, the UP/DOWN function key will permit the user to scroll through the last ten parameters tested.

To turn SMART Key ON:

In program menu, press and hold [ENTER = F3] until “S-KEY” is displayed in lower left hand corner. Refer to Figure 2.5.

To turn SMART Key OFF:

Press and hold [ENTER = F3] for approximately 1 second.



**Figure 2.5: Smart Key Display**

Using SMART Key to program the G1030S instrument:

The SMART Key will save the user some time in the instance of programming the same test for several steps. For example, only needing to change the scanner configuration (switching the high or low connection to Channels 1-8).

Program Test in Step 1

Run Test.

Program Remaining Steps


1. Turn ON Smart Key
2. Press [UP] to go to Step 2
3. Enter each parameter as normal but now selections are limited to the last 10 tests run.
4. Program all steps the same (cannot set scanners with SMART Key ON).
5. Turn SMART Key OFF
6. Scroll through each Step to set Scanners {High, Low or Off (X)}.

## 2.8 PRESET Test Parameters

A number of initial parameters or default conditions may be programmed and stored as the 'power-up' conditions. On the Guardian 1000 Series instruments, this function is labeled PRESET and is accessible on the STAND BY display. Table 2-3 lists the Guardian 1000 Series PRESET test parameters including parameter range and initial (default) value.

**Table 2-3: PRESET Test Parameters**

Parameter	Range	Initial (Default) Value	Description
PASS HOLD	0.2 – 99.9 sec	0.5	Set hold time for a PASS result
STEP HOLD	0.1 – 99.9 sec/KEY	0.2	Set interval time between test steps KEY=Tester will stop after each step and display PASS/FAIL results.
JUDG. WAIT	0.1 – 99.9 sec	0.3	Set the judgment time during DC or IR test
AC-V FREQ.	50 or 60Hz	60	Set frequency for AC Hipot test
GR CONT.	ON or OFF	OFF	Set ground continuity ON or OFF
SOFT. AGC	ON or OFF	ON	Set software automatic gain control function ON or OFF
AUTO RANGE	ON or OFF	OFF	Set auto range function ON or OFF
GFI	ON or OFF	ON	Set ground fault interrupt to trip at 0.5mA
FAIL CONT.	ON or OFF	OFF	Fail continue steps
SCREEN	ON or OFF	ON	Turns display off to increase test speed
PART NO.	0-13 characters	Blank	Assign a Part Number
LOT NO.	0-13 characters	Blank	Assign a Lot Number
SERIAL NO.	0-13 characters	Blank	Assign a Serial Number



**Figure 2-6: Hold Times**

### **2.8.1 PASS HOLD**

The Pass Hold setting allows the option of programming a hold time for the PASS relay (at Remote Interface) after a single test or multiple step tests. The range for Pass Hold is 0.2 – 99.9 sec and the instrument default setting is 0.5sec. Refer to Figure 2-6.

### **2.8.2 STEP HOLD**

The Step Hold setting allows the option of programming a hold time between steps. The range for Step Hold is ON or 0.1 – 99.9seconds or KEY. The instrument default setting is 0.2sec. When Step Hold is ON, the test will stop after one step and display PASS/FAIL. Refer to Figure 2-6. If KEY is selected, the unit will stop after each step and display PASS/FAIL results.

### **2.8.3 JUDG. WAIT**

The Judgment Wait setting allows the option of programming a hold time on a DC Hipot or IR test. This allows the device to be fully charged prior to a measurement being made and then judged PASS/FAIL. The range for Judgment Wait is 0.1 – 99.9sec and the instrument default setting is 0.3sec. Refer to Figure 2-6.

### **2.8.4 AC-V FREQ.**

The AC V Frequency setting allows the option of selecting the frequency for the AC hipot test. The range of AC-V Freq. is 50 or 60Hz and the instrument default setting is 60Hz.

### **2.8.5 GR CONT.**

The G-R CONT. setting allows the option of selecting the Ground Continuity (GR) function ON or OFF. The instrument default setting is OFF.

### **2.8.6 SOFT AGC**

The Software Automatic Gain Control (SOFT AGC) setting allows the option of correcting the output voltage (ON). This is satisfactory when measuring resistors but under special circumstances when measuring large capacitive devices it is best to select Software AGC OFF. The default value is ON.

### **2.8.7 AUTO RANGE**

The Auto Range setting allows the option of using the full scale current range (ON) or using the user programmed maximum current limit (OFF). The low current range (3mA full scale) results in increased measurement resolution. The default value of Auto Range is OFF.

### **2.8.8 GFI**

The Ground Fault Interrupt (GFI) function can be programmed ON or OFF. The instrument default setting is ON. When GFI is activated, the ground fault interrupt circuit is set to trip at 0.5mA.

### **2.8.9 FAIL CONT**

FAIL CONTINUE STEPS function can be programmed ON or OFF. The default setting is OFF. This selection determines if the unit will stop testing or proceed to the next test on fail during a multi-step test. When ON is selected if a test fails, then the instrument proceeds to the next step in the program.

### **2.8.10 SCREEN**

The SCREEN function disables the display while testing. It can be set to ON or OFF. When set to ON, the display is blank and the test time is increased by approximately 100millisec. The pass/fail LED indicators and DANGER LED are operational and will show test resulting addition to the Remote I/O interface.

### **2.8.11 PART NO.**

The PART NUMBER function allows the operator to assign a part number to the device under test. The part number can be made up of 0-13 alpha or numeric characters.

### **2.8.12 LOT NO.**

The LOT NUMBER function allows the operator to assign a lot number to the device under test. The lot number can be made up of 0-13 alpha or numeric characters.

### **2.8.13 SERIAL NO.**

The SERIAL NUMBER function allows the operator to assign a serial number to the device under test. The serial number can be made up of 0-13 alpha or numeric characters.

## 2.9 Storing a Test Setup

To store the previous example of the programmed 3-step test, put the instrument in 'STAND BY' status and press [F3] = MENU to access the memory function.

In MENU with the highlighted box around **MEMORY**, press [F3] = SELECT to enter the memory function.

"STAND BY" or "Power-Up" Display	STEP 1/3      AC	LOW :    OFF	PROGRAM	F1	To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.
	1.250kV	ARC :    OFF	PRESET	F2	
15.00mA	RAMP:   OFF	MENU	F3		
3.0s	REAL:   OFF	MORE..	F4		
	SCAN :   1 2 3 4 5 6 7 8 X X X X X X X X				
	STAND BY   RMT   LOCK   OFST   ERR				

"MENU"	1 <b>MEMORY</b>	UP	F1	To access memory function  To return to "STAND BY"
	2   SYSTEM	DOWN	F2	
	3   OPTION	SELECT	F3	
	4   CALIBRATION	EXIT	F4	
	5   KEY LOCK			
	SELECT FUNC.   RMT   LOCK   OFST   ERR			

"MEMORY"	1   (0)	STORE	F1
	2   (0)	RECALL	F2
	3   (0)	DELETE	F3
	4   (0)	EXIT	F4
	5   (0)		
	SELECT FUNC.   RMT   LOCK   OFST   ERR		

Press [F1] = STORE to access the store function. Press [F2] = DOWN to move highlighted box to the memory location (1-99) in which you wish to store this test setup. Press [F3] = SELECT to accept location number.

"MEMORY"	1   (0)	STORE	F1	To access store function for memory locations 1-99
	2   (0)	RECALL	F2	
	3   (0)	DELETE	F3	
	4   (0)	EXIT	F4	
	5   (0)			
	SELECT FUNC.   RMT   LOCK   OFST   ERR			

"STORE"	1   (0)	UP	F1	To select highlighted memory location and store previously programmed test setup
	2   (0)	DOWN	F2	
	3   (0)	SELECT	F3	
	4   (0)	RETURN	F4	
	5   (0)			
	SELECT MEMORY   RMT   LOCK   OFST   ERR			

### NOTE:

With the front panel locked and lock recall OFF, the recall of memory locations can be performed directly from the STAND BY menu in place of [F1].

Press [F1] = UP (and/or [F2] = DOWN) to enter an alpha/numerical tag/name for this test step. Press [F3] = ENTER after each digit to accept that digit and move on to the next. The tag can be up to 17 characters. When finished entering the numerical tag, press [F3] = ENTER two times. The display will prompt: STORE? Press [F1] = YES to accept storage or [F2] = NO to reject storage. Press [F4] = EXIT two times to return to "STAND BY" status.

"STORE"	1	(0)				UP	F1	To select highlighted memory location and store previously programmed test setup
	2	(0)				DOWN	F2	
	3	(0)				SELECT	F3	
	4	(0)				RETURN	F4	
		SELECT MEMORY		RMT	LOCK	OFST	ERR	

"I.D. LOCATION"	1	(0)	222			UP	F1	To place a numerical identification (1-22 digits) on the selected memory location	
	2	(0)				DOWN	F2		
	3	(0)				ENTER	F3		To accept numerical digit and move on to next digit. <b>Press [F3] = ENTER twice when finished identifying memory location</b>
	4	(0)				EXIT	F4		
		SELECT CHAR.		RMT	LOCK	OFST	ERR		

"EXIT"	1	(0)	222			YES	F1	To store test setup. <b>Returns to "MEMORY" Display. Press [F4] = EXIT to return to "MENU"</b>
	2	(0)				NO	F2	
	3	(0)			STORE?		F3	
	4	(0)					F4	
		SELECT CHAR.		RMT	LOCK	OFST	ERR	

The MEMORY RECALL and DELETE functions work the same way as STORE. When the instrument returns to STAND BY status there will be a tag "Mxx" in the upper right hand corner of the display to indicate which memory location is in use (displayed) as shown in Figure 2-7.

"STAND BY" Display with Memory ID	M01	STEP 1/3	AC	LOW :	OFF	PROGRAM	F1	To view/change system parameters: memory, system, option, calibration, key lock, password, error, & about.
		1.250kV		ARC :	OFF	PRESET	F2	
		15.00mA		RAMP:	OFF	MENU	F3	
		3.0s		REAL:	OFF	MORE..	F4	
		STAND BY		RMT	LOCK	OFST	ERR	
				SCAN :	1 2 3 4 5 6 7 8			
					X X X X X X X X			

**Figure 2-7: Memory Identification on STAND BY display**

## 2.10 Instrument Offset

The Guardian 1000 Series instrument provides automatic offset for lead and/or fixture effects. During the offset process a correction is made (subtracted out) as the result of lead leakage current and stored in instrument memory to be applied to ongoing measurements. For maximum measurement accuracy it is recommended that the OFFSET function be performed on the G1000 Series instrument after power up, any time the test parameters are changed and any time the test leads or fixture is changed.

Prior to performing the OFFSET function:

- Allow the instrument to warm up for 15 minutes.
- Connect the Test cables (or fixture) to the OUTPUT and RTN/LOW connectors.
- Program the test steps.

With the instrument in STAND BY status:

- Press [F4] = MORE
- Press [F3] = OFFSET
- Follow instructions on display: i.e.: connect OPEN across OUTPUT terminal.
- Press green [START] button.
- Wait while instrument gets OFFSET value.
- The **OFST** block at the bottom of the display is now highlighted (back lit).
- Press [F4] = MORE to return to STAND BY status.

- **OR**

To undo the OFFSET function:

- Press [F3] = OFFSET
- Follow prompt on display: “Turn off the offset function?”
- Press [F3] = ENTER to turn **off** OFFSET function.
- The **OFST** block at the bottom of the display is **not** highlighted now.

The following formulas apply to the offset function:

For Total Offset Current  $\leq 100\mu\text{A}$ :

$$\text{Display Current} = \sqrt{(\text{Measured total current})^2 - (\text{Offset total current})^2}$$

For Real Current & Total Current  $> 100\mu\text{A}$ :

$$\text{Display Current} = (\text{Measured real current}) - (\text{Offset real current})$$



# OFFSET Function

There is no offset in IR test mode. Using the pre-programmed example from paragraphs 2.4-2.6 of the AC, DC and IR 3-step test the resultant error and correction is illustrated herein.

"STAND BY"  
Display  
with  
Memory ID

M01	STEP 1/3	AC	LOW :	OFF		PROGRAM	F1
			ARC :	OFF		PRESET	F2
			RAMP:	OFF		MENU	F3
			REAL:	OFF		MORE..	F4
			SCAN :	1 2 3 4 5 6 7 8			
				XXXXXXX			

◀ To access OFFSET function.

Test  
Setups

VOLTAGE MEASURE REAL							F1
1	AC	1.250 kV	15.00 mA	-----		UP	F1
2	DC	2.500 kV	0.500 mA	-----		DOWN	F2
3	IR	0.500 kV	2.50 MΩ	-----		OFFSET	F3
						MORE..	F4

◀ To enter OFFSET function.  
To return to STAND BY status

GET  
OFFSET

1. Please open the HV output terminal.

2. No offset in IR mode.

PRESS TEST KEY TO GET OFFSET..

STAND BY	RMT	LOCK	OFST	ERR	EXIT		F1
							F2
							F3
							F4

START  
◀ To GET OFFSET values  
To return to STAND BY status

OFFSET  
VALUES

There is no OFFSET for an IR Test so **FAIL** LED is **ON**. Press red **[STOP]** button to continue.

VOLTAGE MEASURE REAL							F1
1	AC	1.249 kV	0.08 mA	-----	P	UP	F1
2	DC	2.501 kV	0.000 mA	-----	P	DOWN	F2
3	IR	0.000 kV	0.0 MΩ	-----		OFFSET	F3
						MORE..	F4

ERROR!  
Press [F4] to return to STAND BY.  
Press [F1] = PROGRAM  
Press [F2] = MORE  
Press [F3] = DOWN to get to Step 3 = IR Test  
Press [F1] = DELETE to delete IR Test  
Press [F4] = MORE then [F4] = EXIT to return to STAND BY  
Press [F4] = MORE to access OFFSET for AC & DC Tests  
Press [F3] = OFFSET to enter OFFSET function  
Press [START] to get OFFSET Values

STOP  
◀

VOLTAGE MEASURE REAL							F1
1	AC	1.249 kV	0.08 mA	-----	P	UP	F1
2	DC	2.501 kV	0.000 mA	-----	P	DOWN	F2
						OFFSET	F3
						MORE..	F4


Press two times to return to STAND BY status

Operation

Page 49 of 109


## 2.11 Connection to Device under Test

Figure 2-8 illustrates the connection of the Guardian 1000 Series unit to a single DUT using the S02 1-meter HV cable set that comes standard with the instrument. The custom white banana plug/red alligator clip is connected between the OUTPUT terminal on the G1000 Series unit and the high side of the device under test. The black banana plug/alligator clip is connected between the RTN/LOW terminal on the G1000 Series unit to the low side of the DUT.



**Figure 2-8: S02 Cable Connection**

Figure 2-9 illustrates the connection of the Guardian 1000 Series unit to multiple devices for a SCAN test. The custom white banana plug/white wires are connected between the scan channels (CH1-8) designated as H (high) and the high side of the device under test. The black banana plug/alligator clip is connected between the RTN/LOW terminal on the G1000 Series unit to a common ground on the test fixture.



**Figure 2-9: Scan Cable Connection**

With the test fixture as shown in Figure 2-9, Channels 1, 3, 5 & 7 are designated H (high) and a common ground is connected between the RTN/LOW terminal on the G1000 unit and ground on the test fixture. In this case the Channels 2, 4, 6 & 8 would be designated X (not used). Another configuration for the scan test illustrated in Figure 2-9 is to assign Channels 2, 4, 6 & 8 as L (low) and connect a custom white banana plug between the channel and the low side of each of the four DUTs.

Refer to paragraphs 3.6 through 3.11 for the description and illustration of the connection of several QuadTech accessories to the Guardian 1000 Series instrument.

## 2.12 Measurement Procedure

Before a measurement is made verify the following:

1. Guardian 1000 Series instrument [POWER] ON.
2. 15-minute warm-up.
3. Test parameters programmed and shown on STAND BY display.
4. Test cables or fixture connected.
5. Offset Function initiated.
6. Device under test connected.

The operator has the option of performing a test at power-up conditions (test conditions at which the instrument was last powered down) or recalling one of 99 stored test setups. Refer to paragraphs 2.4 – 2.8 for test programming and storage/recall instructions.

### To initiate a test:

- Press [STOP] to make sure instrument is in STAND BY status.
- Press [START]. DANGER led flashes. Status window shows UNDER TEST.
- The test voltage is shut **off** when all test steps are completed,
- **OR** when a test result is judged a FAIL per programmed test limits,
- **OR** when the [STOP] button is pressed.
- Press [STOP] at any time to terminate the output voltage and stop the test.

The Guardian 1000 Series instrument judges the measurement value as GOOD or NO GOOD. A GOOD judgment means the DUT passed all programmed steps. Upon completion of the test the output voltage is terminated and the display shows PASS. The rear panel PASS signal is functional and the buzzer sounds (if not turned OFF in SYSTEM parameters under MENU).

If the measurement value of the test (or any one step of the test) is abnormal, the DUT is judged as NO GOOD, the display will show FAIL and the buzzer will sound until the [STOP] button is pressed. Press [STOP] at any time to terminate the output voltage and stop the test.

## Error Messages (FAIL result)

When the measurement value was judged NO GOOD and FAIL is shown on the display, an error message denoting the test result will be shown on the display also. Table 2-4 lists the possible error messages for a NO GOOD/FAIL judgment.

**Table 2-4: Error Messages**

Error Message	Description
HI	Measured value (current or resistance) is over the programmed high limit.
HI	Unit's output voltage is less than $(V_{PROGRAM} * 0.9) - 10V$
LO	Measured value (current or resistance) is below the programmed low limit.
ARC	Current arc is over the programmed high limit.
IO	Hardware failure: cannot detect test signal.
CHECK LOW	Charging current is over the low limit.
ADV OVER	Voltage/Current reading is greater than the allowable # of digits.
ADI OVER	Current/Resistance reading is greater than the allowable # of digits.
GR CONT.	Ground Continuity is No Good.
GFI NG	Ground Fault Interrupt is No Good.
AC REAL HI	Measured Real Current value is over the programmed high limit.

## 2.13 MENU Parameters

With the Guardian 1000 Series instrument in STAND BY status, press [F3] = MENU to access programmable instrument parameters. The MENU display contains the Memory, System, Option, Calibration, Key Lock, Change Password, Error Log and About functions. Table 2-5 lists these functions with description and default values.

**Table 2-5: MENU Parameters**

MENU #	Parameter	Function
1	MEMORY	Store, Recall or Delete a test setup from instrument memory
2	SYSTEM	Change display contrast Change beeper volume
3	OPTION	Change RS232 settings Change IEEE-488 address Change Print Options
4	CALIBRATION	Enter instrument calibration routine Qualified service personnel only.
5	KEY LOCK	Lock out front panel program access.
6	CHANGE PASSWORD	Change key lock (user) password.
7	ERROR LOG	View status of error queue.
8	PRINT PROGRAM	Prints programmed test setup
9	ABOUT	Instrument Information Manufacturer, software version, etc

### 2.13.1 MEMORY

Within the MEMORY function is the ability to STORE, RECALL or DELETE test setups to and from instrument memory. There are 99 memory locations available that may contain 1-99 steps each. A caution here: instrument memory contains 500 slots; programming 99 steps and storing that into one memory location will bog down the instrument tremendously. It is wiser to program a smaller amount of test steps into more single memory locations; i.e. a 10-step test in location #1, a 5-step test in location #2, a 3-step test in location #3, etc. Then recall the specific memory location when that set of tests is needed.

### 2.13.2 SYSTEM


Within the SYSTEM function are two programmable parameters: contrast and beeper volume. The contrast parameter adjusts the brightness of the LCD display. The range is 1-16 with 16 being the darkest. The initial setting is 7. The beeper volume can be adjusted from low (soft) to medium (moderate) to high (loud) or it can be turned OFF. The initial setting is high (loud).

### 2.13.3 OPTION

Within the OPTION function are three programmable parameters: RS232, IEEE-488 and Print(er). Within the RS232 function there are three programmable parameters: baud rate, parity and flow control. The baud rate is adjustable as 300, 600, 1200, 2400 4800, 9600 or 19200 bps. The initial setting is 9600. Refer to paragraph 3.2.2 for instructions on changing the RS232 parameters.

Within the IEEE-488 function there is one programmable function: GPIB address. The range for the IEEE-488 address is 0-30 and the initial instrument setting is 3.

Within the Print function there are seven programmable Parameters: Pass, Fail, Part No., Lot No., Serial No., Test Data, and Result. These parameters can be set to ON or OFF. The initial setting is OFF.



**Figure 2-10: Print Option Menu**

## **Print Option Detail**

### **Auto Print**

These two functions are used to determine when print data is desired. Both Pass and Fail can be turned ON to obtain data from all tests.

#### **Pass**

When selected ON, the G1000 will send data to the printer when the test result is a Pass.

#### **Fail**

When selected ON, the G1000 will send data to the printer when the test result is a Fail.

#### **F. Feed**

When selected ON, the printer paper will automatically form feed at the end of the print out. This is used when one test result is desired per a page. If the printer is being used to log data and multiple tests are desired per a page, F. Feed should be set to OFF.

### **Print Data**

These functions are used to determine what data is to be printed.

#### **Part No.**

When selected ON, the part number entered in the Preset section will print.

#### **Lot No.**

When selected ON, the lot number entered in the Preset section will print

#### **Serial No.**

When selected ON, the serial number entered in the Preset section will print

#### **Test Data**

When selected ON, the step #, mode, output voltage, measured current and result will print.

#### **Result**

When selected ON, the final Pass/Fail of all steps will print

Refer to paragraph “3.4 Printer Interface” for detail of print out.


## **2.13.4 CALIBRATION**

The CALIBRATION function requires a password to enter the instrument routine. Only qualified service personnel with NIST traceable standards should perform instrument calibration. Refer to paragraph 4.3 for the Guardian 1000 Series calibration procedure.

### 2.13.5 KEY LOCK

To lock out the PROGRAM and PRESET functions of the Guardian 1000 Series instrument use the KEY LOCK function in the MENU parameters. The range of KEY LOCK is ON or OFF and the initial instrument setting is OFF. To activate the KEY LOCK function:

- Instrument in STAND BY status.
- Press [F3] = MENU
- Press [F2] = DOWN until **KEY LOCK** is backlit.
- Press [F3] = SELECT
- Display prompts 'PASSWORD'
- Press [A] [A] [A] [A] [ENTER]
- **NOTE: AAAA is the default password. If password has been changed use the new password.**
- Display prompts 'RECALL LOCK: YES'
- Press [F1] = YES to select KEY LOCK ON.
- **NOTE: Selecting YES disallows the recalling of programmed tests from memory.**
- The **LOCK** block at bottom of display is backlit.
- Press [F4] = EXIT to return to STAND BY status.
- PROGRAM and PRESET are no longer visible or functional.



**Figure 2-11: Key Lock Display**

**To disable the KEY LOCK function, repeat above steps.**

### 2.13.6 CHANGE PASSWORD


The Guardian 1000 Series instruments have a password function for locking out the front panel so that the instrument PRESET settings and PROGRAM function are disabled. A separate password is used to perform instrument calibration. Refer to paragraph 4.3. The CHANGE PASSWORD function applies to the initial instrument password. To activate the CHANGE PASSWORD function:

- Instrument in STAND BY status.
- Press [F3] = MENU
- Press [F2] = DOWN until **CHANGE PASSWORD** is backlit.
- Press [F3] = SELECT
- Display prompts 'PASSWORD'
- Press [A] [A] [A] [A] [ENTER]
- Display prompts 'NEW PASSWORD'
- Press [B] [B] [B] [B] [ENTER]
- Display prompts 'CONFIRM'
- Press [B] [B] [B] [B] [ENTER]
- Display prompts 'CHANGE PASSWORD OK!! PRESS EXIT TO CONTINUE'.

### 2.13.7 ERROR LOG

The Guardian 1000 Series instruments have an Error Log to track communication errors when the IEEE-488 interface or RS232 interface is being used. Refer to paragraph 3.3.5 and Table 3-5 for a list of error message numbers and their respective description. When the **ERR** block on the bottom of the display is backlit, there is an error message in the queue. To view the contents of the error log:

- Instrument in STAND BY status.
- Press [F3] = MENU
- Press [F2] = DOWN until **ERROR LOG** is backlit.
- Press [F3] = SELECT
- Display lists the contents of the Error Log.



**Figure 2-12: ERROR LOG Display**


The queue will clear itself once the log has been viewed.



### 2.13.8 PRINT PROGRAM

When the G38 printer card is installed in the G1000 Series instrument, then this option can be selected. When F3 “Select” is pressed, the Guardian 1000 Series instrument will send the programmed test setup to the printer. Refer to paragraph 3.4 “Printer Interface” for detail of the print out.

- Instrument in STAND BY status.
- Press [F3] = MENU
- Press [F2] = DOWN until **PRINT PROGRAM** is backlit.
- Press [F3] = SELECT
- Display lists the Print Option Menu. Refer to paragraph 2.13.3.




**Figure 2-13: Select Print Program**

### 2.13.9 ABOUT

The Guardian 1000 Series instruments have a parameter labeled ‘About’. This parameter lists the instrument manufacturer, software version and date. To view the contents of ABOUT:

- Instrument in STAND BY status.
- Press [F3] = MENU
- Press [F2] = DOWN until **ABOUT** is backlit.
- Press [F3] = SELECT
- Display lists the contents of ABOUT.



**Figure 2-14: ABOUT Display**



---

## Section 3: Interface


---

### 3.1 Remote

A 9-pin D-Series remote control connector is located on the rear panel of the Guardian 1000 Series instrument. There is a black 11 screw terminal strip for the remote output signals: UNDER TEST, PASS & FAIL and the remote inputs: START, RESET, COM AND INTERLOCK.

Inputs require a contact closure and outputs provide a contact closure. Figure 3-1 illustrates the Remote terminal strip connector and 9-pin D-Series connector.


Before connecting the instrument to its power source, the interlock function on the rear panel remote connector (terminal strip) must be properly utilized. This is an important safety feature for the protection of the operator. When the INTERLOCK jumper is removed, there is **no** high voltage at the OUTPUT. Therefore, to initiate a test make sure the interlock jumper is in place.




**Figure 3-1: Guardian 1000 Series Remote Connectors**

The Guardian 1000 Series instrument has three output signals on the rear panel. When the OUTPUT switch is in open (switch open), the UNDER TEST relay is closed during a test. The PASS relay is closed when the DUT is judged GOOD. The FAIL relay is closed when the DUT is judged NO GOOD. These relays are rated for voltage up to 115VAC and current <0.3A. When the OUTPUT switch is in the battery signal position, 24VDC 100mA output is present on both UNDER TEST terminals when the unit is in STAND BY mode. When the unit is testing, 24VDC is present only on the bottom (#7) UNDER TEST terminal.

Figures 3-2 and 3-3 illustrate possible remote control connections to the Guardian 1000 Series terminal strip. Use extreme care when using a remote control connection as the High Voltage Output is being turned ON and OFF with an external signal.




**Figure 3-2: Single Control of START or RESET**



**Figure 3-3: Continuous Control of RESET**

START and RESET terminals have unregulated 24VDC present. To initiate a test connect the START and COM terminals. To terminate a test connect the RESET and COM terminals.

Figure 3-4 illustrates the timing diagram for the Guardian 1000 Series instruments under a PASS condition and a FAIL condition.



**Figure 3-4: Guardian 1000 Series Timing Diagram**


## 3.2 RS232 Interface

### 3.2.1 Pin Configuration

The Guardian 1000 Series instruments all come standard with an RS232 Interface for remote operation. Connection is through the silver 9-pin connector labeled 'RS232' on the rear panel of the Guardian 1000 Series instrument. Figure 3-5 illustrates the designation of the pins on the RS232 connector. The connection cable must be a 'straight through' cable for the G1000 series unit to communicate.

#### NOTE

When the RS232 Interface and the IEEE-488 Interface are both installed in a Guardian 1000 Series instrument, only **one** of the two interfaces may be activated at a time.



**Figure 3-5: RS232 Pin Configuration**

When the **ERR** box is backlit on the bottom of the display, there are error messages in the queue. Refer to paragraph 3.3.5, Table 3-7 for explanation of error messages.

### 3.2.2 RS232 Specifications

Data Bits:	8
Stop Bits:	1
Parity:	None, Odd, Even
Baud Rate:	0.3/0.6/1.2/2.4/4.8/9.6/19.2(k) Software selectable
EOS:	LF or CR + LF
Echo:	Off

#### Selecting the Baud Rate, Parity and Flow Control

Setting the Baud Rate is done in the OPTION function under MENU settings:

- From the STAND BY display, press [F3] = MENU.
- Press [F2] = DOWN two times to highlight **OPTION**.
- Press [F3] = SELECT to enter OPTION function.
- Press [F3] = SELECT to select RS232 function.
- Display shows “1. BAUD RATE : **9600**” with rate highlighted.
- Press [F1] = UP to select baud rate.
- Press [F4] to EXIT
- **OR**
- Press [F3] = ENTER to change the parity.
- Display shows “2. PARITY : **ODD**” with parity bit highlighted.
- Press [F1] = UP to select parity.
- Press [F4] to EXIT
- **OR**
- Press [F3] = ENTER to change the flow control.
- Display shows “3. FLOW CTRL. : **NONE**” with parity bit highlighted.
- Press [F1] = UP to select software flow control or no flow control.
- Press [F4] to EXIT

The software flow control allows the RS232 interface to control the intake of data so the amount of data will not overload the I/O. Flow control of an RS232 interface is similar to DAV (Data is available and valid on data lines) on an IEEE interface.

### 3.2.3 RS232 Commands

The command set for the RS232 interface is the same as the IEEE-488 interface command set listed in paragraphs 3.3.3 through 3.3.5 of this instruction manual.

**NOTE**  
**CR + LF are necessary end codes for the RS232 commands.**

There are additional RS232 only commands on the following page.

## Additional RS232 Commands

Some commands for RS232 use only are listed here. These commands follow the SCPI version 1999.0.

```
:SYSTem:LOCK:RELease ==> Change statue to local, as GPIB Go To Local.  
:SYSTem:LOCK:REQuest? ==> Change statue to Remote, return '1' if successful.  
:SYSTem:LOCK:OWNer? ==> Query the statue.  
:SYSTem:LOCK <Boolean> ==> As GPIB Local Lockout.  
:SYSTem:LOCK? ==> Query the Key Lock status.
```

### 3.2.4 Sample QuickBasic Program

```
REM Guardian 1000 series RS232 example program  
REM Created using Quick Basic  
  
REM open serial port as device 1  
OPEN "COM2:9600,N,8,1,RS," FOR RANDOM AS #1  
CLS  
  
REM Send STOP command to device  
PRINT #1, "SOURce:SAFEty:STOP"; CHR$(13); CHR$(10)  
  
REM Ask device how many steps are programmed  
PRINT #1, "SOURce:SAFEty:SNUMBer?"; CHR$(13); CHR$(10)  
  
INPUT #1, SNUMBer  
REM Loop to delete any programmed steps  
IF SNUMBer > 0 THEN  
  FOR I = SNUMBer TO 0 STEP -1  
    IF I = 0 GOTO Program  
    temp$ = INPUT$(LOC(1), 1)  
    PRINT #1, "SOURce:SAFEty:STEP", I, ":DELeTe"; CHR$(13); CHR$(10)  
  NEXT I  
END IF  
  
Program:  
PRINT "Programing G1000"  
REM Program STEP 1 for AC HIPOT  
REM Program AC test voltage for 1000 V  
PRINT #1, "SOURce:SAFEty:STEP1:AC:LEVel 1000"; CHR$(13); CHR$(10)  
  
REM Program high current limit for 6 mA  
PRINT #1, "SOURce:SAFEty:STEP1:AC:LIMit:HIGH 0.006"; CHR$(13); CHR$(10)  
  
REM Program test time for 5 seconds  
PRINT #1, "SOURce:SAFEty:STEP1:AC:TIME:TEST 5.0"; CHR$(13); CHR$(10)  
  
REM Program Low current limit off  
PRINT #1, "SOURce:SAFEty:STEP1:AC:LIMit:LOW 0.0000"; CHR$(13); CHR$(10)  
  
REM Program ARC limit for 0.9 mA  
PRINT #1, "SOURce:SAFEty:STEP1:AC:LIMit:ARC:LEVel 0.0009"; CHR$(13); CHR$(10)  
  
REM Program ramp time for 4 seconds  
PRINT #1, "SOURce:SAFEty:STEP1:AC:TIME:RAMP 4.0"; CHR$(13); CHR$(10)  
  
REM Program Real Current limit for 3 mA  
PRINT #1, "SOURce:SAFEty:STEP1:AC:LIMit:REAL 0.0030"; CHR$(13); CHR$(10)  
  
REM Program STEP 2 for DC HIPOT  
REM Program DC test voltage for 1000 V  
PRINT #1, "SOURce:SAFEty:STEP2:DC:LEVel 1000"; CHR$(13); CHR$(10)  
  
REM Program high current limit for 7 mA  
PRINT #1, "SOURce:SAFEty:STEP2:DC:LIMIT:HIGH 7e-3"; CHR$(13); CHR$(10)
```



```

REM Program test time for 4 seconds
PRINT #1, "SOURce:SAFEty:STEP2:DC:TIME 4"; CHR$(13); CHR$(10)

REM Program low current limit for off
PRINT #1, "SOURce:SAFEty:STEP2:DC:LIMit:LOW 0.0000"; CHR$(13); CHR$(10)

REM Program Arc limit for 1 mA
PRINT #1, "SOURce:SAFEty:STEP2:DC:limit:ARC:LEVel 0.001"; CHR$(13); CHR$(10)

REM Program ramp time for 2 seconds
PRINT #1, "SOURce:SAFEty:STEP2:DC:TIME:RAMP 2.0"; CHR$(13); CHR$(10)

REM Program STEP 3 for IR Test

REM Program IR DC voltage for 100 V
PRINT #1, "SOURce:SAFEty:STEP3:IR:LEVel 100"; CHR$(13); CHR$(10)

REM Program low resistance limit for .4 Mohm
PRINT #1, "SOURce:SAFEty:STEP3:IR:LIMIT:LOW 400000"; CHR$(13); CHR$(10)

REM Program test time for 5 sec
PRINT #1, "SOURce:SAFEty:STEP3:IR:TIME 5"; CHR$(13); CHR$(10)

REM Program high resistance limit off
PRINT #1, "SOURce:SAFEty:STEP3:IR:LIMit:HIGH 0.000"; CHR$(13); CHR$(10)

REM Program ramp time off
PRINT #1, "SOURce:SAFEty:STEP3:IR:TIME:RAMP 0.0"; CHR$(13); CHR$(10)

PRINT #1, "SOURce:SAFEty:SNUMBer?"; CHR$(13); CHR$(10)

INPUT #1, STEPNUM%
CLS
REM Start TEST
PRINT #1, "SOURce:SAFEty:STARt"; CHR$(13); CHR$(10)
PRINT " Testing"
REM Check status of the test
complete$ = "0"
WHILE complete$ <> "1"
  PRINT #1, "SOURce:SAFEty:RESult:COMplete?"; CHR$(13); CHR$(10)
  INPUT #1, complete$
  CLS
  IF complete$ = "1" THEN
    PRINT #1, "SOURce:SAFEty:STOP"; CHR$(13); CHR$(10)

    REM Print Output voltage for each step
    PRINT #1, "SAFEty:RESult:ALL:OMET?"; CHR$(13); CHR$(10)

    FOR j = 1 TO STEPNUM%
      INPUT #1, RESult$
      PRINT "Measured Output Voltage:"
      PRINT "step", j, ":", RESult$

    NEXT j
    PRINT
    PRINT "*****"
    REM Print Measured result for each step
    PRINT #1, "SAFEty:RESult:ALL:MMET?"; CHR$(13); CHR$(10)
    FOR j = 1 TO STEPNUM%
      INPUT #1, RESult$
      PRINT "Measured Result:"
      PRINT "step", j, ":", RESult$
    NEXT j
  END IF
WEND


PRINT #1, "SOURce:SAFEty:STOP"; CHR$(13); CHR$(10)
CLOSE #1
END

```

### 3.3 IEEE-488 Interface

#### 3.3.1 Pin Configuration

The Guardian 1000 Series instrument has an optional IEEE-488 interface that is factory installed when the instrument is ordered. Connection is through the blue 24-pin connector labeled 'GPIB' on the rear panel of the Guardian 1000 Series instrument. This interface can be used to connect a system containing a number of instruments and a controller in which each meets IEEE Standard 488.2 (Standard Digital Interface for Programmable Instrumentation). Figure 3-6 illustrates the designations of the pins on the IEEE-488 connector.



**Figure 3-6: IEEE-488 Interface Pin Configuration**

Table 3-1 lists the IEEE-488 Interface pin designations by pin number, signal name and pin function.

**Table 3-1: IEEE-488 Interface Pin Designations**

<b>Signal Name</b>	<b>Pin Number</b>	<b>Function</b>
DAV	6	Low State: “Data is Available” and valid on DI01 through DI08
NRFD	7	Low State: At least one Listener on the bus is “Not Ready For Data”
NDAC	8	Low State: At least one Listener on the bus is “Not Accepting Data”
ATN	11	“Attention” specifies 1 of 2 uses for the DI01 through DI08 lines: Low State: Controller command messages High State: Data bytes from the Talker device
IFC	9	“Interface Clear” Low State: Returns portion of interface system to a known quiescent state
SRQ	10	“Service Request” Low State: A Talker or Listener signals (to the controller) need for attention in the midst of the current sequence of events.
REN	17	“Remote Enable” Low State: Enables each device to enter remote mode when addressed to listen. High State: All devices revert to Local control.
EOI	5	“End of Identify” If ATN is in HIGH state, then EOI LOW state indicates the end of a multiple-byte data transfer sequence. If ATN is in LOW state, then EOI LOW state indicates a parallel poll.
DI01	1	The 8-Line Data Bus.  If ATN is in LOW state, then the bus conveys interface messages.  If ATN is in HIGH state, then the bus conveys device-dependent messages. (Example: carries remote control commands from the controller or from a talker device)
DI02	2	
DI03	3	
DI04	4	
DI05	13	
DI06	14	
DI07	15	
DI08	16	

### 3.3.2 IEEE-488 Interface Codes and Messages

The IEEE-488 (GPIB) address is defined under the MAIN MENU in the OPTION MENU. Press [MAIN MENU] then the numerical key [2] to enter the OPTION MENU. Press function key [F2] to enter the GPIB SETUP menu. To select a new IEEE-488 address, use the function keys

The Guardian 1000 Series unit is in a remote control status when the **RMT** block on the bottom right hand side of display is backlit.

To switch to Local from Remote press the [LOCAL] key, disabled by LLO message.

Table 3-2 defines the IEEE-488 interface codes and their function. Table 3-3 defines the IEEE-488 interface messages and their function.

**Table 3-2: IEEE-488 Interface Functions**

Code	Function
SH1	Source Handshake
AH1	Acceptor Handshake
T4	Basic Talker Function
L4	Basic Listener Function
SR1	Service Request Function
RL1	All Remote/Local Function
PP0	No Parallel Poll Function
DC1	All Device Clear Function
DT0	Device Trigger Function
C0	No Controller Functions

**Table 3-3: IEEE-488 Interface Messages**

Interface Message	Function	Description
GTL	Go To Local	Switch unit to local
SDC	Selected Device Clear	Reset the unit
LLO	Local Lockout	Disables [LOCAL] switch to local
IFC	Interface Clear	Reset IEEE-488 bus interface

### 3.3.3 IEEE-488 Interface Commands

The interface function is controlled by ASCII commands that include:

{[command + parameter] ; [command + parameter] + ending code}

The maximum string length is consists of 1024 characters. It is not necessary to input any sign or space between the command and parameter. Any two commands can be connected by "," and [Ending Code]. Ending Code can be any type in Table 3-4.

**Table 3-4: IEEE-488 Interface Ending Codes**

Ending Code
LF
CR + LF
EOI
LF + EOI
CR + LF + EOI

**NOTE**  
The data can be sent out by the IEEE-488 interface to achieve transfer function. The data command is {string message + ending code}. The ending codes are listed in Table 3-4.

**NOTE**  
CR + LF are necessary ending codes for the RS232 Commands.

#### 3.3.3.1 IEEE-488 Register Assignments


Table 3-5 lists the bit assignments for the Summary and Event registers. The configuration of these registers is illustrated in Figure 3-7.

**Table 3-5: Summary Status & Event Status Registers**

Summary Status Register			Event Status Register		
Bit	Decimal Value	Use	Bit	Decimal Value	Use
0	1	Not Used	0	1	Operation Complete
1	2	Has Result	1	2	Not Used
2	4	Error/Event Queue	2	4	Query Error
3	8	Not Used	3	8	Device Error (No device contact)
4	16	Message Available	4	16	Execution Error (Over Range, etc.)
5	32	Summary Standard Event Status Register	5	32	Command Error (Syntax)
6	64	Request Service	6	64	Not Used
7	128	Not Used	7	128	Power ON

### 3.3.3.2 IEEE-488 Register Configuration

Figure 3-7 illustrates the configuration of the Summary (Status), Event and Enable Registers for the Guardian 1000 Series IEEE-488 Interface.



**Figure 3-7: Guardian 1000 Series IEEE-488 Register Configuration**

**Table 3-6: IEEE-488 Commands**

<b>Command</b>	<b>Name</b>	<b>Function</b>	<b>Output Format</b>
*CLS	Clear Status	Clear standard event status register. Clear status bit group register except for bit 4 (MAV)	
*ESE	Event Status Enable	Enable standard event status register value.	0 – 255
*ESE?	Event Status Enable	Query standard event status of device enable register	0 – 255
*ESR?	Event Status Register	Query standard event register value of device. After this command, the standard register is cleared to 0.	0 – 255
*SRE	Service Request Enable	Enable service request register value.	0 – 255
*SRE?	Service Request Enable	Query/Read service request register value.	0 – 255
*STB?	Status Byte Register	Query/Read status byte register value	0 – 255
*OPC	Operation Complete	Operation is complete.	
*OPC?	Operation Complete	Query operation complete.	1
*PSC 0   1	Power On	Clear status of Power On	
*PSC?	Power On	Query Power On.	1 or 0
*RST	Reset	Reset Device.	
*IDN?	Identification	Query/Read basic device data. (A comma separates the identification fields.)	4 ID: Manufacturer, Device Model, Serial Number, Firmware Version
*SAV	Save	Save current status to memory.	1 – 99
*RCL	Recall	Recall saved status from memory.	1 – 99

### 3.3.4 IEEE-488 & SCPI Command Summary

The SCPI (Standard Commands for Programmable Instruments) parameter syntax format is listed on the following pages. To illustrate the order of precedence the entire command list is scrolled through. The dual arrow symbol “<>” denotes the defined parameter is a standard SCPI command. The symbol “<numerical value>” denotes the metric system value. The symbol “<boolean>” denotes the Boolean equation data and its value is 0 or 1. The vertical line “|” denotes the OR parameter. When sending the G1000 series unit a decimal number it is necessary to have a zero before the decimal point. Example: DC: LIMit: HIGH: 0.004

#### **:SYSTem**

##### **:VERSion?**

Command: :SYSTEM : VERSion?

This command queries the SCPI version of this device.

##### **:ERRor**

###### **:[NEXT]?**

Command: :SYSTem : ERRor : [NEXT]?

This command reads the message in the Error Queue.

Refer to paragraph 3.3.5 for Error Messages

##### **:LOCK**

###### **:REQuest?1**

Command: :SYSTem : LOCK : REQuest?1

This command locks the front panel (disables start from front panel).

###### **:RELease**

Command: :SYSTem : LOCK : RELease

This command unlocks the front panel (enables start from front panel).

##### **:KLOCK1**

Command: :SYSTem : KLOCK1

This command locks local controls.

#### **:MEMory**

##### **:STATe**

**[:NAME] <name>**

Command: :MEMory : STATe : DEFine: NAME: LOCATION

This command saves setup with name and location.

##### **:DELeTe**

**[:NAME] <name>**

Command: :MEMory : DELeTe : NAME

This command deletes the data in main memory under defined name.

##### **:FREE**

###### **:STEP?**

Command: MEMory : FREE : STEP?

This command queries the next free step in main memory.

###### **:PRESet?**

Command: :MEMory : FREE : PRESet?

This command queries the next free preset number in main memory.



**[:SOURCE]**

**:SAFEty**

**:STARt**

Command: :SOURCE : SAFEty : STARt

This command starts the test.

**:OFFSet GET | OFF**

Command: :SOURCE : SAFEty : STARt : OFFSet GET

This command gets the offset value.

Command: : SOURCE : SAFEty : STARt : OFFSet OFF

This command turns the offset function off.

**:OFFSet?**

Command: : SOURCE : SAFEty : STARt : OFFSet?

This command queries if the offset function is ON or OFF.

**:STOP**

Command: :SOURCE : SAFEty : STOP

This command stops the test.

**:STATus?**

Command: :SOURCE : SAFEty : STATus?

This command queries the execution status of the current device under test.

The return character data is RUNNING | STOPPED

**:RESult**

**:ALL**

**[:JUDGment]?**

Command: :SOURCE : SAFEty : RESult : ALL : JUDGment?

This command queries all the judgment results.

The return format is:

PASS	74	116
USER STOP	71	113
CAN NOT TEST	72	114
TESTING	73	115
STOP	70	112

	AC MODE		DC MODE		IR MODE	
	HEX	DEC	HEX	DEC	HEX	DEC
HI	11	17	21	33	31	49
LO	12	18	22	34	32	50
ARC	13	19	23	35	33	---
IO	14	20	24	36	34	52
Check Low	---	---	25	37	---	---
ADV OVER	16	22	26	38	36	54
ADI OVER	17	23	27	39	37	55
REAL HIGH	1a	26	---	---	---	---
GR CONT.	78	120	78	120	78	120
GFI	79	121	79	121	79	121

**:OMETerage?**

Command: :SOURce : SAFETy : RESult : ALL : OMETerage?

This command queries all the voltage (output meter) readings for the step.

**:MMETerage?**

Command: :SOURce : SAFETy : RESult : ALL : MMETerage?

This command queries all the Measure Meter readings for the step.

**:RMETerage?**

Command: :SOURce : SAFETy : RESult : ALL : RMETerage?

This command queries all the Real Current Meter readings for the step.

**:TIME :TEST?**

Command: :SOURce : SAFETy : RESult : ALL : TIME : TEST?

This command reads back all step test times including failure times.

**:LAST :JUDGment?**

Command: :SOURce : SAFETy : RESult : LAST : JUDGment?

This command queries status while testing.

**:COMPLETED?**

Command: :SOURce : SAFETy : RESult : COMPLETE?

This command queries if all the test results are completed.

The return format is a "1" or a "0".

**:AREPort <Boolean> ON|OFF (RS232 Interface only)**

Command: :SOURce : SAFETy : RESult : AREPort

This command sets the Automatic Reporting of the test results.

**:AREPort ? (RS232 Interface only)**

Command: :SOURce : SAFETy : RESult : AREPort?

This command queries if the Automatic Reporting of test results is ON or OFF.

The return format is a "1" or a "0".

**:SNUMBER?**

Command: :SOURce : SAFETy : SNUMBER?

This command queries the step number being set in memory.

**:STEP <n>**

**:DELEte**

Command: :SOURce : SAFETy : STEP : DELEte

This command clears all setting values in selected step to the initial value.

<n> denotes the step number. Range:  $1 \leq n \leq 99$ .

**:SET?**

Command: :SOURce : SAFETy : STEP : SET?

This command queries all setting values in selected step.

**:MODE?**

Command: :SOURce : SAFETy : STEP <n> : MODE?

This command queries the test Mode of the selected step.

The return format is: ACTL | ACRL | DC | IR.

**:AC**

**[:LEVel] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : AC : LEVEL

This command sets the AC voltage level for the selected step.

<numeric value> is 50 to 5000 and the unit is volts.

**[:LEVel]?**

Command: :SOURce : SAFETy : STEP <n> : AC : LEVEL?

This command queries the AC voltage level for the selected step.

The return format is a numerical value:  $50 \leq \text{value} \leq 5000$  volts.

**:LIMit**

**[:HIGH] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : AC : LIMit : HIGH

This command sets the high current limit for the selected step.

<numeric value> is 0.001 to 30 and the unit is milliamps.

**[:HIGH]?**

Command: :SOURce : SAFETy : STEP <n> : AC : LIMit : HIGH?

This command queries the high current limit for the selected step.

**[:REAL]: HIGH <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : AC : LIMit : REAL : HIGH

This command sets the high limit for real current. Valid for AC Hipot test only.

<numeric value> is 0.001 to 30 and the unit is milliamps.

**[:REAL]?**

Command: :SOURce : SAFETy : STEP <n> : AC : LIMit : REAL : HIGH?

This command queries the high limit for the real current test.

**:LOW <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : AC : LIMit : LOW

This command sets the low current limit for the selected step.

<numeric value> is 0 to 30 and the unit is milliamps.

**:LOW?**

Command: :SOURce : SAFETy : STEP <n> : AC : LIMit : LOW?

This command queries the low current limit for the selected step.

## **:ARC**

**[:LEVel] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : AC : ARC : LEVel

This command sets the arc current limit for the selected step.

**[:LEVel]?**

Command: :SOURce : SAFETy : STEP <n> : AC : ARC : LEVel?

This command queries the arc current limit for the selected step.

## **:TIME**

**:RAMP <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : AC : TIME : RAMP

This command sets the ramp time for the selected step.

<numeric value> is 0 to 999 and the unit is seconds.

**:RAMP?**

Command: :SOURce : SAFETy : STEP <n> : AC : TIME : RAMP?

This command queries the ramp time for the selected step.

**[:TEST] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : AC : TIME : TEST

This command sets the test time for the selected step.

<numeric value> is 0 to 999 and the unit is seconds.

**[:TEST]?**

Command: :SOURce : SAFETy : STEP <n> : AC : TIME : TEST?

This command queries the test time for the selected step.

## **:CHANnel (@ <box #> (<channel list>))**

**[:HIGH] <channel list>**

Command: :SOURce : SAFETy : STEP <n> : AC : CHANnel : HIGH (@ <box #> (<channel list>))

This command sets the high scan channels for the selected step.

**[:HIGH]?**

Command: :SOURce : SAFETy : STEP <n> : AC : CHANnel : HIGH? (@ <box #> (<channel list>))

This command queries the high scan channels for the selected step.

**:LOW <channel list>**

Command: :SOURce : SAFETy : STEP <n> : AC : CHANnel : LOW (@ <box #> (<channel list>))

This command sets the low scan channels for the selected step.

**:LOW?**

Command: :SOURce : SAFETy : STEP <n> : AC : CHANnel : LOW? (@ <box #> (<channel list>))

This command queries the low scan channels for the selected step.

Example: The command :SOURce : SAFETy : STEP 1 : AC : CHANnel : HIGH (@ 1 (1:4))

Sets Channels 1 through 4 HIGH on scanner box #1 (internal scanner)

## **:DC**

**[:LEVel] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : DC : LEVEL

This command sets the DC voltage level for the selected step.

<numeric value> is 50 to 6000 and the unit is volts.

**[:LEVel]?**

Command: :SOURce : SAFETy : STEP <n> : DC : LEVEL?

This command queries the AC voltage level for the selected step.

The return format is a numerical value:  $50 \leq \text{value} \leq 6000$  volts.

## **:LIMit**

### **[:HIGH] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : DC : LIMit : HIGH

This command sets the high current limit for the selected step.

<numeric value> is 0.0001 to 10 and the unit is milliamps.

### **[:HIGH]?**

Command: :SOURce : SAFETy : STEP <n> : DC : LIMit : HIGH?

This command queries the high current limit for the selected step.

### **:LOW <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : DC : LIMit : LOW

This command sets the low current limit for the selected step.

<numeric value> is 0 to 10 and the unit is milliamps.

### **:LOW?**

Command: :SOURce : SAFETy : STEP <n> : DC : LIMit : LOW?

This command queries the low current limit for the selected step.

## **:ARC**

### **[:LEVel] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : DC : ARC : LEVel

This command sets the arc current limit for the selected step.

### **[:LEVel]?**

Command: :SOURce : SAFETy : STEP <n> : DC : ARC : LEVel?

This command queries the arc current limit for the selected step.

## **:TIME**

### **:RAMP <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : DC : TIME : RAMP

This command sets the ramp time for the selected step.

<numeric value> is 0 to 999 and the unit is seconds.

### **:RAMP?**

Command: :SOURce : SAFETy : STEP <n> : DC : TIME : RAMP?

This command queries the ramp time for the selected step.

### **[:TEST] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : DC : TIME : TEST

This command sets the test time for the selected step.

<numeric value> is 0 to 999 and the unit is seconds.

### **[:TEST]?**

Command: :SOURce : SAFETy : STEP <n> : DC : TIME : TEST?

This command queries the test time for the selected step.

**:CHANnel (@ <box #> (<channel list>))**

**[:HIGH] <channel list>**

Command: :SOURce : SAFETy : STEP <n> : DC : CHANnel : HIGH (@ <box #> (<channel list>))

This command sets the high scan channels for the selected step.

**[:HIGH]?**

Command: :SOURce : SAFETy : STEP <n> : DC : CHANnel : HIGH? (@ <box #> (<channel list>))

This command queries the high scan channels for the selected step.

**:LOW <channel list>**

Command: :SOURce : SAFETy : STEP <n> : DC : CHANnel : LOW (@ <box #> (<channel list>))

This command sets the low scan channels for the selected step.

**:LOW?**

Command: :SOURce : SAFETy : STEP <n> : DC : CHANnel : LOW? (@ <box #> (<channel list>))

This command queries the low scan channels for the selected step.

**:IR**

**[:LEVel] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : IR : LEVEL

This command sets the DC voltage level for the selected step.

<numeric value> is 50 to 1000 and the unit is volts.

**[:LEVel]?**

Command: :SOURce : SAFETy : STEP <n> : IR : LEVEL?

This command queries the AC voltage level for the selected step.

The return format is a numerical value:  $50 \leq \text{value} \leq 1000$  volts.

**:LIMit**

**[:HIGH] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : IR : LIMit : HIGH

This command sets the high resistance limit for the selected step.

<numeric value> is 0 to 50G and the unit is ohms.

**[:HIGH]?**

Command: :SOURce : SAFETy : STEP <n> : IR : LIMit : HIGH?

This command queries the high current limit for the selected step.

**:LOW <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : IR : LIMit : LOW

This command sets the low resistance limit for the selected step.

<numeric value> is 0.1 to 50000M and the unit is ohms.

**:LOW?**

Command: :SOURce : SAFETy : STEP <n> : IR : LIMit : LOW?

This command queries the low current limit for the selected step.

**:TIME**

**:RAMP <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : IR : TIME : RAMP

This command sets the ramp time for the selected step.

<numeric value> is 0 to 999 and the unit is seconds.

**:RAMP?**

Command: :SOURce : SAFETy : STEP <n> : IR : TIME : RAMP?

This command queries the ramp time for the selected step.

**[ :TEST ] <numeric value>**

Command: :SOURce : SAFETy : STEP <n> : IR : TIME : TEST

This command sets the test time for the selected step.

<numeric value> is 0 to 999 and the unit is seconds.

**[ :TEST ] ?**

Command: :SOURce : SAFETy : STEP <n> : IR : TIME : TEST?

This command queries the test time for the selected step.

**:CHANnel ( @ <box #> ( <channel list> ) )**

**[ :HIGH ] <channel list>**

Command: :SOURce : SAFETy : STEP <n> : IR : CHANnel : HIGH ( @ <box #> ( <channel list> ) )

This command sets the high scan channels for the selected step.

**[ :HIGH ] ?**

Command: :SOURce : SAFETy : STEP <n> : IR : CHANnel : HIGH? ( @ <box #> ( <channel list> ) )

This command queries the high scan channels for the selected step.

**:LOW <channel list>**

Command: :SOURce : SAFETy : STEP <n> : IR : CHANnel : LOW ( @ <box #> ( <channel list> ) )

This command sets the low scan channels for the selected step.

**:LOW ?**

Command: :SOURce : SAFETy : STEP <n> : IR : CHANnel : LOW? ( @ <box #> ( <channel list> ) )

This command queries the low scan channels for the selected step.

**:PRESet**

**:TIME**

**:PASS <numerical value>**

Command: :SOURce : SAFETy : PRESet : TIME : PASS

This command sets the time the pass relay on the remote I/O is closed when result is pass.

<numerical value> is a value between 0.2 and 99.9 and the unit is seconds.

**:PASS ?**

Command: :SOURce : SAFETy : PRESet : TIME : PASS?

This command queries the set time for the pass relay on the remote I/O to be closed.

**:STEP <numerical value> | KEY**

Command: :SOURce : SAFETy : PRESet : TIME : STEP

This command sets the interval time between steps.

<numerical value> is a value or character key between 0.1 and 99.9 seconds.

**:STEP ?**

Command: :SOURce : SAFETy : PRESet : TIME : STEP?

This command queries the interval time between tests.

**:JUDGment <numerical value>**

Command: :SOURce : SAFETy : PRESet : TIME : JUDGment

This command sets the time between measurement and judgment.

<numerical value> is a value between 0.1 and 99.9 and the unit is seconds.

**:JUDGment ?**

Command: :SOURce : SAFETy : PRESet : TIME : JUDGment?

This command queries the time between measurement and judgment.

## **:AC**

### **:FREQuency <numerical value>**

Command: :SOURce : SAFETy : PRESet : AC : FREQuency

This command sets the test frequency for AC Hipot Test.

<numeric value> is a value between 50 and 600 and the unit is Hz.

### **:FREQuency?**

Command: :SOURce : SAFETy : PRESet : AC : FREQuency?

This command queries the test frequency for the AC Hipot Test.

## **:WRANge**

### **[:AUTO] <boolean> ON | OFF**

Command: :SOURce : SAFETy : PRESet : WRANge : AUTO

This command sets the Auto Range function ON or OFF.

<boolean value> is a "1" or a "0".

### **[:AUTO]?**

Command: :SOURce : SAFETy : PRESet : WRANge : AUTO?

This command queries the status of the Auto Range function.

The return value is a "1" or a "0".

## **:AGC**

### **[:SOFTware] <boolean> ON | OFF**

Command: :SOURce : SAFETy : PRESet : AGC : SOFTware

This command sets the software Automatic Gain Control function ON or OFF.

<boolean value> is a "1" or a "0".

### **[:SOFTware]?**

Command: :SOURce : SAFETy : PRESet : AGC : SOFTware?

This command queries the status of the software Automatic Gain Control function.

The return value is a "1" or a "0".

## **:GCONtinuity <boolean> ON | OFF**

Command: :SOURce : SAFETy : PRESet : GCONtinuity

This command sets the Ground Continuity Check function ON or OFF.

<boolean value> is a "1" or a "0".

### **:GCONtinuity?**

Command: :SOURce : SAFETy : PRESet : GCONtinuity?

This command queries if the Ground Continuity Check function ON or OFF.

The return value is a "1" or a "0".

## **:TRIP**

### **[:SWITCH] OFF | ON**

Command: :SOURce : SAFETy : PRESet : TRIP : SWITCH

This command sets the Ground Fault Interrupt function to OFF or ON.

### **[:SWITCH]?**

Command: :SOURce : SAFETy : PRESet : TRIP : SWITCH?

This command queries the status of the Ground Fault Interrupt function.

The return character is "OFF" or "LOW".

### **NOTE:**

The TRIP command is the GFI setting.



**:NUMber**

**:PART <numerical value>**

Command: :SOURce : SAFETy : PRESet : NUMber : PART  
This command sets the part number for the device under test.  
<numeric value> is a value between 0.2 and 99.9.

**:PART?**

Command: :SOURce : SAFETy : PRESet : NUMber : PART?  
This command queries the part number of the device under test.

**:LOT <numerical value>**

Command: :SOURce : SAFETy : PRESet : NUMber : LOT  
This command sets the lot number for the device under test.  
<numeric value> is a value between 0.2 and 99.9.

**:LOT?**

Command: :SOURce : SAFETy : PRESet : NUMber : LOT?  
This command queries the lot number of the device under test.

**:SERIal <numerical value>**

Command: :SOURce : SAFETy : PRESet : NUMber : SERIal  
This command sets the serial number format.  
<numeric value> is a value between 0.2 and 99.9.

**:SERIal?**

Command: :SOURce : SAFETy : PRESet : NUMber : SERIal?  
This command queries the serial number format.

### 3.3.5 Error Messages

Error messages are saved in an error queue that is accessed by the FIFO method. The first return error message is the first saved in the queue. When the error message queue is over 30 messages, the error message “Queue overflow” will be displayed. The error queue cannot save any more error messages until this queue is cleared. When there is no error in the queue, the first position in the queue displays “No error”. Table 3-7 lists the error messages by number and description. When the **ERR** box is backlit on the bottom of the display, there are error messages in the queue.

**Table 3-7: IEEE-488 Error Messages**

#	Type	Description
-102	Syntax Error	Command includes a prohibited character or symbol
-108	Parameter Not Allowed	Device received a prohibited parameter
-109	Missing Parameter	Parameter missing from programming
-112	Mnemonic Too Long	Command program header is > 12 characters
-113	Undefined Header	Device received undefined header.
-114	Header Suffix Out of Range	Header suffix is out of range
-151	Invalid String of Data	Invalid string (usually missing double quotation marks)
-158	String Not Allowed	Data string is not allowed
-170	Expression Error	Device received incomplete parameter data
-222	Data Out of Range	Data is out of range
-291	Out of Memory	No memory left
-292	Referenced Name	Queried a name that does not exist
-293	Referenced Name	Cannot save a name that already exists
-361	Parity Error	Wrong parity in program message
-363	Input Buffer Overrun	Device received over 1024 characters
-365	Time Out Error	Device did not receive end character within certain time
-400	Queue Error	Output queue data is > 256 characters
-410	Query Interrupted	Query interrupted because query result from previous query has not yet been read.
-420	Query Terminated	Query terminated because the output queue data cannot be read when there is NO data in the queue.

### 3.3.6 Sample IEEE-488 Basic Programs

Included herein are two sample Basic programs. The first will program and run a two-step test and print the results. The second will program a two-step test and save it to G1000 instrument memory. This second program also adds two additional test steps, stores them in a second memory location then recalls first memory location for test.

```
REM-----
REM  G1000 IEEE sample program
REM  Please run the ULI file before this program.
REM  GPIB address is 3
REM-----

REM  This sample will program and run a two step test.
REM  Step 1 is a DC Hipot test at 1000 V
REM  Step 2 is an AC Hipot test at 1000 V
REM  The results of the test will be printed

CLS
PRINT "Program is running"
OPEN "gpib0" FOR OUTPUT AS #1
OPEN "gpib0" FOR INPUT AS #2
PRINT #1, "abort"
PRINT #1, "GPIBEOS IN LF"
PRINT #1, "Remote 03"

REM Send Stop command to G1000
PRINT #1, "output 3::SOURce:SAFEty:STOP"
REM Ask G1000 how many steps are currently programmed
PRINT #1, "output 3::SOURce:SAFEty:SNUMBer?"
PRINT #1, "enter 3"
INPUT #2, STEPNUM%

REM Delete programmed steps
PRINT "DELETE STEPS"

IF STEPNUM% > 0 THEN
  FOR I = STEPNUM% TO 1 STEP -1
    PRINT #1, "output 3::SOURce:SAFEty:STEP", I, ":DELeTe"
  NEXT I
END IF

CLS
REM Program Tester
PRINT "PROGRAM STEPS"

REM Program Step 1 DC test voltage 1 for 1000 V
PRINT #1, "output 3::SOURce:SAFEty:STEP 1:DC 1000"

REM Program high current limit for 0.4 mA
PRINT #1, "output 3::SOURce:SAFEty:STEP 1:DC:LIMit:HIGH 0.0004"

REM Program Test time for 2 seconds
PRINT #1, "output 3::SOURce:SAFEty:STEP 1:DC:TIME 2"
```

```

REM Program Step 2 AC test voltage for 1000 V
PRINT #1, "output 3::SOURce:SAFEty:STEP 2:AC 1000"

REM Program high current limit for 0.2 mA
PRINT #1, "output 3::SOURce:SAFEty:STEP 2:AC:LIMit 0.0002"

REM Program test time for 3 seconds
PRINT #1, "output 3::SOURce:SAFEty:STEP 2:AC:TIME:TEST 3"

REM Send stop command to G1000
PRINT #1, "output 3::SOURce:SAFEty:STOP"

REM Send start command to G1000
PRINT #1, "output 3::SOURce:SAFEty:START"

REM Check status of G1000
complete$ = "0"
WHILE complete$ <> "1"
  PRINT #1, "output 3::SAFEty:RESult:COMplete?"
  PRINT #1, "enter 3"
  INPUT #2, complete$

  IF complete$ = "1" THEN
    PRINT #1, "output 3::SOURce:SAFEty:STOP"
    PRINT #1, "output 3::SAFEty:RESult:ALL:OMET?"
    PRINT #1, "enter 3"

    FOR j = 1 TO STEPNUM%
      INPUT #2, result$
      PRINT "Measured Output Voltage"
      PRINT "step", j, ":", result$
    NEXT j

    PRINT

    PRINT #1, "output 3::SAFEty:RESult:ALL:MMET?"
    PRINT #1, "enter 3"

    FOR j = 1 TO STEPNUM%
      INPUT #2, result$
      PRINT "Measured Result"
      PRINT "step", j, ":", result$
    NEXT j
  END IF
WEND

PRINT #1, "output 3::SOURce:SAFEty:STOP"
CLOSE : SYSTEM
END

```

```

REM -----
REM  G1000 IEEE Sample Program 2
REM  Please run the ULI file before this program
REM  G1000 GPIB address is 3
REM -----
REM This program will set a two step AC hipot test and save it to
REM Memory location 1. It will then add two additional steps and
REM save it to Memory location 3. Finally it will recall Memory
REM location 1.
REM ****In order for this program to function the way it was
REM ****intended be sure there are no steps present in the
REM ****standby mode before running this program

OPEN "gpib0" FOR OUTPUT AS #1
OPEN "gpib0" FOR INPUT AS #2

PRINT #1, "abort"
PRINT #1, "GPIBEOS IN LF"
PRINT #1, "output 3;SOURCE:SAFETY:STOP"
PRINT #1, "output 3;SOURCE:SAFETY:STEP1:AC:LEVEL 600"
PRINT #1, "output 3;SOURCE:SAFETY:STEP1:AC:LIMIT:HIGH 0.0004"

PRINT #1, "output 3;SOURCE:SAFETY:STEP2:AC:LEVEL 500"
PRINT #1, "output 3;SOURCE:SAFETY:STEP2:AC:LIMIT:HIGH 0.0003"

REM Save programed steps to memory location 1 and label it ACAC
PRINT #1, "output 3;*SAV 1"
PRINT #1, "output 3;MEMORY:STATE:DEFINE ACAC,1"

PRINT #1, "output 3;SOURCE:SAFETY:STEP3:DC:LEVEL 700"
PRINT #1, "output 3;SOURCE:SAFETY:STEP3:DC:LIMIT:LOW 0.0001"

PRINT #1, "output 3;SOURCE:SAFETY:STEP4:IR:LEVEL 800"
PRINT #1, "output 3;SOURCE:SAFETY:STEP4:IR:LIMIT:HIGH 5000000"

REM Save 4 step test in location 3, label as ACACDCIR
PRINT #1, "output 3;*SAV 3"
PRINT #1, "output 3;MEMORY:state:DEFINE ACACDCIR,3"


REM Recall ACAC from memory location 1
PRINT #1, "output 3;*RCL 1"

CLOSE : SYSTEM

```

### 3.4 Printer Interface

An optional Printer Interface is available for the Guardian 1000 Series Instrument. The Printer interface takes the place of the IEEE-488 interface and is factory installed when the unit is ordered. Connection is through the black 25-pin connector labeled 'GPIB' on the rear panel of the Guardian 1000 Series instrument. Figure 3-8 illustrates the Printer interface pin designation.



**Figure 3-8: Printer Interface Pin Configuration**

The following printers have been tested with the G38 printer interface: Epson Stylus Color 440, Epson Stylus Color 460, Epson Stylus Photo 720, Epson LQ570C+ dot matrix, Epson LX-300 and HP DeskJet 648C. Included are two sample printouts: "Print Program" and "Auto Print".

When **Print Program** is selected, the programmed test parameters will print:

```
STEP 1 AC
VOLT: 0.050kV
TIME: 3.0S
HIGH: 0.500mA
LOW : OFF
ARC : OFF
RAMP: OFF
REAL: OFF
      12345678
SCAN: XXXXXXXXX
=====
STEP 2 DC
VOLT: 0.054kV
TIME: 3.0s
HIGH: 0.500mA
LOW : OFF
ARC : OFF
RAMP: OFF
      12345678
SCAN: XXXXXXXXX
=====
STEP 3 IR
VOLT: 0.500kV
TIME: 3.0s
LOW : 1.0MO
HIGH: OFF
RAMP: OFF
      12345678
SCAN: XXXXXXXXX
=====
```

The following will print when **Auto Print**: Pass and Fail and all Print Data options are turned ON:


```
=====
P/N:
L/N:
S/N:
Step-01 AC 0.049kV 0.001mA ----- PASS
Step-02 DC 0.054kV 0.010mA ----- PASS
Step-03 IR 0.501kV 0.8MO ----- LOW
-----FAIL -----
```

### 3.5 G16 International Power Strip

The Guardian 1000 Series instrument can be connected to the G16 International Power Strip as illustrated in Figure 3-9 for safety testing of many European corded products.

- |                |                 |              |
|----------------|-----------------|--------------|
| *Australia     | *United Kingdom | *Denmark     |
| *North America | *Norway         | *Finland     |
| *Sweden        | *Germany        | *Netherlands |
| *Austria       | *Switzerland    | *Italy       |

The three G-16 ground connectors are connected to the Guardian 1000 RTN/LOW terminal. There is a second RTN/LOW terminal on the rear of the Guardian 1000 Series instrument.



**Figure 3-9: G16 International Power Strip Connection to Guardian 1000 Series Instrument**



### 3.6 S07 Power Entry Adaptor Cable

The S07 Power Entry Adaptor Cable is a 3-wire AC inlet receptacle for precise testing of corded products. The S07 cable is connected to the Guardian 1000 Series instrument via a two-lead set. The white custom banana plug is connected to the OUTPUT terminal on the G1000 unit. The black banana plug with retaining bracket is connected to the RTN/LOW terminal on the G1000 unit. Figure 3-10 illustrates this connection of the S07 cable to a Guardian 1030S instrument.




Figure 3-10: S07 Power Entry Adaptor Cable

### 3.7 S03 Corded Product Adaptor (115V)

The S03 Corded Product Adaptor is a 3-prong electrical outlet box to facilitate testing of corded products. The S03 cable is connected to the Guardian 1000 Series instrument via a two-lead set. The white custom banana plug is connected to the OUTPUT terminal on the G1000 unit. The black banana plug is connected to the RTN/LOW terminal on the G1000 unit. Figure 3-11 illustrates this connection of the S03 cable to a Guardian 1030S instrument.





Figure 3-11: S03 Corded Product Adaptor

### 3.8 S05 Foot Switch

The S05 Foot Switch provides hands-free remote testing capability. The spade leads on the S05 Foot Switch are connected (screwed) to the terminal strip on the rear panel of the Guardian 1000 Series instrument. The white wire/spade connector is screwed to the START terminal and the red wire/spade connector is screwed to the COM terminal. Figure 3-12 illustrates this connection of the S05 Foot Switch to a Guardian 1000 Series instrument.



**Figure 3-12: S05 Foot Switch**

### 3.9 S08 Gun Probe

The S08 Gun Probe provides fast testing capability with pinpoint control. The custom white banana plug is connected to the OUTPUT terminal on the front panel of the Guardian 1000 Series instrument. Figure 3-13 illustrates this connection of the S08 probe to a Guardian 1030S unit.




Figure 3-13: S08 Gun Probe

### 3.10 S50 Ground Bond Tester

The Guardian 1000 Series instrument can be connected to the Sentry 50 Ground Bond Tester for high current ground testing between chassis and power cord ground. The output current is programmable from 1A to 30A AC in 0.01A increments and resistance can be measured over the range 0.1mΩ to 510mΩ. The rear panels of the Guardian 1000 Series instrument and Sentry 50 instrument are connected via the S15 9-pin interconnection cable. Figure 3-14 illustrates the front panel connections of the two instruments.




Figure 3-14: Guardian 1030S & Sentry 50 Connection



---

## Section 4: Service & Calibration

---

### 4.1 General

Our warranty (at the front of this manual) attests to the quality of materials and workmanship in our products. If malfunction should be suspected, or other information desired, applications engineers are available for technical assistance. Applications assistance is available in the U.S. by calling (978) 461-2100 and asking for Applications Support. For support outside of the United States please contact your local QuadTech Distributor.

### 4.2 Instrument Return

Before returning an instrument to QuadTech for service please call our **Customer Care Center (CCC)** at **800-253-1230** for Return Material Authorization (RMA). It will be necessary to include a Purchase Order Number to insure expedient processing, although units found to be in warranty will be repaired at no-charge. For any questions on repair costs or shipping instructions please contact our CCC Department at the afore-mentioned number. To safeguard an instrument during storage and shipping, please use packaging that is adequate to protect it from damage, i.e. equivalent to the original packaging, and mark the box “Delicate Electronic Instrument”. Return material should be sent freight prepaid to:

**QuadTech, Inc.**  
**5 Clock Tower Place, 210 East**  
**Maynard, Massachusetts 01754**

**Attention: RMA#**

**Shipments sent collect cannot be accepted.**

### 4.3 Calibration

Calibration of the Guardian 1000 Series instruments is recommended on an annual basis. If the unit is returned to QuadTech for factory calibration, refer to paragraph 4.2 for RMA and shipping instructions. Using the calibration procedure in paragraph 4.3.1, the Guardian 1000 Series instrument may be calibrated by a qualified service person IF traceable calibration equipment and standards are available. **The instrument should be powered up for a minimum of 1 hour prior to calibration to ensure maximum stability.**

**Table 4-1: Calibration Equipment**

Equipment	Parameter	Requirements
AC/DC High Voltage Voltmeter	ACV, DCV, IRV	Measure Range: 0 to 6kV, 0.1% accuracy
AC/DC Current Meter	ACA, RACA, DCA	Measure Range: 0 to 40mA, 0.1% accuracy
1GΩ Resistance Standard	IRR	250V
100MΩ Resistance Standard	IRR	500V
10MΩ Resistance Standard	IRR	500V, 1000V & 1200V
420kΩ Resistance Standard	ACA, DCA, RACA	1200V, 3mA, 50W
50kΩ Resistance Standard	ACA, RACA	1200V, 25mA, 200W
150kΩ Resistance Standard	DCA	1200V, 15mA, 100W

### 4.3.1 Calibration Parameters

Table 4-2 contains the calibration parameters for the Guardian 1000 Series instruments. All tests points are not required for each of the instruments (1010, 1030 & 1030S).

**Table 4-2: Calibration Parameters**

TEST		RANGE		CAL. POINT
<b>Voltage Calibration</b>				
CAL	ACV	5kV	OFST	0.100kV
CAL	ACV	5kV	FULL	4.000kV
CAL	DCV	6kV	OFST	0.100kV
CAL	DCV	6kV	FULL	4.000kV
CAL	IR	1kV	OFST	0.100kV
CAL	IR	1kV	FULL	1.000kV
<b>Current Calibration</b>				
CAL	ACA	3mA	OFST	0.120mA
CAL	ACA	3mA	FULL	2.500mA
CAL	ACA	30mA	OFST	2.50mA
CAL	ACA	30mA	FULL	25.00mA
CAL	RACA	3mA	OFST	0.120mA
CAL	RACA	3mA	FULL	2.500mA
CAL	RACA	30mA	OFST	2.50mA
CAL	RACA	30mA	FULL	25.00mA
CAL	DCA	3mA	OFST	0.120mA
CAL	DCA	3mA	FULL	2.500mA
CAL	DCA	10mA	OFST	2.50mA
CAL	DCA	10mA	FULL	8.00mA
<b>WAC and WDC ARCing Calibration</b>				
CAL	AC ARC	30mA	Arc	5.00mA
CAL	DC ARC	10mA	Arc	5.00mA
<b>IR Resistor Mode Calibration</b>				
CAL	IRR Range1	1GΩ	IRR	Range1 to 1GΩ
CAL	IRR Range2	100MΩ	IRR	Range2 to 100MΩ
CAL	IRR Range3	10MΩ	IRR	Range3 to 10MΩ
CAL	IRR Range4	10MΩ	IRR	Range4 to 10MΩ



### 4.3.2 Enable Calibration

The instrument should be powered up for a minimum of 1 hour prior to calibration to ensure maximum stability. With the Guardian 1000 Series instrument in standby status ([RESET] button previously pressed and no warning lights flashing) remove the Calibration seal over the hole labeled “CAL” on the front panel and push the recessed switch to the IN position.

The unit is in STAND BY status.

Press [F3] = MENU.

Press [F2] = DOWN three times until **CALIBRATION** is highlighted (backlit).

Press [F3] = SELECT to choose calibration function.


Display will prompt for a password.

Press [A] [A] [A] [B] [ENTER]

Cal Step 1: ‘ACV 5kV Offset (100V)’ is displayed on the screen.

#### NOTE

Figure 4-1 illustrates the password prompt for calibration and the ‘Calibration is OFF’ display. The ‘Calibration is OFF’ display may occur if the CAL recessed switch has **not** been pressed IN prior to entering Calibration function.



**Figure 4-1: Calibration Password Prompt**

#### NOTE

The term ‘G1000’ is used in this Calibration procedure to denote all instruments in the G1000 Series: G1010, G1030 and G1030S.

The DC and IR calibration procedures are applicable to the G1030 and G1030S instruments. ARC calibration is part of the calibration routine but it is not performed on the Guardian 1010, 1030 or 1030S instrument.

### 4.3.3 AC Voltage Calibration

Connect the OUTPUT terminal of the Guardian1000 Series unit to the input terminal of the AC/DC high voltage meter. Connect the RTN/LOW terminal of the Guardian to the GND terminal of the voltmeter. Set the voltmeter to AC and 2kV range.

#### Cal Step 1: 'ACV 5kV Offset (100V)'

"ACV Offset"  
Display

ACV	5kV	Offset	(500V)	UP
OUTPUT		READING		DOWN
0.500kV		0.000kV		SETUP
STANDARD: 0.100kV				EXIT
SELECT FUNC.	RMT	LOCK	OFST	ERR

F1 To go to next CAL step.

F2 To go to previous CAL step.

F3 To enter ACV OFFSET function

F4 To exit CAL mode & return to MENU.

1 To get OFFSET value

3 To accept OFFSET

ACV	5kV	Offset	(100V)	INC
OUTPUT		READING		DEC
0.100kV		0.000kV		
STANDARD: 0.100 kV				
STOPPED	RMT	LOCK	OFST	ERR

F1 To increase STANDARD value.

F2 To decrease STANDARD value.

F3

F4

Enter voltmeter reading →

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the voltmeter.

Press [STOP] to accept reading.

G1000 reverts to "ACV Offset" display (incorporating new cal value).

Press [F1] = UP to go to **Cal Step 2: 'ACV 5kV Full (4kV)'**. Change voltmeter range to 20kV.

"ACV Full"  
Display

ACV	5kV	Full	(4kV)	UP
OUTPUT		READING		DOWN
4.000kV		0.000kV		SETUP
STANDARD: 4.000kV				EXIT
SELECT FUNC.	RMT	LOCK	OFST	ERR

F1 To go to next CAL step.

F2 To go to previous CAL step.

F3 To enter ACV FULL function

F4 To exit CAL mode & return to MENU.

Press [STOP] to return instrument to steady state.

Press [START] to get full value

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the voltmeter.

Press [STOP] to accept reading.

G1000 reverts to "ACV Full" display (incorporating new cal value).

### 4.3.4 DC Voltage Calibration (DCV)

Change the setting on the Valhalla voltmeter to DC and 2kV range. DC calibration is applicable to the Guardian 1030 and 1030S instruments.

Press [F1] = UP to go to **Cal Step 3: 'DCV 6kV Offset (100V)'**.

"DCV Offset" Display

DCV	6kV	Offset	(100V)	UP	F1	To go to next CAL step.
OUTPUT		READING		DOWN	F2	To go to previous CAL step.
0.100kV		0.000kV		SETUP	F3	To enter DCV OFFSET function
STANDARD: 0.100kV				EXIT	F4	To exit CAL mode & return to MENU.
SELECT FUNC.	RMT	LOCK	OFST	ERR		

1 **START** To get OFFSET value

3 **STOP** To accept OFFSET

DCV	6kV	Offset	(100V)	INC	F1	To increase OUTPUT value.
OUTPUT		READING		DEC	F2	To decrease OUTPUT value.
0.100kV		0.000kV			F3	
STANDARD: 0.100 kV					F4	
STOPPED	RMT	LOCK	OFST	ERR		

Enter voltmeter reading ←

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the voltmeter.

Press [STOP] to accept reading.

G1000 reverts to "DCV Offset" display (incorporating new cal value).

Press [F1] = UP to go to **Cal Step 4: 'DCV 6kV Full (4kV)'**. Change voltmeter range to 20kV.

"DCV Full" Display

DCV	6kV	Full	(4kV)	UP	F1	To go to next CAL step.
OUTPUT		READING		DOWN	F2	To go to previous CAL step.
4.000kV		0.000kV		SETUP	F3	To enter DCV FULL function
STANDARD: 4.000kV				EXIT	F4	To exit CAL mode & return to MENU.
SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the voltmeter.

Press [STOP] to accept reading.

G1000 reverts to "DCV Full" display (incorporating new cal value).

### 4.3.5 IR Voltage Calibration (IRV)

Keep the setting on the Valhalla voltmeter at DC and 2kV range. IR calibration is applicable to the Guardian 1030 and 1030S instruments.

Press [F1] = UP to go to **Cal Step 5: 'IRV 1kV Offset (100V)'**.

"IRV Offset" Display

IRV	1kV	Offset	(100V)	UP	F1	To go to next CAL step.
OUTPUT		READING		DOWN	F2	To go to previous CAL step.
0.100kV		0.000kV		SETUP	F3	To enter IRV OFFSET function
STANDARD: 0.100kV				EXIT	F4	To exit CAL mode & return to MENU.
SELECT FUNC.	RMT	LOCK	OFST	ERR		

1 **START** To get OFFSET value

3 **STOP** To accept OFFSET

IRV	1kV	Offset	(100V)	INC	F1	To increase OUTPUT value.
OUTPUT		READING		DEC	F2	To decrease OUTPUT value.
0.100kV		0.000kV			F3	
STANDARD: 0.100 kV					F4	
STOPPED	RMT	LOCK	OFST	ERR		

Enter voltmeter reading

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the voltmeter.

Press [STOP] to accept reading.

G1000 reverts to "IRV Offset" display (incorporating new cal value).

Press [F1] = UP to go to **Cal Step 6: 'IRV 1kV Full (1kV)'**. Change voltmeter range to 20kV.

"IRV Full" Display

IRV	1kV	Full	(1kV)	UP	F1	To go to next CAL step.
OUTPUT		READING		DOWN	F2	To go to previous CAL step.
1.000kV		0.000kV		SETUP	F3	To enter IRV FULL function
STANDARD: 1.000kV				EXIT	F4	To exit CAL mode & return to MENU.
SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the voltmeter.

Press [STOP] to accept reading.

G1000 reverts to "IRV Full" display (incorporating new cal value).

### 4.3.6 AC Current Calibration (ACA)

Connect the OUTPUT terminal of the Guardian 1000 Series instrument to a resistance box or resistance standard. Connect an AC/DC current meter in series between the resistance load (box/standard) and the RTN/LOW terminal of the Guardian instrument. Table 4-4 lists the resistance loads necessary for the current calibration steps.

**Table 4-4: Resistance Loads**

Mode	Step #	Voltage	Calibration Point	Resistance (Load)
ACA	CAL 7	1200 V	0.12mA	10MΩ
ACA	CAL 8	1200 V	2.5mA full	420kΩ
ACA	CAL9	1200 V	2.5mA	420kΩ
ACA	CAL 10	1200 V	25mA	50kΩ
RACA	CAL 11	1200 V	0.12mA	10MΩ
RACA	CAL12	1200V	2.5mA full	420KΩ
RACA	CAL 13	1200 V	2.5mA	420KΩ
RACA	CAL 14	1200 V	25mA	50kΩ
DCA	CAL 15	1200 V	0.12mA	10MΩ
DCA	CAL 16	1200 V	2.5mA full	420kΩ
DCA	CAL 17	1200 V	2.5mA	420kΩ
DCA	CAL 18	1200 V	8mA	150kΩ

Press [F1] = UP to go to **Cal Step 7: 'ACA 3mA Offset (0.12mA)'**.

"ACA 3mA Offset" Display

ACA	3mA	Offset	(0.12mA)	
OUTPUT	READING		UP	F1
1.200kV	0.000mA		DOWN	F2
STANDARD: 0.120mA			SETUP	F3
SELECT FUNC.	RMT	LOCK	OFST	ERR
				EXIT
				F4

To go to next CAL step.

To go to previous CAL step.

To enter ACA OFFSET function

To exit CAL mode & return to MENU.

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "ACA 3mA Offset" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 8: 'ACA 3mA Full (2.5mA)'**.

"ACA 3mA Full" Display	ACA    3mA    Full    (2.5mA)	UP	F1	To go to next CAL step.
	OUTPUT                  READING	DOWN	F2	To go to previous CAL step.
	1.200kV                  0.000mA	SETUP	F3	To enter ACA FULL function
	STANDARD: 2.500mA	EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.    RMT    LOCK    OFST    ERR			

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "ACA 3mA Full" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 9: 'ACA 30mA Offset (2.5mA)'**.

"ACA 30mA Offset" Display	ACA    30mA    Offset    (2.5mA)	UP	F1	To go to next CAL step.
	OUTPUT                  READING	DOWN	F2	To go to previous CAL step.
	1.200kV                  0.000mA	SETUP	F3	To enter ACA OFFSET function
	STANDARD: 2.500mA	EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.    RMT    LOCK    OFST    ERR			

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "ACA 30mA Offset" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 10: 'ACA 30mA Full (25mA)'**.

"ACA 30mA Full" Display	ACA    30mA    Full    (25mA)	UP	F1	To go to next CAL step.
	OUTPUT                  READING	DOWN	F2	To go to previous CAL step.
	1.200kV                  0.000mA	SETUP	F3	To enter ACA FULL function
	STANDARD: 25.00mA	EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.    RMT    LOCK    OFST    ERR			

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "ACA 30mA Full" display (incorporating the new cal value).

### 4.3.7 Real AC Current Calibration (RACA)

Connect the OUTPUT terminal of the Guardian 1000 Series instrument to a resistance box or resistance standard. Connect an AC/DC current meter in series between the resistance load (box/standard) and the RTN/LOW terminal of the Guardian instrument.

Press [F1] = UP to go to **Cal Step 11: 'RACA 3mA Offset (0.12mA)'**.

"RACA 3mA Offset" Display	RACA    3mA    Offset    (0.12mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter RACA OFFSET function	
	STANDARD: 0.120mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "RACA 3mA Offset" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 12: 'RACA 3mA Full (2.5mA)'**.

"RACA 3mA Full" Display	RACA    3mA    Full    (2.5mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter RACA FULL function	
	STANDARD: 2.500mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "RACA 3mA Full" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 13: 'RACA 30mA Offset (2.5mA)'**.

"RACA 30mA Offset" Display	RACA 30mA Offset (2.5mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter RACA OFFSET function	
	STANDARD: 2.500mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "RACA 30mA Offset" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 14: 'RACA 30mA Full (25mA)'**.

"RACA 30mA Full" Display	RACA 30mA Full (25mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter RACA FULL function	
	STANDARD: 25.00mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "RACA 30mA Full" display (incorporating the new cal value).



### 4.3.8 DC Current Calibration

Connect the OUTPUT terminal of the Guardian 1000 Series instrument to a resistance box or resistance standard. Connect an AC/DC current meter in series between the resistance load (box/standard) and the RTN/LOW terminal of the Guardian instrument.

Press [F1] = UP to go to **Cal Step 15: 'DCA 3mA Offset (0.12mA)'**.

"DCA 3mA Offset" Display	DCA 3mA Offset (0.12mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter DCA OFFSET function	
	STANDARD: 0.120mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "DCA 3mA Offset" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 16: 'DCA 3mA Full (2.5mA)'**.

"DCA 3mA Full" Display	DCA 3mA Full (2.5mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter DCA FULL function	
	STANDARD: 2.500mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "DCA 3mA Full" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 17: 'DCA 10mA Offset (2.5mA)'**.

"DCA 10mA Offset" Display	DCA 10mA Offset (2.5mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter DCA OFFSET function	
	STANDARD: 2.500mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get offset value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "DCA 15mA Offset" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 18: 'DCA 10mA Full (8mA)'**.

"DCA 10mA Full" Display	DCA 10mA Full (8mA)				UP	F1	To go to next CAL step.
	OUTPUT	READING		DOWN	F2	To go to previous CAL step.	
	1.200kV	0.000mA		SETUP	F3	To enter DCA FULL function	
	STANDARD: 8.00mA				EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.	RMT	LOCK	OFST	ERR		

Press [STOP] to return instrument to steady state.

Press [START] to get full value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as the current meter.

Press [STOP] to accept reading.

G1000 reverts to "DCA 15mA Full" display (incorporating the new cal value).

### 4.3.9 ARC Calibration

**NOTE**

ARC calibration is part of the calibration routine but it is **not** performed on the Guardian 1010, 1030 or 1030S instrument.

**ARC Calibration is set at the factory.**

Press [F1] = UP to go to Cal Step 19: ‘AC ARC 30mA (5mA)’. BY-PASS

Press [F1] = UP to go to Cal Step 20: ‘DC ARC 15mA (5mA)’. BY-PASS

### 4.3.10 IR Resistor Calibration (IRR)

Connect the resistance load (per Table 4-5) between the Guardian instrument’s OUTPUT terminal and RTN/LOW terminal.

**Table 4-5: IRR Cal Resistance Loads**

IR Resistor Mode Calibration			
STEP #	TEST	LOAD	CAL. POINT
CAL 21	IRR Range1	1GΩ	Range1 to 1GΩ
CAL 22	IRR Range2	100MΩ	Range2 to 100MΩ
CAL 23	IRR Range3	10MΩ	Range3 to 10MΩ
CAL 24	IRR Range4	10MΩ	Range4 to 10MΩ

Press [F1] = UP to go to **Cal Step 21: ‘IRR Range1 (1GΩ)’**.

"IRR Range1"  
Display

	IRR	Range1		(1GΩ)			
OUTPUT	READING				UP	F1	To go to next CAL step.
0.250kV	0.000MΩ				DOWN	F2	To go to previous CAL step.
STANDARD: 1000MΩ					SETUP	F3	To enter IRR Range1 function
SELECT FUNC.	RMT	LOCK	OFST	ERR	EXIT	F4	To exit CAL mode & return to MENU.

Press [STOP] to return instrument to steady state.

Press [START] to get range1 value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as certified load value.

Press [STOP] to accept reading.

G1000 reverts to “IRR Range1” display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 22: 'IRR Range2 (100MΩ)'**.

"IRR Range2" Display	IRR    Range2    (100MΩ)	UP	F1	To go to next CAL step.
	OUTPUT                  READING	DOWN	F2	To go to previous CAL step.
	0.500kV                  0.000MΩ	SETUP	F3	To enter IRR Range2 function
	STANDARD: 100.0MΩ	EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.    RMT    LOCK    OFST    ERR			

Press [STOP] to return instrument to steady state.

Press [START] to get range2 value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as certified load value.

Press [STOP] to accept reading.

G1000 reverts to "IRR Range2" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 23: 'IRR Range3 (10MΩ)'**.

"IRR Range3" Display	IRR    Range3    (10MΩ)	UP	F1	To go to next CAL step.
	OUTPUT                  READING	DOWN	F2	To go to previous CAL step.
	0.500kV                  0.000MΩ	SETUP	F3	To enter IRR Range3 function
	STANDARD: 10.00MΩ	EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.    RMT    LOCK    OFST    ERR			

Press [STOP] to return instrument to steady state.

Press [START] to get range3 value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as certified load value.

Press [STOP] to accept reading.

G1000 reverts to "IRR Range3" display (incorporating the new cal value).

Press [F1] = UP to go to **Cal Step 24: 'IRR Range4 (10MΩ)'**.

"IRR Range4" Display	IRR    Range4    (10MΩ)	UP	F1	To go to next CAL step.
	OUTPUT                  READING	DOWN	F2	To go to previous CAL step.
	1.000kV                  0.000MΩ	SETUP	F3	To enter IRR Range4 function
	STANDARD: 10.00MΩ	EXIT	F4	To exit CAL mode & return to MENU.
	SELECT FUNC.    RMT    LOCK    OFST    ERR			

Press [STOP] to return instrument to steady state.

Press [START] to get range4 value.

Press [F1] = INC or [F2] = DEC until the G1000 display reads the same as certified load value.

Press [STOP] to accept reading.

G1000 reverts to "IRR Range4" display (incorporating the new cal value).

### 4.3.11 Finalize Calibration

**When all calibration steps are complete:**

Press [F4] = EXIT

Release the [CAL] enable switch to the **OUT** position using the tip of a small screwdriver.

1. Press [F2] = DOWN three times.
2. Press [F3] = SELECT
3. Display prompts: 'PASSWORD'.
4. Press [A] [A] [A] [A] [ENTER]
5. Display prompts: 'Calibration is OFF' or 'Calibration is ON'.
6. If 'Calibration is OFF', repeat steps 1, 2, 3 & 4 until display reads 'Calibration is ON'.