



LR2000
Milliohmmeter
Instruction Manual
Form 150713/A9

©QuadTech, Inc., 2004, 2008

Domestic Sales 800-253-1230

For additional contact information please visit our website
www.quadtech.com

The material in this manual is for informational purposes only and is subject to change, without notice. QuadTech assumes no responsibility for any error or for consequential damages that may result from the misinterpretation of any procedures in this publication.

CAUTION

Voltage may be present on front and rear panel terminals. Follow all warnings in this manual when operating or servicing this instrument. Substantial levels of energy may be stored in capacitive devices tested by this unit.

Contents

Warranty	5
Specifications	7
Accessories	9
Safety Precautions	11
Condensed Operating Instructions	13
Introduction - Section 1	
1.1	Unpacking and Inspection..... 17
1.2	Product Overview 17
1.3	Controls and Indicators 18
1.3.1	Front Panel Controls and Indicators 18
1.3.2	Rear Panel Controls and Connectors 19
1.4	Installation 20
1.4.1	Dimensions 20
1.4.2	Instrument Positioning 20
1.4.3	Power Requirements 20
1.4.4	Safety Inspection..... 21
Operation - Section 2	
2.1	Terms and Conventions 23
2.2	Start-Up..... 28
2.3	SYSTEM SETUP 28
2.3.1	Calibration 28
2.3.2	Memory Manage 28
2.3.3	System Configuration 28
2.3.3.1	AVERAGE NO. 29
2.3.3.2	BEEPER 30
2.3.3.3	KEY LOCK 30
2.3.3.4	CONTRAST 30
2.3.3.5	SOUND MODE 31
2.3.3.6	ALARM MODE 31
2.3.3.7	TRIGGER DELAY 31
2.3.3.8	TRIGGER EDGE 32
2.3.3.9	HANDLER MODE 32
2.3.3.10	MEAS. DELAY 32
2.3.3.11	LINE FREQUENCY 33
2.3.3.12	GPIB ADDRESS 33
2.3.3.13	BAUD RATE 33
2.3.3.14	CORRECTION TEMP 34
2.3.3.15	THERMAL COEFFICIENT 34
2.3.3.16	TEMPERATURE PROBE 34

Contents

Operation - Section 2 - Continued

2.4	MEAS DISPLAY	35
2.4.1	DRIVE	36
2.4.2	DRY Circuit.....	36
2.4.3	TRIGGER	37
2.4.4	RANGE	37
2.4.5	SPEED	38
2.4.6	ZERO	38
2.4.7	COMPARE	38
2.4.8	BINNING	39
2.4.9	TEMP	40
2.5	MAIN INDEX	40
2.5.1	COMPARE	41
2.5.2	BINNING	42
2.5.3	TEMP CONV	45
2.6	Connection To Device Under Test	46
2.7	Measurement Procedure.....	46

Interface - Section 3

3.1	RS-232 Interface	47
3.1.1	Pin Configuration	47
3.1.2	RS-232 Specifications	47
3.1.3	RS-232 Interface Commands	48
3.1.4	Sample Quick Basic Program	48
3.2	IEEE-488 Interface	50
3.2.1	Pin Configuration.....	50
3.2.2	IEEE-488 Interface Function Codes and Messages.....	52
3.2.3	IEEE-488 Interface Commands	54
3.2.4	IEEE-488 Command Format	56
3.2.5	IEEE-488 Commands - Detailed	57
3.3	Handler Interface	68
3.3.1	Handler Pin Assignments for Binning Operation	70
3.3.2	Handler Pin Assignments for Compare Operation	71
3.4	Temperature Compensation Interface	72

Service & Calibration - Section 4

4.1	General	73
4.2	Instrument Return	73
4.3	Calibration	73
4.3.1	LR2000 Verification Procedure	74
4.3.2	LR2000 Verification Data Sheet	74

Warranty



QuadTech warrants that Products are free from defects in material and workmanship and, when properly used, will perform in accordance with QuadTech's applicable published specifications. If within one (1) year after original shipment it is found not to meet this standard, it will be repaired, or at the option of QuadTech, replaced at no charge when returned to a QuadTech service facility.

Changes in the Product not approved by QuadTech shall void this warranty.

QuadTech shall not be liable for any indirect, special or consequential damages, even if notice has been given of the possibility of such damages.

This warranty is in lieu of all other warranties, expressed or implied, including, but not limited to any implied warranty or merchantability of fitness for a particular purpose.

SERVICE POLICY

QuadTech's service policy is to maintain product repair capability for a period of at least five (5) years after original shipment and to make this capability available at the then prevailing schedule of charges.

Specifications

Resistance Range:

Range F.S.	Resolution	Accuracy	Test I (typical)
20mΩ	1μΩ	± (0.1% of rdg + .006mΩ)	1A
200mΩ	10μΩ	± (0.05% of rdg + .06mΩ)	100mA
2Ω	100μΩ	± (0.05% of rdg + .6mΩ)	10mA
20Ω	1mΩ	± (0.05% of rdg + 6mΩ)	1mA
200Ω	10mΩ	± (0.05% of rdg + 40mΩ)	1mA
2kΩ	100mΩ	± (0.05 % of rdg + .2Ω)	1mA
20kΩ	1Ω	± (0.1% of rdg + 2Ω)	100μA
200kΩ	10Ω	± (0.2% of rdg + 20Ω)	10μA
2MΩ	100Ω	± (0.4% of rdg + 200Ω)	1μA

Test Signal:

Modes: DC+, DC-, Pulse+, Pulse-, Pulse +/-, Standby
 Dry Circuit*: Open Circuit Voltage <20mV for 200mΩ, 2Ω & 20Ω

Measurement Rate:

Fast: 65ms/measurement = 15 measurements/second
 Medium: 150ms/measurement = 6 measurements/second
 Slow: 650ms/measurement = 1.5 measurements/second

Trigger:

Manual, Internal or External

Delay Times:

Trigger Delay: 5ms – 1000ms, 5ms increments (falling or rising edge)
 Measurement Delay: 0 – 100s

Ranging:

Automatic or Hold Range

Zeroing:

Short circuit compensation

Averaging:

1 – 10 measurements

Comparator:

Nominal: Hi/Lo Limits (Value or %)

Bin Sorting:

Nominal: Hi/Lo Limits (8 Bins in %)

Front Panel Lockout:

Key Lock, Back Lit Display: LOCK

Display:

240 x 64 dot matrix LCD display

Indication:

Audible alarm programmable High, Low or OFF for Pass or Fail

* Accuracy degraded to 2.5% with Dry Circuit ON.

Specifications (Continued)

Standard Interfaces:	<ul style="list-style-type: none">• RS232				
Optional Interfaces:	<ul style="list-style-type: none">• IEEE-488/Handler• Temperature Compensation				
Temperature Compensation:	Optional Interface for Automatic Thermal Compensation Measurements from 0°C to 100°C using PT100 probe Temperature Display: °C or °F Temperature Range: 0°C to 100°C Temperature Accuracy: ± (0.3% of reading + 0.8°C) Additional Resistance Error: 0°C-39.9°C: ±0.3% 40°C-100°C: ±0.6%				
Connectors:	Front Connection: 4 Sheathed Banana Terminals 1 Ground Terminal				
Mechanical:	Bench Mount Dimensions:(w x h x d): 312.5 x 100.0 x 337.5 mm				
Weight:	5 kg net, 7 kg shipping				
Environmental:	Specifications: 15°C to + 35°C, 75% RH Operating: 10°C to + 40°C, 10-90% RH Storage: 0°C to + 50°C, 10-90% RH Pollution Degree 2 Installation Category II				
Power:	<ul style="list-style-type: none">• 90-125VAC: 50Hz/60Hz, Consumption 80W Max• 190-250VAC: 50Hz/60Hz, Consumption 80W Max				
Supplied:	<ul style="list-style-type: none">• Instruction Manual• LR2000-50 Kelvin Clip Lead Set• Power Line Fuses• AC Power Cable• Calibration Certificate				
Ordering Information:	<table><thead><tr><th><u>Description</u></th><th><u>Catalog No.</u></th></tr></thead><tbody><tr><td>Milliohmmeter</td><td>LR2000</td></tr></tbody></table>	<u>Description</u>	<u>Catalog No.</u>	Milliohmmeter	LR2000
<u>Description</u>	<u>Catalog No.</u>				
Milliohmmeter	LR2000				

Accessories

Accessories Included

Item	Quantity	QuadTech P/N
AC Power Cord	1	4200-0300
Power Line Fuse 1.0A 250V SB, 5x20mm	1	520026
Power Line Fuse 0.5A 250V SB, 5x20mm	1	520138
Lead Set: 4 Banana Connectors to 2 Kelvin Clips	1	LR2000-50
Instruction Manual	1	150713
Calibration Certificate	1	N/A

Accessories/Options Available

Item	Quantity	QuadTech P/N
Lead Set: 4 Banana Connectors to 2 Kelvin Clips	1	LR2000-50
IEEE-488 24-Pin Interface & Handler 24-Pin Interface	1	700171
Temperature Compensation, IEEE & Handler Interface	1	700251
Temperature Compensation Probe	1	700250
RS232 Cable (9-pin)	1	630157
Virtual Front Panel Wizard	1	LR2000-WZD

Safety Precautions

WARNING

The LR2000 Milliohmmeter is a low voltage instrument and provides no more than 1A AC output to the device under test (DUT). Some devices tested (especially capacitors) can store charge and may cause a hazard if not discharged properly. Follow these safety instructions.

1. Operate the LR2000 unit with its chassis connected to earth ground. The instrument is shipped with a three-prong power cord to provide this connection to ground. This power cord should only be plugged in to a receptacle that provides earth ground.
2. Plug the Kelvin Clip Lead Set into the red/black output terminals: DRIVE-, SENSE-, SENSE+, and DRIVE+ for proper connection.
3. Before turning on the LR2000 unit, make sure there is no device (DUT) or fixture connected to the test leads.
4. Before touching the test lead wires or output terminals make sure any capacitive device has been fully discharged.
5. In the case of an emergency, turn OFF the POWER switch using a “hot stick” and disconnect the AC power cord from the wall. Do not touch the LR2000 instrument.
6. Never touch the metal of the High Voltage probe directly. Touch only the insulated parts of the lead(s).
7. Never touch the test leads, test fixture or DUT in any manner (this includes insulation on all wires and clips) when the high voltage is applied and the red **DANGER** light is ON.
8. Before turning on the unit, make sure there is no device (DUT) or fixture connected to the test leads.
9. After each test, press the **[STOP]** (red) button for safety. This terminates the high voltage being applied to the output terminals.
10. When the red **DANGER** LED is lit or flashing, NEVER touch the device under test, the lead wires or the output terminals.
11. Before touching the test lead wires or output terminals make sure :
 12. The red **[STOP]** button has been pressed
 13. The red **DANGER** LED is OFF.
14. In the case of an emergency, turn OFF the POWER switch using a “hot stick” and disconnect the AC power cord from the wall. **DO NOT TOUCH THE INSTRUMENT.**
15. Position the equipment so it is easy to disconnect. Always disconnect by means of the power plug or power connector.
16. If the **DANGER** LED does not go off when the **[STOP]** button is pressed, immediately stop using the tester. It is possible that the output voltage is still being delivered regardless of the TEST ON/OFF control signal.
17. When the instrument is remotely controlled, be extremely careful. The High Voltage Output is being turned On/Off with an external signal.

Safety Symbols

The product is marked with the following safety symbols.




Product will be marked with this symbol (ISO#3864) when it is necessary for the user to refer to the instruction manual in order to prevent injury or equipment damage.



Product marked with this symbol (IEC417) indicates presence of direct current.



Product will be marked with this symbol (ISO#3864) when voltages in excess of 1000V are present.



Indicates the grounding protect terminal, which is used to prevent electric shock from the leakage on chassis. The ground terminal must connect to earth before using the product.

Warning Procedure can cause hazard to human if the warning is neglected.

Caution Avoid product misuse. It may cause damage to the product itself and the DUT if the caution is neglected.


Note Important information or tips for the procedures and applications.

Warning Signal During Testing

“DANGER – HIGH VOLTAGE TEST IN PROGRESS, UNAUTHORIZED PERSONS KEEP AWAY”

Disposal

Do not dispose of electrical appliances as unsorted municipal waste, use separate collection facilities. Contact your local government for information regarding the collection systems available. If electrical appliances are disposed of in landfills or dumps, hazardous substances can leak into the groundwater and get into the food chain, damaging your health and well-being. When replacing old appliances with new one, the retailer is legally obligated to take back your



Condensed Operating Instructions

General Information

The LR2000 Milliohmmeter is an instrument for measuring resistance (R) over the range of $1\mu\Omega$ to $2M\Omega$. Ideal for measuring contact resistance of switches, relays, connectors and cables or for measuring winding resistance of motors, transformers, and solenoids. The LR2000 performs precision low resistance measurements in any environment: production testing, component evaluation, materials testing and incoming inspection. The resistance value can be displayed simultaneously with the comparator function or binning function. Four-Terminal Kelvin connection to device under test is provided through the four sheathed banana terminals on the front panel.

Start-Up

The LR2000 Milliohmmeter can be operated from a power source between 90-125V or 190-250V AC at a power line frequency between 48 and 62Hz. Maximum power consumption is 80W. The standard LR2000 unit is shipped from QuadTech with a 1.0A fuse in place for AC 90-125V operation. (A 0.5A fuse is included for AC 190-250V operation). The LR2000 unit is shipped with the line voltage selector set for 115V. Refer to paragraph 1.4.3 for instructions on changing the fuse or line voltage selector.

Connect the LR2000 Milliohmmeter AC power cord to the source of proper voltage. Operate the LR2000 instrument with its chassis connected to earth ground. The LR2000 instrument is shipped with a three-prong power cord to provide this connection to ground. This power cord should only be plugged into a receptacle that provides earth ground. Serious injury may result if the LR2000 instrument is not connected to earth ground.

To turn the LR2000 instrument ON, press the power button on the front panel. To switch the power OFF, press the button again or if measurements are to be made proceed with the Test Parameter Setup in Table COI-1. The LR2000 instrument should warm up for 15 minutes prior to use.

NOTE

Please read this instruction manual in its entirety before operating this instrument. These condensed operating instructions are not a substitute for all the information provided in the remainder of this manual.

NOTE

Refer to paragraphs 2.3 through 2.4 for a full description of programming test parameters and instruction on how to store the test setup. Test parameters must be set before the LR2000 instrument can be zeroed.

Condensed Operating Instructions (Continued)

There are three main menus within the LR2000 Milliohmmeter instrument software. Familiarize yourself with these menus prior to programming a test. Figure COI-1 illustrates the MEAS DISPLAY screen and lists the functions that can be accessed by pressing the [MAIN INDEX] and [SYSTEM SETUP] keys.




Figure COI-1: LR2000 Instrument Menus

NOTE:

To store setups as 'power-on' conditions (default), the [SYSTEM SETUP] key must be pressed following any changes.

NOTE:

The function keys [F1 – F4] are used to select the parameter to change and in some menus to change the value of that selected parameter.

The function of UP/DOWN depends on the menu. In some menus, the LEFT/RIGHT keys are used to select a digit by moving the underscored cursor left or right.

Condensed Operating Instructions (Continued)

1. Set Test Parameters

- Press [POWER] ON.
- Allow the instrument to warm up for 15 minutes.
- Press [MEAS DISPLAY]
- Set test parameters (drive, range, etc) using the function & arrow keys.

2. Correction (Zero)

After setting your test parameters, use the correction function of the LR2000 Milliohmmer to zero the test leads. With no device connected, connect the appropriate cable to the front panel connectors. Short the test leads of the cable together. Refer to paragraph 2.6 for cable connections.

With the instrument in MEAS DISPLAY status:

1. Press [F4] = NEXT PAGE
2. Press [↓] = until ZERO: **OFF** is highlighted
3. Press [F3] = to change OFF to **ON**
4. Short Test Leads
5. Press [TRIGGER] button.
6. Wait while instrument gets CORRECTION value.
7. Press [ANY KEY] to return to MEAS DISPLAY status.





Figure COI-2: SHORT Correction Configuration

Condensed Operating Instructions (Continued)

3. Connection to Device under Test (DUT)

Figure COI-3 illustrates the connection of the LR2000 Milliohmmeter to a single DUT using the LR2000-50 4-Banana to 2-Kelvin Clips test lead set. As labeled on the LR2000-50 Test leads: the DRIVE-, SENSE-, SENSE+ and DRIVE+ connectors are connected to the corresponding front panel terminals on the LR2000 unit: red to (+) and black to (-). The red Kelvin clip is connected to the high side of the DUT and the black Kelvin clip to the low side of the DUT.



COI-3: Connection to Device under Test

4. Make a Measurement

1. Press [MEAS DISPLAY]
2. Connect device under test (DUT) to test leads.
3. Press [TRIGGER].
4. Record measurement.

Section 1: Introduction

1.1 Unpacking and Inspection

Inspect the shipping carton before opening. If damaged, contact the carrier agent immediately. Inspect the LR2000 Milliohmmeter instrument for any damage. If the instrument appears damaged or fails to meet specifications notify QuadTech (refer to instruction manual front cover) or its local representative. Retain the original shipping carton and packing material for future use such as returning the instrument for recalibration or service.

1.2 Product Overview

The LR2000 Milliohmmeter is a precision low resistance meter for production or laboratory testing of individual components, materials, printed circuit boards and other resistive items. The LR2000 instrument provides nine measurement ranges from $20\mu\Omega$ to $2M\Omega$ over seven current ranges from $1\mu A$ to $1A$. The basic measurement accuracy is $\pm 0.05\%$. Measurement rate is selectable (Slow, Medium or Fast) with rates up to 15 measurements per second. Automatic or Hold Range can also be selected. Measurements can be made continuously or triggered with a programmable delay time to 100 seconds. The RS232 interface is standard and the IEEE-488/Handler interface is optional equipment on the LR2000 instrument. An optional Temperature Compensation interface is also available for the LR2000 instrument. The effects of series resistance in the test leads can be zeroed with the short correction function. The LR2000 instrument is equipped with 8 Pass/Fail bins. High and low limits set in the Comparator function display the measured result as a value or percent. Bin number and count can be displayed as well. Four-terminal Kelvin connection to the device under test is obtained through the 4 sheathed banana terminals on the front panel.




Figure 1-1: LR2000 Milliohmmeter

1.3 Controls and Indicators

1.3.1 Front Panel Controls and Indicators

Figure 1-2 illustrates the controls and indicators on the front panel of the LR2000 Milliohmmeter instrument. Table 1-1 identifies them with description and function.




Figure 1-2: LR2000 Front Panel Controls & Indicators

Table 1-1: LR2000 Front Panel Controls & Indicators

Reference # Figure 1-2	Name	Type	Function
1		Green Push Button	Apply AC POWER: 1=ON, 0=OFF
2		Silver Banana Jack	Chassis ground connection
3	DRIVE- SENSE- SENSE+ DRIVE+	2 Black & 2 Red Sheathed Banana Terminals	Current Drive Terminal, Low (-) Voltage Sense Terminal, Low (-) Voltage Sense Terminal, High (+) Current Drive Terminal, High (+)
4	F1, F2, F3 and F4	4 gray push buttons	Select Instrument Functions Keys perform different functions under different menus. Right side of display shows corresponding key function.
5	←, ↓, →, ↑	4 gray push buttons	Move backlit box around display to choose parameter Change parameter value (increase/decrease)
6	TRIGGER	Gray push button	Initiate measurement
7	SYSTEM SETUP	Gray push button	View, Select or Change System Parameters: Calibration, Memory Manage & System Config (Average Time, Beeper, Key Lock, Contrast, Sound Mode, Alarm Mode, Trigger Delay, Trigger Edge, Handler Mode, Meas. Delay, Line Frequency, GPIB Address & Baud Rate)
8	MAIN INDEX	Gray push button	View, Select or Change Setup & Result Parameters: Compare, & Binning
9	MEAS DISPLAY	Gray push button	View, Select or Change Measurement Parameters: Drive, Dry, Trigger, Range, Speed, Zero, Compare and Binning
10		240 x 64 dot matrix Graphic LCD display	Show measurement results as value, % or bin number. Show programming instructions

1.3.2 Rear Panel Controls and Connectors

Figure 1-3 illustrates the controls and connectors on the rear panel of the LR2000 Milliohmmeeter instrument. Table 1-2 identifies them with description and function.




Figure 1-3a: Rear Panel LR2000 Instrument

Table 1-2: LR2000 Rear Panel Controls & Connectors

Ref # Fig. 1-3	Name	Type	Function
1	RS 232 INTERFACE	Silver /Black 9-pin connector	RS 232 interface for remote operation
2	HANDLER INTERFACE*	Blue 24-pin connector	Handler Interface connector for remote operation
3	TC SENSOR*	PT100 connector	Temp Comp Interface- thermal compensation measurements
4	IEEE-488 INTERFACE*	Blue 24-pin connector	IEEE-488 Interface connector for data transfer
5	LINE VOLTAGE SELECTED	2 Red 2-position Slide Switches	Select Voltage Level corresponding to AC Source 90V – 125V: T1.0A 250V fuse 190V – 250V: T 0.5A 250V fuse
6	FUSE	Black Screw cap fuse holder	Short circuit protection T 1.0A 250V fuse for 115V operation T 0.5A 250V fuse for 230V operation
7	AC Line Input	Black 3-wire module	Connection to AC power source

*** NOTE:**

There are two optional interfaces for the LR2000 Milliohmmeeter: P/N 700171: The Handler and IEEE-488 interfaces packaged as a set or P/N 700251: The Handler, Temp Compensation and IEEE-488 interfaces packaged as a set.




Figure: 1-3b: Optional Interfaces

1.4 Installation

1.4.1 Dimensions

The LR2000 Milliohmmeter is supplied in a bench configuration, i.e., in a cabinet with resilient feet for placement on a table. The LR2000 instrument can be tilted up for convenient operator viewing by extending the front feet out.




Figure 1-4: LR2000 Instrument Dimensions

1.4.2 Instrument Positioning

The LR2000 instrument contains one (1) graphic display for direct readout of measured parameters. The optimum angle for viewing is slightly down and about 10 degrees either side of center. For bench operation the front flip feet should always be used to angle the instrument up. In bench or rack mount applications the instrument should be positioned with consideration for ample air flow around the rear panel fan ventilation hole. An open space of at least 3 inches (75mm) is recommended behind the rear panel. Testing should be performed on a non-conductive surface. An ESD mat is not a recommended test platform.

1.4.3 Power Requirements

The LR2000 can be operated from a power source of 90 to 125V AC or 190 to 250V AC. Power connection is via the rear panel through a standard receptacle. Before connecting the 3-wire power cord between the unit and AC power source, make sure the voltage selection switches on the rear panel (Figure 1-5) are in accordance with the power source being used. For a 90-125V source, use a 1.0A 250V fuse. For a 190-250V source, use a 0.5A 250V fuse. Always use an outlet that has a properly connected protection ground.

CAUTION

Make sure the unit has been disconnected from its AC power source for at least five minutes before proceeding.

Procedure for Changing an LR2000 Instrument Fuse

Unscrew the fuse cap on the rear panel of the LR2000 and pull fuse holder outward.

Once the fuse holder has been removed from the instrument snap the fuse from the holder and replace. Make sure the new fuse is of the proper rating.

Install the fuse back into the cap holder by pushing in until it locks securely in place.




Figure 1-5: Close-Up of LR2000 Rear Panel

1.4.4 Safety Inspection

Before operating the instrument inspect the fuse holder on the rear of the LR2000 instrument to ensure that the properly rated fuse is in place, otherwise damage to the unit is possible. Make sure that the voltage selector switches are set in accordance with the power source in use. Refer to paragraph 1.4.3 and Figure 1-5.

The LR2000 instrument is shipped with a standard U.S. power cord, QuadTech P/N 4200-0300 (with Belden SPH-386 socket or equivalent, and a 3-wire plug conforming to IEC 320). Make sure the instrument is only used with these cables (or other approved international cord set) to ensure that the instrument is provided with connection to protective earth ground.

The surrounding environment should be free from excessive dust to prevent contamination of electronic circuits. The surrounding environment should also be free from excessive vibration. Do not expose the LR2000 instrument to direct sunlight, extreme temperature or humidity variations, or corrosive chemicals.

Section 2: Operation

2.1 Terms and Conventions

Table 2-1: Measurement Unit Prefixes

<u>Multiple</u>	<u>Scientific</u>	<u>Engineering</u>	<u>Symbol</u>
1000000000000000	10 ¹⁵	Peta	P
10000000000000	10 ¹²	Tera	T
1000000000	10 ⁹	Giga	G
1000000	10 ⁶	Mega	M
1000	10 ³	Kilo	k
.001	10 ⁻³	milli	m
.000001	10 ⁻⁶	micro	μ
.000000001	10 ⁻⁹	nano	n
.000000000001	10 ⁻¹²	pico	p
.000000000000001	10 ⁻¹⁵	femto	f

Accuracy: The difference between the measured value or reading and the true or accepted value. The accuracy of an ohmmeter is typically given as a \pm percentage of the measured value for primary parameters and \pm an absolute value for secondary value.

Basic Accuracy: Basic accuracy is specified at optimum test signal, frequencies, highest accuracy setting or slowest measurement speed and impedance of the DUT.

Binning: Procedure for sorting components into bins using sequential limits or nested limits.

Capacitor: Abbreviated C (as in LCR). A capacitor is passive component comprised of two conductors separated by a dielectric. A capacitor stores charge blocks DC flow and allows AC flow based on frequency and capacitor design.

Capacitance: The measure of the ratio of charge on either plate of a capacitor to the potential difference (voltage) across the plates. Unit of measure is the Farad (F).

Capacitive Reactance: A measurement of the actual AC resistance of a capacitor. How effective a capacitor allows AC to flow depends upon its capacitance and the frequency used. $X_C = 1 / 2\pi fC$.

Compare: Procedure for sorting components by comparing the measured value against a known standard.

Current:

AC: Alternating Current. AC is an electrical current that has one polarity during part of the cycle and the opposing polarity during the other part of the cycle. Residential electricity is AC.

DC: Direct Current. Non-reversing polarity. The movement of charge is in one direction. Used to describe both current and voltage. Batteries supply direct current (DC).

Dielectric: A material which is an electrical insulator or in which an electric field can be sustained with a minimum dissipation of power.

Dielectric Constant: Abbreviated K, relative dielectric constant. The dielectric constant of a material is the ratio of the capacitance of a capacitor filled with a given dielectric to that same capacitor having only a vacuum as a dielectric.

Discharge: The act of draining off an electrical charge to ground. Devices that retain charge should be discharged after an IR test or DC hipot test.

Drive Voltage: Voltage applied to DUT.

PULSE +/-: Positive/negative square wave: +2V to 0V to -2V to 0V

PULSE +: Positive square wave: +2V to 0V

PULSE -: Negative square wave: -2V to 0V

DC +: Source signal: +2V


DC -: Source signal: -2V

Dry Circuit: The open circuit test voltage across the test leads is clamped at 20mV to avoid puncturing oxide or film resist on the contacts of devices with film/oxide contacts (switches, relays).

DUT: Device Under Test. (i.e. the product being tested).

Equivalent Circuit:

The configuration of the device under test. Is it a series or parallel equivalent circuit?



Frequency:

The rate at which current or voltage reverses polarity and then back again completing a full cycle, measured in Hertz (Hz) or cycles/second. AC Line Frequency = 50/60 Hz.

Ground:

The base reference from which voltages are measured, nominally the same potential as the earth. Ground is also the side of a circuit that is at the same potential as the base reference.

Impedance:

The AC resistance of the DUT. Impedance (Z) is a vector summation of resistance R and reactance X .

For capacitors reactance is defined as $X_C = 1/j\omega C$

For inductors reactance is defined as $X_L = j\omega L$

For resistors resistance is defined as R

Impedance is defined as $Z = \sqrt{X^2 + R^2}$

Inductor:

Abbreviated L (as in LCR). An inductor is a coil of wire. It is used to create electromagnetic induction in a circuit.

Inductance:

The property of a coil to oppose any change in current through it. If the turns (coils) of the wire are stretched out, the field intensity will be less and the inductance will be less. Unit of measure is the Henry (H).

Inductive Reactance:

A measure of how much the counter electro-magnetic force (emf) of the coil will oppose current variation through the coil. The amount of reactance is directly proportional to the current variation: $X_L = 2\pi fL$.

Interface:


- Handler: Device for remote control of test instrument in component handling operations.
- IEEE-488: General Purpose Interface Bus (GPIB). GPIB is an industry standard definition of a Parallel bus connection for the purpose of communicating data between devices.
- RS232: An industry standard definition for a Serial line communication link or port.
- Scanner: An electronic device designed to switch or matrix signals.

Limits:

- Upper: The high limit is the upper value for a test to be considered a pass. If the measured value is higher than the high limit the test is considered a fail.
- Lower: The low limit is the lower value for a test to be considered a pass. If the measured value is lower than the low limit the test is considered a fail.
- Range: The resistance ranges the instrument uses for reference in making the measurement.
- Repeatability: The difference between successive measurements with no changes in the test setup or test conditions.
- Reproducibility: Similar to repeatability but adds the element of what could be expected under real life conditions. Reproducibility would take into account the variability in thing like fixturing where the DUT being tested is removed from the fixture and then inserted again.
- Resolution: The smallest value that can be shown on the display in a digital instrument. LCR meters typically specify a measurement range that is the largest and smallest value that can be shown on the display.

Source Impedance:

A constant source resistance of the measuring instrument used to level the voltage across the DUT to a constant voltage.



Speed:

The rate at which the instrument makes a measurement in measurements per second. Speed is inversely proportional to accuracy.

Trigger:

The device for initiating the test (applying the voltage or current).

External:

The test is initiated via an external source such as a computer with an IEEE-488 or Handler interface. One measurement is made each time the external trigger is asserted on the handler.

Internal:

The instrument continuously makes measurements.

Manual:

The operator initiates the test by pressing the [TRIGGER] button. One measurement is made each time the trigger is pressed.

2.2 Startup

Check to make sure the red Line Voltage Selector switch on the rear panel agrees with the power source available. Depending on the power source the switch position should be in the up or down position as shown in Figure 1-5 (Close-Up of LR2000 Rear Panel).

Connect the instrument power cord to the source of proper voltage. **The instrument is to be used only with three-wire grounded outlets.**

Power is applied to the LR2000 instrument by pressing the green power switch on the front panel to the ON (1 position). The LR2000 unit should warm up for a period of at least 15 minutes prior to measurements being made.

2.3 SYSTEM SETUP

The SYSTEM SETUP menu contains three functions: Calibration, Memory Management and System Configuration. Press the [SYSTEM SETUP] button to access these functions.

NOTE:
To store setups as 'power-on' conditions (default), the [SYSTEM SETUP] key must be pressed following any changes.

2.3.1 Calibration


Calibration is for qualified service personnel only. Factory calibration of the LR2000 instrument to verify resistance ranges is recommended on an annual basis.

2.3.2 Memory Management

Memory Management is for qualified service personnel only. Warning: The Memory Manage function will clear the instrument memory default conditions.

2.3.3 System Configuration

Prior to programming a test or measuring a device, set up the system controls of the LR2000 instrument. To access the system controls, press [SYSTEM SETUP] then press [F3] = SYSTEM CONFIG.




Use the [▲] [▼] arrows to move through the SYSTEM CONFIG list then select the system parameter to configure. Table 2-2 lists the contents of SYSTEM CONFIG.

Table 2-2: SYSTEM CONFIG

Parameter	Function	Range	Default
AVERAGE NO.	Set # of Measurements to Average	01 - 10	01
BEEPER	Set beeper loudness	OFF, HIGH or LOW	HIGH
KEY LOCK	Lock out front panel programming	OFF/ON	OFF
CONTRAST	Set brightness of display	00 - 15	07
SOUND MODE	Set when the buzzer will sound	PASS/FAIL	FAIL
ALARM MODE	Set type of alarm signal	PULSE/CONTINUOUS	PULSE
TRIGGER DELAY	Set external trigger time	0005 – 1000 ms	0005ms
TRIGGER MODE	Set edge for trigger to activate	FALLING/RISING	FALLING
HANDLER MODE	Set handler interface mode	CLEAR/HOLD	CLEAR
MEAS DELAY	Set measurement delay time	0000 – 100 seconds	0.000s
LINE FREQUENCY	Set power line frequency	50Hz/60Hz	60Hz
GPIB ADDRESS	Set interface address	01 – 30	17
BAUD RATE	Set baud rate	1200/2400/4800/9600/19200/38400	19200
CORRECTION TEMP	Set temp to correct measurement to	0°C to 100°C	20°C
THERMAL COEFFICIENT	Set thermal coefficient of DUT	1-9999ppm	0001ppm
TEMPERATURE PROBE	Set type of probe in use	PT100, PT500	PT100

2.3.3.1 AVERAGE NO. (Number)

The number of measurements to take then average can be set from 01 to 10. The instrument default setting is 01. To change the average time press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to AVERAGE NO is highlighted, then press [F1] = DIGIT UP or [F2] = DIGIT DOWN to select the number of measurements to be taken before the average is calculated.



2.3.3.2 BEEPER

The loudness of the beeper or audible alarm can be set to OFF, HIGH or LOW. The instrument default setting is HIGH. To change the beeper loudness press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to BEEPER is highlighted, then press [F1] = HIGH, [F2] = LOW or [F3] = OFF.

Go to KEY LOCK ▼

< SYSTEM CONFIG >		HIGH
AVERAGE NO.	: 03	LOW
BEEPER	: HIGH	
KEY LOCK	: OFF	OFF
CONTRAST	: 07	
SOUND MODE	: FAIL	

F1 Set Beeper Volume to HIGH
 F2 Set Beeper Volume to LOW
 F3 Turn Beeper OFF
 Default: HIGH

2.3.3.3 KEY LOCK

To lock out the front panel operations with the exception of the [TRIGGER] key, set the key lock function to ON. Press [SYSTEM SETUP], [SYSTEM CONFIG], [↓] until OFF is highlighted next to KEY LOCK, then press [F1] = ON. The backlit LOCK block will appear on the measure display.

Go to CONTRAST ▼

< SYSTEM CONFIG >		ON
AVERAGE NO.	: 03	OFF
BEEPER	: HIGH	
KEY LOCK	: OFF	
CONTRAST	: 07	
SOUND MODE	: FAIL	

F1 Front Panel keys are Non-Operational
 F2 Front Panel keys are Operational
 Default: OFF

To turn the key lock function OFF: press [F1], [F4] and then [SYSTEM SETUP]. Key lock can be set ON or OFF. The instrument default setting is OFF.

2.3.3.4 CONTRAST

The display contrast can be set for optimal viewing from 00 – 15 with 15 as the brightest. The instrument default is 07. To change the contrast of the display, press [SYSTEM SETUP], [SYSTEM CONFIG], [↓] until 07 is highlighted next to CONTRAST, then press [F1] = DIGIT UP or [F2] = DIGIT DOWN to lighten or darken the contrast.

Go to SOUND Mode ▼

< SYSTEM CONFIG >		DIGIT UP
AVERAGE NO.	: 03	DIGIT DOWN
BEEPER	: HIGH	
KEY LOCK	: OFF	
CONTRAST	: 07	
SOUND MODE	: FAIL	

F1 Increase brightness of display: 00-15
 F2 Decrease brightness of display: 15-00
 Default: 07

2.3.3.5 SOUND MODE

The audible alarm can be set to sound on PASS or to sound on FAIL under high or low limit judgment in the measure display. The instrument default setting is FAIL. To change the sound mode press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to SOUND MODE is highlighted, then press [F1] = FAIL for the alarm to sound on a fail result or [F2] = PASS for the alarm to sound on a pass result.

Next Page
Go to ALARM Mode

< SYSTEM CONFIG >		FAIL
AVERAGE NO.	: 03	PASS
BEEPER	: HIGH	
KEY LOCK	: OFF	
CONTRAST	: 07	
SOUND MODE	: FAIL	

F1 Select alarm to sound on FAIL
F2 Select alarm to sound on PASS
Default: FAIL

2.3.3.6 ALARM MODE

The type of audible alarm can be set to PULSE or CONTINUOUS during judgment in the measure display. The instrument default setting is PULSE. To change the alarm mode press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to ALARM MODE is highlighted, then press [F1] = PULSE for the alarm to sound in a pulse tone or [F2] = CONTINUOUS for the alarm to sound continuously.

Go to TRIG. DELAY

< SYSTEM CONFIG >		PULSE
ALARM MODE	: PULSE	CONTINUOUS
TRIG. DELAY	: 0005ms	
TRIG. EDGE	: FALLING	
HANDLER MODE	: CLEAR	
MEAS. DELAY	: 0.000s	

F1 Set Alarm Mode to PULSE
F2 Set Alarm Mode to CONTINUOUS
Default: PULSE

2.3.3.7 TRIG. DELAY

The trigger delay is the amount of time between the activation of a trigger (via IEEE, Handler or front panel) and the LR2000 making the measurement. The delay time can be programmed from 0005 to 1000 milliseconds. The instrument default value is 0005 milliseconds. To change the TRIGGER DELAY press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to TRIGGER DELAY is highlighted, then press [F1] = DIGIT UP to increase the delay time or [F2] = DIGIT DOWN to decrease the delay time.

Go to TRIG. EDGE

< SYSTEM CONFIG >		DIGIT UP
ALARM MODE	: PULSE	DIGIT DOWN
TRIG. DELAY	: 0005ms	
TRIG. EDGE	: FALLING	
HANDLER MODE	: CLEAR	
MEAS. DELAY	: 0.000s	

F1 Increase Trigger Delay Time: 0005 - 1000ms
F2 Decrease Trigger Delay Time: 1000 - 0005ms
Default: 0005ms

2.3.3.8 TRIG. EDGE

Select on which edge the measurement is triggered: FALLING or RISING. The instrument default setting is FALLING. To change the TRIGGER EDGE press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to TRIGGER EDGE is highlighted, then press [F1] = FALLING or [F2] = RISING.

The screenshot shows the 'SYSTEM CONFIG' menu with the following settings: ALARM MODE : PULSE, TRIG. DELAY : 0005ms, TRIG. EDGE : FALLING (highlighted), HANDLER MODE : CLEAR, and MEAS. DELAY : 0.000s. To the left, a dropdown menu is open with 'Go to HANDLER MODE' selected. To the right, function keys are defined: F1 is 'Set Trigger to start on FALLING Edge' and F2 is 'Set Trigger to start on RISING Edge'. The default is noted as 'Default: FALLING'.

2.3.3.9 HANDLER MODE

The handler interface mode can be set to CLEAR or HOLD. The instrument default setting is CLEAR. When set to CLEAR, the handler interface will clear the last test result prior to each subsequent measurement. When set to HOLD, the handler interface will hold the last test result until the next measurement is made and displayed. To change the handler mode press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to HANDLER MODE is highlighted, then press [F1] = CLEAR or [F2] = HOLD.

The screenshot shows the 'SYSTEM CONFIG' menu with the following settings: ALARM MODE : PULSE, TRIG. DELAY : 0005ms, TRIG. EDGE : FALLING, HANDLER MODE : CLEAR (highlighted), and MEAS. DELAY : 0.000s. To the left, a dropdown menu is open with 'Go to MEAS. DELAY' selected. To the right, function keys are defined: F1 is 'Set Handler Mode to CLEAR' and F2 is 'Set Handler Mode to HOLD'. The default is noted as 'Default: CLEAR'.

2.3.3.10 MEAS. DELAY

The measurement delay time can be programmed from 0000 to 100.0 seconds. The instrument default value is 0000 seconds. To change the MEAS DELAY press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to MEAS DELAY is highlighted, then press [F1] = DIGIT UP to increase the delay time or [F2] = DIGIT DOWN to decrease the delay time.

The screenshot shows the 'SYSTEM CONFIG' menu with the following settings: ALARM MODE : PULSE, TRIG. DELAY : 0005ms, TRIG. EDGE : FALLING, HANDLER MODE : CLEAR, and MEAS. DELAY : 0.000s (highlighted). To the left, a dropdown menu is open with 'Next Page Go to LINE Frequency' selected. To the right, function keys are defined: F1 is 'Increase Measurement Delay Time: 0.000 - 100.0s' and F2 is 'Decrease Measurement Delay Time: 100.0 - 0.000s'. The default is noted as 'Default: 0.000s'.

2.3.3.11 LINE FREQUENCY

Select the power line frequency: 50Hz or 60Hz. The instrument default setting is 60Hz. To change the LINE FREQUENCY press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to LINE FREQUENCY is highlighted, then press [F1] = 50Hz or [F2] = 60Hz.

Go to GPIB Address	▼	< SYSTEM CONFIG >		50Hz	F1	Set Line Frequency to 50Hz
		LINE FREQ.	: 60Hz	60Hz	F2	Set Line Frequency to 60Hz
		GPIB ADDRESS	: 17			
		BAUD RATE	: 19200			
		CORREC TEMP	: 20.0°C			
		THERM COEFF	: 0001ppm			Default: 60Hz

2.3.3.12 GPIB ADDRESS CODE

The IEEE-488 interface address can be programmed from 01 to 30. The instrument default setting is 17. To change the GPIB ADDRESS press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to GPIB ADDRESS is highlighted, then press [F1] = DIGIT UP to increase the address, or [F2] = DIGIT DOWN to decrease the address.

Go to BAUD RATE	▼	< SYSTEM CONFIG >		DIGIT UP	F1	Increase GPIB Address: 01 - 17
		LINE FREQ.	: 60Hz	DIGIT DOWN	F2	Decrease GPIB Address: 17 - 01
		GPIB ADDRESS	: 17			
		BAUD RATE	: 19200			
		CORREC TEMP	: 20.0°C			
		THERM COEFF	: 0001ppm			Default: 17

2.3.3.13 BAUD RATE

The baud rate is the amount of bits per second transferred via the RS232 interface. The baud rate can be programmed as: 1200, 2400, 4800, 9600, 19200 or 38400 bps. The instrument default value is 19200 bps. To change the BAUD RATE press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to BAUD RATE is highlighted, then press [F1] = 1200, [F2] = 2400, [F3] = 4800 or [F4] = NEXT PAGE 1/2 to page 2 of baud rate settings. On Page 2/2 choose [F1] = 9600, [F2] = 19200, [F3] = 38400 or [F4] = NEXT PAGE 2/2 to return to page 1 of baud rate settings.

Go to NEXT PAGE	F4	< SYSTEM CONFIG >		1200	F1	Set Baud Rate to 1200 bps
		LINE FREQ.	: 60Hz	2400	F2	Set Baud Rate to 2400 bps
		GPIB ADDRESS	: 17	4800	F3	Set Baud Rate to 4800 bps
		BAUD RATE	: 19200	NEXT PAGE 1/2	F4	Go to Baud Rate Settings, Page 2
		CORREC TEMP	: 20.0°C			
		THERM COEFF	: 0001ppm			
Go to CORREC TEMP	▼	< SYSTEM CONFIG >		9600	F1	Set Baud Rate to 9600 bps
		LINE FREQ.	: 60Hz	19200	F2	Set Baud Rate to 19200 bps
		GPIB ADDRESS	: 17	38400	F3	Set Baud Rate to 38400 bps
		BAUD RATE	: 19200	NEXT PAGE 2/2	F4	Go to Baud Rate Settings, Page 1
		CORREC TEMP	: 20.0°C			
		THERM COEFF	: 0001ppm			

2.3.3.14 CORRECTION TEMP

The correction temperature is the temperature that the measured resistance will be corrected to. The correction temperature can be programmed from 0°C to 100°C in increments of 0.1°C. The instrument default setting is 20.0°C. To change the CORRECTION TEMP press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to CORRECTION TEMP is highlighted, then press [F1] = DIGIT UP to increase the correction temperature, [F2] = DIGIT DOWN to decrease the correction temperature or [F4] to change from °C to °F.

Go to THERM COEFF	▼	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="border: 1px solid black; padding: 2px;">< SYSTEM CONFIG ></td> <td style="padding: 2px;">DIGIT UP</td> </tr> <tr> <td style="padding: 2px;">LINE FREQ. : 60Hz</td> <td style="padding: 2px;">DIGIT DOWN</td> </tr> <tr> <td style="padding: 2px;">GPIB ADDRESS : 17</td> <td style="padding: 2px;">_____</td> </tr> <tr> <td style="padding: 2px;">BAUD RATE : 19200</td> <td style="padding: 2px;">_____</td> </tr> <tr> <td style="padding: 2px;">CORREC TEMP : 20.0°C</td> <td style="padding: 2px;">_____</td> </tr> <tr> <td style="padding: 2px;">THERM COEFF : 0001ppm</td> <td style="padding: 2px;">_____</td> </tr> </table>	< SYSTEM CONFIG >	DIGIT UP	LINE FREQ. : 60Hz	DIGIT DOWN	GPIB ADDRESS : 17	_____	BAUD RATE : 19200	_____	CORREC TEMP : 20.0°C	_____	THERM COEFF : 0001ppm	_____	<table border="0"> <tr> <td style="border: 1px solid gray; padding: 2px;">F1</td> <td>Increase Correction Temperature: 0°C to 100°C in 0.1°C increments</td> </tr> <tr> <td style="border: 1px solid gray; padding: 2px;">F2</td> <td>Decrease Correction Temperature: 100°C to 0°C in 0.1°C increments</td> </tr> </table> <p style="margin-top: 5px;">Default: 20.0°C</p>	F1	Increase Correction Temperature: 0°C to 100°C in 0.1°C increments	F2	Decrease Correction Temperature: 100°C to 0°C in 0.1°C increments
		< SYSTEM CONFIG >	DIGIT UP																
LINE FREQ. : 60Hz	DIGIT DOWN																		
GPIB ADDRESS : 17	_____																		
BAUD RATE : 19200	_____																		
CORREC TEMP : 20.0°C	_____																		
THERM COEFF : 0001ppm	_____																		
F1	Increase Correction Temperature: 0°C to 100°C in 0.1°C increments																		
F2	Decrease Correction Temperature: 100°C to 0°C in 0.1°C increments																		

2.3.3.15 THERMAL COEFFICIENT

The thermal coefficient can be set from 1ppm to 9999ppm. The instrument default setting is 0001ppm. To change the THERMAL COEFFICIENT press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to THERMAL COEFFICIENT is highlighted, then press [F1] = DIGIT UP to increase the thermal coefficient or [F2] = DIGIT DOWN to decrease the thermal coefficient.

Go to TEMP PROBE	▼	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="border: 1px solid black; padding: 2px;">< SYSTEM CONFIG ></td> <td style="padding: 2px;">DIGIT UP</td> </tr> <tr> <td style="padding: 2px;">LINE FREQ. : 60Hz</td> <td style="padding: 2px;">DIGIT DOWN</td> </tr> <tr> <td style="padding: 2px;">GPIB ADDRESS : 17</td> <td style="padding: 2px;">_____</td> </tr> <tr> <td style="padding: 2px;">BAUD RATE : 19200</td> <td style="padding: 2px;">_____</td> </tr> <tr> <td style="padding: 2px;">CORREC TEMP : 20.0°C</td> <td style="padding: 2px;">_____</td> </tr> <tr> <td style="padding: 2px;">THERM COEFF : 0001ppm</td> <td style="padding: 2px;">_____</td> </tr> </table>	< SYSTEM CONFIG >	DIGIT UP	LINE FREQ. : 60Hz	DIGIT DOWN	GPIB ADDRESS : 17	_____	BAUD RATE : 19200	_____	CORREC TEMP : 20.0°C	_____	THERM COEFF : 0001ppm	_____	<table border="0"> <tr> <td style="border: 1px solid gray; padding: 2px;">F1</td> <td>Increase Thermal Coefficient 1ppm to 9999ppm</td> </tr> <tr> <td style="border: 1px solid gray; padding: 2px;">F2</td> <td>Decrease Thermal Coefficient 9999ppm to 1ppm</td> </tr> </table> <p style="margin-top: 5px;">Default: 0001ppm</p>	F1	Increase Thermal Coefficient 1ppm to 9999ppm	F2	Decrease Thermal Coefficient 9999ppm to 1ppm
		< SYSTEM CONFIG >	DIGIT UP																
LINE FREQ. : 60Hz	DIGIT DOWN																		
GPIB ADDRESS : 17	_____																		
BAUD RATE : 19200	_____																		
CORREC TEMP : 20.0°C	_____																		
THERM COEFF : 0001ppm	_____																		
F1	Increase Thermal Coefficient 1ppm to 9999ppm																		
F2	Decrease Thermal Coefficient 9999ppm to 1ppm																		

2.3.3.16 TEMPERATURE PROBE

The temperature probe can be set to PT100 or PT500. The instrument default setting is PT100. To change the TEMPERATURE PROBE press [SYSTEM SETUP], [SYSTEM CONFIG] and the down arrow [↓] until the box next to TEMPERATURE PROBE is highlighted, then press [F1] = PT100 or [F2] = PT500.

Go to AVERAGE NO.	▼	<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="border: 1px solid black; padding: 2px;">< SYSTEM CONFIG ></td> <td style="padding: 2px;">PT100</td> </tr> <tr> <td style="padding: 2px;">TEMP PROBE : PT100</td> <td style="padding: 2px;">PT500</td> </tr> <tr> <td style="padding: 2px;">_____</td> <td style="padding: 2px;">_____</td> </tr> <tr> <td style="padding: 2px;">_____</td> <td style="padding: 2px;">_____</td> </tr> </table>	< SYSTEM CONFIG >	PT100	TEMP PROBE : PT100	PT500	_____	_____	_____	_____	<table border="0"> <tr> <td style="border: 1px solid gray; padding: 2px;">F1</td> <td>Select PT100 Probe</td> </tr> <tr> <td style="border: 1px solid gray; padding: 2px;">F2</td> <td>Select PT500 Probe</td> </tr> </table> <p style="margin-top: 5px;">Default: PT100</p>	F1	Select PT100 Probe	F2	Select PT500 Probe
		< SYSTEM CONFIG >	PT100												
TEMP PROBE : PT100	PT500														
_____	_____														
_____	_____														
F1	Select PT100 Probe														
F2	Select PT500 Probe														

NOTE: Recall that when any system parameters are changed, to store setups as ‘power-on’ conditions (default), the [SYSTEM SETUP] key must be pressed following any changes.

2.4 MEAS DISPLAY

The LR2000 instrument's stand-by display is the MEAS DISPLAY. After power has been applied to the instrument and it cycles quickly through the information screen, the instrument reverts to the MEAS DISPLAY. To view the instrument information screen as illustrated in Figure 2.1, press [SYSTEM SETUP] then [←].




Figure 2.1: Instrument Information Screen






Figure 2.2: MEAS DISPLAY

Figure 2.2 illustrates the three pages of parameters that can be programmed within the MEAS DISPLAY. The binning and comparison functions are enabled/disabled in MEAS DISPLAY and programmed in MAIN INDEX Paragraphs 2.4.1 through 2.4.9 explain each parameter in detail.


2.4.1 DRIVE

The LR2000 instrument provides six test modes: PULSE+/-, PULSE+, PULSE-, DC+, DC- and STBY. In MEAS DISPLAY, press [F1] so that the highlighted cursor is to the right of DRIVE. Press [F1] to toggle through and select test mode. The instrument default setting is PULSE+/- . The PULSE+/- mode is a positive/negative square wave that switches the source signal from +2V to 0V to -2V to 0V. The PULSE+ mode is a positive square wave that switches the source signal for +2V to 0V. The PULSE- mode is a negative square wave that switches the source signal for -2V to 0V. The DC+ mode provides the source signal equal to +2V. The DC- mode provides the source signal equal to -2V. The STBY mode puts the instrument in stand-by status.




2.4.2 DRY Circuit

For low resistance measurements made on devices with film or oxide contacts (switches, relays), select DRY circuit = ON to hold the open circuit voltage across the instrument's test leads clamped at 20mV. This will avoid puncturing the oxidation or film resist on the contacts. Press [F1] to enable the dry circuit function. Press [F2] to disable the dry circuit function. The instrument default setting is OFF.



2.4.3 TRIGGER


The LR2000 instrument can be triggered manually, internally or externally. In MEAS DISPLAY (Pg 1/3), press [F3] so that the highlighted cursor is to the right of TRIG. Use the [F3] key to change the trigger. The instrument default setting is INT (internal trigger). When MANUAL trigger is selected, one measurement will be made each time the trigger is pressed. When EXTERNAL trigger is selected, one measurement will be made each time the external trigger is asserted by the handler. When INTERNAL trigger is selected, measurements are performed continuously when in [MEAS DISPLAY].



DRIVE : DC+
DRY : OFF
TRIG. : F3 Select Trigger:
MAN, INT or EXT
NEXT PAGE 1/3

2.4.4 RANGE

The LR2000 instrument's measurement range can be selected as AUTO or HOLD. The instrument measurement ranges are 20mΩ, 200mΩ, 2Ω, 20Ω, 200Ω, 2kΩ, 20kΩ, 200kΩ and 2MΩ. In MEAS DISPLAY (Pg 2/3) press [F1] so that the box is highlighted. Use the right arrow [⇒] to toggle between A (Auto) and H (Hold). Press [F1] to increase or decrease the range value. The instrument default setting is A (Auto Range). When Dry Circuit is ON, only the 200mΩ, 2Ω and 20Ω ranges are available.



RANGE : 20mΩ F1 Select measurement range
SPEED : FAST Toggle: Auto and Hold
ZERO : OFF
NEXT PAGE 2/3

20mΩ, 200mΩ, 2Ω, 20Ω, 200Ω, 2kΩ, 20kΩ, 200kΩ, 2MΩ

Table: 2-3: Full Scale Measurement Ranges

Full-Scale Range	20mΩ	200mΩ	2Ω	20Ω	200Ω	2kΩ	20kΩ	200kΩ	2MΩ
Resolution	1μΩ	10μΩ	100μΩ	1mΩ	10mΩ	100mΩ	1Ω	10Ω	100Ω

2.4.5 SPEED

The LR2000 instrument can be programmed for Slow (1.5measurements/second), Medium (6 measurements/second) or Fast (15 measurements/second) test times. The basic accuracy (0.05%) is specified for the slow measurement speed. In MEAS DISPLAY (Pg 2/3) press [F2] so that **FAST** is highlighted. Press [F2] to increase/decrease the speed. The instrument default setting is FAST (15 measurements/second).

< MEAS DISPLAY >		RANGE : H 20mΩ
Rx :	2.549 mΩ	SPEED : FAST
		ZERO : INT.
		NEXT PAGE 2/3

F2 Select measurement speed
 FAST: 15 measurements/second
 MEDIUM: 6 measurements/second
 SLOW: 1.5 measurements/second

2.4.6 ZERO

Short circuit compensation can be performed on the test leads/fixture by selecting the ZERO function = ON. In MEAS DISPLAY (Pg 2/3), press [F3] so that the box next to ZERO is highlighted. Press [F3] to select ZERO ON or OFF. The instrument default setting is OFF.

< MEAS DISPLAY >		RANGE : A 20mΩ
Rx :	2.549 mΩ	SPEED : MEDIUM
		ZERO : OFF
		NEXT PAGE 2/3

F3 Short Circuit Compensation: ON/OFF

2.4.7 COMPARE

To enable/disable the compare function, in MEAS DISPLAY (Pg 3/3), press [F1] so that the box next to COMPARE is highlighted. Press [F1] to switch the compare function ON/OFF*. The instrument default setting is OFF. Setting the comparison values is done within the MAIN INDEX menu. Refer to paragraph 2.5.1 for instructions on setup of Compare.

< MEAS DISPLAY >		COMPARE : OFF
Rx :	2.549 mΩ	BINNING : OFF
		TEMP. : OFF
		NEXT PAGE 3/3

F1 Enable/Disable Compare function
 ON-VAL Absolute Value
 ON-Δ Delta Absolute Value
 ON-Δ% Delta Percent Absolute Value
 OFF Compare Function: OFF

< MEAS DISPLAY >		COMPARE : ON - Δ%
Rx :	2.549 mΩ	BINNING : OFF
Δ% :		TEMP. : OFF
PASS		NEXT PAGE 3/3

*** Notes on Compare Settings:**


Setting COMPARE = ON will display the measured reading in addition to a PASS. A LO reading is lower than the set nominal value and a HI reading is higher than the set nominal value.

Setting COMPARE = ON-Δ will display the measured value and the difference between the measured value and the set nominal value. A PASS, LO, or HI judgment is also displayed.


Setting COMPARE = ON-Δ% will display the measured value and the percent difference between the measured value and the set nominal value. A PASS, LO, or HI judgment is also displayed.

2.4.8 BINNING

The LR2000 instrument has 8 pass/fail bins for sorting components by test result. To enable/disable the binning function, in MEAS DISPLAY (Pg 3/3) press [F2] so that the box next to BINNING is highlighted. Press the [F2] key to switch the binning function ON/OFF. The instrument default setting is OFF. Setting the bin values is done within the MAIN INDEX menu. Refer to paragraph 2.5.2 for instructions on setup of Binning.



F2 Enable/Disable Binning function



2.4.9 TEMP

The LR2000's optional temperature measurement can be programmed for AUTO (temp. measurement from probe), 20.0°C (temp. held at 20.0°C) or OFF (disabled). To enable/disable the temperature function in MEAS DISPLAY (Pg 3/3) press [F3] so that the box next to TEMP is highlighted. Press the [F3] key to switch through AUTO/20.0°C/OFF. The instrument default setting is OFF. A temperature measurement will be made each time the LR2000 is triggered, so for continuous temperature measurements the trigger must be set to INT.

The figure shows two screenshots of the LR2000 MEAS DISPLAY screen. The top screenshot shows the following information: < MEAS DISPLAY >, Rx : 2.549 mΩ, COMPARE : OFF, BINNING : OFF, TEMP. : OFF, and NEXT PAGE 3/3. The bottom screenshot shows: < MEAS DISPLAY >, Rx : 2.459 mΩ, TEMP: 25.3°C, COMPARE : OFF, BINNING : ON, TEMP. : AUTO, and NEXT PAGE 3/3. To the right of the screenshots is a legend: F3 Set Temperature Compensation, AUTO: Temp measured by probe, 20.0°C: Temp held at 20.0°C, and OFF: Temperature Compensation disabled.

2.5 MAIN INDEX

Within the LR2000 instrument's MAIN INDEX are the Binning, Compare and Temperature Conversion Setting Functions. To access these functions press [MAIN INDEX] and the display should look as shown in Figure 2-4.

The figure shows a screenshot of the LR2000 MAIN INDEX screen. The screen displays < MAIN INDEX > at the top left and three menu options: COMPARE, BINNING, and TEMP CONV. To the right of the screen is a legend: F1 Enter Compare function, F2 Enter Binning function, and F2 Enter Temperature Conversion function.

Figure 2-4: MAIN INDEX

2.5.1 COMPARE

To set up a comparison test, use the COMPARE function. To access the COMPARE function, press [MAIN INDEX] then press [F1] = COMPARE. Press [F1] = SETTING to set the nominal, upper and lower judgment limits. Press [F1] = DIGIT UP and [F2] = DIGIT DOWN to increase and decrease the limits. Press [F4] to select the mode equal to percent or absolute value.

	<div style="display: flex; justify-content: space-between; align-items: center;"> < MAIN INDEX > <div style="text-align: right;"> <p>COMPARE</p> <hr/> <p>BINNING</p> <hr/> <p>TEMP CONV</p> </div> </div>	<p>F1 Enter Compare function</p> <p>F2 Enter Binning function</p> <p>F2 Enter Temperature Conversion function</p>
<p>F1 SETTING</p>	<div style="display: flex; justify-content: space-between; align-items: center;"> < MAIN INDEX : COMPARE > <div style="text-align: right;"> <p>SETTING</p> <hr/> <hr/> <hr/> </div> </div>	<p>F1 Set Compare Nominal, Upper & Lower Values</p>
<p>Move Cursor: UP ▲</p> <p>Move Cursor: DOWN ▼</p>	<div style="display: flex; justify-content: space-between; align-items: center;"> < COMPARE SET > <div style="text-align: right;"> <p>DIGIT UP</p> <hr/> <p>DIGIT DOWN</p> <hr/> <p>DIGIT</p> <hr/> <p>MODE : %</p> </div> </div> <div style="margin-top: 5px;"> <p>NOMINAL : <u>0</u>08.0000 mΩ</p> <p>UPPER : +010.4995 %</p> <p>LOWER : -010.0000 %</p> <p>Press MAIN INDEX to exit</p> </div>	<p>F1 Increase value of underscored digit</p> <p>F2 Decrease value of underscored digit</p> <p>F3 Move underscore cursor to next digit (L & R arrows also move cursor to next digit)</p> <p>F4 Set Compare Upper/Lower Limits as Percent Value</p>
<p>Move Cursor: UP ▲</p> <p>Move Cursor: DOWN ▼</p>	<div style="display: flex; justify-content: space-between; align-items: center;"> < COMPARE SET > <div style="text-align: right;"> <p>DIGIT UP</p> <hr/> <p>DIGIT DOWN</p> <hr/> <p>DIGIT</p> <hr/> <p>MODE : ABS</p> </div> </div> <div style="margin-top: 5px;"> <p>NOMINAL : <u>0</u>08.0000 mΩ</p> <p>UPPER : 008.3999 mΩ</p> <p>LOWER : 007.2000 mΩ</p> <p>Press MAIN INDEX to exit</p> </div>	<p>F1 Increase value of underscored digit</p> <p>F2 Decrease value of underscored digit</p> <p>F3 Move underscore cursor to next digit (L & R arrows also move cursor to next digit)</p> <p>F4 Set Compare Upper/Lower Limits as Absolute value</p>

* Notes on Compare Settings:

Setting COMPARE = ON will display the measured reading in addition to a PASS. A LO reading is lower than the set nominal value and a HI reading is higher than the set nominal value.

Setting COMPARE = ON-Δ will display the measured value and the difference between the measured value and the set nominal value. A PASS, LO, or HI judgment is also displayed.

Setting COMPARE = ON-Δ% will display the measured value and the percent difference between the measured value and the set nominal value. A PASS, LO, or HI judgment is also displayed.

2.5.2 BINNING

To enter the Bin Setting functions for the LR2000 instrument, press [MAIN INDEX] then [F2] = BINNING.

<div style="border: 1px solid black; padding: 5px;"> <div style="border: 1px solid black; display: inline-block; padding: 2px 10px;">< MAIN INDEX ></div> <div style="margin-left: 20px;"> <p>COMPARE</p> <hr/> <p>BINNING</p> <hr/> <p>TEMP CONV</p> <hr/> </div> </div>	<p>F1 Enter Compare function</p> <p>F2 Enter Binning function</p> <p>F2 Enter Temperature Conversion function</p>
<div style="border: 1px solid black; padding: 5px;"> <div style="border: 1px solid black; display: inline-block; padding: 2px 10px;">< MAIN INDEX BINNING ></div> <div style="margin-left: 20px;"> <p>SETTING</p> <hr/> <hr/> <hr/> <p>COUNT</p> </div> </div>	<p>F1 Set Bin Nominal, High & Low Values</p> <p>F4 View Results by Bin # and Count</p>
<div style="border: 1px solid black; padding: 5px;"> <div style="border: 1px solid black; display: inline-block; padding: 2px 10px;">< BINNING SET ></div> <div style="margin-left: 20px;"> <p>DIGIT UP</p> <hr/> <p>DIGIT DOWN</p> <hr/> <p>DIGIT</p> </div> </div> <p>NOMINAL <u>3</u>10.0000 Ω</p>	<p>F1 Increase value of underscored digit</p> <p>F2 Decrease value of underscored digit</p> <p>F3 Move underscore cursor to next digit (L & R arrows also move cursor to next digit)</p>

- Press [F1] = SETTING to enter the BINNING SET Display.
- To set the nominal value, press [F1] = DIGIT UP to increase the value of the underscored digit.
- Press [F2] = DIGIT DOWN to decrease the value of the underscored digit.
- Press [F3] = DIGIT to move the underscored digit right. The left [←] and right [→] arrow keys also move the underscored digit left or right on a single line.
- Once the nominal value is set, press the [↓] down arrow key to set the bin limits.

BINNING SET Display:

Set Bin 1 High Limit.

< BINNING SET >				DIGIT UP	F1	Increase value of underscored digit
BIN	HI	LO		DIGIT DOWN	F2	Decrease value of underscored digit
1	+010.0000 %	-010.0000 %		DIGIT	F3	Move underscore cursor to next digit (L & R arrows also move cursor to next digit)
2	+020.0000 %	-020.0000 %				
3	+030.0000 %	-030.0000 %				
4	+040.0000 %	-040.0000 %				

Press the right arrow [⇒] key to move from Bin 1 HI to Bin 1 LO. Set Bin 1 Low Limit.
 Press the left arrow [⇐] key and the down arrow [↓] key to go to Bin 2. Set Bin 2 High Limit.
 Press the right arrow [⇒] key to move from Bin 2 HI to Bin 2 LO. Set Bin 2 Low Limit.
 Press the left arrow [⇐] key and the down arrow [↓] key to go to Bin 3. Set Bin 3 High Limit.
 Press the right arrow [⇒] key to move from Bin 3 HI to Bin 3 LO. Set Bin 3 Low Limit.

Continue this setting process until all bin HI and LO limits are set.

< BINNING SET >				DIGIT UP	F1	Increase value of underscored digit
BIN	HI	LO		DIGIT DOWN	F2	Decrease value of underscored digit
5	+000.0000 %	-000.0000 %		DIGIT	F3	Move underscore cursor to next digit (L & R arrows also move cursor to next digit)
6	+000.0000 %	-000.0000 %				
7	+000.0000 %	-000.0000 %				
8	+000.0000 %	-000.0000 %				

When the nominal, and all the bin values are set, press the [F4] key to view bin setup. To exit the Binning menu, press the [MAIN INDEX] key.

To View the BINNING COUNT screen:

Press [MAIN INDEX], [F2] = BINNING and then press [F4] = COUNT. The display will list the results of the 8 bins plus the total for all bins used.

BIN	COUNT	BIN	COUNT	RESET	F1	Reset bin counts to 0.
0	0	5	0	_____		
1	0	6	0	_____		
2	0	7	0	_____		
3	0	8	0	_____		
4	0	OUT	0	_____		
TOTAL:			0			

Two of the most common methods of sorting results into bins are using nested limits or sequential limits.

Nested Limits

Nested limits are a natural choice for sorting components by % tolerance around a single nominal value with the lower bins narrower than the higher numbered bins. Nested limits for three bins are illustrated in Figure 2-5. Note that the limits do not have to be symmetrical (Bin 3 is -7% and $+10\%$).




Figure 2-5: Nested Limits

Sequential Limits

Sequential limits are a natural choice when sorting components by absolute value. Figure 2-6 illustrates the use of sequential limits for a total of three bins. Sequential bins do not have to be adjacent. Their limits can overlap or have gaps depending upon the specified limit. Any component that falls into an overlap between bins would be assigned to the lower numbered bin and any component that falls into a gap between bins would be assigned to the overall fail bin.




Figure 2-6: Sequential Limits

2.5.3 TEMP CONV

To set up the temperature conversion function, use the TEMP CONV function. To access the TEMP CONV function, press [MAIN INDEX] then press [F3] = TEMP CONV. Press [F1] = SETTING to set the initial resistance (INIT RESISTANCE), initial temperature (INIT TEMP) and the inverse of the temperature coefficient normalized to 0°C (CONSTANT). Press [F1] = DIGIT UP, [F2] = DIGIT DOWN and [F3] = DIGIT to increase the value, decrease the value and change the cursor position, respectively.

<div style="border: 1px solid black; padding: 2px; display: inline-block;">< MAIN INDEX ></div>	COMPARE <hr/> BINNING <hr/> TEMP CONV	F1 Enter Compare function F2 Enter Binning function F2 Enter Temperature Conversion function
<div style="border: 1px solid black; padding: 2px; display: inline-block;">< MAIN INDEX TEMP CONV ></div>	SETTING <hr/> <hr/> <hr/>	F1 Set Temperature Conversion factors: Set Initial Resistance Set Initial Temperature Set Inverse of Temperature Coefficient
<div style="border: 1px solid black; padding: 2px; display: inline-block;">< INIT RESISTANCE ></div> NOMINAL <u>3</u> 10.0000 Ω	DIGIT UP <hr/> DIGIT DOWN <hr/> DIGIT	F1 Increase value of underscored digit F2 Decrease value of underscored digit F3 Move underscore cursor to next digit (L & R arrows also move cursor to next digit)
<div style="border: 1px solid black; padding: 2px; display: inline-block;">< INIT TEMP ></div> AMBIENT: 25.3°C	DIGIT UP <hr/> DIGIT DOWN <hr/> DIGIT	F1 Increase value of underscored digit F2 Decrease value of underscored digit F3 Move underscore cursor to next digit (L & R arrows also move cursor to next digit)
<div style="border: 1px solid black; padding: 2px; display: inline-block;">< CONSTANT ></div> T: 20.0°C	DIGIT UP <hr/> DIGIT DOWN <hr/> DIGIT	F1 Increase value of underscored digit F2 Decrease value of underscored digit F3 Move underscore cursor to next digit (L & R arrows also move cursor to next digit)

*** Notes about temperature conversion:**

After the test is setup press [MAIN INDEX], [F4] = MEASURE to start measurements. There will be three options that are changeable; [F1] = RANGE (same as in 2.4.4), [F2] = DISP (selectable as either T for temperature, or ΔT for change in temperature) or [F3] = TEMP. (same as in 2.4.9).

2.6 Connection to Device under Test

Figure 2-9 illustrates the connection of the LR2000 to a single DUT using the LR2000-50 Kelvin Clip Cable lead set. The red Kelvin clip is connected between the Drive (+) and Sense (+) terminals on the LR2000 unit. The black Kelvin clip is connected between the Drive (-) and Sense (-) terminals on the LR2000 unit.




Figure 2-9: LR2000-50 Kelvin Clip Test Leads

2.7 Measurement Procedure

Before a measurement is made verify the following:

1. The rear panel voltage selector switch is set to the correct line voltage.
2. The LR2000 instrument is turned ON.
3. The LR2000 has had a 15-minute warm-up.
4. The Display is set to MEAS DISPLAY.
5. All test parameters programmed.
6. The test cables or fixture is connected.
7. A ZERO function is performed (if desired).
8. The device under test is connected.

To initiate a test:

Press [TRIGGER].

The LR2000 instrument judges the measurement value based on the COMPARE and BINNING functions set up previously. Refer to paragraphs 2.5.1 and 2.5.2 for instructions on setting these judgment parameters. Upon completion of the test the output voltage is terminated and the display shows the test result.

Section 3: Interface

3.1 RS-232 Interface

3.1.1 RS-232 Pin Configuration

The LR2000 instrument comes standard with an RS232 Interface for remote operation. Connection is through the black/silver 9-pin connector labeled 'RS232' on the rear panel of the LR2000 instrument. Figure 3-1 illustrates the designation of the pins on the RS232 connector. The connection cable must be a 'straight through' cable for the LR2000 unit to communicate.




Figure 3-1: RS-232 Interface Pin Configuration

3.1.2 RS232 Specifications

Data Bits:	8
Stop Bits:	1
Parity:	None, Odd, Even
Baud Rate:	1200, 2400, 4800, 9600, 19200 or 38400bps, Software selectable
EOS:	LF or CR + LF
Echo:	Off

Refer to paragraph 2.3.3.13. Setting the Baud Rate is done in the SYSTEM CONFIGURATION function under SYSTEM SETUP settings:

- From the STAND BY display, press [SYSTEM SETUP]
- Press [F3] = SYSTEM CONFIG.
- Press [↓] = until the box next to BAUD RATE is highlighted.
- Press [F1] = INCREASE or [F2] = DECREASE to select baud rate.
- Press [F4] to EXIT

3.1.3 RS232 Commands

The command set for the RS232 interface is the same as the IEEE-488 interface command set listed in paragraphs 3.2.3 through 3.2.5 of this instruction manual.

The following command is for RS232 only:

:SYSTem:LOCal ==> Change status to local, as GPIB Go To Local

NOTE

CR + LF are necessary end codes for the RS232 commands.

Additional RS232 Commands

Some commands for RS232 use only are listed here. These commands follow the SCPI version 1999.0

:SYSTem:LOCK:OWNer?==> Query the statue.
:SYSTem:LOCK:<Boolean> ==> As GRIB Local Lockout.
:SYSTem:LOCK?==> Query the Key Lock status.
:SYSTem:LOCal → Change the status to Local.

3.1.4 Sample QuickBasic Program

This is a simple quick basic program for the LR2000 milliohmmeter.
This is for RS232 communication at a baud rate set to 9600
The program reads *idn from LR2000
The program asks how many measurements to make,
It then sends trigger command to the LR2000 and displays the measured results.

```
Print "Calculating Delay Loops ....."
Rem delay correction routine
q = 1
Do While Environ$(q) <> ""
  If Left$(Environ$(q), 7) = "MACHINE" Then
    qq = q
    mn = Val(Right$(Environ$(q), 1))
    mn$ = Right$(Environ$(q), 1)
  End If
  q = q + 1
```



```

Loop
error1:
t1 = Timer
s = 0
For i = 1 To 30000
Next i
t2 = Timer
k = t2 - t1
If k = 0 Then GoTo error1
k2 = 40000 / k

Open "COM1:9600,n,8,1,cs,ds" For Random As #1:

Rem Get identification string from LR2000
For j = 1 To k2: Next j
Print #1, "*cls"; Chr$(13); Chr$(10)
Print #1, "*idn?"; Chr$(13); Chr$(10)
For j = 1 To k2: Next j
GoSub cget
r45$ = Input$(x, #1)
Print "Identification String is;"
Print r45$
Print ""
Print ""
Print "Enter number of measurements to make"
INPUT nummeas

Cls
For i = 1 To nummeas
For j = 1 To k2: Next j
Print #1, "*cls"; Chr$(13); Chr$(10)

Print #1, "*TRG"; Chr$(13); Chr$(10)
GoSub cget
r45$ = Input$(x, #1)
Print ""
Print "Measurement" + Str$(i)
Print r45$
Next i

Close #1
Print ""
Print "End of Program"
End

cget:
' subroutine to get serial input loop until first character is received
Do While (Loc(1) = 0)
For j = 1 To k2: Next j
Loop
' then get the rest of the string
y = x + Loc(1)
Do While (x <> y)
y = x
For j = 1 To k2 / 10: Next j
x = Loc(1)

```


Loop
'PRINT x
Return

3.2 IEEE-488 Interface

3.2.1 Pin Configuration

An IEEE-488 Interface (illustrated in Figure 3-2) is an available option for the LR2000 instrument. Connection is through the blue 24-pin connector labeled 'IEEE-488 INTERFACE' on the rear panel of the LR2000 instrument. This interface can be used to connect a system containing a number of instruments and a controller in which each meets IEEE Standard 488.2 (Standard Digital Interface for Programmable Instrumentation).

LR2000 IEEE-488 Interface PIN Configuration: Rear Panel View



LR2000 IEEE-488 Interface
PIN Designation




Figure 3-2: IEEE-488 Interface Pin Configuration

Table 3-1 lists the IEEE-488 Interface pin designations by pin number, signal name and pin function. Bus and driver information is also listed.

Table 3-1: IEEE-488 Interface Pin Designations

Bus	Driver	Signal Name	Pin Number	Function
Handshake	3 States	DAV	6	Low State: "Data is Available" and valid on DI01 through DI08
	Open Collector	NRFD	7	Low State: At least one Listener on the bus is "Not Ready For Data"
	Open Collector	NDAC	8	Low State: At least one Listener on the bus is "Not Accepting Data"
Control	3 States	ATN	11	"Attention" specifies 1 of 2 uses for the DI01 through DI08 lines: Low State: Controller command messages High State: Data bytes from the Talker device
	3 States	IFC	9	"Interface Clear" Low State: Returns portion of interface system to a known quiescent state
	Open Collector	SRQ	10	"Service Request" Low State: A Talker or Listener signals (to the controller) need for attention in the midst of the current sequence of events.
	3 States	REN	17	"Remote Enable" Low State: Enables each device to enter remote mode when addressed to listen. High State: All devices revert to Local control.
	3 States	EOI	5	"End of Identify" If ATN is in HIGH state, then EOI LOW state indicates the end of a multiple-byte data transfer sequence. If ATN is in LOW state, then EOI LOW state indicates a parallel poll.
Data	Open Collector	DI01	1	The 8-Line Data Bus. If ATN is in LOW state, then the bus conveys interface messages. If ATN is in HIGH state, then the bus conveys device-dependent messages. (Example: carries remote control commands from the controller or from a talker device)
		DI02	2	
		DI03	3	
		DI04	4	
		DI05	13	
		DI06	14	
		DI07	15	
		DI08	16	

3.2.2 IEEE-488 Interface Function Codes and Messages

The IEEE-488 (GPIB) address is defined under the SYSTEM SETUP in the SYSTEM CONFIG menu. Press [SYSTEM SETUP], then the numerical key [F3] to enter the SYSTEM CONFIG menu. Press down arrow [↓] to enter the GPIB ADDRESS code. To select a new IEEE-488 address, use the function keys. Refer to paragraph 2.3.3.12 for more information. The default setting for the IEEE address is 17.

Table 3-2 defines the IEEE-488 interface codes and their function. Table 3-3 defines the IEEE-488 interface messages the LR2000 instrument responds to and their function.

Table 3-2: IEEE-488 Interface Functions

Code	Function
SH1	Source Handshake (Talker)
AH1	Acceptor Handshake (Listener)
T6	Basic Talker Function
	Serial Poll Function
	Listener-specified Talker Release Function
	No TALK-ONLY Function
L4	Basic Listener Function
	Talker-specified Listener Release Function
SR1	Service Request Function
RL1	All Remote/Local Functions
PP0	No Parallel Poll Function
DC1	Device Clear Function
DT1	Device Trigger Function
C0	No Controller Functions

Table 3-3: IEEE-488 Interface Messages

Interface Message	Function	Description
GTL	Go To Local	Only addressed devices that receive this command are set to local mode. Cancels the remote control mode, making the front panel switches operative.


Table 3-4 lists the IEEE-488 interface commands the LR2000 instrument accepts to set or query a parameter value. Paragraphs 3.2.3 through 3.2.5 detail command function, format, return value and description.

Table 3-4: IEEE-488 Commands

Command	Name	Function	Output Format
*CLS	Clear Status	Clear standard event status register. Clear status bit group register except for bit 4 (MAV)	
*ESE	Event Status Enable	Enable standard event status register value.	0 – 255
*ESE?	Event Status Enable	Query standard event status of device enable register	0 – 255
*ESR?	Event Status Register	Query standard event register value of device. After this command, the standard register is cleared to 0.	0 – 255
*IDN?	Identification	Query/Read basic device data. (A comma separates the identification fields.)	4 ID: Manufacturer, Device Model, Serial Number, Firmware Version
*OPC	Operation Complete	Operation is complete.	0
*OPC?	Operation Complete	Query operation complete.	1
*RST	Reset	Reset Device.	
*SRE	Service Request Enable	Enable service request register value.	0 – 255
*SRE?	Service Request Enable	Query/Read service request register value.	0 – 255
*STB?	Status Byte Enable	Query status register text.	0 – 255
*TRG	Trigger Bus	Trigger the 1715 instrument	
*TST?	Self Test	Perform self test & report error 0 is the desired value. If the value is 4, recalibration should fix it.	0 = no error 1 = CPLD 2 = EEPROM 3 = HANDLER 4 = Cal Data

3.2.3 IEEE-488 Commands

Figure 3-2 illustrates the programming commands accepted by the IEEE-488 interface of the LR2000 instrument. The commands are written in tabular format as a single reference to view all the commands. The command format and examples are detailed in paragraphs 3.2.4 – 3.2.5.



Continued on next page

Figure 3-2a: IEEE-488 Commands

Figure 3-2 Continued: Tabular format of IEEE-488 Commands




Figure 3-2b: IEEE-488 Commands

3.2.4 IEEE-488 Command Format

The IEEE-488 commands are configured in Root format. There are six levels of the instruction from top to bottom. Follow the specific path (as illustrated in Figure 3.2) to configure a specific command. The colon at the beginning of each line denotes that all line signals are root. Use a colon (:) to separate levels. Use the semicolon (;) to separate two commands on the same line.

For example, to format the command for the lower Compare, use this path:

```
:CALCulate:COMP:LIMit:LOW 3.12E2
```

- (1) Command: CALCulate:COMPare:LIMit:NOMinal [:DATA] {<numeric_value> [MIN|MAX] [Suffix Unit]}
Function: It sets or queries nominal of comparison function.
Parameter: numeric_value 0.0000 ~ 999.9999
MIN 0.0000
MAX 999.9999
Unit: It defines unit of setting parameter {MOHM | OHM | KOHM | MAOHM}, if no the command of unit, OHM will be defined automatically. Interval between paramter and units is by blank.
Ex.: CALCulate:COMPare:LIMit:NOMInal 100.000 KOHM
Return: The query returns a numeric value in the format <NR3> and unit. Ex.: 100.0000 KOHM
- (2) Command: CALCulate:COMPare:LIMit:LOWer [:DATA] {<numeric_value> [MIN|MAX] [Suffix Unit]}
Function: It sets or queries the low limit of comparison function.
Parameter: numeric_value 0.0000 ~ 999.9999
MIN 999.9999
MAX 0.0000
Unit: It defines unit of setting parameter {MOHM | OHM | KOHM | MAOHM}, if no the command of unit, OHM will be defined automatically. Interval between paramter and units is by blank.
Ex.: CALCulate:COMPare:LIMit:NOMInal 99.000 KOHM
Return: The query returns a numeric value in the format <NR3> and unit. Ex.: 99.0000 KOHM
- (3) Command: CALCulate:COMPare:LIMit:UPPer[:DATA] {<numeric_value> [MIN|MAX] [Suffix Unit]}
Function: It sets or queries the high limit of comparison function.
Parameter: numeric_value 0.0000 ~ 999.9999
MIN 0.0000
MAX 999.9999
Unit: It defines unit of setting parameter {MOHM | OHM | KOHM | MAOHM}, if no the command of unit, OHM will be defined automatically. Interval between paramter and units is by blank.
Ex.: CALCulate:COMPare:LIMit:NOMInal 101.000 KOHM.

Return: The query returns a numeric value in the format <NR3> and unit.
Ex.: 101.0000 KOHM

If the command is a setting, then put the parameter after the instruction. If the command is an inquiry, then put a question mark (?) after the instruction.

For example, to set the Trigger to External:

:TRIGger:SOURce:EXTernal

To inquire what the Trigger is set to:

:TRIGger:SOURce?

The lowercase letters and portion in parenthesis can be omitted so the above instruction can be rewritten as:

:TRIG:SOUR:EXT

The Ending Code can be any type in Table 3-5.

Table 3-5: IEEE-488 Interface Ending Codes

Ending Code
[CR] (0Dh)
[LF] (0Ah)
[CR] (0Dh) + [LF] (0Ah)

3.2.5 IEEE-488 Commands - Detailed

The IEEE commands listed in Figure 3-2 are detailed in paragraphs 3.2.5.1 – 3.2.5.7 including command, parameter, return value, function, and description. **Note:** Numerical data is transferred via one of three methods: integer format, fixed decimal format or floating point decimal format. Refer to Figure 3-3.




Figure 3-3: Numerical Data Transfer

3.2.5.1 Root Function:

ABOR

Instruction: ABOR
 Parameter: None
 Return Value: None
 Function: Terminate Trigger in process. Reset Trigger.

3.2.5.2 CALCulate Function:

:CALC:ALAR:COND

Instruction: CALC:ALAR:COND
Parameter: {FAIL | PASS}
Return Value: {FAIL | PASS}
Function: Set the alarm to sound on FAIL or PASS result.
Description: FAIL Alarm will sound on FAIL result
PASS Alarm will sound on PASS result
Example: :CALC:ALAR:COND FAIL

:CALC:ALAR:MODE

Instruction: CALC:ALAR:MODE
Parameter: {PULSe | CONTInuous}
Return Value: {PULSe | CONTInuous}
Function: Set the alarm to pulse or to sound continuously.
Description: PULSe Alarm will pulse
CONTInuous Alarm will sound continuously
Example: :CALC:ALAR:MODE CONT

:CALC:BINN:CLEA

Instruction: CALC:BINN:CLEA
Parameter: None
Return Value: None
Function: Clear Bins – reset all bins to 0.
Example: :CALC:BINN:CLEA

:CALC:BINN:STAT

Instruction: CALC:BINN:STAT
Parameter: {ON (1) | OFF (0)}
Return Value: {1 | 0}
Function: Set the BINNING function ON or OFF.
Description: 1 Enable Binning
0 Disable Binning
Example: :CALC:BINN:STAT ON

:CALC:COMP:CLEA

Instruction: CALC:COMP:CLEA
Parameter: None
Return Value: None
Function: Clear Comparison Settings – reset all to 0.
Example: :CALC:COMP:CLEA

:CALC:COMP:RESU?

Instruction: CALC:COMP:RESU?
Parameter: None
Return Value: {LO (0) | HI (+9) | PASS (10) | STBY (11)}
Function: Query the COMPARE result.
Description:
+0 LO Result is below low limit
+9 PASS Result is within low and high limits
10 HI Result is above high limit
11 STBY Result is above high limit
Example: :CALC:COMP:RESU?
Response: +9

:CALC:COMP:MATH:STAT

Instruction: CALC:COMP:MATH:STAT
Parameter: {ON (1) | OFF (0)}
Return Value: {1 | 0}
Function: Set or query if CALCulate:COMPare:MATH is ON or OFF.
Description:
ON (1) Turn on CALCulate:COMPare:MATH
OFF (0) Turn off CALCulate:COMPare:MATH
Example: :CALC:COMP:MATH:STAT ON

:CALC:COMP:LIM:NOM

Instruction: CALC:COMP:LIM:NOM
Parameter: {MAX | MIN | <numeric value> (NR3 mode)}[Suffix Unit]
Return Value: {The nominal value}
Function: Set the NOMINAL limit for COMPARE function.
Example: :CALC:COMP:LIM:NOM 15.0

[:CALC:COMP:LIM:LOW](#)

Instruction: CALC:COMP:LIM:LOW
Parameter: {<numeric value> | MAXimum | MINimum} [Suffix Unit]
Return Value: The lower limit value, the format is <NR3> (Floating point)
Function: Set or query the lower limit value.
Description: MINimum 0.0000
MAXimum 999.9999
Example: :CALC:COMP:LIM:LOW 10.00

[:CALC:COMP:LIM:UPP](#)

Instruction: CALC:COMP:LIM:UPP
Parameter: {The upper limit value | MAXimum | MINimum} [Suffix Unit]
Return Value: The upper limit value, the format is <NR3> (Floating point)
Function: Set or query the upper limit value.
Description: MINimum 0.0000
MAXimum 999.9999
Example: :CALC:COMP:LIM:UPP 20.00

[:CALC:COMP:LIM:STAT](#)

Instruction: CALC{1 | 2}:LIM:STAT
Parameter: {ON (1) | OFF (0)}
Return Value: {1 | 0}
Function: Set or query if the Compare function is ON or OFF.
Description: ON (1) Turn on Compare function
OFF (0) Turn off Compare function
Example: :CALC:COMP:LIM:STAT ON

3.2.5.3 SENSE Function

[:SENS:AVER:COUN](#)

Instruction: SENS:AVER:COUN
Parameter: {<numeric value>} (1 – 10)
Return Value: {<numeric value>} (1 – 10)
Function: Set or query the number of measurements to average.
Description: Set the number of measurements for the instrument to take then average.
Example: :SENS:AVER:COUN 1

:SENS:ZERO:STAT

Instruction: SENS:ZERO:STAT
Parameter: {OFF (0) | ON (1)}
Return Value: {0 | 1}
Function: Select SHORT compensation function ON or OFF.
Description: 0 Short compensation OFF
1 Short compensation ON
Example: :SENS:ZERO:STAT ON

:SENS:ZERO:DATA

Instruction: SENS:ZERO:DATA?
Parameter: None
Return Value: {<numeric value> (NR3 mode)}
Function: Query the numeric correction (short compensation) value.
Description:
Example: :SENS:ZERO:DATA?
Response: 7.309873E-06

:SENS:RANG

Instruction: SENS:RANG
Parameter: {<numeric value> | MIN | MAX}
Return Value: {<numeric value>} in <NR3> format
Function: Set or query the measurement range.
Description: 0 20mΩ range
1 200mΩ range
2 2Ω range
3 20Ω range
4 200Ω range
5 2kΩ range
6 20kΩ range
7 200kΩ range
8 2MΩ range
Example: :SENS:RANG 1

Note: If DRY CIRCUIT is ON and an invalid measurement range is selected, the LR2000 unit will display an error. Valid ranges are 200mΩ, 2Ω, 20Ω and Auto.

:SENS:RANG:AUTO

Instruction: SENS:RANG:AUTO
Parameter: {ON (1) | OFF (0)}
Return Value: {1 | 0}
Function: Set or query if the Auto Range is ON or OFF.
Description: ON (1) Turn on Auto Range
OFF (0) Turn off Auto Range
Example: :SENS:RANG:AUTO ON

:SENS:SPEE

Instruction: SENS:SPEE
Parameter: {FAST | MEDium | SLOW}
Return Value: {FAST | MEDium | SLOW}
Function: Set or query measurement speed.
Description: FAST 15 measurements per second
MEDI 6 measurements per second
SLOW 1.5 measurements per second
Example: :SENS:SPEE SLOW

3.2.5.4 SOURce Function

:SOUR:DRY

Instruction: SOUR:DRY
Parameter: {ON (1) | OFF (0)}
Return Value: {1 | 0}
Function: Set or query if Dry Circuit mode is ON or OFF.
Description: ON (1) Turn on Dry Circuit Mode
OFF (0) Turn off Dry Circuit Mode
Example: :SOUR:DRY 0

:SOUR:DRIV

Instruction: SOUR:DRIV
Parameter: {PULSE+/- (0) | PULSE+ (1) | PULSE- (2) | DC+ (3) | DC- (4) | STBY (5)}
Return Value: {0 | 1 | 2 | 3 | 4 | 5}
Function: Set or query the Drive Signal.
Description: PULSE+/- (0) Drive Signal: +2V – 0V – -2V – 0V
PULSE+ (1) Drive Signal: +2V – 0V
PULSE- (2) Drive Signal: -2V – 0V
DC+ (3) Drive Signal: +2V
DC- (4) Drive Signal: -2V
STBY (5) Drive Signal: Standby
Example: :SOUR:DRIV:0

3.2.5.5 READ Function

READ

Instruction: READ
Parameter: None
Return Value: {<numeric value>} in <NR3> format
Function: Query the present measurement result.
Description:
Example: READ?
Response: 6.698189E+03

3.2.5.6 TRIGger Function

:TRIG:SOUR

Instruction: TRIG:SOUR
Parameter: {BUS | EXTERNAL INT}
Return Value: {BUS | EXTERNAL INT}
Function: Set or query the Trigger Source to bus or external.
Description: BUS Trigger activated by bus signal
EXT Trigger activated by external signal
INT Trigger activates by internal signal
Example: :TRIG:SOUR BUS

:TRIG:DEL

Instruction: TRIG:DEL
Parameter: Trigger Delay Time
Unit: [MS]
Return Value: {Trigger Delay Time} in <NR3> format
Function: Set or query the trigger delay time.
Range Values: 0 ~ 9999ms
Example: :TRIG:DEL: 20

:TRIG:EDGE

Instruction: TRIG:EDGE
Parameter: {FALLing | RISIng}
Return Value: {FALL | RISI}
Function: Set or query the trigger edge.
Example: :TRIG:EDGE RISI

3.2.5.7 SYSTem Function

:SYST:BEEP:MODE

Instruction: SYST:BEEP:MODE
Parameter: {ON, LARGe (0) | ON, SMALl (1) | OFF (2)}
Return Value: {0 | 1 | 2}
Function: Set the loudness of the beeper.
Example: :SYST:BEEP:MODE SMAL

:SYST:LFR

Instruction: SYST:LFR
Parameter: {50 | 60}
Return Value: {50 | 60}
Function: Set or query if the Line Frequency.
Example: :SYST:LFR 60

:SYST:HAND

Instruction: SYST:HAND
Parameter: {CLEAR | HOLD}
Return Value: {CLEAR | HOLD}
Function: Set the Handler to clear result or hold result for each test.
Example: :SYST:HAND HOLD

:SYST:KLOC

Instruction: SYST:KLOC
Parameter: {ON (1) | OFF (0)}
Return Value: {1 | 0}
Function: Set or query if the Key Lock function is ON or OFF.
Description: ON (1) Locks the front panel.
OFF (0) Unlocks the front panel.
Example: :SYST:KLOC 1

:SYST:PRES

Instruction: SYST:PRES
Parameter: None
Return Value: None
Function: Set the instrument to initial default values.
Example: :SYST:PRES

:SYST:ERR?

Instruction: SYST:ERR?
Parameter: None
Return Value: {<numerical value> | <string>}
Function: Reads the error queue.
Example: :SYST:ERR?
Response: 0 “No Error”

3.2.5.8 Temperature Compensation Function

:TEMP:UNIT

Instruction: TEMP:UNIT
Parameter: {DEGC|DEGF}
Return Value: {DEGC|DEGF}
Function: Set or query the unit of temperature value.
Description: DEGC Set temperature to Celsius
DEGF Set temperature to Fahrenheit
Example: :TEMP:UNIT DEGF

:TEMP:ATEMP:MODE

Instruction: TEMP:ATEMP:MODE
Parameter: {OFF|AUTO|MAN}
Return Value: {OFF|AUTO|MAN}
Function: Set or query ambient temperature mode of conversion and correction functions.
Description: OFF Temperature correction function is disabled. The current ambient temperature is equal to the initial temperature setting for temperature conversion function.
AUTO Temperature is measured through the temperature probe.
MAN Temperature is held at users input.
Example: :TEMP:ATEMP:MODE AUTO

:TEMP:ATEMP:INIT

Instruction: TEMP:ATEMP:INIT <numerical value>
Parameter: The value setting range is 0C~99.9C or 32F~211.8F
Return Value: A numerical value in the format <NR3> and unit. Ex.: +25.0C
Function: Set or query the initial temperature for temperature conversion function.
Example: :TEMP:ATEMP:INIT 20.0

:TEMP:ATEMP:CURR

Instruction: TEMP:ATEMP:CURR <numerical value>
Parameter: When TEMP:ATEMP: MODE is manual, the value setting range is 0C~99.9C or 32F~211.8F
Return Value: A numerical value in the format <NR3> and unit. Ex.: +25.0C
Function: Set or query current ambient temperature.
Example: :TEMP:ATEMP:CURR 25.0

:TEMP:RES:INIT

Instruction: TEMP:RES:INIT <numerical value>
Parameter: The value setting range is 0.0000~999.9999; the unit setting range is {MOHM|OHM|KOHM|MAOHM} (if no unit is specified, OHM is default).
Return Value: A numerical value in the format <NR3> and unit. Ex.: 101.0000 KOHM
Function: Set or query DUT's initial resistance under initial temperature of conversion.
Description: MOHM Unit is in milliohms
OHM Unit is in ohms
KOHM Unit is in kiliohms
MAOHM Unit is in megaohms
Example: :TEMP:RES:INIT 101.0000 KOHM

:TEMP:CONS

Instruction: TEMP:CONS <numerical value>
Parameter: The value setting range is 0.0000~999.9999
Return Value: A numeric value in the format <NR3>. Ex.: 101.0000
Function: Set or query the coefficient for temperature conversion function.
Example: :TEMP:CONS 101.0000

:TEMP:CORR

Instruction: TEMP:CORR <numerical value>
Parameter: The value setting range is 0C~99.9C or 32F~211.8F
Return Value: A numeric value in the format <NR3> and unit. Ex.: +25.0C
Function: Set or query the reference temperature of temperature correction function.
Example: :TEMP:CORR +25.0C

:TEMP:TCOEF

Instruction: TEMP:TCOEF <numerical value>
Parameter: The value setting range is 1~9999
Return Value: A numeric value
Function: Set or query thermal coefficient parameter of temperature correction function.
Example: :TEMP:TCOEF 1150

:TEMP:CONV:MODE

Instruction: TEMP:CONV:MODE
Parameter: {0|1|DEV|ABS}
Return Value: The query returns ABS or DEV
Function: Set or query the temperature display mode of temperature conversion function.
Description: ABS Displays the absolute value of the temperature conversion function. Same as using 0.
DEV Displays the percent deviation of the temperature conversion function. Same as using 1.
Example: :TEMP:CONV:MODE 0

:TEMP:CONV:RESU

Instruction: TEMP:CONV:RESU?
Parameter: None
Return Value: A numerical value in the form <NR3>. Ex.: +24.3C
Function: Query the temperature value of the temperature conversion function.
Example: :TEMP:CONV:RESU?

Error Messages:

Table 3-6 lists the error messages for the LR2000 Milliohmmeter.


Table 3-6: Error Messages

Code	Type	Message
0	No error	None
-102	Syntax error	Invalid character exists in the command string.
-104	Data error	Parameter is not defined in the command string.
-106	Illegal parameter	Parameter is not a valid command.
-202	Conflicting Settings	Command conflicts with instrument settings. Example: Send 'Trigger' when mode is external.
-203	Data range	Data exceeds the valid range.
-211	Data stale	No resent measurement result. Example: Send 'Read?' when in Standby status.
-224	Self-Test failed	Self-test via remote interface (*TST) failed.
-225	Excess errors	The error queue is full (more than 20 errors). Queue cleared after power down or *CLS command.
-226	Query interrupted	Device status changed after query sent. Output buffer will be cleared


3.3 Handler Interface

A Handler interface (Figure 3-4) is an available option for the LR2000 instrument. Connection is made through the blue 24-pin connector labeled “HANDLER INTERFACE” on the rear panel of the LR2000 instrument.

LR2000 HANDLER Interface PIN Configuration: Rear Panel View



LR2000 HANDLER Interface
PIN Designation
BINNING



LR2000 HANDLER Interface
PIN Designation
COMPARE




Figure 3-4: Handler Interface Pin Configuration




Figure 3-5: Start Switch

Paragraph 2.3.3.9 contains the instructions for changing the Handler mode. Paragraphs 2.3.3.7 and 2.3.3.8 contain instructions for setting the Trigger Delay time and selecting the Trigger Edge. Figure 3-6 illustrates the Trigger function.




Figure 3-6: Trigger

Output Signals

The output lines of the LR2000 Handler interface are open collector drivers that pull each signal line to a low voltage, signal ground when the signal is active (true). Each external line should be pulled up (with a resistor) to a positive voltage between 5V and 24V. The pull-up resistor must limit the current to < 6mA for a signal of a comparison function and to < 5mA for a control signal (EOT).

Input Signal

The input signal to the LR2000 Handler interface is active low and requires a positive external voltage to pull the signal down below 0.4V, ground.

3.3.1 Handler Pin Assignments for Binning Operation

Table 3-7 lists the pin assignments when the handler interface on the LR2000 instrument is performing a Binning operation. The device under test is sorted by test value. The test limits can be set as absolute value or percent value.

Table 3-7: Handler Pin Assignments for Binning

Pin	Name	Description
1	/EXT	External trigger
2	X	No connection
3, 20	BIN 7	Rx pass (within Bin 7 limits)
4, 24	BIN 8	Rx pass (within Bin 8 limits)
5, 6, 7	GND	Chassis Ground
8	COM	Common Ground
9, 13, 15	BIN OUT	Rx fail
10	VEXT	External DC voltage: 5V ~ 24V
11	VINT	Internal DC voltage: +5V
12	N.C.	No Connection
14	BIN 5	Rx pass (within Bin 5 limits)
16	BIN 6	Rx pass (within Bin 6 limits)
17	BIN 1	Rx pass (within Bin 1 limits)
18	EOT	End of Test
19	BIN 2	Rx pass (within Bin 2 limits)
21	BIN 3	Rx pass (within Bin 3 limits)
22	ACQ	Received data, ready to accept next
23	BIN 4	Rx pass (within Bin 4 limits)

NOTE:
When using External DC Voltage (VEXT), Pins 5, 6, & 7 (GND) must be connected to Pin 8 (COM)




Figure 3-7: Handler I/O Pins

3.3.2 Handler Pin Assignments for Compare Operation

Table 3-8 lists the pin assignments when the handler interface on the LR2000 instrument is performing a Compare operation. The device under test is being compared against a standard of known value. High and low limits can be defined as absolute value or percent value.

Table 3-8: Handler Pin Assignments for Compare

Pin	Name	Description
1	/EXT	External Trigger
2	X	No connection
3, 20	FAIL LO	Rx fail low (test value below low limit)
4, 24	FAIL HI	Rx fail high (test value above high limit)
5, 6, 7	GND	Chassis Ground
8	COM	Common Ground
9, 13	N.C.	No connection
10	VEXT	External DC voltage: 5V ~ 24V
11	VINT	Internal DC voltage: +5V
12	X	No connection
14	X	No connection
15	FAIL	Rx fail (Not within limits)
16	X	No connection
17	X	No connection
18	EOT	End of Test
19	X	No connection
21	PASS	Rx pass (test value within limits)
22	ACQ	Received data, ready to accept next
23	X	No connection

NOTE:

When using External DC Voltage (VEXT), Pins 5, 6, & 7 (GND) must be connected to Pin 8 (COM)

3.4 Temperature Compensation Interface

An optional Temperature Compensation (TC) interface is available for the LR2000 and includes the IEEE and Handler interfaces as shown in Figure 3-8. Figure 3-9 illustrates the PT100 Probe, P/N 700250. Connection of the temperature probe is made through the black/silver 3.5mm mini jack labeled “TC SENSOR” on the rear panel of the LR2000. Paragraphs 2.3.3.14 through 2.3.3.16 contain instructions for implementing the Resistance Correction function. Paragraph 2.5.3 contains instructions for implementing the Temperature Conversion function.




Figure 3.8: TC Interface (P/N 700251)



Figure 3.9: PT100 Probe (P/N 700250)

Section 4: Service & Calibration

4.1 General

Our warranty (at the front of this manual) attests to the quality of materials and workmanship in our products. If malfunction should be suspected or other information be desired, applications engineers are available for technical assistance. Application assistance is available in the U.S. by calling 800-253-1230 and asking for Applications Support. For support outside of the United States, please contact your local [QuadTech Distributor](#).

4.2 Instrument Return

Before returning an instrument to QuadTech for [Service](#) please obtain an [online Return Materials Authorization Number \(RMA#\)](#). This number, when placed on the outside of the shipping package, will speed processing at our Service Lab and will serve as a reference number for the time your unit is at QuadTech. Please contact our **Customer Care Center (CCC)** at **800-253-1230** for additional support. The CCC phone line is staffed from 8:00am to 5:00pm (EST).

It will be necessary to include a Purchase Order Number and credit card information to insure expedient processing, although units found to be in warranty will be repaired at no-charge. For any questions on repair costs or shipment instructions please contact our CCC Department at the above number. To safeguard an instrument during storage and shipping please use packaging that is adequate to protect it from damage, i.e., equivalent to the original packaging and mark the box "Delicate Electronic Instrument". Please follow online instructions for shipping materials back to QuadTech.

4.3 Calibration

Calibration of the LR2000 Milliohmeter instrument is completed at the factory and includes a NIST calibration certificate. Verification of instrument operation and accuracy is recommended on an annual basis. Accurate operation of the LR2000 instrument is confirmed using the LR2000-TP Verification Procedure.

4.3.1 LR2000 Verification Procedure

This section outlines the relevant information to verify performance of the LR2000 Milliohmmeter. It is recommended that performance be performed at least once a year using this outline procedure. Instrument should be warmed up for a minimum of 15 minutes prior to verification. Verification should be performed under the following conditions: Temperature equal to $23^{\circ}\text{C} \pm 1.2^{\circ}\text{C}$ and Relative Humidity (RH) between 35% and 55%.

Recommended standards are listed below. All standards should be traceable to a National Laboratory such as N.I.S.T. with calibrated values for primary and secondary parameters at the required test frequencies. QuadTech's verification conforms to ANSI Z540 and QuadTech recommends that the calibrated values for the primary and secondary standards have an uncertainty 4 times better than the primary and secondary accuracy specified in the Verification Data Sheet. If the calibrated values for the standards used do not have an uncertainty of 4 times better than the specified accuracy of the LR2000 the uncertainty of the standard should be added to the specified accuracy of the LR2000.

4.3.2 LR2000 Verification Data Sheet

Range	Test Value	LR2000 Accuracy	Tool Number	Standard Value	Low limit	Measured Value	High limit
20m Ω		0.10%					
	10m Ω						
	19m Ω						
200m Ω		0.05%					
	100m Ω						
	190m Ω						
2 Ω		0.05%					
	1 Ω						
	1.9 Ω						
20 Ω		0.05%					
	10 Ω						
	19 Ω *						
200 Ω		0.05%					
	100 Ω *						
	190 Ω						
2k Ω		0.05%					
	1k Ω						
	1.9k Ω						
20k Ω		0.10%					
	10K Ω						
	19k Ω						

LR 2000 Verification Table – continued

200kΩ		0.20%					
	100kΩ						
	190kΩ						
2MΩ		0.40%					
	1MΩ						
	1.9MΩ						

Test Value	Standard Value	Low Limit	Pulse +	Pulse -	DC +	DC -	High Limit
10mΩ							
1.9MΩ							

	Test Temp.	LR2000 Accuracy	Tool Number	Actual Temp.	Low Limit	Measured Temp.	High Limit