	пп
GO	1 11
11 15 1 1 1 1	IΠI
	υц

KIIGMIII	M odification B u			M odification B ulletin			: 1/1	
Model: Model-J			Date	e: 25-Jan-02	2	No.: MG060001	1	
Modified Article: Parts Catalog Correction				Prepared	by: H.S	Someya	omeya	
From: Technical Se	ervices Dept., GTS Division							
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To m	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve reliability		()			
	☐ Part standardization	☐ Othe	r	ļ				

Please apply the following corrections to your Parts Catalogs:

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G0609099	Total Counter-RAM-STK12C68-P55			77	202*	IC9
	11040771	IC Socket – 28 PIN			77	113	(Socket)
	14075404	IC – EEPROM I2C BUS 32K DIP			85	267*	IC20
	11040764	IC Socket – 8 PIN			85	125	(Socket)

* New index

33. Printer Control Board

Symbol	Index
No.	No.
IC9	202
(Socket)	113

34. BCU Board

Symbol	Index
No.	No.
IC20	267
(Socket)	125



PAGE: 1/1

Reissued: 20-Feb-02

Model: Model-J	Date: 15-Feb-02	No.: MG060002a

MB Correction

The items in bold italics have been corrected.

Modified Article: Parts Catalog Correction			Prepared by: H.Someya		
From: Technical Services Dept., GTS Division					
Reason for	□ Parts catalog correction	☐ Vendor change ☐ To improve reliability		☐ To meet standards	
Modification:	☐ To facilitate assembly			()	
	☐ Part standardization	☐ Other			

Please apply the following corrections to your Parts Catalogs:

ı	Old part	New part	Description	Q'ty	Int	Page	Index	Note
	number	number						
	G0601267	G0771267	Right Rear Cover			11	17	


Model: Model-J P1b		Date	Date: 3-Apr-02		No.: MG060003
Modified Article: Guide Plate – Middle Registration			Prepared by: T. Itoh		
From: Technical Services Dept., GTS Division					
Reason for	□ Parts catalog correction	☐ Vendor change ☐ To improve reliability		☐ To n	neet standards
Modification:	☐ To facilitate assembly			()
	☐ Part standardization	☐ Other	☐ Other		

A new part, called the Guide Plate – Middle Registration, has been newly registered in place of the three individual parts shown below. This was done because accurate replacement of the Sheet for lower registration in the field is very difficult.

Therefore when one of these three parts needs replacement in the field, please replace all of them with the new (assembled) Guide Plate – Middle Registration.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0602614 ¬		Guide Plate - Middle Registration	1 - 0		23	15	
G0602615—		Guide - Lower Registration	1 - 0		23	16	
G0602632 —		Sheet - Lower Registration	1 - 0		23	14	
L	►G0602613	Guide Plate - Middle Registration	0 - 1	X/O	23	*30	

Note: Please refer to RTB #RG060011 for troubleshooting information on registration area jams.



	ΠЛ
((片(U)	빎

PAGE: 1/1

							_
Model: Model J-P1b			Date: 10-Apr-02		No.: MG060004		
Iodified Article: Vertical Transport Lever			Prepared by: H. Someya				
rom: Technical Services sec. Service Planning Dept.							
leason for	☐ Parts catalog correction	☐ Vendor	Vendor change		☐ To m	neet standards	
lodification:	☑ To facilitate assembly	☐ To improve reliability		reliability	()	
	☐ Part etandardization	☐ Other					

To facilitate assembly on the production line, the following parts have been changed.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0602670	G0602690	Lever – Vertical Transport	1-1	X/X	23	1	
G0602673	G0602691	Grip Shaft	1-1	X/X	23	2	

Note: All parts listed above must be replaced together as a set.

	1		_ ·	
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6010800001
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010800841
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80810001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010800941
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010801396

	OH
լլտլ	UJINI

Modification:

Modification Bulletin

Model: Model J-P1b			te: 11-Apr-02	2	No.: MG060005	
Modified Article: Transfer Unit Release Lever Shaft				Prepared by: H. Someya		
From: Technical Services sec. Service Planning Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To n	neet standards	
B. A. 1161 (1	☐ To facilitate assembly	□ To impro	ve reliability	()	

PAGE: 1/1

To provide for smoother operation of the Transfer Unit Release Lever, the following part has been changed.

☐ To facilitate assembly

☐ Part standardization

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603692	G0603698	Stay	1-1	X/O	41	2	

rea (capan) i reduction								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6010800001				
Savin SLP38c								
Gestetner DSc38								
Lanier 2138								
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010800841				
Nashuatec DSc38								
Rex Rotary DSc38								
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80810001				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010800941				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010701125				

	OH
լլտլ	UJINI

Model: Model J-P1b			Date: 12-Apr-02		2	No.: MG060006
Modified Article: Harness – Fusing DC				Prepared	by: H.	Someya
From: Technical Services sec. Service Planning Dept.				•		
Reason for	☐ Parts catalog correction	☐ Vendor chang☐ To improve re		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly			e reliability	()
	☐ Part standardization	Other	-			

PAGE: 1/1

To make the Fusing DC line Harness more durable for the assembly process, protective tape has been added to some areas of the harness.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0775453	G0775455	Harness – Fusing DC	1-1	X/O	67	16	

NOE (Japan) I Toduction								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6010800001				
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010800841				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80810001				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010800941				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010801396				

ിഥി	ПП
(G(O)	

Modification:

Modification Bulletin

Model: Model J-P1b			te: 12-Apr-0	2	No.: MG060007	7
Modified Article: Power Cord				Prepared by: H. Someya		
From: Technical Services sec. Service Planning Dept.						
Reason for	☐ Parts catalog correction			☐ To m	neet standards	
Madification	☐ To facilitate assembly	To impro	ve reliability	()	

PAGE: 1/1

To improve the durability of the Power Cord, it has been changed over to a new vendor.

☐ To facilitate assembly

☐ Part standardization

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
11500363	11500366	Power Cord – 125V 15A 2.5M	1-1	X/O	65	111	

☐ Other

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6011200001

R		吅
	الالالا	υи


-t += 4 00	Na . Maaaaaaa
ate: 15-Apr-02	No.: MG060008

PAGE: 1/1

Model: Model J-P1b Da			ite: 15-Apr-02		No.: MG060008
Modified Article: Drive Roller			Prepared by: H. Someya		
From: Technical Services sec. Service Planning Dept.					
Reason for	Reason for Parts catalog correction Vendor		ange	☐ To meet standards	
Modification: ☐ To facilitate assembly ☐ To improv		☐ To improve reliability)	
	☐ Part standardization	Other			

The mark used for adjusting the phase of the Transfer Drive Roller has been incorporated into the part's mold (not applied manually as before).

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603866	G0603703	Drive Roller	1-1	0/0	39	7	



Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38	120V, 60Hz	USA, Canada	G060-17	P6011000006
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011000793
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81010001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011001617
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011002121




Model: Model J-P1b D			ate: 15-Apr-0	2	No.: MG060009
Modified Article: 0	Cushion for Transfer Brush	Prepared by: H. Someya			
From: Technical Services sec. Service Planning Dept.					
Reason for	☐ Parts catalog correction	☐ Vendor o	change	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve		ve reliability	()	
	☐ Part standardization	Other			

The following cushions have been newly added to absorb the vibration of the Transfer Charge Brushes, which can generate a low humming noise when a toner/dust buildup on the brush fibers increases the friction between the fibers and transfer belt.

On production machines after the cut-in numbers below, the cushions are attached directly onto the unit underneath the brushes. For machines in the field, the cushions should be attached according to the detailed procedure in RTB #RG060009.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G0603705	Cushion – Transfer Brush	0-1		41	25	new
	G0603705	Cushion – Transfer Brush	0-3		43	18	new





PAGE: 2/2

Model: Model J-P1b Date: 15-Apr-02 No.: MG060009

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6010800001
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010800919
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80810001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010801286
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010801396



PAGE: 1/1

Model: Model J-P1b			Date: 14-May-02		2	No.: MG060010
Modified Article: Controller				Prepared by: H. Someya		
From: Technical Services sec. Service Planning Dept.				•		
Reason for	Reason for Parts catalog correction Ven		☐ Vendor change		☐ To m	neet standards
Modification: ☐ To facilitate assembly ☐ To im		☐ To improve reliability		e reliability	()
		Othe	r			

To further improve printing performance, the clock speed of the Controller CPU has been increased from 250MHz to 300MHz.

Internal test results show an average increase in mainframe processing speed of 10% with PCL, 7% with PS, and 4% with RPCS drivers – depending on the specific combination of PC, application and file data used.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0605740	G0775740	Controller Board	1-1	0/0	67	3	
			1-1	0/0	77	*	
G0605980		Heat Sinker	1-0		77	2	
14075297—		IC - RM7000-250T-REV1.2E	1-0		77	124	
	→ 14075665	IC - RM7000A-300T-REV1.3	0-1		77	124	
16341501—		Resistor – $1.5k\Omega \pm 1\% 1/16W$	1-0		77	182	
	→ 16101486	Resistor – $2k\Omega \pm 0.5\% 1/16W$	0-1		77	182	
16303519—		Resistor – 5.1Ω ±5% 1/10W	2-0		77	161	
	→ 16503109	Resistor – $1\Omega \pm 5\% 1/8W$	0-2		77	161	
16341621—		Resistor – 1.62kΩ ±1% 1/16W	1-0		77	183	
	16546800	Resistor – 680Ω ±1% 1/10W	0-1		77	183	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6011000502
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011100920
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81110001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011001617
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011002121

തെ	пп
	11 5 1
ונטסנט.) I N I

PAGE: 1/1

Model: Model J-P1b			Date	ate: 17-May-02		No.: MG060011		
Modified Article: Decal - Vertical Transport				Prepared by: H.Someya				
From: Technical Services sec. Service Planning Dept.								
Reason for	Parts catalog correction	☐ Vendor change		ange	☐ To m	neet standards		
Modification: ☐ To facilitate assembly ☐ To		☐ To improve reliability		e reliability	()		
	☐ Part standardization	⊠ Other						

The material of the PUSH decal attached to the Vertical Transport Unit has been changed to match that of the unit itself.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
GA003029	GA003044	Decal – Vertical Transport 2	1-1	X/O	25	3	

110 = (04)041) 1 1044041011								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6011000001				
Savin SLP38c								
Gestetner DSc38								
Lanier 2138								
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011000781				
Nashuatec DSc38								
Rex Rotary DSc38								
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81010001				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011000996				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011002121				

ID	Пസി	иπи
K	160	لئالا

PAGE: 1/1

Model: Model J-P1b			Date	ate: 17-May-02		No.: MG060012	
Modified Article: PCU				Prepared by: H. Someya			
From: Technical Services sec. Service Planning Dept.							
Reason for	☐ Parts catalog correction	☐ Vendo		ŭ	☐ To n	neet standards	
Modification:	☐ To facilitate assembly ☐ Part standardization	☐ To improve reliability ☐ Other		e reliability	()	

The shape of the PCU has been changed to ensure the Development Side Seal does not peel off, which can cause firefly spots.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0602219	G0602221	PCU - CMY	3-3	X/O	35	1	

TOE (Supuri) I Toudo				
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6010800164
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010900394
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80910001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010801286
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010901348

തെ	пп
	11 5 1
ונטסנט.) I N I

PAGE: 1/1

Model: Model J-P1b			Date: 17-May-02		No.: MG060013	
Modified Article: Fly Wheel - CMY Stepper Motor				Prepared	by: H.	Someya
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vendor change ☐ To improve reliability ☐ Other		ange	☐ To m	neet standards
Modification:	☐ To facilitate assembly			improve reliability)
	☐ Part standardization					

The size of the Fly Wheel has been increased to improve image quality by minimizing banding.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0 77 1159	G0771168	Fly Wheel – CMY Stepper Motor	1-1	X/O	57	27	
05730030₺		Hexagon Headless Set Screw – M3x3	1-0		57	112	
	►05740060E	Hexagon Headless Set Screw – M4x6	0-1		57	112	

NOE (dapan) i rodaction								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6010800001				
Savin SLP38c								
Gestetner DSc38								
Lanier 2138								
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010800841				
Nashuatec DSc38								
Rex Rotary DSc38								
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80810001				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010801286				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010801396				

തത	ПП
G0	닚


PAGE: 1/2

Model: Model J-P1b			Date	e: 17-May-0	2	No.: MG060014	
Modified Article: Sensor harness - Paper feed unit				Prepared	by: H.	Someya	
From: Technical Services sec. Service Planning Dept.							
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly	☐ Vendor change ☐ To improve reliability		ŭ	☐ To n	neet standards)	
	☐ Part standardization	⊠ Other					

The Harness for the vertical transport sensor has been fixed to the Transport Guide Plate with tape to ensure it does not get caught between the Guide Plate and Lower Cover during factory assembly.

If this tape is necessary in the field, please order using the following (existing) part number:

Part number	Description	Q'ty	Int	Page	Index	Note
G0123897	Film – Toner End Sensor Harness	0-2		23	30	new





PAGE: 2/2

Model: Model J-P1b Date: 17-May-02 No.: MG060014

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6011200001
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011201282
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881120001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81210001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011201572
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011202836

തെ	пп
	11 5 1
ונטסנט.) I N I

PAGE: 1/1

Model: Model J-P1b			Date	Date: 17-May-02		No.: MG060015	
Modified Article: Release lever stopper			Prepared by: H. Someya				
From: Technical Ser	•						
Reason for	Parts catalog correction	☐ Vendo	☐ Vendor change		☐ To n	neet standards	
Modification:	To facilitate assembly		•	e reliability	()	
	Part standardization	I⊠ Other					

The Release Lever Stopper for the Transfer Unit has been deleted since there is already a stay in place preventing simple removal of the unit.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0603674		Release Lever Stopper	1-0		37	20	

110 = (0 a pari) 1 10 a a o a o i								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P601070011				
Savin SLP38c								
Gestetner DSc38								
Lanier 2138								
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010700544				
Nashuatec DSc38								
Rex Rotary DSc38								
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80810001				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010800941				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010701114				

തെ	пп
	11 5 1
ונטסנט.) I N I

PAGE: 1/1

Model: Model J-P1b		I	Date: 24-Jun-02		No.: MG060016		
Modified Article: Right Frame - Transfer Unit				Prepared by: H. Someya			
From: Technical Services sec. Service Planning Dept.							
Reason for	Parts catalog correction	☐ Vendo	☐ Vendor change		☐ To m	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliabi		rove reliability ()	
	☐ Part standardization	M Other					

To minimize the back-and-forth play of the Transfer Brush on the Right Frame, the shape of the attachment area on the Right Frame has been changed.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0603691	G0603704	Right Frame	1-1	X/O	43	6	

TOE (Supur) Troudes	-			
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6010800556
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010900394
Nashuatec DSc38		-		
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80910001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010900494
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010901348

ጦጠ	怬
GO	닚

PAGE: 1/1

Model: Model J-P1	b	Dat	ite: 24-Jun-02		No.: MG060017	
Modified Article: Toner Supply Tube				Prepared by: H. Someya		
From: Technical Se	ervices sec. Service Planning D	ept.				
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly	☐ Vendor ch	•	☐ To n	neet standards)	
	☐ Part standardization	I⊠ Other				

To ensure that the magenta toner supply system stays properly sealed, the length of the magenta toner supply tube has been increased from 230mm to 410mm. In addition, to ensure that the tube does not bend, a Guide Coil has been added.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603239	G0603241	Tube – M Toner Supply	1-1	X/O	31	11	
	AA063656	Guide Coil – M Tube	0-1		31	22	new

KCL (Japan) Produc	CHOH			
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6011000001
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011000781
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81010001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010900993
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011002121

മ്പ	ПΠ
GO	Ш

P	Α	G	Ε	:	1	ľ	1
---	---	---	---	---	---	---	---

Model: Model J-P1b Date						No.: MG060018
Modified Article: Transfer Belt Contact Motor Prepared by: H. Someya						
From: Technical Ser	vices sec. Service Planning D	ept.				
Reason for	Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		e reliability	()
	☐ Part standardization	Other				

When an outside force is applied to the bracket for the Transfer Belt Contact Motor shaft, the bracket can deform and the gear can separate from the bracket. A reinforcing section has been added to the bracket so that even when such an external force is applied, the bracket will be supported by both this newly added area and the Drum Motor Bracket.



Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603706	G0773706	DC Motor – 1.56W	1-1	X/O	59	8	

RCL (Japan) Produc	ction			
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38	120V, 60Hz	USA, Canada	G060-17	P6011200613
Lanier 2138	000 040)/ 50/0011-		0000 00	D0044000074
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011203274
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882010001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80120001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011202067
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011202836

മ്പ	ПΠ
GO	Ш

P	Α	G	Ε	:	1	ľ	1
---	---	---	---	---	---	---	---

Model: Model J-P1b Date			e: 1-Jul-02		No.: MG060019	
Modified Article: T	ransfer belt contact motor	Prepared	by: H.	Someya		
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vendor change ☐ To improve reliability		☐ To n	neet standards	
Modification:	☐ To facilitate assembly			()	
	☐ Part standardization	Other				

The shaft of the Transfer Belt Contact Motor can sometimes disconnect from its bracket, causing the gear to fail. To increase the contact area with the bracket, the bushing inside motor has been lengthened.



Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603990	G0603706	DC Motor – 1.56W	1-1	X/O	59	8	

NOL (Japan) Froud	Clion			
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6011100049
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P60112xxxxx
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81210001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011002054
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011102195

വരു	ПП
(GO	LnJ

PAGE: 1	1/	•
---------	----	---

Model: Model J-P1b Date:			∋: 18-Jul-02		No.: MG060020	
Modified Article: D	Decal - Jam Removal	Prepared	by:			
From: Technical Services sec. Service Planning Dept.						
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To m	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	Othe	r			

The Decal on the inside of the Front Cover, which demonstrates how to remove jammed paper, has been changed to include more clear illustrations for customers.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0601292	G0771292	Sheet – Jam Removal	1-1	X/O	9	3	

NOL (Japan) Froduct	.1011			
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6011100001
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011100920
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81110001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011101150
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011102160

രത	ПП
GO	LnJ

Reason for

Modification:

Model: Model J-P1b

Modified Article: Shaft - Paper Sensor

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

	Date: 19-Jul-0	2	No.: MG060021	
	Prepare	d by: H.	Someya	
ept.				
☐ Vendo	r change	☐ To n	neet standards	
⊠ To imp	prove reliability	()	

PAGE: 1/1

The shape of the feeler for the Paper Overflow Sensor has been changed to ensure that it stays properly engaged when the paper is fed out or the paper stack removed.

☐ Other

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0604483	G0604479	Shaft – Paper Sensor	1-1	X/O	53	18	

Roc (bapan) i roduction									
Model	V/Hz	Destination	Code	Serial Number					
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6011200001					
Savin SLP38c									
Gestetner DSc38									
Lanier 2138									
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011201282					
Nashuatec DSc38									
Rex Rotary DSc38									
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881120001					
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81210001					
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011201572					
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011202836					

രത	ПП
GO	LnJ

Reason for

Modification:

Model: Model J-P1b

Modified Article: Paper Feed Motor Unit

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Date	Date: 26-Jul-02		No.: MG060022	2
	Prepared	by: H.	Someya	
ept.				
Uendor ch	ange	☐ To n	neet standards	
	e reliability	()	

PAGE: 1/1

To ensure the rubber sheet inside the cushion of the Paper Feed Motor stays properly fixed in place, the adhesive for the cushion has been strengthened.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0771170	G0771172	Paper Feed Motor Unit – DC4.42W	1-1	X/O	63	14	
AA161149	AA161153	Motor Cushion	1-1	X/O	63	16	

☐ Other

രത	ПП
GO	LnJ

	PAGE:	1/1
02	No . Mcueuuss	

Model: Model J-P1b	Model: Model J-P1b Dat			e: 26-Jul-02	No.: MG060023	
Modified Article: Transfer Belt Unit			Prepared by: H. Someya			
From: Technical Services sec. Service Planning Dept.						
Reason for Parts catalog correction		☐ Vendor change		☐ To n	neet standards	
Modification: ☐ To facilitate assembly ☐ To improv		☐ To improve reliability		()	
	☐ Part standardization	Other Other	r			

To further ensure that the Transfer Unit is protected against excessive shock and vibration during transport, a securing pin has been added to the unit.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0603802	G0603840	Transfer Unit	1-1	0/0	37	19	

വരി	ПΠ
(GO	LnJ

Model: Model J-P1b Date			e: 26-Jul-02	ul-02 No.: MG060		
Modified Article: Waste Toner Collection Coil			Prepared by: H.Someya			
From: Technical Services sec. Service Planning Dept.						
Reason for Parts catalog correction		☐ Vendo	or ch	ange	☐ To m	neet standards
Modification: ☐ To facilitate assembly ☐ To in		☐ To improve reliability		e reliability	()
	☐ Part standardization	Other				

To ensure that Cyan waste toner does not build up in the collection tube, the tube coil has been lengthened and the shape of the tube changed.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603353	G0603355	Pump – C toner Supply Unit	1-1	X/X	55	12	
G0603386	G0603390	Case – C	1-1	X/X	55	7	

Note: All parts listed above must be replaced together as a set.

NOL (bapail) I roduction								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6020201389				
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020300850				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882030001				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80320001				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020301426				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020302986				

വയത	叽
]Œ0	LnJ

PAGE:	1/

Model: Model J-P1b Date						No.: MG060025
Modified Article: Imaging Unit					by: н.	Someya
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve		e reliability	()
	☐ Part standardization	Other				

The shapes of the Imaging Unit Cover and Duct have been changed to modify the airflow around the laser optics housing unit. This was done to ensure that the hot air from the Polygon Mirror Motor does not warp the F-theta lens, which can cause shifts in the main scan magnification for each color.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0771855	G0771856	Imaging Unit	1-1	X/X	13	1	
G0601041	G0771041	Imaging Unit Duct	1-1	X/X	13	17	

Note: All parts listed above must be replaced together as a set.

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020600001
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020600851
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882060001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80620001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020601401
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020602301

വരു	ПП
(GO	LnJ

PAGE: 1/2

Model: Model J-P1b Date						No.: MG060026	
Modified Article: Paper Exit Gear & Bracket					by: H.	Someya	
From: Technical Services sec. Service Planning Dept.							
Reason for	☐ Parts catalog correction	☐ Vendor chan		ange 🔲 To		neet standards	
Modification:	☐ To improve		☐ To improve reliability		()	
	☐ Part standardization	☐ Other					

To facilitate factory assembly of the Paper Exit gear train, minor changes in the dimensions of the following parts have been made.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0604462	G0774462	Gear - Z18/T28	1-1	X/X	53	33	
G0604464	G0774464	Bracket Gear	1-1	X/X	53	32	

Note: All parts listed above must be replaced together as a set.

Not (bapan) I rodaction							
Model	V/Hz	Destination	Code	Serial Number			
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020400001			
Savin SLP38c							
Gestetner DSc38							
Lanier 2138							
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020401156			
Nashuatec DSc38							
Rex Rotary DSc38							
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882040001			
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80420001			
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020401756			
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020401955			

RIGON

Modification Bulletin

_	_	_	_			
0	Λ	G		•	1	11
Г,	~	J	ᆫ			, ,

Model: Model J-P1b Date				e: 6-Sep-02		No.: MG060027
Modified Article: NVRAM on BCU board					by: H.	Someya
From: Technical Services sec. Service Planning Dept.						
Reason for	Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards
Modification:	dification:		e reliability	()	
☐ Part standardization ☐ Other						

SP7-908-1 thru 8 have been added to store the average Pixel Coverage Ratios for each toner color. With this new counter, B/W pages that follow color pages in ACS will not be included in pixel coverage ratios for CMY toner (only for black). For this new counter, the capacity of the NVRAM on the BCU board has been changed to 8kB.

Note: This feature also requires engine main firmware version B1.17C or newer and controller firmware version 2.13 or newer.

Old part	New part	Description		Int	Page	Index	Note
number	number						
14075404		IC - EEPROM I2C BUS 32K DIP	1-1	X/O	85	267	
	14075751	IC - NVRAM I2C BUS 64K DIP					

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020300001
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020300850
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882030001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80320001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020301426
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020302986

	മ്പ	ПΠ
KU	GO	لتا

_	_	_	_		_	
D	Λ	G		•	1	11
Г,	~	J	ᆫ			, ,

Model: Model J-P1b D				e: 18-Sep-0	2	No.: MG060028	
Modified Article: Front Registration Bushing					by: H.	Someya	
From: Technical Ser	rvices sec. Service Planning D	ept.					
Reason for	☐ Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards	
Modification:	cation: ⊠ To facilitate assembly ☐ To improv		prove	e reliability	()	
	☐ Part standardization	☐ Other	r				


To facilitate skew adjustments performed on the registration section on the production line, the Front Bushing of the Registration Drive Roller and Fixing Screw have been changed.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0602678	G0602684	Front Registration Bushing – M8	1-1	X/X	29	4	
04513006B-	1	Tapping Screw – M3x6	1-0	X/X	29	101	
	^L → A2596239	Screw – M3x4	0-1	X/X	29	28 *1	

*1: New Index

Note: All parts listed above must be replaced together as a set.

NOL (Japan) i Todaci				
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6010800001
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6010800841
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80810001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6010800941
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6010801396




Model: Model J-P1b				te: 18-Sep-02		No.: MG060029	
Modified Article: Snap Ring					by: H.	Someya	
From: Technical Ser	rvices sec. Service Planning D	ept.					
Reason for	Parts catalog correction	U Vend		•	☐ To n	neet standards	
Modification:		☐ To im	☐ To improve reliability		()	
Part standardization							

To ensure that noise does not occur from interference between the Snap Ring and shaft of the Registration Roller, the material for 1 of the 2 Snap Rings shown below has been changed.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
52152621 -	> 52152621	Snap Ring – M6	2-1		29	6	
	^L →AA100013	Snap Ring – M6	0-1	X/O	29	29 *1	

*1: New Index

INOL (Japan) i roduc	Juon			
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6011200001
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011201282
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881120001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81210001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011201572
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011202836



RIGON

Reason for

Modification:

Model: Model J-P1b

Modified Article: Fusing Clutch & BCU Board

From: Technical Services sec. Service Planning Dept.

Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Date: 25-Sep-0			2	No.: MG06003	0
		Prepared	by: H.	Someya	
ept.					
☐ Vendo	or ch	ange	☐ To n	neet standards	
☐ To improve reliability			()	

PAGE: 1/4

A fusing clutch has been added to the Bk development drive unit, which allows the drive to the fusing unit to be cut off during operations such as process control self-checks, line position adjustments and printer/copier image processing. Since the unit does not need to be running during these operations, the clutch will maximize the field durability of the fusing and oil units.

Other

The following changes were then made to components and engine firmware to facilitate the new clutch, and were applied in stages as described below.

Step 1

A DIP switch was added to the BCU board, which instructs the machine to detect or not detect the clutch. Please see RTB #RG060005 for details on the switch settings. Note: The engine firmware was not changed at this stage (i.e. still ver. B1.11G).

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0775061	G0775069	BCU Board	1-1	X/O	67	18	
			1-1	X/O	85	*	
	12042478	DIP Switch – 4P	0-1		85		new

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6011000732
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011100920
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81110001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011001617
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011102121



Model: Model J-P1b

Modification Bulletin

PAGE: 2/4 No.: MG060030

Date: 25-Sep-02


Step 2

The following components were modified so that the clutch could be added. The new clutch is a component of the drive unit for the Bk development unit.

Note: Although the engine firmware was changed to ver B1.11H, the clutch engage/disengage control program had not been added yet. The clutch is therefore constantly engaged and keeps the fusing unit moving, as before.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0601100	G0771100	Drive Unit – K Development	1-1	X/X	57	4	
G0771154	G0771160	Bracket - Drum Drive	1-1	X/X	57	9	
G0601189	G0601560	Upper PSU Duct	1-1	X/X	71	4	
G0601557	G0601561	Duct – DC Motor Guard	1-1	X/X	65	5	
G0775452	G0775456	Harness – Left Main	1-1	X/X	67	17	
G0775069	G0775069A	BCU Board	1-1	X/O	67	18	
			1-1	X/O	85	*	
(Ver. B1.11G)	(Ver. B1.11H)	Engine main firmware	1-1	X/O			

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6011100001
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011100920
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81110001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011001999
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011102160







PAGE: 3/4

Model: Model J-P1b Date: 25-Sep-02 No.: MG060030

29. Electrical Section 1 (G060)



30. Electrical Section 2 (G060)





PAGE: 4/4

Model: Model J-P1b Date: 25-Sep-02 No.: MG060030

Step 3

The engage/disengage program for the clutch was added to the engine firmware (now ver B1.15E). Aside of the firmware, the BCU board itself remains unchanged.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0775069A	G0775067	BCU Board	1-1	X/O	67	18	
			1-1	X/O	85	*	

Not (dapan) i rodaction								
V/Hz	Destination	Code	Serial Number					
120V, 60Hz	USA, Canada	G060-17	P6011200001					
220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011201282					
220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881120001					
220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81210001					
220 - 240V, 50/60Hz 220 - 240V, 50/60Hz	Europe, etc. Asia		P6011201572 P6011202836					
	V/Hz 120V, 60Hz 220 - 240V, 50/60Hz 220 - 240V, 50/60Hz 220 - 240V, 50/60Hz	V/Hz Destination 120V, 60Hz USA, Canada 220 - 240V, 50/60Hz Europe, etc. 220 - 240V, 50/60Hz Europe, etc.	V/Hz Destination Code 120V, 60Hz USA, Canada G060-17 220 - 240V, 50/60Hz Europe, etc. G060-22 220 - 240V, 50/60Hz Europe, etc. G060-24 220 - 240V, 50/60Hz Europe, etc. G060-26 220 - 240V, 50/60Hz Europe, etc. G060-27					

വര	吅
(GO	لتلا

Reason for

Modification:

Model: Model J-P1b

Modified Article: Development Unit

From: Technical Services sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

	Date: 25-Oct-02			No.: M	G060031
		Prepared	by: H.	Someya	
pt.					
☐ Vend	lor ch	ange	☐ To n	neet stan	dards
☐ To improve reliability			()	

PAGE: 1/1

To increase the distribution speed of developer and to help mixing the toner density evenly side to side (front to rear), the rotation speed of the development agitation rollers has been increased by about 1.7 times. In addition to improvement in the uneven ID, this modification reduces the ID change from page to page.

Other

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603011	G0603016	Development Unit - C	1-1	O/O	35	3	
G0603012	G0603017	Development Unit - M	1-1	0/0	35	2	
G0603013	G0603018	Development Unit - Y	1-1	0/0	35	4	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6020100522
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020101876
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882010081
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80220001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020102576
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020203163

വതര	пп
1Œ0	lñl

PAGE: 1/1

Model: Model J-P1b			Date: 28-Oct-02		No.: MG060032		
Modified Article: Development Unit				Prepared by: H. Someya			
From: Technical Services sec. Service Planning Dept.							
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To m	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability ☐ Other		e reliability	()	
	☐ Part standardization						

The following have been changed due to parts standardization with the Development Units for the domestic model in Japan.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0603016	G7643001	Dayslanmant Unit C	1 1	0/0	35	2	
G0603016 G0603017	G7643001 G7643002	Development Unit - C Development Unit - M	1-1 1-1	0/0	35	2	
G0603017	G7643003	Development Unit - Y	1-1	0/0	35	4	

(F)	ጠ	ПП
ரு	U	山

PAGE: 1/	P	٩G	E	: 1	ľ
-----------------	---	----	---	-----	---

Model: Model-J			Date	Oate: 28-Nov-02		No.: MG060033	
Modified Article: Unique parts for Chinese model					by: н.s	Someya	
From: Technical Services sec. Service Planning Dept.							
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improv		prove reliability)	
	☐ Part standardization	Other					

The following have been newly registered as unique parts for the China model (G060-69).

New part	Description	Q'ty	Int	Page	Index	Note
number						
AZ230121	Power Supply Unit - 220V	1		65	18	
GZ000004	Power Supply Cord (CHN)	1		65	111	
GA003065	Decal - Inkjet Paper Caution (CHN)	1		89	14	
G0606521	O/I - Setup Guide (CHN)	1		89	15	
G0606583	O/I - Maintenance Guide (CHN)	1		89	16	
G0606645	O/I - Printer Client Reference (CHN)	1		89	17	
G0606707	O/I - Administrator Reference (CHN)	1		89	18	

	മ്പ	ПΠ
KU	GO	ய

Reason for

Modification:

Modified Article: Paper Feed Unit

From: Technical Services Sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

□ Part standardization

Modification **B**ulletin

Date: 25-Feb-03		No.: MG060034		
Prepared			by: н.т	aguchi
ept.				
☐ Vendor change			☐ To m	neet standards

)

(

PAGE: 1/1

The following has been changed due to parts standardization with the next model.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
Hullibel	Hullibel						
G0602700	G0802700	Paper Feed Unit 1	1 - 1	0/0	19	1	

☐ Other

☐ To improve reliability

GO	U
шеши	l n l
	ш

Reason for

Modification:

Modified Article: Paper Tray 1

From: Technical Service Sec. Service Planning Dept.

☐ Parts catalog correction

☐ To facilitate assembly

□ Part standardization

Modification **B**ulletin

Dat	e: 25-Feb-0	3	No.: MG0600	35
pt.	Prepared	by: н.т	aguchi	
<u></u>		_		
Vendor ch	ange	☐ To m	neet standards	
☐ To improv	e reliability	()	

PAGE: 1/1

The following parts have been changed due to parts standardization with the next model.

Other

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0602768	G0802768	Paper Tray 1	1 – 1	0/0	15	1	
GA003011 -	-	Decal – Paper Tray 1	1 – 0		15	2	
_	➤ GA003066	Decal:Paper Tray:No.1	0 – 1		15	2	

\sim	пп
11121111	121
(GO	Ш


P	Α	G	Ε	:	1	ľ
	•	•	_	•		

Model: Model-J			Date	ate: 27-Feb-03		No.: MG060036	
Modified Article: Parts catalogue collection				Prepared by: H.Taguchi			
From: Technical Se							
Reason for	□ Parts catalog correction	☐ Vend		J	☐ To n	neet standards	
Modification: ☐ To facilitate assembly ☐ To im		☐ To improve reliability		()		
	☐ Part standardization	☐ Other	•				

The following parts have been newly registered due to requests from the field.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G0602633	Guide: Middle: Lower	0 - 1		29	28	New
	G0602618	Guide Plate: Middle: Lower: Adhesion	0 - 1		29	29	New

11. Paper Registration (G060)



RIGON

Modification **B**ulletin

	PAGE:	1/1
-03	No.: MG060037	

Model: Model-J Date			e: 13-Mar-03		No.: MG060037	
Modified Article: Fusing Belt				Prepared by: Hideki Taguchi		
From: Technical Services Sec. Service Planning Dept.						
Reason for	eason for Parts catalog correction Vendor of		or ch	ange	☐ To n	neet standards
Modification:				()	
	☐ Part standardization	☐ Othe	r			

The shape of the strippers has been changed and the spring pressure has been reduced to ensure that the strippers do not scratch the fusing belt or pressure roller.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AA060871	AA060932	Tension Spring	5 – 5	X/X	45	2	1*
AE044034	AE044051	Fusing Belt Stripper	5 – 5	X/X	45	3	1*
AA066589	AA066594	Spring – Pressure Roller Stripper	6 – 6	X/X	47	11	2*
AE044035	AE044050	Pressure Roller Stripper	6 – 6	X/X	47	12	2*

Note 1*: These parts should be replaced as a set (interchangeability as a set: X/O) Note 2*: These parts should be replaced as a set (interchangeability as a set: X/O)

110= (0apan) 1 10aao				
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6021200020
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6021201401
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882120001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81220023
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6021201675
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6021201691

RIGOH

PAGE:	1/1

Model: Model-J Date			te: 16-May-03		No.: MG060038			
Modified Article: Rear Side Plate					Prepared by: Hideki Taguchi			
From: 1st Tech. Support Sec. Service Support Dept.								
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards		
Modification:	☐ To facilitate assembly	☐ To improve		e reliability	()		
	☐ Part standardization	☐ Othe	r					

The following part number has been changed due to parts catalog correction.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0602664	G0602665	Rear Side Plate – Paper Feed	1 – 1	X/O	23	17	

	וטווח
	II II n I
יאנטאו	илип

PAGE: 1/1

Model: Model-J			Date	e: 16-May-0	3	No.: MG060039
Modified Article: Upper Cover			Prepared by: Hideki Taguchi			
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor change		☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		e reliability	()
	□ Part standardization	☐ Othe	r			

The following part has been changed due to parts standardization with the next model.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0601275	G0771275	Upper Cover – Exit Tray	1 – 1	0/0	11	13	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020500862
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020600851
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882060001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80520001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020502616
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020602301

\bigcirc	ጠ	ПП
G	W	닚


P	Α	G	Ε	:	1	ľ
	•	•	_	•		

Model: Model-J Dat		Date	te: 23-May-03		No.: MG060040	
Modified Article: Parts catalog correction			Prepared by: H.Taguchi			
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vend	dor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To in	nprove	e reliability	()
	☐ Part standardization	☐ Othe	r			

Please apply the following index corrections in the illustration to your Parts Catalogs.

Part number	Description	Page	Index
G0602629	Vertical Transport Guide	21	34
G0602730	Guide Plate	21	35

7. 2nd Paper Feed Section (G060)



	\sim $-$
)) ¦
Ատև	Hini
ישעש	ソロロ


PA	G	E:	1	ľ

Model: Model-J Date			e: 29-May-0	3	No.: MG060041	
Modified Article: Parts catalog correction					by: H.1	Гаguchi
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards
Modification:			e reliability	()	
	☐ Part standardization	☐ Othe	r			

Please apply the following correction to your Parts Catalogs.

Delete the following P/N, descriptions and indexes from the illustration. These springs were deleted because they are provided only as part of the G0603694 Release Shaft (index 3 below), not individually.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AA066344	110111201	Rear Torsion Spring	1 – 0		41	23	
AA066345		Front Torsion Spring				24	



	וטווח
	II II n I
יאנטאו	илип

PAGE:	1	1
-------	---	---

Model: Model-J Date			e: 29-May-0	3	No.: MG060042	
Modified Article: F	ROM DIMM - PDL	Prepared	by: H.1	Гаguchi		
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vend	dor ch	ange	☐ To n	neet standards
Modification:			e reliability	()	
	☐ Part standardization	☐ Othe	r			

The Euro currency symbol has been added to 112 fonts in the following ROM DIMM.

Related bulletins: #Rgene011, #RG060002g (Controller v2.18).

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0776120	G0776121	ROM DIMM - PDL	1 – 1	X/O	67	1	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6021000151
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6021000931
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81020001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6021001303
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6021100826

RIGOH

Modification Bulletin

PAGE: 1/2

Model: Model-J		D	ate	e: 10-Jun-03	3	No.: MG060043	}
Modified Article: S	ensor			Prepared	by: н.т	Taguchi	
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.					
Reason for	Parts catalog correction	☐ Vendor		Ŭ	☐ To m	neet standards	
Modification:	☐ To facilitate assembly☐ Part standardization	⊠ To impr □ Other	rove	e reliability	(,	

The following changes have been made to ensure that the transfer belt is not scratched from vibration during transport, which can occur because the machine is shipped from the factory with the belt and drum contacting each other.

- 1) The machine is now shipped with the drum released from the transfer belt, i.e. with the release lever secured with tape in a second (new) unlocked position.
- 2) The parts listed below have been modified so that the front door can be closed with the lever in the second unlocked position for shipping. At installation, the lever must then be set to the locked position for the door to close.


Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
	G0603712	Torsion Spring			41	23	*1
							NEW
G0603694	G0773697	Shaft – Release	1 – 1	X/O	41	3	*1
	07200040	Retaining Ring – M4			41	109	*1
							NEW
G0603923	G0773923	Release Lever	1 – 1	X/O	37	15	*1

Note: *1. Interchangeability is O/O as a set

PAGE: 2/2

Model: Model-J Date: 10-Jun-03 No.: MG060043

17.Transfer Unit 3 (G060)




Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6020600330
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020601050
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882070001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80620001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020601900
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020602394

Model: Model-J Da				e: 25-Jun-0	3	No.: MG060044
Modified Article: T	ransfer Unit			Prepared	by: н.٦	Гаguchi
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.				
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	⊠ To in	nprove	e reliability	()
	☐ Part standardization	☐ Othe	r			

The following sheet has been added to ensure a proper gap between the Left Stay and Transfer Belt, as toner accumulated on the stay from toner scattering can be transferred to the transfer belt and cause an ID sensor misdetection.

Note: The four sheets are attached to the Left Stay, just to the left and right of both ID sensors (see illustration below).

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603840	G0603841	Transfer Unit	1 – 1	X/O	37	19	
	G0603707	Sheet: Stay: Left	4		39	35	NEW





PAGE: 2/2

Model: Model-J Date: 25-Jun-03 No.: MG060044

, ,				
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6011100791
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6011201282
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0881110001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G81210001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6011102054
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6011102195

	וטווח
	II II n I
יאנטאו	илип

	PAGE: 1/1
1-03	No.: MG060045

Model: Model-J Date			Date	e: 25-Jun-0	3	No.: MG060045
Modified Article: Transfer Unit			Prepared by: H.Taguchi			
From: 1st Tech. Su	oport Sec. Service Support Dep	ot.				
Reason for	☐ Parts catalog correction	☐ Vendo	r cha	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly			ereliability	()
	☐ Part standardization	☐ Other				

The following has been changed to ensure the Backup Roller and Bushing stay properly fixed in position despite drop shock during shipping.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0603841	G0773841	Transfer Unit	1 – 1	X/O	37	19	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6020900401
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020901171
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882100001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80920001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020901948
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020902311

ര	ПΠ
(GO	Ш

PAGE: 1/1

Model: Model-J Date			e: 3-Sep-03	No.: MG060046		
Modified Article:	Harness - Power Pack CB			Prepared	by: H.1	Гаguchi
From: 1st Tech. Su	pport Sec. Service Support De	pt.				
Reason for	☐ Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards
Modification:		☐ To im	prove	e reliability	()
	☐ Part standardization	☐ Other	r			

The binding clips for the following harness have been spaced further apart to facilitate assembly (harness length increased).

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0605510	G0775510	Harness – Power Pack CB	1 – 1	O/O	65	10	

മ്പ	ПΠ
(GO	ய

PAGE:	1	/1
-------	---	----

Model: Model-J Date			e: 3-Sep-03	ı	No.: MG060047	
Modified Article: Transfer Belt				Prepared	by: H.1	Гаguchi
From: 1st Tech. Su	pport Sec. Service Support De	pt.				
Reason for	☐ Parts catalog correction	⊠ Vend			☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	☐ Othe	r			

The following part number has been changed due to a vendor change.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603850	G0773850	Transfer Belt	1 – 1	0/0	39	12	

\square	\bigcirc	ПП
	w	$\Box\Box$

PAGE:	1	/1
-------	---	----

Model: Model-J Date			e: 2-Dec-03		No.: MG060048	
Modified Article: Controller Board				Prepared by: Hideki Taguchi		
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	□ Part standardization	☐ Othe	r			

The following has been changed due to parts standardization.

	Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
(G0775740	G0775741	Controller Board	1 – 1	0/0	67	3	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020600552
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020601134
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882070001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80620001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020602151
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020703276

ጦጠ	ιПЛ
(H(I)	囧

Reason for

Modification:

Modified Article: Cleaner - Dust Proof Glass

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Dat	e: 12-Dec-0	3	No.: MG060049	
	Prepared	by: н.т	「aguchi	
t.				
☐ Vendor change		☐ To m	neet standards	
	e reliability	()	

PAGE: 1/1

The cleaner for the dust proof glass has been modified as follows to improve the adhesive strength of the seal's tape:

Other

- 1. The material for the fiber base seal has been changed to a softer material (latex).
- 2. The adhesive strength of the tape has been increased by approximately four times.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0601995	B1491995	HOLDER:PAD:ASS'Y	1 – 1	0/0	9	2	

	വതര	пп
151	1G0	lñl

Model: Model-J Date			e: 19-Feb-0	4	No.: MG060050	
Modified Article: Pump - C Toner Supply Unit					by: н.т	Гaguchi
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	Parts catalog correction	☐ Vendor change		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To improve reliability		()	
	☐ Part standardization	☐ Othe	r			

The following have been modified to further ensure the smooth flow of waste toner.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603353	G0603355	Pump – C Toner Supply Unit	1 – 1	X/O	55	12	*
G0603386	G0603390	Case - C	1 – 1	X/O	55	7	*

Note: These parts should be replaced as a set (interchangeability as a set: X/O)

RCL (Japan) Production							
Model	V/Hz	Destination	Code	Serial Number			
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6020201389			
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020300850			
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882030001			
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80320001			
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020301426			
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020302986			

വതര	пп
1G0	Iñi
	ш

Reason for

Modification:

Modified Article: Pump:Toner Supply Unit

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Date	e: 19-Feb-0	4	No.: MG060051	
· · · · · · · · · · · · · · · · · · ·	Prepared	by: H.T	Гаguchi	
t.				
☐ Vendor change		☐ To m	neet standards	
☐ To improve reliability		()	

PAGE: 1/1

The following parts have been modified to further ensure a smooth supply of toner from the cartridge to the development unit.

Other

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603350	G0603356	Pump – K Toner Supply Unit	1 – 1	X/O	55	10	
G0603352	G0603357	Pump – M Toner Supply Unit	1 – 1	X/O	55	13	
G0603354	G0603358	Pump – Y Toner Supply Unit	1 – 1	X/O	55	11	
G0603355	G0603359	Pump – C Toner Supply Unit	1 – 1	X/O	55	12	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P60402xxxxx
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P60402xxxxx

\sim	пп
(GO	1 4 1
ונוטרטו	ını

Reason for

Modification:

Modified Article: Stripper pawl

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Da	te: 2-Mar-04		No.: MG060052	
1	Prepared	l by: H.٦	「aguchi	
ι. Π Vendor c	hanaa	П то то		
☐ Vendor change☑ To improve reliability		(neet standards)	

PAGE: 1/1

The shape of the following has been changed to ensure oil does not stick to the rear side.

Other

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AE044050 —		Stripper pawl	1 – 1	X/O	47	12	
L	→ AE044057	Pickoff Pawl:PFA					

NOE (bapan) I roduction						
Model	V/Hz	Destination	Code	Serial Number		
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	Service Parts Only		
Savin SLP38c						
Gestetner DSc38						
Lanier 2138						
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	Service Parts Only		
Nashuatec DSc38						
Rex Rotary DSc38						
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	Service Parts Only		
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	Service Parts Only		
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	Service Parts Only		
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	Service Parts Only		

വതര	пп
1G0	Iñi
	ш

	PAGE:	1/1
04	No : MG060053	

Model: Model-J Date			ate: 2-Mar-04		No.: MG060053		
Modified Article: Stripper pawl					Prepared by: H.Taguchi		
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.					
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To m	neet standards	
Modification: ☐ To facilitate assembly ☐ To improv		prove reliability		()		
	☐ Part standardization	☐ Othe	r				

The coating for the following part has been changed to further ensure that the strippers do not scratch the fusing belt.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AE044051¬		Pickoff Pawl:Belt:Fusing	1 – 1	X/O	45	3	
	➤ AE044047	Stripper Pawls:PFA					


NCL (Japan) Froduct				
Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	Service Parts Only
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	Service Parts Only
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	Service Parts Only
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	Service Parts Only
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	Service Parts Only
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	Service Parts Only

Model: Model-J Date				e: 24-Mar-0	4	No.: MG060054
Modified Article: P	Photointerrupter	Prepared by: H.Taguchi				
From: 1st Tech. Sup	pport Sec. Service Support Dep	ot.				
Reason for Modification:	☐ Parts catalog correction☐ To facilitate assembly☑ Part standardization	☐ Vend☐ To in☐ Othe	nprove	ange e reliability	☐ To n	neet standards)

The following have been changed due to parts standardization with the J-P2. In addition, these new parts further ensure that the harness is led properly.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
AW020096	AW010098	Photointerrupter - GP2A231LRSA	1 - 1	X/X	29	15	*1
G0602625	G0802621	Guide Plate:Duplex:Exit:Upper	1 - 1	X/X	29	14	*1
G0602622	G0802622	Guide Plate:Duplex:Exit:Lower	1 - 1	X/X	29	18	*1
G0602634	G0802635	Bracket:Sensor:Paper Feed	1 - 1	X/X	29	17	*1
	11050511	Harness Clamp - LWS - 0306ZC	2		29	108	New
							*1

Note*1: Interchangeability as a set: O/O





PAGE: 2/2

Model: Model-J Date: 24-Mar-04 No.: MG060054

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020900423
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020901171
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882100001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80920001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020902018
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020902311

വതര	пп
1G0	Iñi
	ш

	PAGE:	1/

Model: Model-J Date				e: 29-Mar-04		No.: MG060055	
Modified Article: V	ertical Transport Unit	Prepared by: H.Taguchi					
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification:	dification· ☐ To facilitate assembly ☐ To improve		e reliability	()		
	☐ Part standardization	Othe	r				

The following has been changed to further improve the smoothness of paper transport.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0772531 —	Harrison	Vertical Transport Unit	1 - 1	X/O	25	*	
	→ G0772533	Transport SubUnit:Lengthwise:Ass'y			27	*	

10= (0apail) 1 10aa011011									
Model	V/Hz	Destination	Code	Serial Number					
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P60309xxxxx					
Savin SLP38c									
Gestetner DSc38									
Lanier 2138									
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P60309xxxxx					
Nashuatec DSc38									
Rex Rotary DSc38									
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L088309xxxx					
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G8093xxxx					
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P60309xxxxx					
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P60309xxxxx					
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	China	G060-69	P60309xxxxx					

	വതര	пп
151	1G0	lñl

Reason for

Modification:

Modified Article: PCU

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Dat	e: 31-Mar-0	4	No.: MG060056	
4	Prepared	by: н.т	Гаguchi	
ι.				
☐ Vendor cl	nange	☐ To m	neet standards	
	e reliability	()	

PAGE: 1/1

The adhesive for the PCU cleaning blade has been changed to further improve the operational reliability of the blade mechanism.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G7632201	G7632203	PCU:COLLAR:M-PAC:ASS'Y	1 - 1	X/O	35	1	

Other

NOE (bapan) i roddollon								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020600251				
Savin SLP38c								
Gestetner DSc38								
Lanier 2138								
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020601051				
Nashuatec DSc38								
Rex Rotary DSc38								
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882070001				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80620001				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020601768				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020602395				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	China	G060-69	P6021001734				

\sim	пп
(GO	1 4 1
ונוטרטו	ını

Reason for

Modification:

Modified Article: PCU

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification **B**ulletin

Other

Date: 31-Mar-04			4	No.: MG06009	57
		Prepared	by: H.T	「aguchi	
t.					
☐ Vendor change			☐ To m	neet standards	
☐ To improve reliability			()	

PAGE: 1/1

The inner diameter of the PCU shaft hole has been increased to accommodate the longer shaft, which was lengthened to further improve drum rotational stability.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G7632203		PCU:COLLAR:M-PAC:ASS'Y	1 – 1	X/O	35	1	
	→ G7632205	PCU - CMY					

വതര	пп
1G0	Iñi
	ш

PA	GE	: 1	ľ

Model: Model-J Date				e: 31-Mar-04		No.: MG060058
Modified Article:	PCU	Prepared	by: н.т	Гаguchi		
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improve		e reliability	()		
	☐ Part standardization	☐ Othe	r			

The cleaning brush flicker has been deleted to further ensure proper cleaning of the drum surface.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G7632205		PCU - CMY	1 – 1	O/O	35	1	
	→ G7632207	PCU:COLLAR:M-PAC:ASS'Y					

1702 (oupail) i roudoiloi								
Model	V/Hz	Destination	Code	Serial Number				
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P60307xxxxx				
Savin SLP38c								
Gestetner DSc38								
Lanier 2138								
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P60307xxxxx				
Nashuatec DSc38								
Rex Rotary DSc38								
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L088307xxxx				
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G8073xxxx				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P60307xxxxx				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P60307xxxxx				
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	China	G060-69	P60307xxxxx				

വയയി	ПП
]GO	LnJ

P	٩G	E:	1	1

Model: Model-J Date				e: 2-Apr-04		No.: MG060059	
Modified Article: Vertical Transport Unit					Prepared by: H.Taguchi		
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	Parts catalog correction	☐ Vend	or ch	ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly	☐ To improve reliability		()		
	☐ Part standardization	Othe	r				

The following has been changed to further improve the smoothness of paper transport.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0772531		Vertical Transport Unit	1 - 1	X/O	25	*	
L	→ G0772533	Transport			27	*	
		SubUnit:Lengthwise:Ass'y					

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3850C Savin SLP38c DE Gestetner DSc38F Lanier 2138E	120V, 60Hz	USA, Canada	G082-17	P89309xxxxx

RIGOH

Modification Bulletin

PAGE: 1/1

Reissued: 18-Aug-04

Model: Model-J	Date: 11-Jun-04	No.: MG060060a

MB Correction

The items in bold italics have been corrected or added.

Modified Article: Paper Feed Rollers			Prepared by: H.Taguchi		
From: 1st Tech. Support Sec. Service Support Dept.					
Reason for	Parts catalog correction	☐ Vendor ch	ange	☐ To meet standards	
Modification:	☐ To facilitate assembly	$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ $		()	
	☐ Part standardization	art standardization			

The material for the paper feed rollers has been changed to increase their target yield from 150k to 500k.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0802700	G1062700	Paper Feed Unit:No.1:Ass'y	1 – 1	X/O	19	1	
AF030049	AF030085	Paper Feed Roller - Pickup	1 – 1	X/O	19	3	*1
					21	3	
	AA100014	Retaining Ring C - Separate			19	5	*1
AF031049	AF031085	Paper Feed Roller - Feed	1 – 1	X/O	19	6	*2
					21	5	
	AA100014	Retaining Ring C - Separate			19	5	*2
AF032049	AF032085	Paper Feed Roller - Separate	1 – 1	X/O	19	25	*3
					21	33	
	AA100014	Retaining Ring C - Separate			19	5	*3
G0602750	G1062750	Paper Feed Unit:No.2:Ass'y	1 - 1	X/O	21	1	

Note *1 *2 *3: You should replace these parts as a set.

RIGOH

Modification Bulletin

PAGE: 1/1

Reissued: 19-Aug-04

Model: Model-J	Dat	te: 25-Jun-0	4	No.: MG060061	а	
MB Correction The items in bold i	talics have been correcte	d or added.				
Modified Article: In	Prepared by: H.Taguchi					
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.				
Reason for	Parts catalog correction		endor change		neet standards	
Modification:	☐ To facilitate assembly	☐ Other		()	

The securing of the imaging unit mirrors has been improved to protect against excessive shock and vibration during transport.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0801853	G0801854	Imaging Unit	1-1	X/O	13	1	

Note: The imaging unit changed as follows before the modification shown above.

The following have changed due to parts standardization with Model J-P2 (G080).

Note: In accordance with this change, the service parts for this unit have also changed to the same P/N, descriptions, indices and illustration shown in the Laser Unit section of the J-P2 catalogue.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0771856	G0801853	Imaging Unit	1 – 1	0/0	13	1	

ጦጠ	١ПЛ
ŒŒ	儿山

Reason for

Modification:

Modified Article: Transfer Unit

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Dat	e: 2-Aug-04	ı	No.: MG060062	2
	Prepared	by: н.т	「aguchi	
t.				
Uendor cl	nange	☐ To m	neet standards	
☐ To improve reliability		()	

PAGE: 1/2

The transfer unit has been modified from a transfer brush to a transfer roller system in order to further improve the accuracy of color line positioning.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G0773841	G0773842	Transfer Unit:Ass'y	1 - 1	X/O*	37	19	

Other

Note*: In accordance with this change, the following firmware upgrade and SP mode setting should be done at transfer unit installation.

Firmware Upgrade, SP Settings at Transfer Unit Installation

- Model J-P1b, Model J-P1CF -

1. Upgrade to the following firmware.

Model:	Code:	Engine Firmware:	System Firmware:
Model J-P1b	G060	B1.28 or newer	2.22 or newer
Model J-P1CF	G060 + G570	B1.28 or newer	1.12 or newer

- 2. Do the following to allow the machine to detect the new unit..
 - 1. Access SP2-399-001 [Trans_Cur_Chg] and select "1".
 - 2. Select "OK".
 - 3. Exit SP mode and turn the main switch Off/On.

Number:	Description:	Default Setting:	Adjustable Range:
SP2-399-001	Trans_Cur_Chg	0	0: Transfer Brush Type
			1: Transfer Roller Type



PAGE: 2/2

Model: Model-J Date: 2-Aug-04 No.: MG060062

- Model J-P1c -

1. Upgrade to the following firmware (SP mode setting is automatically performed).

Model:	Code:	Engine Firmware:	System Firmware:
Model J-P1c	G082	C1.28 or newer	(Unnecessary)

- ➤ The firmware for models J-P1c and J-P1b are different (ex. C1.28 vs. B1.28).
- If installing the new transfer unit on a J-P1c machine with Engine **B1.28 or newer** already installed, and you wish to update to a C-version firmware with the same numeric name (e.g. from B1.28 → C1.28), please be sure to 1) first downgrade to B1.27 and then 2) install C1.28 or newer. This is because it is not possible to directly update a Bxxx version to a Cxxx version with the same numeric name.

വതര	пп
1G0	Iñi
ICONCON	ш

Reason for

Modification:

Modified Article: Toner Cartridge Holder - Bk

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

□ Part standardization

Modification Bulletin

☐ To improve reliability

Date: 6-Aug-04		No.: MG060063		
		Prepared	by: H.T	aguchi
t.				
☐ Vendor change		☐ To m	neet standards	

)

PAGE: 1/1

The following have been changed due to part standardization with Model J-P2.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0603202	G0773202	HOLDER: TONER CARTRIDGE:	1 – 1	X/O	33	1	
		BK: DOM: ASS'Y					
G0601560	G0771560	DUCT: POWER SUPPLY UNIT:	1 – 1	X/O	71	4	
		UPPER POSITI					

Other

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C Savin SLP38c Gestetner DSc38 Lanier 2138	120V, 60Hz	USA, Canada	G060-17	P6020500869
Gestetner DSc38 Nashuatec DSc38 Rex Rotary DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020600851
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882060001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80520001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020502615
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020602301
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	China	G060-69	P60207xxxx

വതര	пп
1G0	Iñi
ICONCON	ш

)	PAGE: 1/1
-04	No : MG060064

Model: Model-J Date			e: 6-Aug-04		No.: MG060064	
Modified Article: Toner Cartridge Holder - Bk				Prepared by: H.Taguchi		
From: 1st Tech. Sup	port Sec. Service Support Dep	ot.				
Reason for Parts catalog correction Vendor cha				ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improv		e reliability	()		
☐ Part standardization ☐ Other						

The shape of the following part has been changed in accordance with the metal plate change for the mainframe.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0773202	G0603203	HOLDER: TONER CARTRIDGE: BK: DOM: ASS'Y	1 – 1	X/O	33	1	

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P6020500553
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P6020501651
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L0882060001
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G80520001
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P6020502264
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P6020503027
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	China	G060-69	P60207xxxx

በመጠ	叽
1G0	Ln

PAGE: 1/2

Model: Model-J			Date: 5-Oct-04			No.: MG060065
Modified Article: Guide Plate: Registration: Middle: ADH				Prepared	by: H.7	Гаguchi
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	Reason for Parts catalog correction Vendo		dor ch	ange	☐ To n	neet standards
Modification:	ication:		nprove	e reliability	()
	☐ Part standardization	☐ Othe	r			

The following has been changed to further improve the smoothness of paper transport.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G0602613	G0602645	Guide Plate: Registration: Middle:	1 - 1	X/O	23	30	
		ADH					

Model	V/Hz	Destination	Code	Serial Number
Ricoh Aficio AP3800C	120V, 60Hz	USA, Canada	G060-17	P60309xxxxx
Savin SLP38c				
Gestetner DSc38				
Lanier 2138				
Gestetner DSc38	220 - 240V, 50/60Hz	Europe, etc.	G060-22	P60309xxxxx
Nashuatec DSc38				
Rex Rotary DSc38				
Lanier 2138 AH	220 - 240V, 50/60Hz	Europe, etc.	G060-24	L088309xxxx
Infotec IP 280	220 - 240V, 50/60Hz	Europe, etc.	G060-26	4G8093xxxx
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Europe, etc.	G060-27	P60309xxxxx
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	Asia	G060-29	P60309xxxxx
Ricoh Aficio AP3800C	220 - 240V, 50/60Hz	China	G060-69	P60309xxxxx

	ПП
(G(0)	

Reason for

Modification:

Modified Article: Development Unit

From: 1st Tech. Support Sec. Service Support Dept.

☐ Part standardization

Modification Bulletin

	Oate: 22-Apr-0	05	No.: MG060066	
Development Unit	Prepared b	oy: H.Tag	uchi	
pport Sec. Service Support Dept.				
☐ Parts catalog correction ☐ Vendor cl	hange [Other		
☐ To facilitate assembly ☐ To improve	ve reliability	☐ To mee	et standards	

PAGE: 1/1

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number G7643001	number G7643005	Development Unit - C	1-1	X/O	35	3	
G7643002	G7643006	Development Unit - M	1-1	X/O	35	2	
G7643003	G7643006	Development Unit - Y	1-1	X/O	35	4	

☐ Product Safety

Change: The shape of the joint area of the development unit was changed.

Reason: To make sure the development unit gear engages with the mainframe gear

correctly (to make sure SC38x does not occur).