

VCR990202 Month of Issue: February 1999 Classification: Yellow Page 1 of 2

VIDEO TECHNICAL BULLETIN

MODELS	VCM301HM	VCM302HM	VCM311HM	VCM312HM
	VCM321HM	VCM331HM	VCM522HM	VCMH711HM
	VCMH721HM	VCMH73HM	VCMH731HM	

- **<u>SYMPTOM</u>** Failure of the bias oscillator, leading to permanent erase or loss of the linear audio track during record and playback.
- <u>CAUSE</u> Due to an increase in the localised heat generated by T651, Q651 can go out of tolerance. This may lead to Q652 and R658 failing as well.
- **<u>ACTION</u>** Carry out the following circuit change.
 - 1. Replace R658 with the same type.
 - 2. Replace C655 with a 47uF, 16V capacitor.
 - 3. Replace L651 with the one listed below.
 - 4. Replace Q652. If the PWB is damaged so that this component can not be fitted, follow the instructions on page 2 to fit a radical component.
 - 5. Replace Q651 where necessary and bending it away from the transformer, as shown in the diagram below.

PART NUMBER

REF NO DESCRIPTION

R658 C655 L651 Q652	Resistor Capacitor Coil Transistor	VRD-RA2EE4R7J VCEA9M1CW476M+ VP-DF221K0000* VSDTC323TS/-1	AA AA AB AB
	A	Push Q651 away from T651 as Q651 connect shown from the base of	ions (as viewed of the device)

Figure 1: Correct Positioning of Q651

Sharp Electronics (UK) Limited



PRICE CODE

Reference TBT9902066 Revision 4

White – Carry out as required Yellow – Carry out as required and whenever the unit comes in for service Red – Carry out on all units



VIDEO TECHNICAL BULLETIN

Month of Issue: February 1999 Classification: White

Page 2 of 2

VCR990202




Figure 2: Location of Q652

Fit the radial transistor (Q652) as shown in the diagram above.

Note that the pin connections of Q652 are the same as Q651.

- C (collector) to the negative end of C655.
- E (emitter) to the negative end of C654.
- B (base) to the jumper wire J176.





White – Carry out as required Yellow – Carry out as required and whenever the unit comes in for service Red – Carry out on all units