



VIDEO TECHNICAL BULLETIN

Month of Issue: July 1999

Classification: White

Page 1 of 2

MODELS VCM26HM VCM271HM VCM27HM VCMH67HM

VCMH68HM

SYMPTOM Failure of the front panel buttons.

CAUSE Excess travel of the button, causing the hinge to fracture.

ACTION Replace the broken button assemby and add the holder as shown in the following

diagrams.

Note that there are two types of holder for different models.


Holder one


VCM26HM VCMH67HM

Holder two

VCM271HM VCM27HM VCMH68HM

REF NO	DESCRIPTION	PART NUMBER	PRICE CODE
-	Holder	LHLDZ2072GEZZ	AE
-	Holder	LHLDZ2035GEZZ	AD





1. Remove the original button assembly by cutting the melt point as shown









Month of Issue: July 1999 Classification: White

Page 2 of 2


VIDEO TECHNICAL BULLETIN



2a. Melt the Standby and Eject button into position for Holder One models (note that there is only one melt point)



2b. Melt the Standby and Eject button into position for Holder Two models (note that there are two one melt point)



3. Fitting the Holder

