### **SCHEMATIC DIAGRAM**

IMPORTANT SAFETY NOTICE:

BE SURE TO USE GENUINE PARTS FOR SE-CURING THE SAFETY AND RELIABILITY OF THE SET.

PARTS MARKED WITH " \( \triangle \) " AND PARTS SHADED (IN BLACK) ARE ESPECIALLY IMPORTANT FOR MAINTAINING THE SAFETY AND PROTECTING ABILITY OF THE SET.

BE SURE TO REPLACE THEM WITH PARTS OF SPECIFIED PART NUMBER.

#### SAFETY NOTES:

- 1. DISCONNECT THE AC PLUG FROM THE AC OUTLET BEFORE REPLACING PARTS.
- 2. SEMICONDUCTOR HEAT SINKS SHOULD BE REGARDED AS POTENTIOL SHOCK HAZARDS WHEN THE CHASSIS IS OPERATING.

#### NOTES:

- 1. The unit of resistance "ohm" is omitted (k=1000 ohm, M=1 Meg ohm).
- 2. All resistors are 1/8 watt, unless otherwise noted.
- 3. The unit of capacitance "F" is omitted ( $\mu=\mu F$ ,  $p=\mu\mu F$ ).
- 4. The values in parentheses are the ones in the PB mode; the values without parentheses are the ones in the REC mode.

#### **VOLTAGE MEASUREMENT CONDITIONS:**


- DC voltages are measured between points indicated and chassis ground by VTVM, with AC230V/ 50Hz supplied to unit and all controls are set to normal viewing picture unless otherwise noted.
- 2. Voltages are measured with 10000µV B & W or colour noted.

WAVEFORM MEASUREMENT CONDITIONS: 10000μV 87.5 percent modulated colour bar signal is fed into tuner.

#### **CAUTION:**


This circuit diagram is original one. Therefore there may be a slight difference from yours.

VC-M26HM/LM VC-MH67HM/LM VC-M26HM/LM VC-MH67HM/LM VC-M27HM VC-MH68HM VC-M271LM VC-M271LM



VOLTAGE MEASUREMENT MODE

69



VC-M26HM/LM VC-M27HM VC-M271LM VC-MH68HM MAIN CIRCUIT (3) (VC-M26HM/LM, M27HM, M271LM) -{scl TO MAIN 4

- (PC 9V
- AT 33V
- AT 12V
- (AT 5V
- (V-00)
- (A-040) (2K,+) UNT 150 1 (ALD) RIFU-06720E22 C1402 C1403 C1404 109 109 109 1009 10CCY\_S1 RISIO 0 IMONOI (VRS-CYTUF000US) | Lodor | 12 / O(F) | | R6602 | R6801 | | 8.2 / 8.2 / (CY.33) | L6601 R6803 12 820 071 ICY,53 EI SCART SC2501UN OSOCZ1290GEZZ 3 5 11 12 6


VOLTAGE MEASUREMENT MODE PB . . . . . Parentheses ( ) REC . . . . Without Parentheses

VC-MH68HM VC-MH68HM VC-M27HM VC-M27HM VC-M271LM VC-M27HM VC-M271LM MAIN CIRCUIT (4) (VC-M26HM/LM, M27HM, M271LM) LOADING MOTOR DRIVER R9924 09 (QJUM-0001AJFWX,) ™\_" R904 6.8M (1/2W) (JAX,D) TU PC 9V REG D C939 (.8) D984 Z029CLM 1A3-F D960 D961 1A3-F 1A3-F (///-1X) (///-1X TU PC 5V REG R914 IK II/4Wi + C928 # 479 - (50V) IAVA C937 1000P T \$ R941 \$ 3,9K 1 (CY.S) D928 D929 EX06196E DX0053GE MTZJ6.2C 3 5 9 11


VOLTAGE MEASUREMENT MODE

PB . . . . . Parentheses ( )
REC . . . . Without Parentheses


VC-M26HM/LM VC-MH67HM/LM VC-M26HM/LM VC-M27HM VC-MH68HM VC-M27HM VC-MH68HM VC-M271LM



VC-M26HM/LM VC-M168HM VC-M271LM




TERMINAL PWB (VC-MH67HM/LM, MH68HM)



MPX PWB (VC-MH67HM/LM, MH68HM)


G





OPERATION PWB (VC-M27HM, M271LM, MH68HM)

10 11 12 3 5 6


VC-M26HM/LM VC-M27HM VC-M271LM








## PRECAUTION ON FRONT PANEL SET-UP



Before attaching the front panel in position, rnake sure that the cassette cover open lever is in its right place (lower-most). If it is out of position, push it down with a finger.

Keep the cassette over about 45° open and make sure that the cassette cover open lever is between the front panel and the cassette cover. Now fix the front panel in place.

Do not mount the front panel with the cassette cover tilted too open.
Otherwise the cassette cover might wrongly run on the cassette housing.



Removing the cassette compartment


- cover.
  ① Open the cassette compartment Open the cassette comparts cover fully.

  Remove the center positioner.


  Slide the cover to the right.

  Slightly bend the cover.

- ⑤ Draw out the left-side rod.




### PRECAUTION ON FRONT PANEL SET-UP



Before attaching the front panel in position, make sure that the cassette cover open lever is in its right place (lower-most). If it is out of position, push it down with a finger.

Keep the cassette over about 45° open and make sure that the cassette cover open lever is between the front panel and the cassette cover. Now fix the front panel in place.

Do not mount the front panel with the cassette cover tilted too open.
Otherwise the cassette cover might wrongly run on the cassette housing.



Removing the cassette compartment

- ① Open the cassette compartment Cover fully.

  Remove the center positioner.

  Slide the cover to the right.

  Slightly bend the cover.

  Draw out the left-side rod.

# PACKAGING WEIGHTS DATA SHEET


Model: VCM26HM

MATERIAL TYPE	WEIGHT (grammes)
Cardboard	610
Paper	0
Total Card	610
EPS	89
PE	0
PP	0
Other Plastic	0
Total Plastic	89
Aluminium	0
Steel	0
Total Metal	0
Total Wood	0
Total Glass	0
Other	0

## 12. PACKING OF THE SET

## ■ Setting position of the Knobs

RF conv. CH. preset at "E36" position



MARK ★ Not Replacement Item

## VCR970803



Month of Issue: August 1997

Classification: White

## **VIDEO TECHNICAL BULLETIN**

Page 1 of 1

<b>MODELS</b>	VCM26HM	VCM27HM	VCMH67HM
	VCMH68HM		

V 01/11/0011/1

**REASON** The price codes for the following items are not listed in the service manual.

**ACTION** Please update the service manual as below.

REF NO	<u>DESCRIPTION</u>	PART NUMBER	PRICE CODE
CNV4451	Irish RF Converter	RCNVR0181UMZZ	AY
IC903	IC, MC44603	VHIMC44603/-1	AM
Q605	Transistor, 2PD601AR	VS2PD601AR/-1	AA
C939	Capacitor, 0.1uF Mylar	RC-FZ029CUMZZ	AD
601	Main Frame	GCABB1180UMZZ	AN
602	Antenna Terminal Cover	GCOVA2031UMZZ	AE
602	Antenna Terminal Cover	GCOVA2031UMZZ	AE
602	Antenna Terminal Cover	GCOVA2034UMZZ	AE
501	Front Panel Assembly	CPNLC2223TEVO	AY
501	Front Panel Assembly	CPNLC2231TEVO	AX
501-3	Cassette Flap	HDECQ1625UMSC	AF
501-4	Decoration Window	HDECQ1631UMSA	AF
501-8	Operate Button	JBTN-2799UMSD	AD
501-9	CH/SET Button	JBTN-2800UMSD	AF
501-12	Play Button	JBTN-2810UMSD	AF
501-13	Stop Button	JBTN-2811UMSD	AF
	Remote Control	RRMCG0185AJSA	AX

Sharp Electronics (UK) Limited CE Technical Support Group

Originator 

AUV Supervisor \_\_\_\_\_ Approval Date \_ / / Reference TB-T9706023







Month of Issue: February 1998

Classification: White

## VIDEO TECHNICAL BULLETIN

Page 1 of 1

MODELS VCM26HM VCM27HM VCM271HM

VCMH67HM VCMH68HM VCMH69HM

**SYMPTOM** No operation from the remote control.

**CAUSE** Remote control batteries or the remote control receiver.

**ACTION** If replacement of the remote control batteries does not reinstate the remote

control functions, then it is possible that the remote control receiver is at

fault.

Use the part number below for the remote control receiver.

REF NO DESCRIPTION PART NUMBER PRICE CODE

- Remote control receiver RRMCU0058GEZZ AG







## **VIDEO TECHNICAL BULLETIN**

Month of Issue: August 1998 Classification: White

Page 1 of 1

VCM26HM VCM27HM VCMH67HM **VCMH68HM MODELS** 

The part numbers for switches S8801/2/3/4 are incorrectly shown in the service **REASON** 

manual

**ACTION** Please update service manual with the part numbers given below.

REF NO	DESCRIPTION	PART NUMBER	PRICE CODE
S8801	Pause/Stop switch Play switch	QSW-K0086GEZZ	AC
S8802		QSW-K0086GEZZ	AC
S8803	Record switch Stop switch	QSW-K0086GEZZ	AC
S8804		QSW-K0086GEZZ	AC







Month of Issue: February 1998

Classification: White

## VIDEO TECHNICAL BULLETIN

Page 1 of 1

MODELS VCM26HM VCM27HM VCM271HM

VCMH67HM VCMH68HM VCMH69HM

**SYMPTOM** No operation from the remote control.

**CAUSE** Remote control batteries or the remote control receiver.

**ACTION** If replacement of the remote control batteries does not reinstate the remote

control functions, then it is possible that the remote control receiver is at

fault.

Use the part number below for the remote control receiver.

REF NO DESCRIPTION PART NUMBER PRICE CODE

- Remote control receiver RRMCU0058GEZZ AG







Month of Issue: June 1998

Classification: White

## VIDEO TECHNICAL BULLETIN

Page 1 of 1

VCM26HM **MODELS** 

VCM29HM VCMH675HM VCM27HM VCMH68HM VCM271HM VCMH69HM

**SYMPTOM** No colour and/or noisy picture.

CAUSE Due to the close proximity of the body of X501 to the base of the drum

assembly X501 can be shunted by the drum assembly and cause an open

circuit.

**ACTION** Repair the PWB as necessary and re-seat X501 to avoid contact with the base

of the drum assembly.

**REF NO DESCRIPTION** PART NUMBER PRICE CODE

AΗ X501 RCRSB0166GEZZ Crystal







Month of Issue: November 1998 Classification: White

Page 1 of 1

## VIDEO TECHNICAL BULLETIN

MODELS VCM26HM

**SYMPTOM** Failure of the power supply to operate - no display and no operation. Nomally the

power supply can be heard to trip.

**CAUSE** R955 open circuit.

**ACTION** Replace R995.

REF NO DESCRIPTION PART NUMBER PRICE CODE

R995 Resistor 10R, 1/16W VRS-CY1JF100J AA







Month of Issue: Febuary 1999 Classification: White

Page 1 of 1

## VIDEO TECHNICAL BULLETIN

MODELS VCM26HM VCMH67HM VCMH675HM

**SYMPTOM** The operation of the tape control buttons on the front panel, particually the fast

forward and rewind buttons, under certain conditions, become sensitive and operate

by slight pressure on the top of the front cabinet.

**CAUSE** A degree of warpage may be present in the front panel which will alter the position of


the play button assembley in relation to the switches on the main PWB. This will then

increase the sensitivity of the button operation.

**ACTION** Fit a 25.0 x 9.0 x 0.5mm spacer as indicated in the diagram below.

REF NO DESCRIPTION PART NUMBER PRICE CODE

- Spacer SPACER001UMZZ TBA









Month of Issue: June 1999 Classification: White

Page 1 of 1

## **VIDEO TECHNICAL BULLETIN**

MODELS VCM26HM VCM27HM VCM271HM VCMJ67HM


VCMH675HM VCM68HM

**SYMPTOM** When recieving a signal through the tuner, the screen goes into blue mute. Note that

this will not occur if the blue back fucntion is turned off.

**CAUSE** Input to sync seperator (pin 2 of IC2401) not present due to C2408 being dry jointed.

**ACTION** Re-solder C2408.









Month of Issue: June 1999 Classification: White

Page 1 of 2

### VIDEO TECHNICAL BULLETIN

MODELS VCM26HM VCM271HM VCM27HM VCHM67HM

VCHM675HM VCMH68HM


**SYMPTOM** Head switching point requires adjustment.

#### **ACTION**

When carrying out the head switching adjustment for any of the above models, follow the procedure outlined below.

- 1. Remove the front panel so that access can be gained to the test mode pins.
- 2. Insert the alignment tape (VROCPSV) into the machine.
- 3. Play back the alignment tape.
- 4. Make a momentary short circuit between test points TP5001 and TP5002 (see diagram on page 2).
- 5. Press the PLAY button the automatic adjustment is completed at this point (the play symbol may flash during this process).
- 6. Press the STOP button to return to the normal mode.

Correct head switching points can be checked by connecting an oscilloscope to the video output and triggering it off the head switching pulse (TP2202). Note that if the head switching points can be monitored during the automatic setting procedure.



Relationship Between the Head Switching Point and the Video Output Waveform









## **VIDEO TECHNICAL BULLETIN**

Month of Issue: June 1999 Classification: White

Page 2 of 2



Location of TP5001 and TP5002 at the Front of the Main PWB



Location of TP2202 (Head Switching Point) Test Point at the Rear of the Main PWB







## VIDEO TECHNICAL BULLETIN

Month of Issue: July 1999

Classification: White

Page 1 of 2

MODELS VCM26HM VCM271HM VCM27HM VCMH67HM

VCMH68HM

**SYMPTOM** Failure of the front panel buttons.

**CAUSE** Excess travel of the button, causing the hinge to fracture.

**ACTION** Replace the broken button assemby and add the holder as shown in the following

diagrams.

Note that there are two types of holder for different models.


Holder one


VCM26HM VCMH67HM

Holder two

VCM271HM VCM27HM VCMH68HM

REF NO	DESCRIPTION	PART NUMBER	PRICE CODE
-	Holder	LHLDZ2072GEZZ	AE
-	Holder	LHLDZ2035GEZZ	AD





1. Remove the original button assembly by cutting the melt point as shown









Month of Issue: July 1999 Classification: White

Page 2 of 2


## **VIDEO TECHNICAL BULLETIN**



2a. Melt the Standby and Eject button into position for Holder One models (note that there is only one melt point)



2b. Melt the Standby and Eject button into position for Holder Two models (note that there are two one melt point)



3. Fitting the Holder





## VCR2000 01 02

Page 1 of 1

Month of Issue: January 2000 Classification: White

## **VIDEO TECHNICAL BULLETIN**

VCM26HM VCM27HM VCM29HM **MODELS** VCM271HM

> VCMH67HM VCMH675HM VCMH68HM VCMH69HM

Dead or tripping power supply. SYMPTOM

-25V supply is low or missing, or no power supply feedback. **CAUSE** 

If the –25V supply is low or missing, replace D927 and R995. <u>ACTION</u>

If the D927 and R995 are not found to be faulty, then it is likely that the opto coupler,

IC901, is faulty.

Please use the part numbers below for replacement parts.

REF NO	DESCRIPTION	PART NUMBER	PRICE CODE
D927	Diode, 1SS147	VHD1SS147//-1	AA
R995	SMD resistor, 10 (1/16W)	VRS-CY1JF100J	AA
IC901	Photo coupler	RH-FX0007GEZZ	AE





## VCR2000 06 01

Month of Issue: Classification:

June 2000 White

Page 1 of 1

### VIDEO TECHNICAL BULLETIN

MODELS VCM311HM VCM312HM VCM522HM VCMH721HM

VCMH722HM VCMH73HM VCMH731HM VCM26HM

VCM27HM VCM271HM VCMH67HM VCMH675HM

VCMH68HM VCMH69HM

## **SYMPTOM** Various faults:

- No operation
- Will not come out of standby
- EEPROM can not be programmed correctly
- Erratic or intermittent functions
- Will not respond to the remote control
- Will not respond to the front panel buttons
- Erratic or intermittent timer programming operations

## **CAUSE** Microprocessor program crash.

All of the models listed above utilise a back-up power facility that maintains the memory inside the main processor in case of a mains power failure. If the mains failure is of reasonable short duration, then all original settings are retained and the unit will continue to function as before the mains interruption (including the retention of any corrupted data).

#### **ACTION** Discharge back-up capacitor connected to the supply pins of the processor.





## **VCR990702**

Month of Issue: November 2000

Classification:

White Page 1 of 2

## VIDEO TECHNICAL BULLETIN

MODELS VCM26HM VCM271HM VCM27HM VCMH67HM

VCMH68HM

**SYMPTOM** Failure of the front panel buttons.

**CAUSE** Excessive travel of the button, causing the hinge to fracture.

**ACTION** Replace the broken button assembly and add the holder as shown in the following

diagrams.


Note that there are two types of holder for different models.


Holder one: VCM26HM, VCMH67HM

Holder two: VCM271HM, VCM27HM, and VCMH68HM

REF NO DESCRIPTION PART NUMBER PRICE CODE

Holder oneHolder twoLHLDZ2072GEZZAEHLDZ2035GEZZAD





1. Remove the original button assembly by cutting the melt point as shown

## **Sharp Electronics (UK) Limited**

Reference TBT9905070 Revision 2





## VCR990702


Month of Issue: November 2000

Classification:


White

## Page 2 of 2


## **VIDEO TECHNICAL BULLETIN**



2a. Melt the Standby and Eject button into position for Holder One models (note that there is only one melt point)



2b. Melt the Standby and Eject button into position for Holder Two models (note that there are two one melt point)



3. Fitting the Holder

## **Sharp Electronics (UK) Limited**

Reference TBT9905070 Revision 2

