

SONY[®]

Sony Service Company
National Technical Services
A Division of Sony Electronics Inc.
Park Ridge, New Jersey 07656

CONFIDENTIAL

**Service Bulletin
Hi-Fi Products**

CSA-13

Model: TA-E90ES

No. 496

Subject: No Sound

Date: October 10, 1996

Symptom:

(351)

The customer complaint may state the sound cannot be heard several minutes after the unit is powered ON.

Solution:

Readjust DC bias as follows:

Main Board: RV401, 451

EQ Board: RV101, 151

The procedure is outlined on pg. 5 of the Service Manual.

