

INSTRUCTIONS FOR USE

S 229

Dial Gage



Sylvac S.A.
Ch. du Cloalet 16
Case Postale
1023 Crissier / Switzerland



CONTENTS

OPERATING MANUAL FOR DIAL GAUGE.....	4
I.1 INTRODUCTION.....	4
I.2 FEATURES.....	4
II MULTIFUNCTIONAL DISPLAY.....	5
II.1 DESCRIPTION.....	5
III. FUNCTIONS.....	5
III.1 HOW TO USE BUTTONS.....	5
III.2 OPERATION.....	5
III.3 SWITCH ON.....	5
III.3.1 Using buttons.....	5
III.3.2 Using OPTO-RS.....	6
III.4 MEASURING MODE.....	6
III.4.1 Change units.....	6
III.4.2 Reset (recall preset).....	6
III.5 REFERENCE / HOLD MODE.....	6
III.5.1 Hold measurement, transmit measured value.....	6
III.5.2 Change references.....	6
III.6 PRESET MODE.....	7
III.6.1 Entering a preset value.....	7
III.6.2 Select digit to change.....	7
III.6.3 Change value.....	7
III.6.4 Change sign of preset.....	7
III.6.5 Validate value of preset.....	8
III.6.6 Recommended use.....	8
III.7 SWITCH OFF.....	8
III.8 CHANGE BATTERY.....	8
III.9 CHANGE THE DIRECTION OF MEASUREMENT PERMANENTLY.....	8
IV INITIALIZATION FUNCTIONS.....	8
IV.1 CHANGE THE DIRECTION OF MEASUREMENT AND THE RESOLUTION.....	9
IV.2 LOCKING THE [MODE] BUTTON.....	9
IV.2.1 Operation.....	9
IV.2.2 How to lock the [mode] button.....	9
IV.2.3 Display indicator.....	9
IV.2.4 Unlocking the [mode] button.....	9
IV.3 RESETTING THE INSTRUMENT.....	9
V ERROR MESSAGES ON THE DISPLAY.....	9
V.1 DISABLE ERROR MESSAGE.....	9
VI OPERATION WITH OPTO-RS CONNECTOR.....	10
VI.1 OPERATING MODES.....	10
VI.2 INSERTING THE OPTO-RS CONNECTOR.....	10
VI.3 TRANSMISSION PARAMETERS.....	10
VI.4 OPERATION IN SIMPLEX MODE.....	10
VI.5 ERROR MESSAGES.....	10
VII SPECIFICATIONS.....	11
VIII ACCESSORIES.....	12
IX NOTES.....	12
X. APPENDICES.....	12
X.1 CHANGING THE BATTERY.....	12
X.2 RESETTING THE INSTRUMENT.....	12
X.3 REFERENCE MODE.....	12
X.4 CONNECTING THE OPTO-RS CABLE.....	12
XI IN CASE OF PROBLEMS.....	13
XI.1 [MODE] BUTTON INOPERATIVE.....	13
XI.2 THE INSTRUMENT WON'T SWITCH OFF.....	13

Operating manual for dial gauge

I.1 Introduction

The Sylvac S229 dial gauge can be used as a replacement for mechanical dial gauges, thanks to external dimensions conforming to the various standards for this type of instrument.


The functions of the S229 dial gauge are as follows:

- change units mm/INCH
- change zero point for any probe position
- enter a reference value other than 0.000 mm (preset)
- possibility of measuring with two different references
- store measurement (display hold)
- transmission of measurement to a statistical processing system

The dial gauge has three operating modes, which are selected by pressing the [mode] button for more than 1 second. The functions of each mode are activated by momentarily depressing (< 1 sec) the [set] or [mode] buttons.

The S229 dial gauge is equipped with an OPTO-RS compatible data output.


I.2 Features



1. Lifting cap (M2.5 interchangeable)
2. 8 mm clamping shaft
3. Contact point (M2.5 interchangeable)
4. Rotating dial (270°)
5. Cover for OPTO-RS connector
6. Pull-out slide for battery replacement
7. Multifunctional LCD
8. [mode] button
9. [set] button (ON/OFF)

II Multifunctional display

II.1 Description



1. Active reference indicator (REFI or REFII)
2. Measured value
3. Battery life warning display
4. Indicating cursor for preset
5. Unit of measurement indicator
6. Locked mode indicator
7. Hold indicator
8. Display .0005/.00005 INCH
9. Preset indicator
10. Preset mode indicator

III. Functions

III.1 How to use buttons

	MODE		SET		MODE	SET
Mode	> 1sec	< 1sec	> 1sec	< 1sec	= 1sec	
Mesure		mm ↔ inch	Off	On Set	DIR ↔ RES	
References		Ref I ↔ Ref II	Off	On Data out, hold	MODE0 ↔ MODE1	
Preset		[0.00.123]	[Incr. digit 0.1.2...9]	Digit = digit + 1	> 3 sec (MODE 1, 2, 3)	RESET

III.2 Operation

Press for less than 1 second to activate button function



Press for more than 1 second to activate mode change




III.3 Switch on

III.3.1 Using buttons

Momentarily depress the [set] button.

The instrument switches on in the mode that was active when it was last switched off (eg measuring mode).



III.3.2 Using OPTO-RS


Activate the LED of the OPTO-RS connector or transmit any command from the peripheral equipment to switch the instrument on. The instrument responds with its identification (SY225.xx.x).

III.4 Measuring mode

III.4.1 Change units

Momentarily depress the [mode] button to change the unit.


Note: except for 'mm only' instruments.



III.4.2 Reset (recall preset)

Momentarily depress the [set] button.

The preset value of the active reference is validated as the new zero point (eg 0.000 mm).




III.5 Reference / HOLD mode

III.5.1 Hold measurement, transmit measured value

Place the instrument in reference mode by pressing [mode] for more than 1 second


Momentarily depress the [set] button.

Note: The displayed value is automatically transmitted to the OPTO-RS232 interface. Hold is released if the connector is inserted with the LED active or if the peripheral equipment makes a transmission request (see also operating manual for OPTO-RS connector).




III.5.2 Change references

Place the instrument in reference mode by pressing [mode] for more than 1 second.



Momentarily depress the [mode] button to change the active reference.




III.6 Preset mode

III.6.1 Entering a preset value

A different preset value can be entered for each reference (REF I and REF II). **Maximum preset values are: ± 2999.99 mm/± 89.9995 IN.**


1. Select the active reference (reference mode).
2. Select preset mode (press [mode] for more than 1 second until 'PRESET' indicator appears)



III.6.2 Select digit to change

Momentarily depress [mode] the required number of times until the cursor is located under the digit to be changed.


The cursor returns to the sign after the last digit.



III.6.3 Change value


Momentarily depress [set] the required number of times to increase the underlined digit in increments of '1'.

Alternatively, keep the [set] button pressed until the required value is obtained.



III.6.4 Change sign of preset

Move the cursor under the sign, then momentarily depress [set].



III.6.5 Validate value of preset

Press [mode] for more than 1 second until the 'PRESET' indicator disappears.


III.6.6 Recommended use

Set value of preset to 0.000 for reference I, and use reference II for different preset values.

III.7 Switch off

Press the [set] button until the display disappears.

It is not possible to switch the instrument off in preset input mode, or when the LED of the OPTO-RS connector is illuminated.




III.8 Change battery

Change the battery when the 'B' indicator appears.


Clear the display by pressing the [mode] and [set] buttons.

Note: after changing the battery, the instrument displays « RESET », then reverts to measuring mode and displays 0.000 mm (or 0.00 mm).



III.9 Change the direction of measurement permanently

Remove the rear cover and reverse the direction of the switch.




Reset the instrument (press [mode] and [set] to clear the display) to validate the change of direction of measurement

IV Initialization functions

These functions make it possible to change the initial parameters of the instrument. These changes are not permanent (disabled after battery replacement or a reset) and require a good working knowledge of the instrument.

IV.1 Change the direction of measurement and the resolution

Select measuring mode, then momentarily depress [mode] and [set] simultaneously the required number of times to change the resolution and the required direction of measurement. (Resolution cannot be changed on instruments displaying hundredths).



Then check the zero point and the unit of measurement.

IV.2 Locking the [mode] button


IV.2.1 Operation

Disables the function of the [mode] button to prevent the accidental modification of instrument parameters by the user. This function can only be activated in reference mode.

The [set] button (transmit data/hold measurement) remains active.

IV.2.2 How to lock the [mode] button


Place the instrument in reference mode, then momentarily depress [set] and [mode] simultaneously to display <MOdE 0>.



Then check the active reference.

IV.2.3 Display indicator

The 'C' indicator appears whenever [mode] is used.



IV.2.4 Unlocking the [mode] button

Momentarily depress [set] and [mode] simultaneously, or reset the instrument.

IV.3 Resetting the instrument


This function recalls the initial configuration of the instrument (status after battery replacement or RESET). Press [mode] and [set] simultaneously to clear the display. The latter briefly displays "RESET" when both buttons are released.

V Error messages on the display

If a measuring error is detected, the instrument displays the 'Err0' message and simultaneously transmits the <ERRO> message to the OPTO-RS output.

V.1 Disable error message

Press [set] to restart measurement, or acknowledge by means of an OPTO-RS transmission request.



Important: then check the measurement reference.

VI Operation with OPTO-RS connector

VI.1 Operating modes

The dial gauge works in simplex mode: the displayed value is sent from the instrument or requested from the peripheral equipment (pedal or request from peripheral equipment). It can also be used with a duplex OPTO-RS connector. It recognizes any command (ASCII character sent by the computer) as a request to transmit the displayed value.

VI.2 Inserting the OPTO-RS connector

Check that the connector is the right way round by means of the polarizing slot. Neither the instrument nor the connector can be damaged if the latter is inserted the wrong way round.

VI.3 Transmission parameters

4800 Bd, even parity, 7 data bits, 2 stop bits

VI.4 Operation in simplex mode

- Transmission from the instrument: select reference mode, then momentarily depress [set] to transmit the displayed value. The value is transmitted regardless of the status of the LED of the OPTO-RS connector. If the LED is extinguished, the display remains frozen until [set] is pressed again or a transmission request is made by the peripheral equipment.
- Transmission request by the peripheral equipment: transmission of the measured value can be requested from the peripheral equipment (printer, computer) in measuring and reference modes, by sending any ASCII character or by interrupting the LED for 140 msec.

See operating manual of optical connector for details.

VI.5 Error messages

In the event of an error, the instrument sends the following message:

<ERR0> Measuring system error. Acknowledge by a data request or by means of the [set] button.

VII Specifications

Measuring range:	0-12.5 mm / .5" 0-25 mm / 1"
Resolution:	0.001 mm / .00005" (0.01 mm / .0005")
Accuracy:	5µm (.0002") / 10µm (.0004")
Repeatability:	2µm or .0001" (+/-2s)
Max. probe travel speed:	1.5 m/sec.
Number of measurements per second:	
0.01 mm:.....	8 measurements/sec.
0.001 mm:.....	5 measurements/sec.
Measuring force:	0.6 to 1.1 N for 0-25 mm (1") 0.7 to 0.95 N for 0-12.5 mm (.5")
Units of measurement:	metric/imperial (inch) (direct conversion)
Maximum preset:	±2999.99 mm/±89.9995 IN
Measuring system:	SYLVAC system (patented)
Display:	digital LCD sign (-), 6 digits (7 in ") height 8.5 mm, (0.05 mil in inch), display of unit and operating mode.
Power:	1 lithium battery 3 V, type CR2032, capacity 190 mAh.
Battery types:	Toshiba CR2032 Maxell CR2032 Renata B/CR2032 Sanyo CR2032 Ucar CR2032 Panasonic CR2032 Rayovac CR2032 Varta CR2032.
Power consumption:	60 µA.
Battery life:	1 year or > 3000 hours with normal use When 'B' is displayed, the remaining battery life is several hours. (To protect the environment, please recycle the battery at a facility intended for this purpose.)
Working temperature:	+5 to +40 °C.
Data output:	RS232 compatible format.
Interface:	RS232 interface cable, with optical coupling.
Construction:	- aluminium case - polyamide rotating dial (270°) - hardened and ground stainless-steel measuring spindle
Clamping:	lower bushing diameter 8 h6 mm
Contact point:	M 2.5 interchangeable
Protection:	IP 51 (according to IEC 529)
Weight:	130 g

VIII Accessories

OPTO-RS232 connector, 2m cable, duplex connection for PC-AT (Dsub 9p)
External power supply (+5.0Vdc to +12.0 Vdc), binder connector 719 (3p)

IX Notes

- The lifting cap and contact point must be tightened by hand only.
- The dial face of the instrument can be opened correctly only by means of special manufacturer's tooling.
- The accuracy referred to in the specifications is guaranteed only when the dial gauge is attached to the clamping shaft.

X. Appendices


X.1 Changing the battery

Remove battery housing and insert new battery, ensuring correct polarity.

X.2 Resetting the instrument


Changing the battery will automatically reset the instrument. In the event of a problem, press [set] and [mode] simultaneously to clear the display.

X.3 Reference mode



X.4 Connecting the OPTO-RS cable

Enter the connector with opto-electronic components facing the user. There is no risk of damage in case of wrong insertion!



XI In case of problems

In the event of a malfunction (incorrect or frozen display, for example), reset the instrument.

XI.1 [mode] button inoperative

- Check if the [mode] button is locked ('C' symbol displayed when [mode] button is pressed). If so, disable this function by momentarily pressing [set] and [mode] simultaneously.

XI.2 The instrument won't switch off

- Remove the OPTO-RS connector, or disable the LED of the connector.

Modifications reserved