Release Notes

Tektronix

MTS400 Series MPEG Test Systems 071-1726-06

This document applies to software version 1.4.

www.tektronix.com



Copyright © Tektronix. All rights reserved. Licensed software products are owned by Tektronix or its subsidiaries or suppliers, and are protected by national copyright laws and international treaty provisions.

Tektronix products are covered by U.S. and foreign patents, issued and pending. Information in this publication supercedes that in all previously published material. Specifications and price change privileges reserved.

TEKTRONIX and TEK are registered trademarks of Tektronix, Inc.

Contacting Tektronix

Tektronix, Inc. 14200 SW Karl Braun Drive P.O. Box 500 Beaverton, OR 97077 USA

For product information, sales, service, and technical support:

- In North America, call 1-800-833-9200.
- Worldwide, visit www.tektronix.com to find contacts in your area.

Release Notes

These release notes provide the following information for version 1.4 of the MTS400 Series MPEG Test Systems:

- Document part numbers
- Features in this version
- Installation and operational problems or behaviors that you might encounter while using the instrument and explanations of how you can minimize or eliminate the impact on instrument operation

Introduction

Tektronix has redefined the MPEG analyzer with its ground-breaking MTS400 Series MPEG Test Systems and MTX100B portable analyzer options. Increased productivity is provided through many new technical features.

- The MTS430 is well suited for applications in research, development, and manufacturing test.
- The MTS400 is equally well suited for applications in broadcasting and network operations.
- The MTS4SA provides the MTS400 Series software applications for standalone use on PCs.
- The MTX100B with analysis options is ideal where portability is required.

A wide variety of applications simplify the complex tasks of creating transport streams for set top box design and manufacturing, as well as triggering and recording intermittent errors during live broadcasts.

The following information provides an overview of the MTS400 Series and MTX100B features:

- IP and RF Connectivity and Analysis Acquires transport streams from the network interface for analysis and recording of streams over IP (internet protocol), or RF broadcast interfaces (High Performance Network Interface and RF Interfaces available for MTS400 and 430 only).
- CaptureVu[™] Simplifies the task of triggering, recording, and analyzing events.
- **High Performance Engine** Measurement throughput up to 400 Mbps.

- Intuitive GUI A simple, yet powerful GUI (graphic user interface) provides real time analysis and recording, as well as deferred time analysis.
- Languages Windows Unicode fonts provide regional language support.
- Hardware/Interfaces 144 GB of storage, ASI up to 214 Mbps, fast Intel P4 processor, integrated XGA display, and dual Ethernet ports for LAN support and GigE transport analysis.
- Application Packages Analysis of Audio and Video Elementary Streams, Packetized Elementary Streams, Transport Streams, and Data Broadcasting Streams, as well as Multiplexing Audio, Video, and Data Broadcasting Streams.
- International Standards Support for MPEG-2, ATSC, DVB, and ISDB.

Related User Documentation

The following user documentation supports firmware version 1.4:

- MTS400 Series Getting Started Manual (English)
 Tektronix part number 020-2654-08 (includes user documentation CD-ROM)
- MTS400 Series Getting Started Manual (Japanese)
 Tektronix part number 020-2655-04
 (includes user documentation CD-ROM)
- *MTS400 Series User Manual* (English) Tektronix part number 071-1507-04
- MTS400 Series Specifications and Performance Verification Technical Reference (English)
 Tektronix part number 071-1724-03
- *MTS400 Series Programmer Manual* (English) Tektronix part number 071-1725-02

Enhancements

Buffer Analyzer

- T-SDT Buffer Analysis for H.264 video CODEC streams
- New Trace view has been added into the application that provides details of the buffer movements for in-depth analysis of the results.
 - Trace view entries may be synchronised with other views for enhanced diagnosis capability.
- Usability enhancements including a new program view added (looks similar to other applications), and view synchronization now includes the tracer tool.

Transport Stream Compliance Analyzer

- H.264 thumbnails:
 - Video thumbnail decode enhanced to display video streams encoded using the H.264 compression standard.
 - ES header information will also be displayed with the thumbnails.

MPEG Player

- Integration with MTS400 Series player user interface, provides ease of use for those familiar with existing applications, and enables playout over multiple interfaces (IP, ASI, SMPTE310M or DVB Parallel (SPI), one interface at a time).
- Support for Parametric playout:
 - Error Insertion Capability (Packet Drops, Checksum Errors, Sequence Errors and Jitter)
 - Burst mode (both timing and packet number based)
 - Manual error generation capabilities
- Advanced Mode with Protocol header customization capabilities for source and destination ports and addresses, with Advanced mode for setting MAC address, transport checksum, network checksum, and user editing of any packet header field parameters.
- Session replication to simultaneously encapsulate and play a TS over many IP sessions.

- Continuous looping with timing information and continuity updates to ensure seamless looping at the transport stream layer:
- Make seamless application can be used to ensure continuous looping at the elementary stream layer
- Single session playout up to 214 Mbps and multi session playout up to 300 Mbps.

Option Key

The hardware dongle security mechanism for MTS400 series software applications has been updated to a software option key system to aid Tektronix manufacturing. Hardware Parallel and USB dongles will be retained for use with the MTS series but will now be used only for their serial number as a unique ID. All permissions will be set by the software option key system.

Version 1.4 Software Features Availability

Table 1 shows the options required to access the new features.

Table 1: Software availability

Feature	MTS430	MTS400	MTS4SA
H.264 thumbnail display [TSCA]	Standard	Real time standard	Real time requires TSCR
		Deferred time requires TSCA	Deferred time requires TSCA
H.264 Buffer Analysis [Buffer Analyser]	Standard	Requires BA	Requires BA
H.264 Multiplexing [Multiplexer]	Standard	Requires MX	Requires MX
IP playout over host NIC [Player]	Standard	Requires IPE	n/a

GbE Interface - Option GBE (MTS400 and MTS430 only)

Video over IP interface - GbE electrical and optical High performance hardware interface card.

- High resolution H/W timestamp
 - Enables precise cross layer timing analysis
- MDI and statistical display of IP Packet Interarrival time (histograms)
- IP Session Capture and real or deferred time analysis down to the IP packet level
 - Uses industry standard PCAP file format for use with Wireshark (Ethereal)

- H/W packet filtering enables use with up to full line rate traffic on GbE link
- Can be used simultaneously with ASI or RF interface
- Wide range of interface options available with four SFP ports
 - 1000BaseT electrical
 - 1000BaseSX optical
 - 1000BaseLX optical
 - 1000BaseZX optical
 - Will not support 10/100BaseT electrical. Existing MTS400 platform has 10/100BaseT IP interconnection available through the host Network Interface Card (NIC).

Table 2: New video over IP feature availablility

Feature	MTS430	MTS400	MTS4SA
Capture files to disk in PCAP format [TSCA]	Requires GBE	Requires GBE	n/a
Open files for de- ferred time analysis of IP stream captures [TSCA]	Standard	Requires TSCA	Requires TSCA
MDI metrics [TSCA]	Real time requires GBE Deferred time stan- dard	Real time requires GBE Deferred time requires TSCA	Real time n/a Deferred time requires TSCA
IP Parameters and Statistics, IP layer checksums [TSCA]	Standard	Real time requires IPE or GBE Deferred time requires TSCA	Real time requires TSCR Deferred time re- quires TSCA
PIT Histograms and Instantaneous PIT Measurements (Min, max, mean) [TSCA]	Real time requires GBE Deferred time stan- dard	Real time requires GBE Deferred time re- quires TSCA	Real time n/a Deferred time requires TSCA

Table 3: Existing video over IP feature availablility

Feature	MTS430	MTS400	MTS4SA
PCR_OJ, PCR_FO, PCR_DR:	Real time requires GBE	Real time requires GBE	Real time not applica- ble
[TSCA]	Deferred time stan- dard	Deferred time requires TSCA	Deferred time requires TSCA
Average PIT Measurement [TSCA]	Standard	Real time requires IPE or GBE	Real time requires TSCR
		Deferred time requires TSCA	Deferred time requires TSCA

COFDM Interface

Option CF (MTS400 and MTS430 only)

- Supports DVB-T terrestrial broadcast standard
- MER measurements to 37 dB
- Support for hierarchical modulation
- Impulse response measurements for Single Frequency networks
- Constellation with innovative MER rings, EVM, SNR, and BER measurements
- Can be used simultaneously with IP interface
- Dual level warning and failure alarms plus RF drift tests for long term trend monitoring
- Trend graphs and alarms for detection of long term signal degradation

8VSB Interface

Option VS

- Supports 8VSB for ATSC terrestrial broadcast standard
- Leverage existing ATSC analysis capabilities such as Closed Caption consistency checking
- Symbol distribution display with innovative MER lines, EVM, SNR, and BER measurements
- Can be used simultaneously with IP interface
- Dual level warning and failure alarms plus RF drift tests for long term trend monitoring
- Trend graphs and alarms for detection of long term signal degradation

8PSK Interface

Option EP

- Supports QPSK for DVB-S and 8PSK for Broadcom Turbo code satellite broadcast standards
- Constellation with innovative MER rings, EVM, SNR, and BER measurements
- Can be used simultaneously with IP interface
- Dual level warning and failure alarms plus RF drift tests for long term trend monitoring
- Trend graphs and alarms for detection of long term signal degradation
- Will not support the DVB-S2 standard
- IPTV broadcast infrastructure

QAM (Annex B) Interface

Option QB2

- Supports ITU J.83 Annex B for US Cable broadcast standard
- Support for QAM 64 or 256 modes
- Both Level 1 and 2 interleaving
- Constellation with innovative MER rings, EVM, SNR, and BER measurements
- Can be used simultaneously with IP interface
- Dual level warning and failure alarms plus RF drift tests for long term trend monitoring
- Trend graphs and alarms for detection of long term signal degradation

Installation Issues (MTS400 and MTS430)

The following issues affect the installation of the MTS400 Series instruments and/or software:

Using the Correct Software Recovery Media

The serial number range assigned to the MTS400 Series instruments changed from B01xxxx to B02xxxx, and the software version changed from v1.0 to v1.1. The software number change was required only because of a hardware change; there were no changes to the software functionality. However, the software versions are not compatible between the two serial number ranges of the instrument. This issue does not affect the MTS400 Series standalone software.



CAUTION. To prevent software problems on your MTS400 Series instrument, use the v1.0 recovery media only on instruments with a serial number of B01xxxx, and use the v1.1 recovery media only on instruments with a serial number of B02xxxx.

For instruments with serial numbers B01xxxx, if you know or suspect that hardware changes have been made, look at the rear panel of the instrument for upgrade information labels. If a label states that the instrument has been upgraded to B02xxxx hardware, use the v1.1 recovery media or later to restore the software on that instrument.

Internal Error Dialog Box

After the files have been copied during installation, the instrument may report an internal error. Clicking OK will close the dialog box, and the installation will complete successfully.

Uninstalling the MTS400

When uninstalling the MTS400, a dialog box lists a number of DLLs that cannot be deleted from the registry. Clicking OK will close the dialog box, and the uninstall will complete successfully.

License Agreement Acceptance Follow-up

When the instrument is powered up for the first time, you must complete the Windows XP license and registration process, after which the instrument will automatically restart.

If the Found New Hardware Wizard opens after the system has restarted (see Figure 1), you must complete the wizard before the instrument will operate properly.

Perform the following steps to complete the Found New Hardware Wizard:

- 1. In the Found New Hardware Wizard window (see Figure 1), enable the **No, not this time** option.
- 2. Click Next to continue.




Figure 1: Found New Hardware Wizard page 1

- **3.** On the second page of the wizard (see Figure 2), verify that **Install the software automatically (Recommended)** is selected. No installation CD or floppy disk is required.
- 4. Click **Next** to continue.

The wizard will search for the required drivers, as shown in Figure 3. When the drivers are found, the Next button will be enabled.

5. Click **Next** to proceed.




Figure 2: Found New Hardware Wizard page 2




Figure 3: Wizard searching for drivers

- **6.** When the wizard dialog box shown in Figure 4 is displayed, click **Finish**.
- 7. Select **Restart** from the Start menu to reboot the MTS400 Series system. The Windows XP registration and hardware setup are complete.




Figure 4: Completing the wizard

Restoring the MTS400 and MTS430

The MTS400 Series System restore process is described in the MTS400 Series Getting Started Manual (071-1505-05).

If, after the system is restored, you are unable to import the SCSI drives, perform the following steps:

- 1. Copy the file "SCSIKeyDel.reg" from the restore DVD to C:\.
- **2.** Double-click the file name, and when prompted to add information to the registry, press Yes.
- 3. When the process has successfully completed, press OK.
- **4.** Reboot the instrument.
- **5.** Use the process to described in the *MTS400 Series Getting Started Manual* to Import the SCSI drives.

Installation Issues (MTS4SA)

The following issue affects the installation of the MTS4SA software:

Windows NT Installation of the MTS4SA is no longer supported on Windows NT.

Multiplexer If the latest Multiplexer software is installed from the MTS4SA application

CD-ROM, versions of the Multiplexer previously installed and prior to version

2.0 will no longer work.

MPEG Player Issues (MTS400 and MTS430)

Administrator Rights for

Recording

The MPEG Player application allows you to record to RAM. You need local

administrator rights on the machine to make a recording.

MPEG Player and TSCA Application Interaction If the MPEG Player application is playing a stream near its maximum bit rate limit (214 Mbps simplex or 107 Mbps duplex), and you start the TSCA application, the instrument may display the message "Mega FIFO empty error" and the player application may stop. Once the TSCA has started, you can start playing the stream again.

A workaround is to ensure that the TSCA is started before playing a stream at high bit rates.

Duplex Support in IP Mode

The MPEGPlayer does not support duplex mode (via any interface) when in IP

Playout mode.

Maximum Playout Bit Rate

The maximum playout bit rate supported by the player is determined by the NIC

interface setting and Windows Network Component settings.

To reach optimal bit rates, the NIC configurations should be optimized and the

Windows ICS service should be turned off.

IP Packet Drops Do Not Affect RTP Sequence Numbers If the Player is configured to playout with packet drops in RTP mode, the sequence numbers do not reflect the dropped packets. As a result of this, although the packets are dropped, and TS continuity count errors will be detected, the RTP layers tests do not detect the dropped packets.

DVB SPI In Port Ignores the D Valid Setting

When recording using the SPI port marked "DVB SPI In", the setting in the "Ignore Dvalid" check box under the Record > Target dialog box is ignored, and all data will be recorded with Dvalid active and inactive.

The port marked "DVB SPI Out" is capable of both input and output, and this setting is applied correctly. However, recordings made using this port will not be timestamped.

Ensure that File Path is set before Triggered Recording

Before performing a triggered recording, ensure that the correct path is set using the File > Save... dialog box. If the path is not set, a File Not Found error will be generated when the recording starts.

Transport Stream Compliance Analyzer Issues (MTS400, MTS430, MTS4SA and MTX100B)

Program Tree Does Not Always Update Correctly

After deferred analysis has completed, occasionally the program tree might not display the program names even though they appear in the Summary View. If you switch from the Program tab to another tab, and then back again, the program names will appear.

Administrator Rights for IP Analysis

To perform real-time IP analysis using an NIC (network interface card), you must have local administrator rights.

Lost Packets During Recording on IP Analysis on Low Specification PCs

On some low-specification PCs (with old network cards and slower hardware), if you record a stream that is being analyzed over IP using an NIC, packets might be lost. This is because of the hardware dropping Ethernet frames.

Processing may Become Strained with Script ValidationEenabled in Real Time Mode

If you enable Script Validation for Real Time Analysis, the TSCA might become strained. If this occurs, and script validation is required, disable the feature, make a recording in real time, and then perform a deferred analysis on the recording with the feature enabled.

RTP Analysis - TS Availability Error Reported for 204 byte Packet Streams

When analyzing a 204 byte packet stream over RTP, the TS Availability test will activate at the start of the stream.

Analyzing RTP Streams Using UDP causes the TSCA to Become Overwhelmed

When you select an IP session to analyze from the "Browse for UDP flow..." dialog box, the TSCA attempts to identify whether it is RTP or UDP, and automatically updates the "Use RTP" check box in the Real-time Analysis Open Transport Stream dialog box. If you manually clear the "Use RTP" and analyze a known RTP stream, this can cause the TSCA to become overwhelmed and data to be lost.

Streams Transmitted Over UDP May be Recognized as RTP

It has been seen very infrequently that UDP sessions are detected as RTP in the "Browse for UDP flow..." dialog box. This is due to specific byte patterns appearing in the transport stream. If this occurs, clear the "Use RTP" check box manually.

IP Packet Interarrival Timing

The TSCA uses WinPcap for IP input using an NIC. The timing of WinPcap is affected by the type of processor, hyper-threading and SMP. See the WinPcap change log (http://www.winpcap.org/misc/changelog.htm) for more details.

IP Packet timing measurements using an NIC are based on timestamps averaged over a 40 ms period. You can define an integration period for the graphical display of average Packet Inter-Arrival Time. The default integration period is 1 second.

Ethernet Packet Timestamp Smoothing

Under certain conditions of heavy network traffic, it has been noted that timestamping of Ethernet packets can be delayed within the network interface kernel mode driver when using an NIC.

To overcome this issue, an Ethernet packet arrival smoothing algorithm has been implemented in this release to ensure that erroneous jitter does not affect the transport stream timing measurements. This algorithm results in the smoothing of the PCR Arrival Interval measurement and the associated graphs when using the IP interface through an NIC.

MDI Media Loss Rate Calculation

The TSCA provides an RTP Jitter Buffer to reorder out-of-order packets. This can be set within a range of 0 ms and 5000 ms. If the value is set to 0 ms, all out-of-order packets will contribute to the MDI Media Loss Rate calculation. When the value is greater than 0 ms, any packets reordered will not be taken into account. This allows the user to determine the effect on MDI MLR of the Jitter Buffer.

Note that a packet is considered out of order if the sequence number received is less than or equal to the previous sequence number received.

RTP Dropped Packet Test

The RTP Dropped Packet tests checks the RTP sequence number of packets leaving the Jitter buffer after they have been reordered. The test will fail if the difference in the RTP sequence number between two subsequent packets is greater than one.

H.264 Thumbnails with Recovery Points

The TSCA thumbnail decoder does not support H.264 Recovery Points.

Concurrent Analysis Behaviour

It is possible to have multiple instances of the TSCA running at the same time. However, the following behaviour should be noted:

- Triggers are saved on restarting analysis. The effect of setting a trigger in an instance and restarting analysis will be to cause the trigger to be inherited inother instances when analysis is restarted in those instances.
- When a parameter is modified in one instance, it will be inherited in other instances when analysis is restarted in those instances.

Connection to VLAN Sessions Using a NIC

The VLAN tag will not appear in the TSCA analysis because, by default, Intel adapters strip the VLAN tag before passing IP up the stack.

If you need to analyse VLAN sessions, you should update to the latest Intel driver for the NIC, and add a DWORD a registry entry "MonitorModeEnabled" to a value of 1 within:

 $\label{local_MACHINE} HKEY_LOCAL_MACHINE\SYSTEM\controlSet001\control\class\{4D36E972-E325-11CE-BFC1-08002BE10318\}\control\color=100002BE10318\}\control\color=100002BE10318\}\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control\color=100002BE10318\control$

Symbol Distribution Graph not listed in the Add Graphs menu for 8VSB

When using an 8VSB interface card for analysis, the "Symbol Distribution" graph entry is missing from the Add Graphs menu on the Instantaneous Graphs tab panel. You can display the Symbol Distribution graph by selecting the Add All Graphs option.

Transport Stream Compliance Analyzer Issues (MTX100B Only)

Duplex Operation Not Supported

The TSCA can not be used to analyze streams using ASI, SMPTE, or DVB Parallel inputs while the MPEG Player is running.

Streams Not Detected when Time Stamping is Switched Off

Transport streams are not detected if time stamping is disabled using the Open dialog box check box.

Transport Stream Compliance Analyzer Issues (GBE Option Only)

Packets with IP Checksum Errors are Discarded

Packets with IP checksum errors will be discarded by the interface card. The user will be notified that the checksum errors have occurred, but they will not be passed on for analysis. This will result in dropped packet and continuity count errors.

Interface Card Startup Time

The Interface Card takes around 90 seconds to boot up after the user logs in. No sessions will be visible during this time.

Cheetah Connection Appears in Network Connections

A connection called "Cheetah Connection" will appear in the Network Connections window. Users must not change any of the settings for this connection, as any modifications will prevent the interface card from operating. Note that the IP address specified within the Internet Protocol (TCP/IP) settings is not the IP address of the ports on the card. This is set through the TSCA user interface on a port by port basis.

Maximum Aggregate Bit Rates across all Four Ports Restricted to 3.6 Gbps

Although a user may be analysing a session through a single port, all four ports are still active. The maximum total bit rate that the card can handle through all ports is 3.6 Gbps.

Laser Active on all Optical SFP Ports during Analysis

It should be noted that although only one port can be used for analysis, all ports are active on the card. Therefore, if an optical SFP is plugged into one of the ports not being used for analysis, the laser will be active.

Only Select Active Mode on Ports with Live Connections

Active mode, used when ARP and IGMP support is required, should only be selected on ports with live connections. If active mode is selected for a port without a live connection, the card will attempt to issue live messages, and will block until they can be delivered. This will also prevent ARP and IGMP messages being transmitted on other ports. If you suspect that you have selected a port in active mode on a connection that is not live, re-starting the unit will ensure that ARP and IGMP messages can be transmitted on the live connections.

ES Analyzer Issues (MTS400, MTS430, MTS4SA and MTX100B)

Only Partially Decodes 4:2:2 Profile@HighLevel File 4:2:2 Profile@HighLevel files are only partially supported by the ES Analyzer. It fails to correctly recognize the 0x82 Profile/Level type.

Presentation Order is Incorrect Sometimes the Presentation Order chart does not present field encoded material in the correct order.

Multiplexer Issues (MTS400, MTS430, MTS4SA and MTX100B)

- Elementary stream within other containers, such as *.h264, *.MP4, Fluxmux and others, are **not** directly supported.
- Incomplete access units (for the last access unit, will be dropped during multiplexing.
- On looping small files, the PAT and PMT table stop time resets to the start time. The repetition interval then becomes zero because there is only one occurrence in each of these table sections.
- The multiplexer does not consider the start time of the stream when adjusting the PTS/DTS values of the elementry stream. A workaround for this is to enter a DTS offset for the PID equal to its lag against the PCR PID.
- Altering some stream properties (like duration) does not affect other stream properties. For Example, Other PIDs do not automatically adjust to new transport stream durations automatically. However, the stream properties can be set manually.

H.264 Specific Issues

- Frame reordering is not supported in this release of the multiplexer. PTSs in the PES header are calculated without reordering.
- On looping H.264 elementary streams, there may be Annex C violations reported on nominal removal times at loop points.
- Bit rate auto-detection of non-SEI interlaced video is not supported.
- Frame rates are fixed at 29.97 fps.

Carousel Analyzer Issues (MTS400, MTS430, MTS4SA and MTX100B)

Spikes on Bite Rate Graphs for Long Streams

The Carousel Analyser bit rate graphs for long streams may show spikes.

Security Patches (MTS400, MTS430 and MTS4SA)

The software has been verified with the following Microsoft Security Patches:

Microsoft Windows 2000 (Service Pack 4)

No patches.

Microsoft Windows XP Pro (Service Pack 2)

KB887742	KB899588	KB888113
KB905915	KB899591	KB891781
KB896424	KB883939	KB888302
KB900725	KB890046	KB885250
KB901017	KB896428	KB890175
KB905749	KB896358	KB873339
KB905414	KB896422	KB885836
KB904706	KB893086	KB885835
KB902400	KB893066	KB885884
KB899589	KB890859	KB834707
KB899587	KB890923	KB870669
KB896727	KB873333	KB893803
KB893756	KB867282	Q819696
KB896423	KB890047	KB912945
KB918118	KB927802	KB929969
KB924667	KB928090	KB931836
KB926436	KB928255	Nero 7 Essentials OEM STE1
KB927779	KB928843	

■ End of document