

Reinstall Brake Light Switch

Classification Campaign Bulletin Section/Group 33 - Brakes Country/Region All

Year 2018, 2019 Model Model 3 Version All

Bulletin Classification: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN range listed. These instructions assume knowledge of motor vehicle and high voltage electrical component repairs, and should only be executed by trained professionals. Tesla assumes no liability for injury or property damage due to a failure to properly follow these instructions or repairs attempted by unqualified individuals.

Condition

Certain Model 3 vehicles might have an incorrectly positioned brake light switch that might cause continuous brake light illumination. This situation prevents the vehicle from entering sleep state and increases energy consumption.

Correction

Remove and reinstall the brake light switch to the correct position.

Correction Description	Correction	Time
SB-19-33-002 Not Applicable	S011933002	0.00
Reinstall Brake Light Switch	S021933002	0.35

Procedure

- Remove and reinstall the same brake light switch (refer to Service Manual procedure 33252002).
- 2. Verify the brake light switch operation. If the brake light still illuminates continuously or intermittently, refer to Toolbox Knowledgebase for further troubleshooting.

Affected VIN(s) Affected Model 3 vehicles built between approximately November 12, 2018 and March 8, 2019.

NOTE: This is a simplified summary of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

For feedback on the accuracy of this document, email ServiceBulletinFeedback@tesla.com.