| | esla, Inc. ervice Bulletin | Inspect Outer Rear Quarter Panel Body | | |
|-------------------|-------------------------------|---------------------------------------|----------------|--|
| SB-21-11-001 | | Joint Sealant For Trunk Water Ingress | | |
| January 22, 2021 | | | | |
| Classification | | Section/Group | Mobile Service | |
| Campaign Bulletin | | 11 - Closures | Cannot Perform | |
| Model Year | Model | Country/Region | Version | |
| 2020 | Model 3 | All | All | |

Campaign Bulletin: This campaign bulletin addresses a known non-safety-related condition and provides recommended technical diagnosis and repair procedures. Apply this procedure to all vehicles in the affected VIN list.

Condition

On some Model 3 vehicles, the body joint sealant on the outer rear quarter panels are missing or were not properly applied, causing water ingress to the trunk compartment.

Correction

Inspect the vehicle for symptoms related to the condition. If symptoms are present, apply new sealant to the affected area(s).

| Correction Description | Correction | Time |
|--|------------|------|
| SB-21-11-001 Not Applicable | S012111001 | 0.00 |
| Inspect Outer Rear Quarter Panel Body Joint Sealant; No Repair Needed | S022111001 | 0.05 |
| Inspect Outer Rear Quarter Panel Body Joint Sealant; Apply Sealant To LH Side Only (No Repair Needed On RH Side) | S032111001 | 0.15 |
| Inspect Outer Rear Quarter Panel Body Joint Sealant; Apply Sealant To RH Side Only (No Repair Needed On LH Side) | S042111001 | 0.15 |
| Inspect Outer Rear Quarter Panel Body Joint Sealant; Apply Sealant To Both LH And RH Sides | S052111001 | 0.20 |



| | Part Number | Description | Quantity | |
|--|--|---|-----------|--|
| Parts Required (If Necessary) | | Use one of the following: | | |
| | 1460201-00-A | ADHESIVE, LOCTITE 5910, SI | As Needed | |
| | 1589861-00-A | LOCTITE 5900, GEN 3 CHARGER SEALANT 190 ml | As Needed | |
| | 1031090-02-A | 3M Drip-Chek Sealer | As Needed | |
| | | * Permatex Clear RTV Sealant | As Needed | |
| | | * LOCTITE SI 595 CL (Clear RTV Silicone Adhesive Sealant) | As Needed | |
| * Source using Procurement tool or locally | | | | |
| | NOTE: One tube of sealant can typically be used for multiple vehicles. | | | |
| | If none of the sealants listed above are available, source a sealant using the following criteria: | | | |
| | • Non | Non-corrosive, water resistant, and 120% to 140% elongation at rupture/break | | |
| | Pror | Promotes adhesion for a variety of surfaces and bonds to dissimilar materials | | |
| | Mate | Material: RTV, silicone, or polyurethane | | |
| | • Colo | or: Clear (ideal for precise and neat application) | | |
| | • Can | withstand a temperature range of at least -50°F to 150°F / -45°C | to 65°C | |
| | | numbers were current at the time of publication. Use the revisions listed or later, unless pecified in the Parts Catalog. | | |
| Shop Supplies | Blow Gun | | | |

Shop Supplies Blow Gun Caulk And Adhesive Gun Bone Tool

Procedure

- 1. Remove the trunk garnish (refer to Service Manual procedure 15111102).
- 2. Remove the trunk sill trim (refer to Service Manual procedure <u>15244802</u>).
- 3. Move the LH quarter glass seal aside (Figure 1), and then insert a trim tool between the body and quarter glass for access (Figure 2).



Figure 1



Figure 2

TESLA

4. Visually inspect the area between the body panels under the seal lip (Figure 3).



Figure 3

- If there is no visible gap, continue to the next step.
- If there is a visible gap, skip to step 6.
- 5. Apply a small amount of soapy water to the body joint sealant area, and then blow the area with shop air (Figures 4 and 5).

WARNING: To reduce the risk of personal injury, use appropriate eye protection while performing this step.



Figure 4



Figure 5

- If a leak is detected, continue to the next step.
- If no leak is detected, repeat from step 3 for the RH side of the vehicle.
- If no leak is detected on the LH and RH sides of the vehicle, skip to step 11.



6. Prepare a caulking gun and sealant.

NOTE: The applicator tip should have an opening 2 mm wide (Figure 6).



Figure 6

7. Using the lowest speed setting on the caulking gun, apply sealant to the gap between the body panels (Figure 7).




Figure 7

TESLA

8. Flatten the bead of the sealant (Figure 8) and remove any excess sealant from the surrounding area.



Figure 8

- 9. Repeat step 3 through step 8 for the RH side of the vehicle.
- 10. Allow the sealant to dry for at least 30 minutes.

NOTE: Refer to the body sealant label for work time and full cure time. Chemicals may vary by region.

- 11. Install the trunk sill trim (refer to Service Manual procedure 15245302).
- 12. Install the trunk garnish (refer to Service Manual procedure 15111102).