

CX1000 Installation and **Connection Guide**

IM 04L31A01-73E 2nd Edition

YOKOGAWA

Disk No. RE35 nd Edition: July 2005 (YK) All Right Reserved, Copyright © 2001 okogawa Electric Corporation

Yokogawa Electric Corporation

Thank you for purchasing the CX1000.

This manual contains simple explanations about how to install and connect the CX1000. For more information about the procedures described herein, safety precautions, and the CX1000 functions and operation, please refer to the PDF manual found on the provided CD-ROM.

Installation Procedure


1. Cut the instrument panel according to the diagram below.

Unit: mm

For the panel cut dimensions when installing multiple units closely together, see the CX1000 User's Manual IM 04L31A01-03E found on the provided CD-ROM.


Panel Cut Diagram

When installing



- 2. Insert the CX1000 into the front of the panel.
- 3. Using the mounting brackets that came with the package, attach the CX1000 to the panel as shown in the following figure.

First, attach the two mounting brackets and temporarily fasten the attachment screws. Next, fix the CX1000 in place by tightening the attachment screws with the appropriate torque (0.7 to 0.9 N-m.). As you fasten the screws, press the mounting bracket against the case so that they are in contact with each other.



Mounting bracket (Part No.: B9900BX)

Attachment position is either top and bottom or left and right

For details about the CX1000 external dimensions, installation environment. and more, please refer to the CX1000 User's Manual (IM 04L31A01-01E).


Connection Types and Procedures

There are various terminals and connectors on the rear panel of the CX1000. Connecting them to peripheral devices allows you to perform control and measurement operations. Below are the names of each connector and terminal, as well as connection procedures.

Connecting the Ethernet Interface


When only Connecting to a Hub


Connect the CX1000 and the PC through a HUB as shown in the following figure.



When Connecting to a Preexisting Network

The following figure illustrates an example in which the CX1000 and a PC are connected to the network. When connecting the CX1000 or the PC to a preexisting network items such as the transfer rate and connector type must match. For details, consult your system or network administrator.





Connecting Input/Output Connectors

When connecting various input/output connectors for control or measurement, proceed as described below.

Connect the crimp connectors (for 4-mm screws) to the terminal strip.

- 1. Turn off the CX1000 and remove the terminal cover.
- 2. Wire the signal wires to the terminals. Attach the terminal cover and secure it with screws.

Connecting the Serial Interface

Measurement alarm output

(/A6 option)

Measurement alarm output

+ FAIL/memory end output

(/A4F option)

- RS-232 (When Connecting to a Computer or Other Such Devices)
 - Verify that the CX1000 has an RS-232 connector, and then connect a serial cable to it. Connect the other end of the serial cable to the other device.

12345	Pin No.	Signal Name	Signal Meaning
	2	RD (Received Data)	Received data from the
	3	SD (Send Data)	Send data to the connect
	5	SG (Signal Ground)	Signal ground.
6789	7	RS (Request to Send)	Handshaking signal use
	8	CS (Clear to Send)	Handshaking signal use
	* Pins 1,	4, 6, and 9 are not used	1.

RS-422/485 (When Connecting to a PLC, Temperature Controller or Other Such Devices)

Verify that the CX1000 has an RS-422/485 connector, and then connect the crimp connectors (for 4-mm screws) to the terminal strip as illustrated on the right. Do not expose more than 5 cm of the cable surface from the shield.

+ remote input/output


(/A6R option)


Measurement alarm

output + FAIL/memory


end output + remote

input/output (/A4FR option





ed when sending data to the connected device. Input signal



A When using electrical wiring, be certain to follow the safety

- 1. Turn OFF the CX1000 and open the cover (transparent) for the
- 2. Connect the power cord and the protective ground cord to the power

3. Close the cover (transparent) for the power supply wires and secure

For the power supply specifications and connection method of the 24VDC/AC power supply option, please refer to the CX1000 User's Manual.

Arrangement of the Control Input/Output Terminals


Input/Output Assignments of the Analog Control Input **Terminal Block**

There are five input terminals. The PV inputs (PV) and remote inputs (RSP) are assigned as shown in the following figure. The following figure denotes the three terminals (/b, +/A, -/B) of a single column using a single cell

							Measu	iromon	t innut t	terminals
[Control mode setting]	LO	OP2		LOOP1]	measu	ar cinicin	Input	criminais
[eenner mede coung]	2	1	3	2	1					
During single-loop control →	(RSP)	PV		(RSP)	PV					
During cascade control -	·	PV		(RSP)	PV					
During loop control with \rightarrow	PV2	PV1	(RSP)	PV2	PV1					
PV switching			PV inpu na proc				ed term	inal		


Terminal Arrangements of the Control Output Terminal Block Each block has a control output containing two loops of current output,

voltage pulse output, and relay contact output terminals, six contact input, two relay contact output, and four transistor output terminals. The following figure shows their arrangement.




Arrangement of the Measurement Input/Output Terminals

Terminal Arrangements of the Measurement Input Terminal Block Six measurement input terminals are available on each terminal block as shown in the following figure.



Terminal Arrangements of the Measurement Alarm Option **Terminal Block**

The measurement alarm option terminal block is the terminal block that you specified as an option to the CX1006 at the time of purchase. The following four types are available.




Label on the Terminal Cover

A label indicating the terminal arrangement is affixed to the front and back of the terminal cover of each terminal block.


Label on the Front of the Terminal Cover

The terminal numbers used to check the connection (not the numbers used in the settings) are written on the label on the front of the terminal cover (see the following figure).


For the 6 Loop Analog Control Input Terminal Block



For the Control Expansion DIO Terminal Block



The terminal numbers are unique three-digit numbers. The highest digit indicates the arrangement position of the terminal block shown in the following figure; the lower two digits indicate the terminal position within the terminal block (top right terminal is assigned "01"; bottom left terminal is assigned "36"). The terminals that cannot be used are indicated as "□".



Label on the Back Cover of the Terminal Cover


Indicates the type of input/output signal for each connector. Below is an illustration of a control/measurement input terminal block.

Terminal symbol

	L00 2	OP 2 1	3	LOOP 1 2	1	6		4	3	2	1
SNGL	(RSP)	PV		(RSP)	PV		- <u>-</u>	+	+	+	- <u>-</u> b +.]
CAS		PV		(RSP)	PV						
PVSW	PV2	PV1	(RSP)	PV2	PV1	ЦВ	В	В	В	В	В


Input Wiring

Measurement Input Wiring





Contact Input (DIGITAL IN/REMOTE) Wiring

Measurement Alarm Option Terminal Block Remote Input (REMOTE)



Control Output Terminal Block (DIGITAL IN)






Relay Contact Input/Transistor Input


Input signal: no-voltage contact, open collector Input condition: ON voltage, under 0.5 V (30 mADC); OFF voltage, leakage current under 0.25 mA

Input format: photocoupler isolation (common)

Withstand voltage: 500 VDC, 1 min (between input terminal and earth)







Transistor output of the control output terminal block Connection example

Output Wiring

Control Output (LOOP1 and 2) Wiring

$\begin{array}{c c} \cdot & \text{Current output} \\ & & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & & \\ & & & & \\ & & & \\$							
Relay contact output							
NO 250 VAC, 3 A or 30 VDC, 3 A (resistive load) (when set to energized)							
Current Output							
Output signal: 4 to 20 mADC or 0 to 20 mADC							
Besistive load: 600Ω or less							
Voltage Pulse Output							
Output signal: ON voltage=12 VDC							
Besistive load: 600Ω or more							
Relay Contact Output							
Output signal: NC, NO, COM							
Contact rating: 250 VAC (50/60 Hz)/3 A or 30 VDC/3 A (resistive load)							
Contact Output (DIGITAL OUT) Wiring							
Relay contact output of the control output terminal block							
250 VAC, 1 A or C→ 30 VDC, 1 A (resistive load)							

	5	5	3	tor a tra	
ŗ			4 24 VDC/50 mA	3 to 6	V+ ≷ Pull-up resistor
Ļ	-				——O -

Relay Output

Output form: relay contact

Contact rating: 250 VAC (50/60 Hz)/1 A or 30 VDC/1 A (resistive load) **Transistor Output**

Output method: open collector output

Contact rating: 24 VDC/50 mA