# MALFUNCTION

### LAUNCHING

BRIDGE FAILS TO LIFT OFF THE BRIDGE SEAT BRIDGE FAILS TO SCISSOR OPEN BRIDGE FAILS TO LOWER FROM THE VERTICAL BRIDGE FALLS DURING LAUNCHING BRIDGE WILL NOT RELEASE FROM THE TONGUE

## RETRIEVING

TONGUE WILL NOT ENGAGE THE BRIDGE
BRIDGE FAILS TO LIFT
BRIDGE FAILS TO RETRACT FROM THE VERTICAL
BRIDGE DROPS ON THE LAUNCHER
FOLDED BRIDGE WILL NOT ENGAGE THE BRIDGE SEAT

## **GENERAL**

HYDRAULIC SYSTEM FAILS

# AVLB HYDRAULIC TROUBLE SHOOTING GUIDE

GTA 05-04-038

HEADQUARTERS, DEPARTMENT OF THE ARMY

OCTOBER 1988

#### Instructions

- Slide the insert until the arrow points to the appropriate malfunction.
- 2. Turn the GTA to the reverse side.
- Starting with probable cause 1, follow the numerical sequence until the cause of the malfunction is determined.

# PROBABLE CAUSE OF MALFUNCTION

DISTRIBUTION: US Army Training and Audiovisual Support Centers (TASCs)

BRIDGE AND LAUNCHER NOT ON THE SAME PLANE HYDRAULIC PUMP NOT ENGAGED

Approved for public release; distribution is unlimited.

OIL PRESSURE LOW CLUTCH SLIPS

POWER TAKE-OFF SYSTEM DEFECTIVE TIE-DOWN CHAINS NOT RELEASED OVERHEAD CYLINDER FAILS TO OPERATE

SCISSORS CYLINDER FAILS TO OPERATE
TONGUE CYLINDER FAILS TO OPERATE


TONGUE HYDRAULIC QUICK DISCONNECTS NOT ENGAGED TONGUE CYLINDER EXTENDS TOO RAPIDLY

LOCKING CYLINDER NOT RETRACTED
EJECTION CYLINDER NOT OPERATING/EXTENDED
OVERHEAD CYLINDER RETRACTS TOO RAPIDLY
TONGUE CYLINDER NOT FULLY RETRACTED

NO HYDRAULIC PRESSURE OIL IN RESERVOIR LOW

## MALFUNCTION

HEADQUARTERS, DEPARTMENT OF THE ARMY GTA 5-4-38 (INSERT)



# PROBABLE CAUSE OF MALFUNCTION

					1					
1		1		1		1	1		2	1
3	3	3	2	3		3	3			
4	4	4	3	6		4	4	2		4 5
6	5	5	4	7		5	5	3		5
5 7										
7							6		3	
	6									
		6				6				
	1									
			5							
				4	2					
				5	3					
								4		
									1	
8								5		
2	2	2	1	2		2	2	1		2