

**TM 55-6115-498-40**

**DEPARTMENT OF THE ARMY TECHNICAL MANUAL**

---

**GS MAINTENANCE MANUAL**

**DIRECT CURRENT GENERATOR**

**PART NO. 30B37-37-A**

**(BENDIX)**

---

**HEADQUARTERS, DEPARTMENT OF THE ARMY, WASHINGTON, D. C.**

**AUGUST 1969**

## **WARNING**

### **PRECAUTIONARY DATA**

Personnel performing instructions involving operations, procedures, and practices which are included in this technical manual shall observe the following instructions. Disregard of these warnings and precautionary information can cause serious injury, death, or an aborted mission.

### **CLEANING SOLVENT**

Use solvent (in a well-ventilated area. Avoid inhaling solvent fumes. Do not allow solvent to contact skin as burns may occur.

CHANGE }  
 No. 1 }

HEADQUARTERS  
 DEPARTMENT OF THE ARMY  
 WASHINGTON, D. C., 11 October 1975

GS Maintenance Manual

DIRECT CURRENT GENERATOR  
 PART NO. 30B37-37-A (BENDIX)

TM 55-6115-498-40, 8 August 1969, is changed as follows:

Page 2-2. Add the following to table 2-3 as item 18: Solder QQS571SN5WRAP3.

Page 3-10. The following is added to paragraph 3-4c(7):

Armatures with balancing rings installed, balance statically and dynamically to .020 in. ounces, by applying solder (Item 18, table 2-3), to inside of balancing rings. Solder may not extend beyond lips of rings.

By Order of the Secretary of the Army:

Official:

**PAUL T. SMITH**

*Major General, United States Army  
 The Adjutant General*

**FRED C. WEYAND**

*General, United States Army  
 Chief of Staff*

DISTRIBUTION:

To be distributed in accordance with DA Form 12-31, Direct and General Support Maintenance Requirements for UH-1B, UH-1C/M, UH-1D/H aircraft.



**GS Maintenance Manual**  
**DIRECT CURRENT GENERATOR**  
**PART NO. 30B37-37-A**  
**(BENDIX)**

**TABLE OF CONTENTS**

	Page
LIST OF ILLUSTRATIONS -----	ii
LIST OF TABLES -----	ii
Section I. INTRODUCTION -----	1-1
1-1. General Information -----	1-1
1-2. Purpose of Equipment -----	1-1
1-3. Equipment Records -----	1-1
1-4. Description -----	1-1
1-5. Leading Particulars -----	1-1
1-6. Painting Requirements -----	1-1
1-7. 1-7. Preservation, Packing and Marking Requirements -----	1-2
Section II. TEST EQUIPMENT, SPECIAL TOOLS, AND MATERIALS -----	2-1
2-1. Test Equipment -----	2-1
2-2. Special Tools -----	2-1
2-3. Consumable Materials -----	2-1
Section III. GENERAL SUPPORT MAINTENANCE -----	
3-1. Disassembly -----	3-1
3-2. Inspection Requirements -----	3-5
3-3. Cleaning -----	3-8
3-4. Repairer or Replacement -----	3-8
3-5. Lubrication -----	3-11
3-6. Reassembly -----	3-11
Section IV. FINAL TEST PROCEDURES -----	4-1
4-1. General -----	4-1
4-2. Flashing the Field -----	4-2
4-3. Brush Seating -----	4-2
4-4. Final Test -----	4-2
Section V. DIFFERENCE DATA SHEETS -----	5-1
VI. FEDERAL MANUFACTURERS' CODES -----	6-1
Appendix A. REFERENCES -----	A-1

## LIST OF ILLUSTRATIONS

Number	Title	Page
1-1.	Three-quarter View, DC Generator Part No. 30B37-37A -----	1-2
1-2.	Preservation, Packaging, Packing and Marking Requirements-----	1-3
3-1.	DC Generator, Exploded View -----	3-2
3-2.	End Bell Assembly, Exploded View -----	3-4
3-3.	Generator Stator, Exploded View-----	3-6
3-4.	Fabrication of Diamond-tipped Cutting Tool -----	3-9
3-5.	Mounting of Commutator Cutting Tool -----	3-9
3-6.	Fabrication of Carboloy-tipped Cutting Tool -----	3-10
3-7.	DC Generator, Schematic Diagram -----	3-11
4-1.	Typical Brush Seating -----	4-2

## LIST OF TABLES

Number	Title	Page
1-1.	Leading Particulars-----	1-1
1-2.	Painting Requirements -----	1-1
2-1.	Test Equipment Required -----	2-1
2-2.	Special Tools Required -----	2-1
2-3.	Consumable Materials Required -----	2-1
3-1.	Detail Inspection Requirements -----	3-5
3-2.	Fits and Clearances -----	3-8
4-1.	Troubleshooting -----	4-1
4-2.	Heating Test Readings -----	4-3
4-3.	Commutator Test Readings -----	4-3

## SECTION I

## INTRODUCTION

## 1-1. GENERAL INFORMATION.

a. This technical manual comprises overhaul instruction for DC Generator, Part No. 30B37-37A (figure 1-1). This equipment is manufactured by The Bendix Corporation, Electric power Division (Federal Code 83298), Eatontown, New Jersey 07724. Sections I through IV of this technical manual contain instructions for the basic type.

b. Report of errors, missions, and recommendations for improving this publication by the individual user is encouraged. Reports should be submitted on DA Form 2028 (Recommended Changes DA Publications) and forwarded directly to: Commanding General, U. S. Army Aviation Systems Command, ATTN: AMSAV-R-M, P. O. Box 209, St. Louis, Missouri 63166.

## 1-2. PURPOSE OF EQUIPMENT.

The dc generator is used to generate the electrical power required for 28-volt aircraft electrical systems.

## 1-3 EQUIPMENT RECORDS.

The Army equipment record system and procedures established in TM 38-750 apply to this equipment. The applicable forms as required by TM 38-750 shall be used.

## 1-4. DESCRIPTION.

The dc generator is a brush-type rotating machine capable of delivering 30 volts dc at a rated current of 300 amperes, when driven at its rated

speed (5000 rpm). The unit is self-cooled by means of an integral fan rotating with output shaft. A terminal board is mounted on the housing to facilitate external connections. Slotted mounting holdes are provided for ease of installation on the engine.

## 1-5. LEADING PARTICULARS.

Refer to table 1-1 for leading particulars of the dc generator.

Table 1-1. Leading Particulars

ITEM	CHARACTERISTICS
Rated Voltage	80 V
Rated Current	300 amp
Rated Speed	5000 rpm
Minimum Speed for Regulation	5000 rpm
Maximum Speed for Regulation	10,000 rpm
Cooling Air	40°C (max)
Weight	47 lb (max)
Diameter (Housing)	6-9/16 in.
Length (Housing)	11-54/64 in.
Output Spline	16 teeth
Mounting Bolt Circle Diameter	5.000 in.
No. of Mounting Slots	6
Rotation (Viewing Drive End)	Counterclockwise

## 1-6 PAINTING REQUIREMENTS


Repainting or retouching surfaces, if required shall be done in accordance with table 1-2.

Table 1-2. Painting Requirements

Item name	Fig. No.	Index No.	Paint type and specification	Method of application	No. of coats	Notes
END Bell Cover Assembly	3-1	12	MIL-P-15328, Primer TT-E-485	Wash	1	Apply primer
			Enamel, color olive drab (MIL-E-5556, X84087)	Brush	2	Paint entire assy

1-7. PRESERVATION, PACKAGING, PACKING AND MARKING REQUIREMENTS.

Preservation, Packaging, Paking and Marking shall be in accordance with figure 1-2.



*Figure 1-1. Three-quarter view, DC Generator Part No. 30B37-37-A.*







## SECTION II

### TEST, EQUIPMENT, SPECIAL TOOLS, AND MATERIALS

#### 2-1. TEST EQUIPMENT.

Refer to table 2-1 for a list of test equipment required to perform the procedures described in this manual.

*Table 2-1. Test Equipment Required*

Part, model or mil des	Fmc	Nomenclature	Technical description
Model 40B	06365	Balancing Machine	Used to balance armature assy
1001	60998	Dial Indicating Gage	Used to measure spring compression length
1650A	24655	Capacitance Bridge	Used to check capacitor values
13700-1C	19315	Insulation Breakdown Test Set	Used to perform insulation breakdown tests
7085-5	99664	Electrical Test Stand	Used to provide load conditions for performance testing
7199-1	99664	Aircraft Generator Test Stand	Used for performance testing of starter generator
	45598	Steam Dispenser	Used to steam clean armature assembly and generator stator

*NOTE.* Equivalent test equipment may be used.

#### 2-2. SPECIAL TOOLS.

Refer to table 2-2 for a list special tools required to perform the procedures described in this manual.

*Table 2-2. Special & Tools Required*

Part, model or mil des	Fmc	Nomenclature
QB80004-3	83298	Spring Scale
QB80059-3	83298	Generator Shaft Holding Wrench
QB80277-1	83298	Brush Spring Hook
QB80338-1	83298	Puller

*Table 2-2. Special Tools Required-Continued*

Part, model or mil des	Fmc	Nomenclature
1106038	83298	Bearing Puller
1106187	83298	Generator Stand
1106207	83298	Generator Interface
1106208	83298	Brush Box Aligner
1106209	83298	Pilot Holder
1106210	83298	Armature Stand

*NOTE.* Equivalent tools may be used.

#### 2-3. CONSUMBLE MATERIALS.

Refer to table 2-3 for a list of all consumable materials required to perform the procedures described

*Table 2-3. Consumable Materials Required.*

Item No.	Nomenclature	Specification number	Title
1	Trichlorethylene	MIL-T-7003	Trichlorethylene, Stabilized De-greasing
2	Solvent	P-D-680	Dry Cleaning Solvent
3	Lint-free cloth	CCC-C-440	Cloth, Cotton, Cheesecloth, Bleached and Unbleached
4	Cleaner	PC437-125LBDR	Cleaning Compound for Steam Cleaner
5	Lubricating oil	MIL-L-7870	Lubricating Oil, General Purpose, Low Temperature

Table 2-3. Consumable Materials Required-Continued

Item No.	Nomenclature	Specification number	Title
<b>6</b>	Corrosion preventive	MIL-C-4339	Corrosion Preventive, Soluble Oil
<b>7</b>	Shellac	TT-S-271	Shellac, Dry
<b>8</b>	Denatured alcohol	MIL-A-6091	Alcohol, Ethyl, Specially Denatured, Aircraft
<b>9</b>	Soft solder	QQ-5-571	Solder, Tin Alloy
<b>10</b>	Brazing alloy	MIL-B-15395, Grade 3	Silver Brazing Alloy
<b>11</b>	Spline lubricant	Pioneer No. 31 FMC 83298	
<b>12</b>	High temperature lubricating grease (Alternate for item 11)	MIL-G-3545	Lubricating Grease, High Temperature
<b>13</b>	Red Glyptal lacquer	No. 1201 FMC 04314	
<b>14</b>	Sealant, grade A	MIL-S-22473	Sealing, Locking and Retaining Compounds, Single Component
<b>15</b>	LockWire	MS20995C32-8	
<b>16</b>	Lockwire	MS20995C20-4	
<b>17</b>	Molybdenum coating	MIL-L-8937, FORMA	

2. Solder (MS20995C32-8)

## SECTION III

## GENERAL SUPPORT MAINTENANCE

## 3-1. DISASSEMBLY.

*a. General.*

(1) Disassemble the dc generator to the extent necessary for repair by using the illustrated parts breakdowns and the exploded views (figures 3-1 through 3-3), as described in paragraphs *b* through *d* below. To remove screws that are treated with sealant, hold a heat gun having a maximum temperature of 177°C (350°F) against head of screw until compound softens and screws can be removed.

(2) The index numbers are assigned in the order of disassembly, except that attaching parts are listed immediately following the parts they attach.

*b. DC Generator*

(1) Secure the dc generator to generator interface 1106207 (table 2-2) and mount on generator stand 1106187 (table 2-2).

(2) Remove terminal block cover (1, figure 3-1) and protective cap (20), if they are installed.

(3) Cut and discard lockwire from screw (6) on brush access (7) and bolts (13) in end bell cover assembly (12).

(4) Loosen screw (6) enough to spread brush access cover (7), and slide the brush access cover off the fan end of end bell assembly (38).

## NOTE

The last two threads of screw (6) have been distorted to captivate nut (5).

(5) Remove eight cap screws (9), eight lock (10), and eight washers (11) that secure the brush terminals. Using brush spring hook QB80277-1 (table 2-2), lift up the brush springs and remove eight electrical contact brushes (8). Discard the brushes.

(6) Remove four bolts (13), four lock washers (14), four washers (15), and end bell cover assembly (12).

(7) Hold the spline of drive shaft assembly (21) with shaft holding wrench QB80059-3 (table 2-2), use a suitable socket wrench to remove self-locking nut (16). Remove flat washer (17), and impression spring (18). Remove

drive shaft assembly (21) and front plate (22). If necessary, remove fan (19).

(8) Remove two screws (23), two lock washers (24), and two flat washers (25) to free the capacitor leads and terminals (29). Remove four screws (26), four lock washers (27), four washers (28), and the capacitor assembly from end bell assembly (38).

## NOTE

Removing screws (26) also release bearing retainer (40).

(9) Remove four screws (33) to free bearing retainer (44). Remove outer race bearing retainer (32).

(10) Using retaining ring pliers, remove lock rings (36 and 41). Remove outer dirt slingers (37 and 42).

(11) Using puller Q1380338-1 (table 2-2), remove end bell assembly (38). Refer to paragraph *c* below for disassembly procedures of the end bell assembly.

(12) Press armature assembly (45), with ball bearings attached, out of open end of generator stator (48).

(13) Using bearing puller 1106038 (table 2-2), remove ball bearings (39 and 43) from shaft of armature assembly (45). Discard the ball bearings at each overhaul.

(14) Remove inner dirt slingers (37 and 42) and bearing retainers (40 and 44). Remove four bushings (34) from housing of stator generator (48).

(15) If necessary, remove four screws (47) and identification plate (46).

(16) Refer to paragraph *d* below for disassembly procedures of the generator stator.

*c. End Bell Assembly.*

(1) Do not disassemble end bell assembly (38, figure 3-1) unless replacement of damaged parts or bearing bore metallizing is required.

(2) Do not remove four electrical contact holders (1, figure 3-2) unless damage is visible. Remove four cap screws (2), four lock washer (3), four flat washers (4), sixteen insulating washers (5), and four insulating tubes (6) from end bell (7).

**CAUTION**

**Do not remove cast-in bearing liner from end bell (7).**




Figure 8-1. DC Generator, Exploded View

Legend For Figure 3-1:

Index No.	Part number	Description	Qty per assy
3-1-	30B37-37-A	. GENERATOR, Direct current	1
-1	11d1055	. COVER, Terminal block	1
-2	MS20365-624A	. NUT, Self-locking	2
-3	MS35338-46	. WASHER, Lock	2
-4	AN960-616	. WASHER	2
	1532119	. COVER ASSY, Brush access	1
-5	833656	.. NUT, Plain square, cad. pl stl, No. 10-32 thd x 1/8 in. thk	1
-6	AN501A10-20	. SCREW	1
-7	1108811	. COVER, Brush access	1
-8	1108139	. BRUSH, Electrical contact (ATTACHING PARTS)	8
-9	890065-2	. SCREW, Cap, sch, cad. pl brz, 1/4-28 thd x 1/2 in. lg	8
-10	MS35338-44	. WASHER, Lock	8
-11	AN960-416	. WASHER	8
		---*---	
-12	1544572	. COVER ASSY, End bell (ATTACHING PARTS)	1
-13	1546947-121	. BOLT, Drilled, hex hd, cad. pl stl, 1/4-20 thd x 5-1/4 in. lg	4
-14	MS35338-82	. WASHER, Lock	4
-15	AN960C416L	. WASHER	4
		---*---	
-16	AN363C524	. NUT, Self-locking	1
-17	1320032	. WASHER, Flat, cad. pl stl, 21/64 id x 23/32 od x 3/32 in. thk	1
-18	1320031	. SPRING, Compression	1
-19	1107926	. FAN	1
-20	843-7/8 I.L.	. CAP, Protective (15819) (83298 part No. 1549704-1)	1
-21	1544668	. SHAFT ASSY, Drive	1
-22	1111791	. PLATE, Front	1
	1546898-1	. CAPACITOR ASSY (ATTACHING PARTS)	1
-23	819006-008	. SCREW, Fil h, sst, No. 6-32 thd x 1/4 in. lg	2
-24	819001-016	. WASHER, Lock, sst, for No. 6 screw	2
-25	819092-006	. WASHER, Flat, sst, for No. 6 screw	2
-26	MS35275-49	. SCREW	4
-27	MS35338-42	. WASHER, Lock	4
-28	AN960C8L	. WASHER	4
		---*---	
-29	19437	.. TERMINAL	2
-30	1111235	.. NIPPLE, Cable	4
-31	1113897	.. CAPACITOR SUBASSY	1
-32	1322942	. RETAINER, Bearing, outer race (ATTACHING PARTS)	1
-33	1322944	. SCREW, Flat hd, cad. pl stl, No. 8-32 thd x 15/16 in. lg	4
		---*---	
-34	1325794-3	. BUSHING	4
-35	MS171434	. PIN, Roll	1
-36	MS16624-1098	. RING, Lock	1
-37	844923	. SLINGER, Dirt	2
-38	1544529	. END BELL ASSY (See fig. 3-2)	1
-39	890659-5	. BEARING, Ball	1
-40	1329018	. RETAINER, Bearing	1
-41	MS16624-1098	. RING, Lock	1
-42	844923	. SLINGER, Dirt	2
-43	890659-5	. BEARING, Ball	1
-44	1329018	. RETAINER, Bearing	1
-45	1544645	. ARMATURE ASSY	1
-46	1544747	. PLATE, Identification (ATTACHING PARTS)	1
-47	22996-16	. SCREW, Self-tapping, rd hd, stl, No. 4 thd x 3/8 in. lg	4
		---*---	
-48	1544612	. STATOR, Generator (See fig. 3-3)	1




Figure 3-2. End Bell Assembly, Exploded View.

Legend For Figure 3-2:

Index No.	Part number	Description	Qty per assy
3-2-	1544529	END BELL ASSY (See item 38, fig. 3-1 for nha)	Ref
-1	1544527	. HOLDER, Electrical contact (ATTACHING PARTS)	4
-2	1543503	. SCREW, Cap, hex hd. 5/16-18 thd x 1-1/8 in. lg	4
-3	MS35338-45	. WASHER, Lock	4
-4	867491	. WASHER, Flat, cad. pl stl, for 5/16 in. screw	4
-5	1543622	. WASHER, Insulating	16
-6	1328928	. TUBE, Insulating --- * ---	4
-7	1544432-1	. BELL, End	1

*d. Generator Stator.*

(1) Do not disassemble generator stator (48, figure 3-1 ) unless replacement of damaged parts or bearing bore metallizing is required.

(2) Remove two self-locking nuts (2, figure 3-1 ), two lock washers (3), and two washers (4) from the E and B terminal studs, if not removed previously.

(3) Remove terminal plates (5 and 6, figure 3-3) and disconnect electrical lead (18) and

terminal lug (19) from the E and B terminal lugs, respectively.

(4) Remove two self-locking nuts (2), two lock washers (3), two washers (4), and two terminals ( 5 and 6), and disconnect the stator leads from the A and D terminal studs.

(5) Remove one bolt (7), one washer (8), two bolts (10), two washers (11), terminal board (9), and terminal board insulator (12).



(6) If removal of winding and pole shoe assembly (14) is required, use a suitable screwdriver press and screwdriver remove stake screws (13). Push out winding and pole shoe assembly (14) through opening in housing (22).

(7) If required, remove stator insulation (17).

**3-2. INSPECTION REQUIREMENTS.**

a. Refer to table 3-1 for detail inspection requirements for components of the dc generator

*Table 3-1. Detail Inspection Requirements*

Fig. No.	Index No.	Nomenclature	Inspection category	Methods of inspection	Remarks
3-1	31	Capacitor Subassembly (four capacitors)	Cracks, leaks, damaged insulation  Electrical rating—1.0 uf ±20%, 200 VDCW	Visual	Refer to parts list for values.
3-1	18	Compression Spring	Cracks, distortion  Load at compressed length of 0.875 in. to be 180 to 200 lb	Visual	
3-1	21	Drive Shaft Assy	Cracks	Magnetic particle (Specification MIL-I-6868)	Para 3-2b(1)
3-1	45	Armature Assy	Commutator undercut to 0.030 in. wide by 1/32 in. deep  Commutator contact surface	Visual	Para 3-4c
			Cracks, damaged insulation, damaged conductors	Visual	Para 3-2c Para 3-4b
			Insulation breakdown—300 volts, 60 Hz for 1 sec between commutator bars and shaft (ground)	13700-1C	Para 3-4b(5)
			Static and dynamic balance within 0.020 oz in.	Model 40B	Para 3-4c(7)
			Bearing surfaces		Table 7
3-1	48	Generator Stator (housing and stator)	Cracks, damaged insulation Bearing bore worn Insulation breakdown—300 volts, 60 Hz for 1 sec between any winding and housing (ground)	Visual	Para 3-2d
				13700-1C	
3-2	1	Electrical Contact Holder	Cracks, distorted springs Spring pressure to be 46 to 52 oz when spring is just lifted beyond brush position	Visual 1106140-3	Table 4
3-2	6	Insulating Tube	Cracks	Visual	
3-2	7	End Bell	Cracks, damaged threads Bearing bore worn	Visual	Para 3-2d




Figure 3-3. Generator Stator, Exploded View.

Legend For Figure 3-3:

Index No.	Part number	Description	Qty per assy
3-3-	1544612	STATOR, Generator (see item 48, fig. 3-1 for nha)	Ref
-1	1109458	. PLATE, Terminal	2
-2	MS20365-1032A	. NUT, Self-locking	2
-3	MS35337-43	. WASHER, Lock	2
-4	AN960-10L	. WASHER	2
-5	1101570	. TERMINAL	1

## Legend For Figure 8-9:-Continued

Index No.	Part number	Description	Qty per assy
3-3-6	1101569	M	1
-7	NK3-23	. BOLT, Machine, self-locking, cad. pl stl, No. 10-32 thd x 2-13/32 in. lg (02615) (83298 part No. 890662-23)	1
-8	AN960-10	. WASHER	1
-9	1109452	. BOARD, Terminal (ATTACHING PARTS)	1
-10	NK3-6	. BOLT, Machine, self-locking, cad. pl stl, No. 10-32 thd x 25/32 in lg (02615) (83298 part No. 890662-6)	2
-11	AN960-10	. WASHER ----*----	2
-12	1109569	. INSULATOR, Terminal board	1
-13	828998-4	. SCREW, Flat hd, cad. pl stl, No. 10-24 thd x 29/16 in. lg	16
-14	1544604	. SHOE ASSY, Winding and pole	1
	1544594-1	.. LEAD ASSY, Electrical	1
-15	1544578	... LUG, Terminal	1
	1544594-2	. LEAD ASSY, Electrical	1
-16	1544578	. . . LUG, Terminal	1
-17	1100850-3	. INSULATION, Stator	1
-18	1544593	. LEAD, Electrical	1
	1544580	. LEAD ASSY, Electrical	1
-19	1545983	.. LUG, Terminal	1
-20	1544578	.. LUG, Terminal	2
	1329845	. LEAD ASSY	1
-21	1329221	.. TERMINAL	1
-22	1544457	. HOUSING	1

## b. Drive shaft and amature shaft inspection:

(1) Check the drive shaft assembly (21, figure 3-1) splines for wear. The "top land" dimension of new spline teeth are 0.029 inch minimum for the 16-tooth spline and 0.039 inch minimum for the 12-tooth spline. Replace the drive shaft assembly when the "top land" dimension of a spline reaches zero.

(2) Closely examine the spline inside the shaft of amatum assembly (45) for wear. The degree of spline war may be determined by visual inspection. Make certain to check the entire length of tie spline for wear. Replace the amture assembly when the "top land" dimension of the spline reaches zero.

## NOTE

The spline is safe down to a "top land" dimension of zero, but if service records indicate "top land" dimension may reach zero during the next service period, the drive shaft assembly or armature assembly should be replaced.

## CAUTION

Spline wear rate will increase rapidly after reaching the zero "top land" dimension Contition.

(3) Inspect the drive shaft assembly for indication of overheating. Bear in mind that although discoloration may indicate a weakened shaft, this condition can be present in a sound shaft. Disregard uniform discoloration along the pencil section of the shaft; if, however, localized or blotchy discoloration is noted, overheating may be indicated.

(4) If slight bluing is observed, the drive shaft assembly may still be serviceable, provide a magnetic particle inspection (Specification MILP6868) reveals no surface cracks.

(5) If black discoloration is observed, discard the drive shaft assembly. Check for the cause of this condition, such as overload or excessive vibration.

c. Inspection the commutator of armature assembly (45). The brush contact surface should be even, highly burnished, and dark brown or almost black in color. If the contact surface is rough, pitted, burned, or covered by a hardened film of carbon or oil which cleaning does not remove, resurface the commutator as described in paragraph 3-4b.

d. Refer to table 3-2 for fits and clearances of component parts. If the inside diameter end bell (34, figure 3-2) or stator (22, figure 3-3) of housing bearing bone is worn beyond 2.0475

inches, when measured with an air gage, air probe, and a 2.0475-inch setting ring, metallize the worn surface as described in paragraph 3-4 d.

Table 3-2. Fits and Clearances

Part No.	Nomenclature	Service dimensions (inches)	Mating parts part No.	Nomenclature	Service dimensions (inches)	Service tolerance (inches)
1544645	Armature Assy shaft bearing surfaces)	0.9843 OD	890659-5	Ball Bearing	0.9843 ID	0.0000 L/L
154443-1	End Bell (bearing bore)	2.0475 ID	890659-5	Ball Bearing	2.0470 OD	0.0005 L
1544457	Stator Housing (bearing bore)	2.0475 ID	890659-5	Ball Bearing	2.0470 OD	0.0005 L

**3-3. CLEANING.**

a. General. Clean all parts of the dc generator with trichlorethylene (item 1, table 2-3) or dry cleaning solvent (item 2, table 2-3 ). Do not dip pants into the solvent. Use a stiff, nylon brush to scrub the parts thoroughly,

**WARNING**

Use solvent in a well-ventilated area. Avoid inhaling solvent fumes. Do not allow solvent to contact the skin as burns may occur.

*NOTE*

Refer to paragraph 3-3b for steam cleaning procedures for armature assembly (45, figure 3-1) and generator Water (48).

(1) Ultrasonic cleaning equipment may be used, if available. Consult the manufacturer of this equipment for proper cleaning solutions and methods to be used.

(2) Dry parts with a clean, lint-free cloth (item 3, table 2-3).

b. *Armature Assembly and Generator Stator.* Steam clean armature assembly (45, figure 3-1 ) and enerator stator (48) to remove any carbon, copper particles embedded, or any other foreign matter between the commutator bars and stator windings, as described in following steps (1) through (6).

**WARNING**

Goggles, rubber gloves, and other protective clothing should be worn.

(1) Prepare a quantity of detergent, using approximately 7 1/2 pounds of cleaner (item 4, table 2-3 ) per 100 gallons of water. The solution should be heated and thoroughly agitated by

placing the steam nozzle of steam dispenser (table 3) in the mixing tank.

*NOTE*

The strength of the solution can be varied to suit conditions.

(2) Use approximately 140 psi of steam and regulate the pressure at the boiler rather than at the nozzle to avoid pressurizing the hose line.

(3) Using a spray booth with adequate ventilation and exhaust fans, thoroughly clean the generator stator and armature assembly with the mixture of steam and detergent until all caked grease and carbon are removed. The proportion of detergent to steam can be varied depending upon the condition of Ithe generator stator and armature assembly.

(4) Shut off the detergent and continue blasting with steam until all traces of detergent are removed.

(5) With an oven capable of maintaining 149° C (300°F), bake the generator stator and armature assembly at 121° C (250° F) for 4 hours to thoroughly dry the parts.

(6) After baking, apply a light film of lubricating oil (item 5, table 2-3 ) or corrosion preventive (item 6, table 2-3 ) to all ferrous metal surfaces to prevent rusting.

**CAUTION**

Do not apply oil to the commutator surface.

**3-4. REPAIR OR REPLACEMENT.**

*NOTE*

Paragraphs b through f below list and describe procedures for repairable parts only.

*a. General.*

- (1) Replace all parts that are worn or damaged.
- (2) Replace electrical contact brushes (8, figure 3-1) and ball bearings (39 and 43) at each overhaul.
- (3) Replace all wiring having burned, discolored or cracked insulation, or broken or corroded terminals.

*b. Armature Assembly.* Replace armature assembly (45, figure 3-1) if any of the following conditions exist:

- (1) If the shaft diameter is less than 0.9843 inch.
- (2) If the commutator has badly burned bars, because such a condition is usually the result of open-circuited armature coils.
- (3) If commutator bars are loose or out of alignment.
- (4) If resurfacing the commutator (paragraph c below) would reduce the outside diameter below the specified minimum of 2.800 inches. This diameter is indicated by a step cut into the edge of the commutator.
- (5) If the insulation breakdown test (table 3-1) between bars and shaft (ground) shows indication of insulation breakdown.

**CAUTION**

When performing insulation breakdown test, keep test probes outside brush path to avoid damaging commutator contact surface.

*c. Resurfacing the Commutator.*

(1) To remove oil or carbon film, mount armature assembly (39, figure 3-1) in a lathe and take a single light cut across the face of the commutator at a speed of approximately 600 surface feet per minute. If the contact surface is scored, rough, or pitted, take a series of light cuts at approximately 200 surface feet per minute. A diamond-tipped cutting tool (figure 3-4) is recommended. The point of the cutting tool must be held on the centerline of the armature shaft. (See figure 3-5.) If a Carbide-tipped cutting tool (figure 3-6) is used, the point of the cutting tool must be held 0.031 inch below the centerline of the armature shaft. The minimum diameter to which the commutator may be turned down is 2.800 inches. This limit is indicated by a step cut into the commutator. If necessary to remove metal beyond this point, replace the armature assembly.




Figure 3-4. Fabrication of Diamond-tipped Cutting Tool.




Figure 3-5. Mounting of Commutator Cutting Tool.




Figure 3-6. Fabrication of Carboly-tipped Cutting Tool.

(2) After the commutator has been turned down, measure the depth of undercutting between commutator bars. If the depth is less than 0.031 inch, undercut the mica to this depth and to a width of 0.030 inch.

(3) After undercutting, take a final light cut of not more than 0.001 inch across the face of the commutator to remove burrs. If a diamond-tipped cutting tool (figure 3-4) is not available, make the final cut with a freshly honed carboly-tipped tool (figure 3-6). Cutting speed should be approximately 600 surface feet per minute with either type tool. Do not use polishing abrasives. After the final cut, remove burrs between commutator bars with a strip of fiber.

(4) Check that the commutator is concentric with the bearing surfaces of the armature shaft within 0.0005 inch, full indicator reading.

(5) Check that centerline of commutator slot is aligned within 0.010 inch with centerline of commutator mica.

(6) After resurfacing, clean the commutator to remove all traces of oil, grease, and metal chips, as specified in paragraph 3-3b.

(7) Check the armature assembly for static and dynamic balance, using balancing machine,

Model 40B (table 2-1). If out of balance by more than 0.020 ounce-inch, rebalance by inserting leaded epoxy material inside and under winding (core) openings, as required.

d. *Metallizing Bearing Bores.* If the bearing bore of end bell (7, figure 3-2) or stator housing (22, figure 3-3) is worn beyond 2.0475 inch, metallize the bore as described in following steps (1) through (9), below.

(1) Degrease the face of the bore and adjacent areas from which contaminants might be introduced, using a solvent specified in paragraph 3-3.

(2) Mask the area adjacent to the face of the bearing bore with shellac (item 7, table 2-3) to prevent adherence of the sprayed metal to these surfaces. Any shellac on the face of the bore will be removed by boring (step (3)).

(3) Using a feed which will provide a suitable base for metallizing, rough bore the bearing surface to correct any taper or out-of-round condition. Remove at least 0.006 inch, but do not exceed the original dimension by more than 0.015 inch on the radius.

(4) Insert the end bell or stator housing in a lathe, and rotate it at a speed of approximately 60 rpm.

### CAUTION

The area to be metallized must be absolutely clean.

(5) To prevent condensation of moisture, make several rapid passes over the work with the flame only, immediately before applying the molybdenum coating (item 17, table 2-3). Should the bore be so impregnated with grease as to prevent metallizing, replace the end bell or stator housing.

(6) Make several passes over the bearing bore to deposit a thin coat of molybdenum.

(7) Complete the metallizing with molybdenum or 0.80 percent carbon steel wire to a thickness of 0.006 inch on top of the finished diameter (finished diameter minus 0.012 inch).

(8) Rough bore the surface to 0.010 inch under the finished diameter. Finish the surface by grinding to an inside diameter of 2.0472, plus 0.0003, minus 0.0000 inches. The concentricity between the inside diameter of the bearing bore and both the outermost (4.122-inch) diameter of the stator housing, and the largest inside (6.125-inch) diameter of the end bell must be within 0.002 inch, full indicator reading.

(9) Remove masking shellac and grinding residue with denatured alcohol (item 8, table 2-3).

### e. Soldering.

(1) If terminals (29, figure 3-1) were replaced, use a rosin core solder composed of 100 percent tin (item 9, table 2-3) to solder the terminals to the capacitor leads. This solder has a melting point of 232° C (450° F).

### CAUTION

Do not use an acid solder or an acid flux, Do not burn insulation when soldering.

(2) For all other soldering operations, use silver brazing alloy (item 10, table 2-3) composed of 15 percent silver, 80 percent copper, and 5 percent phosphorous. This solder has a melting range between 650° C and 705° C (1200° F and 1300° F).

(3) All soft soldering must be done in accordance with Specification MIL-S-6872B. All silver brazing must be done in accordance with Specification MIL-B-7883B.

(4) After soldering or brazing, clean all joints with denatured alcohol (item 7, table 2-3)

to remove all traces of rosin and other foreign matter.

f. *Sleeving Replacement.* If it is necessary to replace sleeving on capacitor leads, use vinyl-flex fiberglass tubing. The sleeving replacement should have a black color, an inside diameter of between 0.040 inch and 0.049 inch, and a length of 1 3/4 inches.

### 3-5. LUBRICATION.


The only lubrication required for the dc generator is after assembly, coat the drive shaft spline with a light film of spline lubricant (item 11, table 2-3). If this lubricant is not available, use high-temperature lubricating grease (item 12, table 2-3)

### NOTE

Use of sealing compounds is specified throughout the reassembly paragraphs.

### 3-6. REASSEMBLY.

Reassembly is basically the reverse of disassembly. Follow the exploded views (figures 3-1, 3-2, and 3-3), the schematic diagram (figure 3-7) and the detailed procedures as described in paragraphs 3-6 a, b and c for reassembly instructions.



### NOTE:

ALL WIRING INSULATED FROM HOUSING

Figure 3-7. DC Generator, Schematic Diagram.

### a. Generator Stator.

(1) If any terminals were removed or replaced, braze terminals to leads as specified in paragraph 3-4e.

(2) Place stator insulation (17, figure 3-3) behind each compensating winding and main pole of winding and pole shoe assembly (14).

(3) Install and align winding and pole shoe assembly (14) in housing (22) and secure with sixteen screws (13). Tighten screws (13) to a torque of 40 pound-inches and check that the minimum gage clearance between opposite pole shoes is 4.273 inches. Stake each screw in two places.

(4) In(stall) terminal board insulator (12) and terminal board (9) on housing (22) and secure with bolts (7 and 10) and washers (8 and 11).

(5) Make certain terminal lug (19) is connected to the B terminal post.

(6) Make certain electrical lead (18) is connected to the E terminal post and brazed to the compensating winding.

(7) Make certain terminal (6) is connected to the A terminal post and terminal (5) is connected to the D terminal post.

(8) Tighten bolts (10 and 11) in terminal board (9) to a torque of 35 pound-inches.

*b. End Bell Assembly.*

(1) Using brush box aligner 1106208 (table 4) and pilot holder 1106209 (table 4), secure electrical contact holders (1, figure 3-2) to end bell (7) with four screws (2), four lock washers (3), four flat washers (4), sixteen insulating washers (5), and four insulating tubes (6).

(2) Coat the area between the insulating washers and the electrical contact holder bosses with red Glyptal lacquer (item 13, table 2-3).

(3) Bake the assembled parts in an oven at 177° C (350° F) for two hours.

(4) Retighten screws (2) to a torque of 75 to 80 pound-inches after baking.

*c. DC Generator.*

(1) Mount bearing retainer (44, figure 3-1) and one dirt slinger (42) on the drive end of armature assembly (45).

(2) Mount bearing retainer (40) and cme dirt slinger (37) with flange toward bearing, on the commutator end of armature assembly (45).

(3) Stand armature assembly (45) on stand 1106210 (table 4). Heat ball bearings (39 and 43) to 250°F ( 121°C) and install on shaft of armature assembly (45), making sure that the dirt Slingers are properly positioned.

(4) Install the remaining dirt slingers (37 and 42) with flange toward bearing, and lock rings (36 and 41), using retaining ring pliers.

(5) Insert armature assembly (45) into generator stator (48), seating ball bearing (43) in the bore of the housing.

(6) Mount end bell assembly (38) on ball bearing (39), making sure that mounting holes are aligned. If roll pin (35) is installed in the stator housing, align notch in the end bell with roll pin (35).

(7) Secure the stator housing to generator interface 1106207 (table 2-2) and mount on generator stand 1106187 (table 2-2).

(8) Align bearing retainer (44) with the four holes in the stator housing. Apply sealing compound (item 14, table 2-3) to the threads of four screws (33). Install bushings (34) and outer race bearing retainer (32), and secure with four screws (33).

(9) Align bearing retainer (40) with the four holes in end bell assembly (38). Apply sealing compound (item 14, table 2-3) to the threads of four screws (26). Install and align the capacitor assembly with terminals (29) adjacent to the two positive contact holder threaded screws. Secure the capacitor assembly to end bell assembly (38) and bearing retainer (40) with four screws (26), four lock washers (27), and four washers (28).

(10) Apply sealing compound (item 14, table 2-3) to the threads of two screws (23). Connect two terminals (29) of capacitor subassembly (31) to the two positive contact holder threaded screws and secure with two screws (23), two lock washers (24), and two washers (25).

(11) Mount front plate (22) on drive shaft assembly (21), and insert the drive shaft assembly through the shaft of armature assembly (45) at drive end.

(12) Install fan (19) between drive shaft assembly (21) and the shaft of armature assembly (45).

(13) Install a new compression spring (18) and flat washer (17). Use shaft holding wrench QB80059-3 (table 2-2) to keep the drive shaft from turning. Place a flat ring plate on top of shaft and mount dial setting gage 1001 (table 3) so that the stem rests on flat washer (17), and dial is set on zero. Take the free length of the compression spring (1-5/32 inch) and subtract the compression spring assembled length (7/8 inch) from it. Install and tighten self-locking nut (16) until the dial setting gage (table 2-1) reads the difference between the two valves (9/32 inch). The compression spring assembled length should be 0.875 inch and the load on the spring should be between 180 and 200 pounds.



**CAUTION**

The dial setting gage (table 2-1) shall be used to avoid any damage and/or incorrect readings. Do not use a torque wrench to adjust the compression spring.

(14) Apply sealing compound (item 14, table 2-3) to the threads of four bolts (13). Install end bell cover assembly (12) and secure with four bolts (13), four lock washers (14), and four washers (15).

(15) Using brush spring hook QB80277-1 (table 2-2) to lift up brush springs, install eight electrical contact brushes (8) in brush holders and secure brush terminals with eight screws (9), eight lock washers (10), and eight washers (11). Tighten the screws to a torque of 35 pound-inches.

(16) Slide brush access cover (7) over end bell assembly (38), and tighten screw (6) and square nut (5).

(17) After the dc generator has been tested satisfactorily, safety-wire the four mounting bolts

(13) with lock wire (item 15, table 2-3). Secure drilled head screw (6) to brush access cover assembly (7) with lock wire (item 16, table 2-3) in accordance with Military Standard MS 33540 (ASG).

(18) After the final test procedure has established optimum position of brushes, lock the end bell assembly in position. Using the notch in the end bell for location, press in roll in (35) flush to the Astor housing. If there is no drilled hole in the stator housing, refer to step (19).

(19) If required because either winding and shoe pole assembly (14, figure 3-3) or stator housing (22) was replaced, or as a result of testing, drill a 0.062, plus 0.003, minus 0.000 inch diameter hole through the stator housing, using the notch in the end bell for location. Then press in roll pin (35, figure 3-1) flush to the stator housing.



SECTION IV

FINAL TEST PROCEDURES

4-1. GENERAL.

If the dc generator fails to meet any of the test requirements and visual inspection does not disclose the cause of the trouble, refer to trou-

bleshooting table 4-1, disassemble, and repeat inspection procedures as outlined in Section III. After reassembling, repeat the test procedure from the beginning. Test conditions are as described in paragraph through *i* below.

Table 4-1. Troubleshooting

Item	Trouble	Probable cause	Remedy
1	Short brush life or excessive sparking	Worn, improperly seated, or loose fitting brushes Low brush spring tension Dirty commutator Scored, pitted, or out-of-round commutator Short, grounded, or open armature Ball bearings worn Shorted compensating winding	Replace, service, and/or readjust brushes as necessary. Readjust and/or replace spring. Service commutator. Resurface commutator. Replace armature. Replace ball bearings. Replace yoke assembly.
2	Generator noisy	Faulty condensers Discharged battery Excessive sparking at generator brushes	Replace condensers. Replace battery. See Item 1.
3	Output voltage low or no reading	Shorted or open rotor or exciter and/or shorted or open diodes Control panel faulty Shorted and/or open output windings Drive inoperative	Test; if faulty, replace rotor and/or diodes. Replace control panel. Test; replace housing if necessary. Check drive.
4	Output voltage indicates high	Control panel faulty Worn or faulty connections between generator and control panel	Replace control panel. Make proper connections and/or tighten connections.
5	Output voltage erratic or fluctuates	Faulty control panel High resistance, internal or external connection in the dc connection of generator	Replace control panel. Clean and/or tighten connections.
6	Output phase sequence incorrect with generator rotation correct	Intermittently shorted, grounded, or open ac rotor and/or stator. External wiring not properly connected	Test; replace rotor and/or housing if necessary. Check external wiring. Make proper connections. Refer to wiring diagram (figure 3-7).
7	System meters indicate zero, low, or fluctuating readings (output voltage satisfactory)	External wiring not properly connected Improper adjustment of voltage regulator	Check external wiring. Make proper connections and tighten. Check adjustments. Make proper adjustments.
8	System meters read off scale in wrong direction, with generator connected to load	Generator field magnetized in wrong direction External wiring not properly connected	Flash field in proper direction. Refer to wiring diagram (figure 3-7). Check all wiring connections. All connections should be clean and tight.
9	Equipment operating unsatisfactorily although no load voltage is at proper value	Faulty control panel Improper frequency	Replace control panel. Check drive.
10	Generator overheats	Excessive load	Check and reduce load, if necessary.

a. *Temperature.* Since the dc generator is self-cooled, no cooling air is required. Check that the ambient temperature is  $77 \pm 27^\circ\text{F}$  ( $25 \pm 15^\circ\text{C}$ ).

b. *Direction Of Rotation.* Drive the dc generator in a counterclockwise direction, as viewed from the drive end, during all tests.

c. *Plastic Windows.* It is recommended that a transparent plastic window strap be used during the brush seating procedure, so that the commutator end brushes will be visible. A spare brush access cover can be modified in the shop by cutting out squares, and riveting transparent non-flammable plastic window panes in place on the cover.

**CAUTION**

**Do not operate the dc generator without the brush access cover in place, as overheating may occur.**

d. *Mounting.* The dc generator should be mounted on aircraft generator test stand 7199-1 (table 2-1) or an equivalent test stand capable of driving the generator at speeds from 5000 to 11,000 rpm. The longitudinal axis of the generator should be horizontal.

e. *Excitation.* The dc generator should be self-excited and controlled by a suitable variable resistance in series with the shunt field.

*NOTE*

The shunt field current should not be considered as part of the dc generator load current.

f. *Load Location.* The load for the dc generator should be located so that it will not affect the ambient or blast cooling air temperature.

g. *Warm-Up.* The dc generator should be operated at a continuous operating speed, delivering the rated load at the rated voltage to obtain a constant temperature.

h. *Output Voltage Measurements.* Measure output voltages between terminals E and B.

i. *Shunt Field Voltage.* Measure the voltage drop across the shunt field between terminals A and E. (See figure 3-7.)

**4-2. FLASHING THE FIELD.**

To be sure that the dc magnetic circuit retains enough residual residual, to allow the dc generator voltage to build up properly, flash the field as described in steps a through d, below.

a. Connect the positive terminal of a 12-volt battery through a single-pole, single-throw knife switch to terminal A on terminal board (9, figure 3-3).

b. Connect the negative terminal of the battery to terminal E on the terminal board.

c. Apply battery current to the shunt field for 5 seconds by closing the knife switch.

d. Repeat the operation several times to be sure that the field is properly flashed.

**CAUTION**

**Use a knife switch when flashing the field. Opening the circuit at the starter generator or battery terminals can result in severe damage to the terminals or explosion of the battery.**

**4-3. BRUSH SEATING.**

Remove the brush access cover and replace it with the plastic window strap. (Refer to paragraph 4-1a(3). The brush "run-in" can now be observed.

b. Operate the dc generator at 5000 rpm until the face of each brush contacts the commutator 100 percent in the direction of rotation and for at least 75 percent of brush dimension parallel to the shaft. (See figure 4-1.) There must be no evidence of excessive grooving or other surface damage to the face of the brush.




Figure 4-1. Typical Brush Seating.

c. There must be no sparking except for fine pinpoint sparking at the generator brushes. Brushes should be removed from their brush holders for periodic inspection.

*NOTE*

If the brushes are removed from the brush holders, be sure to return each brush to the holder from which it was removed.

d. When brush seating is completed, remove, load and stop the dc generator. Allow the unit to cool before proceeding.

**4-4. FINAL TESTS.**

a. *General.* Mount the dc generator on the test stand as described in paragraph 4-1a(4).

b. *Maximum Speed for Regulation.*

**NOTE**

The dc generator must not be given an operation warm-up prior to this test .

(1) Turn on the test stand controls and increase the drive motor speed to 10,000 rpm.

(2) Adjust the regulator until the output voltage is 30 volts.

(3) Record the field voltage (Ef) and field current (If).

(4) Calculate the external resistance (Rx) in the field circuit by dividing the field voltage by the field current.

(5) The external resistance in the shunt field must not exceed 35 ohms.

c. *Heating, Commutation, Minimum Speed, and Equalizing Voltage.*

(1) For heating, commutation, minimum speed, and equalizing voltage tests, the following is considered as a continuous operating condition: While the dc generator is cold, the resistance and temperature of the shunt field must be determined for use in calculating the average field temperature rise during continuous operation at full load. The dc generator is considered to have reached its continuous operating condition when the rate of rise of the shunt field temperature does not increase more than 2°F (1°C) during a five-minute period.

(2) Start the blower and drive motor. Increase the drive motor speed to operate the dc generator at 8000 rpm. Close suitable switches of the load bank to apply 300 amperes dc load. When the dc generator reaches its continuous operating condition as described in paragraph c(1), proceed as follows:

(a) Check the readings of the instruments. During the heat run, readings must be limited to those shown in table 4-2.

*Table 4-2. Heating Test Readings*

Shunt Field	8 amperes (max)
Load Ammeter	300 amperes
Line Voltage	30 volts

(b) Measure the equalizing voltage across terminals D and E on terminal board (9, figure

3-3. The voltage must be between 1.9 and 2.1 volts.

(3) After completing the previous test, decrease the speed of the motor until the minimum rated of 5000 rpm is measured on the tachometer. Adjust the voltage regulator until a 26-volt reading is obtained. The starter generator must deliver rated current of 300 amperes, as read on the ammeter.

**NOTE**

At no time during the above heat runs should the required resistance external to the shunt field be less than 1.25 ohms. Refer to paragraph b (5) above to calculate the external shunt field resistance.

(4) Readjust the regulator until a 30-volt reading is obtained.

d. *Commutation.* Immediately following the previous heat runs, and with the dc generator hot, observe the commutation of the dc generator over the speed range 5000 to 8000 rpm for no load (all load switches off), half load (suitable load switches turned on give 150 amperes), and rated load bud (suitable switches turned on to give 300 amperes). Table 4-3 lists the various conditions. There should be no sparking except for the fine pinpoint sparking at the generator brushes.

**NOTE**

For any speed within the speed range, the field current must increase with increases in load.

e. *Overspeed.*

(1) Perform this test while the dc generator is hot as a result of testing.

(2) Open all load switches and the field switch. (Operate the generator at no load

(3) Increase the speed of the driving motor 11,000 rpm. The generator must operate at this speed for five minutes without mechanical failure, the throwing of varnish, or impairment of electrical performance.

*Table 4-3. Commutation Test Readings*

Speed (rpm)	Line voltage	Load (amperes)
5000	30	0
5000	30	150
5000	30	300
6500	30	0
6500	30	150
6500	30	300
8000	30	0
8000	30	150
8000	30	300

(4) At the end of the five-minute over-speed run, reduce the speed to 6500 rpm. Apply rated load of 300 amperes.

(5) Operate the dc generator for one minute and check the electrical performance. The results should compare with those observed in paragraph 4-4c,

*f. Dielectric Strength.*

(1) Perform this test while the dc generator is hot as a result of previous tests.

(2) Remove all external connections from dc generator terminal board, and disconnect terminals (29, figure 3-1 ) of capacitor subassembly (31).

(3) Using insulation breakdown test set 13700-1C, apply 300 volts ac (60 Hz) for one

second between the frame (ground ) and each terminal (A, B, D, and E) in turn. There must be no evidence of insulation breakdown or leakage current in excess of 2 milliamperes.

(4) Reconnect capacitor terminals.

*g. Polarity Check.*

(1) Operate the dc generator at rated speed and load conditions. Connect the voltmeter leads to stator generator terminals B and E, observing proper polarity.

(2) If the voltmeter connections must be reversed to obtain a reading, the polarity of the dc generator is reversed. In this case, flash the field in the proper direction as described in paragraph 4-2.

**SECTION V**  
**DIFFERENCE DATA SHEETS**

**NOT applicable**





## SECTION VI

## FEDERAL MANUFACTURERS' CODES

Code	Manufacturer and Location	Code	Manufacturer and Location
04314 ----	General Electric Co., Appliance Control Dept., Bridgeport, Conn.	45598 ----	Pantex Div., AMETEK, Inc., Pawtucket ,R.I.
06365 ----	Bear Manufacturing Co., 2016 5th Ave., Rock Island, Ill. 61202	60998 ----	Tubular Micrometer Co., St. James, Minn.
19315 ----	Bendix Corporation, Eclipse Pioneer Div., Teterboro, N.J. 07608	83298 ----	Bendix Corporation, Electric Power Div., Eatontown, N.J. 07724
24655 ----	General Radio Co., Cambridge, Mass.	99664 ----	United Manufacturing Div., UMC Electronics Co., North Haven, Conn. 06473



## APPENDIX A REFERENCES

<b>MS33540 (ASG)</b>	Safe Wiring and Cotter Pinning, General Practices for
<b>MIL-B-7883B</b>	Brazing of Steels, Copper, Copper Alloys, Nickel Alloys, Aluminum and Aluminum Alloys
<b>MIL-I-6868</b>	Magnetic Particle Inspection
<b>MIL-S-6872B</b>	Soldering Process, General Specification for
<b>TM 38-750</b>	Army Equipment Record Procedures
<b>TM 55-405-10</b>	Ground Handling and Service Equipment

By Order of the Secretary of the Army:

**W. C. WESTMORELAND,**  
*General, United States Army,*  
*Chief of Staff.*

**Official:**

**KENNETH G. WICKHAM,**  
*Major General, United States Army,*  
*The Adjutant General*

**DISTRIBUTION:**

To be distributed in accordance with DA Form 12-31 requirements for Direct and General Support Maintenance Instructions for UH-1A-1B, UH-1C and UH-1D Aircraft.

☆ U. S. GOVERNMENT PRINTING OFFICE: 1969-390921/47





**TM 55-6115-498-40, GS MAINTENANCE MANUAL, DIRECT CURRENT GENERATOR. PART  
NO. 30B37-37-A-1969**