

TB 9-6695-293-50

CHANGE 1

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

CALIBRATION PROCEDURE FOR CALIBRATOR, JOHN FLUKE, MODEL 5700A/() AND 5720A/() (WITH WIDEBAND AC VOLTAGE, OPTION 03); AMPLIFIER, JOHN FLUKE, MODEL 5725A/(); POWER AMPLIFIER, JOHN FLUKE, MODEL 5215A/CT; AND TRANSCONDUCTANCE AMPLIFIER, JOHN FLUKE MODEL 5220A/CT

Headquarters, Department of the Army, Washington, DC

6 October 2004

Distribution Statement A: Approved for public release; distribution is unlimited.

TB 9-6695-293-50, 8 October 2003, is changed as follows:

1. Remove old pages and insert new pages as indicated below. New or changed material is indicated by a vertical bar in the margin of the page.

Remove Pages

7 and 8
15 and 16

Insert Pages

7 and 8
15 and 16

2. File this change sheet in front of the publication for reference purposes.

By Order of the Secretary of the Army:

Official:



JOEL B. HUDSON

*Administrative Assistant to the
Secretary of the Army*

PETER J. SCHOOMAKER

*General, United States Army
Chief of Staff*

0422219

Distribution:

To be distributed in accordance with STD IDS No. RLC-1500, 2 January 2003, requirements for calibration procedure TB 9-6695-293-50.

***TB 9-6695-293-50**

DEPARTMENT OF THE ARMY TECHNICAL BULLETIN

CALIBRATION PROCEDURE FOR CALIBRATOR, JOHN FLUKE, MODEL 5700A/() AND 5720A/() (WITH WIDEBAND AC VOLTAGE, OPTION 03); AMPLIFIER, JOHN FLUKE, MODEL 5725A/(); POWER AMPLIFIER, JOHN FLUKE, MODEL 5215A/CT; AND TRANSCONDUCTANCE AMPLIFIER, JOHN FLUKE MODEL 5220A/CT

Headquarters, Department of the Army, Washington, DC

8 October 2003

Distribution Statement A: Approved for public release; distribution is unlimited.

REPORTING OF ERRORS AND RECOMMENDING IMPROVEMENTS

You can improve this manual. If you find any mistakes or if you know of a way to improve these procedures, please let us know. Mail your letter or DA Form 2028 (Recommended Changes to Publications and Blank Forms) directly to: Commander, U.S. Army Aviation and Missile Command, ATTN: AMSAM-MMC-MA-NP, Redstone Arsenal, AL 35898-5000. A reply will be furnished to you. You may also provide DA Form 2028 information to AMCOM via e-mail, fax, or the World Wide Web. Our fax number is DSN 788-6546 or Commercial 256-842-6546. Our e-mail address is: 2028@redstone.army.mil. Instructions for sending an electronic 2028 may be found at the back of this manual. For the World Wide Web, use <https://amcom2028.redstone.army.mil>.

SECTION		Paragraph	Page
I.	IDENTIFICATION AND DESCRIPTION		
	Test instrument identification	1	2
	Forms, records, and reports.....	2	3
	Calibration description	3	3
II.	EQUIPMENT REQUIREMENTS		
	Equipment required.....	4	7
	Accessories required.....	5	7
III.	CALIBRATION PROCESS FOR CALIBRATOR JOHN FLUKE, MODEL 5700A/() AND 5720A/()		
	Preliminary instructions	6	9
	Equipment setup	7	11
	Artifact calibration.....	8	12
	Dc voltage verification	9	14
	Resistance verification.....	10	15

*This bulletin supersedes TB 9-6695-293-50, dated 9 November 1998, including all changes.

		Paragraph	Page
	Dc current verification	11	17
	Ac current verification	12	19
	Ac voltage verification	13	22
	Wideband ac voltage (option 03)	14	25
	Final procedure	15	34
SECTION	IV. CALIBRATION PROCESS FOR AMPLIFIER JOHN FLUKE, MODEL 5725A/()		
	Preliminary instructions	16	35
	Equipment setup	17	35
	Artifact calibration 5725A/().....	18	35
	High ac voltage verification.....	19	36
	Dc current verification	20	37
	Ac current verification	21	38
	Final procedure	22	40
SECTION	V. CALIBRATION PROCESS FOR POWER AMPLIFIER JOHN FLUKE, MODEL 5215A/CT		
	Preliminary instructions	23	41
	Equipment setup	24	41
	High ac voltage.....	25	42
	Power supply	26	44
	Final procedure	27	44
	VI. CALIBRATION PROCESS FOR TRANSCONDUCTANCE AMPLIFIER, JOHN FLUKE, MODEL 5220A/CT		
	Preliminary instructions	28	45
	Equipment setup	29	45
	Dc accuracy and line regulation.....	30	47
	Frequency response.....	31	48
	Final procedure	32	50

SECTION I IDENTIFICATION AND DESCRIPTION

1. Test Instrument Identification. This bulletin provides instructions for the calibration of Calibrator, John Fluke, Model 5700A/ () and 5720A/ (), (with Wideband Ac Voltage, Option 03), Amplifier, John Fluke, Model 5725A/ (); Power Amplifier, John Fluke, Model 5215A/CT; and Transconductance Amplifier, John Fluke, Model 5220A/CT. The manufacturers' manuals and MIS-35947 were used as the prime data sources in compiling these instructions. The equipment being calibrated will be referred to as the TI (test instrument) throughout this bulletin.

a. Model Variations. None.

b. Time and Technique. The time required for this calibration is approximately 8 hours, using the dc and low frequency technique.

2. Forms, Records, and Reports

a. Forms, records, and reports required for calibration personnel at all levels are prescribed by TB 750-25.

b. No physical adjustments will be performed on the calibrator, Model 5700A/(), 5720A/() or amplifier, Model 5725A/(). Instead, an artifact calibration will be performed prior to performance verification tests. If an out-of-tolerance condition is detected, verify condition of standards, accessories, and equipment connections. If TI indications remain out of tolerance, repair action is required.

c. Adjustments to models 5215A/CT and 5220A/CT should be recorded and are designated (R) at the end of the sentence in which they appear. Report only those adjustments made and designated with (R).

3. Calibration Description. TI parameters and performance specifications which pertain to this calibration are listed in table 1.

Table 1. Calibration Description

Test instrument parameters	Performance specifications																																				
Calibrator, John Fluke, Model 5700A/() and 5720A/()																																					
Dc voltage	Output: 0 to 1100 V Accuracy: $\pm(\text{ppm reading} + \mu\text{V})$ Range : 220 mV..... 9 + 0.8 2.2 V..... 8 + 1.2 11 V..... 8 + 4 22 V..... 8 + 8 220 V..... 9 + 100 1100 V..... 11 + 600																																				
Resistance	Output: 0 to 100 M Ω Accuracy: $\pm(\text{ppm})^1$ Nominal output: <table style="margin-left: 40px; border: none;"> <tr> <td>0 Ω</td> <td>50 $\mu\Omega$</td> </tr> <tr> <td>1.0 Ω</td> <td>110</td> </tr> <tr> <td>1.9 Ω</td> <td>110</td> </tr> <tr> <td>10 Ω</td> <td>33</td> </tr> <tr> <td>19 Ω </td> <td>31</td> </tr> <tr> <td>100 Ω</td> <td>20</td> </tr> <tr> <td>190 Ω</td> <td>20</td> </tr> <tr> <td>1.0 kΩ</td> <td>15</td> </tr> <tr> <td>1.9 kΩ</td> <td>15</td> </tr> <tr> <td>10 kΩ </td> <td>14</td> </tr> <tr> <td>19 kΩ</td> <td>14</td> </tr> <tr> <td>100 kΩ</td> <td>16</td> </tr> <tr> <td>190 kΩ</td> <td>16</td> </tr> <tr> <td>1.0 MΩ</td> <td>23</td> </tr> <tr> <td>1.9 MΩ </td> <td>24</td> </tr> <tr> <td>10 MΩ</td> <td>46</td> </tr> <tr> <td>19 MΩ</td> <td>55</td> </tr> <tr> <td>100 MΩ</td> <td>130</td> </tr> </table>	0 Ω	50 $\mu\Omega$	1.0 Ω	110	1.9 Ω	110	10 Ω	33	19 Ω	31	100 Ω	20	190 Ω	20	1.0 k Ω	15	1.9 k Ω	15	10 k Ω	14	19 k Ω	14	100 k Ω	16	190 k Ω	16	1.0 M Ω	23	1.9 M Ω	24	10 M Ω	46	19 M Ω	55	100 M Ω	130
0 Ω	50 $\mu\Omega$																																				
1.0 Ω	110																																				
1.9 Ω	110																																				
10 Ω	33																																				
19 Ω	31																																				
100 Ω	20																																				
190 Ω	20																																				
1.0 k Ω	15																																				
1.9 k Ω	15																																				
10 k Ω	14																																				
19 k Ω	14																																				
100 k Ω	16																																				
190 k Ω	16																																				
1.0 M Ω	23																																				
1.9 M Ω	24																																				
10 M Ω	46																																				
19 M Ω	55																																				
100 M Ω	130																																				

See footnotes at end of table.

Table 1. Calibration Description – Continued

Test instrument parameters	Performance specifications				
Calibrator, John Fluke, Model 5700A/() and 5720A/()					
Ac voltage (cont.)	22 mV	100 – 300 kHz	.13 % +	15	
		300 – 500 kHz	.18 % +	30	
		500 kHz – 1.0 MHz	.48 % +	40	
	220 mV	10 – 20 Hz	600 +	16	
		20 – 40 Hz	240 +	10	
		40 Hz – 20 kHz	110 +	10	
		20 – 50 kHz	360 +	10	
		50 – 100 kHz	900 +	30	
		100 – 300 kHz	.11 % +	30	
		300 – 500 kHz	.18 % +	40	
2.2 V	10 – 20 Hz	600 +	100		
	20 – 40 Hz	180 +	30		
	40 Hz – 20 kHz	85 +	7		
	20 – 50 kHz	140 +	20		
	50 – 100 kHz	280 +	80		
	100 – 300 kHz	480 +	150		
	300 – 500 kHz	.12 % +	400		
22 V	500 kHz – 1.0 MHz	.24 % +	1.0 mV		
	10 – 20 Hz	600 +	1.0 mV		
	20 – 40 Hz	180 +	300		
	40 Hz – 20 kHz	85 +	70		
	20 – 50 kHz	140 +	200		
	50 – 100 kHz	280 +	400		
	100 – 300 kHz	600 +	1.7 mV		
220 V	300 – 500 kHz	.14 % +	5.0 mV		
	500 kHz – 1.0 MHz	.30 % +	9.0 mV		
	10 – 20 Hz	600 +	10 mV		
	20 – 40 Hz	180 +	3.0 mV		
	40 Hz – 20 kHz	90 +	1.0 mV		
	20 – 50 kHz	250 +	4.0 mV		
	50 – 100 kHz	600 +	10 mV		
1100 V	100 – 220 kHz	.16 % +	110 mV		
	50 Hz – 1.0 kHz	90 +	4.0 mV		
Frequency accuracy: Range: 10 Hz to 1 MHz Accuracy: ±0.01%					
Wideband ac voltage (Option 03)	Amplitude flatness, 1 kHz reference: ±(% of output + μV)				
	Frequency: 10 Hz to 30 MHz				
	Frequency		Voltage range		
			1.1 mV	3 mV	>3 mV
	10 Hz to 30 Hz		.3 + 0	.3 + 0	.3 + 0
	30 Hz to 120 kHz		.1 + 0	.1 + 0	.1 + 0
	120 kHz to 2.0 MHz		.2 + 3	.1 + 3	.1 + 3
	2.0 MHz to 10 MHz		.4 + 3	.3 + 3	.2 + 3
10 MHz to 20 MHz		.6 + 3	.5 + 3	.4 + 3	
20 MHz to 30 MHz		1.5 +	1.5 + 3	1.0 + 3	
15					

See footnotes at end of table.

Table 1. Calibration Description - Continued

Test instrument parameters	Performance specifications																																																																																																												
Calibrator, John Fluke, Model 5700A/() AND 5720A/()																																																																																																													
	Wideband frequency: Range: 10 Hz to 30 MHz Accuracy: 0.01%																																																																																																												
Wideband ac voltage (Option 03) (cont.)	Voltage output: Absolute uncertainty: $\pm(\% \text{ of output} + \mu\text{V})^3$ Range: 1.1 mV (- 46 dBm) to 3.5 V (+ 24 dBm) Frequency: 10 Hz to 30 MHz																																																																																																												
	<table border="1"> <thead> <tr> <th colspan="2">Accuracy:</th> <th colspan="4">Range</th> </tr> <tr> <th>Frequency</th> <th></th> <th>1.1 mV - 46 dBm</th> <th>3.0 mV - 37 dBm</th> <th>11 mV - 26 dBm</th> <th>33 mV - 17 dBm</th> </tr> </thead> <tbody> <tr> <td colspan="6" style="text-align: center;">$\pm (\% \text{ output} + \mu\text{V})$</td> </tr> <tr> <td>10 - 30 Hz</td> <td>1.1 + 2</td> <td>1.0 + 3</td> <td>1.0 + 8</td> <td>0.9 + 16</td> <td></td> </tr> <tr> <td>30 Hz - 500 kHz</td> <td>0.8 + 2</td> <td>0.7 + 3</td> <td>0.7 + 8</td> <td>0.6 + 16</td> <td></td> </tr> <tr> <td>0.5 - 2.0 MHz</td> <td>1.0 + 5</td> <td>0.8 + 6</td> <td>0.8 + 11</td> <td>0.7 + 19</td> <td></td> </tr> <tr> <td>2.0 - 10 MHz</td> <td>1.2 + 5</td> <td>1.1 + 6</td> <td>0.9 + 11</td> <td>0.8 + 19</td> <td></td> </tr> <tr> <td>10 - 20 MHz</td> <td>1.4 + 5</td> <td>1.3 + 6</td> <td>1.1 + 11</td> <td>1.0 + 19</td> <td></td> </tr> <tr> <td>20 - 30 MHz</td> <td>2.3 + 17</td> <td>2.2 + 18</td> <td>1.7 + 11</td> <td>1.6 + 19</td> <td></td> </tr> <tr> <td colspan="6" style="text-align: center;">$\pm (\% \text{ output} + \mu\text{V})$</td> </tr> <tr> <td></td> <td></td> <td>110 mV - 6.2 dBm</td> <td>330 mV + 3.4 dBm</td> <td>1.1 V + 14 dBm</td> <td>3.5 V + 24 dBm</td> </tr> <tr> <td colspan="6" style="text-align: center;">$\pm (\% \text{ output} + \mu\text{V})$</td> </tr> <tr> <td>10 - 30 Hz</td> <td>0.9 + 40</td> <td>0.8 + 100</td> <td>0.8 + 400</td> <td>0.7 + 500</td> <td></td> </tr> <tr> <td>30 Hz - 500 kHz</td> <td>0.6 + 40</td> <td>0.5 + 100</td> <td>0.5 + 400</td> <td>0.4 + 500</td> <td></td> </tr> <tr> <td>0.5 - 2.0 MHz</td> <td>0.7 + 43</td> <td>0.6 + 103</td> <td>0.6 + 403</td> <td>0.5 + 503</td> <td></td> </tr> <tr> <td>2.0 - 10 MHz</td> <td>0.8 + 43</td> <td>0.7 + 103</td> <td>0.7 + 403</td> <td>0.6 + 503</td> <td></td> </tr> <tr> <td>10 - 20 MHz</td> <td>1.0 + 43</td> <td>0.9 + 103</td> <td>0.9 + 403</td> <td>0.8 + 503</td> <td></td> </tr> <tr> <td>20 - 30 MHz</td> <td>1.6 + 43</td> <td>1.5 + 103</td> <td>1.5 + 403</td> <td>1.4 + 503</td> <td></td> </tr> </tbody> </table>	Accuracy:		Range				Frequency		1.1 mV - 46 dBm	3.0 mV - 37 dBm	11 mV - 26 dBm	33 mV - 17 dBm	$\pm (\% \text{ output} + \mu\text{V})$						10 - 30 Hz	1.1 + 2	1.0 + 3	1.0 + 8	0.9 + 16		30 Hz - 500 kHz	0.8 + 2	0.7 + 3	0.7 + 8	0.6 + 16		0.5 - 2.0 MHz	1.0 + 5	0.8 + 6	0.8 + 11	0.7 + 19		2.0 - 10 MHz	1.2 + 5	1.1 + 6	0.9 + 11	0.8 + 19		10 - 20 MHz	1.4 + 5	1.3 + 6	1.1 + 11	1.0 + 19		20 - 30 MHz	2.3 + 17	2.2 + 18	1.7 + 11	1.6 + 19		$\pm (\% \text{ output} + \mu\text{V})$								110 mV - 6.2 dBm	330 mV + 3.4 dBm	1.1 V + 14 dBm	3.5 V + 24 dBm	$\pm (\% \text{ output} + \mu\text{V})$						10 - 30 Hz	0.9 + 40	0.8 + 100	0.8 + 400	0.7 + 500		30 Hz - 500 kHz	0.6 + 40	0.5 + 100	0.5 + 400	0.4 + 500		0.5 - 2.0 MHz	0.7 + 43	0.6 + 103	0.6 + 403	0.5 + 503		2.0 - 10 MHz	0.8 + 43	0.7 + 103	0.7 + 403	0.6 + 503		10 - 20 MHz	1.0 + 43	0.9 + 103	0.9 + 403	0.8 + 503		20 - 30 MHz	1.6 + 43	1.5 + 103	1.5 + 403	1.4 + 503	
Accuracy:		Range																																																																																																											
Frequency		1.1 mV - 46 dBm	3.0 mV - 37 dBm	11 mV - 26 dBm	33 mV - 17 dBm																																																																																																								
$\pm (\% \text{ output} + \mu\text{V})$																																																																																																													
10 - 30 Hz	1.1 + 2	1.0 + 3	1.0 + 8	0.9 + 16																																																																																																									
30 Hz - 500 kHz	0.8 + 2	0.7 + 3	0.7 + 8	0.6 + 16																																																																																																									
0.5 - 2.0 MHz	1.0 + 5	0.8 + 6	0.8 + 11	0.7 + 19																																																																																																									
2.0 - 10 MHz	1.2 + 5	1.1 + 6	0.9 + 11	0.8 + 19																																																																																																									
10 - 20 MHz	1.4 + 5	1.3 + 6	1.1 + 11	1.0 + 19																																																																																																									
20 - 30 MHz	2.3 + 17	2.2 + 18	1.7 + 11	1.6 + 19																																																																																																									
$\pm (\% \text{ output} + \mu\text{V})$																																																																																																													
		110 mV - 6.2 dBm	330 mV + 3.4 dBm	1.1 V + 14 dBm	3.5 V + 24 dBm																																																																																																								
$\pm (\% \text{ output} + \mu\text{V})$																																																																																																													
10 - 30 Hz	0.9 + 40	0.8 + 100	0.8 + 400	0.7 + 500																																																																																																									
30 Hz - 500 kHz	0.6 + 40	0.5 + 100	0.5 + 400	0.4 + 500																																																																																																									
0.5 - 2.0 MHz	0.7 + 43	0.6 + 103	0.6 + 403	0.5 + 503																																																																																																									
2.0 - 10 MHz	0.8 + 43	0.7 + 103	0.7 + 403	0.6 + 503																																																																																																									
10 - 20 MHz	1.0 + 43	0.9 + 103	0.9 + 403	0.8 + 503																																																																																																									
20 - 30 MHz	1.6 + 43	1.5 + 103	1.5 + 403	1.4 + 503																																																																																																									
Amplifier, John Fluke 5725A/()																																																																																																													
Ac voltage	Output: 110 to 1100 V ac Frequency: 40 Hz to 100 kHz Accuracy: \pm (ppm of output + mV) <table border="1"> <thead> <tr> <th>Range</th> <th colspan="3">Frequency</th> </tr> <tr> <td></td> <td>40 Hz to 1 kHz</td> <td>1 to 20 kHz</td> <td>20 to 30 kHz</td> </tr> </thead> <tbody> <tr> <td>1100</td> <td>90 + 4</td> <td>165 + 6</td> <td>600 + 11</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th>Range</th> <th colspan="2">Frequency</th> </tr> <tr> <td></td> <td>30 to 50 kHz</td> <td>50 to 100 kHz</td> </tr> </thead> <tbody> <tr> <td>750</td> <td>600 + 11</td> <td>0.23 % + 45</td> </tr> </tbody> </table>	Range	Frequency				40 Hz to 1 kHz	1 to 20 kHz	20 to 30 kHz	1100	90 + 4	165 + 6	600 + 11	Range	Frequency			30 to 50 kHz	50 to 100 kHz	750	600 + 11	0.23 % + 45																																																																																							
Range	Frequency																																																																																																												
	40 Hz to 1 kHz	1 to 20 kHz	20 to 30 kHz																																																																																																										
1100	90 + 4	165 + 6	600 + 11																																																																																																										
Range	Frequency																																																																																																												
	30 to 50 kHz	50 to 100 kHz																																																																																																											
750	600 + 11	0.23 % + 45																																																																																																											
Dc current	Range: 11 A Accuracy: \pm (360 ppm of output + 480 μ A)																																																																																																												
Ac current	Range : 11 A Accuracy: \pm (ppm of output + μ A) <table border="1"> <thead> <tr> <th>Frequency</th> <th></th> <th></th> </tr> <tr> <td>40 Hz to 1 kHz</td> <td>1 to 5 kHz</td> <td>5 to 10 kHz</td> </tr> </thead> <tbody> <tr> <td>460 + 170</td> <td>950 + 380</td> <td>0.36 % + 750</td> </tr> </tbody> </table>	Frequency			40 Hz to 1 kHz	1 to 5 kHz	5 to 10 kHz	460 + 170	950 + 380	0.36 % + 750																																																																																																			
Frequency																																																																																																													
40 Hz to 1 kHz	1 to 5 kHz	5 to 10 kHz																																																																																																											
460 + 170	950 + 380	0.36 % + 750																																																																																																											

See footnotes at end of table.

TB 9-6695-293-50

Table 2. Minimum Specifications of Equipment Required

Common name	Minimum use specifications	Manufacturer and model (part number)
AC MEASUREMENT STANDARD	Range: 2.0 mV to 1000 V ac Accuracy: Test report ¹	Fluke, Model 5790A (13534003)
AC SHUNT SET	Range: 10 mA to 10 A Accuracy: Test report ¹	Holt Instrument Laboratories, Model HCS1 (MIS-10235)
DC REFERENCE STANDARD	Range: 10 V dc Accuracy: Test report	John Fluke, Model 732A (732A)
FREQUENCY COUNTER	Range: 10 Hz to 30 MHz Accuracy: $\pm 0.0025\%$	Fluke, Model PM6681/656 (PM6681/656)
MULTIMETER	Dc volts: Range: 100 mV through 1000 V Accuracy: From ± 2.1 ppm @ 10 V to 5.2 ppm at 500 V ² Dc current: Range: 100 μ A through 100 mA Accuracy: From ± 13 ppm @ 10 mA to 28 ppm at 100 mA ³ Resistance: Range: 0 through 1 M Ω Accuracy: From ± 2.2 ppm @ 10 k Ω to 11 ppm at 1 M Ω ²	Hewlett-Packard, Model 3458A (3458A)
RESISTANCE STANDARD	Range: 100 Ω to 1000 Ω Accuracy: $\pm 1.0\%$	Biddle Instruments, Model 71-631 (7910328)
RESISTANCE MEASURING SYSTEM	Range: 1.9 to 100 M Ω Accuracy: From ± 10 ppm @ 190 M Ω to 32.5 ppm at 100 M Ω	ESI, Model SP2980 (MIS-10281)
STANDARD RESISTOR NO. 1	Value: 10 k Ω Accuracy: Test report	General Radio, Type 1444A (MIS-10400)
STANDARD RESISTOR NO. 2	Value: 1.0 Ω Accuracy: Test report	L&N, Model 4020B (8616289)
STANDARD RESISTOR NO. 3	Value: .10 Ω Accuracy: Test report ²	L&N, Model 4221B (8616294)
STANDARD RESISTOR NO. 4	Value: .010 Ω Accuracy: Test report ²	Biddle Gray, Model 601235 (7902994)
STANDARD RESISTOR NO. 5	Value: .001 Ω Accuracy: Test report ²	Biddle Gray, Model 601240 (7902993)

¹Combined accuracy of ac shunt set and ac measurement standard is : From ± 50 ppm @ 10 mA, 1 kHz to $\pm .255\%$ @ 2.0 A, 10 kHz.

²Utilizes manufacturer's 24-hour specification for dc voltage, resistance (0 through 1 M Ω), and dc current (100 μ A to 100 mA).

³Combined accuracy of multimeter and standard resistor No. 3 is $\pm 0.002\%$, No. 4 is $\pm 0.01\%$, and No. 5 is $+0.016\%$.

SECTION III
CALIBRATION PROCESS FOR
CALIBRATOR, JOHN FLUKE, MODEL 5700A/() AND 5720A/()

6. Preliminary Instructions

a. The instructions outlined in paragraphs 6 and 7 are preparatory to the calibration process. Personnel should become familiar with the entire bulletin before beginning the calibration.

b. Items of equipment used in this procedure are referenced within the text by common name as listed in table 2.

c. Unless otherwise specified, verify the results of each test and, whenever the test requirement is not met, take corrective action before continuing with the calibration. Additional maintenance information is contained in the manufacturers' manuals for this TI.

d. Unless otherwise specified, all controls and control settings refer to the TI.

e. Multimeter, Hewlett-Packard, Model 3458A, Characterization

NOTE

The characterization is required to establish the manufacturer's 24-hour specifications. If ambient temperature drifts more than 1 degree Celsius prior to completing paragraphs 9 through 11 below, the characterization (and paragraph(s) must be repeated.

NOTE

Control and control settings in this paragraph refer to the multimeter, unless otherwise specified.

- (1) Remove all external input signals from the front and rear terminals.
- (2) Select the **DCV FUNCTION** and the **100 mV RANGE**.
- (3) Set front panel **TERMINALS** pushbutton to **FRONT** position.
- (4) Ensure that at least a 4-hour warmup has elapsed since power was applied.

TB 9-6695-293-50

(5) Front Terminal Offset:

(a) Connect a four-terminal short across the front panel terminals as shown in figure 1.

(b) After connecting the short, allow 5 minutes for thermal equilibrium.




Figure 1. Four-terminal short.

NOTE

Take precautions to prevent thermal changes near four-wire short. Do not touch short after it is installed. If drafts exist, cover **INPUT** terminals/short to minimize thermal changes.

(c) Execute the **CAL 0** command by pressing: **Blue**, **AUTO CAL**, **0**, **,**, **3**, **4**, **5**, **8**, and **ENTER** keys. This adjustment takes about 5 minutes. When completed, the multimeter will return to displaying dc voltage measurements.

(d) Set to **10 V RANGE** and remove four-terminal short from front terminals.

(6) Dc Gain:

(a) Select **DCV FUNCTION** and set front panel **TERMINALS** pushbutton to **FRONT**.

(b) Connect dc reference standard 10 V output to **INPUT HI**, **LO**, and **GUARD** terminals.

(c) Execute the **CAL** command specifying the 10 V test report value of dc reference standard. For example, if the test report value is 10.000001 V press: **Blue, AUTO CAL, 1, 0, ., 0, 0, 0, 0, 0, 1, , , 3, 4, 5, 8** and **ENTER** keys. This adjustment takes about 2 minutes and, when completed, multimeter will display dc voltage measurements.

(d) Disconnect dc reference standard from multimeter.

(7) Resistance and Dc Current:

(a) Select the four-wire ohms measurement **FUNCTION** and enable the offset compensation by pressing: **Blue, OHMF/OHM, OFFSET COMPΩ, ↑** , and **ENTER** keys.

(b) Connect standard resistor No. 1 to multimeter using four-wire technique and set **GUARD** pushbutton to the **TO LO** position

(c) Execute the **CAL** command specifying the test report value of the standard resistor. For example, if the test report value is 10.00011 kΩ press: **Blue, AUTO CAL, 1, 0, ., 0, 0, 0, 1, 1, E, 3, , , 3, 4, 5, 8**, and **ENTER** keys. This adjustment takes about 12 minutes and, when completed, multimeter will return to displaying resistance readings.

(d) Disconnect standard resistor and execute **ACAL AC** by pressing: **AUTO CAL, ↓, ↓, 3, 4, 5, 8**, and **ENTER** keys.

7. Equipment Setup

WARNING

HIGH VOLTAGE is used or exposed during the performance of this calibration. DEATH ON CONTACT may result if personnel fail to observe safety precautions. REDUCE OUTPUT(S) to minimum after each step within the performance check where applicable.

- a. Connect TI to a 115 V ac source.

NOTE

If TI is being calibrated in conjunction with a 5725A/() amplifier, the 5725A/() should be connected to TI at this time. The 5725A/() should be warmed up for 30 minutes and in the **ON** state during **b** below and during paragraph **8** below. Afterwards, the 5725A/() could be in the **OFF** state until performance of section IV below.

- b. Set **POWER** switch to **ON** and allow at least 30 minutes to warmup

NOTE

When turned on, the TI undergoes a self test. If self test fails, take corrective action before proceeding.

- c. Perform the **DC ZERO CALIBRATION** by pressing the following softkeys:
 - (1) **SETUP MENUS**
 - (2) **CAL**
 - (3) **ZERO**

8. Artifact Calibration

NOTE

Through the following calibration steps the TI display screen will provide some instructions. When the display reads "...Please Wait...", wait until display changes before continuing with next step.

- a. Press **RESET** pushbutton then press **SETUP MENUS** softkey.
- b. Press **CAL** softkey; then press **CAL** softkey again.
- c. Press one of the softkeys under the **CALIBRATION** display.
- d. Enter ambient temperature and press **ENTER**.
- e. Connect equipment as shown in figure 2.




Figure 2. 10 V internal calibration.

- f. Enter the test report value of the dc reference standard 10 V output; then press **ENTER** and wait for **PROCEED** to appear on TI display.

- g. Press **PROCEED** softkey.
- h. Reverse the **HI** and **LO** connections at the dc reference standard; then press **ENTER** and wait for next instructions to appear on TI display.
- i. Connect equipment as shown in figure 3.




Figure 3. 10 kΩ internal calibration.

- j. Enter the test report value of standard resistor No. 1, then press **ENTER** and wait for **PROCEED** to appear on TI display.
- k. Press the **PROCEED** softkey.
- l. Connect equipment as shown in figure 4.




Figure 4. 1 Ω internal calibration.

TB 9-6695-293-50

- m. Enter the test report value of standard resistor No. 2; then press **ENTER** and wait for **PROCEED** to appear on TI display.
- n. Remove standard resistor from equipment setup; then press **PROCEED** softkey.
- o. After TI calculations have completed set the TI rear panel **CALIBRATION** switch to **ENABLE** and, if a 5725A amplifier is being calibrated, set its rear panel **CALIBRATION** switch to **ENABLE**; then press **STORE VALUES** softkey on TI.
- p. Press the **DONE WITH CAL** softkey.
- q. Set the TI rear panel **CALIBRATION** switch to **NORMAL** and, if a 5725A amplifier is being calibrated, set its rear panel **CALIBRATION** switch to **NORMAL**.
- r. Press **RESET** pushbutton.

9. Dc Voltage Verification

NOTE

The characterization of the multimeter is required for this performance check. If ambient temperature drifts more than 1 degree Celsius (from time of characterization) prior to completing paragraph 9 below, the characterization (and paragraph 9) must be repeated.

WARNING

The TI is capable of supplying lethal voltages. Do not make connections to the output terminals when any voltage is present. Placing the TI in **STANDBY** may not be enough to avoid shock hazard, since the **OPR/STBY** pushbutton could be pressed accidentally. Press the **RESET** pushbutton and verify that **STANDBY** is lit before making connections to the **OUTPUT** terminals.

- a. Connect TI **OUTPUT HI**, **LO**, and **GUARD** terminals to multimeter **INPUT HI**, **LO**, and **GUARD** terminals. Ensure that TI **EX SENS** and **EX GRD** pushbuttons are in the off positions.
- b. Set multimeter for most accurate dc voltage measurements and to the manual 100 mV range.
- c. Set TI for a 100 mV dc output. Multimeter will indicate between 099.9983 and 100.0017 mV dc.
- d. Set multimeter to 1 V range and set TI for a 1 V dc output. Multimeter will indicate between 0.9999908 and 1.0000092 V dc.

e. Repeat **d** above for multimeter range settings and output voltages listed in table 3. Multimeter will indicate within the limits listed.

Table 3. Dc Voltage Linearity Test Multimeter Indications

Multimeter range setting (V dc)	Test instrument output (V dc)	Multimeter indications (V dc)	
		Min	Max
10	2	01.999980	02.000020
10	3	02.999972	03.000028
10	4	03.999964	04.000036
10	5	04.999956	05.000044
10	6	05.999948	06.000052
10	7	06.999940	07.000060
10	8	07.999932	08.000068
10	9	08.999924	09.000076
10	10	09.999916	10.000084
100	100	099.99900	100.00100
1000	1000	999.9884	1000.0116

f. Set TI to the minimum output then press **RESET** pushbutton.

10. Resistance Verification

NOTE

The characterization of the multimeter is required for this performance check. If ambient temperature drifts more than 1 degree Celsius (from time of characterization) prior to completing paragraph **10** below, the characterization (and paragraph **10**) must be repeated.

a. Connect equipment as shown in figure 5.




Figure 5. Resistance (0 through 1 MΩ).

b. Configure multimeter for most accurate four-wire resistance measurements. (Configuration modifications will be required depending on value of input resistance; e.g., set **0COMP** to **ON** until **100 kΩ**, then set **0COMP** to **OFF**.)

TB 9-6695-293-50

c. Set TI for a 1 Ω output. Multimeter will indicate within ± 110 ppm of displayed value on TI.

d. Repeat technique of c above for settings listed in table 4. Multimeter will indicate within the listed limits.

Table 4. Resistance

Test instrument output	Multimeter indication \pm (ppm of test instrument displayed value)
1.9 Ω	110
10 Ω	33
19 Ω	31
100 Ω	20
190 Ω	20
1 k Ω	15
1.9 k Ω	15
10 k Ω	14
19 k Ω	14
100 k Ω	16
190 k Ω	16
1 M Ω	23
0 Ω	50 $\mu\Omega$

e. Set TI to **STANDBY**.

f. Connect equipment as shown in figure 6.

g. Set TI for a 1.9 M Ω output. Measure resistance. Resistance measuring system will indicate within ± 24 ppm of TI displayed value.

h. Set TI for a 10 M Ω output. Measure resistance. Resistance measuring system will indicate within ± 46 ppm of TI displayed value.




Figure 6. Resistance (1.9 through 19 MΩ).

- i. Set TI for a 19 MΩ output. Measure resistance. Resistance measuring system will indicate within ± 55 ppm of TI displayed value.
- j. Set TI for a 100 MΩ output. Measure resistance. Resistance measuring system will indicate within ± 130 ppm of TI displayed value.
- k. Press **RESET**.

11. Dc Current Verification

NOTE

The characterization of the multimeter is required for this performance check. If ambient temperature drifts more than 1 degree Celsius (from time of characterization) prior to completing paragraph 11 below, the characterization (and paragraph 11) must be repeated.

- a. Connect **OUTPUT HI**, **LO**, and **GUARD** terminals to multimeter **INPUT I**, **LO**, and **GUARD** terminals. Configure multimeter for most accurate dc current measurements.

TB 9-6695-293-50

b. Set TI for a 1 mA output.

c. Using output adjustment control, set TI for a 1.0000000 mA (± 10 digits) indication on multimeter. TI **Error** display will be within the limits listed in table 5.

Table 5. Dc Current

Test instrument		Error display Limits (\pm ppm)
Output		
1	mA	70
10	mA	70
100	mA	80
100	μ A	160

d. Set TI for a -1 mA output.

e. Using output adjustment control, set TI for a -1.0000000 mA (± 10 digits) indication on multimeter. TI **Error** display will be within the limits listed in table 5.

f. Repeat technique of **b** through **e** above for values listed in table 5, section A. TI **Error** display will indicate within the listed limits.

g. Connect equipment as shown in figure 7.




Figure 7. Dc current (1 and 2 A).

h. Configure multimeter for most accurate dc voltage measurements.

- i. Set TI for a 1 A dc output and record multimeter indication.
- j. Refer to test report for standard resistor No. 3 and divide test report value into multimeter indication recorded in **i** above. The calculated current will be between .999875 and 1.000125 A.
- k. Repeat technique of **i** and **j** above for -1 A dc.
- l. Repeat technique of **i** through **k** above for 2 A dc. The calculated current will be between (+ and -) 1.99978 and 2.00022 A.

12. Ac Current Verification

a. 10 mA to 2.0 A

- (1) Connect equipment as shown in figure 8. Press **INPUT 1** pushbutton on ac measurement standard.




Figure 8. Ac current (10 mA to 2 A)

- (2) Enter the ac-to-dc difference corrections for each shunt at each frequency in the appropriate column of table 6.

Table 6. Ac Current

Test instrument output		Ac measurement standard error display	Ac shunt ac-dc difference	Calculated error (± %)	Error limits (± %)
Current	Frequency				
2.0 A	3.0 kHz				0.090
	20 Hz				0.077
	10 kHz				1.010
1.0 A	1.0 kHz				0.079
	5.0 kHz				0.095
	10 kHz				1.020
100 mA	10 Hz				0.085
	20 Hz				0.046
	1.0 kHz				0.022
	5.0 kHz				0.120
	10 kHz				0.280
10 mA	10 Hz				0.085
	20 Hz				0.046
	1.0 kHz				0.020
	5.0 kHz				0.120
	10 kHz				0.280
1.0 mA	10 Hz		N/A	N/A	0.085
	20 Hz		N/A	N/A	0.046
	1.0 kHz		N/A	N/A	0.020
	5.0 kHz		N/A	N/A	0.120
	10 kHz		N/A	N/A	0.280
100 μA	10 Hz		N/A	N/A	0.110
	20 Hz		N/A	N/A	0.067
	1.0 kHz		N/A	N/A	0.036
	5.0 kHz		N/A	N/A	0.120
	10 kHz		N/A	N/A	0.280

(3) Set TI for a +2.0 A dc output. Allow at least 10 minutes for shunt stabilization.

NOTE

The 10 minute stabilization may only be required for the first measurement after ac shunt values are changed. Afterwards allow at least 1 minute after each TI output change before noting TI or multimeter indications.

(4) When the reading has settled, press **SET REF** soft key on ac measurement standard and set display to indicate **PCT** units.

NOTE

When **SET REF** is engaged the display shows the difference between an applied input and the stored reference, or average of references. The difference can be displayed in units of V (or mV), ppm, percent, or ratio. Once a reference has been established you can cycle through each choice by pressing any of the three softkeys below the display. The display will cycle through **PPM** (power on state), **PCT**, **VOLTS**, and **RATIO**, and displays the equation used in each case.

- (5) Set TI for 2.0 A, 3.0 kHz ac output. Record ac measurement standard displayed error indication in appropriate column of table 6.
- (6) Return to +2.0 A dc output that was set in (3) above and verify that the ac measurement standard error display returns to a zero reading ± 0.0010 PCT; if not, repeat technique of (3) through (5) above.
- (7) Algebraically add the resulting error indication to the test reported ac-to-dc difference of the ac shunt. The result will be within the limits specified.
- (8) Repeat technique of (5) through (7) above for 20 Hz and 10 kHz.
- (9) Repeat technique of (2) through (8) above for 1.0 A, 100 mA and 10 mA using the appropriate ac shunts.

b. 1.0 mA and 100 μ A

- (1) Connect equipment as shown in figure 9. Set resistance standard dials to 000100.00. Press **INPUT 2** pushbutton on ac measurement standard.




Figure 9. Ac current (1.0 mA and 100 μ A).

- (2) Set TI for a +1.0 mA dc output.

TB 9-6695-293-50

- (3) When the reading has settled, press **SET REF** soft key on ac measurement standard.
- (4) Set TI for 1.0 mA, 1.0 kHz ac output. Record ac measurement standard displayed error indication in appropriate column of table 6. The result will be within the limits specified.
- (5) Return to +1.0 mA dc output that was set in (2) above and verify that the ac measurement standard error display returns to a zero reading ± 0.0010 PCT; if not, repeat technique of (2) through (4) above.
- (6) Repeat technique of (4) and (5) above for 10 Hz, 20 Hz and 5 kHz and 10 kHz.
- (7) Repeat technique of (2) through (6) above for 100 μ A, but set the resistance standard dials to 001000.00.

13. Ac Voltage Verification

a. Frequency Accuracy

- (1) Connect **OUTPUT HI** and **LO** terminals to frequency counter.
- (2) Set TI for a 1 V, 10 Hz output. Frequency counter will indicate between 99.99 and 100.01 ms.
- (3) Repeat technique of (2) above for the frequencies listed in table 7. Frequency counter will indicate within the listed limits.

Table 7. Ac Voltage, Frequency Accuracy

Test instrument frequency	Frequency counter indications			
	Min		Max	
15 Hz	66.66	ms	66.6733	ms
100 Hz	9.999	ms	10.001	ms
200 Hz	199.98	Hz	200.02	Hz
500 Hz	499.95	Hz	500.05	Hz
1kHz	999.9	Hz	1000.1	kHz
5kHz	4999.5	Hz	5000.1	Hz
10 kHz	9.999	kHz	10.001	kHz
50 kHz	49.995	kHz	50.005	kHz
100 kHz	99.99	kHz	100.01	kHz
140 kHz	139.986	kHz	140.014	kHz
200 kHz	199.98	kHz	200.02	kHz
500 kHz	499.95	kHz	500.05	kHz
1MHz	999.9	kHz	1.0001	MHz

b. Ac Voltage (2 mV through 1000 V)

(1) Place ac measurement standard on top of TI and connect equipment as shown in figure 10. Press **INPUT 2** pushbutton on ac measurement standard.




Figure 10. Ac voltage (2 mV through 1000 V).

(2) On the ac measurement standard, press the **UTIL MENUS** pushbutton then the **MEAS CONTROL** soft key. Set **DIGITAL FILTER MODE** to **FAST** and **RESTART** to **MEDIUM**. Push the **DONE** soft key twice to return to the measurement display and set to **AUTO** range.

(3) Set TI for a 1 mV, 1 kHz output. Adjust TI output adjustment knob for an indication of 2.0000 mV (± 2 digits) on the ac measurement standard. Record the TI error display indication in table 8.

(4) Verify that the result is within the limits listed in table 8.

(5) Repeat technique of (3) and (4) above for remaining frequencies for 1 mV output level.

(6) Repeat technique of (3) through (5) above for the remaining output levels and frequencies listed in table 8. In (3) above, ± 5 digits can be used for output levels ≥ 100 mV.

Table 8. Ac Voltage, 2 mV through 1000 V

Test instrument		Measured Error (%)	Limits (0 ±%)
Output level	Frequency		
1 mV	10 Hz		0.560
1 mV	30 Hz		0.524
1 mV	1 kHz		0.512
1 mV	30 kHz		0.541
1 mV	90 kHz		0.895
1 mV	200 kHz		1.630
1 mV	400 kHz		3.180
1 mV	1 MHz		4.480
10 mV	10 Hz		0.120
10 mV	30 Hz		0.084
10 mV	1 kHz		0.072
10 mV	30 kHz		0.101
10 mV	90 kHz		0.175
10 mV	200 kHz		0.280
10 mV	400 kHz		0.480
10 mV	1 MHz		0.880
100 mV	10 Hz		0.076
100 mV	30 Hz		0.034
100 mV	1 kHz		0.021
100 mV	30 kHz		0.046
100 mV	90 kHz		0.120
100 mV	200 kHz		0.140
100 mV	400 kHz		0.220
100 mV	1 MHz		0.460
1.0 V	10 Hz		0.070
1.0 V	30 Hz		0.021
1.0 V	1 kHz		0.0092
1.0 V	30 kHz		0.016
1.0 V	90 kHz		0.036
1.0 V	200 kHz		0.063
1.0 V	400 kHz		0.160
1.0 V	1 MHz		0.340

Table 8. Ac Voltage, 2 mV through 1000 V - Continued

Test instrument		Measured error (%)	Limits (0 ±%)
Output level (V)	Frequency		
10 V	10 Hz		0.070
10 V	30 Hz		0.021
10 V	1 kHz		0.0092
10 V	30 kHz		0.016
10 V	90 kHz		0.032
10 V	200 kHz		0.077
10 V	400 kHz		0.190
10 V	1 MHz		0.390
100 V	10 Hz		0.070
100 V	30 Hz		0.021
100 V	1 kHz		0.010
100 V	30 kHz		0.029
100 V	90 kHz		0.070
100 V	200 kHz		0.270
1000 V	1 kHz		0.0094

14. Wideband Ac Voltage (Option 03)

a. Gain (Cable and 50Ω Termination) Calibration

- (1) Verify that TI has warmed up for at least 30 minutes.
- (2) Press **SETUP MENUS** soft key.
- (3) Press **CAL** soft key; then press **CAL** again.
- (4) Press **WIDEBAND GAIN** soft key.
- (5) Enter the ambient temperature and press **ENTER** pushbutton.
- (6) Connect TI as shown in figure 11 for positive gain calibration.
- (7) Press **ENTER** pushbutton.




Figure 11. Gain calibration.

NOTE

As wideband gain calibration proceeds, messages appear on the display identifying all processes as they are encountered. Proceed to (8) below when positive gains calibration is complete.

(8) For negative gain calibration, reverse connection at the **SENSE** input so that center conductor is connected to **LO** and then press **ENTER** pushbutton.

(9) At completion of (8) above, set rear panel **CALIBRATION NORMAL/ENABLE** switch to **ENABLE** and press **STORE VALUES** soft key.

(10) Press **DONE WITH CAL** soft key until TI display returns to normal. Then set rear panel **CALIBRATION NORMAL/ENABLE** switch to **NORMAL**.

(11) Press **RESET** pushbutton.

NOTE

Paragraphs **b** through **d** below comprise the verification test for the wideband option. Paragraph **e** below is the flatness calibration procedure. Performance of **e** below is only required if an out-of-tolerance condition exists in **b** and **d** below or upon initial calibration of wideband option. In both cases paragraphs **a** above and **c** below must be completed prior to **d** and **e** below in order to establish, or characterize, voltage accuracies at 1 kHz. If an out-of-tolerance condition exists in **c** below, repeat **a** above and **c** below. If an out-of-tolerance condition still exists, a repair action is required.

b. Frequency Accuracy

- (1) Connect wideband output to frequency counter **CHANNEL A** input, using termination and cable supplied with TI. Set TI for a 0 dBm, 10 Hz wideband output.
- (2) Measure output frequency; frequency counter will indicate between 99.99 and 100.01 ms.
- (3) Adjust TI frequency to those listed in table 9. At each frequency setting repeat (2) above. Frequency counter will indicate within the listed limits.
- (4) Press **RESET** pushbutton.

Table 9. Wideband Frequency Accuracy

Test instrument frequency	Frequency counter indication	
	Min	Max
100 Hz	9.999 ms	10.001 ms
300 Hz	299.97 Hz	300.03 Hz
500 Hz	499.95 Hz	500.05 Hz
800 Hz	799.92 Hz	800.08 Hz
900 Hz	899.91 Hz	900.09 Hz
1 kHz	999.9 Hz	1.0001 kHz
1.19 kHz	1.189881 kHz	1.190119 kHz
2.2 MHz	2.19978 MHz	2.20022 MHz
3.5 MHz	3.49965 MHz	3.50035 MHz
3.8 MHz	3.79962 MHz	3.80038 MHz
10 MHz	9.999 MHz	10.001 MHz
20 MHz	19.998 MHz	20.002 MHz
30 MHz	29.997 MHz	30.003 MHz

TB 9-6695-293-50

c. 1 kHz Wideband Accuracy

- (1) Connect equipment as shown in figure 12.




Figure 12. 1 kHz output level.

- (2) Set ac measurement standard as specified in (a) through (g) below:
- (a) Press **INPUT 2** pushbutton.
 - (b) Press **2.2 V RANGE** pushbutton.
 - (c) Press **UTIL MENUS** pushbutton.
 - (d) Select **MEAS CONTROL** soft key.
 - (e) Select **FAST DIGITAL FILTER** mode.
 - (f) Select **MEDIUM RESTART**.

- (g) Press the **DONE** soft key twice to return to measurement mode.
- (3) Set TI for a 2.1 V, 1 kHz wideband output.
- (4) Using output adjustment knob, adjust TI for an ac measurement standard indication of 2.100000 V (± 20 digits).
- (5) Record TI **Error** display indication (in %, including polarity) in table 10. Error will be within the limits specified.
- (6) Set ac measurement standard range display to auto and repeat technique of (3) through (5) above for remaining output levels listed in table 10.

Table 10. Wideband 1 kHz Accuracy

Wideband output level	Error display indication $\pm(\%)$	Limits %
2.1 V (± 20 digits)		.4238
1.0 V (± 10 digits)		.5400
0.3 V (± 3 digits)		.5333
0.1 V (± 10 digits)		.6400
30 mV (± 3 digits)		.6533
10 mV (± 1 digit)		.7800
3 mV (± 1 digit)		.8000
1 mV (± 1 digit)		1.0000

d. Wideband Output Flatness

- (1) Connect equipment as shown in figure 13. Press the **WBND** pushbutton on the ac measurement standard.




Figure 13. Wideband flatness.

(2) Set TI for a 3.0 V, 1 kHz wideband output. When the ac measurement standard indication has settled, press the **SET REF** soft key and set display to indicate **PCT** units.

NOTE

When **SET REF** is engaged the display shows the difference between an applied input and the stored reference, or average of references. The difference can be displayed in units of V (or mV), ppm, percent, or ratio. Once a reference has been established you can cycle through each choice by pressing any of the three softkeys below the display. The display will cycle through **PPM** (power on state), **PCT**, **VOLTS**, and **RATIO**, and displays the equation used in each case.

(3) Set TI to frequencies listed in table 11 for 3.0 V output level. At each frequency, record ac measurement standard error indication $[(V_{in} - Ref)/Ref \text{ indication}]$ in flatness error column of table 11 (include polarity). Flatness error will be within the limits specified; if not, perform e below.

- (4) Press **CLEAR REF WBND** soft key.
- (5) Repeat technique of (2) through (4) above for the remaining output levels listed in table 11.

Table 11. Wideband Output Flatness

Test instrument						
Output frequency	Output level 3.0 V		Output level 1.0 V		Output level 300 mV	
	Flatness error	Limits ± (%)	Flatness error	Limits ± (%)	Flatness error	Limits ± (%)
10 Hz		0.3000	---	---	---	---
30 Hz		0.1000	---	---	---	---
10 kHz		0.1000		0.1000		0.100
120 kHz		0.1000		0.1000		0.100
500 kHz		0.1001		0.1003		0.101
2 MHz		0.1001		0.1003		0.101
5 MHz		0.2001		0.2003		0.201
10 MHz		0.2001		0.2003		0.201
20 MHz		0.4001		0.4003		0.401
30 MHz		1.0001		1.0003		1.001

Test Instrument						
Output frequency	Output level 100 mV		Output level 30 mV		Output level 10 mV	
	Flatness error	Limits ± (%)	Flatness error	Limits ± (%)	Flatness error	Limits ± (%)
10 kHz		0.100		0.10		0.10
120 kHz		0.100		0.10		0.10
500 kHz		0.103		0.11		0.13
2 MHz		0.103		0.11		0.13
5 MHz		0.203		0.21		0.23
10 MHz		0.203		0.21		0.23
20 MHz		0.403		0.41		0.43
30 MHz		1.003		1.01		1.03

Test instrument				
Output frequency	Output level 3 mV		Output level 1 mV	
	Flatness error	Limits ± (%)	Flatness error	Limits ± (%)
10 Hz		0.10		0.10
120 kHz		0.10		0.10
500 kHz		0.20		0.50
2 MHz		0.20		0.50
5 MHz		0.40		0.70
10 MHz		0.40		0.70
20 MHz		0.60		0.90
30 MHz		1.60		3.00

e. Wideband Flatness Calibration

NOTE

Paragraphs **b** through **d** above comprise the verification test for the wideband option. Paragraph **e** below is the flatness calibration procedure. Performance of **e** below is only required if an out-of-tolerance condition exists in **b** and **d** above or upon initial calibration of wideband option. In both cases paragraphs **a** and **c** above must be completed prior to **e** below in order to establish, or characterize, voltage accuracies at 1 kHz (**c** above must be in tolerance prior to performing **e** below).

- (1) Connect equipment as shown in figure 13.
- (2) Set rear panel **CALIBRATION NORMAL/ENABLE** switch to **ENABLE**.
- (3) Press the **WBND** pushbutton on the ac measurement standard.
- (4) Call up the TI wideband flatness calibration routine by pressing the soft key sequence **SETUP MENUS**, **CAL**, **CAL** (again) and **WIDEBAND FLAT**.
- (5) Enter the present ambient air temperature as prompted and press **ENTER**; press **ENTER** again.
- (6) Press **OPERATE** pushbutton. Wideband flatness calibration starts with a nominal 3 V at 1 kHz output. If TI displayed value is not 3.00000 V, use output adjustment knob to enter this value. When this is completed, the **Error** indication should indicate 0.0 ppm.
- (7) When the ac measurement standard settles to a reading, press the **SET REF** soft key. (This is the 3 V reference value from which all 3 V frequencies will be compared.)
- (8) Press **ENTER** pushbutton; the frequency will advance to the next value.
- (9) Adjust the TI output adjustment knob to bring the ac measurement standard error display to indicate 0 PPM (± 30 PPM); then press **ENTER** pushbutton.
- (10) Repeat (9) above for each frequency displayed through 30 MHz.
- (11) Press the **CLEAR REF WBND** soft key on the ac measurement standard. The TI wideband output should nominally be 1 V, 1 kHz. If TI displayed value is not 1.00000 V, use output adjustment knob to enter this value. When this is completed, the **Error** indication should indicate 0.0 ppm.
- (12) When the ac measurement standard settles to a reading, press the **SET REF** soft key. (This is the 1 V reference value from which all 1 V frequencies will be compared.)
- (13) Press **ENTER** pushbutton; the frequency will advance to the next value.

(14) Adjust the TI output adjustment knob to bring the ac measurement standard error display to indicate 0 PPM (± 10 PPM); then press **ENTER** pushbutton.

(15) Repeat (14) above for each frequency displayed through 30 MHz.

(16) Press the **CLEAR REF WBND** soft key on the ac measurement standard. The TI wideband output should nominally be 300 mV, 1 kHz. If TI displayed value is not 300.000 mV, use output adjustment knob to enter this value. When this is completed, the **Error** indication should indicate 0.0 ppm.

(17) When the ac measurement standard settles to a reading, press the **SET REF** soft key. (This is the 300 mV reference value from which all 300 mV frequencies will be compared.)

(18) Press **ENTER** pushbutton, the frequency will advance to the next value.

(19) Adjust the TI output adjustment knob to bring the ac measurement standard **Error** display to indicate 0 PPM (± 30 PPM), then press **ENTER** pushbutton.

(20) Repeat (19) above for each frequency displayed through 30 MHz.

(21) Press the **CLEAR REF WBND** soft key on the ac measurement standard. The TI wideband output should nominally be 100 mV, 1 kHz. If TI displayed value is not 100.000 mV, use output adjustment knob to enter this value. When this is completed, the **Error** indication should indicate 0.0 ppm.

(22) When the ac measurement standard settles to a reading, press the **SET REF** soft key. (This is the 100 mV reference value from which all 100 mV frequencies will be compared.)

(23) Press **ENTER** pushbutton; the frequency will advance to the next value.

(24) Adjust the TI output adjustment knob to bring the ac measurement standard **Error** display to indicate 0 PPM (± 10 PPM), then press **ENTER** pushbutton.

(25) Repeat (24) above for each frequency displayed through 30 MHz. Only the 10 MHz, 20 MHz and 30 MHz points are adjusted.

(26) Press the **CLEAR REF WBND** soft key on the ac measurement standard. The TI wideband output should nominally be 30 mV, 1 kHz. If TI displayed value is not 30.0000 mV, use output adjustment knob to enter this value. When this is completed, the **Error** indication should indicate 0.0 ppm.

(27) When the ac measurement standard settles to a reading, press the **SET REF** soft key. (This is the 30 mV reference value from which all 30 mV frequencies will be compared.)

(28) Press **ENTER** pushbutton; the frequency will advance to the next value.

(29) Adjust the TI output adjustment knob to bring the ac measurement standard error display to indicate 0 PPM (± 30 PPM); then press **ENTER** pushbutton.

TB 9-6695-293-50

(30) Repeat (29) above for each frequency displayed through 30 MHz.

(31) Press the **CLEAR REF WBND** soft key on the ac measurement standard. The TI wideband output should nominally be 10 mV, 1 kHz. If TI displayed value is not 10.0000 mV, use output adjustment knob to enter this value. When this is completed, the **Error** indication should indicate 0.0 ppm.

(32) When the ac measurement standard settles to a reading, press the **SET REF** soft key. (This is the 10 mV reference value from which all 10 mV frequencies will be compared.)

(33) Press **ENTER** pushbutton, the frequency will advance to the next value.

(34) Adjust the TI output adjustment knob to bring the ac measurement standard error display to indicate 0 PPM (± 10 PPM), then press **ENTER** pushbutton.

(35) Repeat (34) above for each frequency displayed through 30 MHz. Only the 10 MHz, 20 MHz, and 30 MHz points are adjusted.

(36) Ensure that rear panel **CALIBRATION NORMAL/ENABLE** switch is in the **ENABLE** position. Store the values by pressing the **STORE VALUES** soft key.

(37) Press the **DONE WITH CAL** soft key.

(38) When TI display returns to normal, set rear panel **CALIBRATION NORMAL/ENABLE** switch to **NORMAL**.

(39) Press **RESET** pushbutton.

(40) Repeat (or perform initially) paragraphs **a** through **e** above.

15. Final Procedure

- a.** Deenergize and disconnect all equipment.
- b.** Annotate and affix DA label/form in accordance with TB 750-25.

**SECTION IV
CALIBRATION PROCESS FOR
AMPLIFIER, JOHN FLUKE, MODEL 5725A/()**

16. Preliminary Instructions

a. The instructions outlined in paragraphs **16** and **17** are preparatory to the calibration process. Personnel should become familiar with the entire bulletin before beginning the calibration.

b. Items of equipment used in this procedure are referenced within the text by common name as listed in table 2.

c. Unless otherwise specified, verify the results of each test and, whenever the test requirement is not met, take corrective action before continuing with the calibration. Additional maintenance information is contained in the manufacturer's manual for this TI.

d. Unless otherwise specified, all controls and control settings refer to the calibrator connected to the TI.

17. Equipment Setup

WARNING

HIGH VOLTAGE is used or exposed during the performance of this calibration. DEATH ON CONTACT may result if personnel fail to observe safety precautions. REDUCE OUTPUT(S) to a minimum after each step within the performance check where applicable.

NOTE

Instructions which refer to the John Fluke, Model 5700A/() also pertain to John Fluke, Model 5720A/().

a. Connect TI to calibrator, John Fluke, Model 5700A/(). The calibrator does not necessarily have to be the one normally used with the TI.

b. Connect TI and calibrator to a 115 V ac source.

c. Set TI and calibrator power switches to **ON** and allow 30 minutes warmup.

18. Artifact Calibration 5725A/()

a. If TI is being calibrated in conjunction with a 5700A/() calibrator, the artifact calibration should have already been performed; therefore, proceed to paragraph **19** below.

b. If TI is being calibrated separately, perform paragraph **8** above (Artifact Calibration) prior to proceeding to paragraph **19** below.

NOTE

In both cases, the TI will have to be connected to the 5700A and in the **ON** state.

19. High Ac Voltage Verification

a. Connect equipment as shown in figure 14. Press **INPUT 2** pushbutton on ac measurement standard.




Figure 14. High ac voltage accuracy.

b. On the ac measurement standard, press the **UTIL MENUS** pushbutton and then the **MEAS CONTROL** soft key. Set **DIGITAL FILTER MODE** to **FAST** and **RESTART** to **MEDIUM**. Press the **DONE** soft key twice to return to the measurement display.

c. Set ac measurement standard to manual 700 V range.

d. Set the TI for a 300 V, 20 kHz output. Adjust TI output adjustment knob for an indication of 300.000 V (± 1 digit) on the ac measurement standard.

e. Record calibrator **Error** display indication in table 14. Verify that the result is within the limits listed.

f. Repeat technique of **d** and **e** above for the remaining output levels and frequencies listed in table 12. In **d** above, ± 2 digits can be used for output levels of 600 and 1000 V.

Table 12. High Ac Voltage

Test instrument		Measured error (%)	Limits (0 \pm %)
Output level	Frequency		
300 V	20 kHz		0.0185
600 V	50 kHz		0.0618
600 V	100 kHz		0.2375
Set ac measurement standard to 1 kV range			
1000 V	20 kHz		0.0171
1000 V	30 kHz		0.0611
1000 V	40 Hz		0.0094

g. Set TI to **STANDBY**; then press **RESET**.

20. Dc Current Verification

a. Connect equipment as shown in figure 15.




Figure 15. Dc current (5 and 10 A).

TB 9-6695-293-50

- b.** Configure multimeter for most accurate dc voltage measurements.
- c.** Set TI for a +10.0 A dc output.
- d.** Allow approximately 10 minutes for stabilization; then record multimeter indication.
- e.** Calculate measured value by dividing multimeter indication by test report value for standard resistor No. 4. Resulting value will be between 9.99592 and 10.00408 A (4.99772 and 5.00228); if not, perform **b** below.
- f.** Calculate percent of error for only +10 A dc and record for use in paragraph **21c** below.

NOTE

The following formula may be used to calculate percent of error:

$$\frac{\text{Measured Value} \times 100}{\text{Nominal Value}} - 100 = \text{Error (\%)}$$

- g.** Press +/- then **ENTER** pushbutton.
- h.** Repeat technique of **d** and **e** above with a -10.0 A dc output. Resulting value will be between -999592 and -10.00408 A (-4.99772 and -5.00228).
- i.** Repeat technique of **c** through **h** above for 5 A dc, using values in parenthesis.
- j.** Set to **STANDBY**; then press **RESET**.

21. Ac Current Verification

- a.** Connect equipment as shown in figure 16. Press **INPUT 1** pushbutton on ac measurement standard.




Figure 16. Ac current (10 A)

b. Enter the ac-to-dc difference corrections for ac shunt at each frequency in the appropriate column of table 13.

Table 13. Ac Current

Test instrument output		Ac measurement standard error display	Ac shunt ac-to dc difference	Calculated error (±%)	Error limits (±%)
Current	Frequency				
10.0 A	1.0 kHz				0.0477
10.0 A	40 Hz				0.0477
10.0 A	5 kHz				0.0988
10.0 A	10 kHz				0.3675

c. Set TI for a 10 A dc output. Adjust output adjustment control for an **Error** display equal to the previously recorded calculated error for + 10 A as recorded in paragraph 20f.

d. Press **NEW REF** pushbutton.

e. Allow at least 30 minutes for shunt stabilization. When the reading has settled, press **SET REF** soft key on ac measurement standard and set display to indicate PCT units.

NOTE

The 30 minute stabilization may only be required for the first measurement. Afterwards allow at least 2 to 5 minutes after each TI output frequency change before noting TI or ac measurement standard indication.

NOTE

When **SET REF** is engaged the display shows the difference between an applied input and the stored reference, or average of references. The difference can be displayed in units of V (or mV), ppm, percent, or ratio. Once a reference has been established you can cycle through each choice by pressing any of the three softkeys below the display. The display will cycle through **PPM** (power on state), **PCT**, **VOLTS**, and **RATIO**, and displays the equation used in each case.

f. Set TI for 10.0 A, 1.0 kHz ac output. Record ac measurement standard displayed error indication in appropriate column of table 13.

g. Return to error corrected +10.0 A dc output that was set in c above and verify that the ac measurement standard error display returns to a zero reading ± 0.0010 PCT within 1 to 3 minutes; if not, set a new reference on ac measurement standard by pressing **CLEAR REF INPUT 1** soft key, then press **SET REF** softkey. Repeat f above.

h. Algebraically add the ac measurement standard error indication recorded in f above to the test reported ac-to-dc difference of the ac shunt. The result will be within the limits specified.

i. Repeat technique of f and g above for remaining frequencies listed in table 13. At each frequency, record the ac measurement standard error indication. Algebraically add the resulting error indication to the associated test reported ac-to-dc difference of the ac shunt. The result will be within the limits specified.

22. Final Procedure

a. Deenergize and disconnect all equipment.

b. Annotate and affix DA label/form in accordance with TB 750-25.

SECTION V
CALIBRATION PROCESS FOR
POWER AMPLIFIER, JOHN FLUKE, MODEL 5215A/CT

23. Preliminary Instructions

a. The instructions outlined in paragraphs **23** and **24** are preparatory to the calibration process. Personnel should become familiar with the entire bulletin before beginning the calibration.

b. Items of equipment used in this procedure are referenced within the text by common name as listed in table 2.

c. Unless otherwise specified, verify the results of each test and, whenever the test requirement is not met, take corrective action before continuing with the calibration. Adjustments required to calibrate the TI are included in this procedure. Additional maintenance information is contained in the manufacturer's manual for this TI.

d. Unless otherwise specified, all controls and control settings refer to the TI.

24. Equipment Setup**WARNING**

HIGH VOLTAGE is used or exposed during the performance of this calibration. DEATH ON CONTACT may result if personnel fail to observe safety precautions. REDUCE OUTPUT(S) to minimum after each step within the performance check where applicable.

NOTE

Instructions which refer to the John Fluke, Model 5700A/() also pertain to John Fluke, Model 5720A/().

NOTE

When indications specified in paragraph **25** are not within tolerance, perform the power supply check in paragraph **26** prior to making adjustments. After adjustments are made, repeat paragraph **25**. Do not perform power supply check if all other parameters are within tolerance.

a. Remove protective cover on TI, as required, for making adjustments.

b. Connect TI to calibrator, John Fluke, Model 5700A/CT. The calibrator should be the one normally used with the TI and should have been recently calibrated.

c. Connect TI and calibrator to a 115 V ac source.

25. High Ac Voltage

a. Performance Check

(1) Connect equipment as shown in figure 17. Press **INPUT 2** pushbutton on ac measurement standard.




Figure 17. High voltage.

NOTE

Ensure that **OUTPUT LOW** and (chassis ground) terminal connecting strap is securely in place on TI.

(2) Set both TI and calibrator **POWER** switches to **ON**. Allow at least 1 hour for equipment to warmup and stabilize.

NOTE

The operation of the TI is controlled by the calibrator. The TI controls referred to in the remainder of this check are located on the calibrator.

(3) On the ac measurement standard, press the **UTIL MENUS** pushbutton and then the **Meas Control** soft key. Set **DIGITAL FILTER MODE** to **FAST** and **RESTART** to **MEDIUM**. Press the **DONE** soft key twice to return to the measurement display.

(4) Set for a 1000 V, 1 kHz output and press **BOOST** to enable TI output. Adjust TI output adjustment knob for an indication of 1000.000 V (± 2 digits) on the ac measurement standard.

(5) Record calibrator **Error** display indication in table 14. Verify that the result is within the limits listed, if not perform **b(1)** below.

(6) Set for a 600 V, 100 kHz output. Adjust TI output adjustment knob for an indication of 600.000 V (± 2 digits) on the ac measurement standard.

(7) Record calibrator **Error** display indication in table 14. Verify that the result is within the limits listed, if not perform **b(2)** below.

(8) Repeat technique of (6) and (7) above for the remaining output levels and frequencies listed in table 14.

Table 14. High Ac Voltage

Test instrument		Measured error (%)	Limits (0 \pm %)
Output level	Frequency		
1000 V	1.0 kHz		0.0420
600 V	100 kHz		0.2000
600 V	50 kHz		0.0883
1000 V	20 kHz		0.0420
1000 V	40 Hz		0.0500
1000 V	20 Hz		0.1250

(9) Set to **STANDBY**; then press **RESET**.

b. Adjustments

(1) Adjust R9, LF GAIN (fig. 18) for TI measured output between 0.99990 and 1.00010 kV. (R)

(2) Adjust C14, HF GAIN (fig. 18) for TI measured output between 0.99990 and 1.00010 kV. (R)




Figure 18. Power amplifier – adjustment locations.

26. Power Supply

a. Performance Check

NOTE

Do not perform power supply check if other parameter is within tolerance.

(1) Connect digital multimeter between TP11 +15V and TP19 GND (fig. 18). If digital multimeter does not indicate between 14.95 and 15.05 V, perform **b** below.

(2) Connect digital multimeter between TP12 -15V and TP19 GND (fig. 18). Digital multimeter will indicate between -14.65 and -15.35 V.

b. Adjustments. Adjust R82 +15V (fig. 18) for a digital multimeter indication between +14.95 and 15.05 V dc. (R)

27. Final Procedure

- a. Deenergize and disconnect all equipment.
- b. Annotate and affix DA label/form in accordance with TB 750-25.

SECTION VI
CALIBRATION PROCESS FOR
TRANSCONDUCTANCE AMPLIFIER
JOHN FLUKE, MODEL 5220A/CT

28. Preliminary Instructions

a. The instructions outlined in paragraphs **28** and **29** are preparatory to the calibration process. Personnel should become familiar with the entire bulletin before beginning the calibration.

b. Items of equipment used in this procedure are referenced within the text by common name as listed in table 2.

c. Unless otherwise specified, verify the results of each test and, whenever the test requirement is not met, take corrective action before continuing with the calibration. Adjustments required to calibrate the TI are included in this procedure. Additional maintenance information is contained in the manufacturer's manual for this TI.

d. Unless otherwise specified, all controls and control settings refer to the TI.

29. Equipment Setup

WARNING

HIGH VOLTAGE is used or exposed during the performance of this calibration. DEATH ON CONTACT may result if personnel fail to observe safety precautions. REDUCE OUTPUT(s) to minimum after each step within the performance check where applicable.

NOTE

Instructions which refer to the John Fluke, Model 5700A/() also pertain to John Fluke, Model 5720A/().

a. Remove TI protective covers, as required, for adjustments.

b. Connect TI to a 115 V ac source.

c. Connect equipment as shown in figure 19, except do not connect calibrator to TI at this point.




Figure 19. Dc current.

- d. Set TI and calibrator **POWER** switches to **ON** and allow at least 30 minutes before proceeding.
- e. Configure multimeter for most accurate dc voltage measurements.
- f. Ensure TI is in **STBY** mode; multimeter will indicate $0 \pm 1 \mu\text{V}$.
- g. Connect a short jumper wire between the front **VOLTAGE INPUT HI** and **LO** terminals.
- h. Set to **OPR** mode. Multimeter will indicate $0 \pm 100 \mu\text{V}$ dc; if not, adjust R6 on the A5 preamplifier PCB assembly (fig. 20).
- i. Set to **STBY** mode and remove jumper **VOLTAGE INPUT** terminals.
- j. Set TI and calibrator **POWER** switches to **OFF**.
- k. Connect TI to calibrator, John Fluke, Model 5700A/CT. The calibrator should be the one normally used with the TI and should have been recently calibrated.
- l. Set TI and calibrator **POWER** switches to **ON** and allow sufficient time to restabilize.




Figure 20. John Fluke, Model 5220A/CT - board location.

NOTE

The operation of the TI is controlled by the calibrator. The TI controls referred to in the remainder of this check are located on the calibrator.

30. Dc Accuracy and Line Regulation

a. Performance Check

- (1) Replace standard resistor No. 3 (.1Ω) with standard resistor No. 4 (.01Ω).
- (2) Set TI for a +10.0 A dc output.

TB 9-6695-293-50

(3) Allow approximately 10 minutes for stabilization; then record multimeter indication.

(4) Calculate output current by dividing multimeter indication by test report value for standard resistor No. 4. Resulting value will be between 9.996 and 10.004 A (4.9975 and 5.0025); if not, perform **b** below.

(5) Press +/- then **ENTER** pushbuttons.

(6) Repeat technique of (3) and (4) above with a -10.0 A dc output. Resulting value will be between -9.996 and -10.004 A (-4.9975 and -5.0025).

(7) Repeat technique of (2) through (6) above for 5 A dc, using values in parenthesis.

(8) Replace standard resistor No. 4 (.01 Ω) with standard resistor No. 5 (.001 Ω).

(9) Set TI for a +20.0 A dc output.

(10) Repeat technique of (3) and (4) above for 20 A. Calculated value will be between 19.987 and 20.013 A.

(11) Set to **STANDBY**.

b. Adjustments. Adjust R3 on the A5 preamplifier assembly (fig. 19) for an indication on the multimeter that is 10 times the test report value of standard resistor No. 4 ± 0.002 mV (multimeter indication). For example, if the test report value is 0.0100253 Ω , adjust R3 for a multimeter indication of 0.100253 V dc ± 0.002 mV dc. (R)

31. Frequency Response

a. Performance Check

(1) Connect equipment as shown in figure 21. Press **INPUT 1** pushbutton on ac measurement standard.




Figure 21. Frequency response.

- (2) Enter the ac-to-dc difference corrections for ac shunt at each frequency in the appropriate column of table 15.
- (3) Set TI for a 10 A dc output.
- (4) Allow 30 minutes for ac shunt to stabilize.

NOTE

The 30 minute stabilization may only be required for the first measurement. Afterwards allow at least 2 to 5 minutes after each TI output frequency change before noting TI or ac measurement standard indication.

NOTE

When **SET REF** is engaged the display shows the difference between an applied input and the stored reference, or average of references. The difference can be displayed in units of V (or mV), ppm, percent, or ratio. Once a reference has been established you can cycle through each choice by pressing any of the three softkeys below the display. The display will cycle through **PPM** (power on state), **PCT**, **VOLTS**, and **RATIO**, and displays the equation used in each case.

- (5) Set TI for 10.0 A, 1.0 kHz ac output. Record ac measurement standard displayed **Error** indication in appropriate column of table 15.

TB 9-6695-293-50

(6) Return to +10.0 A dc output. Verify that the ac measurement standard **Error** display returns to a zero reading ± 0.0010 PCT within 1 to 3 minutes; if not, set a new reference on ac measurement standard by pressing **CLEAR REF. INPUT 1** soft key, then press **SET REF** soft key. Repeat (5) above.

(7) Algebraically add the ac measurement standard **Error** indication recorded in 5 above to the test reported ac-to-dc difference of the ac shunt. The result will be within the limits specified; if not, perform **b.** below.

(8) Repeat technique of (5) and (6) above for remaining frequencies listed in table 15. At each frequency record the ac measurement standard **Error** indication. Algebraically add the resulting error indication to the associated test reported ac-to-dc difference of the ac shunt. The result will be within the limits specified; if not, perform **b** below.

Table 15. Ac Current

Test instrument output		Ac measurement standard Error display	Ac shunt ac-dc difference	Calculated error (\pm %)	Error limits (\pm %)
Current	Frequency				
10.0 A	1.0 kHz				0.16
10.0 A	20 Hz				0.16
10.0 A	5 kHz				0.17

b. Adjustments

(1) Set TI to **STANDBY**; then set TI for a 10 A, 1 kHz output.

(2) Allow 3 minutes for stabilization; set a new reference on ac measurement standard by pressing **CLEAR REF. INPUT 1** soft key, then press **SET REF** soft key.

(3) Change TI output frequency to 5 kHz; wait 1 minute, then adjust C4 on A5 PREAMPLIFIER PCB (fig.20) for a zero (± 0.010 PCT) **Error** indication on ac measurement standard. (R)

32. Final Procedure

a. Deenergize and disconnect all equipment.

b. Annotate and affix DA label/form in accordance with TB 750-25.

By Order of the Secretary of the Army:

Official:



JOEL B. HUDSON
*Administrative Assistant to the
Secretary of the Army*

0322301

PETER J. SCHOOMAKER

*General, United States Army
Chief of Staff*

Distribution:

To be distributed in accordance with STD IDS No. RLC-1500, 2 January 2003, requirements for calibration procedure TB 9-6695-293-50.

Instructions for Submitting an Electronic 2028

The following format must be used if submitting an electronic 2028. The subject line must be exactly the same and all fields must be included; however, only the following fields are mandatory: 1, 3, 4, 5, 6, 7, 8, 9, 10, 13, 15, 16, 17, and 27.

From: "Whomever" whomever@redstone.army.milT
To: <2028@redstone.army.mil

Subject: DA Form 2028

1. **From:** Joe Smith
2. **Unit:** home
3. **Address:** 4300 Park
4. **City:** Hometown
5. **St:** MO
6. **Zip:** 77777
7. **Date Sent:** 19-OCT -93
8. **Pub no:** 55-2840-229-23
9. **Pub Title:** TM
10. **Publication Date:** 04-JUL-85
11. **Change Number:** 7
12. **Submitter Rank:** MSG
13. **Submitter FName:** Joe
14. **Submitter MName:** T
15. **Submitter LName:** Smith
16. **Submitter Phone:** 123-123-1234
17. **Problem:** 1
18. **Page:** 2
19. **Paragraph:** 3
20. **Line:** 4
21. **NSN:** 5
22. **Reference:** 6
23. **Figure:** 7
24. **Table:** 8
25. **Item:** 9
26. **Total:** 123
27. **Text**

This is the text for the problem below line 27.

