

# \*SB 11-641

## DEPARTMENT OF THE ARMY SUPPLY BULLETIN

---

### REPAIR AND RETURN PROCEDURES UNDER RELIABILITY IMPROVEMENT WARRANTY (RIW) FOR RADIO RECEIVING SETS AN/ARN-123 (V) 1 (NSN 5826-01-016-2762), AN/ARN-123 (V) 3 (NSN 5826-01-058-6800), AND AN/ARN-123 (V) 4 (NSN 5826-01-070-4067) AND R-1963/ARN, RECEIVER, RADIO (NSN 5826-01-015-1574)

---

Headquarters, Department of the Army, Washington, DC  
21 November 1980

---

	Paragraph	Page
General .....	1	1
References .....	2	2
Background .....	3	2
Concept .....	4	2
Scope .....	5	3
Procedures .....	6	3
Queries .....	7	13

**1. General:** *a. Purpose.* This Supply Bulletin (SB) provides the basic Repair and Return (R&R) concept (with property accountability retained by the user, by item type, not necessarily by serial number), and also furnishes instruction for the return for repair of subject equipment under warranty. It further provides Army Field Commanders, other services and authorized contract facilities involved with Army aircraft with the

method of disposition, handling and accounting under the Reliability Improvement Warranty (RIW).

*b. Comments Relating to This Publication.* Any queries concerning the general content of this bulletin should be directed to the Commander, U.S. Army Communications and Electronics Materiel Readiness Command, ATTN: DRSEL-MMO-R, Fort Monmouth, NJ 07703. Specific queries concerning the technical,

---

\* This Supply Bulletin supersedes SB 11-641, dated 20 May 1977.

maintenance, transportation, supply and/or reliability warranty aspects of this program should be directed to those addresses listed in paragraph 7.

- 2. References:** *a.* Contract DAAB07-75-C-0853 with Bendix Corporation, Avionics Division, 2100 N.W. 62nd Street, Ft. Lauderdale, Florida 33310
- b.* Equipment Technical Manuals
- (1) AN/ARN-123(V) TM 11-5826-258-24  
TM 11-582&258-20P
- (2) R-1963/ARN TM 11-5826-257-24
- c.* TM 38-750 The Army Maintenance Management System (TAMMS).
- d.* AR 725-50 Requisition and Issue of Supplies and Equipment, Requisitioning Receipt and Issue System.
- e.* AR 710-3 Asset and Transaction Reporting System.
- AR 700-58 Packaging Improvement Report.
- AR 340-3 Official Mail.
- SB 38-100 Preservation, Packaging, Packing and Marking Materials, Supplies and Equipment Used by the Army.

**3. Background:** *a.* The AN/ARN-123(V), Receiving Set, Radio, when installed in Army aircraft (both fixed and rotary wing) equipped with appropriate instrumentation will provide manual and automatic Very High Frequency Omrange (VOR) bearing, Localizer (LOC), Glideslope (GS) and Marker Beacon (MB) position information for enroute and terminal navigation and Instrument Landing Systems (ILS) approach and landing.

*b.* The R-1963/ARN, Receiver, Radio, will provide glideslope and marker beacon information during ILS approach and landing. When interfaced with an updated AN/ARN-82/VOR-LOC, Receiver a complete VOR-ILS system will be constituted.

*c.* AN/ARN-123(V), Receiving Set, Radio, has three configurations utilized by the Army. Their components are as follows:

- (1) AN/ARN-123(V) is comprised of a C-10048, Control, R-2023, Receiver and MT-4834, Mount.
- (2) AN/ARN-123(V)3, is comprised of a C-10048, Control, R-2023, Receiver and MT-4980, Mount.
- (3) AN/ARN-123(V)4 is comprised of a C-10048, Control, R-2139, Receiver and MT-4834, Mount.

*d.* Radio Receivers AN/ARN-123(V) and R-1963/ARN were procured by US Army CERCOM with a **4-year Reliability Improvement Warranty (RIW)** from the manufacturer, Bendix Corporation, Avionics Division, Ft. Lauderdale, Florida. A subsequent **2-year RIW extension** has been contractually added to each receiver for an overall **6-year RIW** total. The warranty provides that the manufacturer repair, overhaul or replace, as required, any radio set or component as listed during the six year period.

**NOTE**

The AN/ARN-123(V)2 is used exclusively by the U.S. Coast Guard.

*e.* During the life of the warranty period, there is to be no repair of these items within Army Maintenance channels, AVUM, AVIM, Depot or by any facilities other than those of the manufacturer.

*f.* **THE EQUIPMENT WILL CONTAIN APPROPRIATE SEALS WHICH MUST NOT BE BROKEN OR TAMPERED WITH IN ORDER TO COMPLY WITH WARRANTY CONDITIONS OF THE CONTRACT.**

*g.* The return to the contractor of receivers found to be operating satisfactorily by both the contractor and Government DCASMA personnel at the contractor's plant will, under the provisions of the RIW, subject the Government to monetary penalties. To avoid such penalties, failures must be carefully checked in accordance with the TM, prior to return to the contractor.

*h.* The RIW maintenance philosophy uses a direct interface between the user's maintenance organization (i.e., usually the aviation unit maintenance (AVUM) or aviation intermediate maintenance (AVIM)) and the equipment manufacturer's repair facility. This means that the user's maintenance organization receives, processes and returns the failed unit to the manufacturer. Shipment of the replacement/repaired unit will be made direct to the evacuating maintenance unit. Multiple handling of serviceable/unserviceable equipment between intermediate organizations is to be avoided to eliminate long handling and processing times.

*i.* Reliability Improvement Warranty (RIW) effectiveness is based upon quick processing of failed equipments to and from the contractor's repair facilities.

*j.* Aircraft utilizing AN/ARN-123(V)1, (V)3, (V)4 and R-1963/ARN through the new production or retrofit installation route are:

<i>A/C type</i>	<i>AN/ARN-123</i>	<i>R-1963/ARN</i>
-----------------	-------------------	-------------------

	(V)1	(V)3	(V)4
AH-1S		x	
CH-47C/D	x		
OH-58C	x		
T-42	x		
U-8F	x		
UH-60			x
UH-1	x		x
CH-54			x
OV-1/RV-1			x
U-21/RU-21			x
UH-1V			x

*k.* Aviation units receiving aircraft with the new subject equipment may requisition float as authorized.

**4. Concept:** *a.* Equipment furnished under the Reliability Improvement Warranty (RIW) will be free

from defects in materiel, workmanship, and design and will operate in its intended environment in accordance with the specifications of the contract for a period of 6 years. THE EQUIPMENT WILL CONTAIN APPROPRIATE SEALS WHICH MUST NOT BE BROKEN OR TAMPERED WITH IN ORDER TO COMPLY WITH WARRANTY CONDITIONS OF THE CONTRACT. It should be noted that all items returned for repair to the contractor will undergo a joint inspection at the contractor's plant by both a government and a contractor representative. If this inspection discloses broken seals or the radio receiver, control, or mounting have been tampered with, or undergone willful mistreatment, such units will not be repaired under the contract warranty. These units will be repaired under a separate maintenance contract with the manufacturer.

b. Under the contract terms of the warranty, the contractors shall not be obligated for the repair of any radio receivers under this warranty if failure of nonconformance is caused by fire, explosion, submersion, aircraft crash, enemy action, natural disaster, and/or accidental or willful mistreatment. However, receivers damaged or requiring repair because of the aforementioned causes, are still required to be returned to the contractor for final inspection, evaluation and disposition. It should be noted that items returned in the above categories which are found to void the warranty will still be evaluated for repair under a separate contract with the manufacturer.

c. Warranty and contract terms contain monetary penalty conditions to the government involving the return of radio receivers found to be operating satisfactorily by the contractor and Government Product Assurance personnel upon inspection at the plant. Evacuating activities of radio receivers should therefore follow the applicable procedures involving the tests prescribed in TM's at the respective support levels to assure that a receiver is not functioning as required before returning equipment for repair. Penalty charges of \$100.00 per radio set will be charged to the government when no verified failure of the equipment occurs. Based on this fact, using units must ensure that, prior to return of equipment for warranty, all prescribed tests performed verify that an unserviceable unit exists.

**5. Scope:** These instructions provide Army field commanders, other services and authorized contract facilities (including airframe manufacturers and commercial airframe overhaul facilities) involved with Army aircraft, with the method of disposition, handling and accounting, under the Reliability Improvement Warranty (RIW).

**6. Procedures:** a. *Equipment under Warranty:* Items authorized for Repair and Return under Contract DAAB07-75-C-0853 are identified as follows:

NSN	NOMENCLATURE	TYPE NO
5826-01-020-2263	Control, Receiver	C-10048/ARN-123(V)
5826-01-020-2258	Receiver, Radio	R-2023/ARN-123(V)
5826-01-070-4065	Receiver, Radio	R-2139/ARN-123(V)
5826-01-020-2266	Mounting Base, Electrical Equipment	MT-4834/ARN-123(V)
5826-01-058-7717	Mounting Base, Electrical Equipment	MT-4980/ARN-123(V)
5826-01-015-1574	Receiver, Radio	R-1963/ARN
5826-01-022-9257	Mounting Base, Electrical Equipment	MT-4835/ARN

*b. Materiel Flow:*

(1) A general repair and return warranty flow diagram for AN/ARN-123(V)( ), Receiving Set, Radio, and R-1963/ARN, Receiver, Radio, is shown in figure 1.

(2) As indicated in paragraph a above, those components requiring repair will be returned directly to the contractor, addressed and marked as follows:

Bendix Corporation  
 Avionics Division  
 2100 N.W. 62nd Street  
 Ft. Lauderdale, Florida 33310  
 ATTN: CONUS Repair Service Administrator  
 Reliability Improvement Warranty  
 M/F: Contract DAAB07-75-C-0853

**NOTE**

Using activities *should not requisition replacements* for those components returned for Repair and Return under this equipment warranty program.

c. *AVUM Procedures.* Using technical manual procedures, AVUM will verify that a Line Replaceable Unit (LRU) has failed. The LRU will be removed from the aircraft; DA Form 2407 prepared, logbook entries made, and the Installation/Removal Data Label affixed to the LRU will be filled out. The LRU will be taken to AVIM and exchanged for a good LRU. AVUM will then fill in the information on the Installation/Removal Data Label on the replacement unit, install the LRU in the aircraft; and make the appropriate entries in the aircraft logbook.

d. *A VIM Procedures.* AVIM will verify that the LRU brought by AVUM has failed using TM procedures. AVIM will then give AVUM a good LRU from stock and package the failed LRU in the same packaging that has been used to store the spare LRU. AVIM will prepare a DD Form 1348-1 with *MILSTRIP* docu-




Figure 1. Repair and Warranty Flow Receiving Set, Radio AN/ARN-123(V)( ) and Receiver, Radio R-1963/ARN.

ment number, perform stock record accounting, mail the failed LRU to the contractor's plant. AVIM will prepare DD Form 173/2 (OCR), Joint Message Form and assure that it is properly transmitted by the message center to the contractor with information copies as required. Upon receipt of a LRU from the contractor's plant, AVIM will inspect and test the LRU, store the LRU in the shipping packaging, and perform stock record accounting.

*e. Accountability.* Accountability for equipment returned for repair/replacement for the AN/ARN-123(V), Receiving Set, Radio and R-1963/ARN, Receiver, Radio components will be the responsibility of the user (returnee) until receipt at the contractor's repair facility at which time accountability will be assumed by the Defense Contracting Administration Services Management Area (DCASMA) Administrative Contracting Officer (ACO) for Contract DAAB07-75-C-0853.

*j. Documentation.* All activities that return any AN/ARN-123(V) or R-1963/ARN component for warranty repair are required to prepare a message, electrical, which must contain the following minimal information to assure expedited replacement/return of the unserviceable component. See figure 2 for typical example.

1. *POINT-OF-CONTACT AND TELEPHONE NUMBER* (Specify Autovon or Commercial).
2. *COMPONENT, SERIAL NUMBER, NATIONAL STOCK NUMBER.*
3. *AIRCRAFT TYPE AND TAIL NUMBER.*
4. *FAILURE INDICATION.*
5. *DATE INSTALLED.*
6. *DATE REMOVED.*
7. *USPS MAIL RETURN RECEIPT NUMBER.*
8. *MILSTRIP DOCUMENT NUMBER.*
9. *DA FORM 2407 CONTROL NUMBER.*
10. *REPAIRED EQUIPMENT SHIP TO ADDRESS (WITH ATTENTION LINE).*

**NOTE**

Failure to provide complete data in the message will cause delay in forwarding a replacement component. Omitted data will have to be obtained from the returning activity before replacement.

- (1) Message will be sent to:

Bendix Corp.  
Avionics Division  
2100 NW 62nd St.  
Ft. Lauderdale, Florida 33310  
ATTN: CONUS Repair Service Administrator  
Reliability Improvement Warranty

- (2) Information Copies to:

- (a) DCASMA, Bendix Avionics, Ft. Lauderdale, Fla.  
(b) CDR CERCOM, Ft. Monmouth, NJ.  
ATTN: DRSEL-MME-AN  
(c) CDRAVRADA, Ft. Monmouth, NJ. ATTN:

DAVAA-P

(3) Army activities returning components for warranty repair are to complete the following blocks only of the DA Form 2407, Maintenance Request (see fig. 3).

(a) Heading-Enter a "X" in Warranty space.

(b) Blocks 1 through 15—complete as prescribed in TM 38-750, paragraph 3-8 c.

(c) Block 16—State in clear terms the following facts concerning the item identified in block 3:

1. Date the item became inoperable.

2. Indicate aircraft type and tail number in which failure occurred/or other.

3. An opinion as to the cause of the failure.

4. Identification of the performance test which the item failed; i.e., the test which confirmed the item to be unserviceable and the basis for which the item is being returned to the manufacturer for repair.

5. The statement that the "Installation/Removal Data label has been filled out."

(d) Block 30-Enter the complete in-the-clear address of where the item is to be shipped after repair.

(e) DA Form 2407 distribution shall be as follows:

1. Receipt Copy #1-Place with the failed component being returned to the contractor for warranty repair.

2. NMP Copy #2-Mail to the following address:

Commander  
US Army CERCOM  
ATTN: DRSEL-ME-EW  
Fort Monmouth, NJ 07703

*j* Another copies (#3 through #5) will be disposed of as prescribed by the local command.

(4) SF 368, Quality Deficiency Report is used when a failure occurs at an Army depot or prime contractor supplied with Government Furnished Avionics Equipment (GFAE) that is under the RIW concept. SF 368 Form is used in lieu of the DA Form 2407.

(a) Complete the SF 368 Form in accordance with DSA REG. NO. 4155.24(AR 702-7), Reporting of Quality Deficiency Data.

(b) Mandatory entries required:

1. Item 13—Equipment Operating Hours.

2. Item 16—Fill in acft type and tail no.

3. Item 19—YES Block.

4. Item 21—Released for Investigation.

5. Item 22—In addition to details describing the problem, the following statements must be included in block 22 "Installation/Removal Data Label has been filled in, and "FOR INFORMATION ONLY-RELIABILITY IMPROVEMENT WARRANTY".

(c) Attach copy to the equipment being returned to the manufacturer.

(d) Failed items should be returned immediately to the manufacturer. Normal conditions call for withholding disposition, pending receipt of disposition instructions from the Product Assurance Directorate

MESSAGE EXAMPLE

FROM: 11 AVN BN HANAU GER //                    / /  
TO: 510-955-9884 BENDIX AVIONICS/ FT. LAUDERDALE/ FL //  
CONUS RIW ADMINISTRATOR  
INFO: CDR CERCOM FT. MONMOUTH, NJ // DRSEL-MME-AN //  
CDRAVRADA FT. MONMOUTH, NJ // DAVAA-P //  
510-955-9884 DCASMA, FT. LAUDERDALE, FL //  
BENDIX QAR

UNCLAS

SUBJ NOTICE OF AN/ARN-123 (OR R-1963/ARN) FAILURE,  
CONTR DAAB007-75-C-0853Z REQUEST REPLACEMENT OR  
REPAIR OF FOLLOWING COMPONENT:

1. CW3 SMITH/ AUTOVON 314-555-1234
2. R-2023/ARN-123(V)z SER #152Az USN 5826-01-020-2258
3. AH-1S 76-22602
4. UNIT DISPLAYS ERRATIC VOR BEARING OUTPUT
5. INSTALLED 15 FEB 79
6. REMOVED 1 NOV 79
7. US POSTAL SYSTEM INSURED RETURN RECEIPT NO 323
8. WK4K6A 9338 01 05
9. DA FORM 2407 CONTROL #654321
10. // AVN BN, ATTN: AVIONICS, APO NEW YORK 09165

EL7PK002

Figure 2. Sample Electrically Transmitted Message.

PAGE <b>1</b> OF <b>1</b> PAGES		MAINTENANCE REQUEST For use of this form, see TM 38-750. The proponent agency is DCSLOG.				REQUIREMENT CONTROL SYMBOL CSGLD-1047 (RI)	
SECTION I - GENERAL DATA							
<input type="checkbox"/> WORK REQUEST		<input type="checkbox"/> MWO		<input checked="" type="checkbox"/> WARRANTY		ORGANIZATION ISSUE PRIORITY DESIGNATOR CODE	
CONTROL NUMBER <b>010436</b>	14. ORGANIZATION <b>E CO., 227<sup>TH</sup> AVN BN</b>			15. LOCATION <b>FT. HOOD, TX 76545</b>		16. UNIT IDENTIFICATION CODE <b>WH6BEO</b>	
SERIAL NUMBER <b>327A</b>	1. NOUN NOMENCLATURE <b>RCVR</b>	4. LINE NUMBER <b>AH-1S</b>	5. MODEL <b>R-2023</b>	6. NATIONAL STOCK NUMBER <b>5826-01-020-2258</b>			
7. STRAC <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		8. UTILIZATION CODE <b>DN</b>	9. SELECTED ITEM <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		10. HOURS <b>857</b>	11. MILES	12. ROUNDS
12. FAILURE DETECTED DURING (Select one - use / or X) <input type="checkbox"/> SCHEDULED <input type="checkbox"/> MAINTENANCE <input type="checkbox"/> HANDLING <input type="checkbox"/> TEST		13. NORMAL OPERATION <input type="checkbox"/> OPERATION <input type="checkbox"/> STORAGE <input type="checkbox"/> INSPECTION			14. FLIGHT <input checked="" type="checkbox"/> FLIGHT <input type="checkbox"/> OTHER		
15. FIRST INDICATION OF TROUBLE (Select one - use / or X) <input checked="" type="checkbox"/> 068 INOPERATIVE				<input type="checkbox"/> 258 OVERHEATING		<input type="checkbox"/> 790 OUT OF ADJUST.	
<input type="checkbox"/> 008 NOISY				<input type="checkbox"/> 387 LOW PERFORMANCE		<input type="checkbox"/> OTHER	
16. DESCRIBE DEFICIENCIES OR SYMPTOMS ON THE BASIS OF COMPLETE CHECKOUT AND DIAGNOSTIC PROCEDURE IN EQUIPMENT TM (Do not abbreviate responses) <b>WARRANTY CLAIM ACTION</b>							
<b>DATE ITEM FAILED: 9252 : AIRCRAFT AH-1S 75-00356</b>							
<b>INTERMITTENT OPERATION IN VOR MODE ON CH 108.60 :</b>							
<b>CONFIRMED BY BENCH TEST PER TM II</b>							
<b>INSTALLATION/REMOVAL DATA LABEL FILLED OUT</b>							
SECTION II - WORK ACCOMPLISHED							
17. REPAIR ORGANIZATION/ACTIVITY			18. UNIT IDEN CODE		19. TYPE ORGANIZATION/ACTIVITY ACCOMPLISHING WORK (Select one - use / or X) <input type="checkbox"/> 1 TOE <input type="checkbox"/> 2 TD <input type="checkbox"/> 3 CONTRACTOR		19. AMS ACT. CODE
20. LOCATION			20a. Action Code		20b. Failure Code		20c. COMPONENT/PART NOUN, SERVICE, OR MWO NO. 20d. CB Code
20e. Reference Designator			20f. MFR Code		20g. Manhours (hours & tenths)		20h. National Stock Number
20i. Part Source Code			20j. Quantity		20k. Parts Cost		20l. Parts Cost
21. TOTAL MANHOURS				21. TOTAL MANHOURS COST		21. TOTAL PARTS COST	
22. DELAY (Select one - use / or X) <input checked="" type="checkbox"/> 1 PARTS <input type="checkbox"/> 2 MANPOWER <input type="checkbox"/> 3 FACILITIES <input type="checkbox"/> 4 FUNDS <input type="checkbox"/> 5 TOOLS				23. DATA TRANSCRIBED TO LOG BOOK <input type="checkbox"/>			
24. RECEIVED BY <b>PEB</b>		25. WORK STARTED BY		26. INSPECTED BY		27. ACCEPTED BY	
28. JULIAN DATE <b>9254</b>		28. JULIAN DATE		28. JULIAN DATE		28. JULIAN DATE	
29. NORMAL REPLACEMENT (Select one - use / or X) <input type="checkbox"/> 1 YES <input type="checkbox"/> 2 NO				30. DISPOSITION (Select one - use / or X) <input type="checkbox"/> A To Unit <input type="checkbox"/> C Salvaged <input type="checkbox"/> M To Stock <input type="checkbox"/> D Evaluated <input type="checkbox"/> F Cannibaliz.			
30. REMARKS <b>COMMANDER E CO., 227<sup>TH</sup> AVN BN 1<sup>ST</sup> CAV DIV ATTN: AVIONICS FT HOOD, TX 76545</b>							

DA FORM 2407  
1 JUL 79

EDITION OF 1 OCT 73 WILL BE USED UNTIL EXHAUSTED.

EL7PK003

Figure 3. Sample DA Form 2407

CERCOM; however, for these warranties immediate return to the contractor is authorized.

(5) *Installation/Removal Data Label/Instruction Decal* is affixed to the R-2023 and R-2139/ARN-123(V), Receivers, Radio, C-10048/ARN-123(V), Control, Receiver and R-1963/ARN, Receiver, Radio. The Installation/Removal Data label shall be completed legibly by the returning activity using a ball point pen. The label is shown in Figure 4.

g. *Receipt, Return, Unpacking, Packaging and Packing:*

(1) *Packing and unpacking.*


(a) *Packaging data.* The AN/ARN-123(V), Receiving Set, Radio, R-1963/ARN, Receiver, Radio and mounts are individually packaged in separate weather-resistant corrugated fiberboard cartons with all seams and joints sealed with water-resistant pressure sensitive tape. Each item is inclosed within a sealed plastic bag and cushioned within the carton with preformed plastic molding material. A typical packaging configuration with contents is shown in Figures 5 and 6. The approximate exterior dimensions of the equipment and boxes are provided in tables I and II (fig. 7).

INSTALLATION DATA						FOR CONTRACTOR USE	
	A/C TYPE	A/C NO.	DATE & TIME TOTALIZING METER				ONLY Code
			IN A/C	TTM	OUT A/C	TTM	
1	AH-1S	75-00356	10 DEC 75	68	9 SEP 79	857	
2							
3							
4							
5							
6							

EL7PK004


Figure 4. Installation/Removal Data Label.





EL7PK005

Figure 5. Interface Conversion Group Packaging Diagram for Receiving Set, Radio AN/A RN-123(V).



EL7PK006

Figure 6. Interface Conversion Group Packaging Diagram for Receiver, Radio R-1963/ARN.

TABLE I	RECEIVING SET, RADIO AN/ARN-123(V)1		PACKAGING DATA	
COMPONENT	ITEM NET DIM (IN)	CARTON SIZE (IN) (ID)	VOLUME (CU FT)	WEIGHT (LB)
C-10048/ARN-123(V)1 Control, Receiver	5.13 X 5.75 X 2.625	9.75 X 6.62 X 12.25	0.46	4.00
R-2023/ARN-123(V) or R-2139/ARN-123(V) Receiver, Radio	11.93 X 4.12 X 7.18	11.25 X 8.12 X 17	0.89	12.00
MT-4834/ARN-123(V) Mounting Base, Electrical Equipment	13.62 X 4.38 X 2.25	17-1/8 X 9-3/4 X 4-1/8	0.40	2.00
Consolidation Box		17-3/4 X 11-5/8 X 18-1/2	2.20	19.00
Wooden Box		17-7/8 X 11-3/4 X 18-5/8	2.98	32.00
MT-4980/ARN-123(V) Mounting Base, Electrical Equipment	13.62 X 7.06 X 1.17	17-1/8 X 11-5/8 X 2-5/8	0.35	2.00

TABLE II	RECEIVER, RADIO R-1963/ARN AND MOUNTING BASE, ELECTRICAL EQUIPMENT		PACKAGING DATA	
COMPONENT	ITEM NET DIM (IN)	CARTON SIZE (IN) (ID)	VOLUME (CU FT)	WEIGHT (LB)
R-1963/ARN Receiver, Radio	8.43 X 3.56 X 4.06	8 X 8 X 12	0.44	6.00
MT-4835/ARN Mounting Base, Electrical Equipment	9.87 X 3.84 X 2.25	12-3/8 X 8 X 2-5/8	0.15	2.00
Consolidation Box		12-7/8 X 8-1/2 X 11-5/8	0.74	9.00
Wooden Box		13 X 8-5/8 X 11-3/4	1.13	16.00

EL7PK007

Figure 7. Packaging Data (Tables I and II).

(b) *Unpacking instructions.* Unpack the radio set or the receiver in the same manner. Pry off the wooden box cover. Remove each individual box from the consolidation container. Open the component boxes; use care when removing the items so as not to damage the components or the cartons, plastic bag or the internal dunnage. *Do not dispose of the packaging materials.*

**NOTE**

The containers utilized for the following components are 10 TRIP REUSABLE CONTAINERS, designed with specially preformed plastic molded inserts. These containers shall be retained for use in repackaging and shipping between the government and contractor's overhaul facility.

R-2023/ARN-123(V), Receiver, Radio

R-2139/ARN-123(V), Receiver, Radio

C-10048/ARN-123(V), Control, Receiver

MT-4834/ARN-123(V), Mounting Base, Electrical Equipment

R-1963/ARN, Receiver, Radio

MT-4835/ARN, Mounting Base, Electrical Equipment

MT-4980/ARN, Mounting Base, Electrical Equipment.

(2) *Checking unpacked equipment.*

(a) Inspect the equipment for damage that may have occurred during shipment. If the equipment has been damaged, or packaging deficiencies are discovered, fill out and forward Standard Form 364 (AR 735-1 1-2).

(b) Check to see that the equipment is complete as listed on the packing slip. If the packing slip is not available, check the equipment against the items listed in tables I and II (fig. 7).

(3) *Repacking.*

(a) Repackage the equipment using the reverse procedure shown in subparagraph g(1) above and figures 5 and 6. If the original packaging materials are not available for use, package the equipment in the following manner:

(b) Place each item within a plastic bag fabricated of material conforming to L-P-378. Wrap the item in cellulosic cushioning material conforming to PPP-C-843, type II, a minimum of 6 inches on all surfaces and secure the wrap with tape conforming to PPP-T-76. Place the cushioned item within a close fitting fiberboard box conforming to PPP-B-636, W5c, and seal all seams and joints with tape conforming to PPP-T-76.

(c) When individual components are being shipped, the packaged item shall be overpacked within a close-fitting box,

(d) When more than one item or set is being shipped, a quantity of the package items shall be overpacked within a close-fitting box.

(e) Substitute packaging materials may be selected from those items listed in SB 38-100.

(4) *Shipment markings for return of warranty repair items.* The packed radio sets or individual items shall be addressed to the contractor marked as follows:

Bendix Corporation

Avionics Division

2100 N.W. 62nd Street

Ft. Lauderdale, Florida 33310

ATTN: CONUS Repair Service Administrator

Reliability Improvement Warranty

M/F: Contract DAAB-07-75-C-0853

*h. Transportation.*

(1) *The transportation costs for the shipments of failed equipment to the contractor's plant or repair facility are to be borne by the user or shipping activity.*

(2) Special procedures for activities returning defective equipment are as follows:

(a) Materiel will be shipped to the contractor's plant for repair and returned in accordance with those procedures contained in the equipment technical manual (TM), along with the documentation prescribed therein.

(b) Equipment returned to the contractor's plant will contain only those items covered under this contract and listed in 6a above.

(c) All Army and other DOD activities returning AN/ARN-123(V) or R-1963/ARN components for warranty repair will complete a DD Form 1348-1 as required by AR 725-50 (Requisitioning, Receipt, and Issue System).

(d) *All items are to be shipped by insured priority mail with return receipt requested.* In addition to the priority mail markings the parcels should also be marked "Fourth Class Mail Enclosed". Authorization for the above exception to AR 340-3 has been granted for RIW items by Director, Postal Directorate, HQDA. The Authorization is contained in DAAG-MAP (1 Jul 77) 3rd Endorsement subject: Request for Exception to Permit the Use of Certified Mail and Return Receipts when Mailing MILSTRIP Parcels dated 11 April 1978. All failed units are to be shipped back to the contractor as soon as they are packaged and all accompanying documents are completed. All shipments must be insured up to the limit of their value or permissible maximum allowed by the USPS (not to exceed the shipment value).

(e) All materiel for repair and return is to be shipped to the address listed in g(4) above. The address is to be clearly identifiable on the outside of the shipping container and all accompanying shipping documents.

(f) *Activities returning equipment for repair (RIW) shall also indicate their complete in-the-clear address where the equipment is to be shipped after repair. This in-the-clear address shall be included on DA Form 2407, block 30. Failure to include the return address will delay equipment returns to users.*

(g) All Air Frame Contractors and other authorized DOD commercial repair facilities returning

system components for warranty will *complete a DD Form 1149 as required by DOD 4160.21-M, Defense Disposal Manual* (formerly AR 755-20).

**NOTE**

Although shipment will be accomplished through use of one or the other documents listed above (DD Form 1348-1 or DD Form 1149), accountability for equipment returned for repair/replacement will be the responsibility of the USER (returnee) until receipt at the Contractor Repair Facility. Accountability will then be assumed by the Defense Contracting Administration Service Management Area (DCASMA) Administration Contracting Office (ACO), for contract DAABO07-75-C-0853.

(h) Distribution of DD Form 1348-1 or DD Form 1149 is as follows:

1. One copy accompanying the equipment returned to the contractor, addressed to:

Bendix Corporation  
Avionics Division  
2100 N.W. 62nd St.  
Ft. Lauderdale, Fla. 33113  
ATTN: CONCUS Repair Service Administrator

2. One copy to the DCASMA ACO, addressed to:

DCASMA  
ATT: DCRA-GOCC-6  
3555 Maguire Blvd.  
Orlando, Fla. 32083

3. One copy addressed to:  
CGUSACERCOM  
ATTN: PCO CONTR DAAB07-75-C-0853  
Fort Monmouth, NJ 07703

(i) If a radio receiver is lost or destroyed, procedures outlined in AR 710-3, Asset and Transaction Reporting System shall be used. Distribution specified in AR 710-3, for the DA Form 3906-R, a duplicate copy will be required to be forwarded for Loss Code 1—Combat Loss, and Loss Code 4—Crash/Accident/Act of God to the following address:

Commander  
US Army CERCOM  
ATTN: DRSEL-MME-AN  
Fort Monmouth, NJ 07703

**NOTE**

This copy is required by the National Inventory Control Point for warranty cost adjustment with the manufacturer.

(j) The equipment technical manuals TM 11-5826-258-24 for the AN/ARN-123(V) and TM 11-5826-257-24 for the R-1963/ARN contain the re-

quired tests to determine if the suspected item is unserviceable.

**7. Queries:** The Reliability Improvement Warranty (RIW) is a new approach for the repair and maintenance of an equipment within the Army inventory. Therefore, the referenced regulations and procedures outlined herein must be complied within order to assure effective and orderly equipment repair and return to users. Any queries concerning the general content of this bulletin (e.g., format) should be directed to the Commander, US Army CERCOM, Materiel Management Directorate, DRSEL-MMO-R, Fort Monmouth, NJ 07703. Specific queries concerning the Technical, Maintenance, Transportation, Supply and/or Warranty Reliability aspects of this program should be direct to those addressees listed below:

<i>INFORMATION REQUIRED</i>	<i>ADDRESS</i>
Technical	Commander US Army AVRADA ATTN: DAVAA-N Fort Monmouth, NJ 07703 Autovon 995-2623 Commercial (201) 544-2623
Maintenance	Commander US Army CERCOM Maintenance Directorate ATTN: DRSEL-ME-EW Fort Monmouth, NJ 07703 Autovon 992-2890
Transportation	Commander US Army CERCOM Materiel Management Directorate ATTN: DRSEL-MM-DD-T Fort Monmouth, NJ 07703 Autovon 992-2234
Supply	Commander US Army CERCOM Materiel Management Directorate ATTN: DRSEL-MME-AN Fort Monmouth, NJ 07703 Autovon 992-1626
Any other area regarding Reliability Improvement Warranties not specifically identified above	Commander US Army CERCOM ATTN: DAVVAA-P Fort Monmouth, NJ 07703 Autovon 995-2844

By Order of the Secretary of the Army:

E. C. MEYER  
*General, United States Army*  
*Chief of Staff*

Official:

J. C. PENNINGTON  
*Major General, United States Army*  
*The Adjutant General*

Distribution:

ACTIVE ARMY, USAR, ARNG: To be distributed in accordance with DA Form 12-31, Operator Maintenance requirements for Section VI, all Fixed and all Rotor Wing Aircraft

☆ U.S. GOVERNMENT PRINTING OFFICE: 1980-703-029/343