


3746 Nways Multiprotocol Controller
Model 950



Service Guide



3746 Nways Multiprotocol Controller
Model 950



Service Guide

Note!

Before using this information and the product it supports, be sure to read the general information under "Notices" on page xv.

Fifth Edition (July 1999)

This edition applies to the 3746 Nways Multiprotocol Controller Model 950.

Order publications through your IBM representative or the IBM branch office serving your locality. Publications are not stocked at the address given below.

A form for readers' comments appears at the back of this publication. If the form has been removed, address your comments to:

Department CGFA
Design & Information Development
IBM Corporation
PO Box 12195
Research Triangle Park NC 27709
U.S.A.

When you send information to IBM, you grant IBM a nonexclusive right to use or distribute the information in any way it believes appropriate without incurring any obligation to you.

© Copyright International Business Machines Corporation 1996, 1999. All rights reserved.

US Government Users Restricted Rights – Use, duplication or disclosure restricted by GSA ADP Schedule Contract with IBM Corp.

Contents

Figures	ix
Tables	xiii
Notices	xv
Electronic Emission Notices	xvi
Industry Canada Class A Emission Compliance Statement	xvi
Avis de conformité aux normes d'Industrie Canada	xvi
European Union (EU) Mark of Conformity Statement	xvi
Japanese Voluntary Control Council for Interference (VCCI) Statement	xvii
Korean Communications Statement	xvii
Taiwanese Class A Warning Statement	xviii
New Zealand Radiocommunications (Radio) Regulations	xviii
Notice to UK Users	xviii
Year 2000 Statement	xviii
Trademarks	xx
General and Product Safety Information	xxi
Service Inspection Safety Procedures	xxi
Safety and Disposal Instructions For Batteries	xxi
Service Inspection Safety Procedures	xxii
Introduction	xxii
Sicherheitsüberprüfungen	xxxii
Einführung	xxxii
Bedeutung der LEDs am Bedienungsfeld des 3746-950	xlii
3746-950 Power Supply CP/CB Reference	liii
Safety Label Locations	liv
3746-950 Safety Label Locations	liv
Safety Label on LCB	lv
3746-950/LCB Safety Label Identifications	lv
Safety Label Part Numbers by Country	lvii
Controller Expansion Label Location	lviii
About This Manual	lix
Aim of this Manual	lix
Who Should Read this Manual	lix
How this Manual Is Organized	lix
Chapter 1. START	1-1
START - How to Begin Troubleshooting	1-1
Console Use for maintenance	1-1
Finding a Service Procedure	1-3
CPN or FRU to Exchange	1-4
Other Symptoms	1-4
Run Diagnostics	1-4
Miscellaneous Informations	1-6
3746-950/Service Processor Windows Overview	1-7
Service Processor Menu Details	1-8
3746-9x0 Menu Details	1-10
Problems During Machine, EC or MES Installation	1-12

Selection Table	1-12
Symptom Index	1-13
General Verbal Symptoms	1-13
3746-950 Control Panel Symptoms	1-14
3746-950 Control Panel Codes	1-15
Using the MIP FRU Group Table	1-24
3746-950 FRU Group Table	1-25
3746-950/Service Processor Maintenance Using a CPN	1-26
3746-950 Maintenance Using an SRC Sequence Number	1-28
3746-950 Maintenance Using a FRU list	1-28
Service Processor Maintenance Using an SRC Sequence Number	1-28
3746-950 FRU List	1-29
MAP: 3746-950 FRU Exchange	1-33
MAP: CBSA Check LED ON	1-35
MAP: Ready and Standby LEDs are OFF	1-36
MAP: Standby LED Blinking	1-39
MAP: Standby LED ON	1-42
MAP: Ready LED Blinking	1-48
MAP: Ready LED ON	1-51
3746-950 FRU list for exchange	1-54
MAP: ARC	1-56
MAP: CBSP/CBSP2/CBSP3	1-61
MAP: CLP/CLP3	1-64
MAP: TIC3 of the CBSP	1-73
MAP: ESCC/ESCC2/ESCP/ESCP2/ESCP3	1-75
MAP: TRP/TRP2/TRP3	1-81
MAP: LCPE	1-84
MAP: LCEE	1-86
MAP: LCPB, LCPE, LCEB, LCEE	1-88
MAP: LIC11	1-91
MAP: LIC12	1-97
MAP: TIC3	1-101
MAP: SIE	1-104
MAP: SPD2	1-107
MAP: 3746-950 SPS, Control Panel	1-111
3746-950 ACPW, DCPW, Transformer	1-113
MAP: 3746-950 in Offline Mode	1-114
MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode	1-120
MAP: 3746-950 Ending Exchange Procedure After Power ON	1-125
MAP: 3746-950 Ending Procedure In Offline Mode	1-126
MAP: 3746-950 Ending Procedure in Concurrent Mode	1-128
MAP: 3746-950 ESCC/ESCC2 Disabling	1-131
MAP: 3746-950 ESCC/ESCC2 Enabling	1-133
MAP: 3746-950 CLP Backup or Standard Mode Setting	1-135
Activate/Deactivate a Resource Via CCM	1-139
3746-950 Setting in Offline Mode	1-142
Display the FRU List After a Diagnostic Failure	1-143
3746-950 EEPROM Upgrade	1-144
EEPROM Upgrade Overview	1-144
EEPROM Upgrade/Downgrade Processing	1-144
Engineering Data Transfer	1-146
Overview	1-146
Preparing Engineering Data on the Local Service Processor	1-146

Transferring Engineering Data from the Service Processor	1-147
3746-950 Diagnostic Requirements	1-148
3746-950 Control Panel Use	1-149
Purpose of the Control Panel	1-149
Explanation of 3746-950 Panel Keys, LEDs and Switches	1-150
3746-950 Control Panel Display Description	1-151
How to Perform 3746-950 Control Panel Operations	1-152
Power ON	1-152
General IML	1-152
CBSA IML	1-152
CBSP Dump	1-152
General IML With Diagnostics	1-152
CBSA IML Without Diagnostics	1-152
Panel Test	1-152
Service Processor Link Restart	1-152
Display Error Code	1-152
Control Panel LED Status Versus 3746-950 States	1-153
IML Request Versus 3746-950 States	1-153
 Chapter 2. MAPs for FRU Isolation	 2-1
3746-950 RSF MAP	2-1
MAP 2000: 3746-950 Manual Call	2-1
3746-950 Power MAPs	2-4
MAP 2500: 3746-950 Power Control Subsystem Problems	2-4
MAP 2510: 3746-950 Power ON Problem in Remote Mode	2-8
MAP 2520: 3746-950 Power ON Problem in Local Mode	2-10
MAP 2530: 3746-950 CP1 Tripped.	2-11
3746-950 -48v DC DISTRIBUTION	2-13
MAP 2540: 3746-950 CP2 or CP3 Tripped	2-14
MAP 2550: 3746-950 CP4, CP5, CP6, or CP7 Tripped	2-16
MAP 2560: 3746-950 Ready LED Blinking.	2-17
3746-950/Service Processor/Network Node Processor MAPs	2-19
MAP 2600: 3746-950/Service Processor/Network Node Processor/Multiaccess Enclosure Link Icons Color Symptom	2-19
MAP 2605: 3746-950 Either CP3, CP4, CP5, CP6, or CP7 is Tripped	2-26
MAP 2610: 3746-950 ESCA, LAN, or CLP Problem	2-29
MAP 2615: 3746-950 Configuration Mismatch	2-31
MAP 2620: 3746-950 Control Panel Problem	2-36
MAP 2625: LAN Checking	2-37
MAP 2630: 3746-950 Service Logic Problem	2-38
3746-950 Service Logic Cabling	2-40
MAP 2635: 3746-950 Several Fans Are in Errors	2-43
MAP 2640: 3746-950 Cable From SPD1 to SPD2	2-45
MAP 2645: 3746-950 Cable From DCDP to SPD1	2-47
MAP 2650: 3746-950 Signal Power cable from SPD1 to the Control Panel	2-48
MAP 2655: 3746-950 Cable From SIE to SAC in Multiaccess Enclosure	2-49
MAP 2660: 3746-950 Intermittent Box Errors	2-51
MAP 2665: 3746 Model 950 Resource Not Present in CDF-E	2-53
MAP 2670: 3746-950 Processor Non-Identified in CDF-E	2-55
MAP 2675: 3746 Model 950 ESCC/TIC3 Non-Identified in CDF-E	2-57
MAP 2680: 3746 Model 950 LIC11/LIC12 Non-Identified in CDF-E	2-61
MAP 2685: 3746-950 LCB Non-Identified in CDF-E	2-73
3746-950 ESCA MAPs	2-78
MAP 2700: 3746-950 Permanent ESCA Problem	2-78

MAP 2710: 3746-950 Any Intermittent ESCA Problem	2-79
MAP 2720: 3746-950 Bit Error Rate Validation	2-80
MAP 2730: 3746-950 ESCA Activation Problem	2-81
3746-950 LAN MAPs	2-84
MAP 2750: 3746-950 Permanent Service Processor Link Problem	2-84
MAP 2760: 3746-950 TRP LAN Problem	2-86
MAP 2770: 3746-950 Duplicate Token Ring Local Address	2-96
3746-950 CLP MAPs	2-97
MAP 2800: 3746-950 All the Lines of CLP Have a Problem	2-97
MAP 2810: 3746-950 Problem on a Group of ARCs	2-100
MAP 2820: 3746-950 Problem on a LIC11	2-105
MAP 2830: 3746-950 Problem on a LIC12	2-117
MAP 2840: 3746-950 CLP Fallback Problem	2-123
MAP 2850: 3746-950 Activate/Deactivate Line Problems or Line Errors on CLP	2-124
MAP 2860: 3746-950 All the Lines of LCBE Have Problem	2-128
Service Processor MAPs	2-133
MAP 2950: LAN Problem on LAN Attached to the Service Processor	2-133
MAP 2960: 3746-950/APPN Link Problem	2-138
 Chapter 3. How to Run Diagnostics	 3-1
3746-950 Diagnostic Description	3-1
3746-950 Concurrent Maintenance	3-13
Concurrent Diagnostics	3-13
Concurrent Repair	3-13
Concurrent Mode Activation Procedure	3-13
How to Run the 3746-950 Control Panel Test	3-14
How to run the 3746-950 Service Processor Link Restart	3-15
MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode	3-16
MAP 2980: How to run 3746-950 Diagnostic in Offline Mode	3-39
MAP 2990: How to Run 3746-950 Specific Diagnostics	3-41
3746-950 Service Logic Cabling	3-44
MAP 3000: How to Run the Selective IML on the Multiaccess Enclosure	3-47
 Chapter 4. 3746-950 FRU Exchange	 4-1
Exchange Precautions	4-1
List of 3746-950 FRUs	4-2
3746-950 FRU Physical Locations	4-3
3746-950 Basic Board Locations	4-4
3746-950 Expansion Board Locations	4-6
3746-950 Front Side Details	4-8
3746-950 Rear Side Details	4-9
Exchange an Air Filter	4-10
Exchange an ACPW	4-11
Exchange an ARC	4-13
Exchange a Board	4-15
Exchange a CBSP/CBSP2/CBSP3	4-16
Exchange the Control Panel	4-18
Exchange a Connectivity Switch	4-19
Exchange a CSCE	4-21
Exchange DCDC of Processor	4-22
Exchange a Connectivity Switch DCDC	4-23
Exchange the Power Distribution DCDP	4-25
Exchange a DCPW	4-27

Exchange an Enclosure (Basic or Expansion)	4-29
Exchange an ESCC/ESCC2	4-31
Exchange a Fan Drawer	4-32
Exchange a Processor Other than the CBSP (CLP/CLP3, ESCP/ESCP2/ESCP3 or TRP/TRP2/TRP3)	4-33
Exchange a LCEE	4-34
Exchange a LCEB	4-36
Exchange a LCPB	4-38
Exchange a LCPE	4-40
Exchange a LIC (Type 11 or 12)	4-42
Exchange an SIE	4-43
Exchange an SPD1	4-44
Exchange an SPD2	4-45
Exchange an SPS	4-46
Exchange a TIC3 associated With the CBSP	4-47
Exchange a TIC3	4-49
Exchange a Transformer	4-50
CE Leaving Procedure	4-53
Appendix A. Maintenance Aids	A-1
Special Tools	A-1
General Purpose Tools	A-1
ESD kit	A-1
Shipping Group Tools	A-2
Service Processor Group Tools	A-2
Controller Expansion Group Tools	A-2
Appendix B. 3746 Model 950 Bibliography	B-1
Customer Documentation for the 3746 Model 950	B-1
Service Documentation for the IBM 3746 Model 950	B-5
Related Signal Converter Products Information	B-8
World Wide Web	B-8
Glossary	X-1

Figures

0-1.	Ground Pin on Mainline ac/dc Power Cable	xxiii
0-2.	Ground Wire Connection Between the Controller Expansion and Attached 3746-950 Frame	xxiv
0-3.	Ground Wire Connection for the 3746-950 and Controller Expansion Located at Less than Six Meters	xxv
0-4.	Ground Wire Connection Between the Controller Expansion and 3745-950 at more than Six Meters	xxvi
0-5.	Ground Pin of the ac Outlet Distribution Box	xxvii
0-6.	LCB Grounding Via Screws	xxviii
0-7.	LCB Grounding Via Ground Wire	xxviii
0-8.	Ground Wire Connection	xxix
0-9.	Schutzleiterkontakt am Hauptnetzkabel	xxxiii
0-10.	Schutzleiteranschluß zwischen Erweiterung der Steuereinheit und angeschlossenem Rahmen des 3746-950	xxxiv
0-11.	Schutzleiteranschluß bei einem Abstand unter 6 Meter zwischen 3746-950 und Erweiterung der Steuereinheit	xxxv
0-12.	Schutzleiteranschluß bei einem Abstand über 6 Meter zwischen 3746-950 und Erweiterung der Steuereinheit	xxxvi
0-13.	Schutzleiterkontakt des Wechselstromverteilerkastens	xxxvii
0-14.	Erdung des Verteilerkastens über Schrauben	xxxviii
0-15.	Erdung des Verteilerkastens über Schutzleiter	xxxviii
0-16.	Schutzleiteranschluß	xxxix
0-17.	3746 Model 950 Label Locations	liv
0-18.	Safety Label Location on LCB	lv
0-19.	3746 Model 950 Safety Labels	lvi
0-20.	LCB Safety Label	lvii
0-21.	Controller Expansion label Locations	lviii
1-1.	Service Processor Configuration Management Functions	1-8
1-2.	Service Processor Problem Management Functions	1-8
1-3.	Service Processor Operation Management Functions	1-8
1-4.	Service Processor Change Management Functions	1-8
1-5.	Service Processor Ethernet Bridge Functions	1-9
1-6.	Service Processor Performance Management Function	1-9
1-7.	Service Processor PE Functions	1-9
1-8.	3746-9x0 Configuration Management Functions	1-10
1-9.	3746-9x0 Problem Management Functions	1-10
1-10.	3746-9x0 Operation Management Functions	1-10
1-11.	3746-9x0 Network Node Processor Management Functions	1-11
1-12.	3746-9x0 MAE Management Functions	1-11
1-13.	3746-9x0 Change Management Functions	1-11
1-14.	3746-9x0 Performance Management Function	1-11
1-15.	3746-9x0 PE Functions	1-11
1-16.	Manage Engineering Data Window	1-146
1-17.	3746-950 Control Panel Layout	1-149
2-1.	TB1 and TB2 Location on Transformer	2-4
2-2.	DCDP and Power Boxes	2-5
2-3.	3746-950 Remote Powering Possibilities	2-8
2-4.	RPO Location 07R-A1	2-9
2-5.	-48 Volts DC Distribution	2-13
2-6.	CP2 Circuit	2-15

2-7.	Stand Alone Service Bus (SASB) Routing with Basic Board Only	2-40
2-8.	Stand Alone Service Bus (SASB) Routing with Expansion Board	2-41
2-9.	Stand Alone Service Bus (SASB) Routing Two Expansion Boards	2-42
2-10.	3746 Model 9x0 TRP LAN	2-86
2-11.	LAN attached to the Service Processor	2-133
2-12.	LAN attached to the Service Processor	2-138
3-1.	Parts of 3746-950 Tested by IML With Diagnostics or Whole 3746-950 Offline Diagnostics	3-7
3-2.	Parts of 3746-950 Tested by CLP SATs	3-8
3-3.	Parts of 3746-950 Tested by LIC11 MAT	3-8
3-4.	Parts of 3746-950 Tested by LIC12 SAT	3-9
3-5.	Parts of 3746-950 Tested by LIC12 MAT	3-9
3-6.	Parts of 3746-950 Tested by LCB SAT1	3-9
3-7.	Parts of 3746-950 Tested by LCB SAT2	3-10
3-8.	Parts of 3746-950 Tested by ARC SAT and ARC MAT	3-10
3-9.	Parts of 3746-950 and MAE Tested by MAE Selective IML	3-11
3-10.	Stand Alone Service Bus (SASB) Routing with Basic Board Only	3-44
3-11.	Stand Alone Service Bus (SASB) Routing with one Expansion Board	3-45
3-12.	Stand Alone Service Bus (SASB) Routing with two Expansion Boards	3-46
4-1.	3746 Model 950	4-3
4-2.	3746 Model 950	4-3
4-3.	Basic Board O7G-A1 Locations (Processor side)	4-4
4-4.	Basic Board O7N-A1 Locations (Coupler side)	4-4
4-5.	Basic board component location	4-5
4-6.	Expansion Board O7D-A1 or O7E-A1 Locations (Processor side)	4-6
4-7.	Expansion Board O7L-A1 or O7M-A1 Locations (Coupler side)	4-6
4-8.	Expansion Board Component Location	4-7
4-9.	3746-950 Front Side	4-8
4-10.	3746-950 Rear Side	4-9
4-11.	3746-950 Air Filter Replacement	4-10
4-12.	Rear of the 3746-950	4-12
4-13.	ARC Assembly Identification	4-13
4-14.	3746 Model 9x0 CBSP Cassette	4-17
4-15.	3746-950 Control Panel Cards	4-18
4-16.	3746-950 Connectivity Switch	4-20
4-17.	3746-950 CSCE Cable Connection to the Connectivity Switch (CS)	4-21
4-18.	3746-950 Processor DC/DC	4-22
4-19.	3746-950 Connectivity Switch and DCDC	4-24
4-20.	3746-950 Power Distribution Box DCDP Front and Rear View	4-26
4-21.	3746-950, Rear of DC Power Box	4-28
4-22.	3746-950 Enclosure Installation	4-30
4-23.	3746-950 ESCC Coupler	4-31
4-24.	3746-950 Cooling Units	4-32
4-25.	3746-950 Fan Drawers Location	4-32
4-26.	3746-950 Cassette Processor	4-33
4-27.	Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)	4-34
4-28.	LCPE into the LCEE	4-35
4-29.	Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)	4-36
4-30.	LCPB into the LCEB	4-37
4-31.	Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)	4-38

4-32.	LCPB into the LCEB	4-39
4-33.	Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)	4-40
4-34.	LCPE into the LCEE	4-41
4-35.	3746-950 LIC11 Coupler	4-42
4-36.	3746-950 LIC12 Coupler	4-42
4-37.	3746-950 SIE Cassette	4-43
4-38.	3746-950 SPD1 Cassette	4-44
4-39.	3746-950 SPD2 Cassette	4-45
4-40.	3746-950 TIC3 Coupler	4-49
4-41.	3746-950 Transformers	4-51
4-42.	3746-950 Transformer Handling	4-52

Tables

0-1.	ac Input Adjustment for the 3746-950	xxx
0-2.	Stromversorgung 3746-950, Überstromschutzschalter und Sicherungsautomaten	xxxix
0-3.	Einstellung des Wechselstromeingangs für den 3746-950	xli
0-4.	Bedeutung der LEDs am Bedienungsfeld des 3746-950	xlii
0-5.	3746-950 Power Supply CP/CB Reference	liii
0-6.	Safety Label Numbers by Country	lvii
1-1.	General Symptoms	1-13
1-2.	Control Panel Symptoms	1-14
1-3.	3746 Model 950 Control Panel Code	1-15
1-4.	3746 Model 950 FRU Group	1-25
1-5.	Panel Display Values	1-151
1-6.	LED Status Versus 3746-950 States	1-153
1-7.	IML Request Versus 3746-950 States	1-153
2-1.	Icons Color Selection Table	2-19
3-1.	3746 Model 950 Diagnostics Available	3-2
B-1.	Customer Documentation for the 3746 Model 950	B-1
B-2.	Service Documentation for the 3746 Model 950	B-5

Notices

References in this publication to IBM products, programs, or services do not imply that IBM intends to make these available in all countries in which IBM operates. Any reference to an IBM product, program, or service is not intended to state or imply that only IBM's product, program, or service may be used. Any functionally equivalent product, program, or service that does not infringe any of IBM's intellectual property rights may be used instead of the IBM product, program, or service. Evaluation and verification of operation in conjunction with other products, except those expressly designated by IBM, are the user's responsibility.

IBM may have patents or pending patent applications covering subject matter in this document. The furnishing of this document does not give you any license to these patents. You can send license inquiries, in writing, to:

IBM Director of Licensing
IBM Corporation
North Castle Drive
Armonk, NY 10504-1785
U.S.A.

For license inquiries regarding double-byte (DBCS) information, contact the IBM Intellectual Property Department in your country or send inquiries, in writing, to:

IBM World Trade Asia Corporation
Licensing
2-31 Roppongi 3-chome, Minato-ku
Tokyo 106, Japan

The following paragraph does not apply to the United Kingdom or any other country where such provisions are inconsistent with local law:

INTERNATIONAL BUSINESS MACHINES CORPORATION PROVIDES THIS PUBLICATION "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Some states do not allow disclaimer of express or implied warranties in certain transactions, therefore, this statement may not apply to you.

This information could include technical inaccuracies or typographical errors. Changes are periodically made to the information herein; these changes will be incorporated in new editions of the publication. IBM may make improvements and/or changes in the product(s) and/or the program(s) described in this publication at any time without notice.

This information is for planning purposes only. The information herein is subject to change before the products described become available.

Electronic Emission Notices

Federal Communications Commission (FCC) Statement

Note: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case the user will be required to correct the interference at his own expense.

Properly shielded and grounded cables and connectors must be used in order to meet FCC emission limits. IBM is not responsible for any radio or television interference caused by using other than recommended cables and connectors or by unauthorized changes or modifications to this equipment. Unauthorized changes or modifications could void the user's authority to operate the equipment.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Industry Canada Class A Emission Compliance Statement

This Class A digital apparatus complies with Canadian ICES-003.

Avis de conformité aux normes d'Industrie Canada

Cet appareil numérique de la classe A est conforme à la norme NMB-003 du Canada.

European Union (EU) Mark of Conformity Statement

This product is in conformity with the protection requirements of EU Council Directive 89/336/EEC on the approximation of the laws of the Member States relating to electromagnetic compatibility. IBM cannot accept responsibility for any failure to satisfy the protection requirements resulting from a non-recommended modification of the product, including the fitting of non-IBM option cards.

This product has been tested and found to comply with the limits for Class A Information Technology Equipment according to CISPR 22/European Standard EN 55022. The limits for Class A equipment were derived for commercial and industrial environments to provide reasonable protection against interference with licensed communication equipment.

Attention: This is a Class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

Zulassungsbescheinigung laut dem Deutschen Gesetz über die elektromagnetische Verträglichkeit von Geräten (EMVG) vom 30. August 1995 (bzw. der EMC EG Richtlinie 89/336).

Dieses Gerät ist berechtigt, in Übereinstimmung mit dem Deutschen EMVG das EG-Konformitätszeichen - CE - zu führen.

Verantwortlich für die Konformitätserklärung nach Paragraph 5 des EMVG ist die IBM Deutschland Informationssysteme GmbH, 70548 Stuttgart.

Informationen in Hinsicht EMVG Paragraph 3 Abs. (2) 2:

Das Gerät erfüllt die Schutzanforderungen nach EN 50082-1 und EN 55022 Klasse A.

EN 55022 Klasse A Geräte müssen mit folgendem Warnhinweis versehen werden:

“Warnung: Dies ist eine Einrichtung der Klasse A. Diese Einrichtung kann im Wohnbereich Funkstörungen verursachen; in diesem Fall kann vom Betreiber verlangt werden, angemessene Maßnahmen durchzuführen und dafür aufzukommen.”

EN 50082-1 Hinweis:

“Wird dieses Gerät in einer industriellen Umgebung betrieben (wie in EN 50082-2 festgelegt), dann kann es dabei eventuell gestört werden. In solch einem Fall ist der Abstand bzw. die Abschirmung zu der industriellen Störquelle zu vergrößern.”

Anmerkung:

Um die Einhaltung des EMVG sicherzustellen, sind die Geräte, wie in den IBM Handbüchern angegeben, zu installieren und zu betreiben.

Japanese Voluntary Control Council for Interference (VCCI) Statement

This product is a Class A Information Technology Equipment and conforms to the standards set by the Voluntary Control Council for Interference by Technology Equipment (VCCI). In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

この装置は、情報処理装置等電波障害自主規制協議会（VCCI）の基準に基づくクラスA情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。

Korean Communications Statement

Please note that this device has been certified for business purpose with regard to electromagnetic interference. If you find this is not suitable for your use, you may exchange it for one of residential use.

A급 기기(업무용)

이 기기는 업무용으로 전자파적합등록을 받은 기기이오니 판매자 또는 이용자는 이점을 주의하시기 바라며, 만약 구입하였을 때에는 구입한 곳에서 가정용으로 교환하시기 바랍니다.

Taiwanese Class A Warning Statement

警告使用者：
這是甲類的資訊產品，在
居住的環境中使用時，可
能會造成射頻干擾，在這
種情況下，使用者會被要
求採取某些適當的對策。

New Zealand Radiocommunications (Radio) Regulations

Attention: This is a Class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

Notice to UK Users

The IBM 3746 Model 900 and IBM 3746 Model 950 are manufactured according to the International Safety Standard IEC950 and, as such, are approved in the UK under the General Approval number NS/G/1234/J/100003.

The Active Remote Couplers (ARCs) and the X.21 Interface, housed within the 3746 Model 900 and 3746 Model 950, are approved separately, each having their own independent approval number. These interface adapters, supplied by IBM, do not contain excessive voltages. An excessive voltage is one which exceeds 42.4 V peak ac or 60 V dc. They interface with the 3746 Model 900 or 3746 Model 950, using Safe Extra Low Voltages only.

In order to maintain the independent approval of the IBM adapters, it is essential that other optional cards, not supplied by IBM, do not use mains voltages or any other excessive voltages. Seek advice from a competent engineer before installing other adapters not supplied by IBM.

Year 2000 Statement

This product is Year 2000 ready. When used in accordance with its associated documentation, it is capable of correctly processing, providing, and/or receiving date data within and between the 20th and 21st centuries, provided all other products (for example, software, hardware, and firmware) used with the product properly exchange accurate date data with it.

For more information, refer to:

<http://www.ibm.com/year2000>

The 3745 and 3746 controllers require a certain level of microcode to be Year 2000 ready. For more detailed information, access the URL listed above and click **Product Readiness**.

Trademarks

The following terms are trademarks of International Business Machines Corporation in the United States, or other countries, or both:

AIX
APPN
ESCON
IBM

Nways
OS/2
RETAIN
VTAM

NetView and Tivoli are trademarks of Tivoli Systems, Inc. in the United States, or other countries, or both.

Java and all Java-based trademarks and logos are trademarks or registered trademarks of Sun Microsystems, Inc. in the United States and/or other countries.

Microsoft, Windows, Windows NT, and the Windows logo are trademarks or registered trademarks of Microsoft Corporation.

Pentium is a registered trademark of Intel Corporation in the U.S. and other countries.

UNIX is a registered trademark in the United States and other countries licensed exclusively through X/Open Company Limited.

Other company, product, and service names may be trademarks or service marks of others.

General and Product Safety Information

This product meets IBM safety standards.

For more information, see the following manual:

3745 Communication Controller All Models
3746 Nways Multiprotocol Controller Models 900 and 950
Safety Information, GA33-0400.

Service Inspection Safety Procedures

Service Inspection Safety Procedures - English
Sicherheitsüberprüfungen - Deutsch
服务检查安全程序—简体中文版

xxii
xxxii
xlii

Safety and Disposal Instructions For Batteries

When disposing of the batteries, follow procedures in accordance with your national or local regulations for recycling the materials. If no regulation of this kind exists, return the batteries to your equipment seller or to IBM.

Service Inspection Safety Procedures

Introduction

A safety inspection procedure for the 3746-9x0 and controller expansion should be performed:

- When it is inspected for an IBM agreement
- When IBM service is requested and no service has recently been performed by IBM
- When an alterations and attachments review is performed
- When changes have been made to the equipment that might affect its safety.

If the inspection indicates unacceptable safety conditions, the conditions must be corrected before IBM services the machine.

Note: The correction of any unsafe condition is the responsibility of the owner of the equipment.

The 3746-950 and controller expansion areas and functions checked through these procedures are:

1. External covers
2. Safety labels
3. Safety covers and shields
4. Grounding (earthing)
5. Circuit breaker and protector rating
6. Input power voltage
7. Power control switch
8. Power ON indicator.

Note: The 3746-950 is set in **Ready** state or in **Standby** state through:

- The service processor
- A host
- Locally.

Hazardous voltages are still present in some areas of the 3746-950 when it is in **Ready** state or **Standby** state.

Steps 1 through 6 must be performed after **power OFF**, as follows:

- **CB1s are switched OFF** on the 3746-950.
- **All the equipment installed in the controller expansion is powered OFF.**
- **Power supplies for the 3746-950 and controller expansion at the customer's premises are switched OFF.**

Do not remove the power cords and ground wire **A** on the 3746-950 and controller expansion in order to maintain the ground protection (see Figure 0-2 on page xxiv, Figure 0-3 on page xxv, or Figure 0-4 on page xxvi).

1 External Covers

Check that:

- They are all present on the 3746-950 and on the controller expansion.
- They can be fully opened.
- Appropriate service clearance and access are provided around the frames with external covers opened.

Leave all external covers opened to allow further safety inspection steps.

2 Safety Labels

Check that each safety label corresponds to the letter as shown in the “3746-950/LCB Safety Label Identifications” on page lv.

3 Safety Covers and Shields

Referring to the FRU location (Chapter 4), check that:

- All the safety covers are present and secured with screws.
- All the voltage terminal boards (TBs) are protected by a plastic shield screwed on top of the TB.

4 Grounding (Earthing)

Note

In this manual, "ground" means that the equipment must be connected to the earth.

a Grounding of the 3746-950 and Controller Expansion to the Premises Grounding System

Electrical continuity is assured between the 3746-950, the controller expansion frame ground and the premises grounding system, through their power cords and ground wire **A**.

On the 3746-950 and Controller Expansion

- Check the mainline ac/dc power cable for damaged or burned pins and broken insulation.
- Measure the resistance of the disconnected mainline ac/dc power cable from the ground pin on one end to the ground pin on the other end.

The measurement should be 0.1 ohm or less.




Figure 0-1. Ground Pin on Mainline ac/dc Power Cable

- Check the presence of ground wire **A** according to your configuration (see Figure 0-2 on page xxiv, Figure 0-3 on page xxv, or Figure 0-4 on page xxvi).




Figure 0-2. Ground Wire Connection Between the Controller Expansion and Attached 3746-950 Frame




Figure 0-3. Ground Wire Connection for the 3746-950 and Controller Expansion Located at Less than Six Meters




Figure 0-4. Ground Wire Connection Between the Controller Expansion and 3745-950 at more than Six Meters

Notes:

- 1) **A** Ground wire (PN 58G5691)
- 2) **B** Screw (PN 61F4513), star washer (PN 1622347 or PN 17G5853), and lock washer (PN 1622319)
- 3) **C** Screw (PN 61F4511), star washer (PN 17G5852), and lock washer (PN 1622318).

b Internal Grounding in the 3746-950 and Controller Expansion

In the 3746-950

Check that electrical continuity is assured between the LCB housing and 3746-950 frame, if LCBs are present. This operation must be performed before any network connection.

In the Controller Expansion

- Check that electrical continuity is assured between each equipment installed in the controller expansion (service processor, network node processor, modem, optical disk drive) and the ground pin of the ac outlet distribution box (see Figure 0-5).
- Check that electrical continuity is assured between the ground pin of the ac outlet distribution box and the controller expansion mount frame.




Figure 0-5. Ground Pin of the ac Outlet Distribution Box

- Check that electrical continuity is assured between the LCB housing and the controller expansion frame, if LCBs are present. This operation must be performed before any network connection (see Figure 0-6 on page xxviii).

Note: All the previous checking should indicate 0.1 ohm or less.

C Grounding of Line Connection Boxes (LCBs) not Installed in the 3746-950 or Controller Expansion

Check that electrical continuity is assured between the LCB housing and the premises grounding system.

There are two ways to ensure proper grounding of the LCB, according to where it is installed:

- 1) Grounding is ensured by the four screws (which secure the LCB on the rack) if the frame of the rack is connected to the premises ground system.




Figure 0-6. LCB Grounding Via Screws

2) Grounding is ensured by a wire connected from the LCB to the premises ground system.




Figure 0-7. LCB Grounding Via Ground Wire

IBM does not provide this wire. In order to ensure correct grounding, this ground wire must be made using an AWG 12 wire (minimum 2.5 square millimeters).

Screw: Diameter: 5 mm

Length: 6 to 10 mm (refer to Figure 0-8 on page xxix).

Connection of Ground Wire to LCB




Figure 0-8. Ground Wire Connection

This operation must be performed before any network connection.

Note: All the previous checking should indicate 0.1 ohm or less.

d Building Grounding

- Check that there is less than 1 V ac between the metal housings of plugs, connectors, receptacles, and so on, and any grounded point in the building. This can be any grounded metal structure, such as the stanchions of a raised floor (if they are electrically connected to the building ground), a metal water pipe, building steel, and so on.

Notes:

- 1) When probing a painted metal part, be sure that the meter probe tip penetrates the paint.
- 2) Also, check the plugs metal housing of incoming cables.

5 Circuit Breaker and Protector Rating

Refer to Table 0-5 on page liii for CB and CP locations.

Check that:

- All CBs and CPs in the 3746-950 are rated at the indicated values in Table 0-5 on page liii. If the rating is not indicated, check the part number against the parts catalog.
- The fuses in the controller expansion ac outlet distribution box must be 7 A, 250 V slow (PN 58G5782).

6 Input Power Voltage

- a** On the **3746-950**, the power rating plate indicates the voltage range available (200/220/240) and the frequency (50/60 Hz).

Check that the power rating plate of the 3746-950 is consistent with the frequency and the voltage measured at the customer's power supply. If not, inform your branch office. Refer to "3746-950/LCB Safety Label Identifications" on page Iv for power rating plate location.

dc Input Voltage

For dc input, the customer's voltage must be within -40.0 V to -60.0 V. There is **no adjustment** for the optional dc input.

ac Input Voltage

Safety

For ac input, the customer's voltage must be within 180 V to 240 V.

Adjustment of the input voltage can be done according to the customer voltage on the TB1 of the transformer(s) located at the rear of the 3746-950.

- b** On the **controller expansion**, the power rating plate of the ac outlet distribution box indicates the voltage range available (200 to 240) and the frequency (50/60 Hz).

Check that the power rating plate of the ac outlet box (of the controller expansion) is consistent with the frequency and the voltage measured at the customer's power supply. If not, inform your branch office. Refer to "Controller Expansion Label Location" on page Iviii for the power rating plate location.

Table 0-1. ac Input Adjustment for the 3746-950		
Measured Voltage	Wire Position	Nominal Voltage
From 180 to 210 Volts	TB1-2	200/208 Volts
From 210 to 230 Volts	TB1-3	220 Volts
From 230 to 260 Volts	TB1-4	240 Volts

Important Note:

Since the 3746-950 can be remotely powered ON, all the following procedures must be performed with the 3746-950 Control Panel set to **local mode**.

7 Test of the Power Control Switch on the 3746-950

- Ask the customer to connect the power cord to the customer's mains supply
- Set the CB1(s) ON
- Power the 3746-950 ON (power control function to Local on the control panel).
- Operate the power control switch to the position (⏻) and check that:
 - The 3746-950 is powered OFF.
 - All the fans are stopped.

Note

When the power control switch is set to the position (⏻), the primary powers (ACDC) or filter sections (DCDC) stay energized.

For total disconnection:

- Turn the CBs OFF.
- Remove all the power plugs from supply outlets or shutdown the installation.

8 Power ON Indicator on the 3746-950

Set the power control switch to ON and check that the Standby LED (on the 3746-950 control panel) is lit according to the table shown in "Bedeutung der LEDs am Bedienungsfeld des 3746-950" on page xlii.

Once the Standby LED is permanently ON, press the Start key on the 3746-950 control panel, check that the Ready LED (on the 3746-950 control panel) is lit according to the table shown in “Control Panel LED Status Versus 3746-950 States” on page 1-153.

Sicherheitsüberprüfungen

Einführung

Die Sicherheit des 3746-950 und der Erweiterung der Steuereinheit sollte in folgenden Fällen überprüft werden:

- Bei einer Prüfung nach Absprache mit IBM
- Wenn eine IBM Wartungsleistung angefordert wird, und in der letzten Zeit keine Wartung durch IBM durchgeführt worden war.
- Wenn Änderungen am Gerät oder Anschlüsse überprüft werden.
- Wenn Änderungen am Gerät vorgenommen worden sind, die möglicherweise die Sicherheit beeinträchtigen.

Wenn bei der Überprüfung ein unzureichender Sicherheitszustand festgestellt wird, müssen die Mängel behoben werden, bevor IBM das Gerät wartet.

Note: Für die Behebung von Sicherheitsmängeln ist der Besitzer des Geräts verantwortlich.

Folgende Bereiche und Funktionen des 3746-950 und der Erweiterung der Steuereinheit werden im folgenden geprüft:

1. Äußere Abdeckungen
2. Sicherheitsaufkleber
3. Sicherheitsabdeckungen und Abschirmungen
4. Erdung
5. Sicherungsautomat und Überstromschutzschalter
6. Netzeingangsspannung
7. Netzkontrollschalter
8. Betriebsanzeige

Note: Der 3746-950 wird durch folgendes in den **Betriebsstatus** oder **Bereitschaftsstatus** versetzt:

- Serviceprozessor
- Host
- lokal.

In einigen Bereichen des 3746-950 liegt eine **gefährliche Spannung** an, während sich das Gerät im **Betriebsstatus** oder im **Bereitschaftsstatus** befindet.

Nach dem **Ausschalten** müssen die Schritte 1 bis 6 folgendermaßen durchgeführt werden:

- Am 3746-950 die **Sicherungsautomaten CB1 öffnen**.
- **Alle im Einschub der Erweiterung der Steuereinheit installierten Geräte ausschalten**.
- **Stromversorgungen für den 3746-950 und die Erweiterung der Steuereinheit beim Kunden ausschalten**.

Netzkabel und Schutzleiter **A** am 3746-950 und an der Erweiterung der Steuereinheit nicht entfernen, damit die Erdung gewährleistet ist (siehe Figure 0-10 on page xxxiv, Figure 0-11 on page xxxv oder Figure 0-12 on page xxxvi).

1 Äußere Abdeckungen

Prüfen, ob

- alle äußeren Abdeckungen am 3746-950 und an der Erweiterung der Steuereinheit angebracht sind.

- sie vollständig geöffnet werden können.
- die Einschübe genügend Raum und Zugänge für Wartungsarbeiten haben, wenn die äußeren Abdeckungen geöffnet sind.

Alle äußeren Abdeckungen für weitere Überprüfungen offen lassen.

2 Sicherheitsaufkleber

Prüfen, ob jeder Sicherheitsaufkleber dem jeweiligen Buchstaben entspricht, wie unter "3746-950/LCB Safety Label Identifications" on page Iv angegeben.

3 Sicherheitsabdeckungen und Abschirmungen

Bezüglich des Standorts der durch den Kundendienst austauschbaren Funktionseinheit (Kapitel 4) prüfen, ob

- alle Sicherheitsabdeckungen vorhanden und mit Schrauben gesichert sind.
- alle Spannungsklemmleisten durch eine Plastikblende an der Oberseite der Klemmenplatte geschützt sind.

4 Erdung

a Schutzleiterverbindung des 3746-950 und der Erweiterung der Steuereinheit an das Erdungssystem des Gebäudes

Die elektrische Verbindung zwischen dem 3746-950, der Gehäuseerdung der Erweiterung der Steuereinheit und dem Erdungssystem des Gebäudes wird über die Netzkabel und den Schutzleiter **A** sichergestellt.

3746-950 und Erweiterung der Steuereinheit

- Hauptnetzkabel auf beschädigte oder verbrannte Kontakte und beschädigte Isolierung prüfen.
- Den Widerstand des nicht angeschlossenen Hauptnetzkabels zwischen dem Schutzleiterkontakt am einen und dem Schutzleiterkontakt am anderen Ende messen.

Der Widerstand darf maximal 0,1 Ohm betragen.




Figure 0-9. Schutzleiterkontakt am Hauptnetzkabel

- Prüfen, ob entsprechend der Konfiguration ein Schutzleiter **A** vorhanden ist (siehe Figure 0-10 on page xxxiv, Figure 0-11 on page xxxv, oder Figure 0-12 on page xxxvi).




Figure 0-10. Schutzleiteranschluß zwischen Erweiterung der Steuereinheit und angeschlossenem Rahmen des 3746-950




Figure 0-11. Schutzleiteranschluß bei einem Abstand unter 6 Meter zwischen 3746-950 und Erweiterung der Steuereinheit




Figure 0-12. Schutzleiteranschluß bei einem Abstand über 6 Meter zwischen 3746-950 und Erweiterung der Steuereinheit

Notes:

- 1) Schutzleiter **A** (Teilenummer 58G5691)
- 2) Schraube **B** (Teilenummer 61F4513), Zahnscheibe (Teilenummer 1622347 oder Teilenummer 17G5853) und Sicherungsring (Teilenummer 1622319)
- 3) Schraube **C** (Teilenummer 61F4511), Zahnscheibe (Teilenummer 17G5852) und Sicherungsring (Teilenummer 1622318)

b Interne Erdung im 3746-950 und in der Erweiterung der Steuereinheit

3746-950

Prüfen, ob die elektrische Verbindung zwischen dem Gehäuse des Verteilerkastens und dem Rahmen des 3746-950 gewährleistet ist, sofern Verteilerkästen vorhanden sind. Dieser Schritt muß vor dem Anschluß von Signalkabeln erfolgen.

Erweiterung der Steuereinheit

- Prüfen, ob die elektrische Verbindung zwischen allen in der Erweiterung der Steuereinheit installierten Einheiten (Serviceprozessor, Netzknotenprozessor, Modem, optisches Plattenlaufwerk) und dem Schutzleiterkontakt des Wechselstromverteilerkastens gewährleistet ist (siehe Figure 0-13).
- Prüfen, ob die elektrische Verbindung zwischen dem Schutzleiterkontakt des Wechselstromverteilerkastens und dem Montagerahmen der Erweiterung der Steuereinheit gewährleistet ist.




Figure 0-13. Schutzleiterkontakt des Wechselstromverteilerkastens

- Prüfen, ob die elektrische Verbindung zwischen dem Gehäuse des Verteilerkastens und dem Rahmen der Erweiterung der Steuereinheit gewährleistet ist, sofern Verteilerkästen vorhanden sind. Dieser Schritt muß vor dem Anschluß von Signalkabeln erfolgen (siehe Figure 0-14 on page xxxviii).

Note: Bei allen vorherigen Prüfungen sollten maximal 0,1 Ohm gemessen werden.

C Erdung der nicht im 3746-950 oder in der Erweiterung der Steuereinheit installierten Verteilerkästen

Prüfen, ob die elektrische Verbindung zwischen dem Gehäuse des Verteilerkastens und dem Erdungssystem des Gebäudes gewährleistet ist.

Je nach Installationsort kann der Verteilerkasten auf zweierlei Arten geerdet werden:

- 1) Erdung über die vier Schrauben (mit denen der Verteilerkasten am Gehäuse befestigt ist), falls der Gehäuserahmen mit dem Erdungssystem des Gebäudes verbunden ist.




Figure 0-14. Erdung des Verteilerkastens über Schrauben

- 2) Erdung über ein Kabel, das den Verteilerkasten mit dem Erdungssystem des Gebäudes verbindet.




Figure 0-15. Erdung des Verteilerkastens über Schutzleiter

IBM liefert diesen Schutzleiter nicht mit. Der Schutzleiter muß aus einem Draht mit mind. 2,5 mm² Querschnitt (AWG 12) bestehen, damit eine korrekte Erdung gewährleistet ist.

Schraube: Durchmesser: 5 mm

Länge: 6 bis 10 mm (siehe Figure 0-16 on page xxxix).

Verbindung des Schutzleiters mit dem Verteilerkasten




Figure 0-16. Schutzleiteranschluß

Dieser Schritt muß vor dem Anschluß von Signalkabeln erfolgen.

Note: Bei allen vorherigen Prüfungen sollten maximal 0,1 Ohm gemessen werden.

d Erdung des Gebäudes

- **Sicherstellen, daß zwischen den Metallgehäusen von Steckern, Buchsen usw. und jeder geerdeten Stelle im Gebäude eine Wechselspannung von maximal 1 Volt anliegt. Dies kann jedes geerdete Metallteil sein, wie z. B. die Stützen eines Doppelbodens (wenn sie mit dem Gebäudeerder verbunden sind), ein metallisches Wasserrohr, Baustahl usw..**

Notes:

- 1) Beim Prüfen an einem lackierten Metallteil sicherstellen, daß die Prüfspitze die Farbe durchbohrt.
- 2) Auch Metallgehäuse der anzuschließenden Kabel überprüfen.

5 Nennleistung der Sicherungsautomaten und Überstromschutzschalter

Positionen der Sicherungsautomaten und Überstromschutzschalter, siehe Table 0-2.

Prüfen, ob

- alle Sicherungsautomaten und Überstromschutzschalter im 3746-950 die unter Table 0-2 angegebene Leistung haben. Wenn die Leistung nicht aufgeführt ist, die Teilenummer im Teilekatalog überprüfen.

Table 0-2 (Page 1 of 2). Stromversorgung 3746-950, Überstromschutzschalter und Sicherungsautomaten			
Sicherungs- automat/ Überstrom- schutzschalter	Position	Nennleistung	Stromversorgung
Sicherungs- automat CB1 AC	07K-A1/07J-A1	15 A/220 V	Wechselstrom
Sicherungs- automat CB1 DC	07J-A1	50 A	Gleichstrom
Überstrom- schutzschalter CP1	07K-A1/07J-A1	5 A	Gleichstrom

Table 0-2 (Page 2 of 2). Stromversorgung 3746-950, Überstromschutzschalter und Sicherungsautomaten			
Sicherungs- automat/ Überstrom- schutzschalter	Position	Nennleistung	Stromversorgung
Überstrom- schutzschalter CP2	07H-A1	12 A	Gleichstrom
Überstrom- schutzschalter CP3	07H-A1	12 A	Gleichstrom
Überstrom- schutzschalter CP4	07H-A1	12 A	Gleichstrom
Überstrom- schutzschalter CP5	07H-A1	12 A	Gleichstrom

- Die Sicherungen im Wechselstromverteilerkasten der Erweiterung der Steuereinheit müssen 7 A, 250 V träge aufweisen (Teilenummer 58G5782).

6 Eingangsspannung

- a** Der zulässige Spannungsbereich (200/220/240V) und die Frequenz (50/60 Hz) sind dem Etikett für Anschlußwerte am **3746-950** zu entnehmen.

Prüfen, ob die Angaben auf dem Etikett am 3746-950 mit der an der Stromversorgung des Kunden gemessenen Frequenz und Spannung übereinstimmt. Wenn dies nicht der Fall ist, zuständige Geschäftsstelle informieren. Ort des Etiketts für Anschlußwerte, siehe "3746-950/LCB Safety Label Identifications" on page Iv.

Gleichstromeingangsspannung

Am Gleichstromeingang muß die Spannung beim Kunden zwischen -40,0 V und -60,0 V liegen. Der optionale Gleichstromeingang **kann nicht eingestellt werden**.

Wechselstromeingangsspannung

Am Wechselstromeingang muß die Spannung beim Kunden zwischen 180 V und 240 V liegen.

Die Einstellung der Eingangsspannung gemäß der Spannung beim Kunden kann an der Klemmleiste TB1 der Transformatoren an der Rückseite des 3746-950 erfolgen.

- b** Der zulässige Spannungsbereich (200 bis 240 V) und die Frequenz (50/60 Hz) sind dem Etikett für Anschlußwerte des Wechselstromverteilerkastens an der **Erweiterung der Steuereinheit** zu entnehmen.

Prüfen, ob die Angaben auf dem Etikett am Wechselstromverteilerkasten (der Erweiterung der Steuereinheit) mit der an der Stromversorgung des Kunden gemessenen Frequenz und Spannung übereinstimmt. Wenn dies nicht der Fall ist, zuständige Geschäftsstelle informieren. Ort des Etiketts für Anschlußwerte, siehe "Controller Expansion Label Location" on page Iviii.

Table 0-3. Einstellung des Wechselstromeingangs für den 3746-950

Gemessene Spannung	Ort des Leiters	Nennspannung
180 bis 210 Volt	Klemmleiste TB1-2	200/208 Volt
210 bis 230 Volt	Klemmleiste TB1-3	220 Volt
230 bis 260 Volt	Klemmleiste TB1-4	240 Volt

Wichtiger Hinweis:

Der 3746-950 kann über Fernsteuerung eingeschaltet werden. Deshalb muß für die Ausführung der folgenden Schritte am Bedienungsfeld des 3746-950 **local mode** eingestellt werden.

7 Testen des Netzkontrollschalters am 3746-950

- a. Den Kunden bitten, das Netzkabel an die Netzstromversorgung anzuschließen.
- b. Die/den Sicherungsautomat(en) CB1 einschalten.
- c. Den 3746-950 einschalten (Netzkontrollschalter am Bedienungsfeld muß auf Local stehen).
- d. Den Netzkontrollschalter auf die Position (⏻) und prüfen, ob:
 - der 3746-950 ausgeschaltet ist.
 - alle Lüfter nicht laufen.

Hinweis

Wenn sich der Netzkontrollschalter in der Position (⏻) befindet, bleiben die primären Versorgungs- (ACDC) oder Filterbereiche (DCDC) unter Strom.

Komplettes Abschalten:

1. Sicherungsautomaten ausschalten.
2. Alle Netzstecker aus den Steckdosen ziehen oder die Anlage abschalten.

8 Betriebsanzeige am 3746-950

Netzkontrollschalter einschalten und prüfen, ob die Bereitschaft-LED (am Bedienungsfeld des 3746-950) gemäß den Angaben in Tabelle "Bedeutung der LEDs am Bedienungsfeld des 3746-950" on page xlii leuchtet.

Wenn die LED 'Bereitschaft' ständig leuchtet, die Starttaste am Bedienungsfeld des 3746-950 drücken, prüfen, ob die LED 'Betrieb' (am Bedienungsfeld des 3746-950) gemäß den Angaben in Tabelle "Bedeutung der LEDs am Bedienungsfeld des 3746-950" on page xlii leuchtet.

Bedeutung der LEDs am Bedienungsfeld des 3746-950

Table 0-4. Bedeutung der LEDs am Bedienungsfeld des 3746-950

LED Bereitschaft	LED Betrieb	Status des 3746-950	Kommentar
Blinken	AUS	Wechselstrom EIN	Initialisierung der CBSP-Hardware. Der 3746-950 wartet auf erste Erkennung durch den MOSS-E beim LAN-Anschluß.
EIN	AUS	Bereitschaft	Der eingangs vom MOSS-E erkannte 3746-950 wartet auf das Einschalten (nur das CBSP EEPROM-Programm ist aktiv).
AUS	Blinken	Einschalten	Das einleitende Maschinenladen wird in allen 3746-950-Prozessoren durchgeführt.
AUS	EIN	Betrieb	Die 3746-950 ist nun betriebsbereit.

服务检查安全性过程

介绍

对于 3746-950 及扩充的安全性检查过程须在以下情形下进行：

- 在 IBM 同意下检查
- 要求 IBM 服务，而最近没有 IBM 进行的服务
- 进行替代和连接附件复查
- 该设施被施以可能影响其安全性的改动

如果这检查表示不可接受的安全情况，此情况必需在 IBM 维持此机器前校正。

注：校正任何不安全情况是该设施所有者的责任。

通过这过程检查的 3746-950 和控制器扩充区域和功能有：

1. 外盖
2. 安全性标签
3. 安全性盖板和屏蔽
4. 接地
5. 断路器和保护器额定
6. 轮入电源电压
7. 电源控制开关
8. 电源开启显示

注：3746-950 通过下列各处设置于“就绪”或“待用”状态：

- 服务处理器
- 主机
- 本地

当 3746-950 处于“就绪”状态或“待用”状态时，有些区域仍有致命的电压。

步骤 1 至 6 必须在电源关闭后进行。例如：

- 关掉
- 关闭所有安装在控制器扩充里的设施
- 关掉用户屋内 3746-950 和控制器扩充的电源供应。

不要除去 3746-950 和控制器扩充的电源线和接地线，以维持对接地线的保护（参见在第 3 页的图 1-2，在第 4 页的图 1-3，或在第 5 页的图 1-4）。

1 外盖

检查以证实：

- 它们全部在 3746-950 和控制器扩充上出现。
- 它们能被完全开启。
- 外盖打开后，框周围提供适当的服务清除和存取。

把所有外盖打开以侷容许以后的安全检查的步骤。

Safety

2 安全性标签：

检查以证实每个安全性标签与出现在 "Safety Label Locations" 里的字母有关。

3 安全盖板和屏蔽

参考 FRU 位置（第 4 章），检查：

- 安全盖板齐全并以螺丝关紧
- 所有电压终端板（TB）均受一胶屏保护。这胶屏关紧在 TB 顶。

4 接地

注意

这书里，“接地 (ground)” 解释为此设施必须与地下连接。

- a 把 3746-950 和控制器扩充接地至室内接地系统。

在 3746-950，控制器扩充框接地和室内接地系统间，通过电源线和接地线 **A** 保证电力的持续性。

在 3746-950 和控制器扩充上

- 检查主线 AC/DC 电源电缆上有没有损坏或烧坏的针和弄坏了的绝缘。
- 测量已断路的主线 AC/DC 电源电缆由一端的接地针至另一端的接地针的电阻。

其大小须是 0.1 欧姆或以下。




图 1-1. 主线 AC/DC 电源电缆上的接地针

- 检查接地线 **A** 是否依设置出现（参见页 3 的图 1-2，页 4 的图 1-3 和页 5 的图 1-4）。




图 1-2. 控制器扩充和连接著的 3746-950 框之间的接地线的连接




图 1-3. 3746-950 和控制器扩充距离少于 6 米时接地线的连接




图 1-4. 3746-950 和控制器扩充距离多于 6 米时接地线的连接

注：

- 1) **A** 接地线 (PN 58G5691)
- 2) **B** 螺钉 (PN 61F4513)，星状垫圈 (PN 1622347 或 PN 17G5853)，和锁状垫圈 (PN 1622319)
- 3) **C** 螺钉 (PN 61F4513)，星状垫圈 (PN 17G5852)，和锁状垫圈 (PN 1622319)

b 3476-950 和控制器扩充里的内部接地

3476-950 里

检查 LCB 外壳和 3476-950 框间肯定有电力连接。这项操作必须在任何网络连接前进行。

控制器扩充里

- 检查各安装在控制器扩充里的设施（服务处理器、网络节点处理器、调制解调器、光盘驱动器）和 AC 输出分布框的接地针（参见图 1-5）都肯定有电力连接。
- 检查 AC 输出分布框和控制器扩充安装框间肯定有电力连接。




图 1-5. 输出分布框的接地针

- 如果有 LCB，检查 LCB 外壳和控制器扩充间肯定有电力连接。这项操作必须在任何网络连接前进行（参见页 7 的图 1-6）。
- 注：以上所有检查结果须是 0.1 欧姆或以下。

c 没有安装在 3746-950 或控制器扩充的线连接框 (LCB) 的接地

检查 LCB 外壳和室内接地系统间肯定有电力连接

依 LCB 安装之处，有两个方法保证 LCB 有适当的接地：

- 1) 若机架的框已连接室内接地系统，4 条螺钉（保护机架上的 LCB）可保证接地。




图 1-6. LCB 经螺钉接地

2) 一条由 LCB 连接至室内接地系统的导线可保证接地。




图 1-7. LCB 经接地导线接地

IBM 没有供应这种导线。为保证正确接地，必须用 AWG12 导线（最少 2.5 平方毫米）作为接地线。

螺钉：直径：5 毫米

长度：6 至 10 毫米（参见页 8 的图 1-8）

把接地导线连接至 LCB




图 1-8. 接地线的连接

这项操作必须在任何网络连接前进行。

注：以上所有检查结果都须在 0.1 欧姆或以下。

d 建筑物接地

- 检查插头、连接器、插座等的金属外壳，和任何建筑物的接地点的 AC 是否少于 1 伏特。建筑物的接地点可以是任何已接地的金属结构，例如上升地面的支柱（如果它们已与建筑物地面接电），一条金属水管、建筑物钢材等。

注：

- 1) 探测已涂漆的金属表面时，确定探测计的金属顶端透过油漆。
- 2) 同时，检查输入电缆插头的金属外壳。

5 断路器和保护器额定

参见表 1-1 中 CB 和 CP 的位置。

检查以证实：

- 所有 3746-950 里的 CB 和 CP 以表 1-1 指示的值作额定。如果没有该额定，检查其部件号并对照部件编目。

表 1-1. 3746-950 电源供应 CP/CB 参考			
CP/CB	位置	额定	电源供应
CB1 ac	07K-A1/07J-A1	15 A/220 V	ac 电源
CB1 dc	07J-A1	50 A	dc 电源
CP1	07K-A1/07J-A1	5 A	dc 电源
CP2	07H-A1	12 A	dc 电源
CP3	07H-A1	12 A	dc 电源
CP4	07H-A1	12 A	dc 电源
CP5	07H-A1	12 A	dc 电源

- 控制器扩充 AC 输出分布框里的保险丝必须为 7A，250V slow (PN 58G5782)。

6 输入电源电压

- a 在 3746-950，电源额定板指示可用的电压范围 (200/220/240) 和频率 (50/60 Hz)。
- 检查 3746-950 的电源额定板和用户电源供应所测量的电压和频率相符。如果不相符，通知您的分行办公室。电源额定板的位置，参见 "Safety Label Locations"。

DC 输入电压

对于 DC 输入，用户的电压必须在 -40.0 V 至 -60.0 V 以内。任选的 DC 输入没有调整。

AC 输入电压

对于 AC 输入，用户的电压必须在 180 V 至 240 V 以内。输入电压可依位于 3746-950 末端的变压器的 TB1 的用户电压进行调整。

- b 在控制扩充，AC 输出分布框里的电源额定板指示可用的电压范围 (200 至 400) 和频率 (50/60 Hz)。
- 检查 AC 输出分布框（在控制器扩充里）的电源额定板和用户电源供应测量的电压和频率相符。如果不相符，通过您的分行办公室。电源额定板的位置，参见 "Controller Expansion Label Locations"

表 1-2. 3746-950 的 AC 输入调整		
测量得的电压	导线位置	额定的电压
从 180 至 210 Volts	TB1-1	200/208 Volts
从 210 至 230 Volts	TB1-2	220 Volts
从 230 至 260 Volts	TB1-3	240 Volts

重要：

由于 3476-950 可远程开启电源，以下所有过程必须在 3476-950 控制面板设置至 “本地方式” 时进行。

- 7 测试 3476-950 上的电源控制开关
- a 要求用户连接电源线至用户的主电源供应
- b 设置 CB1 至 “开”
- c 开启 3476-950 的电源（控制面板上的电力控制功能为本地）。
- d 操作电源控制开关至位置 (⏻) 并检查：
- 3476-950 的电源已关闭。
 - 所有风扇已停止。

注意

当电源控制开关设置至位置(⏻)，主电源 (ACAD) 或过滤部份 (DCDC) 仍然在活动状态。

要完全断开：

1. 转 CB 至“关”
2. 自供电输出口除去所有电源插头或关掉设置。

8 在 3746-950 上的电源开启指示器

设定电源控制开关于“开”并检查“待用 LED（在 3746-950 控制面板上）”是否已按照“控制面板 LED 状态对比 3746-950 状态”里所示的表发光。

一旦“待用 LED”永久性开启，按下在 3746-950 控制面板上的“开启”键，检查“就绪 LED（在控制面板上）”是否已按照“控制面板 LED 状态对比 3746-950 状态”里所示的表发光。

控制面板 LED 状态对比 3746-950 状态

表 1-3. LED 状态对比 3746-950 状态			
待用 LED	就绪 LED	3746-950 状态	注解
闪烁	关	AC 开	CBSP 硬件初始化。3746-950 等待 LAN 连接上的 MOSS-E 的初次认可。
开	关	待用	获 MOSS-E 初次认可的 3746-950 正等待电源开启的条件（只有 CBSP EEPROM 码正在运行。）
关	闪烁	电源开启	所有 3746-950 处理器正装入 IML
关	开	就绪	3746-950 现在可用

3746-950 Power Supply CP/CB Reference

<i>Table 0-5. 3746-950 Power Supply CP/CB Reference</i>			
CB/CP	Location	Rating	PS
CB1 AC	07K-A1 / 07J-A1	15A/220V	AC Power
CB1 DC	07J-A1	50A	DC Power
CP1	07K-A1 / 07J-A1	5A	DC Power
CP2	07H-A1	12A	DC Power
CP3	07H-A1	12A	DC Power
CP4	07H-A1	12A	DC Power
CP5	07H-A1	12A	DC Power

Safety Label Locations

3746-950 Safety Label Locations

On the following figures, labels are designated by letters. A particular wording corresponds to each letter (see "3746-950/LCB Safety Label Identifications" on page Iv).




Figure 0-17. 3746 Model 950 Label Locations

Safety Label on LCB




Figure 0-18. Safety Label Location on LCB

3746-950/LCB Safety Label Identifications

The safety labels shown in in Figure 0-19 on page Ivi are in the English language. They are also available in other languages. See “Safety Label Part Numbers by Country” on page Ivii for ordering.

Safety


LABEL K1



LABEL K2




LABEL L




LABEL A


LABEL M




LABEL D




LABEL N1



LABEL N2



LABEL P



LABEL Q




Figure 0-19. 3746 Model 950 Safety Labels


LABEL S

Figure 0-20. LCB Safety Label

Safety Label Part Numbers by Country

The following table gives the label group part number according to the language(s) of the country in which the 3746-950 is installed.

<i>Table 0-6. Safety Label Numbers by Country</i>			
LANGUAGE	3746-950 PART NUMBER	3746-950 LABEL Q	LCB LABEL S
Canadian French		17G5876	80G3928
Danish	72F0673	17G5876	80G3928
Dutch	72F0676	17G5876	80G3928
English	72F0664	17G5876	80G3928
Finnish	72F0674	17G5876	80G3928
French	72F0665	17G5876	80G3928
French/Dutch		17G5876	80G3928
German	72F0666	17G5876	80G3928
Italian	72F0667	17G5876	80G3928
Japanese	72F0670	17G5876	80G3928
Norwegian	72F0671	17G5876	80G3928
Portuguese	72F0668	17G5876	80G3928
Spanish	72F0669	17G5876	80G3928
Swedish	72F0677	17G5876	80G3928

Controller Expansion Label Location




Figure 0-21. Controller Expansion label Locations

About This Manual

Aim of this Manual

The service guide gives the service representative the information needed to:

- Analyze the problem or symptoms reported by the system user for the service processor and its attached modem.
- Restore the normal 3746-950 operation.
- Exchange all the FRUs of 3746-950.
- Run diagnostics on the 3746-950.

It is expected that the customer has used the *Problem Analysis Guide* (online document) prior calling IBM for service.

Who Should Read this Manual

The person using this manual should be:

- Trained to service 3746-950.
- Familiar with the configuration and operation of the 3746-950.

The intended audience for this manual are Product-Trained Customer Engineers (PT-CE). The Product-Support Customer Engineer (PST-CE) is also expected to refer to the manual when he is required to perform the same tasks as the PT CE.

How this Manual Is Organized

This manual is organized as follows:

- Safety information is at the start of this manual.
 - Chapter 1** Gives the start page which points on the service or troubleshooting procedures.
 - Chapter 2** Gives MAPs for FRU isolation.
 - Chapter 3** Gives information on diagnostics and how to run them.
 - Chapter 4** Gives the procedure to exchange the FRU on the 3746-950.
- At the back of the manual are appendixes:
 - External cable references
 - Maintenance Aids
 - Bibliography and related signal converter product information
 - Parts catalog
 - Part number index
 - Glossary
 - Index.

Chapter 1. START

START - How to Begin Troubleshooting

IMPORTANT

- Your safety is part of every maintenance call and can never be over-emphasized. Specific information can be found in "General and Product Safety Information" on page xxi and "Safety Label Locations" on page liv.

Start here when you use this manual to repair a 3746-950 hardware failure.

- Remember that the 3746-950 is machine which is designed to be repaired while the customer is still using the operational areas, this is called **Concurrent Maintenance**. Before changing FRUs, you will be directed to ensure that you have the correct area of the machine ready for maintenance.
- During a call for service, it will normally be necessary to use the service processor. To log on at service processor console, proceed as directed in "Console Use for maintenance."

Console Use for maintenance

001

Is the 3746 a Model 950?

Yes No

002

For 3746 model 900 use *IBM 3746 Expansion Unit Model 900*, SY33-2116, or *IBM 3745 Communication Controller Models 210 to 61A, Maintenance Information Procedures*, SY33-2054, or *IBM 3745 Communication Controller Models 130 to 17A, Maintenance Information Procedures*, SY33-2070 .

003

Is the service processor operational?

Yes No

004

Continue with "Finding a Service Procedure" on page 1-3

005

You will have to get the service processor maintenance password from the customer so that you can logon at the service processor console.

To log on:

- On the "MOSS-E View" window, click on "Program" (in the action bar).
- Click on "MOSS-E View Logon".
- Enter the password.

Are you here to investigate a RSF problem? If you don't know continue with Step 006.

Yes No

006

- On the "MOSS-E View" window, double click on the service processor icon.
- The "Service Processor Menu" window is displayed.
- Click on the "Configuration Management" option.
- Double click on the "Manage Remote Operations" option.
- On the "Remote Operation Management" window, select the "Remote operations authorization" option and click on "OK".
- On the "Remote Support Facility" window, select the two following options:
 - "Disable Remote Support Facility"

(Step **006** continues)

Start

- 006** (continued)
 - "Do not generate alerts" and click on "OK".
 - Continue with Step 007.

007

Look on "3746-950/Service Processor Windows Overview" on page 1-7 to see the main panels used to perform the procedures documented in this manual.

Now continue with "Finding a Service Procedure" on page 1-3 .

Finding a Service Procedure

Select the first entry point which fits your situation.

IF YOU HAVE	THEN	GO TO
3746-950 CONTROL PANEL CODE	3746-950 Control panel code reported	"3746-950 Control Panel Codes" on page 1-15.
GENERAL SYMP- TOMS	General Verbal Symptoms	"General Verbal Symptoms" on page 1-13.
	Color symptom for icons on "MOSS-E View" window.	"MAP 2600: 3746-950/Service Processor/Network Node Processor/Multiaccess Enclosure Link Icons Color Symptom" on page 2-19
	Problem during installation	"Problems During Machine, EC or MES Installation" on page 1-12.
	Problem while installing an EC or MES	"Problems During Machine, EC or MES Installation" on page 1-12.
	3746-950 any Power Problem	"MAP 2500: 3746-950 Power Control Sub-system Problems" on page 2-4
	3746-950 Control Panel Symptom	"3746-950 Control Panel Symptoms" on page 1-14.
	Service processor/Display/Optical Disk symptom	"Service Processor Problem Determination" in the corresponding <i>Service Processor Installation and Maintenance</i> manual.
	Network Node Processor symptom	"Network Node Processor Problem Determination" in the corresponding <i>Network Node Processor Installation and Maintenance</i> manual.
	Problem with the service processor integrated modem	"How to Run the Service Processor Diagnostics" in the corresponding <i>Service Processor Installation and Maintenance</i> manual, and run the integrated V.32 modem, or refer to the <i>IBM Asynchronous/SDLC V.32 Modem/A; Installation, Operation, and Problem Determination Guide SA27-3955</i> .
MAINTENANCE ACTION	Problem on external modem attached at the service processor	The modem documentation: <ul style="list-style-type: none"> • For IBM 7855, refer to the <i>7855 Modem Model 10 Guide to Operation</i>, GA33-0160 • For IBM 7857, refer to the <i>IBM 7857 Guide to Operation</i>, GA13-1839 • For IBM 7858, refer to the <i>IBM 7858 Professional Modem Guide to Operation</i>, GA13-1981 • For other modem, refer to the appropriate documentation.
	Other Symptoms	"Other Symptoms" on page 1-4
	A customer problem number (CPN), system reference code sequence number, FRU list, or FRU group to exchange	"CPN or FRU to Exchange" on page 1-4
	Run diagnostics on the 3746-950, service processor, network node processor, or multiaccess enclosure	"Run Diagnostics" on page 1-4
	Miscellaneous Informations	"Miscellaneous Informations" on page 1-6

CPN or FRU to Exchange

IF YOU HAVE....	THEN GO TO
Customer problem number (CPN)	"3746-950/Service Processor Maintenance Using a CPN" on page 1-26
3746-950 System reference code sequence number	"3746-950 Maintenance Using an SRC Sequence Number" on page 1-28
3746-950 FRU group number to exchange	"Using the MIP FRU Group Table" on page 1-24.
3746-950 FRU list to exchange	"3746-950 Maintenance Using a FRU list" on page 1-28.
Service processor system reference code sequence number	"Service Processor Maintenance Using an SRC Sequence Number" on page 1-28.

Other Symptoms

IF YOU HAVE ...	THEN GO TO
3746-950 Configuration mismatch	"MAP 2615: 3746-950 Configuration Mismatch" on page 2-31.
3746-950 Service Processor Link Symptom	"MAP 2950: LAN Problem on LAN Attached to the Service Processor" on page 2-133.
3746-950 Token-Ring LAN problem	"MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
3746-950 Ethernet LAN problem	"MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
3746-950 ESCA problems	"MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
3746-950 ARCs Group problem	"MAP 2810: 3746-950 Problem on a Group of ARCs" on page 2-100.
3746-950 All the lines on CLP have a problem	"MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
3746-950 CLP fallback problem	"MAP 2840: 3746-950 CLP Fallback Problem" on page 2-123.
3746-950 All the lines on LIC11 have a problem	"MAP 2820: 3746-950 Problem on a LIC11" on page 2-105.
3746-950 LIC12 problem	"MAP 2830: 3746-950 Problem on a LIC12" on page 2-117.
3746-950 Intermittent problems	"MAP 2660: 3746-950 Intermittent Box Errors" on page 2-51.
3746-950 Resource not present in CDF-E	"MAP 2665: 3746 Model 950 Resource Not Present in CDF-E" on page 2-53.
A problem on your multiaccess enclosure	Refer to to the <i>Multiaccess Enclosure Installation and Maintenance</i> , manual manual.

Run Diagnostics



IF YOU WANT TO....	THEN GO TO
Run 3746-950 diagnostics in concurrent maintenance mode	"MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16.
Run 3746-950 diagnostics in offline mode	"MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39.
Run 3746-950 Specific diagnostics in offline mode	"MAP 2990: How to Run 3746-950 Specific Diagnostics" on page 3-41.
Run the 3746-950 control panel test	"How to Run the 3746-950 Control Panel Test" on page 3-14
Run the 3746-950 service processor link restart	"How to run the 3746-950 Service Processor Link Restart" on page 3-15
Run diagnostics on service processor	"How to Run the Service processor Diagnostics" in the corresponding <i>Service Processor Installation and Maintenance</i> manual.
Run diagnostics on network node processor	The appropriate <i>Network Node Processor Installation and Maintenance</i> .
Run diagnostics on Ethernet Bridge	The <i>8229 Bridge Manual</i> , GA27-4025 manual.

IF YOU WANT TO....	THEN GO TO
Run diagnostics on multiaccess enclosure	<p>The following:</p> <ul style="list-style-type: none">• For specific resource on multiaccess enclosure refer to the <i>Multiaccess Enclosure Installation and Maintenance</i>, manual manual.• For a selective IML on multiaccess enclosure refer to "MAP 3000: How to Run the Selective IML on the Multiaccess Enclosure" on page 3-47.


Miscellaneous Informations

IF YOU WANT TO....	THEN GO TO
Find information about using the 3746-950 control panel	"3746-950 Control Panel Use" on page 1-149
Display the 3746-950 FRU list after a diagnostic failure	"Display the FRU List After a Diagnostic Failure" on page 1-143.
Investigate about 3746-950 Intermittent problems	"MAP 2660: 3746-950 Intermittent Box Errors" on page 2-51.
Display the 3746-950 bit error rate on ESCA	"MAP 2720: 3746-950 Bit Error Rate Validation" on page 2-80.
Check voltages on 3746 Model 950	3746-950 YZ pages
Perform the 3746-950 EEPROM Upgrade Function	"3746-950 EEPROM Upgrade" on page 1-144
Install a 3746-950 MES	The instruction provided with the MES. Use the service processor, when specified, to select the desired 3746-950 and all available functions necessary for installing and testing.
Apply a Microcode Change on 3746-950	"Handling the Microcode Change Levels" in the chapter "Maintaining the Code Loaded in the Service Processor" in the <i>Service Processor and Network Node Processor Service User</i> or in the corresponding <i>Service Processor Installation and Maintenance</i> manual.
Perform Engineering Data Transfer	"Engineering Data Transfer" on page 1-146.
Apply a Microcode Change on a service processor	"Handling the Microcode Change Levels" procedure in chapter "Maintaining the Service Processor" in the <i>Service Processor and Network Node Processor Service User</i> or in the corresponding <i>Service Processor Installation and Maintenance</i> manual.
Find Modem Setting for RSF	The <i>Service Processor Installation and Maintenance</i> paragraph "Installing and Connecting the RSF Modem to the Service Processor", according to your modem type.
Have a Service Processor windows overview	"3746-950/Service Processor Windows Overview" on page 1-7
Know 3746-950 control panel function	"3746-950 Control Panel Use" on page 1-149
See the 3746-950 parts catalog	<i>IBM 3746 Expansion Unit Model 900, IBM 3746 Nways Multiprotocol Controller Model 950, Parts Catalog, S135-2015</i>

3746-950/Service Processor Windows Overview



For **3746-9x0 Menu** details see page 1-10.



For **Service Processor Menu** details see page 1-8.

Service Processor Menu Details




Figure 1-1. Service Processor Configuration Management Functions




Figure 1-2. Service Processor Problem Management Functions




Figure 1-3. Service Processor Operation Management Functions



Figure 1-4. Service Processor Change Management Functions




Figure 1-5. Service Processor Ethernet Bridge Functions




Figure 1-6. Service Processor Performance Management Function




Figure 1-7. Service Processor PE Functions

3746-9x0 Menu Details




Figure 1-8. 3746-9x0 Configuration Management Functions




Figure 1-9. 3746-9x0 Problem Management Functions




Figure 1-10. 3746-9x0 Operation Management Functions




Figure 1-11. 3746-9x0 Network Node Processor Management Functions




Figure 1-12. 3746-9x0 MAE Management Functions




Figure 1-13. 3746-9x0 Change Management Functions




Figure 1-14. 3746-9x0 Performance Management Function




Figure 1-15. 3746-9x0 PE Functions

Problems During Machine, EC or MES Installation

When installing a 3746-950, the *IBM 3746 Nways Multiprotocol Controller Model 950, Installation Guide*, SY33-2107 should be used. When installing an EC or MES, the instructions supplied should be used. It is possible that the task or diagnostic you were asked to perform during the installation detected an error, and you were requested to start troubleshooting using this manual.

The primary purpose of this manual is to resolve problems that occur in an operational environment after a successful installation. That is, the machine has worked previously and is now failing.

At installation time, or after an EC or MES is installed, it is possible that errors may occur due to conditions which would not exist in an operational environment.

- Cables plugged incorrectly.
- Terminators missing.
- Mismatch between CDF-E and machine configuration.
- Mismatch between line characteristics and set ups.
- Wrong address set.
- Top card connectors incorrectly installed.
- Loose cards.

During your path through the service guide, you should remember these possibilities and, when the failing area is identified, check with the aid of this manual and YZ pages that these conditions do not exist prior to changing FRUs.

Now, starting at the top of the "Selection Table," work down until you find an entry that matches the symptom detected during the installation.

Be sure to read "Exchange Precautions" on page 4-1 before removing any FRUs from this machine.

Selection Table

IF YOU HAVE A...	THEN GO TO...
3746-950 resource not present in CDF-E	"MAP 2665: 3746 Model 950 Resource Not Present in CDF-E" on page 2-53.
3746-950 control panel code reported	"3746-950 Control Panel Codes" on page 1-15.
3746-950 diagnostic failure Display the FRU list	"Display the FRU List After a Diagnostic Failure" on page 1-143.
3746-950 any Power Problem	Go to "MAP 2500: 3746-950 Power Control Subsystem Problems" on page 2-4
multiaccess enclosure any Power Problem	The <i>Multiaccess Enclosure Installation and Maintenance</i> , manual manual.
3746-950 control panel symptoms	"3746-950 Control Panel Symptoms" on page 1-14.
General Verbal Symptoms	"General Verbal Symptoms" on page 1-13.

Symptom Index

General Verbal Symptoms

Table 1-1. General Symptoms		
IF THE	SYMPTOM	THEN:
Host	Has detected <ul style="list-style-type: none"> channel errors on this 3746-950 route inop missing interrupt 	Go to "MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
	Is unable to activate an ESCA or no traffic on ESCA	Go to "MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
The APPN® control Point on the network node processor	Is unable to activate (start) a ring or has errors while running a ring connected to a 3746-950	Go to "MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
	Is unable to activate (start) or has problem on all the lines of a 3746-950 CLP.	Go to "MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29.
	Is unable to activate (start) or has problem on all the lines of a 3746-950 LIC11.	Go to "MAP 2820: 3746-950 Problem on a LIC11" on page 2-105.
	Is unable to activate or has problem on all the lines of the same ARC group	Go to "MAP 2810: 3746-950 Problem on a Group of ARCs" on page 2-100.
	Is unable to activate or has problem on all the lines of the same line connection box expansion (LCBE)	Go to "MAP 2860: 3746-950 All the Lines of LCBE Have Problem" on page 2-128.
	Is unable to activate or has problem on all the line of a 3746-950 LIC12	Go to "MAP 2830: 3746-950 Problem on a LIC12" on page 2-117.
	Has a suspected program loop or hang	☎ your support structure for assistance with this problem.
	Has unexpected re-IPLs	☎ your support structure for assistance.
Hardware Central Service	On 3746-950, the RSF link is down	Go to "MAP 2000: 3746-950 Manual Call" on page 2-1.
The Service Processor	Is unable to establish a link with the 3746-950	Go to "MAP 2950: LAN Problem on LAN Attached to the Service Processor" on page 2-133.

3746-950 Control Panel Symptoms

Check the 3746-950 control panel with the following table.

<i>Table 1-2. Control Panel Symptoms</i>	
IF THE 3746-950	THEN:
CBSA Check indicator ON.	Change the CBSP, go to "3746-950 FRU List" on page 1-29
Control panel displays any wrong character or all segments of all characters are On.	Run the Control Panel test, refer to "How to Run the 3746-950 Control Panel Test" on page 3-14. When a FRU is called for an error, go to "3746-950 FRU List" on page 1-29. If no error is detected and the problem still exists, contact your support structure for a possible microcode problem.
Control panel display has a missing character.	Run the Control Panel test, refer to "How to Run the 3746-950 Control Panel Test" on page 3-14. When a FRU is called for an error, go to "3746-950 FRU List" on page 1-29. If no error is detected and the problem still exists, contact your support structure for a possible microcode problem.
Has one or more control panel keys that do not work.	Run the Control Panel test, refer to "How to Run the 3746-950 Control Panel Test" on page 3-14. When a FRU is called for an error, go to "3746-950 FRU List" on page 1-29. If no error is detected and the problem still exists, contact your support structure for a possible microcode problem.
Control panel display is blank with Standby or Ready LED lighted or blinking.	Go to "How to Run the 3746-950 Control Panel Test" on page 3-14.
Control panel display is blank with Standby and Ready LED OFF.	Go to "MAP 2500: 3746-950 Power Control Subsystem Problems" on page 2-4.

3746-950 Control Panel Codes

Note

When the microcode is a possible cause of the error, it is recommended that you check if you have the highest level of microcode for your machine and that any applicable MCFs are installed. Your support structure will have this information.

Important

The panel codes indicate an error when they are flashing or if they stay ON more than 60 seconds.

If a flashing panel code is not described below, a hardware problem is suspected, call your support for assistance.

Table 1-3 (Page 1 of 9). 3746 Model 950 Control Panel Code

Panel Code	Action to be Taken
00000000	IML complete, box available.
00101001	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24. If the error is not corrected a microcode problem is suspected. Contact your support structure.
00101003	Error detected with BATS. Exchange the FRU Group 2502 on page 1-25, go to page 1-24.
00101004 to 00101006	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00101007	Error detected with BATS. Exchange the FRU Group 2503 on page 1-25, go to page 1-24.
00101008 to 0010100F	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00101010	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00101013	Error detected with BATS. Exchange the FRU Group 2520 on page 1-25, go to page 1-24.
00101020 to 00101021	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00101022	Error detected with BATS. Exchange the FRU Group 2503 on page 1-25, go to page 1-24.
00101030	BATS Start memory test
00101031	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00101033	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00101036	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00101038	Error detected with BATS. Exchange the FRU Group 2504 on page 1-25, go to page 1-24.
0010103F	BATS ended without error
00101041	BATS Responder phase started
00101050 to 00101052	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00323270	Error detected at IML. TIC3 of CBSP not present. If TIC3 is present exchange the FRU Group 2518 on page 1-25, go to page 1-24.
00323272	Coupler 1 (normally TIC3) of CBSP unplugged in concurrent mode.
00323273	Error detected at IML. Coupler 1 of the CBSP has an unknown type. Exchange the FRU Group 2506 on page 1-25, go to page 1-24.
00323274 or 00323275	Error detected at IML. Coupler 1 of the CBSP is not a TIC3. Install a TIC3 coupler in position 07N-A1-F1.
00323277	TIC3 of CBSP unplugged before being set to concurrent mode. If the TIC3 is correctly plugged exchange the FRU Group 2521 on page 1-25, go to page 1-24.
00323279	Error detected on hot plugging. Coupler 1 of the CBSP has an unknown type. Exchange the FRU Group 2506 on page 1-25, go to page 1-24.

3746-950 Panel Codes

Table 1-3 (Page 2 of 9). 3746 Model 950 Control Panel Code	
Panel Code	Action to be Taken
0032327A or 0032327B	Error detected on hot plugging. Coupler 1 of CBSP is not a TIC3. Install a TIC3 coupler in position 07N-A1-F1.
0032327C	TIC3 of CBSP successfully hot-plugged.
0032327D	Error detected on hot plugging. Coupler 1 of CBSP has been hot-plugged but cannot be accessed. Exchange the FRU Group 2518 on page 1-25, go to page 1-24.
003636600 to 00363661	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00363667	Error detected with BATS. Exchange the FRU Group 2504 on page 1-25, go to page 1-24.
00363669	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
0036366A	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00363670	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00363671	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
00363677	Error detected with BATS. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
0036367F	BATS ended without error
00393908 to 0039390A	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
0039390B	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
003939BB	Error detected at IML. TIC3 not present or not detected. Check the TIC3 plugging. If TIC3 is present and correctly plugged exchange the FRU Group 2507 on page 1-25, go to page 1-24.
003939C8 to 003939CB	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
003939E6	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
003939F3 to 003939F4	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
003939F8 to 003939FA	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
0050502A	A microcode problem is suspected. Contact your support structure.
04D50E02	Exchange the FRU Group 2505 on page 1-25, go to page 1-24.
04D50EDC	Exchange the FRU Group 2505 on page 1-25, go to page 1-24.
04D5D568	A microcode problem is suspected. Contact your support structure.
04D5D56E	The TIC3 of CBSP is missing at initialization. Check the plugging of TIC3 in position 07N-A1-F1 and do an IML with diags. If the same error is reported exchange the FRU Group 2506 on page 1-25, go to page 1-24.
04D5D57B	A microcode problem is suspected. Contact your support structure.
04D5D580	A microcode problem is suspected. Contact your support structure.
04D5D5B4	A microcode problem is suspected. Contact your support structure.
04D6D602	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
04D6D603	Do an IML with diag, if the same code is displayed exchange the FRU group 2505 on page 1-25, go to page 1-24. If after exchange the problem is still present contact your support structure.
04D6D604	Do an IML with diag, if the same code is displayed exchange the FRU group 2505 on page 1-25, go to page 1-24. If after exchange the problem is still present contact your support structure.
04D9D9A9	Error session. Do the problem determination using <i>Token-Ring Network, problem Determination Guide</i> SX27-3710. If the problem persists exchange the FRU group 2506 on page 1-25, go to page 1-24.
04D9D9AA	Duplicate token ring local address. Two machines are installed on the LAN with the same token ring local address. Go to "MAP 2770: 3746-950 Duplicate Token Ring Local Address" on page 2-96.

Table 1-3 (Page 3 of 9). 3746 Model 950 Control Panel Code	
Panel Code	Action to be Taken
04D9D9AB	Remove command received from the ring following a user request. Re-initialize the link by activating the 3746-950 service processor link restart. Refer to "How to run the 3746-950 Service Processor Link Restart" on page 3-15.
04D9D9AE	Error session. Do the problem determination using <i>Token-Ring Network, problem Determination Guide</i> SX27-3710. If the problem persists exchange the FRU group 2506 on page 1-25, go to page 1-24.
04D9D9BA	Error session. Do the problem determination using <i>Token-Ring Network, problem Determination Guide</i> SX27-3710. If the problem persists exchange the FRU group 2506 on page 1-25, go to page 1-24.
04D9D9BB	Re-initialize the link by activating the 3746-950 service processor link restart refer to "How to run the 3746-950 Service Processor Link Restart" on page 3-15 If the problem is always present, it can be a ring failure, refer to "MAP 2950: LAN Problem on LAN Attached to the Service Processor" on page 2-133.
04D9D9BC	Invalid parameter. A microcode problem is suspected. Contact your support structure.
04D9D9BD	A microcode problem is suspected. Contact your support structure.
04D9D9BE	A microcode problem is suspected. Contact your support structure.
05232320	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232330	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232339	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
0523233C	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232340	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232350	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232360	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232370	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232380	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05232390	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
052323A0	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
052323FF	IML Progression code. If this code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242400	Do an IML with diag, if the same code is displayed, a microcode problem is suspected or Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242401 to 05242405	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242407	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24. or microcode problem is suspected. Contact your support structure.
05242414	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242416	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242440	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242470	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242480	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05242490	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
052424A0	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05282800 to 05282804	IML progression code. If the code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.

Table 1-3 (Page 4 of 9). 3746 Model 950 Control Panel Code

Panel Code	Action to be Taken
05282805	<p>IML progression code. If the code is permanently displayed check the 'Service processor not accessible digit' on the 3746-950 control panel.</p> <ul style="list-style-type: none"> • If A and F are alternatively displayed, a service processor problem is suspected. Go to <i>Service Processor Installation and Maintenance</i> manual, chapter "Service Processor Problem Determination". • If a B is displayed, wait 50 seconds either: <ul style="list-style-type: none"> – B is always displayed and a new control panel is flashing. Follow the procedure attached to this new control panel code. – Or, B is always displayed with the same control panel code. Exchange the FRU Group 2501 on page 1-25, go to page 1-24. – Or, B is no longer displayed and the IML continues. It was a transient error.
05282806	<p>IML progression code.</p> <ul style="list-style-type: none"> • If the code is permanently displayed and if the Standby LED is ON there is no error. The 3746-950 is in standby state waiting a power ON. The power ON can be initiated via the start key on the control panel if the 'Power control' is set in local mode (3). • If the Standby LED is blinking check the 'Service processor not accessible digit' on the 3746-950 control panel. <ul style="list-style-type: none"> – If A and F are alternatively displayed, a service processor problem is suspected. Go to <i>Service Processor Installation and Maintenance</i> manual, chapter "Service Processor Problem Determination". – If a B is displayed, wait 50 seconds either: <ul style="list-style-type: none"> - B is always displayed and a new control panel is flashing. Follow the procedure attached to this new control panel code. - Or, B is always displayed with the same control panel code. Exchange the FRU Group 2501 on page 1-25, go to page 1-24. - Or, B is no longer displayed and the IML continues. It was a transient error.
05282807 to 052828FD	<p>IML progression code. If the code is permanently displayed check the 'Service processor not accessible digit' on the 3746-950 control panel.</p> <ul style="list-style-type: none"> • If A and F are alternatively displayed, a service processor problem is suspected. Go to <i>Service Processor Installation and Maintenance</i> manual, chapter "Service Processor Problem Determination". • If a B is displayed, wait 50 seconds either: <ul style="list-style-type: none"> – B is always displayed and a new control panel is flashing. Follow the procedure attached to this new control panel code. – Or, B is always displayed with the same control panel code. Exchange the FRU Group 2501 on page 1-25, go to page 1-24. – Or, B is no longer displayed and the IML continues. It was a transient error.
052828FE to 052828FF	IML progression code. If the code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
052B2BFF	IML progression code. If the code is permanently displayed exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05303061	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
05303063	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
05303065	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
05303067	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
0530306B	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
05303077	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
0530307F	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
05303083	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
053030B2 to 053030B3	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053030B4 to 053030B6	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
053030B7	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.

<i>Table 1-3 (Page 5 of 9). 3746 Model 950 Control Panel Code</i>	
Panel Code	Action to be Taken
053030B8	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
053030B9	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053030BA to 053030BE	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
053030BF	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24.
053030C0 to 053030CB	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053030CC to 053030CE	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
053030CF	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053030D0	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053030D1 to 053030D2	Error detected at IML. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
053030D3	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053030D9	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053030DC	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
05313141	Error detected at IML. The type of the processor installed in position 07G-A1-F1 is unknown. It should be a CBSP. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05313143	Error detected on hot plugging. The type of the processor installed in position 07G-A1-F1 is unknown. It should be a CBSP. Exchange the FRU Group 2501 on page 1-25, go to page 1-24.
05393950	Too many EEPROM retry. Suspect any station on LAN ring and the service processor access control unit, otherwise exchange the FRU Group 2521 on page 1-25, go to page 1-24. If after exchange the same error is reported contact your support structure.
05393901	Code level incompatibility between CBSP EEPROM and CBSP code. Do an IML with diag, if the same code is displayed contact your support structure.
05393903	Bad loading of information table. Do an IML with diag, if the same code is displayed contact your support structure.
05393905	Bad frame length configuration. Check the frame length size of MOSS-E under communication manager. Contact your support structure.
05393906	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
05393907	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
05393965	Error detected at IML. Exchange the FRU Group 2506 on page 1-25, go to page 1-24.
05393967	Function failure on open adapter. Suspect a problem in LAN cable, service processor access unit, or TIC3. Do the problem determination using <i>Token-Ring Network, problem Determination Guide SX27-3710</i> .
05393969	Signal loss on open adapter. LAN error, suspect the service processor access unit, or other LAN cables or other LAN adapters. Do the problem determination using <i>Token-Ring Network, problem Determination Guide SX27-3710</i> .
0539396B	Error detected at IML. Wire fault on open adapter. Suspect a problem in the LAN cable
0539396D	Error detected at IML. Frequency error on open adapter. Exchange the FRU Group 2505 on page 1-25, go to page 1-24.
0539396F	Error detected at IML. Insertion time out on open adapter. LAN ring congestion. Wait for decongestion. Re-IML if the same code is displayed exchange the FRU Group 2506 on page 1-25, go to page 1-24.
05393971	Error detected at IML. Ring failure on open adapter. Wait 30 seconds. Re-IML if the same code is displayed exchange the FRU Group 2506 on page 1-25, go to page 1-24.

Table 1-3 (Page 6 of 9). 3746 Model 950 Control Panel Code	
Panel Code	Action to be Taken
05393973	Error detected at IML. Ring beaconing open adapter. Wait 30 seconds. Re-IML and if the same code is displayed check the speed of the ring which should be 16 MB. Suspect also the service processor access unit or other LAN cable. Do the problem determination using <i>Token-Ring Network, problem Determination Guide SX27-3710</i> .
05393975	Error detected at IML. Duplicate node address on open adapter. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after the FRU exchange the same error is reported contact your support structure.
05393977	Error detected at IML. No response from ring parameter server on open adapter. LAN ring congestion. Wait 30 seconds, Re-IML. If the same error is reported contact your support structure.
05393979	Error detected at IML. Removed received on open adapter. Too many stations on the ring. Check on network station management, if it is correct exchange the FRU Group 2506 on page 1-25, go to page 1-24.
0539397B	Error detected at IML. IMPL force received on open adapter. Exchange the FRU Group 2506 on page 1-25, go to page 1-24. or microcode problem is suspected. Contact your support structure.
0539397D	Error detected at IML. No monitor detected for RPL at open adapter. Exchange the FRU Group 2505 on page 1-25, go to page 1-24.
0539397F	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. or microcode problem is suspected. Contact your support structure.
05393981	Check the LAN connection between the 3746-950 and the service processor access unit. If after IML the same code is reported a microcode problem is suspected. Contact your support structure.
05393983	Do an IML with diag, if the same code is reported a microcode problem is suspected. Contact your support structure.
05393985	Do an IML with diag, if the same code is reported, a microcode problem is suspected. Contact your support structure.
05393987	Error detected at IML. Exchange the FRU Group 2508 on page 1-25, go to page 1-24.
05393989	Error detected at IML. Exchange the FRU Group 2507 on page 1-25, go to page 1-24.
0539398B	Error detected at IML. Ring status change hard error (beaconing). Suspect any station on the ring or the service processor access unit. Exchange the FRU Group 2506 on page 1-25, go to page 1-24. Do the problem determination using <i>Token-Ring Network, Problem Determination Guide SX27-3710</i> .
0539398F	Error detected at IML. Exchange the FRU Group 2506 on page 1-25, go to page 1-24.
05393991	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
05393993	Error detected at IML. Suspect error on any station on the ring. Do the problem determination using <i>Token-Ring Network, Problem Determination Guide SX27-3710</i> .
05393995	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
05393997	Error detected at IML. Exchange the FRU Group 2506 on page 1-25, go to page 1-24.
05393999	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
0539399B	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
0539399D	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
0539399F	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
053939A1	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.

Table 1-3 (Page 7 of 9). 3746 Model 950 Control Panel Code	
Panel Code	Action to be Taken
053939A3	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
053939A5	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24.
053939A7	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
053939A9	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939AB	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
053939AD	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939AF	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939B1	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939B2	Error detected at IML. Suspect any station on the ring. Do the problem determination using <i>Token-Ring Network, problem Determination Guide SX27-3710</i> . Exchange the FRU Group 2521 on page 1-25, go to page 1-24.
053939B3 to 053939B8	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939B9	Ring status change lobe wire fault. Check the 3746-950 LAN cable.
053939C1	A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939C3 to 053939C4	Bad frame length configuration. Check the frame length size of MOSS-E under communication manager. If the frame length is OK suspect a microcode problem, contact your support structure.
053939C5 to 053939C6	A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939C7	Error detected at IML. Exchange the FRU Group 2508 on page 1-25, go to page 1-24.
053939CC	A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939CD	A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939CF	A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939D0 to 053939D1	A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939D2	Suspect a problem on MOSS-E. Check error displayed on the MOSS-E screen.
053939D3	A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939D5 to 053939D6	Do an IML with diag, if the same code, is displayed contact your support structure.
053939D7	Permanent beaconing. Do an IML with diag. If the same code is displayed do the problem determination using <i>Token-Ring Network, Problem Determination Guide SX27-3710</i> .
053939DA	Error detected at IML. Ring status change auto removal or remove received. Exchange the FRU Group 2506 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed, a microcode problem is suspected. Contact your support structure.
053939DD	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24.
053939DE to 053939DF	Do an IML with diag. If the same code is displayed, contact your support structure.
053939E0	Do an IML with diag, if the same code, is displayed contact your support structure.
053939E1	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939E2	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.

3746-950 Panel Codes


Table 1-3 (Page 8 of 9). 3746 Model 950 Control Panel Code

Panel Code	Action to be Taken
053939E3	Error detected at IML. Exchange the FRU Group 2505 on page 1-25, go to page 1-24. If after exchanging, the same code is displayed a microcode problem is suspected. Contact your support structure.
053939E4	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939E5	This panel code indicates that the service processor link test is successful.
053939E7	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939E8	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939E9	Error detected at IML. A microcode problem is suspected. Do an IML with diag, if the same code is displayed contact your support structure.
053939EA	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939EC	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939EE to 053939EF	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939F0	Missing file on MOSS-E. Contact your support structure.
053939F1 to 053939F2	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939F6 and 053939F7	Do an IML with diag, if the same code is displayed a microcode problem is suspected. Contact your support structure.
053939FB to 053939FF	Do an IML with diag. If the same code is displayed, a microcode problem is suspected. Contact your support structure.
053C3C00 to 053C3C08	Progression code during CBSP dump If this code is permanently displayed, do a CBSA IML with diag to confirm the problem.
053C3C0C to 053C3C0D	Progression code during CBSP dump If this code is permanently displayed, do a CBSA IML with diag to confirm the problem.
053C3C50 to 053C3C53	Error code detected during a CBSP dump. Suspect the FRU Group 2521 on page 1-25. Do a CBSA IML with diag to confirm the problem before exchange.
053C3C54 to 053C3C56	Error code detected during a CBSP dump. Connection problem with the MOSS-E. Do a CBSA IML with diag to confirm the problem.
053C3C57 to 053C3C5A	Error code detected during a CBSP dump. Suspect the FRU Group 2521 on page 1-25. Do a CBSA IML with diag to confirm the problem before exchange.
053C3C5C	Error code detected during a CBSP dump. Connection problem with the MOSS-E. Do a CBSA IML with diag to confirm the problem.
053A3A00	IML Progression code
05AEAE2F	IML Progression code. If this code is permanently displayed, exchange the FRU Group 2519 on page 1-25, go to page 1-24.
05AEAE30	IML Progression code. If this code is permanently displayed, suspect a problem in any processor of the 3746-950.
05AEAE31	IML Progression code. If this code is permanently displayed, suspect a microcode error. Contact your support structure.
05AEAE32	IML Progression code. If this code is permanently displayed, suspect a microcode error. Contact your support structure.
05AF0901	Error detected with BATS. Exchange the FRU Group 2513 on page 1-25, go to page 1-24.
05AF0902	Error detected with BATS. Exchange the FRU Group 2510 on page 1-25, go to page 1-24.
05AF0908	Error detected with BATS. Exchange the FRU Group 2510 on page 1-25, go to page 1-24.
05AF0909	Error detected with BATS. Exchange the FRU Group 2513 on page 1-25, go to page 1-24.
05AF09F1	Error detected with BATS. Exchange the FRU Group 2511 on page 1-25, go to page 1-24.
05AF09F2	Error detected with BATS. Exchange the FRU Group 2512 on page 1-25, go to page 1-24.
05AFAF01	Error detected with BATS. Exchange the FRU Group 2513 on page 1-25, go to page 1-24.
05AFAF02	Error detected with BATS. Exchange the FRU Group 2514 on page 1-25, go to page 1-24.

Table 1-3 (Page 9 of 9). 3746 Model 950 Control Panel Code

Panel Code	Action to be Taken
05AFAF03	Error detected with BATS. Exchange the FRU Group 2513 on page 1-25, go to page 1-24.
05AFAF04	Error detected with BATS. Exchange the FRU Group 2514 on page 1-25, go to page 1-24.
05AFAF05	Error detected with BATS. Exchange the FRU Group 2514 on page 1-25, go to page 1-24.
05AFAF08	Error detected with BATS. Exchange the FRU Group 2515 on page 1-25, go to page 1-24.
05AFAF0A	Error detected with BATS. Exchange the FRU Group 2510 on page 1-25, go to page 1-24.
05AFAF0B	Error detected with BATS. Exchange the FRU Group 2516 on page 1-25, go to page 1-24.
05AFAF0E	Error detected with BATS. Exchange the FRU Group 2517 on page 1-25, go to page 1-24.
05AFAF0F	Error detected with BATS. Exchange the FRU Group 2517 on page 1-25, go to page 1-24.
05AFAF10	Error detected with BATS. Exchange the FRU Group 2515 on page 1-25, go to page 1-24.
05AFAF12	Error detected with BATS. Exchange the FRU Group 2510 on page 1-25, go to page 1-24.
05AFAF15	Error detected with BATS. Exchange the FRU Group 2510 on page 1-25, go to page 1-24.
05AFAF1E	Error detected with BATS. Exchange the FRU Group 2517 on page 1-25, go to page 1-24.
05AFAF21	Error detected with BATS. Exchange the FRU Group 2512 on page 1-25, go to page 1-24.
05AFAF22	Error detected with BATS. Exchange the FRU Group 2515 on page 1-25, go to page 1-24.
05AFAF25	Error detected with BATS. Exchange the FRU Group 2515 on page 1-25, go to page 1-24.
05AFAF41	Error detected with BATS. Exchange the FRU Group 2514 on page 1-25, go to page 1-24.
05AFAF42	Error detected with BATS. Exchange the FRU Group 2515 on page 1-25, go to page 1-24.
05AFAFF4	SPS diagnostics successfully ended during BATS.
05AFAFFD	Do an IML with diag, if the same code is displayed, a microcode problem is suspected. Contact your support structure.
05AFAFFE	Do an IML with diag. If the same code is displayed, a microcode problem is suspected. Contact your support structure.
05B0B0F0	The operator activated function 8 (CBC ESCC logical disconnection). The next operation is to press the general IML pushbutton as specified on the control panel.
05B0B0FD	Service processor link restart
05B0B0FE	Service processor link restart. User error
05B0B0FF	Service processor link restart error, a microcode problem is suspected. Contact your support structure.
05C2C269	TIC3 of CBSP unplugged. Check that the TIC3 is correctly plugged in position 07N-A1-F1. If it is correctly plugged, exchange the FRU Group 2506 on page 1-25, go to page 1-24.
05C2C26E	The maintenance switch has been pulled up
05C2C26F	The maintenance switch has been pushed down

Using the MIP FRU Group Table



The MIP FRU group table lists the FRU groups likely to be called in this manual.

- Each FRU group contains from one to three FRUs, listed by name and location.
- The “1st FRU” is the most likely to be failing; the “3rd FRU” is the least likely.
- Usually, only one FRU in an FRU group is failing, and you should **try to reduce the FRU group to the one failing FRU.**
- If you can reproduce the 3746 failure, exchange FRUs one at a time until the failing FRUs are isolated.
- ***As soon as you have recorded the FRU(s) and LOCATION in the FRU GROUP,***
 - ***go to “3746-950 Maintenance Using a FRU list” on page 1-28 for 3746-950 problem.***

ALWAYS

- Ensure that the failing area of the machine is available for service.
- Consult the “Exchange Precautions” on page 4-1 before removing any FRUs.
- Check for loose cards, cables, and crossovers before exchanging FRUs.
- Run diagnostics after any repair action.
- Follow the 'CE leaving' procedure before returning the machine to the customer.

The FRU group table starts on next page.

3746-950 FRU Group Table

<i>Table 1-4. 3746 Model 950 FRU Group</i>			
FRU Group	1st FRU Name Location	2nd FRU Name Location	3rd FRU Name Location
2501	CBSP 07G-A1-F1		
2502	SPS 07G-A1-D1	CBSP 07G-A1-F1	BOARD 07G-A1
2503	SPS 07G-A1-D1	CBSP 07G-A1-F1	
2504	CBSP 07G-A1-F1	TIC3 07N-A1-F1	TIC3 07N-A1-E1
2505	TIC3 07N-A1-F1	CBSP 07G-A1-F1	
2506	TIC3 07N-A1-F1		
2507	TIC3 07N-A1-F1	CBSP 07G-A1-F1	BOARD 07G-A1
2508	TIC3 07N-A1-F1	TIC3 07N-A1-E1	CBSP 07G-A1-F1
2509	CBSP 07G-A1-F1	TIC3 07N-A1-E1	BOARD 07G-A1
2510	SPS 07G-A1-D1	CBSP 07G-A1-F1	BOARD 07G-A1
2511	PANEL	SPD1 07N-A1-A1	SPS 07G-A1-D1
2512	SPS 07G-A1-D1		
2513	CBSP 07G-A1-F1	SPS 07G-A1-D1	BOARD 07G-A1
2514	CBSP 07G-A1-F1	BOARD 07G-A1	
2515	SPS 07G-A1-D1	BOARD 07G-A1	
2516	SPS 07G-A1-D1	BOARD 07G-A1	PANEL
2517	PANEL	SPS 07G-A1-D1	BOARD 07G-A1
2518	CBSP 07G-A1-F1	TIC3 07N-A1-F1	BOARD 07G-A1
2519	CS 07B-A1	CBSP 07G-A1-F1	
2520	CBSP 07G-A1-F1	CS 07B-A1	BOARD 07G-A1
2521	CBSP 07G-A1-F1	TIC3 07N-A1-F1	

3746-950/Service Processor Maintenance Using a CPN

You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

1. On the "MOSS-E VIEW" window, click on "PROGRAM" (in the action bar).
2. Click on "Search CPN".
3. Enter the CPN.
4. The controller icon corresponding to the CPN is highlighted. On the bottom line of the MOSS-E VIEW the type of controller (3745, 3746-900 or 3746-950) and its serial number are displayed. Note the type of controller and double click on the highlighted controller icon.

001

Is a 3745 controller highlighted?

Yes No

002

Is a 3746-900 controller icon highlighted?

Yes No

003

Is a 3746-950 controller icon highlighted?

Yes No

004

Go to Step 013 on page 1-27.

005

Go to Step 008

006

For 3746-900 icon highlighted, stop your investigation using this *Service Guide* and restart it with the appropriate manual: *IBM 3746 Expansion Unit Model 900*, SY33-2116, or *IBM 3745 Communication Controller Models 210 to 61A*, *Maintenance Information Procedures*, SY33-2054, or *IBM 3745 Communication Controller Models 130 to 17A*, *Maintenance Information Procedures*, SY33-2070.

007

For 3745 icon highlighted, stop your investigation using this *Service Guide* and restart it with the appropriate *Maintenance Information Procedures* (MIP).

Use the following MIP according to the 3745 model.

- SY33-2070 for 3745 model 17A
- SY33-2054 for 3745 models 21A to 61A

008

A 3746-950 icon is highlighted.

Are you here for a hardware problem (with FRU)?

Yes No

009

Are you here for a mismatch configuration on 3746-950?

Yes No

010

For a 3746 microcode problem refer to the *Service Processor Installation and Maintenance* manual. Use the "Handling the Microcode Change Levels" procedure in chapter "Maintaining the Service Processor".

011

Go to "MAP 2615: 3746-950 Configuration Mismatch" on page 2-31.

012

- On the "MOSS-E VIEW" window, double click on the 3746-950 on which you want to work.
- The "3746-900 menu" window is displayed.
- Click on the "Problem management" option.
- Double click on the "Perform Maintenance" option.
- The "Resource Selection Options for Maintenance" window is displayed.

On this window, select:

- "By specific Customer Problem Number (CPN)".
- Click on "OK". The "Specific Customer Problem Number" window is displayed.
- Enter the CPN number and click on "OK".
- The "Resource Selector" window shows the location of suspected FRUs and their fault probability.

Note

If a **resource** appears without its resource code, ignore it.

- Record this FRU list with their fault probability. Then go to "3746-950 FRU List" on page 1-29 to identify each FRU.
-

013

The service processor icon is highlighted.

Are you here for a hardware problem (with FRU)?

Yes No

014

For a service processor microcode problem, refer to the *Service Processor Installation and Maintenance* manual. Use the "Handling the Microcode Change Levels" procedure in chapter 3 "Maintaining the Service Processor".

015

- On the "MOSS-E VIEW" window, double click on the service processor.
 - The "Service Processor Menu" window is displayed.
 - Click on the "Problem management" option.
 - Double click on the "Display Alarms" option.
 - The "Display Alarms" window is displayed.
 - Record the SRC number of the alarm which has the CPN corresponding to your call.
 - Return to the "Problem management" window.
 - Double click on the "Manage Alarms/Errors/Events (SRCs)".
 - Select "Alarms" then click on "OK".
 - Double click on the alarm which has the SRC number previously recorded.
 - A FRU or a list of FRUs with the FRU location is displayed.
 - Record this FRU list with their fault probability. Then go to "Service Processor Problem Determination" in the corresponding *Service Processor Installation and Maintenance* manual.
-

3746-950 Maintenance Using an SRC Sequence Number

You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

1. On the "MOSS-E VIEW" window, double click on the 3746-950 on which you want to work.
2. The "3746-9x0 Menu" window is displayed.
3. Click on the "Problem management" option. *
4. The "Problem management functions" window is displayed.
5. Double click on the "Perform Maintenance" option.
6. The "Resource Selection Options for Maintenance" window is displayed.
On this window, select:
 - "By the sequence number of a system reference code".
7. Click on "OK". The "System Reference Code Sequence Number" window is displayed.
8. Enter the SRC sequence number and click on "OK".
9. The "Resource Selector" window is displayed with the FRU suspected and their fault probability.
10. Record this FRU list with their fault probability. Then go to "3746-950 FRU List" on page 1-29 to identify each FRU.

3746-950 Maintenance Using a FRU list

You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

1. On the "MOSS-E VIEW" window, double click on the 3746-950 on which you want to work.
2. The "3746-9x0 Menu" window is displayed.
3. Click on the "Problem management" option.
4. Double click on the "Perform Maintenance" option.
5. The "Resource Selection Options for Maintenance" window is displayed.
On this window, select:
 - "Via the active CDF-E".
6. Click on "OK". The "Resource selector" window is displayed. Go to "3746-950 FRU List" on page 1-29 to identify each FRU.

Service Processor Maintenance Using an SRC Sequence Number

You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

1. On the "MOSS-E VIEW" window, double click on the service processor icon.
2. The "Service Processor Menu" window is displayed.
3. Click on the "Problem management" option.
4. Double click on the "Manage Alarms/Errors/Events (SRCs)" option.
5. Select the "Alarm" option then click on "OK".
6. On the next window double click on the alarm which has the SRC number that you want.
7. A FRU or a list of FRUs with the FRU location is displayed.
8. Record this FRU list with their fault probability. Then go to "Service Processor Problem Determination" in the corresponding *Service Processor Installation and Maintenance* manual.

3746-950 FRU List

The FRU codes for the 3746-950 are listed in alphabetical order in the following list. **Identify** the FRU you are going to work with and **go to the page shown**.

FRU Code	Type	FRU name	Text
ACPW	220	ACPW in 07K/J-A1	Alternative Current power box. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
ACUN	AC0	LAN ring access unit	Go to "MAP 2625: LAN Checking" on page 2-37.
AC1	220	ACPW in 07K-A1	Alternative Current power box. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AC2	220	ACPW in 07J-A1	Alternative Current power box. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
ARC		ARC	ARC type not identified.
ARCG		ARCG	Group of ARCs suspected defective. Go to "MAP 2810: 3746-950 Problem on a Group of ARCs" on page 2-100.
ARCS		ARCS	All ARCs of LCB.
AR1A	010	ARC1A1	V 24 DCE attachment with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1B	120	ARC1B	V 24 DTE attachment with 15 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1C	090	ARC1C	V 24 DCE 3745 interface with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1D	0A0	ARC1D	V 24 DTE 3745 interface with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1E	110	ARC1A2	V 24 DCE attachment with 15 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1F	DB0	ARC1AX	ARC V.24 without cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1G	C10	ARC1A0	ARC V.24 with cable to DCE attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1H	C20	ARC1B0	ARC V.24 with cable to DTE attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1J	C90	ARC1C0	ARC V.24 with cable to DCE 3745 attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR1K	CA0	ARC1D0	ARC V.24 with cable to DTE 3745 attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3A	040	ARC3A1	V 35 DCE attachment with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3B	150	ARC3B	V 35 DTE attachment with 15 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3C	0C0	ARC3C	V 35 DCE 3745 interface with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3D	0D0	ARC3D	V 35 DTE 3745 interface with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3E	140	ARC3A2	V 35 DCE attachment with 15 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3F	D50	ARC3AX	ARC V.35 without cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3G	C40	ARC3A0	ARC V.35 with cable to DCE attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.

3746-950 FRU List

FRU Code	Type	FRU name	Text
AR3H	C50	ARC3B0	ARC V.35 with cable to DTE attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3J	CC0	ARC3C0	ARC V.35 with cable to DCE 3745 attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3K	CD0	ARC3D0	ARC V.35 with cable to DTE 3745 attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3L	DC0	ARC3CX	ARC V.35 3745 DCE without cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR3M	DD0	ARC3DX	ARC V.35 3745 DTE without cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4A	060	ARC4A1	X 21 DCE attachment with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4E	160	ARC4A2	X 21 DCE attachment with 15 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4F	260	ARC4A3	X 21 DCE attachment with 5 m tethered cable (transfix). Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4G	360	ARC4A4	X 21 DCE attachment with 15 m tethered cable (transfix). Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4B	070	ARC4B	X 21 DTE attachment with 15 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4C	0E0	ARC4C	X 21 DCE 3745 interface with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4D	0F0	ARC4D	X 21 DTE 3745 interface with 5 m tethered cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4H	FF0	ARC4AX	ARC X.21 without cable. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4J	E60	ARC4A0	ARC X.21 with cable to DCE attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4K	E70	ARC4B0	ARC X.21 with cable to DTE attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4L	EE0	ARC4C0	ARC X.21 with cable to DCE 3745 attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4M	EF0	ARC4D0	ARC X.21 with cable to DTE 3745 attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
AR4N	C60	ARC4E0	ARC X.21 with cable Transfix to DCE attached. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
BAS	310	Basic Board 07N-A1	Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
BOAR	300	Board	Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
CAB2	620	Cable	Cable assembly cooling control. This cable is suspected. In order to more precisely identify the defective FRU, go to "MAP 2635: 3746-950 Several Fans Are in Errors" on page 2-43.
CAB9	690	Cable	Cable DC distribution to FANs and connectivity switch (CS). This cable is suspected. In order to more precisely identify the defective FRU, go to "MAP 2635: 3746-950 Several Fans Are in Errors" on page 2-43.
CABA	6A0	Cable	Cable Pres/reset from SPD1 to SPD2. This cable is suspected. In order to more precisely identify the defective FRU, go to "MAP 2640: 3746-950 Cable From SPD1 to SPD2" on page 2-45.
CABB	780	Cable	Cable from SIE cassette to SAC into the Multiaccess Enclosure. This cable is suspected. In order to more precisely identify the defective FRU, go to "MAP 2655: 3746-950 Cable From SIE to SAC in Multiaccess Enclosure" on page 2-49.

FRU Code	Type	FRU name	Text
CABC	6C0	Cable	Cable power signals/control from SPD1 to SPD2. This cable is suspected. In order to more precisely identify the defective FRU, go to "MAP 2645: 3746-950 Cable From DCDP to SPD1" on page 2-47.
CABD	6D0	Cable	Cable power signals/control from SPD1 to panel. This cable is suspected. In order to more precisely identify the defective FRU, go to "MAP 2650: 3746-950 Signal Power cable from SPD1 to the Control Panel" on page 2-48.
CABM	770	Cable	Cable between LIC11 and LCBB. This cable is suspected. In order to more precisely identify the defective FRU, go to "MAP 2820: 3746-950 Problem on a LIC11" on page 2-105.
CAB4	640	SL Cable	The 3746-950 service logic is suspected. In order to more precisely identify the defective FRU, go to "MAP 2630: 3746-950 Service Logic Problem" on page 2-38.
CBSP	850 8A0	CBSP CBSP2 CBSP3	Controller bus and service processor Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
CLP	820 870	CLP CLP3	Communication line processor. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
CSCE	200	CSCE	Connectivity switch cable extension cassette. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
CS	580	CS	Connectivity switch. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DCDC	290	DCDC for Processor	Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DCDP	210	DCDP	Direct Current power distribution board Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DCPW	240	DCPW	Direct current power distribution box. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DCSW	2A0	DCDC for CS	Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DRW1	250	Fan Drawer 1	(Fans 1 and 2) Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DRW2	250	Fan Drawer 2	(Fans 3 and 4) Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DRW3	250	Fan Drawer 3	(Fans 5 and 6) Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
DSKP	470	HDD of MAE System card	Hardware disk drive located on the multiaccess enclosure system card. For exchanging this FRU, refer to the <i>Multiaccess Enclosure Installation and Maintenance</i> manual.
ENCL	340	Enclosure	Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
ESCC	410	ESCC ESCC2	Enterprise system connection coupler. ESCC and ESCC2 are identified by EC. Use "MAP: 3746-950 FRU Exchange" on page 1-33.
ESCP	830 880	ESCP ESCP2 ESCP3	Enterprise system connection processor. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
FILT	260	Air Filter in 07G	Go to "3746-950 Maintenance Using a FRU list" on page 1-28. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
LCBB		LCBB	Line connection enclosure expansion (board + enclosure + LCPB).
LCBE		LCBE	Line connection enclosure expansion (board + enclosure + LCPE).
LCEE	5E0	LCEE	Line connection enclosure expansion (board + enclosure). Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
LCEB	5F0	LCEB	Line connection enclosure base (board + enclosure). Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
LCPB	510	LCPB	DC/DC converter and logic card for LCBB. If the LIC11 FRU is also present in the FRU list, check it first (whatever its fault probability is). Refer to "MAP: 3746-950 FRU Exchange" on page 1-33.

3746-950 FRU List

FRU Code	Type	FRU name	Text
LCPE	5B0	LCPE	DC/DC converter for LCBE. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
LIC11 LICA	590	LIC11	Line interface coupler type 11. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
LIC12 LICC	520	LIC12	Line interface coupler type 12. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
MAE	870	MAE Problem	Suspect a multiaccess enclosure problem which can be the SIE card, the SAC card, or the cable between SIE and SAC. Perform problem determination using the <i>Multiaccess Enclosure Installation and Maintenance</i> manual.
PNL1	2D0	Control panel 07A-A1	Operator panel card of the control panel. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
PNL2	2E0	Control panel 07A-A1	Keyboard display card of the control panel. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
PPC	460	System Control Card	System control card of the Multiaccess Enclosure. For exchanging this FRU refer to the <i>Multiaccess Enclosure Installation and Maintenance</i> manual.
SAC	450	Switch attach- ment card	Switch attachment card of the Multiaccess Enclosure. For exchanging this FRU refer to the <i>Multiaccess Enclosure Installation and Maintenance</i> manual.
SIE	440	SIE	Switch interface extender card. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
SPD1	270	SPD1	Signal and power distribution cassette (base enclosure). Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
SPD2	280	SPD2	Signal and power distribution cassette (expansion enclosure). Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
SPS	5C0	SPS	Service and power support card. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
TRFM	2B0	Transformer	Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
TIC3	420	TIC3	Token ring coupler type 3. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
TRF1	2B0	Transformer	Transformer for AC1. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
TRF2	2B0	Transformer	Transformer for AC2. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
TRP	840 890	TRP TRP2 TRP3	Token ring processor. Go to "MAP: 3746-950 FRU Exchange" on page 1-33.
WLOB	AD0	Wire/cable to ring access unit	Go to "MAP 2625: LAN Checking" on page 2-37.

MAP: 3746-950 FRU Exchange

When using MOSS-E, use the Help facility if you need any help on the window. If you are not familiar with the MOSS-E window environment, refer to the *Basic Operations Guide, SA33-0177*.

You are here because you entered in maintenance mode with a CPN, SRC sequence number, or an FRU list.

001

Do you have to change a fan drawer and/or air filter on your 3746-950?

Yes No

002

Go to Step 005

003

Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the fan drawer or the air filter, then return here.

Do you have an other FRU to exchange?

Yes No

004

- Return to the "MOSS-E View" window.
- Go to "CE Leaving Procedure" on page 4-53.

005

The maintenance mode depends of the state of the machine, thus before continuing, it is important to check it in the following order.

Status of the 3746-950 LEDs on control panel	Action
CBSA Check LED ON	Go to "MAP: CBSA Check LED ON" on page 1-35
Ready AND Standby LEDs are OFF	Go to "MAP: Ready and Standby LEDs are OFF" on page 1-36
Standby LED is blinking	Go to "MAP: Standby LED Blinking" on page 1-39
Standby LED is ON	Go to "MAP: Standby LED ON" on page 1-42
Ready LED is blinking	Go to "MAP: Ready LED Blinking" on page 1-48
Ready LED is ON	Go to Step 006

006

Is there a character displayed in the "Service processor not accessible" window on the 3746-950 control panel?

Yes No

007

Ask to the customer if there is traffic on the 3746-950.

Is there customer traffic on the 3746-950?

Yes No

008

Go to "MAP: 3746-950 in Offline Mode" on page 1-114.

009

Go to "3746-950 FRU list for exchange" on page 1-54.

010

(Step **010** continues)

010 (continued)

Go to "MAP: Ready LED ON" on page 1-51.

MAP: CBSA Check LED ON**001**

- You do not have the possibility to put the suspected FRU in concurrent mode and to run diagnostics. Nevertheless, follow these steps:
 - On the "Resource Selector" window, select the CBSP then click on "OK".
 - On the following "Resource Selector" window, select the CBSP then click on "OK".
 - The "Confirmation" window is displayed. Click on "OK".
 - A new window informs you that you cannot put the FRU in concurrent mode (The concurrent mode request will however be saved by the MOSS-E and taken into account at the next IML, and the FRU will be set in concurrent mode).
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the CBSP, then return here.

Is the CBSA check LED ON again.**Yes No****002**

Problem solved.

- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the Resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected, then click on "Start".
- A "Specific Adapter" window is displayed. Select the "CBSP" and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?**Yes No****003**

Call your support for assistance.

004

- Using the "Cancel" key, return to the "Maintenance Options" window.
- On the "Maintenance Options" window, select "Initialize Resource" and click on "OK".
- Select the "Remove from Concurrent Mode" option and click on "OK".
- On the "Resource Selector" window, click on "Cancel".
- Return to the "3746-9x0 Menu" window.

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

005

Call your support for assistance

MAP: Ready and Standby LEDs are OFF

Before starting this MAP be sure that the unit emergency switch is ON.

001

Set the 3746-950 to Offline mode.

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem management" option.
- Double click on the "Set 3746-9x0 Online/Offline Option".
- On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
- On the next "Set 3746-9x0 Online/Offline" window, click on "OK".

Is there a backup ACPW or DCPW installed in your 3746-950?

Yes No

002

Go to Step 008.

003

Check the position of CB1 on both power supplies.

Are both CB1s in the ON position?

Yes No

004

Switch both CB1s to the ON position.

Is the 3746-950 powering ON now with its standby LED blinking?

Yes No

005

Go to Step 025 on page 1-38.

006

Go to Step 012.

007

Go to Step 012.

008

Check the position of CB1 on the Basic ACPW box.

Is CB1 in the ON position?

Yes No

009

Switch CB1 to the ON position.

Is the 3746-950 powering ON now with its standby LED blinking?

Yes No

010

Go to Step 012.

011

Go to Step 025 on page 1-38.

012

- Switch the CB1(s) OFF on your 3746-950.
- (Step 012 continues)

012 (continued)

- Go to Chapter 4, “3746-950 FRU Exchange” on page 4-1 to exchange the FRU on your FRU list which has the highest fault probability, then return here.
- Switch the CB1(s) ON.

Is the 3746-950 powering ON now with its standby LED blinking?**Yes No****013****Is there an other FRU in your FRU list for exchange?****Yes No****014**

Restart the problem determination. Go to “MAP 2500: 3746-950 Power Control Subsystem Problems” on page 2-4.

015

- Switch the CB1(s) OFF on your 3746-950.
- Go to Chapter 4, “3746-950 FRU Exchange” on page 4-1 to:
 - Remove the previously installed FRU.
 - Exchange the next FRU of your FRU list then return here.
- Switch the CB1(s) ON.

Is the 3746-950 powering ON now with its standby LED blinking?**Yes No****016**

Go to Step 013

017

Go to Step 018.

018

After a power ON the standby LED blinks for about 20 seconds. Afterwards the standby LED is ON, or else the ready LED blinks until the end of IML and then comes permanently ON.

Is the ready LED ON?**Yes No****019****Is the standby LED ON?****Yes No****020**

You have another problem. Restart the problem determination. Go to “MAP 2500: 3746-950 Power Control Subsystem Problems” on page 2-4.

021

- Press the 'Start' key on the 3746-950 control panel.
- Wait for about 3 minutes at the end of IML.

Is the Ready LED ON?**Yes No****022**

You have another problem. Restart the problem determination. Go to “MAP 2500: 3746-950 Power Control Subsystem Problems” on page 2-4.

023

Go to “MAP: 3746-950 Ending Exchange Procedure After Power ON” on page 1-125

3746-950 FRU Exchange

024

Go to "MAP: 3746-950 Ending Exchange Procedure After Power ON" on page 1-125

025

After a power ON the standby LED blinks for about 20 seconds. Afterwards the standby LED is ON, or else the ready LED blinks until the end of IML and then comes permanently ON.

Is the standby LED permanently blinking?

Yes No

026

Is the standby LED permanently ON?

Yes No

027

Is the ready LED permanently blinking (more than 3 mn)?

Yes No

028

Ready LED is ON. Go to Step 032

029

Go to "MAP: Ready LED Blinking" on page 1-48

030

Go to "MAP: Standby LED ON" on page 1-42.

031

Go to "MAP: Standby LED Blinking" on page 1-39.

032

Is there a character displayed in the "Service processor not accessible" window on the 3746-950 control panel?

Yes No

033

Problem solved. Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

034

Go to "MAP: Ready LED ON" on page 1-51.

MAP: Standby LED Blinking

You are here because the 3746-950 has its standby LED blinking permanently.

001

- Set the 3746-950 to Offline mode if not already done.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem management" option.
 - Double click on the "Set 3746-9x0 Online/Offline Option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK".
 - Select the FRU of your FRU list with the highest fault probability, then go to Step 002
-

002

Is this FRU the CBSP or the TIC3 of CBSP?

Yes No

003

Go to Step 005.

004

- If you change the CBSP, go to Step 026 on page 1-41.
 - If you change the TIC3 of the CBSP, go to Step 018 on page 1-40
-

005

- Switch the CB1(s) OFF on your 3746-950.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the selected FRU, then return here.
- Switch the CB1(s) ON.
- After a power ON the standby LED blinks for about 20 seconds. Afterwards the standby LED is ON, or else the ready LED blinks until the end of IML (about 3 minutes) and then comes permanently ON.

Is the 3746-950 standby LED permanently blinking (more than 30 seconds)?

Yes No

006

Go to Step 010.

007

Is there another FRU in your FRU list for exchange?

Yes No

008

Call support for assistance.

009

- Switch the CB1(s) OFF on your 3746-950.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to remove the FRU previously installed.
 - Switch the CB1(s) ON.
 - Go to Step 002 to exchange the next FRU.
-

010

Is the Standby LED ON?

Yes No

011

(Step 011 continues)

011 (continued)

Is the ready LED blinking?

Yes No

012

Go to Step 015.

013

- Wait for about 3 minutes at the end of IML.
 - Go to Step 015.
-

014

- Press the 'Start' key on the 3746-950 control panel.
 - Wait for about 3 minutes at the end of IML.
 - Go to Step 015.
-

015

Is the Ready LED ON?

Yes No

016

You have another problem. Restart the problem determination. Go to "MAP 2500: 3746-950 Power Control Subsystem Problems" on page 2-4.

017

Go to "MAP: 3746-950 Ending Exchange Procedure After Power ON" on page 1-125

018

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the TIC3 replacement and after replacing the FRU, continue this procedure.

Did you replace the TIC3 by a new one?

Yes No

019

Go to Step 023 on page 1-41

020

- Press the 'Exit' key on the 3746-950 control panel.

Is 00000000 displayed on the 3746-950 control panel?

Yes No

021

- Changing the TIC3 did not solve the problem. Reinstall the TIC3 that was previously removed by following the next two steps.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement, then after FRU replacement return here to continue this procedure.
- Press the 'Exit' key on the 3746-950 control panel. then go to Step 023 on page 1-41.

022

- The TIC3 of the CBSP has been successfully changed. There is no diagnostic for this FRU.
 - As you were here because the 3746-950 had its standby LED blinking permanently, and now that it is IMLED, you have solved your problem.
 - Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.
-

023

(Step 023 continues)

023 (continued)

Is there another FRU to exchange in your FRU list?

Yes No

024

Call support for assistance.

025

Go to Step 002 on page 1-39 to exchange the next FRU.

026

- Go to Chapter 4, “3746-950 FRU Exchange” on page 4-1 for the CBSP replacement and after the CBSP replacement, continue this procedure.

Did you replace the CBSP by a new one?

Yes No

027

Is there another FRU to exchange in your FRU list?

Yes No

028

Call support for assistance.

029

Go to Step 002 on page 1-39 to exchange the next FRU.

030

- The CBSP has been successfully changed.
 - As you were here because the 3746-950 had its standby LED blinking permanently, now that it is IMLed, you have solved your problem.
 - Go to “MAP: 3746-950 Ending Procedure In Offline Mode” on page 1-126.
-

MAP: Standby LED ON

You are here because the 3746-950 has its standby LED ON. This state is usually a normal state, but in order to have all the diagnostics facilities the 3746-950 must be IMLed with its ready LED ON.

001

Set the 3746-950 to Offline mode if not already done.

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem management" option.
- Double click on the "Set 3746-9x0 Online/Offline Option".
- On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
- On the next "Set 3746-9x0 Online/Offline" window, click on "OK".

Is the "power control" mode (1) or (3) displayed on the 3746-950 control panel?

Yes No

002

- Select the FRU of your FRU list with the highest fault probability.
- Go to Step 006.

003

Go to Step 014 on page 1-43.

004

Is there another FRU to exchange in your FRU list?

Yes No

005

Call support for assistance.

006

Is this FRU the CBSP or the TIC3 of CBSP?

Yes No

007

Go to Step 009.

008

- If you change the CBSP, go to Step 061 on page 1-47.
 - If you change the TIC3 of the CBSP, go to Step 056 on page 1-46.
-

009

- Switch the CB1(s) OFF on your 3746-950.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the FRU on your FRU list which has the highest fault probability, then return here.
- If not already done, switch the CB1(s) ON.

Is the "power control" mode displayed on the 3746-950 control panel?

Yes No

010

Is there another FRU in your FRU list for exchange?

Yes No

011

Call support for assistance.

012

(Step 012 continues)

012 (continued)

- Switch the CB1(s) OFF on your 3746-950.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to remove the FRU previously installed
 - If not already done, switch the CB1(s) ON.
 - Go to Step 006 on page 1-42 to exchange the next FRU of your FRU list.
-

013

- You have found a problem. Nevertheless, continue this procedure.
 - Go to Step 014
-

014

Is the "power control" display set to (3) on the 3746-950 control panel?

Yes No

015

Do the following:

- Press the "power control" key until (3) is displayed in the power control window.
- Press the "validate" key.

Did you succeed in changing the "power control" mode.

Yes No

016

Go to Step 037 on page 1-45.

017

Go to Step 018.

018

- Press on the "start" key on the 3746-950 control panel.

Does the ready LED start to blink?

Yes No

019

- Select the FRU on your FRU list with the highest fault probability.
- Go to Step 027 on page 1-44

020

- A normal IML is terminated when 00000000 is displayed on the control panel and the ready LED comes ON after about 3 minutes. In case a problem occurs during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

Does the ready LED come steady ON?

Yes No

021

Go to "MAP: Ready LED Blinking" on page 1-48.

022

Did you change an FRU during this procedure?

Yes No

023

(Step 023 continues)

3746-950 FRU Exchange

023 (continued)

Go to "MAP: 3746-950 in Offline Mode" on page 1-114.

024

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

025

Is there another FRU to exchange in your FRU list?

Yes No

026

Call support for assistance.

027

Is this FRU the CBSP or the TIC3 of CBSP?

Yes No

028

Go to Step 030.

029

- If you change the CBSP, go to Step 061 on page 1-47.
 - If you change the TIC3 of the CBSP, go to Step 056 on page 1-46
-

030

- Switch the CB1(s) OFF on your 3746-950.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the FRU on your FRU list which has the highest fault probability, then return here.
- If not already done, switch the CB1(s) ON.
- When the standby LED is ON, press the start key.

Does the ready LED start to blink?

Yes No

031

Is there another FRU in your FRU list for exchange?

Yes No

032

Call support for assistance.

033

- Switch the CB1(s) OFF on your 3746-950.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to remove the FRU previously installed
 - If not already done, switch the CB1(s) ON.
 - Go to Step 027 to exchange the next FRU of your FRU list.
-

034

- You have found a problem. Nevertheless continue this procedure.
- A normal IML is terminated when 00000000 is displayed on the control panel and the ready LED comes ON after about 3 minutes. In case a problem occurs during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

(Step **034** continues)

034 (continued)

Is the ready LED Steady ON?

Yes No

035

Go to "MAP: Ready LED Blinking" on page 1-48.

036

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

037

- You are here because the 3746-950 "power control" mode is set to remote mode and you cannot change it. So you can be stopped at this state (standby LED ON) because of the 3746-950 problem or because the other units connected are not powered ON. In the following procedure after power ON, the 3746-950 can stop with a standby LED ON or continue its IML with the ready LED blinking.
 - Select the FRU on your FRU list with the highest fault probability.
 - Go to Step 040.
-

038

Is there another FRU to exchange in your FRU list?

Yes No

039

Call support for assistance.

040

Is this FRU the CBSP or the TIC3 of the CBSP?

Yes No

041

Go to Step 043.

042

- If you change the CBSP, go to Step 061 on page 1-47.
 - If you change the TIC3 of the CBSP, go to Step 056 on page 1-46
-

043

- Switch the CB1(s) OFF on your 3746-950.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the FRU on your FRU list with the highest fault probability, then return here.
- If not already done, switch the CB1(s) ON, then wait about 30 seconds.

Does the standby LED stay ON?

Yes No

044

Go to Step 049 on page 1-46.

045

Do the following:

- Press the "power control" key until (3) is displayed in the power control window.
- Press the "validate" key.

(Step **045** continues)

3746-950 FRU Exchange

045 (continued)

Did you succeed in changing the "power control" mode?

Yes No

046

Is there another FRU in your FRU list for exchange?

Yes No

047

Call support for assistance.

048

- Switch the CB1(s) OFF on your 3746-950.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to remove the FRU previously installed
 - If not already done, switch the CB1(s) ON.
 - Go to Step 040 on page 1-45 to exchange the next FRU on your FRU list.
-

049

- You have found a problem. Nevertheless continue this procedure.
- Press the "Start" key on the 3746-950 control panel.

After pressing the start key, the ready LED should blink until the end of IML with 00000000 displayed on the control panel and the ready LED ON. In case a problem occurs during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

Does the ready LED start to blink?

Yes No

050

Is there another FRU in your FRU list for exchange?

Yes No

051

Call support for assistance.

052

- Switch the CB1(s) OFF on your 3746-950.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to remove the FRU previously installed
 - If not already done, switch the CB1(s) ON.
 - Go to Step 040 on page 1-45 to exchange the next FRU of your FRU list.
-

053

Wait about 3 minutes for the IML to end.

Is the ready LED ON?

Yes No

054

Restart the problem determination. Go to "MAP: Ready LED Blinking" on page 1-48.

055

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126

056

(Step 056 continues)

056 (continued)

- Go to Chapter 4, “3746-950 FRU Exchange” on page 4-1 for the TIC3 replacement. After replacing the FRU, continue this procedure.

Did you replace the TIC3 by a new one?

Yes No

057

Go to Step 064.

058

- Press the 'Exit' key on the 3746-950 control panel.

Is 00000000 displayed on the 3746-950 control panel?

Yes No

059

- Changing the TIC3 did not solve the problem. Reinstall the TIC3 previously removed using the following steps.
- Go to Chapter 4, “3746-950 FRU Exchange” on page 4-1 for the FRU replacement. Then after replacing the FRU, return here to continue this procedure.
- Press the 'Exit' key on the 3746-950 control panel. Then go to Step 064.

060

The TIC3 has been successfully changed. Go to “MAP: 3746-950 Ending Procedure In Offline Mode” on page 1-126.

061

- Go to Chapter 4, “3746-950 FRU Exchange” on page 4-1 for the CBSP replacement. After replacing the CBSP, continue this procedure.

Did you replace the CBSP by a new one?

Yes No

062

Go to Step 064.

063

- The CBSP has been successfully changed.
 - Since you were here because the 3746-950 was blocked with the standby LED ON, now that it is IMLed, you have solved the problem.
 - Go to “MAP: 3746-950 Ending Procedure In Offline Mode” on page 1-126.
-

064

Continue the procedure according to the table below:

If you are here because:	Go to:
The "power control" mode (1) or (3) is not displayed	Step 004 on page 1-42
You can not change the "power control" mode	Step 038 on page 1-45
After pressing the 'start' key on the 3746-950 control panel, the ready LED does not blink.	Step 025 on page 1-44

MAP: Ready LED Blinking

You are here because the 3746-950 has its ready LED blinking with an error control panel code permanently displayed or flashing.

001

- Set the 3746-950 to Offline mode if not already done.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem management" option.
 - Double click on the "Set 3746-9x0 Online/Offline Option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK".
 - Select the FRU on your FRU list with the highest fault probability, then go to Step 002.
-

002

Is this FRU the CBSP or the TIC3 of the CBSP?

Yes No

003

Go to Step 005.

004

- If you change the CBSP go, to Step 026 on page 1-50.
 - If you change the TIC3 of the CBSP, go to Step 018 on page 1-49
-

005

- Switch the CB1(s) OFF on your 3746-950.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the FRU on your FRU list with the highest fault probability, then return here.
- If not already done, switch the CB1(s) ON.
- After a power ON the standby LED blinks for about 20 seconds. Then it should remain ON, **or** else the ready LED blinks until the end of IML (about 3 minutes) and then comes permanently ON.

Is the Standby LED ON?

Yes No

006

Is the ready LED blinking?

Yes No

007

Go to Step 010

008

- Wait for about 3 minutes at the end of IML.
 - Go to Step 013 on page 1-49.
-

009

- Press the 'Start' key on the 3746-950 control panel.
 - Wait for about 3 minutes at the end of IML.
 - Go to Step 013 on page 1-49.
-

010

(Step **010** continues)

010 (continued)

Is the ready LED ON?

Yes No

011

You have another problem. Suspect the FRU that you exchanged. Restart the problem determination. Go to "MAP 2500: 3746-950 Power Control Subsystem Problems" on page 2-4.

012

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126

013

Is the ready LED ON?

Yes No

014

Is there another FRU in your FRU list for exchange?

Yes No

015

Call your support for assistance.

016

- Switch the CB1(s) OFF on your 3746-950.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to remove the FRU previously installed
 - Exchange the next FRU on your FRU list. Then return here.
 - If not already done, switch the CB1(s) ON.
 - Go to Step 002 on page 1-48 to exchange the next FRU.
-

017

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126

018

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the TIC3 replacement. After replacing the FRU, continue this procedure.

Did you replace the TIC3 by a new one?

Yes No

019

Go to Step 023 on page 1-50

020

- Press the 'Exit' key on the 3746-950 control panel.

Is 00000000 displayed on the 3746-950 control panel?

Yes No

021

- Changing the TIC3 did not solve the problem. Reinstall the previously removed TIC3 by following the next two steps.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU return here to continue this procedure.
- Press the 'Exit' key on the 3746-950 control panel. Then go to Step 023 on page 1-50.

022

(Step **022** continues)

3746-950 FRU Exchange

022 (continued)

- The TIC3 of the CBSP has been successfully changed. There is no diagnostic for this FRU.
 - Since you were here because the 3746-950 had its ready LED blinking permanently, now that it is IMLed, you have solved your problem.
 - Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.
-

023

Is there another FRU to exchange in your FRU list?

Yes No

024

Call support for assistance.

025

Go to Step 002 on page 1-48 to exchange the next FRU.

026

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the CBSP replacement and after the CBSP replacement, continue this procedure.

Did you replace the CBSP by a new one?

Yes No

027

Is there another FRU to exchange in your FRU list?

Yes No

028

Call support for assistance.

029

Go to Step 002 on page 1-48 to exchange the next FRU.

030

- The CBSP has been successfully changed.
 - Since you were here because the 3746-950 had its ready LED blinking permanently, now that it is IMLed, you have solved your problem.
 - Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.
-

MAP: Ready LED ON

You are here because the 3746-950 has:

- Its ready LED ON
- A character displayed in the "Service processor not accessible" window on the 3746-950 control panel.

001

There is no link between the 3746-950 and the service processor.

Is the CBSP and/or its associated TIC3 and/or the basic board in your FRU list?

Yes No

002

You have another problem on your 3746-950. Go to "MAP 2750: 3746-950 Permanent Service Processor Link Problem" on page 2-84 for problem determination.

003

- Select the FRU in your FRU list with the highest fault probability.
 - If the TIC3 has the highest fault probability, go to Step 004
 - If the CBSP has the highest fault probability, go to Step 018 on page 1-52
 - If the basic board has the highest fault probability, go to "MAP: 3746-950 in Offline Mode" on page 1-114.
-

004

- Ask the customer to stop traffic on the TIC3 of the CBSP.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the TIC3 replacement. After replacing the TIC3, continue this procedure.

Did you replace the TIC3 by a new one?

Yes No

005

Go to Step 015 on page 1-52.

006

- Press the 'Exit' key on the 3746-950 control panel.

Is 00000000 displayed on the 3746-950 control panel?

Yes No

007

Go to Step 010.

008

Is there a character displayed in the "Service processor not accessible" window on the 3746-950 control panel?

Yes No

009

- The TIC3 of the CBSP has been successfully changed. There is no diagnostic for this FRU.
- Since you were here because there was no link between the 3746-950 and the service processor, you have solved your problem.
- Go to Step 025 on page 1-53.

010

- Changing the TIC3 did not solve the problem. Reinstall the TIC3 previously removed using the following steps.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement, then after FRU replacement return here to continue this procedure.
- (Step 010 continues)

3746-950 FRU Exchange

010 (continued)

- Press the 'Exit' key on the 3746-950 control panel.

Is 00000000 displayed on the 3746-950 control panel?

Yes No

011

The TIC3 is defective. Order a new one and restart the exchange procedure.

012

Is there a character displayed in the "Service processor not accessible" window on the 3746-950 control panel.

Yes No

013

The problem no longer exists. Suspect a connection problem. Go to Step 025 on page 1-53.

014

Go to Step 015

015

Is there the CBSP or the basic board in your FRU list?

Yes No

016

Call support for assistance.

017

- Go to Step 018 to exchange the CBSP if not already done.
 - Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to exchange the basic board if it is in your FRU list.
 - Otherwise call your support for assistance.
-

018

- Ask the customer to stop all traffic from the 3745.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the CBSP replacement and after the CBSP replacement, continue this procedure.

Did you replace the CBSP by a new one?

Yes No

019

Is there the TIC3 of the CBSP or the basic board in your FRU list?

Yes No

020

Call your support for assistance.

021

- Go to Step 004 on page 1-51 to exchange the TIC3 if not already done.
 - Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to exchange the basic board if it is in your FRU list.
 - Otherwise call your support for assistance.
-

022

(Step **022** continues)

022 (continued)

Is there a character displayed in the "Service processor not accessible" window on the 3746-950 control panel?

Yes No

023

- The CBSP has been successfully changed.
- Since you were here because there was no link between the 3746-950 and the service processor, you have solved your problem.
- Go to Step 025.

024

- Changing the CBSP did not solve the problem. Reinstall the CBSP previously removed using the following steps.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement, then after FRU replacement return here to continue this procedure.
- Go to Step 004 on page 1-51 to exchange the TIC3 if not already done.
- Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to exchange the basic board if it is in your FRU list.
- Otherwise call your support for assistance.

025

- As you change an FRU, this FRU is automatically set to concurrent mode. Now you must get the FRU installed out of concurrent mode using the following steps.
 - Return to the "3746-9x0 Menu".
 - Click on the "Problem Management" option.
 - Double click on the "Perform Maintenance"
 - On the "Resource Selection Option for Maintenance" window, select the "Via active CDF-E" option and click on "OK".
 - On the next three "Resource Selector" windows that are displayed, select the FRU you have exchanged and click on "OK".
 - On the "Maintenance Options" window, select the "Remove the resource from the concurrent mode" option, then click on "OK".
 - On the "Warning" window, click on "OK".
- Before returning the machine to the customer, check on the CDF-E that all the resources of your 3746-950 are available or active.
 - Using the "Cancel" key, return to the "3746-9x0 Menu" window.
 - Click on the "Configuration Management" option.
 - Double click on the "Display/update Active Configuration (CDF-E) option.
 - The contents of the active CDF-E is displayed.

Are the CBSP and its associated TIC3 available or active now?

Yes No

026

Call your support.

027

- Then go to Step 028.

028

- Return to the "3746-9x0 Menu" window.
 - Click on "Function" (in the action bar).
 - Click on the "Exit" option.
- If you have changed the power control mode from remote to local, set it back to remote mode:
 - Press the 'Power control' key until (1) is displayed in the power control window.
 - Press the 'Validate' key.

Inform the customer that the resource(s) is(are) now available, then go to "CE Leaving Procedure" on page 4-53.

3746-950 FRU list for exchange

Important

Before selecting a FRU for exchange, be sure that the 'power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.


If the state of the machine does not allow knowing or changing this 'Power Control' mode, continue this procedure.

The first time you use this FRU table, select the FRU on your FRU list with the highest fault probability (except when that was specified before).

The second time you use this FRU table, select the FRU on your FRU list with the second highest fault probability, and so on.

Select FRU	Action
ARC	"MAP: ARC" on page 1-56
ACPW	"3746-950 ACPW, DCPW, Transformer" on page 1-113
Board	"MAP: 3746-950 in Offline Mode" on page 1-114
CBSP/CBSP2/CBSP3	"MAP: CBSP/CBSP2/CBSP3" on page 1-61
Control Panel	"MAP: 3746-950 SPS, Control Panel" on page 1-111
CLP/CLP3	"MAP: CLP/CLP3" on page 1-64
CS	"MAP: 3746-950 in Offline Mode" on page 1-114
CSCE	"MAP: 3746-950 in Offline Mode" on page 1-114
DCDC of CBSP/CBSP2/CBSP3	"MAP: CBSP/CBSP2/CBSP3" on page 1-61
DCDC of CLP	First check the state of CP3, CP4, or CP5. If one or several CP(s) are OFF go to "MAP 2605: 3746-950 Either CP3, CP4, CP5, CP6, or CP7 is Tripped" on page 2-26 otherwise go to "MAP: CLP/CLP3" on page 1-64
DCDC of CS	"MAP: 3746-950 in Offline Mode" on page 1-114
DCDC of ESCP/ESCP2/ESCP3	First check the state of CP3, CP4, or CP5. If one or several CP(s) are OFF go to "MAP 2605: 3746-950 Either CP3, CP4, CP5, CP6, or CP7 is Tripped" on page 2-26 otherwise go to "MAP: ESCC/ESCC2/ESCP/ESCP2/ESCP3" on page 1-75
DCDC of TRP/TRP2/TRP3	First check the state of CP3, CP4, or CP5. If one or several CP(s) are OFF go to "MAP 2605: 3746-950 Either CP3, CP4, CP5, CP6, or CP7 is Tripped" on page 2-26 otherwise go to "MAP: TRP/TRP2/TRP3" on page 1-81
DCDP	"MAP: 3746-950 in Offline Mode" on page 1-114
DCPW	"3746-950 ACPW, DCPW, Transformer" on page 1-113
Enclosure	"MAP: 3746-950 in Offline Mode" on page 1-114
ESCC/ESCC2	"MAP: ESCC/ESCC2/ESCP/ESCP2/ESCP3" on page 1-75
ESCP/ESCP2	"MAP: ESCC/ESCC2/ESCP/ESCP2/ESCP3" on page 1-75
LCEB	"MAP: LCPB, LCPE, LCEB, LCEE" on page 1-88
LCEE	"MAP: LCEE" on page 1-86
LCPB	If LIC11 is present in your FRU list and not already tested using this procedure go to "MAP: LIC11" on page 1-91 otherwise go to "MAP: LCPB, LCPE, LCEB, LCEE" on page 1-88
LCPE	"MAP: LCPE" on page 1-84
LIC11	"MAP: LIC11" on page 1-91
LIC12	"MAP: LIC12" on page 1-97
SIE	"MAP: SIE" on page 1-104
SPD1	"MAP: 3746-950 in Offline Mode" on page 1-114
SPD2	"MAP: SPD2" on page 1-107
SPS	"MAP: 3746-950 SPS, Control Panel" on page 1-111
TIC3 of CBSP (which assures the link with the service processor, located in position 07N-A1-F1)	"MAP: TIC3 of the CBSP" on page 1-73
TIC3 other	"MAP: TIC3" on page 1-101
Transformer	"3746-950 ACPW, DCPW, Transformer" on page 1-113
TRP/TRP2/TRP3	"MAP: TRP/TRP2/TRP3" on page 1-81

Note: If during the preceding procedures you cannot select a resource because it is not present in CDF-E, go to "MAP 2665: 3746 Model 950 Resource Not Present in CDF-E" on page 2-53.

MAP: ARC**001****Is the "Resource Selector" window displayed?****Yes No****002**

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 004.

003**Are you on the "Resource selector" window with the suspected FRU list displayed, obtained via the CPN number?****Yes No****004**

- On the "Resource Selector" window, select the LIC11 (address range) associated with the ARC that you want to test, then click on "OK".
- On the following "Resource Selector" window, select the "ARCs" corresponding to the address range, then click on "OK".

Is the ARC that you want to test is alone in its ARC group?**Yes No****005**

Continue with Step 007.

006

Go to Step 010 on page 1-57.

007

- Check with your customer **all** the lines speed connected to the ARCs which belong to the same ARC group of the ARC that you want to test.

(Step **007** continues)

007 (continued)

Is there a line speed higher than 64 Kbps in the ARC group?

Yes No

008

Go to Step 010.

009

- Ask your customer to deactivate **all** the lines of this ARC group.
- If APPN/IP is installed, deactivate all the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure with Step 010.

010

- On the next two "Resource Selector" windows, select the suspected ARC and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

011

- Check that the customer stopped traffic on the suspected ARC.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK", and go to Step 004 on page 1-56.

012

- On this window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC SAT", then click on "OK".
- The "Diagnostic Active Status" window is displayed, and when the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

013

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, continue with Step 029 on page 1-59.

014

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC MAT", then click on "OK".
- When the "Information Required" window is displayed, disconnect the ARC cable from the DTE, DCE, or cable and install the wrap plug according to the ARC type (see "Shipping Group Tools" on page A-2).
- Enter "YES" and click on "OK".
- The "Diagnostic Active Status" window is displayed, and when the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window prompts you to remove the wrap from the ARC cable, and reconnect the ARC cable previously removed. Click on "OK" when it is done.

(Step 014 continues)

014 (continued)



- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

015

Is the ARC you tested an ARC assembly B (with a detachable cable at the rear)?



Yes No

016

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, continue with Step 029 on page 1-59.

017

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC MAT", then click on "OK".
- When the "Information Required" window is displayed, disconnect the cable at the rear of the ARC and install the wrap plug according to the ARC type you are testing (see "Shipping Group Tools" on page A-2).
- Enter "YES" and click on "OK".
- The "Diagnostic Active Status" window is displayed, and when the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window prompts you to remove the wrap from the ARC cable, and reconnect the cable previously removed at the rear of the ARC. Click on "OK" when it is done.
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

018

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the ARC replacement.
- After replacing the ARC, wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Continue with Step 029 on page 1-59.

019

(Step 019 continues)

019 (continued)

- The cable at the rear of the ARC is defective.
 - Order a new cable and change it.
 - Then continue with Step 033 on page 1-60.
-

020

Do you have ONLY this FRU in your FRU list?

Yes No

021

Is there any other FRU in your FRU list to test?

Yes No

022

You have tested all the FRU of your FRU list and all are error free.

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

023

Is there any other processor or CS in your FRU list?

Yes No

024

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

025

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

026

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement.
- After replacing the ARC, wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed with "SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed, and when the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

027

The FRU that you exchanged is defective.

028

Go to Step 033 on page 1-60.

029

- Return to the "Maintenance Options" window.
 - On this window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- (Step 029 continues)

3746-950 FRU Exchange

029 (continued)

- The "Test and Running Option Selection" window is displayed with "SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed, and when the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

030

Is there another FRU in your FRU list to test?

Yes No

031

Call support for assistance. Restart the procedure.

032

Go to "3746-950 FRU list for exchange" on page 1-54.

033

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
 - Follow the instructions of the "Warning" windows and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: CBSP/CBSP2/CBSP3

In this manual CBSP is the generic name for CBSP, CBSP2, or CBSP3.

001

Is the "Resource Selector" window displayed?

Yes No

002

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- In order to set the CBSP to concurrent mode, make sure there is no traffic on the CBSP. So stop the APPN.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Network Node Processor (NNP) Management" option.
 - On the following "Network Node Processor (NNP) Management" window, double click on the "Manage Control Points on NNPs" option.
 - On the "Manage Control Points (CP) on NNP" window, in the "Options" select the CP to stop (CP/NNP-A or CP/NNP-B), then click on the "Stop CP" option.
 - Click on "OK", and continue with Step 004.

004

- Return to the "3746-9x0 Menu".
- Click on the "Problem management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- On the next three "Resource Selector" windows, select the CBSP and click on "OK".
- Once the resource is set to concurrent mode the "Maintenance Options" window is displayed.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the "CBSP" and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostics error-free ?

Yes No

005

- Using the "Cancel" key, return to the "Maintenance Options" window and select "Replace the resource" option and click on "OK".
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, continue with Step 015 on page 1-62.

006

Do you have ONLY this FRU in your FRU list?

Yes No

007

(Step **007** continues)

007 (continued)

Is there any other FRU in your FRU list to test?

Yes No

008

You have tested all the FRU of your FRU list and all are error free.

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

009

Is there any other processor or CS in your FRU list?

Yes No

010

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

011

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

012

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After CBSP replacement continue with the next bullet.
- Wait for the end of IML and for the current CDF-E to be updated.
- Return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on resource" option then click on "OK".
- A "Diagnostics" window is displayed, check that the "Specific Adapter" and "no wrap" options are selected, then click on "Start".
- A "Specific Adapter" window is displayed, select the "CBSP" and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

013

Suspect the FRU that you exchanged.

014

Go to Step 019 on page 1-63.

015

- Wait for the end of IML and for the current CDF-E to be updated.
- Return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on resource" option then click on "OK".
- A "Diagnostics" window is displayed, check that the "Specific Adapter" and "no wrap" options are selected, then click on "Start".
- A "Specific Adapter" window is displayed, select the "CBSP" and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

(Step **015** continues)

015 (continued)

Is the diagnostic error-free ?

Yes No

016

Is there another FRU to diagnose ?

Yes No

017

go to "MAP: 3746-950 in Offline Mode" on page 1-114

018

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

019

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the CBSP with the attached couplers (CBC, TIC3).
 - Select "Remove the resource from the concurrent mode" option, and click on "OK".
 - On the "Resource selector" window, click on "Cancel"
 - Return to the "Maintenance Options" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: CLP/CLP3


In this manual CLP is the generic name for CLP or CLP3.

The hardware can connect four adjacent LICs to two adjacent CLPs. This hardware connection allows the CLPs to operate in standard mode or backup mode depending upon the option defined in the MOSS-E table.


The Backup Mode is only possible between two adjacent positions

CLP Position	Line Addresses	Attached LIC Position	CLP Backup Position
07G-A1-H	2112-2175	07N-A1 G and H	07G-A1 K
07G-A1-K	2176-2239	07N-A1 J and K	07G-A1 H
07G-A1-M	2240-2303	07N-A1 L and M	07G-A1-P
07G-A1-P	2304-2367	07N-A1 N and P	07G-A1-M
07E-A1-D	2368-2431	07M-A1 C and D	07E-A1-F
07E-A1-F	2432-2495	07M-A1 E and F	07E-A1-D
07E-A1-H	2496-2559	07M-A1 G and H	07E-A1-K
07E-A1-K	2560-2623	07M-A1 J and K	07E-A1-H
07E-A1-M	2624-2687	07M-A1 L and M	07E-A1-P
07E-A1-P	2688-2751	07M-A1 N and P	07E-A1-M
07D-A1-D	2752-2815	07L-A1 C and D	07D-A1-F
07D-A1-F	2816-2879	07L-A1 E and F	07D-A1-D
07D-A1-H	2880-2943	07L-A1 G and H	07D-A1-K
07D-A1-K	2944-3007	07L-A1 J and K	07D-A1-H
07D-A1-M	3008-3071	07L-A1 L and M	07D-A1-P
07D-A1-P	3072-3135	07L-A1 N and P	07D-A1-M

CLP in Backup Mode



CLP in Standard Mode



001

- Before continuing it is necessary to check if the suspected CLP has a backup CLP and if the LICs normally under the control of the suspected CLP are now under the control of the backup CLP.
 - Using the "Cancel" key return to the "3746-9x0 Menu" window.
 - Click on the "Configuration Management" option.
 - Double click on the "Define Backup CLP" option.
 - The following "CLP Backup" window is displayed.

Processor Backup

Select a processor:

Processor Type	Primary Processor	Backup Processor	Automatic Fallback	Fallback State	Switchback Requested	
CLP	2112	2176	no	no	no	1
CLP	2176	2112	no	yes	no	2
CLP	2240		no	no	no	3
CLP	2304		no	no	no	3

Notes:

- 1** and **2** These lines indicate that the CLP line addresses ranges from 2112 and from 2176 can be backup for each other.
- 2** This line with a "yes" in the fallback state column indicates that the primary processor (2176) is controlling the LICs of the backup processor (2112).
- 3** These lines indicate that the CLPs have no backup.

Does the suspected primary CLP have a backup processor with a "Yes" in the fallback state column?


Yes No

002

Go to Step 027 on page 1-69.

003

The resources of the suspected CLP are under the control of the backup CLP.



Test of the suspected CLP without its LIC(s) attached

- Click on the "Cancel" key.
- Return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window select the "Via the active CDF-E" option and click on "OK".

(Step **003** continues)

003 (continued)

- On the "Resource Selector" windows, select the processor for concurrent maintenance, then click on "OK".
- Once the resource is set to concurrent mode the "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

004

- Check that the customer stopped traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Go to Step 003 on page 1-65.

005

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

006

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the CLP replacement. After replacing the FRU, continue on Step 018 on page 1-68.

007

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU.
- Follow the instructions on the "Warning" window and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" option, then click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "3746-9x0 Menu" window.

Now you must test the CLP with its attached LIC(s).

- Ask the customer to stop traffic on the LIC(s) associated with the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- When the traffic is stopped, click on the "Configuration Management" option on the "3746-9x0 Menu" window.
- Double click on the "Define Backup CLP" option.
- The "CLP Backup" window is displayed.
- Select the suspected CLP. Then click on the "Switchback" key.
- On the "Confirmation" window, click on "OK".
- Wait for alarm "Switchback successful" and click on "OK".
- Click on "cancel" to return to the "3746-9x0 Menu" window.
- Select the "problem Management" option.
- Double click on the "Perform maintenance" option.
- On each of the next "Resource Selector" windows displayed, select the suspected CLP for concurrent maintenance by clicking on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".

(Step 007 continues)

007 (continued)

- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

008

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue on Step 018 on page 1-68.

009**Do you have ONLY this FRU in your FRU list?**

Yes No

010**Is there any other FRU in your FRU list to test?**

Yes No

011**You have tested all the FRU of your FRU list and all are error free.**

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

012**Is there any other processor or CS in your FRU list?**

Yes No

013

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

014

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

015**No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.**

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue on with the next bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected, then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

(Step **015** continues)

3746-950 FRU Exchange

015 (continued)

Is the diagnostic error-free ?

Yes No

016

The FRU that you exchanged is defective.

017

Go to Step 024.

018

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected, then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

019

Is there another FRU in your FRU list to test?

Yes No

020

Call support for assistance.

021

Is there any other processor or CS in your FRU list?

Yes No

022

Go to "3746-950 FRU list for exchange" on page 1-54 to change the next FRU.

023

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to continue the procedure.

024

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU.
- Follow the instructions on the "Warning" window and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" option, then click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "3746-9x0 Menu" window.

Now you must test the new CLP with its attached LIC(s).

- Ask the customer to stop traffic on the LIC(s) associated with the suspected processor and switchback the LIC(s) on the CLP.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- When the traffic is stopped, click on the "Configuration Management" option on the "3746-9x0 Menu" window.

(Step 024 continues)

024 (continued)

- Double click on the "Define Backup CLP" option.
- The "CLP Backup" window is displayed.
- Select the CLP that you have changed. Then click on the "Switchback" key.
- On the "Confirmation" window, click on "OK".
- Wait for alarm "Switchback successful" and click on "OK".
- Click on "cancel" to return to the "3746-9x0 Menu" window.
- Select the "Problem Management" option.
- Double click on the "Perform maintenance" option.
- On each of the next "Resource Selector" windows displayed, select the suspected CLP for concurrent maintenance by clicking on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?


Yes No

025

- Display the list of suspected FRUs. See "Display the FRU List After a Diagnostic Failure" on page 1-143.
- Select the FRU (other than the CLP) with the highest fault probability.
- Restart the procedure. Refer to "3746-950 FRU list for exchange" on page 1-54.

026

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the CLP and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" option, and click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "Maintenance Options" window.
- Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

027**The suspected CLP has no backup.**

- Click on the "Cancel" key to return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".

(Step **027** continues)

027 (continued)

- On each of the next three "Resource Selector" windows, select the processor for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

028

- Check that the customer stopped traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Then go to Step 027 on page 1-69

029

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected, then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

030

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, continue on Step 040 on page 1-71.

031

Do you have ONLY this FRU in your FRU list?

Yes No

032

Is there any other FRU in your FRU list to test?

Yes No

033

You have tested all the FRU of your FRU list and all are error free.

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

034

Is there any other processor or CS in your FRU list?

Yes No

035

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

036

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

037

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.

(Step 037 continues)

037 (continued)

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue on with the next bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected, then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

038

The FRU that you exchanged is defective.

039

Go to Step 046 on page 1-72.

040

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

041**Is there another FRU in your FRU list to test?**

Yes No

042

Call support for assistance.

043**Is there any other processor or CS in your FRU list?**

Yes No

044

Go to "3746-950 FRU list for exchange" on page 1-54 to change the next FRU.

045

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to continue the procedure.

046(Step **046** continues)

046 (continued)

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the FRU.
 - Follow the instructions on the "Warning" window and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" option, and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: TIC3 of the CBSP**001****Is the "Resource Selector" window displayed?****Yes No****002**

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- Ask the customer to stop all traffic on the TIC3 associated with the CBSP.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- On the "resource selector" window, select the TIC3 of the CBSP and click on "OK".
- On the next "resource selector" window, select the TIC3 of the CBSP and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.
- On this window, select the "Replace the resource" option and click on "OK".
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, continue this procedure.

Did you replace the TIC3 by a new one?**Yes No****004**

Go to Step 016 on page 1-74.

005

- Press the 'Exit' key on the 3746-950 control panel.

Is 00000000 displayed on the 3746-950 control panel?**Yes No****006**

Go to Step 011 on page 1-74.

007**Is there a character displayed in the "Service processor not accessible" window on the 3746-950 control panel?****Yes No****008**

- The TIC3 of the CBSP has been successfully changed. There is no diagnostic for this FRU.
- On the "Maintenance Options" window, select the "Remove from concurrent mode" option.
- On the next "Resource selector" window, click on "Cancel".
- Return to the "Maintenance Options" window.

Is there another FRU in your FRU list?**Yes No****009**

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

010

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

011

(Step 011 continues)

3746-950 FRU Exchange

011 (continued)

- Suspect the TIC3 you have changed. Reinstall the TIC3 previously removed using the following steps.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. Then after FRU replacement, return here to continue this procedure.
- Press the 'Exit' key on the 3746-950 control panel.

Is 00000000 displayed on the 3746-950 control panel?

Yes No

012

The TIC3 is defective. Order a new one and restart the exchange procedure.

013

Is there a character displayed in the "Service processor not accessible" window on the 3746-950 control panel?

Yes No

014

The TIC3 that you received for exchange is defective. Order a new one and restart the exchange procedure.

015

Go to Step 016

016

Is there another FRU in your FRU list?

Yes No

017

Call support for assistance.

018

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

MAP: ESCC/ESCC2/ESCP/ESCP2/ESCP3

In this manual ESCP is the generic name for ESCP, ESCP2, or ESCP3, and ESCC is the generic name for ESCC or ESCC2.

001

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- On each of the next "Resource Selector" windows, select the ESCP for concurrent maintenance.
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

002

Go to Step 004

003

Go to Step 030 on page 1-78

004

- Check that the customer stopped traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Perform the following steps to disable the ESCC.
 - Return to the "3746-9x0 Menu".
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP, and click on "OK".
 - The "ESCON Configuration Lines" window is displayed.
 - Click on "Options" (in the action bar). Then select the "Manage ESCC Status" option.
 - The "ESCC Status Management" window is displayed.
 - Select the "disable" option.
 - Click on the "Options" (in the action bar). Then select the "Send request" option.
 - A "confirmation" window is displayed, click on "OK".
 - A "Warning" windows inform you that the ESCP configuration is saved. Click on "OK".
 - Click on "Refresh"(in the action bar). Then select "Permanent Refresh" (no more action is possible from this screen).
 - When the "disable" is complete the "ESCC x Status" line should display: DISABLED. It should not display: ENABLED.

Is the "ESCC x Status" line displaying: ENABLED?

Yes No

005

- Click on "Refresh" (in the action bar). Then select "Stop permanent refresh".
- Click on the "Options" (in the action bar). Then select the "Return" option.
- On the "ESCON Configuration lines" window, click on "Options" and then on "Exit".
- On the "Confirmation" window, click on "OK".
- On the "ESCP Management - Resource Selector" window, click on "Cancel".
- The "3746-Menu" is displayed.
- Select the "problem Management" option.
- Double click on the "Perform maintenance" option
- On the "Resource Selection Options for Maintenance", select the "Via the Active CDF-E" option and click on "OK".
- On each of the next "Resource Selector" windows, select the ESCP for concurrent maintenance.
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

(Step **005** continues)

005 (continued)

Is the "Maintenance Options" window displayed?

Yes No

006

Call your support for assistance.

007

Go to Step 030 on page 1-78

008

In this Step we will try to set the ESCP in permanent reset. If the operation is not successful nevertheless continue with Step 009.

- Press the Ctrl/Esc keys at the same time.
 - On the "Window List" Window, double click on the "3746-9x0 Menu".
 - Click on "Problem Management" option.
 - Double click on "Change Resource Status".
 - Click on the ESCP that you want to remove the ESCC, then click on "OK".
 - On "Resource Selector" window, select the ESCP then click on "OK".
 - On "Resource Status Change - Selection" window, select "Permanent reset" option, then click on "OK".
 - On the "Resource Status Change - Selection" window, click on "Cancel".
 - Continue with Step 009.
-

009

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the ESCC/ESCP replacement (Change first the FRU with the highest fault probability).
- After FRU replacement, return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- On each of the next "Resource Selector" windows, select the ESCP for concurrent maintenance.
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

010

Is there an ESCC or an ESCP in your FRU list not yet changed?

Yes No

011

Is there another FRU to test in your FRU list?

Yes No

012

Call support for assistance.

013

Is there any other processor or CS in your FRU list?

Yes No

014

Go to "3746-950 FRU list for exchange" on page 1-54 to change the next FRU.

015

(Step 015 continues)

015 (continued)

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to continue the procedure.

016

Go to Step 009 on page 1-76

017

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

018

Is there an ESCC or an ESCP in your FRU list not yet changed?

Yes No

019

- Display the list of suspected FRUs. (See "Display the FRU List After a Diagnostic Failure" on page 1-143 for the procedure).

Are the suspected FRU already changed?

Yes No

020

Go to Step 013 on page 1-76.

021

Call support for assistance.

022

- Using the "Cancel" key, return to the "Maintenance Options" window. Select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the ESCC or ESCP replacement (change first the FRU with the highest fault probability, or the FRU not yet changed).
- After FRU replacement, wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

023

(Step **023** continues)

023 (continued)

Is there another FRU to test in your FRU list?

Yes No

024

Call support for assistance.

025

Is there any other processor or CS in your FRU list?

Yes No

026

Go to "3746-950 FRU list for exchange" on page 1-54 to change the next FRU.

027

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to continue the procedure.

028

Go to Step 046 on page 1-80.

029

Go to Step 046 on page 1-80.

030

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

031

Do you intend to exchange the ESCC?

Yes No

032

- Press the Ctrl/Esc keys at the same time.
- On the "Window List" Window, double click on the "3746-9x0 Menu".
- Click on "Problem Mangement" option.
- Double click on "Change Resource Status".
- Click on the ESCP that you want to remove the ESCC, then click on "OK".
- On "Resource Selector" window, select the ESCP then click on "OK".
- On "Resource Status Change - Selection" window, select "Permanent reset" option, then click on "OK".
- On the "Resource Status Change - Selection" window, click on "Cancel".
- Continue with Step 033.

033

- Using the "Cancel" key, return to the "Maintenance Options" window. Select the "Replace the resource" option and click on "OK".
 - A "Confirmation" window is displayed.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the ESCC or ESCP replacement (change first the FRU with the highest fault probability, or the FRU not yet changed).
- (Step **033** continues)

033 (continued)

- After FRU replacement, continue with Step 037.
-

034

Is there any other processor or CS in your FRU list?

Yes No

035

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120.

036

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to continue the procedure.

037

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

038

Is there an ESCC or an ESCP in your FRU list not yet changed?

Yes No

039

Is there another FRU to test in your FRU list?

Yes No

040

Call support for assistance.

041

Is there any other processor or CS in your FRU list?

Yes No

042

Go to "3746-950 FRU list for exchange" on page 1-54. to change the next FRU.

043

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to continue the procedure.

044

Go to Step 031 on page 1-78.

045

(Step **045** continues)

045 (continued)

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the FRU.
 - Follow the instructions on the "Warning" window and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" option. Then click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

046

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option. Then click on "OK", to reinitialize the FRU(s).
 - Follow the instructions on the "Warning" windows and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Enable the ESCC before removing the ESCC from concurrent mode.
 - Press the Ctrl/Esc keys at the same time.
 - On the "Window List" window, double click on the "3746-9x0 Menu" option.
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
 - The "ESCON Configuration Lines" window is displayed.
 - Click on the "Options" (in the action bar), then select the "Manage ESCC Status" option.
 - The "ESCC Status Management" window is displayed.
 - Select the "enable" option.
 - Click on the "Options" (in the action bar). Then select the "Send request" option.
 - A "confirmation" window is displayed. Click on "OK".
 - A "Warning" windows informs you that the ESCP configuration is saved. Click on "OK".
 - Click on the "Options" (in the action bar). Then select the "Return" option.
 - On the "ESCON Configuration lines" window, click on "Options" and then on "Exit".
 - On the "Confirmation" window, click on "OK".
 - On the "ESCP Management Resource Selector" window, click on "Cancel".
 - The "3746-Menu" is displayed.
 - Return to the "Maintenance Options" window.
 - Select "Remove the resource from the concurrent mode" option. Then click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - The "Resource Selection Options for Maintenance" window is displayed.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: TRP/TRP2/TRP3

In this manual TRP is the generic name for TRP, TRP2, or TRP3.

001

Is the "Resource Selector" window displayed?

Yes No

002

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- On the "Resource Selector" window, select the processor for concurrent maintenance.
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

004

- Check that the customer stopped traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu"
- Select the "problem Management" option.
- Double click on the "Perform maintenance" option. Then go to Step 003

005

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

006

- Using the "Cancel" key, return to the "Maintenance Options" window. Select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with Step 016 on page 1-82.

007

Do you have ONLY this FRU in your FRU list?

Yes No

008

Is there any other FRU in your FRU list to test?

Yes No

009

You have tested all the FRU of your FRU list and all are error free.
(Step 009 continues)

3746-950 FRU Exchange

009 (continued)

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

010

Is there any other processor or CS in your FRU list?

Yes No

011

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

012

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

013

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue with the following bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

014

The FRU that you exchanged is defective.

015

Go to Step 022 on page 1-83.

016

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

(Step **016** continues)

016 (continued)

Is the diagnostic error-free ?

Yes No

017

Is there another FRU in your FRU list to test?

Yes No

018

Call support for assistance.

019

Is there any other processor or CS in your FRU list?

Yes No

020

Go to "3746-950 FRU list for exchange" on page 1-54 to change the next FRU.

021

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to continue the procedure.

022

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the FRU.
 - Follow the instruction of the "Warning" window and click on "OK" when Prompted.
 - The "Maintenance options" window is displayed.
 - Select the "Remove the resource from the concurrent mode" option, and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: LCPE

001

Is the "Resource Selector" window displayed?

Yes No

002

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- On the "Resource Selector" window, select the line connection box (LCB) for concurrent maintenance. Then click on "OK".
- On the next "Resource Selector" window, click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

004

- Check that the customer stopped traffic on the suspected line connection box.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 003

005

Is there a line traffic on ARCs installed in LCBB?

Yes No

006

Go to "MAP: LCPB, LCPE, LCEB, LCEE" on page 1-88

007

- On this window, select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LCPE replacement. After the FRU replacement, continue with the following bullet.
- On the "Maintenance Options" window, select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "Resource Selection Options for Maintenance" window.

Is a LCEE in your FRU list?

Yes No

008

Go to Step 011 on page 1-85.

009

Did you already change the LCEE?

Yes No

010

Go to "MAP: LCEE" on page 1-86

011

Is there another FRU in your FRU list

Yes No

012

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128

013

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

MAP: LCEE

001

Is the "Resource Selector" window displayed?

Yes No

002

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- On the "Resource Selector" window, select the line connection box (LCB) for concurrent maintenance. Then click on "OK".
- On the next "Resource Selector" window, click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

004

- Check that the customer stopped traffic on the suspected line connection box.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 003

005

Is there a line traffic on ARCs installed in LCBB?

Yes No

006

Go to "MAP: LCPB, LCPE, LCEB, LCEE" on page 1-88

007

- On this window, select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LCEE replacement. After the FRU replacement, continue with the following bullet.
- On the "Maintenance Options" window, select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "Resource Selection Options for Maintenance" window.

Is a LCPE in your FRU list?

Yes No

008

Go to Step 011 on page 1-87.

009

Did you already change the LCPE?

Yes No

010

Go to "MAP: LCPE" on page 1-84

011

Is there another FRU in your FRU list

Yes No

012

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128

013

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

MAP: LCPB, LCPE, LCEB, LCEE**001****Is the "Resource Selector" window displayed?****Yes No****002**

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- On the "Resource Selector" window, select the line connection box (LCB) for concurrent maintenance. Then click on "OK".
- On the next "Resource Selector" window, click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?**Yes No****004**

- Check that the customer stopped traffic on the suspected line connection box.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 003

005

- On this window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****006**

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, continue with Step 012 on page 1-89.

007

- Using the "Cancel" key, return to the "Maintenance Options" window. Select the the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

(Step **007** continues)

007 (continued)

Is the diagnostic error-free ?

Yes No

008

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with Step 015.

009

Is there another FRU to test in your FRU list (other than LCPB, LCEB, LCPE, LCEE)?

Yes No

010

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120.

011

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

012

- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

013

Go to Step 018 on page 1-90.

014

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
 - Follow the instructions on the "Warning" windows and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

015

- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

(Step **015** continues)

3746-950 FRU Exchange

015 (continued)

Is the diagnostic error-free ?

Yes No

016

Go to Step 018

017

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "Resource Selection Options for Maintenance" window.
- Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128

018

Do you have another FRU to exchange?

Yes No

019

Are you sent here using a CPN or SRC sequence number?

Yes No

020

Go to Step 022.

021

Check if you have another FRU suspected in your FRU list.

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- The "Resource Options Selection for Maintenance" is displayed.
On this window, select:
 - "By Specific Customer Problem Number (CPN)", if you are here with a CPN or,
 - "By the sequence number of a system reference code" if you are here with a SRC sequence number.
- Click on "OK".
- On the next window enter either the CPN or the SRC sequence number according to your previous selection, and click on "OK".
- The "Resource Selector" window is displayed with the FRU suspected and their fault probability.

Is there another FRU suspected in your FRU list?

Yes No

022

Call support for assistance.

023

- Order the FRU suspected and exchange it.
- Go to "3746-950 FRU list for exchange" on page 1-54.

024

Go to "3746-950 FRU list for exchange" on page 1-54.

MAP: LIC11**001****Is the "Ressource Selector" window displayed?****Yes No****002**

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- On the "Resource Selector" windows, select the LIC11 for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?**Yes No****004**

- Check that the customer stopped traffic on the suspected LIC11.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 003

005

- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LIC11.
- Unfasten the screws which maintain the cable, coming from the LCBB, on the rear of the LIC11 and unplug the cable.
- On the rear of the LIC11 install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?**Yes No****006**

Go to Step 026 on page 1-94.

007

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

(Step **007** continues)

007 (continued)

Is the diagnostic error-free ?

Yes No

008

Go to Step 027 on page 1-94.

009

- Click on "Cancel".
- Replug the cable coming from the LCBB on the rear of the LIC11 and secure it.
- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LCBB.
- Unfasten the screws which maintain the cable, coming from the LIC11, on the LCBB and unplug this cable from the LCBB.
- On the end of the cable install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

010

Go to Step 024 on page 1-93.

011

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

012

Go to Step 025 on page 1-94.

013

Do you have ONLY this FRU in your FRU list?

Yes No

014

Is there any other FRU in your FRU list to test?

Yes No

015

You have tested all the FRU of your FRU list and all are error free.

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

016

(Step **016** continues)

016 (continued)

Is there any other processor or CS in your FRU list?

Yes No

017

Go to Step 032 on page 1-95.

018

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

019

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LIC11 replacement. After the LIC11 replacement, continue with the next bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Install the wrap plug PN 58G9425 on the rear of the LIC11.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

020

Check the LIC11 installation. If everything is correct, the LIC11 that you installed is defective.

021

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

022

Check the LIC11 installation. If everything is correct, the LIC11 that you installed is defective.

023

- Connect and secure the cable from the LCBB to the rear of the LIC11.
 - Go to Step 043 on page 1-96
-

024

- Enter "No" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window informs you that the wrap test is not running. Click on "OK".

(Step **024** continues)

024 (continued)

- The "Diagnostic Active Status" window is displayed. Then an "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window remind you to remove the wrap plug.
 - Unplug the wrap plug if not already done and click on "OK".
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 025.
-

025

The cable between the LIC11 and the LCBB is faulty. Order a new one, exchange it, and when it is done go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

026

- Enter "No" on the "Information Required" window and click on "OK".
 - The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
 - The "Diagnostic Active Status" window is displayed. Then an "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window remind you to remove the wrap plug.
 - Unplug the wrap plug if not already done and click on "OK".
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 027.
-

027

- The LIC11 is defective.
- Using the "Cancel" key, return to the "Maintenance Options" window, select the "Replace the Resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LIC11 replacement. After the LIC11 replacement, continue with the next bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Install the wrap plug PN 58G9425 at the rear of the LIC11.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

028

Call your support for assistance.

029

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

(Step 029 continues)

029 (continued)

Is the diagnostic error-free ?

Yes No

030

Call your support for assistance.

031

- Connect and secure the cable from the LCBB to the rear of the LIC11.
- Go to Step 043 on page 1-96

032

- Connect and secure the cable from the LCBB to the rear of the LIC11.
- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".

Is initialization successful?

Yes No

033

- On the "Warning" window, click on "OK".
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the **all** LCB part replacement of your FRU list (LCPB or LCEB) and after the replacement, continue with the next bullet.
- Wait until you have seen messages saying 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' displayed on the service processor screen then continue.
- Return to the "Maintenance Options" window, by clicking on "OK" on the "Resource Selector" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".

Is initialization successful?

Yes No

034

Call your support for assistance.

035

- On the "Warning" window, click on "OK".
- Using the "Cancel" and "Leave" keys, return to the "Resource Selection Options for Maintenance" window,
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the LCB and click on "OK".
- On the next "Resource Selector" windows, select the LCB and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

036

Call your support for assistance.

037

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

(Step 037 continues)

037 (continued)

Is the diagnostic error-free ?

Yes No

038

Call your support for assistance.

039

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

040

Call your support for assistance.

041

Go to Step 043

042

- On the "Warning" window, click on "OK".
 - Return to the "Maintenance options" window.
 - Select "Remove the resource from the concurrent mode" option and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.
-

043

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Initialize and remove from the concurrent mode all the resources previously set in that mode using the following steps for each one:
 - Select the "Initialize the resource" option to reinitialize the FRU.
 - Follow the instructions on the "Warning" windows and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" option and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Click on "Cancel" key.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: LIC12**001****Is the "Resource Selector" window displayed?****Yes No****002**

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- On the "Resource Selector" window, select the LIC12 for concurrent maintenance. Then click on "OK".
- On the next "Resource Selector" window, click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?**Yes No****004**

- Check that the customer stopped traffic on the suspected coupler.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 003

005

- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 SAT" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****006**

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with Step 023 on page 1-99.

007

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
 - The "Test and Running Option Selection" window is displayed.
 - Select the "LIC12 MAT" option and click on "OK".
 - A "Diagnostic Active Status" window is displayed then an "Information Required" window prompts you to install a wrap plug.
 - Locate the LIC12 that you want test on the 3746-950.
- (Step 007 continues)

007 (continued)

- Unfasten the screws which maintain the cable at the rear of LIC12 and unplug the cable from the LIC12.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

008

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with Step 023 on page 1-99.

009

- If you have installed the wrap plug according to the type of connection continue with Step 011.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps plugs?

Yes No

010

Go to Step 007 on page 1-97 to run the diagnostic again using the other wrap plug.

011

Do you have ONLY this FRU in your FRU list?

Yes No

012

Reconnect and secure the cable at the rear of LIC12.

Is there any other FRU in your FRU list to test?

Yes No

013

You have tested all the FRU of your FRU list and all are error free.

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

014

Is there any other processor or CS in your FRU list?

Yes No

015

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

016

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

017

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU,

using the following procedure.

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue with the following bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Continue with Step 018.

018

- Return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is Complete an, "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window ask you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

019

The FRU that you exchanged is defective.

020

- If you have installed the wrap plug according to the type of connection continue with Step 030 on page 1-100.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps?

Yes No

021

Go to Step 018 to run the diagnostic again using the other wrap plug.

022

Go to Step 030 on page 1-100.

023

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Continue with Step 024.

024

- Return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 MAT" option and click on "OK".

(Step 024 continues)

024 (continued)

- An "Information Required" window is displayed prompting you to install a wrap plug.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is Complete an, "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window ask you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

025

Is there another FRU to test in your FRU list?

Yes No

026

Call support for assistance. Restart the procedure.

027

Go to "3746-950 FRU list for exchange" on page 1-54.

028

- If you have installed the wrap plug according to the type of connection continue with Step 030.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps?

Yes No

029

Go to Step 024 on page 1-99 to run the diagnostic again using the other wrap plug.

030

- Reconnect and secure the cable at the rear of LIC12.
 - Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
 - Follow the instructions on the "Warning" windows and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: TIC3**001****Is the "Resource Selector" window displayed?****Yes No****002**

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- On the "Resource Selector" window, select the coupler for concurrent maintenance.
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?**Yes No****004**

- Check that the customer stopped traffic on the suspected coupler.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 003.

005

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed with "TIC3 SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****006**

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, continue with Step 016 on page 1-102.

007**Do you have ONLY this FRU in your FRU list?****Yes No****008****Is there any other FRU in your FRU list to test?****Yes No****009**

You have tested all the FRU of your FRU list and all are error free.
(Step 009 continues)

3746-950 FRU Exchange

009 (continued)

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

010

Is there any other processor or CS in your FRU list?

Yes No

011

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

012

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

013

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.

- Using the "Cancel" key, return to the "Maintenance Options" window. Then select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue with the following bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed with "TIC3 SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

014

The FRU that you exchanged is defective.

015

Go to Step 020 on page 1-103.

016

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed with "TIC3 SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

017

(Step **017** continues)

017 (continued)

Is there another FRU in your FRU list to test?

Yes No

018

Call support for assistance. Restart the procedure.

019

Go to "3746-950 FRU list for exchange" on page 1-54.

020

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
 - Follow the instructions on the "Warning" windows and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

MAP: SIE

001

- Be sure that the customer stopped traffic on the MAE.
- Return to the "3746-9x0 Menu".
- Click on the "Multiaccess Enclosure (MAE) Management" option.
- Double click on the "Perform Maintenance on MAE" option.
- The "MAE Maintenance" window is displayed, asking you to confirm that you want to perform maintenance on MAE. Click on "Yes".
- A new "MAE Maintenance" window is displayed, with "Operation Successfully sent on NNP", Click on "OK".
- Wait until an alarm window displays: "MAE Concurrent Maintenance in progress". Click on "OK".
- Wait until the MAE link icon comes red.
- Return to the "Multiaccess Enclosure (MAE) Management" window.
- Double click on the "Selective IML" option.
- The "MAE Selective IML" window is displayed, asking you to confirm that you want to perform MAE selective IML. Click on "Yes".
- A new "MAE Selective IML" window is displayed, with "Operation Successfully sent on NNP", Click on "OK".
- An alarm window is displayed with "MAE Selective IML in progress". Click on "OK".
- Wait until An alarm window is displayed with "MAE IML Complete". Click on "OK".

Is the MAE Selective IML Complete?

Yes No

002

- Return to the "Multiaccess Enclosure (MAE) Management" window.
- Double click on the "Perform Maintenance on MAE" option.
- The "MAE Maintenance" window is displayed, asking you to confirm that you want to perform maintenance on MAE. Click on "Yes".
- A new "MAE Maintenance" window is displayed, with "Operation Successfully sent on NNP", Click on "OK".
- Wait until an alarm window displays: "MAE Concurrent Maintenance in progress". Click on "OK".
- Wait until the MAE link icon comes red.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue with the following bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- Click on "OK" to remove the alarm messages.
- Go to Step Step 012 on page 1-105.

003

Do you have ONLY this FRU in your FRU list?

Yes No

004

Is there any other FRU in your FRU list to test?

Yes No

005

You have tested all the FRU of your FRU list and all are error free.

Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120

006

Is there any other processor or CS in your FRU list?

Yes No

007

Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.

008

(Step 008 continues)

008 (continued)

Go to "MAP: 3746-950 in Offline Mode" on page 1-114

009

No error detected on the suspected FRU using the concurrent mode diagnostics. Change the FRU, using the following procedure.

- Return to the "Multiaccess Enclosure (MAE) Management" window.
- Double click on the "Perform Maintenance on MAE" option.
- The "MAE Maintenance" window is displayed, asking you to confirm that you want to perform maintenance on MAE. Click on "Yes".
- A new "MAE Maintenance" window is displayed, with "Operation Successfully sent on NNP", Click on "OK".
- Wait until an alarm window displays: "MAE Concurrent Maintenance in progress". Click on "OK".
- Wait until the MAE link icon comes red.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue with the following bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen. Then continue.
- Return to the "Multiaccess Enclosure (MAE) Management" window.
- Double click on the "Selective IML" option.
- The "MAE Selective IML" window is displayed, asking you to confirm that you want to perform MAE selective IML. Click on "Yes".
- A new "MAE Selective IML" window is displayed, with "Operation Successfully sent on NNP", Click on "OK".
- An alarm window is displayed with "MAE Selective IML in progress". Click on "OK".
- Wait until An alarm window is displayed with "MAE IML Complete". Click on "OK".

Is the MAE Selective IML Complete?

Yes No

010

The FRU that you exchanged is defective.

011

Go to Step 018 on page 1-106.

012

- Return to the "Multiaccess Enclosure (MAE) Management" window.
- Double click on the "Selective IML" option.
- The "MAE Selective IML" window is displayed, asking you to confirm that you want to perform MAE selective IML. Click on "Yes".
- A new "MAE Selective IML" window is displayed, with "Operation Successfully sent on NNP", Click on "OK".
- An alarm window is displayed with "MAE Selective IML in progress". Click on "OK".
- Wait until An alarm window is displayed with "MAE IML Complete". Click on "OK".

Is the MAE Selective IML Complete?

Yes No

013

Is there another FRU in your FRU list to test?

Yes No

014

Call support for assistance.

015

(Step **015** continues)

3746-950 FRU Exchange

015 (continued)

Is there any other processor or CS in your FRU list?

Yes No

016

Go to “3746-950 FRU list for exchange” on page 1-54 to change the next FRU.

017

Go to “MAP: 3746-950 in Offline Mode” on page 1-114 to continue the procedure.

018

- Go to “MAP: 3746-950 Ending Procedure in Concurrent Mode” on page 1-128
-

MAP: SPD2

Before exchanging the SPD2, make sure that all processors installed in the expansion enclosure are either unavailable or disconnected. Otherwise, you must set the processor(s) in concurrent mode.

001

Is the "Resource Selector" window displayed?

Yes No

002

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Options Selection for Maintenance" window, select the "Via the Active CDF-E" option, click on "OK".
- Go to Step 003.

003

- Return to the "3746-9x0 Menu".
- Click on the "Configuration Management" option.
- Double click on the "Display Active Configuration CDF-E" option.
- Note all the processors belonging to the expansion enclosure which are active or available.

Is there processor of the expansion enclosure active or available?

Yes No

004

Go to Step 016 on page 1-108.

005

- Ask the customer to stop all the traffic on all the processors of the expansion enclosure.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Go to Step 006

006

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance"
- On the "Resource Selection Options for Maintenance" select the "Via the active CDF-E" option.
- On the three following "Resource Selector" windows, select the processor that you want to set in concurrent mode and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

007

- Check that the customer stopped traffic on the suspected processor.

Is the selected processor a ESCP?

Yes No

008

Go to Step 006

009

Go to Step 013 on page 1-108

010

(Step 010 continues)

010 (continued)

Is there another processor in the expansion enclosure to set in concurrent mode?

Yes No

011

Go to Step 016

012

Go to Step 006 on page 1-107

013

- Perform the following steps to disable the ESCC.
 - Return to the "3746-9x0 Menu".
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
 - The "ESCON Configuration Lines" window is displayed.
 - Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
 - The "ESCC Status Management" window is displayed.
 - Select the "disable" option.
 - Click on the "Options" (in the action bar). Then select the "Send request and save" option.
 - A "confirmation" window is displayed. Click on "OK".
 - A "Warning" window informs you that the ESCP configuration is saved. Click on "OK".
 - Click on "Refresh"(in the action bar). Then select "Permanent Refresh" (no more action is possible from this screen).
 - When the "disable" is complete the "ESCC x Status" line should display: DISABLED. It should **not** display: ENABLED.

Is the "ESCC x Status" line displaying: ENABLED?

Yes No

014

- Click on "Refresh" (in the action bar). Then select "Stop permanent refresh".
- Click on the "Options" (in the action bar). Then select the "Return" option.
- On the "ESCON Configuration lines" window, click on "Options" and on "Exit".
- On the "Confirmation" window, click on "OK".
- On the "ESCP Management Resource Selector" window, click on "Cancel".
- The "3746-Menu" is displayed.
- Go to Step 006 on page 1-107

015

- You are not able to disable the ESCC and set the ESCP in concurrent mode.
 - If you have another processor to set in concurrent mode, go to Step 006 on page 1-107. Otherwise, go to Step 016.
-

016

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the SPD2 and continue with the next bullet.
 - On the service processor screen, the alarms generated by SPD2 unplugging and plugging are displayed.
 - Click on "OK" of each alarm received during the SPD2 exchange and check that all the processors of the expansion enclosure have generated a plug alarm.
 - Since there is no specific diagnostic for the SPD2 card, start a diagnostic on a processor in the expansion enclosure.
 - Go to Step 017
-

017

- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option, and click on "OK".

(Step 017 continues)

017 (continued)

- A "Diagnostics" window is displayed. Check that the "specific Adapter" and "no wrap" options are selected and click on "OK".
- A "Specific Adapter" window is displayed. Select the desired processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

018**Is there another FRU in your FRU list to test?**

Yes No

019

Call your support for assistance.

020

- Click on "Cancel" to return to the "Maintenance Options" window.
 - Go to "3746-950 FRU list for exchange" on page 1-54 to select the next FRU.
-

021

- Click on "Cancel" to return to the "Maintenance Options" window.
- Select the "Initialize the Resource" option and click on "OK".
- At the "Warning" message, click on "OK".

Is this processor an ESCP?

Yes No

022

Go to Step 024.

023

- It is necessary to enable the ESCC before removing the ESCP from concurrent mode.
 - Simultaneously press the Ctrl/Esc keys.
 - On the "Window List" window, double click on the "3746-9x0 Menu" option.
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
 - The "ESCON Configuration Lines" window is displayed.
 - Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
 - The "ESCC Status Management" window is displayed.
 - Select the "enable" option.
 - Click on the "Options" (in the action bar). Then select the "Send request and save" option.
 - A "confirmation" window is displayed. Click on "OK".
 - A "Warning" window informs you that the ESCP configuration is saved. Click on "OK".
 - Click on the "Options" (in the action bar). Then select the "Return" option.
 - On the "ESCON Configuration lines" window, click on "Options" and then on "Exit".
 - On the "Confirmation" window, click on "OK".
 - On the "ESCP Management Resource Selector" window, click on "Cancel".
 - The "3746-Menu" is displayed.
 - Return to the "Maintenance Options" window.
 - Select "Remove the resource from the concurrent mode" option, then click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - The "Resource Selection Options for Maintenance" window is displayed.
-

024(Step **024** continues)

3746-950 FRU Exchange

024 (continued)

- On the "Maintenance Options" window, select the the "Remove the Resource from the Concurrent Mode" option and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource Selector" window, click on "Cancel".

Is there another processor in the expansion enclosure to remove from concurrent mode?

Yes No

025

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

026

- Return to the "3746-9x0 Menu".
 - Click on the "Problem Management" option.
 - Double click on the "Perform Maintenance"
 - On the "Resource Selection Options for Maintenance", select the "Via the active CDF-E" option and click on "OK".
 - On each of the next three "Resource Selector" windows, select the processor that you want removed from concurrent mode and click on "OK".
 - A "Maintenance Options" window is displayed.
 - Go to Step 017 on page 1-108
-

MAP: 3746-950 SPS, Control Panel**001****Do you want to change the control panel?****Yes No****002**

Go to Step 012

003

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement and after the FRU replacement, return here.
- From the 3746-950 control panel, run the 3746-950 control panel test (see "How to Run the 3746-950 Control Panel Test" on page 3-14).

Is the diagnostic error-free?**Yes No****004****Is there another FRU in your FRU list?****Yes No****005**

Restart problem determination. Go to "MAP 2620: 3746-950 Control Panel Problem" on page 2-36.

006

Go to "3746-950 FRU list for exchange" on page 1-54.

007**Is the control panel the only FRU in your FRU list?****Yes No****008****Have all other suspected FRUs been tested?****Yes No****009**

Go to "3746-950 FRU list for exchange" on page 1-54.

010

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

011

- Return to the "3746-9x0 Menu" window.
- Click on "Functions" (in the action bar).
- Select "Exit".
- On the "MOSS-E View" window, click on "Program" (in the action bar).
- Click on "Log off MOSS-E"
- If you changed the power control mode from remote to local, set it back to remote mode:
 - Press the 'Power control' key until (1) is displayed in the power control window.
 - Press the 'Validate' key.

Inform the customer that the resource(s) is(are) now available.

012

- On the "Resource Selector" window, select the SPS.
- (Step 012 continues)

3746-950 FRU Exchange

012 (continued)

- A "Confirmation" window is displayed, prompting you to pull out the maintenance switch. After you pull out the maintenance switch, click on "OK".
- Once the resource is set to concurrent mode A "Concurrent Maintenance Options" window is displayed.
- On this window, select the "Replace the resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to exchange the SPS. Then return here.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Check that no alarm referring to SPS malfunction is displayed on the service processor.

Is there an SPS malfunction alarm displayed?

Yes No

013

- Return to the "Maintenance Options" window.
- Select the "Remove the resource from the concurrent mode" and click on "OK".
- On the next "Warning" window, click on "OK" after pushing in the maintenance switch.
- Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

014

Suspect the FRU that you exchanged. Restart the problem determination. Go to "MAP 2500: 3746-950 Power Control Subsystem Problems" on page 2-4.

3746-950 ACPW, DCPW, Transformer

001

Is there a backup ACPW or DCPW installed in your 3746-950

Yes No

002

Go to "MAP: 3746-950 in Offline Mode" on page 1-114.

003

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement, then return here.

Is there another FRU to exchange?

Yes No

004

- Return to the "3746-9x0 Menu" window.
- Click on "Functions" (in the action bar).
- Select "Exit".
- On the "MOSS-E View" window, click on the "Program" (in the action bar).
- Click on "Log off MOSS-E".
- If you have changed the power control mode from remote to local, set it again to remote mode:
 - Press the 'Power control' key until (1) is displayed in the power control window.
 - Press the 'Validate' key.

Inform the customer that the resource(s) is(are) now available.

005

Is the FRU that you have to exchange one of the following: CSCE, DCDP, SPD1?

Yes No

006

Go to "3746-950 FRU list for exchange" on page 1-54.

007

Go to "MAP: 3746-950 in Offline Mode" on page 1-114.

MAP: 3746-950 in Offline Mode

001

Ask the customer to stop all traffic on the 3746-950 if this is not already done. If APPN/IP is installed, deactivate all the ports (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.

Set the 3746-950 to Offline mode.

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem management" option.
- Double click on the "Set 3746-9x0 Online/Offline Option".
- On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
- On the next "Set 3746-9x0 Online/Offline" window, click on "OK".

Is the FRU that you have to exchange one of the following: ACPW, DCPW, transformer, CSCE, DCDP, SPD1?

Yes No

002

Go to Step 010

003

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. Then return here.
- Press the 'Start' key on the 3746-950 control panel. This starts an IML.

A normal IML is terminated when 00000000 is displayed on the control panel and when the ready LED comes ON after about 3 minutes. In case of a problem during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

Does the ready LED come ON?

Yes No

004

Check that you followed the FRU exchange procedure. If you cannot identify the problem, suspect the FRU that you installed and call your support.

005

Is there another FRU to exchange?

Yes No

006

Go to "MAP: 3746-950 Ending Exchange Procedure After Power ON" on page 1-125.

007

Is the FRU that you have to exchange one of the following: ACPW, DCPW, transformer, CSCE, DCDP, SPD1?

Yes No

008

Go to Step 010

009

Go to Step 003.

010

- Start a general IML.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Operations Management" option.
 - Double click on the "Perform a general IML" option.

(Step 010 continues)

010 (continued)

- On the "Perform general IML" window, click on "YES" to continue.
- On the next "Perform general IML" window, click on "NO" to start an IML without diagnostic.
- Return to the "MOSS-E View" window.
- Click on the "Program" title bar.
- Click on "Status" option and wait for the IML to end with 00000000 displayed and the ready LED ON. Then click on "OK". In case of a problem during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

Does the ready LED come ON?**Yes No****011**

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement, then return here.

Did you change the TIC3 of the CBSP?**Yes No****012**

Go to Step 027 on page 1-116

013**Is there a character displayed in the "Console not accessible" window on the 3746-950 control panel?****Yes No****014**

Go to Step 048 on page 1-118

015Go to Step 028 on page 1-116

016**Are you here for a DCDC problem on CLP?****Yes No****017**

Go to Step 019.

018

- First check the state of CP3, CP4, CP5, CP6, or CP7.
 - If one or several CP(s) are OFF go to "MAP 2605: 3746-950 Either CP3, CP4, CP5, CP6, or CP7 is Tripped" on page 2-26
 - Otherwise go to Step 019.
-

019**Are you here for a CLP problem?****Yes No****020**

Go to Step 024 on page 1-116.

021(Step **021** continues)

3746-950 FRU Exchange

021 (continued)

Have you more than one CLP installed on the 3746-950?

Yes No

022

Go to Step 024.

023

Before starting this procedure check if CLP(s) are set in standard or backup mode in order to see what will be tested during this Offline procedure. Go to "MAP: 3746-950 CLP Backup or Standard Mode Setting" on page 1-135 to check the CLP status and change it if necessary. Then return here and continue with Step 024.

024

- Run all the diagnostics on the 3746-950.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
 - Double click on the "Perform Offline Diagnostics" option.
 - The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "no wrap" options. Then click on "Start".
 - The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:" on page 1-119).
 - At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

025

- Change the FRU for which you entered in this procedure.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with Step 032.

026

- No error detected. Exchange **all** the FRUs on your FRU list.
 - Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to replace all the FRUs. After replacing the FRUs, continue with Step 041 on page 1-117.
-

027

Does the ready LED come ON?

Yes No

028

Is there another FRU in your FRU list?

Yes No

029

Call your support for assistance, or restart problem determination.

030

Go to Step 011 on page 1-115 to exchange the next FRU.

031

Go to Step 048 on page 1-118

032

- Run all the diagnostics on the 3746-950.
(Step 032 continues)

032 (continued)

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on the "Perform Offline Diagnostics" option.
- The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "no wrap" options. Then click on "Start".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:" on page 1-119).
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?**Yes No****033****Is there another FRU to test in your FRU list?****Yes No****034**

Call for assistance.

035

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to:
 - Remove the FRU previously installed
 - Exchange the next FRU on your FRU list. Then return here.
- Run all the diagnostics on the 3746-950.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
 - Double click on the "Perform Offline Diagnostics" option.
 - The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "no wrap" options. Then click on "Start".
 - The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:" on page 1-119).
 - At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?**Yes No****036****Is there another FRU to test in your FRU list?****Yes No****037**

call for assistance.

038

Go to Step 035.

039

Go to Step 040

040

Problem solved. Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

041**Is the 3746-950 in standby?****Yes No****042**

Go to Step 045 on page 1-118

3746-950 FRU Exchange

043

- Press the 'Start' key on the 3746-950 control panel. An IML is started. A normal IML is terminated when 00000000 is displayed on the control panel and the ready LED comes ON after about 3 minutes. In case of a problem during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

Does the ready LED come ON?

Yes No

044

Check that you followed the FRU exchange procedure. If you do not identify the problem. Suspect a FRU that you have installed and call your support.

045

- Run all the diagnostics on the 3746-950.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
 - Double click on the "Perform Offline Diagnostics" option.
 - The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "no wrap" options. Then click on "Start".
 - The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:" on page 1-119).
 - At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

046

- Suspect an FRU that you changed.
- Display the list of suspected FRUs. (See "Display the FRU List After a Diagnostic Failure" on page 1-143 for procedure).
- Select the FRU with the highest fault probability.
- Restart the procedure, refer to "MAP: 3746-950 in Offline Mode" on page 1-114.

047

Problem solved. Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

048

- Run all the diagnostics on the 3746-950.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
 - Double click on the "Perform Offline Diagnostics" option.
 - The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "no wrap" options. Then click on "Start".
 - The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:" on page 1-119).
 - At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

049

Is there another FRU to test in your FRU list?

Yes No

050

Call for assistance.

051

(Step 051 continues)

051 (continued)

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 to:
 - Exchange the next FRU on your FRU list, then return here.
- Run all the diagnostics on the 3746-950.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
 - Double click on the "Perform Offline Diagnostics" option.
 - The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "no wrap" options. Then click on "Start".
 - The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:").
 - At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?**Yes No****052****Is there another FRU to test in your FRU list?****Yes No****053**

Call your support for assistance.

054

Go to Step 051 on page 1-118.

055

Go to Step 056.

056

Problem solved. Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

Note: If a diagnostic timeout occurs when you have started the diagnostic on the "Whole 3746-950" with "No wrap" option, restart once the diagnostic. If diagnostic timeout is again displayed contact your support.

MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode

Note

This procedure does not apply for SIE cassette and MAE cards.

No error detected on **all** on the FRU list using the concurrent mode diagnostics.

Change **all** FRUs, one by one, using the following procedure.

001

- Using the "Cancel" key, return to the "Maintenance options" window.
- Select the "Replace the Resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After replacing the FRU, continue with the next bullet.
- Wait until the 'Alarm xxxx FRU unplugged' and 'Alarm xxxx FRU plugged' messages are displayed on the service processor screen.
- On the "Confirmation" window, click on "OK".
- If you have another FRU to exchange, go to Step 001. Otherwise go to Step 002.

002

On the following table scan the FRU selection column from top to bottom, until you find one of the FRUs you suspected. Then select the test.

If none of the FRUs you changed are listed below, go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

FRU Selection	Test Name	FRU Tested	Action
CBSP/CBSP2/CBSP3	Specific Adapter	CBSP, Part of TIC3	Go to Step 003.
CLP/CLP3	Specific Adapter	CLP/CLP3, LIC11, LIC12, LCPB, LCEB, LCPE, LCEE, ARCs	Go to Step 003.
ESCP/ESCP2/ESCP3	Specific Adapter	ESCP, ESCC	Go to Step 003.
TRP/TRP2/TRP3	Specific Adapter	TRP, TIC3	Go to Step 003.
DCDC of CBSP, CLP, ESCP or TRP	Specific Adapter	Processor and attached Coupler	Go to Step 003.
ESCC	ESCC SAT	ESCC	Go to Step 006 on page 1-121.
TIC3	TIC3 SAT	TIC3	Go to Step 006 on page 1-121.
LIC12	LIC12 MAT	LIC12	Go to Step 009 on page 1-121.
LIC11	LIC11 MAT	LIC11	Go to Step 009 on page 1-121.
LCPB LCEB LCPE LCEE	LCBB SAT1 LCBB SAT2	LCPB, LCEB, LCPE, LCEE	Go to Step 025 on page 1-123.
ARCx	ARCxx MAT	ARCxx	Go to Step 028 on page 1-123.

003

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "No Wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor that you want to test and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed Time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

(Step **003** continues)

003 (continued)

Is the diagnostic error free?

Yes No

004

Suspect a FRU that you changed. Restart the procedure.

005

Go to Step 030 on page 1-123.

006

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Test and Running Option Selection" window is displayed with the diagnostics available.
- Select the "xxx SAT" according to the coupler that you want to test. Then click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error free?

Yes No

007

Suspect a FRU that you changed. Restart the procedure.

008

Go to Step 030 on page 1-123.

009

Do you want to test a LIC11?

Yes No

010

Go to Step 018 on page 1-122.

011

You test a LIC11.

- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LCBB.
- Unfasten the screws which maintain the cable, coming from the LIC11, on the LCBB and unplug this cable from the LCBB.
- On the end of the cable install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

012

Suspect a FRU that you changed. Restart the procedure.

013

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".

(Step 013 continues)

013 (continued)

- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

014

Suspect a FRU that you changed. Restart the procedure.

015

Is there another FRU that you changed to test?

Yes No

016

- Plug the cable in the LCBB and secure it using screws.
- Go to Step 033 on page 1-124.

017

- Plug the cable in the LCBB and secure it using screws.
- Go to Step 002 on page 1-120.

018

You test a LIC12.

- Locate the LIC12.
- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 MAT" option and click on "OK".
- A "Diagnostic Active Status" window is displayed then an "Information Required" window prompts you to install a wrap plug.
- Locate the LIC12 that you want tested on the 3746-950.
- Unfasten the screws which maintain the cable at the rear of LIC12 and unplug the cable from the LIC12.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

019

Suspect a FRU that you changed. Restart the procedure.

020

- If you have installed the wrap plug according to the type of connection continue with Step 022 on page 1-123.
- Otherwise continue this procedure.

(Step 020 continues)

020 (continued)

Did you run the LIC12 MAT diagnostic using the two wraps plugs?

Yes No

021

Go to Step 018 on page 1-122 to run the diagnostic again using the other wrap plug.

022

Reconnect and secure the cable at the rear of LIC12.

Is there another FRU that you changed to test?

Yes No

023

Go to Step 033 on page 1-124.

024

Go to Step 002 on page 1-120.

025

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Test and Running Option Selection" window is displayed with the diagnostics available.
- Select the "LCBB SAT2" and click on "OK".
- The "Diagnostic Active Status" window is displayed. Then when the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error free?

Yes No

026

Suspect a FRU that you changed. Restart the procedure.

027

Go to Step 030.

028

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Test and Running Option Selection" window is displayed with the diagnostics available.
- Select the "ARC SAT" and click on "OK".
- The "Diagnostic Active Status" window is displayed. Then when the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error free?

Yes No

029

Suspect a FRU that you changed. Restart the procedure.

030

Is there another FRU that you changed to test?

Yes No

031

Go to Step 033 on page 1-124.

032

(Step **032** continues)

032 (continued)

Go to Step 002 on page 1-120.

033

- Select "initialize the resource" option and click on "OK".
- On the "Warning" window, click on "OK".

Did you put the ESCC in concurrent mode?

Yes No

034

Go to Step 036

035

- Enable the ESCC before removing the ESCC from concurrent mode.
 - Simultaneously press the Ctrl/Esc keys.
 - On the "Window List" window, double click on the "3746-9x0 Menu" option.
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
 - The "ESCON Configuration Lines" window is displayed.
 - Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
 - You obtain the "ESCC Status Management" window.
 - Select the "enable" option.
 - Click on the "Options" (in the action bar). Then select the "Send request and save" option.
 - A "confirmation" window is displayed. Click on "OK".
 - A "Warning" window informs you that the ESCP configuration is saved. Click on "OK".
 - Click on the "Options" (in the action bar). Then select the "Return" option.
 - On the "ESCON Configuration lines" window, click on "Options" then on "Exit".
 - On the "Confirmation" window, click on "OK".
 - On the "ESCP Management Resource Selector" window, click on "Cancel".
 - The "3746-Menu" is displayed.
 - Return to the "Maintenance Options" window.
-

036

- Select "Remove the resource from the Concurrent Mode" and click on "OK".
- On the "Resource Selector" window, click on "Cancel".
- The "Resource Selection Options for Maintenance" is displayed.
- Click on the "Cancel" key.

Have you removed all the resources from concurrent mode?

Yes No

037

Go to Step 033 to remove resource from concurrent mode.

038

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

MAP: 3746-950 Ending Exchange Procedure After Power ON

You are here, because you put the 3746-950 in ready state, after an FRU replacement. Before returning the machine to the customer, perform all diagnostics from the service processor.

001

- Run all the diagnostics on the 3746-950.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
 - Double click on the "Perform Offline Diagnostics" option.
 - The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "no wrap" options. Then click on "start".
 - The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:").
 - At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

002

Restart problem determination. See "Display the FRU List After a Diagnostic Failure" on page 1-143.

003

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

Note: If a diagnostic timeout occurs when you have started the diagnostic on the "Whole 3746-950" with "No wrap" option, restart once the diagnostic. If diagnostic timeout is again displayed contact your support.

MAP: 3746-950 Ending Procedure In Offline Mode

You are here after performing procedure in offline mode.

001

Have you solved a connection problem to RETAIN?

Yes No

002

Was there a RETAIN connection problem for transmitting the last call?

(If you do not know and if the customer cannot provide the answer go to Step 006).

Yes No

003

Go to Step 009.

004

Go to "MAP 2000: 3746-950 Manual Call" on page 2-1.

005

Go to Step 009.

006

- Return to the "MOSS-E View" panel.
- Double click on the service processor icon.
- The "Service Processor Menu" is displayed.
- Click on the "Problem Management" option.
- Double click on the "Display Alarms" option.
- Scroll the alarm to find if there is an alarm 0643 or 064C.

Do you find an alarm 0643 or 064C in the alarm list?

Yes No

007

No RETAIN connection problem have been found. Go to Step 009.

008

You had a RETAIN connection problem. Go to "MAP 2000: 3746-950 Manual Call" on page 2-1.

009

- Return to the "3746-9x0 Menu" window.
- Select the "Configuration Management" option.
- Select the "Display/Update Active Configuration (CDF-E)".

Have you changed any FRU which appears in the CDF-E?

Yes No

010

Go to Step 015 on page 1-127

011

- You need to save the active CDF-E as Reference CDF-E.
 - Return to the "Configuration Management" window.
 - Click on the "Save active CDF-E as Reference CDF-E" option.
 - Follow the procedure displayed on successive screens.
- You need to copy the reference CDF-E on the 3746-950 installation parameter diskette.
 - Return to the "Configuration Management" window.
 - Select the "Copy Reference CDF-E on Diskette" option.

(Step 011 continues)

011 (continued)

- Follow the procedure displayed on successive screens.
- Then go to Step 012.

012**Have you changed a processor?**

Yes No

013

Go to Step 015.

014

- Go to "3746-950 EEPROM Upgrade" on page 1-144 to perform the EEPROM upgrade. When it is complete continue with the next bullet.
- Return to the "3746-9x0 Menu" and click on "Operation Management".
- Double click on the "Perform General IML".
- A Normal IML is terminated when 00000000 is displayed on the 3746-950 control panel.
 - If the control panel displays 00000000 go to Step 015.
 - If the control panel displays another code than 00000000 call your support.

015

- Set the 3746-950 to online mode, if not already done.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem management" option.
 - Double click on the "Set 3746-9x0 Online/Offline Option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK".
- Start a general IML.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Operations Management" option.
 - Double click on the "Perform a general IML" option.
 - On the "Perform general IML" window, click on "YES" to continue.
 - On the next "Perform general IML" window, click on "NO" to start an IML without diagnostic.
 - Return to the "MOSS-E View" window.
 - Click on the "Program" title bar.
 - Click on the "Status" option and wait for the IML to end with 00000000 displayed. Then click on "OK".
- Go to Step 016.

016**Have you been working on CLP?**

Yes No

017

Go to Step 019.

018

Check the CLP mode setting with the customer and change it if necessary. Use the "MAP: 3746-950 CLP Backup or Standard Mode Setting" on page 1-135. When it is complete continue with Step 019.

019

- Return to the "MOSS-E VIEW" window.
- On the 3746-950 control panel, set the power control mode to its initial value.

Go to "CE Leaving Procedure" on page 4-53

MAP: 3746-950 Ending Procedure in Concurrent Mode

You are here after performing a procedure in concurrent mode.

001

Have you solved a connection problem to RETAIN?

Yes No

002

Was there a RETAIN connection problem for transmitting the last call?

(If you do not know and if the customer cannot provide the answer, go to Step 006).

Yes No

003

Go to Step 009.

004

Go to "MAP 2000: 3746-950 Manual Call" on page 2-1.

005

Go to Step 009.

006

- Return to the "MOSS-E View" panel.
- Double click on the service processor icon.
- The "Service Processor Menu" is displayed.
- Click on the "Problem Management" option.
- Double click on the "Display Alarms" option.
- Scroll the alarm to find if there is an alarm 0643 or 064C.

Do you find an alarm 0643 or 064C in the alarm list?

Yes No

007

No RETAIN connection problem have been found. Go to Step 009.

008

You had a RETAIN connection problem. Go to "MAP 2000: 3746-950 Manual Call" on page 2-1..

009

Before returning the machine to the customer, check on the CDF-E that all the resources of your 3746-950 are available or active

- Return to the "3746-9x0 Menu" window.
- Click on the "Configuration Management" option.
- Select the "Display/Update Active Configuration (CDF-E).

Are all the resources that you put in concurrent mode available or active now?

Yes No

010

- Return to the "Problem Management" window.
 - Select the "Perform Maintenance" option.
 - On the "Resource Selection Options for Maintenance" select, "Via the active CDF-E" option.
 - On the following "Resource Selector" windows, select the resource that you want removed from concurrent mode.
 - On the "Maintenance Options" window, select "Remove from concurrent mode" and click on OK.
 - On the "Resource Selector" window, click on "Cancel".
- (Step **010** continues)

010 (continued)

- On the "Maintenance Options" window, click on "Cancel" to go back to the "3746-9x0 Menu" window.
- On the "3746-9x0 Menu" window, select the "Configuration Management" option.
- Select the "Display/Update Active Configuration (CDF-E).

Are all the resources that you put in concurrent mode available or active now?

Yes No

011

Is there an ESCP or an ESCC not available?

Yes No

012

Call your support.

013

Go to "MAP: 3746-950 ESCC/ESCC2 Enabling" on page 1-133 to enable it then go to Step 009 on page 1-128.

014

Go to Step 015.

015

Have you changed any FRU which appears in the CDF-E?

Yes No

016

Go to Step 026 on page 1-130.

017

Have you changed a processor?

Yes No

018

Go to Step 022 on page 1-130.

019

- Go to "3746-950 EEPROM Upgrade" on page 1-144 to perform the EEPROM upgrade. When it is complete continue here.
- Return to the "3746-9x0 Menu" and click on "Problem Management".
- Double click on the "Change Resource Status" option.
- The "Resource Status Change-Resource Selector" window is displayed. Select the processor that you have changed and click on "OK".
- On the next "Resource Selector" window, click on "OK".
- On the "Resource Status Change-Selection" window, select the "IML without diagnostics" option and click on "OK".
- A "Warning" window is displayed saying you that your request is being performed and waiting for its completion.

Is the "Warning" window saying that your request has been successfully completed?

Yes No

020

Call your support.

021

- On the "warning" window, click on "OK".
- (Step **021** continues)

021 (continued)

- The "Resource Status Change-Resource Selector" window is displayed. Click on "Cancel".
 - The "3746-9x0 Menu" window is displayed.
 - Go to Step 022
-

022

- You need to save the active CDF-E as Reference CDF-E.
 - Return to the "Configuration Management" window.
 - Click on the "Save active CDF-E as Reference CDF-E" option.
 - Follow the procedure displayed on successive screens.
 - You need to copy the reference CDF-E on the 3746-950 installation parameter diskette.
 - Return to the "Configuration Management" window.
 - Select the "Copy Reference CDF-E on Diskette" option.
 - Follow the procedure displayed on successive screens.
 - Then go to Step 023.
-

023

Have you been working on CLP?

Yes No

024

Go to Step 026

025

Check the CLP mode setting with the customer and change it if necessary. Use the "MAP: 3746-950 CLP Backup or Standard Mode Setting" on page 1-135. When it is complete continue with the Step 026

026

- Return to the "3746-9x0 Menu" window.
 - Click on "Function" (in the action bar).
 - Select "Exit".
- If you have changed the power control mode from remote to local set it again to remote mode:
 - Press the 'Power control' key until (1) is displayed in the power control window.
 - Press the 'Validate' key.

Inform the customer that the resource(s) is(are) now available, then go to "CE Leaving Procedure" on page 4-53.

MAP: 3746-950 ESCC/ESCC2 Disabling

001

Perform the following steps to disable the ESCC:

- You should be logged ON the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the 3746-950 icon on which you want to work.
- On the "3746-9x0 Menu", click on the "Configuration Management" option.
- Double click on the "Manage ESCON Processors" option.
- On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
- The "ESCON Configuration Lines" window is displayed.
- Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
- The "ESCC Status Management" window is displayed.

ESCC Satus Management			
Options Refresh Help			
ESCP 2240		Configuration from ESCP	
ESCC 0: 2240	Present: YES	ESCC 1: 2272	Present: NO
ESCC 0 Status: DISABLED		ESCC 1 Status:	
Request to change ESCC 0 status:		Request to change ESCC 1 status:	
o Enable		o Enable	
o Transmit offline sequence		o Transmit offline sequence	
o Disable		o Disable	
Fiber status IN =		Fiber status IN =	
Fiber status OUT =		Fiber status OUT =	
Control unit link address		Control unit link address	
(CNTLUNIT LINK):		(CNTLUNIT LINK):	
Bit error rate counter:		Bit error rate counter:	

- Select the "disable" option.
- Click on "Options" (in the action bar). Then select the "Send request and save" option.
- A "confirmation" window is displayed. Click on "OK".
- A "Warning" window informs you that the ESCP configuration is saved. Click on "OK".
- Click on "Refresh" (in the action bar). Then select "Permanent Refresh" (no further action is possible from this screen).
- When the "disable" is complete the "ESCC x Status" line displays: DISABLED.

Is DISABLED displayed?

Yes No

002

Suspect a problem in ESCC or ESCP. Go to "3746-950 Maintenance Using a FRU list" on page 1-28 to exchange the suspected FRU.

003

- Click on "Refresh" (in the action bar). Then select "Stop permanent refresh".
- Return to the "3746-9x0 Menu".
 - Click on "Options" (in the action bar). Then select the "Return" option.
 - On the "ESCON Configuration lines" window, click on "Options" and on "Exit".

(Step **003** continues)

3746-950 Procedures

003 (continued)

- On the "Confirmation" window, click on "OK".
 - On the "ESCP Management Resource Selector" window, click on "Cancel".
 - The "3746-Menu" is displayed.
 - Return to the step in the MAP you were performing.
-

MAP: 3746-950 ESCC/ESCC2 Enabling

001

Perform the following steps to enable the ESCC:

- You should be logged ON the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window double click on the 3746-950 icon on which you want to work.
- On the "3746-9x0 Menu", click on the "Configuration Management" option.
- Double click on the "Manage ESCON Processors" option.
- On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
- The "ESCON Configuration Lines" window is displayed.
- Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
- The "ESCC Status Management" window is displayed.

ESCC Satus Management			
Options Refresh Help			
ESCP 2240		Configuration from ESCP	
ESCC 0: 2240	Present: YES	ESCC 1: 2272	Present: NO
ESCC 0 Status: ENABLED		ESCC 1 Status:	
Request to change ESCC 0 status:		Request to change ESCC 1 status:	
o Enable		o Enable	
o Transmit offline sequence		o Transmit offline sequence	
o Disable		o Disable	
Fiber status IN =		Fiber status IN =	
Fiber status OUT =		Fiber status OUT =	
Control unit link address		Control unit link address	
(CNTLUNIT LINK):		(CNTLUNIT LINK):	
Bit error rate counter:		Bit error rate counter:	

- Select the "enable" option.
- Click on "Options" (in the action bar). Then select the "Send request and save" option.
- A "confirmation" window is displayed. Click on "OK".
- A "Warning" window informs you that the ESCP configuration is saved. Click on "OK".
- Click on "Refresh" (in the action bar). Then select "Permanent Refresh" (no further action is possible from this screen).
- When the "enable" is complete the "ESCC x Status" line displays: ENABLED.

Is ENABLED displayed?

Yes No

002

- Check that the wrap plug is not installed on the ESCC.
- Check that the fiber optic is well installed on the ESCC.

If everything is "OK", call your support. Otherwise correct the problem and re-start the ESCC enabling.

003

- Click on "Refresh" (in the action bar). Then select "Stop permanent refresh".
- (Step **003** continues)

003 (continued)

- Return to the "3746-9x0 Menu".
 - Click on "Options" (in the action bar). Then select the "Return" option.
 - On the "ESCON Configuration lines" window, click on "Options" and on "Exit".
 - On the "Confirmation" window, click on "OK".
 - On the "ESCP Management Resource Selector" window, click on "Cancel".
 - The "3746-Menu" is displayed.
 - Return to the step in the MAP you were performing.
-


MAP: 3746-950 CLP Backup or Standard Mode Setting

The hardware can connect four adjacent LICs to two adjacent CLPs. This hardware connection allows the CLPs to operate in standard mode or backup mode depending on the option defined in the MOSS-E table.


The Backup Mode is only possible between two adjacent positions

CLP Position	Line Addresses	Attached LIC Position	CLP Backup Position
07G-A1-H	2112-2175	07N-A1 G and H	07G-A1 K
07G-A1-K	2176-2239	07N-A1 J and K	07G-A1 H
07G-A1-M	2240-2303	07N-A1 L and M	07G-A1-P
07G-A1-P	2304-2367	07N-A1 N and P	07G-A1-M
07E-A1-D	2368-2431	07M-A1 C and D	07E-A1-F
07E-A1-F	2432-2495	07M-A1 E and F	07E-A1-D
07E-A1-H	2496-2559	07M-A1 G and H	07E-A1-K
07E-A1-K	2560-2623	07M-A1 J and K	07E-A1-H
07E-A1-M	2624-2687	07M-A1 L and M	07E-A1-P
07E-A1-P	2688-2751	07M-A1 N and P	07E-A1-M
07D-A1-D	2752-2815	07L-A1 C and D	07D-A1-F
07D-A1-F	2816-2879	07L-A1 E and F	07D-A1-D
07D-A1-H	2880-2943	07L-A1 G and H	07D-A1-K
07D-A1-K	2944-3007	07L-A1 J and K	07D-A1-H
07D-A1-M	3008-3071	07L-A1 L and M	07D-A1-P
07D-A1-P	3072-3135	07L-A1 N and P	07D-A1-M

CLP in Backup Mode



CLP in Standard Mode



001

- Before continuing it is necessary to check if the CLP under investigation has a backup CLP and if the LIC(s) normally under the control of the CLP under investigation are now under the control of the backup CLP.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Configuration Management" option.
 - Double click on the "Define Backup CLP" option.
 - The following "CLP Backup" window is displayed.

CLP Backup

Select a processor:

Processor Type	Primary Processor	Backup Processor	Automatic Fallback	Fallback State	Switchback Requested	
CLP	2112	2176	no	no	no	1
CLP	2176	2112	no	yes	no	2
CLP	2240		no	no	no	3
CLP	2304		no	no	no	3

Notes:

- 1** and **2** These lines indicates that the CLP line addresses ranges from 2112 and from 2176 can be backup for each other.
 - 2** This line with a "yes" in the fallback state column indicates that the primary processor (2176) is controlling the LICs of the backup processor (2112).
 - 3** These lines indicate that the CLPs have no backup.
- Note if the CLP under investigation is backuped by another one, then click on the "Cancel" key.

Does the primary CLP under investigation have a backup CLP with a "Yes" in the fallback state column?


Yes No

002

Go to Step 006 on page 1-137

003

The LIC(s) of the CLP under investigation are under the control of the backup CLP.



LICs under control
of the CLP Backup

LICs under control of their
own CLP after Switchback

Do you want to switchback the LIC(s) under the control of their own CLP?

Yes No

004

Return to the step in the MAP you were performing.

005

- Ask the customer to stop traffic on the LIC(s) associated with the processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- When the traffic is stopped, on the "CLP Backup" window, select the CLP and click on the "Switchback" key.
- On the "Confirmation" window, click on "OK".
- Wait for alarm "Switchback successful" and click on "OK".
- Click on "Cancel" to return to the "3746-9x0 Menu".
- Return to the step in the MAP you were performing.

006

Do you want put the LIC(s) of the CLP under investigation, under the control of the backup CLP?

Yes No


007

Return to the step in the MAP you were performing.

008

The LIC(s) of the CLP under investigation, are under the control of the backup CLP.

3746-950 Procedures



- Ask the customer to stop traffic on the LIC(s) associated with the processor.
 - If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
 - When the traffic is stopped, click on the "Configuration Management" option on the "3746-9x0 Menu" window.
 - Double click on the "Define Backup CLP" option.
 - The "CLP Backup" window is displayed.
 - Select the CLP on which you want remove the attached resources and click on the "Fallback" key.
 - On the "Confirmation" window, click on "OK".
 - After fallback, the "3746-9x0 Menu" is displayed.
 - Return to the step in the MAP you were performing.
-


Activate/Deactivate a Resource Via CCM

Note


This procedure does not apply for MAE resources see the *Multiaccess Enclosure Installation and Maintenance*, manual manual.

You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.


1. Click on the 3746-950 on which you want to work.
2. The "3746-900 menu" window is displayed.
3. Click on the "Network Node Processor (NNP) Management" option.
4. Double click on the "CCM Controller Configuration and Management" option.
5. The "CCM" window is displayed.




6. Click on "Management" in the title bar, select "Manage resources with filter" , then click on "Ports".



7. In the "Port Management Filters" window, select "Port Number". The address range of the resource appears in the right of the window. Modify this address range according to the resource that you want to manage.



8. Click on "OK".
9. The "Ports Management" window is displayed, click on "Operations". A "Details" menu appears.
- If you want to activate the resource select "Activate listed Ports" option.
 - If you want to deactivate the resource select "Deactivate/Disable Selected Resources (Normal Mode)".



10. Click on "OK" in the following window.
11. Return where do you come from.

3746-950 Setting in Offline Mode

To set the 3746-950 in Offline mode, you must first set the 3746-950 in Offline mode and then start an IML.

- Set the 3746-950 in Offline mode.
 - You should be logged ON the service processor console. If not go to “Console Use for maintenance” on page 1-1 for logging ON and return here.
 - On the "MOSS-E View" window, double click on the 3746-950 icon on which you want to work.
 - On the "3746-9x0 Menu", click on the "Problem Management" option.
 - Double click on the "Set 3746-9x0 Online/Offline Option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK"
- Start a general IML.
 - Return to the "3746-9x0 Menu".
 - Click on the "Operations management" option.
 - Double click on the "Perform a General IML" option.
 - On the "Perform General IML" window, click on "YES" to continue.
 - On the next "Perform General IML" window, click on "NO" to start the IML without diagnostic.
 - Return to the "MOSS-E View" window.
 - Click on the "Program" title bar.
 - Click on the "Status" option and wait for the IML to end with 00000000 displayed. Then click on "OK".
- Return to the step in the MAP you were performing.

Display the FRU List After a Diagnostic Failure

1. If you are here after following the steps in a MAP press simultaneously the Ctrl/Escp keys on the keyboard and continue with the next step otherwise go to step 4.
2. The "Window List" window is displayed.
3. Double click on the "3746-9x0 Menu" option.
4. From the "3746-9x0 Menu" window, click on the "Problem management" option.
5. The "Problem management" window is displayed.
6. Double click on "Manage Alarms/Errors/Events (SRC)".
7. The "System reference code option Selection" window is displayed.
8. Select "Alarms (Interpretation possible)", "All resources" option and click on "OK".
9. An "Alarms" window is displayed.

3746-9x0 Alarms

Options View Help									
Select an alarm for more information									
Number	Type	NT	UU	RRRR	MM/DD/YY	HH:MM:SS	Text		
9	ALARM	06	30	3030	10/30/92	14:45:10	ALARM	0521	POWER LOGIC
7	ALARM	06	30	3030	10/30/92	14:44:48	ALARM	0501	HARDWARE ERR
3	ALARM	06	30	3030	10/30/92	14:44:02	ALARM	0501	HARDWARE ERR

OK
Previous List
Next List
List Selection
Cancel
Help

10. Select the last alarm (it is the one which is at the top of the screen).
11. Click on "View" (in the action bar). Then click on "Problem Interpretation" option.
12. A "Problem Interpretation" window gives you the list of suspected FRUs with their fault probability.
13. Record the FRU list and probability for later use.
14. If you were there leaded by a procedure return to the point in the procedure where you come from using the "Cancel" key.

3746-950 EEPROM Upgrade

EEPROM Upgrade Overview

The EEPROM of processors in the 3746-950 must be upgraded after certain:

- Microcode change levels (MCLs)
 - Note:** For MCL, the EEPROM Upgrade is done automatically.
- Microcode change fixes (MCFs),
- EC installation
- Processor replacement.

EEPROM Upgrade/Downgrade Processing

Warning

During EEPROM Upgrade/Downgrade, **Do not** power OFF or IML the 3746-950.

You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

1. On the "MOSS-E VIEW" window, double click on the 3746-950 icon on which you want to work (Note 1).
2. On the "3746-9x0 Menu" window, click on the "Change Management" option.
3. Double click on the "Upgrade/Downgrade EEPROM Code Level".
4. An "EEPROM Upgrade" window is displayed telling you that the service processor is searching the 3746-950 configuration.
5. On the "EEPROM Upgrade" window, the upgradable or downgradable processors are highlighted in reverse video according to the preselected status of the "Upgrade" or "Downgrade" options at the top of the window.

0 Upgrade 0 Downgrade (Note 2)		
Processor	EEPROM level: PN - EC - MCL	Upgrade Status
CBSP 2048 Available	Current: 43G3435 - D21455 - 002 New : 43G3435 - D22455 - 008	
TRP 2112 Disconnected	Current: 43G3425 - D22455 - 007 New : 43G3425 - D22455 - 008	
TRP 2170 Available	Current: 43G3435 - D22455 - 001 New : 43G3435 - D22455 - 008	
TRP 2304 Active	Current: 43G3425 - D22455 - 037 New : 43G3425 - D22455 - 008	

1
2
3

OK

CANCEL

HELP

- **1** Shows the list of the 3746-950 processors in CDF-E with their status (available, disconnected or active).
- **2** Shows the current and new EEPROM levels: PN/EC/Level of each processor.
- **3** The upgrade status after the activation of the function.

6. Select the "Upgrade" or "Downgrade" option at the top of the screen. Then click on "OK" according to the action that you want to perform.
7. An "EEPROM Upgrade" window informs you that the EEPROM upgrade or downgrade is in progress and the time duration.
8. At the end of the EEPROM upgrade or downgrade, an updated "EEPROM Upgrade" window is displayed with the status of the upgrade or downgrade for each processor.
9. Check the result of your EEPROM upgrade/downgrade operation using the following table and take the appropriate action:

EEPROM Status	Action
Complete	Upgrade done without error continue with the next step.
Start failed	Call your support
Failed	Call your support
Completion failed	Call your support

10. **If you have done the EEPROM Upgrade after exchanging a processor, leave this procedure and return to the step in the MAP you were performing.** Otherwise, continue with the next step.
11. Return to the "3746-9x0 Menu" and click on "Operation Management".
12. Double click on the "Perform General IML".
13. A Normal IML is terminated when 00000000 is displayed on the 3746-950 control panel.
 - If the control panel displays 00000000, go to "CE Leaving Procedure" on page 4-53
 - If the control panel displays another code than 00000000, call your support.

Notes:

1. During MCL (which is automatic), steps 1, 2, 3 are hidden (see MCL process).
2. During MCL (which is automatic), Upgrade and Downgrade options are not shown on screen.

Engineering Data Transfer

Overview

The engineering data can be transferred in three main ways:

- On diskettes
- DCAF (Distributed Console Access Facility) via LAN, SDLC
- Using Java file manager.

The transfer can be done from:

- The local service processor using diskettes (when files are not too big)
- The remote service processor using DCAF or console for Java.

Preparing Engineering Data on the Local Service Processor

1. If not already logged, enter the "Service Processor maintenance password" (default is IBM3745), or ask the customer if a specific password has been defined.
2. Double click on the "Service Processor" icon.
3. Click on "Operation Management".
4. Double click on "Manage Engineering Data". The following window is displayed:

Figure 1-16. Manage Engineering Data Window

5. Enter the PMH number, the branch office and the country codes.
6. Select the "processor" with the radio button. If you do not want zip some of these files, select them and click on "Remove".
7. Repeat the two preceding Steps for each processor.
8. When you have terminated your selection, click on "Create Zip Files...", then wait until the message "zip files successfully created" is displayed.
9. Click on "OK".

Note: The Zip files created are on the disk H: of the service processor.

Transferring Engineering Data from the Service Processor

Using a Diskette

To copy the engineering data on diskette you must have access to an OS/2 window which is available after logging on the "MOSS-E View" with a PE password. An OS/2 window is available in the "Functions to Use Under PE Guidance only". Copy the Zip files which are on the H: disk of the service processor on the diskette.

Using DCAF or Console for Java

The transfer of the engineering data from the service processor to the remote service processor (or workstation) must be initiated from the remote site using DCAF or console for Java. Refer to the &csg. manual for detailed procedure.

Note

Do not forget to "Delete" the engineering data when they have been successfully recorded on diskette, or transferred to a support center via DCAF or Java.

3746-950 Diagnostic Requirements

If you want to run diagnostics you must first ensure that the area to be tested by the diagnostics is correctly disabled, from customer resources.

The following list gives the prerequisite to be able to run test on specific 3746-950 area.

For tests available for each 3746-950 area refer to “3746-950 Diagnostics Invocation” on page 3-2.


<u>AREA</u>	<u>WHERE YOU SHOULD GO</u>
ALL	Only very rarely should it be necessary to run all diagnostics. If the customer is using the machine, consider if it is really necessary to run all. If so ask the customer to stop using the machine and go to “MAP 2980: How to run 3746-950 Diagnostic in Offline Mode” on page 3-39.
CBSP	To run the diagnostic in concurrent mode APPN must be stopped. Refer to “MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode” on page 3-16.
CLP	No specific requirement.
CS	The 3746-950 must be set in Offline mode. Refer to “MAP 2980: How to run 3746-950 Diagnostic in Offline Mode” on page 3-39
CSCE	The 3746-950 must be set in Offline mode. Refer to “MAP 2980: How to run 3746-950 Diagnostic in Offline Mode” on page 3-39
ESCC	To run the diagnostic in concurrent mode the ESCC must be disabled: Refer to “MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode” on page 3-16 or refer to “MAP: 3746-950 ESCC/ESCC2 Disabling” on page 1-131. After diagnostic the ESCC must be enabled again, follow the procedure “MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode” on page 3-16 or refer to “MAP: 3746-950 ESCC/ESCC2 Enabling” on page 1-133.
ESCP	To run the diagnostic in concurrent mode the ESCC must be disabled: Refer to “MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode” on page 3-16 or refer to “MAP: 3746-950 ESCC/ESCC2 Disabling” on page 1-131. After diagnostic the ESCC must be enabled again, follow the procedure “MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode” on page 3-16 or refer to “MAP: 3746-950 ESCC/ESCC2 Enabling” on page 1-133.
LCPB/LCPE/ARC	No specific requirement.
LIC11	No specific requirement.
LIC12	No specific requirement.
MAE	No specific requirement for specific device of the MAE. For the complete test of the MAE no customer traffic, refer to “MAP 3000: How to Run the Selective IML on the Multiaccess Enclosure” on page 3-47.
TIC3	No specific requirement.
TRP	No specific requirement.

3746-950 Control Panel Use

WARNING: Providing the 3746-950 power control switch or the 3746-950 CB1 have not been activated, the control panel always has power and will display information on power control and service even though the 3746-950 is powered OFF.

Purpose of the Control Panel

The control panel allows the execution of functions which cannot be accessed via the service processor.



Note: Functions 0, 1, and 2 are not selectable using the function key. Use the keys on the right of the panel to initiate these functions.

Figure 1-17. 3746-950 Control Panel Layout

Explanation of 3746-950 Panel Keys, LEDs and Switches

Refer to Figure 1-17 on page 1-149 for the location of the keys and switches.

The following three keys allow the operator to scroll the different options available.

Function key: The 'Function' key allows you to scroll through functions (3, 4, 5, 6, 7, 8) in the display window. On the panel display, the digit of the selected function starts blinking.

Notes:

1. In 'normal (0)' service mode, pressing the function key will scroll through functions 3, 4, 6 and 8.
2. In 'maintenance (1)' service mode, pressing the function key will scroll through functions 3 to 8.

Service Mode Key: The 'Service mode' key allows you to scroll through functions (0, 1) in the display window. On the panel display, the digit of the selected function starts blinking.

Note: A 'D' is displayed when the SPS card is under test and no action is allowed on the 3746-950 control panel.

Power Control Key: The 'Service mode' key allows you to scroll through functions (1, 3) in the display window. On the panel display, the digit of the selected function starts blinking.

Validate Key: When you press this key, the digit of the selected function stop blinking and the action is carried out. A function that is not validated is de-selected after a time out of 60 seconds.

Exit Key: Pressing this key cancels the selected function.

Start Key: This key allows the operator to put the 3746-950 in 'Ready' state when in 'Local' power control mode and 'Standby' state.

Standby Key: This key allows the operator to put the 3746-950 in 'Standby' state when in 'Local' power control mode and 'Ready' state.

General IML Key: This key allows the operator to initiate a general reset and IML without diagnostics.

Warning

Before starting a general IML perform a function 8. This prevents alarms/alerts being sent from the service processor to ESCON manager on fiber link.

CBSA IML Key: This key allows the operator to initiate a CBSA reset followed by a CBSA IML with diagnostics.

CBSP Dump Key: This key allows the operator to initiate a CBSP reset followed by a CBSP dump.

Ready Indicator: This indicator is a green LED. It blinks when the 3746-950 starts to power ON. It stays ON as soon as the machine is in power ON state and IML is complete.

Standby Indicator: This indicator is a yellow LED. It blinks when the AC is applied on the 3746-950. It stays ON when the Standby state is reached and turns OFF as soon as the machine is in power ON state.

CBSA Check Indicator: This indicator is a yellow LED. It goes ON when the CBSP card is diagnosed as being faulty.

Power Control Switch: This key allows the operator to power down the 3746-950.

Note

When the power control switch is to the position (⏻), the primary powers (ACDC) or filters section (DCDC) stay energized.

For total disconnection:

1. Turn the CBs OFF
2. Remove all the power plugs from supply outlets or shutdown installation.

3746-950 Control Panel Display Description

The control panel display is a gas panel and the various fields can have different values. The meaning of each value is given in Table 1-5.

Table 1-5. Panel Display Values		
Indicator	Display	Description
Function	0	General IML without diagnostics (see Note 1)
	1	CBSA IML with diagnostics (see Note 1)
	2	CBSP dump (see Note 1)
	3	General IML with diagnostics (see Note 2)
	4	CBSA IML without diagnostics (see Note 2)
	5	Panel test
	6	Service processor link restart
	7	Display error code
	8	ESCC logical disconnection
Code	00000000 to FFFFFFFF	An 8 hexadecimal character code which shows function progress codes and error codes. A code blinks when an error condition has been detected.
Service Mode	D	Diagnostics (SPS under test)
	0	Normal
	1	Maintenance
Power Control	1	Remote: the 3746-950 is powered ON and OFF from the host system, or service processor. If ac power is lost and then restored, an <i>Auto Restart</i> is performed.
	3	Local: the 3746-950 is powered ON from the 'START' key and powered OFF from the 'STAND-BY' key on the control panel.
All channels disabled	※	Indicator ON indicates all channels are disabled.
	Blank	Indicator OFF indicates that at least one channel is enabled.
Service processor not accessible	※	Indicator ON, the service processor is not available for the CBSP

Notes:

- Functions 0, 1, and 2 are not selectable using the function key. Use the keys on the right side of the panel to start these functions.
- Function 8 is automatically executed when you start functions 3 and 4.

How to Perform 3746-950 Control Panel Operations

IMPORTANT

Before working on non-customer access areas of the 3746-950, power control should be set to Local Mode. This can be done as follows:

1. Using the 'Power Control' key, scroll until the selected value is **3**, Local Mode.
2. Press the 'Validate' key.

Power ON

To start the machine in 'Standby' state, press the 'Start' key. A Power ON sequence is executed followed by a general IML. At successful conclusion of the operation, the display appears as follows:

0	0 0 0 0 0 0 0 0	X X
---	-----------------	-----

X= variable values

General IML

Press the 'General IML' key to select 'Function 0' (General IML without diagnostics). A general reset, followed by a general IML is executed. At successful conclusion of the operation the display appears as follows:

0	X X X X X X X X	X X
---	-----------------	-----

X= variable values

CBSA IML

Press the 'CBSA IML' key to select 'Function 1' (CBSA IML with diagnostics). A CBSA reset is initiated, followed by a CBSA IML. At successful conclusion of the operation the display appears as follows:

1	X X X X X X X X	X X
---	-----------------	-----

X= variable values

CBSP Dump

Press the 'CBSP Dump' key to select 'Function 2' (CBSP dump). A CBSA reset and dump of CBSP microcode are executed. At successful conclusion of the operation, the display appears as follows:

2	X X X X X X X X	X X
---	-----------------	-----

X= variable values

General IML With Diagnostics

1. Using the 'Function' key scroll until the selected value is **3**, (General IML with diagnostics).
2. Press the 'Validate' key.

This initiates a General Reset and IML with diagnostics.

The progression code (system reference code SRC) is dynamically displayed on the control panel until the normal end of the power ON IML, is indicated as follows:

- Ready LED **ON**
- Standby LED **OFF**
- SRC **00000000** is displayed on the control panel.

CBSA IML Without Diagnostics

1. Using the 'Function' key, scroll until the selected value is **4**, CBSA IML without diags.
2. Press the 'Validate' key.

This initiates a CBSA reset and CBSA IML without diagnostics.

Panel Test

See the procedures described in "How to Run the 3746-950 Control Panel Test" on page 3-14.

Service Processor Link Restart

See the procedures described in "How to run the 3746-950 Service Processor Link Restart" on page 3-15.

Display Error Code

1. Using the 'Function' key, scroll until the selected value is **7**, (Display reference code).
2. Press the 'Validate' key.

This displays the next part of the reference code.

- Press the 'Service mode' key to scroll forward.
- Press the 'Power control' key to scroll backward.

Control Panel LED Status Versus 3746-950 States

Table 1-6. LED Status Versus 3746-950 States			
Standby LED	Ready LED	3746-950 State	Comment
Blinking	OFF	AC ON	Initialization of the CBSP hardware, and the 3746-950 waits for first recognition by the MOSS-E on LAN connection.
ON	OFF	Standby	The 3746-950, initially recognized by the MOSS-E, waits for a power ON condition, (only the CBSP EEPROM code is running).
OFF	Blinking	Power ON	IML loading in all 3746-950 processors.
OFF	ON	Ready	The 3746-950 is now available.

IML Request Versus 3746-950 States

The CBSA IML, the general IML, the service processor link restart function started from the control panel, and the selective IML on a processor started from the MOSS-E are all executed (or not) depending on the initial 3746-950 state.

The requested action is started only if the 3746-950 is in ready state. If not, a default action is started as shown in the following table.

Table 1-7. IML Request Versus 3746-950 States				
Initial 3746-950 State	CBSA IML Request (1/4)	General IML Request (0/3)	Selective IML Request	Service Processor Link Restart (6)
AC ON (Note 1)	General IML (0/3)	General IML (0/3)	NA	General IML (3)
Standby (Note 1)	General IML (0/3)	General IML (0/3)	NA	General IML (3)
Power ON /IML in progress (Note 2)	General IML (0/3)	General IML (0/3)	NA	General IML (3)
Ready (Note 2)	CBSA IML (1/4)	General IML (0/3)	Selective IML	Service Processor Link Restart (6)
CBSA IML in progress (Note 2)	CBSA IML (1/4)	General IML (0/3)	NA	CBSA IML (1/4)
Selective IML (Note 2)	CBSA IML (1/4)	General IML (0/3)	Wait previous selective IML end	Service Processor Link Restart (6)

Notes:

1. The final state is standby.
2. The final state is ready.

Chapter 2. MAPs for FRU Isolation

3746-950 RSF MAP

MAP 2000: 3746-950 Manual Call

You are here because there was a problem in connecting the service processor to RETAIN or because you want to test this facility.

Perform a manual call using the 3746-950 facilities to check this connection.

You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

Before starting this MAP check the "Remote Support facility" options using the following procedure:

- On the "MOSS-E VIEW" window, double click on the service processor icon.
- The "Service Processor Menu" window is displayed.
- Click on the "Configuration Management" option.
- Double click on the "Manage Remote Operations" option.
- On the "Remote Operation Management" window, select the "Remote operations authorization" option and click on "OK".
- On the "Remote Support Facility" window, check that the two following options:
 - "Enable Remote Support Facility"
 - "Generate alerts"
 are selected.
- Select them if not already done and click on "OK".
- Click on "Cancel" to return to "Service Processor Menu".

001

- Return to the "MOSS-E View" window, then double click on the 3746-950 icon.
- Click on the "Problem Management" option.
- Double click on the "Report Problem Using Remote Support Facilities".
- On the "Problem Analysis" window, enter a short description: 'Testing the RSF link'. Then click on "OK".
- On the "Report Problem Using RSF" window click on "OK".
- Wait for either the alarm "Call to RETAIN successful" indicating the normal end of transmission, or the message "Call to RETAIN failed".
- Write down the alarm number.

Is the alarm "Call to RETAIN successful" displayed?

Yes No

002

Go to Step 004 on page 2-2.

003

The connection to RETAIN is successful. The following table shown the alarms generated by this connection.

Select the alarm number	Meaning
0641	Your microcode is up-to-date, so no fix has been downloaded.
0642	Fix has been downloaded automatically. Install the fix.
0649	Call to RETAIN successful but no download, MCL too large/not enough disk space. Active and accepts all MCL(s) already received to free space disk and retry the normal call for the new MCL(s). If problem persists call your support. PE problem.

3746-950 Control Panel

If following the MAP you changed a FRU:

- In concurrent mode, go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.
- In offline mode, go to "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39.

Otherwise, go to "CE Leaving Procedure" on page 4-53.

004

Locate the alarm number in the following table and perform the action required.

Select the alarm number	Action
0643	Go to Step 005
0644	Call to RETAIN not authorized. Refer to the <i>Service Processor Installation and Maintenance</i> manual, step "Recording the Customer Informations".
064C	<p>The call to RETAIN has been performed but RETAIN required a disconnection due to a bad product set up. The following information is missing in RETAIN customer CCPF file or system registration file.</p> <ul style="list-style-type: none">• Customer number• Machine model xxA• Branch office number• Area number• Warranty/Status <p>Provide thus information to your support before he contacts the RETAIN coordinator for updating.</p>
068C	Suspect a communication manager problem. Check the communication manager configuration. Refer to the <i>Service Processor Installation and Maintenance</i> manual, step "Setting Up Communication Parameters to Allow Remote and Netview Operations". Re-boot the service processor. If the problem persists call your support.
068D	Check the connection between modem and the line. Check that the telephone number used is correct. Refer to the <i>Service Processor Installation and Maintenance</i> manual, step "Recording the Customer Informations".

005

Click on "OK" on the alarm window. A second alarm should be displayed. Locate this second alarm number in the following table and perform the action required.

Select the alarm number	Action
064A	PE problem. Call your support
064B	PE problem. Call your support
064D	<p>The call to RETAIN has not been performed because:</p> <ul style="list-style-type: none"> • The associated data have not been tersed or • The associated tersed data have not been written to the service processor disk (the partition was full). To free space on disk perform the following steps. <ol style="list-style-type: none"> 1. Return to the "MOSS-E View" window. 2. Double click on the service processor icon. 3. On the "Service Processor Menu" click on the "Operation Management" option. 4. Double click on "Delete Engineering Data" option. 5. A "Deleting Engineering Data" window is displayed, asking you to confirm your choice. Click on "YES". 6. Follow the prompts. 7. When this operation is finished retry a call to RETAIN. <p>If the problem persists call your support for assistance.</p>
0681	<p>Suspect a multiprotocol adapter problem.</p> <ul style="list-style-type: none"> • Run the multiprotocol diagnostic (refer to the <i>Service Processor Installation and Maintenance</i> manual, chapter "How to Run the Service Processor Diagnostics"). • Check that the communication manager has been correctly initialized. • If everything is correct, suspect a modem problem. Refer to the modem documentation to run diagnostics.
0682	Suspect a communication manager problem. Re-start the communication manager or if this fails re-boot the service processor.
0685	<p>Machine not registered in RETAIN data base. The following information are missing in RETAIN CCPF.</p> <ul style="list-style-type: none"> • Machine type • Serial number <p>Provide thus information to your support before he contacts the RETAIN coordinator for updating.</p>
0686	Check telephone number and prefix configuration. Refer to the <i>Service Processor Installation and Maintenance</i> manual, step "Recording the Customer Informations".
0687	<p>Suspect an integrated modem problem.</p> <ul style="list-style-type: none"> • Run the integrated modem diagnostics using the wrap plug (refer to the <i>Service Processor Installation and Maintenance</i> manual, chapter "How to Run the Service Processor Diagnostics"). • If the modem is error free and if the problem persists call your support.
0688	<p>Suspect an integrated modem problem.</p> <ul style="list-style-type: none"> • Run the modem diagnostic using the wrap plug (refer to the <i>Service Processor Installation and Maintenance</i> manual, chapter "How to Run the Service Processor Diagnostics"). • If the modem is error free and if the problem persists call your support.
0689	Local modem is already in use. Check that the remote console is not in use.
068A	Integrated modem is already in use. Check that the remote console is not in use.
068B	<p>Suspect a modem problem.</p> <ul style="list-style-type: none"> • If you have an integrated modem, run the modem diagnostic using the wrap plug (refer to the <i>Service Processor Installation and Maintenance</i> manual, chapter "How to Run the Service Processor Diagnostics"). • If you have an external modem, refer to the modem documentation to run diagnostics. • If the modem is error free, suspect a line problem. Call the appropriate service representative.

3746-950 Power MAPs

MAP 2500: 3746-950 Power Control Subsystem Problems

Symptom Explanation	Conditions That Could Cause This Symptom
Machine will not Power ON. Ready or standby LED not lit.	<ul style="list-style-type: none"> • UEPO • CB1 or CP1 tripped • ACPW or DCPW • Any CBSA card or control panel • SPD1 or Basic board • SPS

FUNCTIONAL NOTE

Power may be present when nothing is displayed on the control panel.

001

– On the 3746-950 control panel.

Are the ready and standby LEDs OFF?

Yes No

002

Go to Step 025.

003

– Check the position of CB1 on the basic ACPW box. See Figure 2-2 on page 2-5.

Is CB1 in the ON position ?

Yes No

004

Go to Step 020.

005

– Refer to Figure 2-1. Check the ac main voltage on TB1 of the transformer.

Between pin and pinif input is

1	2	200 v
1	3	220 v
1	4	240 v




Figure 2-1. TB1 and TB2 Location on Transformer

Is the voltage correct?

Yes No

006

The customer power supply is defective. Also check that the ac cable is correctly seated in J2.

007

– Check CP1 on the ACPW box. See Figure 2-2 on page 2-5.

Is CP1 in the ON position ?

Yes No

008

Continue at "MAP 2530: 3746-950 CP1 Tripped." on page 2-11.

009

– Check CP2 and CP3 on the DCDP. See Figure 2-2 on page 2-5.
(Step 009 continues)




Figure 2-2. DCDP and Power Boxes

009 (continued)

Are both CP2 and CP3 in the ON position ?

Yes No

010

Continue at "MAP 2540: 3746-950 CP2 or CP3 Tripped" on page 2-14.

011

- Check CP4, CP5, CP6, and CP7 on the DCDP. See Figure 2-2.

Are all previous CPs in the ON position ?

Yes No

012

Continue at "MAP 2550: 3746-950 CP4, CP5, CP6, or CP7 Tripped" on page 2-16.

013

- Measure the 'dc sense 1' -48v at the Test 1 connector pin 5 as shown in Figure 2-2. Refer to YZ page 234 for test 1 pin assignment.

Is the voltage present and within tolerance between -40V and -60V. ?

Yes No

014

Exchange the ACPW box, go to "3746-950 Maintenance Using a FRU list" on page 1-28.

015

- Measure the 'UEPO SENSE' -5v at the Test 1 connector pin 14. Refer to YZ page 234 for test 1 pin assignment.
- (Step **015** continues)

015 (continued)

Is the voltage present ?

Yes No

016

UEPO problem. Check that the 3746-950 UEPO switch is in the normal position or use the YZ 242 page.

017

- Measure the 'HOLD UP' -48v at the SPD1 test connector J10 pin 5. Refer to YZ page 131 for SPD1 test connector pin assignment.

Is the voltage present ?

Yes No

018

Exchange the ACPW box, go to "3746-950 Maintenance Using a FRU list" on page 1-28.

019

First exchange the SPS. Then if the problem persists exchange the CBSP and the control panel. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

020

- Switch CB1 to the ON position.
 - Try to power ON again.
- (Step **020** continues)

020 (continued)

Is the 3746-950 powering ON now ?**Yes No****021****Is CB1 tripping again?****Yes No****022**

Go to Step 005.

023

Check that the machine is correctly wired for the customer's input voltage. Refer to Figure 2-1 on page 2-4. Check the ac main voltage on the TB1 of the transformer.

Between pin and pinif input is

1	2	200 v
1	3	220 v
1	4	240 v

If the voltage is correct exchange the ACPW box, go to "3746-950 Maintenance Using a FRU list" on page 1-28. Refer to YZ page 105 for an eventual transformer problem.

024

Go to "CE Leaving Procedure" on page 4-53 to return the machine to the customer. If the problem is still present, contact your support.

025**Is the STANDBY light permanently ON?****Yes No****026****Is the STANDBY light blinking?****Yes No****027**

Go to Step 038.

028**Is the SERVICE PROCESSOR NOT ACCESSIBLE digit ON?****Yes No****029****Is the CBSA CHECK light ON?****Yes No****030**

Note the 3746-950 control panel code. Go to "3746-950 Control Panel Codes" on

page 1-15 and perform the action required.

031

Exchange the CBSP. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

032

Go to "MAP 2750: 3746-950 Permanent Service Processor Link Problem" on page 2-84.

033

– Look at the power control window on the 3746-950 control panel and check the mode validity.

(1) for remote

(3) for Local.

Is the power mode in 'remote' ?**Yes No****034**

Are you here because you have a problem putting the 3746-950 power ON in 'local' mode?

Yes No**035**

Press the 'Power Control' key until 1 ('remote' mode) is displayed in the power control window. Then press the 'Validate' key. Try to power ON again.

036

Go to "MAP 2520: 3746-950 Power ON Problem in Local Mode" on page 2-10.

037

Go to "MAP 2510: 3746-950 Power ON Problem in Remote Mode" on page 2-8.

038**Is the READY indicator blinking ?****Yes No****039**

The READY LED is ON, the 3746-950 power ON is completed.

040

The 3746-950 has received a power ON command.
(Step 040 continues)

040 (continued)

Is the SRC displayed on the 3746-950 control panel changing?

Yes No

041

Is the SRC different from 0528 2806?

Yes No

042

Go to "MAP 2560: 3746-950 Ready LED Blinking." on page 2-17.

043

Note the 3746-950 control panel code. Go to "3746-950 Control Panel Codes" on page 1-15 and perform the action required.

044

Does the READY LED come ON?

Yes No

045

Note the 3746-950 control panel code. Go to "3746-950 Control Panel Codes" on page 1-15 and perform the action required.

046

– The 3746-950 power ON sequence is complete. The READY LED is ON, the 3746-950 power ON sequence is complete.

MAP 2510: 3746-950 Power ON Problem in Remote Mode

Symptom Explanation	Conditions That Could Cause This Symptom
Standby LED ON. Machine will not Power ON.	<ul style="list-style-type: none"> • ACPW or DCPW • Any CBSA cassette or control panel • SPD1 or Basic board • SPS cassette

FUNCTIONAL NOTE

Power may be present when nothing is displayed on the control panel.

The 3746-950 can be powered ON, when in 'remote' power mode by:

Host system connected to the 3746-950 (1)
Service Processor (2)




Figure 2-3. 3746-950 Remote Powering Possibilities

001

Is the 3746-950's power sequence initiated by a host connected to the 3746-950?

Yes No

002

The 3746-950's power sequence is controlled by the service processor.

Using the service processor check the errors logged.

- Go to the service processor console and if you are not already logged ON, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the 3746-950 icon.
- On the "3746-9x0 Menu" Click on the "Problem Management" option.
- Double click on the "Manage Alarms/Errors/Events (SRCs)" option.

(Step **002** continues)

002 (continued)

- The "System Reference Code Option Selection" window is displayed.
- On this window, select the options:
 1. "Errors (Correlation and interpretation possible)"
 2. "All resources"
 3. Specify the date interval that you want to see.
- Click on "OK".
- The "Error Type Selection" window is displayed.
- Select the "All types" option and click on "OK".
- An "Errors" window is displayed.
- Search for error on service processor LAN attachment to the 3746-900. (You can display all the lists using the "Previous List" and "Next List" keys.)
- Once you have find one error of this type, click on "View" (in the action bar). Then click on "Problem Interpretation" option.
- A "Problem Interpretation" window gives you the list of suspected FRUs with their fault probability for later use.
- Return to the "3746-9x0 Menu" window using the "Cancel" key.

003

the 3746-950's power sequence is controlled by a host connected to the 3746-950.

- Check for -28v between frame ground and the back of the host connector that initiated the command at RPO 01S Jx pins 1 and 5. See Figure 2-4 on page 2-9.




Figure 2-4. RPO Location 07R-A1

- Check the '-28 v unit source' on pin 1.

Is -28v present on pin 1 ?

Yes No

004

- Check that the cable is correctly plugged into the J8 connector at the back of the DCDP.

Is plugging correct?

Yes No

005

Plug the cable correctly and restart the operation.

006

Exchange the DCDP. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

007

- Check the 'Power hold command' on pin 5.

Is -28v present on pin 5 ?

Yes No

008

Host or cable problem.

009

- Check the 'PWRHOLDEPO' on pin 36 of the test 1 connector. Refer to YZ page 234 for test 1 pin assignment.
(Step 009 continues)

009 (continued)

Is -5v present?


Yes No

010

Exchange the DCDP. Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

011

- Check that the cable is correctly plugged into the J8 connector on the SPD1 and into the J7 connector on DCDP.



Is plugging correct?

Yes No

012

Plug the cable correctly and restart the operation.

013

First exchange the SPS. If the problem persists exchange the SPD1. Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

MAP 2520: 3746-950 Power ON Problem in Local Mode

Symptom Explanation	Conditions That Could Cause This Symptom
Standby LED ON. Machine will not power ON.	<ul style="list-style-type: none"> • ACPW or DCPW • Any CBSA cassette or control panel • SPD1 or basic board • SPS cassette

FUNCTIONAL NOTE

Power may be present when nothing is displayed on the control panel

In 'Local' mode, you can only power ON the 3746-950 manually using the 'start' key on the 3746-950 control panel.

001

– Press the 'start' key on the 3746-950 control panel.

Is the READY LED blinking on the 3746-950 control panel?

Yes No

002

Is the 3746-950 control panel display blank or is there an undefined message displayed (jumbled characters)?

Yes No

003

Go to Step 005

004

Go to "MAP 2620: 3746-950 Control Panel Problem" on page 2-36.

005

Is system reference code 0528 2806 displayed on the 3746-950 control panel?

Yes No

006

Note the 3746-950 control panel code. Go to "3746-950 Control Panel Codes" on page 1-15 and perform the action required.

007

Go to "MAP 2560: 3746-950 Ready LED Blinking." on page 2-17.

MAP 2530: 3746-950 CP1 Tripped.

Symptom Explanation	Conditions That Could Cause This Symptom
CP1 tripped -48v missing	<ul style="list-style-type: none"> • Overload on -48v • CP

The entire machine must be available to perform this procedure.

001

CP1 trips with overcurrent of the 'STANDBY' or 'HOLD UP' voltage distribution or a fan error condition.

Locate in Figure 2-5 on page 2-13 the tripping CP1 and its corresponding circuit.

- On the service processor, see if there is an SRC pointing to a fan catastrophic error condition. To do so:

You should be logged ON on the service processor console. If not, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

- Return to the "MOSS-E View" window and double click on the 3746-950 icon.
- Click on the "Problem Management" option.
- Double click on the "Display Alarms" option.
- Scan the last alarms to see if you have one of the following SRCs indicating a FAN error.
 - 05B2 098A
 - 05B2 098B
 - 05B2 098C
 - 05B2 0984
 - 05B2 0985
 - 05B2 0986
 - 05B2 0987
 - 05B2 0988
 - 05B2 0989

SRC pointing to fan error?

Yes No

002

- Unplug the DCDP connector J5. See Figure 2-5 on page 2-13.
- Reset CP1.

Is CP1 tripping again?

Yes No

003

Check the fan circuits. (fans 1 and 3). Refer to YZ page 118.

004

- Reconnect J5, (Step 004 continues)

004 (continued)

- Remove connector J11 from the DCDP.
- Reset CP1.

Is CP1 tripping again ?

Yes No

005

Exchange the DCDP. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

006

- Reconnect J11.
- Unplug the DCDP connector J4.
- Reset CP1.

Is CP1 tripping again?

Yes No

007

An overload exists on the -48v HOLDUP.

- Unplug from the basic board the following cassettes:
 - SPS 07G-A1-D, CBSP 07G-A1-F.
- Reconnect J4.

Is CP1 tripping ?

Yes No

008

Reinstall the cards one at a time to isolate the failing one and exchange it.

009

The problem is either on the board, SPD1 card, or cable between DCDP and SPD1. Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

010

- Remove connector J12 from the DCDP.
- Reset CP1.

Is CP1 tripping again?

Yes No

011

Exchange the DCDP. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

012

Exchange the AC box. Go to “3746-950 Maintenance Using a FRU list” on page 1-28.

013



CP1 trips two minutes after a two or more fan error condition occurs.

- Refer to the following fan SRCs to identify the failing fans and exchange them.

SCR	Interpretation
05B2 098A	Two or more fans faulty in drawer 1, 3
05B2 098B	Two or more fans faulty in drawer 2, 3
05B2 098C	Three or more fans faulty in drawer 1, 2, 3
05B2 0984	Four fans are reported as faulty or CP2
05B2 0985	All fans are reported as faulty
05B2 0986	Two fans are faulty in drawer 1
05B2 0987	Two fans are faulty in drawer 2
05B2 0988	Two fans are faulty in drawer 3
05B2 0989	Two or more fans faulty in drawer 1, 2

- Reset CP1 and power ON the 3746-950. (Also reset CP1 on ACPW or DCPW backup if present)
-

3746-950 -48v DC DISTRIBUTION



SPDs Test Points

Pin	Signal Name
9	Power Ground
7	Logic Ground
6	General Reset
5	-48v Hold Up
4	-48v A
3	-48v B
2	SPA Dump
1	SPA Reset

SPD1 Test Points
Connector J10

Pin	Signal Name
9	Power Ground
7	
6	
5	
4	-48v A
3	-48v B
2	
1	

SPD2 Test Points
Connector J4

Figure 2-5. -48 Volts DC Distribution

MAP 2540: 3746-950 CP2 or CP3 Tripped

Symptom Explanation	Conditions That Could Cause This Symptom
CP2 or CP3 tripped -48v missing	<ul style="list-style-type: none"> • Overload on -48v • CS/DCDC • FANS • SPD1 or basic board • Any processor or coupler

001

An overload is mainly due to a board or cabling malfunction. All the processor cassettes or CS DC/DCs are protected by an individual fuse. The fuse is located inside of each of those elements and prevents a general -48v overload. These fuses are non-replaceable.
Locate the tripping CP and its corresponding circuit in Figure 2-5 on page 2-13.

Is CP2 tripped?**Yes No****002**

CP3 tripped
Go to Step 007.

003

Unplug the DCDP connector J5 and reset CP2.

Is CP2 tripping again ?**Yes No****004**

The overload is on the CS or fans.
Using Figure 2-6 on page 2-15 locate the CP2-protected circuit.
Disconnect the J1 connector on the CS/DCDC and reset CP2.

Is CP2 tripping again?**Yes No****005**

Exchange the CS/DCDC. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

006

Locate the failing fans by disconnecting the J2 connector alternatively on them one at time.

007

The overload is on the basic board or in its SPD1 cassette.

Pull the corresponding SPD1 cassette out and reset the CP.

(Step **007** continues)

007 (continued)**Is the CP tripping again ?****Yes No****008**

The problem is on the board distribution.
Reseat the SPD1 cassette
Unplug all the processors and couplers connected on the board and reset the CP.

Is the CP tripping again ?**Yes No****009**

Reinstall all the processors and couplers one at a time until the failing part is isolated.

010

The board is failing. Exchange it. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

011

The problem is in the cable between the DCDP connector J4 and the SPD1 cassette connector J11 or SPD1 cassette. Check with a meter on the test points. The CP may also be failing.




Figure 2-6. CP2 Circuit

MAP 2550: 3746-950 CP4, CP5, CP6, or CP7 Tripped

Symptom Explanation	Conditions That Could Cause This Symptom
CP4, CP5, CP6, or CP7 tripped -48v missing	<ul style="list-style-type: none"> • Overload on -48v • SPD2 or expansion board • Any processor or coupler

An overload is mainly due to a board or cabling malfunction. All the processor cassettes or CS DC/DCs are protected by an individual fuse. The fuse is located inside of each of those elements and prevents a general -48v overload. These fuses are non-replaceable.

Locate the tripping CP and its corresponding circuit in Figure 2-5 on page 2-13.

Notes:

1. CP4 and CP5 are used for expansion enclosure 1.
2. CP6 and CP7 are used for expansion enclosure 2.

001**Is CP4 and/or CP5 tripped?****Yes No****002**

Go to Step 006.

003**CP4 and/or CP5 are tripped**

Unplug the DCDP connector J3 and reset CP4 and/or CP5.

Is CP4 and/or CP5 tripping again ?**Yes No****004**

Go to Step 009.

005

Go to Step 008

006**CP6 and/or CP7 are tripped**

Unplug the DCDP connector J2 and reset CP6 and/or CP7.

Is CP6 and/or CP7 tripping again ?**Yes No****007**

Go to Step 009.

008

Exchange the DCDP box. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

009

The overload is on the expansion board or in its SPD2 cassette.

Pull the corresponding SPD2 cassette out and reset the CP(s).

Is/are the CP(s) tripping again ?**Yes No****010**

The problem is on the board distribution.

Reseat the SPD2 cassette

Unplug all the processors and couplers connected on the board and reset the CP(s).

Is/are the CP(s) tripping again ?**Yes No****011**

Reinstall all the processors and couplers one at a time until the failing part is isolated.

012

The expansion board is failing. Exchange it. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.


013

- If CP4 and/or CP5 are tripped, the problem is in the cable between the DCDP connector J3 and the SPD2 cassette connector J5 or SPD2 cassette. Check with a meter on the test points.
- If CP6 and/or CP7 are tripped, the problem is in the cable between the DCDP connector J2 and the SPD2 cassette connector J5 or SPD2 cassette. Check with a meter on the test points.

MAP 2560: 3746-950 Ready LED Blinking.

Symptom Explanation	Conditions That Could Cause This Symptom
Ready LED blinking. Machine will not power ON.	<ul style="list-style-type: none"> • ACPW or DCPW • SPD1 or Basic board • SPS

Do not go directly through this MAP. You must first go through the "MAP 2500: 3746-950 Power Control Subsystem Problems" on page 2-4 or "MAP 2520: 3746-950 Power ON Problem in Local Mode" on page 2-10.



Are the power cables correctly plugged into the J11 and J12 connectors at the rear of DCDP?

Yes No

011

Plug the cables correctly and restart the operation.

012

First exchange the DCDP. If the problem persists exchange the ACPW (basic). Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

013

– Check on the test 1 connector pin 28 if the PWRONCMD2 line is at + 5v. Refer to YZ page 234 for test 1 pin assignment.

Is + 5v present on pin 28?

Yes No

014

Go to Step 018.

015

Are the power cables correctly plugged into the J09 and J10 connectors at the rear of DCDP?

Yes No

016

Plug the cables correctly and restart the operation.

017

First exchange the DCDP. If the problem persists exchange the backup power (ACPW or DCPW). Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

018

– Check that the cable is correctly plugged into the J8 connector on SPD1 and into the J7 connector on the DCDP.
(Step 018 continues)

018 (continued)

Is plugging correct?

Yes No

019

Plug the cable correctly and restart the operation.

020

First exchange the DCDP. If the problem persists exchange the backup power (ACPW or DCPW). Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

3746-950/Service Processor/Network Node Processor MAPs

MAP 2600: 3746-950/Service Processor/Network Node Processor/Multiaccess Enclosure Link Icons Color Symptom

Symptom Explanation	Conditions That Could Cause This Symptom
<p>3746-950, Network Node Processor (NNP), or Multiaccess Enclosure problem</p> <p>The 3745 icon, the 3746-950 icon, the NNP icon, and/or the MAE-Link icon on the "MOSS-E View" window are/is not green.</p>	<ul style="list-style-type: none"> • 3746-950 one or more processors, or ESCC have failed • No link between 3746-950 with the service processor • No link between NNP and the service processor • No link between NNP and the 3746-950 • NNP has failed • No link between the service processor and multiaccess enclosure • PCMCIA card, cable, multiaccess enclosure

001

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- The color of the 3746-950, network node processor, and service processor icons reflects their status. For example a green icon indicates that the machine is operational. The following table shows what step describes the status represented by the other icon colors.

Table 2-1 (Page 1 of 2). Icons Color Selection Table

Machine	Icon Color	Go to
Service Processor	White	Step 002 on page 2-20.
3746	Yellow	Step 003 on page 2-20.
	White	Step 004 on page 2-20.
	Grey	Step 005 on page 2-20.
	Pink	Step 006 on page 2-20.
	Red	Step 030 on page 2-23.
NNP-X	White	The control point is being started and the configuration is being activated. This is a normal state, however if this state stay a too long time suspect a problem. Check if you have alarms at the service processor
	Grey	<p>There is:</p> <ul style="list-style-type: none"> • No connection between the service processor and the network node processor. • Or link not ready between the 3746-9xx and the control point of the network node processor. <p>Go to Step 031 on page 2-23.</p>
	Pink	The control point is waiting for operator start, or no NDF (Node Definition File). Go to Step 044 on page 2-25.
	Blue	The connection between the service processor and the network node processor is OK. The network node processor is in standby mode state. The control point must be started. Go to Step 047 on page 2-25.

Table 2-1 (Page 2 of 2). Icons Color Selection Table

Machine	Icon Color	Go to
MAE-Link	White	A selective IML is being started on the multiaccess enclosure. This is a normal state, however if this state stay a too long time suspect a problem. Check if you have alarms at the service processor
	Grey	There is no connection between the service processor and the multiaccess enclosure. Go to Step 022 on page 2-22.
	Red	The multiaccess enclosure is in concurrent maintenance. To put back the multiaccess enclosure in normal mode start a "Selective IML on MAE". Refer to "3746-950/Service Processor Windows Overview" on page 1-7.

002

The service processor icon is white.

- Check if the yellow LED of the service processor indicating disk access is active.
- If the yellow LED is sometimes ON and sometimes OFF wait a few more minutes. If the symptom persists, call your support for assistance.
- If the yellow LED is always OFF, call your support for assistance.

003

The 3746-950 icon yellow is a normal state. Its duration depends on the 3746-950 configuration.

- On the 3746-950 control panel, check if there is a character displayed on the "Service processor not accessible" digit.
- If a character is displayed, go to "MAP 2950: LAN Problem on LAN Attached to the Service Processor" on page 2-133. Otherwise check if the yellow LED of the service processor indicating disk access is active.
- If the yellow LED is sometimes ON or sometimes OFF wait a few more minutes. If the symptom persists, call your support for assistance.
- If the yellow LED is always OFF call your support for assistance.

004

The 3746-950 icon white is a normal state. Its duration depends on the 3746-950 configuration.

- Check either the 3746-950 control panel code displayed or
- The 3746-950 status on the service processor:
 - On the "MOSS-E View" window double click on the 3746-950 icon.
 - Click on "Program" (in the action bar)
 - Click on "Status" option.
 - The "3746-950 Status" window indicates the IML steps, the address of any processor, CBC or unavailable ESCC, and the control panel code.
- Note the control panel code displayed. Go to "3746-950 Control Panel Codes" on page 1-15 and follow the procedure.

005

The 3746-950 icon is grey.

- The 3746-950 is not connected to the service processor.
- Go to "MAP 2950: LAN Problem on LAN Attached to the Service Processor" on page 2-133.

006

(Step **006** continues)

006 (continued)

The 3746-950 icon is pink.

- On the "MOSS-E View" window double click on the 3746-950 pink icon.
- Click on "Program" in the action bar.
- Click on "Status" option.
- The "3746-950 Status" window indicates the IML steps and the address of any processor or CBC, or unavailable ESCC.
- The normal status is: IML complete with CDF-E updated and no processor unavailable.
- Check that CP3, CP4, and CP5 are ON.

Are CP3, CP4, and CP5 ON?

Yes No

007

Go to "MAP 2605: 3746-950 Either CP3, CP4, CP5, CP6, or CP7 is Tripped" on page 2-26

008

If you have several resource unavaible perform the following procedure for each resource one by one.

- Unplug and then plug in again the suspected resource.
- Wait a few minutes for the "unplug/plug alarm" to be displayed on the service processor screen.

Is there an unplug alarm displayed?

Yes No

009

Is there a plug alarm displayed?

Yes No

010

Exchange the suspected resource. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

011

- Click on "OK".
 - Go to Step 014.
-

012

Click on "OK". Then wait for the "plug alarm" to be displayed.

Is there a plug alarm displayed?

Yes No

013

Exchange the suspected resource. Go to "3746-950 FRU List" on page 1-29.

014

After plugging the ressource must be IMLed.

- Return to the "3746-9x0 menu" window.
- Click on the "Problem Management" option.
- Double click on the "Change Resource Status" option.
- The "Resource Status Change - Resource Selector" window is displayed, select the resource that you have plugged/unplugged and click on "OK".
- On the next "Resource Selector", select the resource that you have plugged/unplugged and click on "OK".
- The "Resource Status Change - Selection" window is displayed, select the "IML without Diagnostic" option and click on "OK".

(Step **014** continues)

014 (continued)

- On "Confirmation" window, click on "OK".
- A "Warning" window informs you that your request is being performed and to wait for its completion.
- At completion a "Warning" window is displayed, click on "OK".

Is the IML completed successfully?

Yes No

015

Exchange the suspected FRU. Go to "3746-950 FRU List" on page 1-29.

016

Remove the resource from the concurrent mode.

- Return to the "3746-9x0 menu" window.
 - Click on the "Configuration Management" option.
 - Double click on the "Add/Retrieve Resource in Concurrent Mode" option.
 - On the "Confirmation" window, click on "OK".
 - On the "Resource Selector" select the resource and click on "OK".
 - The "Add/Retrieve Resource Options" window is displayed.
 - Select the "Remove the Resource from the concurrent mode" and click on "OK".
 - At completion a "Warning" window is displayed, click on "OK".
 - On the "Confirmation" window, click on "Cancel" and go to Step 017.
-

017

Did you unplug and plug all the suspected resources?

Yes No

018

Go to Step 008 on page 2-21.

019

Is the 3746-950 icon always pink?

Yes No

020

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

021

- On the "MOSS-E View" window double click on the 3746-950 pink icon.
 - Click on "Program" in the action bar.
 - Click on "Status" option.
 - The "3746-950 Status" window indicates the IML steps and the address of any processor, CBC, or unavailable ESCC.
 - List the resource unavailable and go to "3746-950 FRU List" on page 1-29 for exchange.
-

022

The MAE-Link icon is grey when there is no link between the service processor and the multiaccess enclosure.

Is the multiaccess enclosure powered ON?

Yes No

023

Refer to the 'Multiaccess Enclosure Basic Verification' in the *Multiaccess Enclosure Installation and Maintenance*, manual manual to check the multiaccess enclosure.

024**Is the PCMCIA LED ON?****Yes No****025**

Continue with Step Step 027

026

Refer to the 'Multiaccess Enclosure Basic Verification' in the *Multiaccess Enclosure Installation and Maintenance*, manual manual to check the multiaccess enclosure.

027

Check that:

- The PCMCIA card cable is correctly plugged into the PCMCIA card.
- The PCMCIA card cable is correctly plugged into the SPAU (8228).
- The Token-Ring cable coming from the service processor is correctly connected into the SPAU (8228) and to the rear of the service processor.

Did you find the problem?**Yes No****028**

If the other units connected to the service processor have their icon green on the service processor display suspect an multiaccess enclosure problem. Refer to the 'Multiaccess Enclosure Basic Verification' in the *Multiaccess Enclosure Installation and Maintenance*, manual manual to check the multiaccess enclosure.

029

Go to "CE Leaving Procedure" on page 4-53.

030

The 3746-950 icon is red when it is set in Offline mode.

- To set the 3746-950 in Online mode follow these steps.
 - Double click on the 3746-950 icon.
 - On the "3746-9x0 Menu" window, click on the "Problem management" option.
 - Click on the "Set 3746-950 Online/Offline option".
 - On the "Set 3746-950 Online/Offline" window, click on "Yes".
 - On the next "Set 3746-950 Online/Offline" window click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-950 Online/Offline" window, click on "OK".
 - Start a general IML in order to set the 3746-950 in Online mode.
 - At completion of the IML, the 3746-950 icon must be green.
 - Return to the "MOSS-E View" window.
 - Go to "CE Leaving Procedure" on page 4-53 to return the machine to the customer. If the problem persists contact your support.
-

031

There is no connection between the service processor and the network node processor or the link between the 3746-9xx and the control point of the network node processor is not ready.

(Step 031 continues)

031 (continued)

Is the network node processor powered ON?

Yes No

032

– Power ON the network node processor.

Is the network node processor powered ON?

Yes No

033

Go to the appropriate *Network Node Processor Installation and Maintenance* manual.

034

Problem solved.

035

- Return on the "MOSS-E View" window, double click on the 3746-950 icon.
- The "3746-9x0 menu" is displayed.
- Click on the "Network Node Processor (NNP) Management" option.
- Double click on the "Manage Controls Points on NNP" option.
- The "Manage Control Points (CP) on NNP" window is displayed.
- On this window look the status of the CP/NNP. This status is displayed in the **CP/NNP-X Status Area**.

Is in CP/NNP-x Status Area "Down" displayed?

Yes No

036

Is in CP/NNP-x Status Area "Link not ready" displayed?

Yes No

037

Check the NNP-X icon color and restart the problem determination. Go to Step 001 on page 2-19.

038

– On the 3746-950 control panel check the status of the "Service Processor Not Accessible" digit.

Is the "Service Processor Not Accessible" digit present?

Yes No

039

Go to "MAP 2960: 3746-950/APPN Link Problem" on page 2-138.

040

Suspect a 3746-950 LAN problem. Go to "MAP 2750: 3746-950 Permanent Service Processor Link Problem" on page 2-84.

041

- Check the network node processor and service processor LAN cable are well connected at the rear of the network node processor and service processor and on the service processor access unit.

Is your problem solved?

Yes No

042

(Step 042 continues)

042 (continued)

Go to the appropriate *Network Node Processor Installation and Maintenance* manual.

043

Go to "CE Leaving Procedure" on page 4-53.

044

- On the "MOSS-E View" window, double click on the 3746-950 icon.
- The "3746-9x0 menu" is displayed.
- Click on the "Network Node Processor (NNP) Management" option.
- Double click on the "Manage Controls Points on NNP" option.
- The "Manage Control Points (CP) on NNP" window is displayed.
- On this window in "Options" select the CP/NNP that you want to manage: CP/NNP-A or CP/NNP-B, then click on "Activate Configuration".

Is the problem solved?

Yes No

045

Call for suport.

046

Go to "CE Leaving Procedure" on page 4-53.

047

- On the "MOSS-E View" window, double click on the 3746-950 icon.
- The "3746-9x0 menu" is displayed.
- Click on the "Network Node Processor (NNP) Management" option.
- Double click on the "Manage Controls Points on NNP" option.
- The "Manage Control Points (CP) on NNP" window is displayed.
- On this window in "Options" select the CP/NNP that you want to manage: CP/NNP-A or CP/NNP-B, then click on "Start CP".

Is the problem solved?

Yes No

048

Call for suport.

049

Go to "CE Leaving Procedure" on page 4-53.

MAP 2605: 3746-950 Either CP3, CP4, CP5, CP6, or CP7 is Tripped

Symptom Explanation	Conditions That Could Cause This Symptom
3746-950 problem The 3746-950 icon on the "MOSS-E View" window is not green.	<ul style="list-style-type: none"> • Overload on -48v • CS/DCDC • FANS • SPD1 • Basic or Expansion board • Any processor or coupler

001

Reset the CP(s).

Is/are the CP(s) trip again?**Yes No****002****Are you here via a CPN?****Yes No****003**

Go to Step 011 on page 2-27.

004

- On the "Resource Selector" window, select the suspected processor and click on "OK".
- The "Maintenance Options" window is displayed.
- Select the "Initialize the resource" option and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.

Is the initialization successfully?**Yes No****005**

Exchange the suspected FRU. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

006

- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- On the "Resource Selection" window, click on "Cancel".
- Return to the "Resource Selection Options for Maintenance" window.
- Go to Step 008.

007

Go to "MAP 2540: 3746-950 CP2 or CP3 Tripped" on page 2-14 or "MAP 2550: 3746-950 CP4, CP5, CP6, or CP7 Tripped" on page 2-16.

008(Step **008** continues)

008 (continued)

Do you have an other CPN?

Yes No

009

Go to Step 016.

010

- On the "Resource Selection Options for Maintenance" window, select the "By Specific Customer Problem Number (CPN)" and click on "OK".
 - On the "Specific Customer Problem Number" window, enter the new CPN and click on "OK".
 - The "Resource Selector" window is displayed with the FRUs suspected their location and their fault probability.
 - go to Step 004 on page 2-26.
-

011

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the suspected resource and click on "OK".
- The "Maintenance Options" window is displayed.
- Select the "Initialize the resource" option and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.

Is the initialization successfully?

Yes No

012

Exchange the suspected FRU. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

013

- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- On the "Resource Selection" window, click on "Cancel".
- Return to the "Resource Selection Options for Maintenance" window.

Is there another DCDC of processor suspected in your FRU list.

Yes No

014

Go to Step 016

015

Go to Step 011

016

- Return to the "MOSS-E View" window.

(Step **016** continues)

3746-950 MAPs

016 (continued)

Is the 3746-950 icon green?

Yes No

017

Restart problem determination. Go to “MAP 2600: 3746-950/Service Processor/Network Node Processor/Multiaccess Enclosure Link Icons Color Symptom” on page 2-19.

018

Go to “MAP: 3746-950 Ending Procedure in Concurrent Mode” on page 1-128.

MAP 2610: 3746-950 ESCA, LAN, or CLP Problem

Symptom Explanation	Conditions That Could Cause This Symptom
LAN or ESCA activation problem Line activation problem on all the lines of one or more CLP Traffic down on one or more ESCAs, LANs (Token-Ring or Ethernet) or all the lines of CLP	<ul style="list-style-type: none"> One or more processors are unplugged or failing ESCP or ESCC TRP or TIC3 Fiber Optic Host System LAN Ring (Token-Ring, Ethernet, 8229) CLP or TIC3

001

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, click on the 3746-950 on which you want to work.
- The "3746-9x0 Menu" window is displayed.
- Click on the "Configuration Management" option.
- Double click on the "Compare Reference CDF-E with Active CDF-E".
- If there is no discrepancy a "Compare CDF-E" window is displayed and warns you. Click on OK, and go to Step 004 on page 2-30.
- If there is discrepancies a "Compare reference CDF-E with Active CDF-E" window is displayed.

Compare Reference CDF-E with Active CDF-E

The following discrepancies have been found.
Select an item to display more information.

Reference CDF-E	Active CDF-E
CLP-2240.LIC11-2304.LCB-2304.ARC3B-2307	

- Two cases have to be considered:
 - Only in the reference CDF-E column, one or more processors/coupler/arcs are displayed. That means that the resource listed are not present in the active CDF-E.
 - Processor(s) are present both under reference CDF-E and active CDF-E. That means that the resource are present but not in a correct status (not IMLed) or with an EC discrepancy.

Is there a mismatch?


Yes No

002

Go to Step 004 on page 2-30.

003

Go to "MAP 2615: 3746-950 Configuration Mismatch" on page 2-31.



MAP 2615: 3746-950 Configuration Mismatch

Symptom Explanation	Conditions That Could Cause This Symptom
There is a discrepancy between the current and the reference CDF-E	<ul style="list-style-type: none"> One or more processors are unplugged, or failing One or more couplers are unplugged, or failing One or more ARCs are unplugged or failing SPD1, SPD2, or cables CP3, CP4, or CP5 OFF

001

Do you come from "MAP 2610: 3746-950 ESCA, LAN, or CLP Problem" on page 2-29?

Yes No

002

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, click on the 3746-950 on which you want to work.
- The "3746-9x0 Menu" window is displayed.
- Click on the "Configuration Management" option.
- Double click on the "Compare Reference CDF-E with Active CDF-E".
- If there is no discrepancy a "Compare Reference CDF-E with Active CDF-E" window is displayed and warns you. Click on OK, and restart problem determination.
- If there is discrepancies a "Compare reference CDF-E with Active CDF-E" window is displayed.

Compare Reference CDF-E with Active CDF-E

The following discrepancies have been found.
Select an item to display more information.

Reference CDF-E	Active CDF-E
CLP-2240.LIC11-2304.LCB-2304.ARC3B-2307	

- Two cases have to be considered:
 - Only in the reference CDF-E column, one or more processors/coupler/arcs are displayed. That means that the resource listed are not present in the active CDF-E.
 - Processor(s) are present both under reference CDF-E and active CDF-E. That means that the resource are present but not in a correct status (not IMLed) or with an EC discrepancy.
- Go to Step 003.

003

(Step 003 continues)

003 (continued)

Is the mismatch concern several processor?

Yes No

004

Go to Step 006.

005

Go to Step 026 on page 2-34.

006

- Click on "OK".
- Either you get a message saying you cannot have any more information and go to Step 007, or you get a window giving you the hardware cause of the problem.

Example

3746-950 xxxxxxxxxx Discrepancies		
Hardware type:	Reference CDF-E	Active CDF-E
EC Level	ARC3B	
	X'00'	
<div> <input type="button" value="OK"/> <input type="button" value="Cancel"/> </div>		

- Click on "OK" and continue the procedure go to Step 007.

007

For the suspected resource perform the following procedure. (If the mismatch concerns **several** resources. Select **one** of them and perform the following procedure).

- Unplug and then plug in again the suspected resource.
- Wait a few minutes for the "unplug/plug alarm" to be displayed on the service processor screen.

Is there an unplug alarm displayed?

Yes No

008

Is there a plug alarm displayed?

Yes No

009

Go to Step 023 on page 2-34.

010

- Click on "OK".
- Go to Step 013 on page 2-33.

011

Click on "OK". Then wait for the "plug alarm" to be displayed.

Is there a plug alarm displayed?

Yes No

012

Exchange the suspected resource. Go to "3746-950 FRU List" on page 1-29.

013

Did you unplug/plug a processor?

Yes No

014

Go to Step 018.

015

After plugging the resource must be IMLed.

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on the "Change Resource Status" option.
- The "Resource Status Change - Resource Selector" window is displayed, select the resource that you have plugged/unplugged and click on "OK".
- On the next "Resource Selector", select the resource that you have plugged/unplugged and click on "OK".
- The "Resource Status Change - Selection" window is displayed, select the "IML without Diagnostic" option and click on "OK".
- On "Confirmation" window, click on "OK".
- A "Warning" window informs you that your request is being performed and to wait for its completion.
- At completion a "Warning" window is displayed, click on "OK".

Is the IML completed successfully?

Yes No

016

Exchange the suspected FRU. Go to "3746-950 FRU List" on page 1-29.

017

Remove the resource from the concurrent mode.

- Return to the "3746-9x0 Menu" window.
- Click on the "Configuration Management" option.
- Double click on the "Add/Retrieve Resource in Concurrent Mode" option.
- On the "Confirmation" window, click on "OK".
- On the "Resource Selector" select the resource and click on "OK".
- The "Add/Retrieve Resource Options" window is displayed.
- Select the "Remove the Resource from the concurrent mode" and click on "OK".
- At completion a "Warning" window is displayed, click on "OK".
- On the "Confirmation" window, click on "Cancel" and go to Step 018.

018

Did you unplug and plug all the suspected resources?

Yes No

019

Go to Step 007 on page 2-32.

020

- Return to the "3746-9x0 Menu" window.
- Click on the "Configuration Management" option.
- Double click on the "Compare Reference CDF-E with Active CDF-E".
- A "Compare reference CDF-E with Active CDF-E" window is displayed. Click on "OK".
- The discrepancies are displayed on a "Compare reference CDF-E with Active CDF-E" window.

Is the mismatch always present?

Yes No

021

Problem solved. Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

022

Exchange the suspected resource(s). Go to "3746-950 FRU List" on page 1-29.

023

Is the suspected resource a processor?

Yes No

024

Exchange the suspected FRU. Go to "3746-950 FRU List" on page 1-29.

025

- If the suspected processor is alone in the expansion enclosure:
 - Check the SPD2 connection on the expansion board.
 - Check all cables connected on the SPD2.
 - Check that CP4 and CP5 are ON.
 - Exchange the suspected processor. Go to "3746-950 FRU List" on page 1-29.
-

026

- Click on "Cancel". The "3746-9x0 Menu" is displayed.
- Make sure that the 'power control' display is set to local (3) on the control panel. If not, do the following:
 - Press the 'Power Control' key until (3) is displayed in the power control window.
 - Press the 'Validate' key.
- Ask the customer to stop all the traffic on the 3746-950 (if this has not been already done).
- When the traffic is stopped, press the 'standby' key on the control panel.
- The 3746-950 is now powered-OFF:
 - Unplug and then plug in again all the suspected processors.
 - Check the SPD1 connection on the basic board.
 - Check all the cables connected on the SPD1.
 - Check the SPD2 connection on the expansion board.
 - Check all cables connected on the SPD2.
 - Check that CP3, CP4, CP5 are ON.
- Set the 3746-950 to Offline mode.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
 - Double click on the "Set 3746-9x0 Online/Offline Option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting to put the 3746-950 in Offline mode.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK"
- From the 3746-950 control panel, press the 'Start' key to start an IML.
- The end of the IML is indicated when 00000000 is displayed on the control panel and the ready LED is ON.

Is the ready led ON?

Yes No

027

Go to "MAP 2500: 3746-950 Power Control Subsystem Problems" on page 2-4

028

- Click on "Program" in the action bar.
- Click on "Status" option.
- The "3746-9x0 Status" window indicates the IML steps and the address of any Processor or ESCC unavailable.

Is there any resource unavailable?

Yes No

029

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

030

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 to exchange the resource.

MAP 2620: 3746-950 Control Panel Problem

Symptom Explanation	Conditions That Could Cause This Symptom
Undefined or no panel message No action possible from the control panel.	<ul style="list-style-type: none"> Loose cables Control panel cards SPS CBSP

001

– Refer to the MOSS-E screen to see if a system reference code is displayed.

Is system reference code xxxxxxxx displayed?

Yes No

002

Go to Step 004.

003

Using the service processor "Problem Management" menu, look up the SCR meaning and the corresponding action required.

004

Is the 3746-950 control panel display blank?

Yes No

005

Is there an undefined message displayed (jumbled characters)?

Yes No

006

Go to Step 011.

007

Go to Step 010

008

– Check that the cable is correctly plugged into the the control panel card display 07A-A1 and into the SPD1 connector J7. Refer to page YZ 232.

Is the cable correctly plugged?

Yes No

009

Plug the cable correctly and restart the operation.

010

– First exchange the display card from the control panel. If the problem persists, exchange the SPS and then the CBSP. Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

011

– If the nature of the fault does not allow control panel actions, first exchange the lamp card from the control panel. If the problem persists, exchange the SPS. Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

MAP 2625: LAN Checking

You are here because you suspect the LAN cable (WLOB) or the service processor access unit (ACUN).

001

Perform the following steps:

- Check that the service processor LAN cable is correctly connected to the rear of the service processor and in the service processor access unit.
- Check that all the LAN cables are correctly connected to the service processor access unit.

Did you find the problem?

Yes No

002

Exchange the suspected FRU.

003

Problem solved go to “CE Leaving Procedure” on page 4-53.

MAP 2630: 3746-950 Service Logic Problem

The FRU CAB4 is an undetermined problem on the 3746-950 service logic. This MAP will lead you to run specific diagnostic on the suspected service logic.

Ask the customer to stop all traffic on the 3746-950 (if this has not already done). If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here. These diagnostics must be run in Offline Mode.

001

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- Set the 3746-950 in Offline mode if it is not already.
 - Double click on the 3746-950 icon.
 - The "3746-9x0 Menu" is displayed.
 - Click on the "Problem Management" option.
 - Double click on the "Set 3746-9x0 Online/Offline Option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK".
 - Start a general IML.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Operation Management" option.
 - Double click on the "Perform General IML" option.
 - When the 3746-950 has terminated its IML with the ready LED ON, go to Step 002.

002

- Return to the "3746-9x0 Menu."
- Click on the "Problem Management" option.
- Double click on the "Perform Specific Diagnostics" option.
- On the "Diagnostic Control Monitor" window select the "Run diagnostics for the Service Bus" option and click on "OK".
- The "Service Bus Group Selection" window is displayed.
- Select the "PRC SL" option and click on "OK".
- On the "Resource option Selection" window, select the "All Resources" option and click on "OK".
- On the "Test and Running Options selection" window, select the "SAS BUS MAT" option and click on "OK".
- A "Diagnostic Active Status" window is displayed briefly. Then the first "Information required" window is displayed prompting you to perform tasks on the 3746-950. Perform all the steps following the prompts. Refer to Figure 2-7 on page 2-40, Figure 2-8 on page 2-41, or Figure 2-9 on page 2-42 to locate the different components.

Is the diagnostic error free?

Yes No

003

Have you changed all the suspected FRU?

Yes No

004

- Go to "Display the FRU List After a Diagnostic Failure" on page 1-143.
- Once you have the FRU list, go to Chapter 4, "3746-950 FRU Exchange" on page 4-1. to exchange the faulty FRU.
- After FRU exchange go to Step 002.

005

(Step **005** continues)

005 (continued)

Call your support for assistance.

006

Did you exchange a FRU?

Yes **No**

007

- If you have:
 - A FRU list, exchange **all** FRUs. Go to Chapter 4, “3746-950 FRU Exchange” on page 4-1 for the exchange. Then go to Step 002 on page 2-38.
 - No FRU list or no suspected FRU, call your support for assistance.

008

Go to “MAP: 3746-950 Ending Procedure In Offline Mode” on page 1-126.

3746-950 Service Logic Cabling




Figure 2-7. Stand Alone Service Bus (SASB) Routing with Basic Board Only




Figure 2-8. Stand Alone Service Bus (SASB) Routing with Expansion Board




Figure 2-9. Stand Alone Service Bus (SASB) Routing Two Expansion Boards

MAP 2635: 3746-950 Several Fans Are in Errors

Symptom Explanation	Conditions That Could Cause This Symptom
3746-950 problem Several Fans are in error	<ul style="list-style-type: none"> • Missing -48v • Cable between DCDP/Fans • Cable between SPD1/Fans • DCDP • SPD1 • CP2

The entire machine must be available to perform this procedure.

001

- Check the CP2.

Is the CP2 tripped?

Yes No

002

Go to Step 004.

003

Suspect an overload condition, go to "MAP 2540: 3746-950 CP2 or CP3 Tripped" on page 2-14.

004

- Check that the cable between DCDP (07H-A1-J5), the Fans (07F-A1/B1/C1) and the CS (07B-B2-J1) is correctly plugged in each of these connectors.

Is plugging correct?

Yes No

005

Plug the cable correctly and restart the operation.

006

- Check that the cable between the Fans (07F-A1/B1/C1) and the SPD1 (07N-A1-A-J1) is correctly plugged in each of these connectors.

Is plugging correct?

Yes No

007

Plug the cable correctly and restart the operation.

008

- Check that the cable between DCDP, the Fans, and the DCDC of CS.
 - Unplug the cable between the DCDP (07H-A1-J5), from the Fans (07F-A1-J1/B1-J1/C1-J1) and from the DCDC of CS (07B-B2-J01).
 - On each connector of the cable check that the pins are present and not damaged.
 - Using the YZ page 118 check the cable continuity between each pin connector.

(Step **008** continues)

008 (continued)

Is the cable correct?

Yes No

009

Repair the cable (if possible) or order a new one.

010

- Check that the cable between the Fans and the SPD1.
 - Unplug the cable between from the Fans (07F-A1-J2/B1-J2/C1-J2) and from the SPD1 (07N-A1-A-J1).
 - On each connector of the cable check that the pins are present and not damaged.
 - Using the YZ page 236 check the cable continuity between each pin connector.

Is the cable correct?

Yes No

011

Repair the cable (if possible) or order a new one.

012

Is there an other FRU in your FRU list to test?

Yes No

013

Call your support for assistance.

014

Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

MAP 2640: 3746-950 Cable From SPD1 to SPD2

Symptom Explanation	Conditions That Could Cause This Symptom
3746-950 problem All adapters of expansion enclosure have a problem	<ul style="list-style-type: none"> • Cable between SPD1/SPD2 • SPD1 • SPD2 • SPS

The entire machine must be available to perform this procedure.

001

Identify the expansion enclosure which has the problem, then go to:

- Step Step 002 for expansion enclosure 07M-A1
- Step Step 007 for expansion enclosure 07L-A1

002

- Check that the cable between SPD1 (07N-A1-A-J2), and the SPD2 (07M-A1-A-J1) is correctly plugged in each of these connectors.

Is plugging correct?

Yes No

003

Plug the cable correctly and restart the operation.

004

- Check the cable between SPD1 (07N-A1-A-J2), and the SPD2 (07M-A1-A-J1).
 - Unplug the cable from SPD1 (07N-A1-A-J2), and from the SPD2 (07M-A1-A-J1).
 - On each connector of the cable check that the pins are present and not damaged.
 - Using the YZ page 229 check the cable continuity between each pin connector.

Is the cable correct?

Yes No

005

Repair the cable (if possible) or order a new one.

006

Go to Step 011 on page 2-46

007

- Check that the cable between SPD1 (07N-A1-A-J3), and the SPD2 (07L-A1-A-J1) is correctly plugged in each of these connectors.

Is plugging correct?

Yes No

008

Plug the cable correctly and restart the operation.

009

- Check the cable between SPD1 (07N-A1-A-J3), and the SPD2 (07L-A1-A-J1).
 - Unplug the cable from SPD1 (07N-A1-A-J3), and from the SPD2 (07L-A1-A-J1).

(Step 009 continues)

009 (continued)

- On each connector of the cable check that the pins are present and not damaged.
- Using the YZ page 229 check the cable continuity between each pin connector.

Is the cable correct?

Yes No

010

Repair the cable (if possible) or order a new one.

011

Is there an other FRU in your FRU list to test?

Yes No

012

Call your support for assistance.

013

Go to “3746-950 Maintenance Using a FRU list” on page 1-28 for FRU exchange.

MAP 2645: 3746-950 Cable From DCDP to SPD1

Symptom Explanation	Conditions That Could Cause This Symptom
3746-950 problem The machine is not ready All adapters of the machine have a problem	<ul style="list-style-type: none"> • Cable between DCDP/SPD1 • SPD1 • SPD2 • SPS

The entire machine must be available to perform this procedure.

001

- Check that the cable between DCDP (07H-A1-J7), and the SPD1 (07N-A1-A-J8) is correctly plugged in each of these connectors.

Is plugging correct?

Yes No

002

Plug the cable correctly and restart the operation.

003

- Check the cable between DCDP (07H-A1-J7), and the SPD1 (07N-A1-A-J8).
 - Unplug the cable from DCDP (07H-A1-J7), and from the SPD1 (07N-A1-A-J8).
 - On each connector of the cable check that the pins are present and not damaged.
 - Using the YZ page 234 check the cable continuity between each pin connector.

Is the cable correct?

Yes No

004

Repair the cable (if possible) or order a new one.

005

Is there an other FRU in your FRU list to test?

Yes No

006

Call your support for assistance.

007

Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU exchange.

MAP 2650: 3746-950 Signal Power cable from SPD1 to the Control Panel

Symptom Explanation	Conditions That Could Cause This Symptom
3746-950 problem Control panel problem Diagnostics failed on control panel or SPS	<ul style="list-style-type: none"> • Cable between SPD1 and the control panel • SPS • CBSP • SPD1 • PNL1 • BAS

001

- Check that the cable between SPD1 (07N-A1-A-J7), and the control panel (07A-A1-J1) is correctly plugged in each of these connectors.

Is plugging correct?

Yes No

002

Plug the cable correctly and restart the operation.

003

- Check the cable between SPD1 (07N-A1-A-J7), and the control panel (07A-A1-J1).
 - Unplug the cable from SPD1 (07N-A1-A-J7), and from the control panel (07A-A1-J1).
 - On each connector of the cable check that the pins are present and not damaged.
 - Using the YZ page 232 check the cable continuity between each pin connector.

Is the cable correct?

Yes No

004

Repair it (if possible) or order a new one.

005

Is there an other FRU in your FRU list to test?

Yes No

006

Call your support for assistance.

007

Go to “3746-950 Maintenance Using a FRU list” on page 1-28 for FRU exchange.


MAP 2655: 3746-950 Cable From SIE to SAC in Multiaccess Enclosure

Symptom Explanation	Conditions That Could Cause This Symptom
3746-950 problem no link with the Multiaccess Enclosure	<ul style="list-style-type: none"> Cable between SIE/SAC SIE SAC


The entire multiaccess enclosure (MAE) must be available to perform this procedure.

001

- You should be logged ON on the service processor console. If not, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- Ask the customer to stop the traffic on "all" the Multiaccess Enclosure.
- Be sure that all the MAE resources has been deactivated using CCM (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139).
- On the Service Processor select the "3746/9x0 Menu".
- Click on the "Multiaccess Enclosure (MAE) Management".
- Double click on the "Perform Maintenance on MAE".
- The following window is displayed:



- Click on "Yes".
- The following window is displayed:



- Click on "OK".
- You should first received an alarm message saying: "MAE Concurrent Maintenance in Progress".
- Click on "OK".
- Wait until the "MAE Link" icon is red.
- Power OFF the MAE.
- Check that the cable between SIE and SAC located in the Multiaccess Enclosure is correctly plugged in each of these connectors.

Is plugging correct?

Yes No

002

Plug the cable correctly and restart the operation.

003

- Check the cable between SIE and SAC.
- (Step **003** continues)

003 (continued)

- Unplug the cable from SIE and from the SAC.
- On each connector of the cable check that the pins are present and not damaged.
- Refer to the *Multiaccess Enclosure Installation and Maintenance*, manual manual, in appendix *Multiaccess Enclosure Cables* to check the cable continuity between each pin connector.

Is the cable correct?

Yes No

004

Repair the cable (if possible) or order a new one.

005

- Replug the cable into the SIE cassette and into the SAC of the MAE.
- Power ON the MAE.

Is there an other FRU in your FRU list to test?

Yes No

006

Call your support for assistance.

007

Go to “3746-950 Maintenance Using a FRU list” on page 1-28 for FRU exchange.

MAP 2660: 3746-950 Intermittent Box Errors

This procedure can help you in case of intermittent problem on 3746-950.

001

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the 3746-950 icon.
- On the "3746-9x0 Menu", click on the "Problem Management" option.
- Double click on the "Manage Alarms/Errors/Events (SRCs)" option.
- The "System Reference Code Option Selection" window is displayed.

3746-9x0/System Reference Code Options Selection

Select a type of system reference code:

- ☐ All alarms, errors, events
- ☐ Alarms (interpretation possible)
- ☐ Errors (correlation and interpretation possible)
- ☐ Events

Select a resource:

- ☐ All resources
- ☐ Specific resource
- ☐ MOSS-E
- ☐ Controller bus and service processor
- ☐ ESCON processors
- ☐ Token-ring processors
- ☐ Controller bus and service adapter
- ☐ Communication Line Processor

Date interval (MM-DD-YY9 from to

- On this Screen select the options:
 1. "Errors (Correlation and interpretation possible)"
 2. "All resources" if you have no idea on the resource which can cause the errors. Otherwise select "Specific resource" or the attachment type suspected.
 3. Specify the Date interval that you want to see.
- Click on "OK".
- The "Error Type Selection" window is displayed.
- Select the "All types" option and click on "OK".
- An "Errors" window is displayed.

3746-9x0 Errors

Options View Help

Select an error for more information

Number	Type	NT	UU	RRRR	MM/DD/YY	HH:MM:SS	Text
5036	ERROR	06	00	0087	11/17/93	14:45:10	Error in the initializat
5037	ERROR	06	45	4501	11/17/93	14:44:48	XTPI_RS_F PHONE_DIAL or
5033	ERROR	06	00	0087	11/17/93	14:44:02	Error detected by the M

OK Previous List Next List List Selection Cancel Help

- Select the error that you want to see. You can display all the lists using the "Previous List" and "Next List" keys.
- Click on "View" (in the action bar). Then click on "Problem Interpretation" option.
- A "Problem Interpretation" window gives you the list of suspected FRUs with their fault probability.
- Record the FRU list and their fault probability for later use.
- Return to the "3746-9x0 Menu" window using the "Cancel" key.

MAP 2665: 3746 Model 950 Resource Not Present in CDF-E

Important


The SIE and MAE Resources are not present in CDF-E

You are here because you try to select a resource which is not present in the CDF-E.

This resource cannot be present because:

- The resource is defective
- The resource with the level higher is not present too.

So before to start this MAP you must determine from your FRU list the FRU with the highest level and start this procedure from this FRU



001

- From your FRU list identify the FRU with the highest level and check if this FRU is identified in current active CDF-E. The FRU is identified when its name **and** its address are present.
- Return to the "3746-9x0 Menu".
- Click on the "Configuration Management" option.
- Double click on the "Display/Update Active Configuration (CDF-E)" option.
- On the "Active CDF-E Display - Resource Selector" window search for the highest non-identified resource.

Once you have identified the highest missing resource in the CDF-E select it in the table below and perform the specified action.

3746-950 MAPs

Resource Level	Not Identified Resource	Then go
1	ESCP/TRP/CLP	"MAP 2670: 3746-950 Processor Non-Identified in CDF-E" on page 2-55.
2	ESCC/TIC3	"MAP 2675: 3746 Model 950 ESCC/TIC3 Non-Identified in CDF-E" on page 2-57.
2	LIC11/LIC12	"MAP 2680: 3746 Model 950 LIC11/LIC12 Non-Identified in CDF-E" on page 2-61.
3	LCB	"MAP 2685: 3746-950 LCB Non-Identified in CDF-E" on page 2-73.

MAP 2670: 3746-950 Processor Non-Identified in CDF-E

001

Test of the processor alone

- Unplug all the couplers connect on the suspected processor, but without to remove them from the enclosure.
- Continue with Step 002

002

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the processor and click on "OK".
- On the next "Resource Selector" windows, select the processor and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

003

Go to Step 009 on page 2-56.

004

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- A "Diagnostic" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostics error free?

Yes No

005

Did you change the suspected processor?

Yes No

006

Go to Step 012 on page 2-56.

007

Go to Step 009 on page 2-58.

008

According to the processor type that you have tested continue this procedure as indicated in the following table.

Processor Tested	Go to
ESCP/TRP	"MAP 2675: 3746 Model 950 ESCC/TIC3 Non-Identified in CDF-E" on page 2-57.
CLP	"MAP 2680: 3746 Model 950 LIC11/LIC12 Non-Identified in CDF-E" on page 2-61.

009

Did you already change the processor?

Yes **No**

010

- Exchange the suspected FRU. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- After replacing the FRU, wait until the 'alarm xxxx FRU plugged' is displayed and continue with Step 002 on page 2-55.

011

Call your support for assistance.

012

- Return to the "Maintenance Options" window.
 - Select the "Replace the resource" and click on "OK".
 - Exchange the suspected FRU. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
 - After replacing the FRU, continue with Step 002 on page 2-55.
-

MAP 2675: 3746 Model 950 ESCC/TIC3 Non-Identified in CDF-E**001****Did you test or replace a processor?****Yes No****002****Note**

Before continuing this procedure you must be sure that all traffic is stopped on attached processor.

You are here with processor identified but not tested or replaced.

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the **processor** and click on "OK".
- On the next "Resource Selector" windows, select the **processor** and click on "OK".

Is the "Maintenance Options" window displayed?**Yes No****003**

- Exchange the suspected processor. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- After replacing the FRU, continue with Step 002.

004

- **Unplug the couplers associated with this processor**, but without to remove them from the enclosure.
- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- A "Diagnostic" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostics error free?**Yes No****005****Did you change the processor?****Yes No****006**

- Return to the "Maintenance Options" window.
- Select the "Replace the resource" and click on "OK".
- Exchange the suspected processor. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- After replacing the FRU, continue with Step 002.

007

Call your support for assistance.

008

Go to Step 009.

009

You are here with a processor installed, error free and without any coupler.

- Plug the first coupler associated with the processor.
 - Continue with Step 010.
-

010

- Plug the coupler associated with the processor.
- Return to the "3746-9x0 Menu".
- Click on the "Configuration Management" option.
- Double click on the "Display/Update Active Configuration (CDF-E)" option.
- On the "Active CDF-E Display - Resource Selector" window check the presence of the plugged coupler. The coupler must be identified by **both** its name and line address.

Is the coupler identified by its name and its line address in the CDF-E?

Yes No

011

Is the associated processor still identified in the current CDF-E?

Yes No

012

Go to Step 026 on page 2-59

013

Go to Step 014

014

Here we test the processor and its attached coupler

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the **processor** and click on "OK".
- On the next "Resource Selector" windows, select the **processor** and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

015

Call your support for assistance.

016

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".

(Step 016 continues)

016 (continued)

- A "Diagnostic" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostics error free?

Yes No

017**Did you change the suspected coupler?**

Yes No

018

Go to Step 025.

019

Call your support for assistance.

020**Is there another coupler to replug on the processor?**

Yes No

021**Did you change a FRU during this procedure?**

Yes No

022

- The problem can be intermittent change all the suspected FRU(s).
- Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120.

023

Problem solved. Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

024

- Go to Step 010 on page 2-58.

025

- Return to the "Maintenance Options" window.
- Select the "Replace the resource" and click on "OK".
- Exchange the suspected **coupler** Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- Wait until the "alarm xxxx FRU unplugged" and 'alarm xxxx FRU plugged' are displayed then continue.
- On the "Confirmation" window, click on "OK".
- Go to Step 016 on page 2-58.

026

- Exchange the suspected coupler. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
 - Wait until the "alarm xxxx FRU unplugged" and 'alarm xxxx FRU plugged' are displayed then continue.
- (Step **026** continues)

026 (continued)

- Go to Step 014 on page 2-58.
-

MAP 2680: 3746 Model 950 LIC11/LIC12 Non-Identified in CDF-E**001****Is/are the suspected LIC unplugged.?****Yes No****002**

Go to Step 006.

003**Is a LIC11 to plug?****Yes No****004**

- Plug the LIC12.
- Go to Step 065 on page 2-69.

005

- Remove the cable at the rear of the LIC11.
 - Plug the LIC11.
 - Go to Step 009.
-

006**Is the LIC not identified a LIC11?****Yes No****007**

Go to Step 066 on page 2-69.

008

- Remove the cable at the rear of the LIC11.
 - Unplug, then plug the LIC11.
 - Go to Step 009.
-

009

- Return to the "3746-9x0 Menu".
- Click on the "Configuration Management" option.
- Double click on the "Display/Update Active Configuration (CDF-E)" option.
- On the "Active CDF-E Display - Resource Selector" window check the presence of the plugged coupler. The coupler must be identified by **both** its name and line address.

Is the coupler now present in CDF-E and identified by its name and its line address?**Yes No****010**

Go to Step 012.

011

Go to Step 021 on page 2-62.

012(Step **012** continues)

012 (continued)

- Exchange the suspected **coupler**. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- Wait until the 'alarm xxxx FRU unplugged' and 'alarm xxxx FRU plugged' are displayed then continue.

013

- On the "Active CDF-E Display" - Resource Selector" check the presence of the plugged coupler. The coupler must be identified by **both** its name and line address.

Is the coupler now present in CDF-E and identified by its name and its line address?

Yes No

014

Did you change the processor?

Yes No

015

Go to Step 020.

016

Call your support for assistance.

017

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the LIC11 and click on "OK".
- On the next "Resource Selector" windows, select the LIC11 and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

018

Call your support for assistance.

019

Go to Step 036 on page 2-65.

020**Note**

Before continuing this procedure you must be sure that all traffic is stopped on attached processor.

- Exchange the suspected **processor**. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- Wait until the 'alarm xxxx FRU unplugged' and 'alarm xxxx FRU plugged' are displayed then continue with Step 013.

021

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".

(Step **021** continues)

021 (continued)

- On the "Resource Selector" window, select the LIC11 and click on "OK".
- On the next "Resource Selector" windows, select the LIC11 and click on "OK".

Is the "Maintenance Options" window displayed?**Yes No****022**

Call your support for assistance.

023

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" then, click on "OK".
- An "Information Required" window is displayed asking you to install a wrap plug.
- Locate the LIC11.
- On the rear of the LIC11 install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?**Yes No****024**

Go to Step 034 on page 2-64.

025

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****026**

Go to Step 034 on page 2-64.

027

- Click on "Cancel".
- Locate the LCBB connected to this LIC11.
- **On the LCBB** unfasten the screws which maintain the cable coming from LIC11 and unplug it.
- On the rear of the LIC11 plug the cable coming from the LCBB and secure it.
- On the "Maintenance Options" window select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" then, click on "OK".
- An "Information Required" window is displayed asking you to install a wrap plug.
- On the end of the cable plugged on LIC11, install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

(Step **027** continues)

027 (continued)

Are the both LEDs of wrap plug ON?

Yes No

028

Go to Step 032.

029

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

030

Go to Step 032.

031

Go to Step 040 on page 2-65.

032

- Enter "No" on the "Information Required" window and click on "OK".
 - The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
 - The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window remind you to remove the wrap plug.
 - Unplug the wrap plug if not already done and click on "OK".
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 033.
-

033

The cable between the LIC11 and the LCBB is faulty. Order a new one, exchange it, and when it is done go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

034

- Enter "No" on the "Information Required" window and click on "OK".
 - The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
 - The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window remind you to remove the wrap plug.
 - Unplug the wrap plug if not already done and click on "OK".
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 035 on page 2-65.
-

035

(Step 035 continues)

035 (continued)

- The LIC11 is defective.
- Using the "Cancel" key return to the "Maintenance Options" window, select the "Replace the Resource" option then click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LIC11 replacement and after the LIC11 replacement, continue with the next bullet.
- Wait until you have seen messages saying 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' displayed on the service processor screen.
- On the "Confirmation" window click on "OK".
- Return to the "Maintenance Options" window, then continue with Step 036.

036

- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" then, click on "OK".
- An "Information Required" window is displayed asking you to install a wrap plug.
- Install the wrap plug PN 58G9425 at the rear of the LIC11.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

037

Call your support for assistance.

038

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

039

Call your support for assistance.

040

- Connect and secure the cable from the LCBB to the rear of the LIC11.
- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".

(Step **040** continues)

040 (continued)

Is the LIC11 identified by both its name and line address in the "Resource Selector" window?

Yes No

041

Go to Step 058 on page 2-68.

042

Is the LCB attached present in the "Resource Selector" window?

Yes No

043

Go to Step 058 on page 2-68.

044

Go to Step 045.

045

You are here with LIC11 changed and/or tested error free.

- On the "Resource Selector" window, select the LCB and click on "OK".
- On the next "Resource Selector" windows, select the LCB and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

046

Go to Step 058 on page 2-68.

047

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

048

- Using the "Cancel" key return to the "Maintenance Options" window, select the "Replace the Resource" option then click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LCB part replacement of your FRU list (LCPB or LCEB) and after the replacement, continue with the next bullet.
- Wait until you have seen messages saying 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' displayed on the service processor screen, then continue with Step 052 on page 2-67.

049

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" then, click on "OK".

(Step 049 continues)

049 (continued)

- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

050

- Using the "Cancel" key return to the "Maintenance Options" window, select the "Replace the Resource" option then click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LCB part replacement of your FRU list (LCPB or LCEB) and after the replacement, continue with the next bullet.
- Wait until you have seen messages saying 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' displayed on the service processor screen, then continue with Step 055.

051

Go to Step 064 on page 2-68.

052

- On the "Confirmation" window, click on "OK".
- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

053

Call support for assistance.

054

Go to Step 064 on page 2-68.

055

- On the "Confirmation" window, click on "OK".
- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

056

Call support for assistance.

057(Step **057** continues)

057 (continued)

Go to Step 064.

058

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the all LCB part replacement of your FRU list (LCPB or LCEB) and after the replacement, continue with the next bullet.
- Wait until you have seen messages saying 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' displayed on the service processor screen then continue.
- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the LCB and click on "OK".
- On the next "Resource Selector" windows, select the LCB and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

059

Call your support for assistance.

060

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

061

Call your support for assistance.

062

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

063

Call your support for assistance.

064

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option and click on "OK".
- Follow the instructions on the "Warning" window and click on "OK" when prompted.

(Step **064** continues)

064 (continued)

- The "Maintenance Options" window is displayed.
 - Select the "Remove the resource from concurrent mode" option and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource Selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Go to Step 085 on page 2-71
-

065

- Return to the "3746-9x0 Menu".
- Click on the "Configuration Management" option.
- Double click on the "Display/Update Active Configuration (CDF-E)" option.
- On the "Active CDF-E Display - Resource Selector" window check the presence of the plugged LIC12. The LIC12 must be identified by **both** its name and line address.

Is the LIC12 now identified by its name and its line address in the CDF-E?

Yes No

066

- Exchange the suspected **LIC12**. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- Wait until the 'alarm xxxx FRU unplugged' and 'alarm xxxx FRU plugged' are displayed then continue with Step 068.

067

Go to Step 076 on page 2-70.

068

- Return to the "3746-9x0 Menu".
- Click on the "Configuration Management" option.
- Double click on the "Display/Update Active Configuration (CDF-E)" option.
- On the "Active CDF-E Display - Resource Selector" window check the presence of the LIC12. The LIC12 must be identified by **both** its name and line address.

Is the LIC12 now identified by its name and its line address in the CDF-E?

Yes No

069**Did you change the processor?**

Yes No

070

Go to Step 075 on page 2-70.

071

Call your support for assistance.

072

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the LIC12 and click on "OK".

(Step **072** continues)

072 (continued)

- On the next "Resource Selector" windows, select the LIC12 and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

073

Go to Step 069 on page 2-69.

074

Go to Step 082 on page 2-71.

075

Note

Before continuing this procedure you must be sure that all traffic is stopped on attached processor.

- Exchange the suspected **processor**. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
 - Wait until the 'alarm xxxx FRU unplugged' and 'alarm xxxx FRU plugged' are displayed then continue with Step 068 on page 2-69.
-

076

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the LIC12 and click on "OK".
- On the next "Resource Selector" windows, select the LIC12 and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

077

Go to Step 066 on page 2-69.

078

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 SAT" then, click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

079

Go to Step 081.

080

Go to Step 084 on page 2-71.

081

(Step 081 continues)

081 (continued)

- Return to the "Maintenance Options" window.
- Select the "Replace the resource" and click on "OK".
- Exchange the suspected FRU. Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- The "Maintenance Options" window is displayed.
- Continue with Step 082.

082

- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 SAT" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

083

Go to Step 069 on page 2-69.

084

- Reconnect and secure the cable at the rear of LIC12.
- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "Resource Selection Options for Maintenance" window.
- Continue with Step 085

085**Is there another LIC to test?**

Yes No

086**Did you change a FRU during this procedure?**

Yes No

087

- The problem can be intermittent change all the suspected FRU(s).
- Go to "MAP: No Problem Found on All the FRUS with Diagnostics in Concurrent Mode" on page 1-120.

088

Problem solved. Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

089

(Step 089 continues)

089 (continued)

Go to Step 001 on page 2-61.

MAP 2685: 3746-950 LCB Non-Identified in CDF-E**001****Is the cable between the LIC11 and the suspected LCB unplugged?****Yes No****002**

Go to Step 005

003

- Plug correctly the suspected cable.
- Return to the "3746-9x0 Menu".
- Click on the "Configuration Management" option.
- Double click on the "Display/Update Active Configuration (CDF-E)" option.
- On the "Active CDF-E Display - Resource Selector" window, check the presence of the LCB.

Is the LCB now present in CDF-E?**Yes No****004**

Go to Step 005

005

- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- On the "Resource Selector" windows, select the LIC11 for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?**Yes No****006**

- Check that the customer stopped traffic on the suspected LIC11.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Then go to Step 005

007

- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LIC11.
- Unfasten the screws which maintain the cable, coming from the LCBB, on the rear of the LIC11 and unplug the cable.
- On the rear of the LIC11 install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?**Yes No****008**

Go to Step 018 on page 2-75.

009

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

010

Go to Step 019 on page 2-75.

011

- Click on "Cancel".
- Replug the cable coming from the LCBB on the rear of the LIC11 and secure it.
- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LCBB connected to this LIC11.
- **On the LCBB** unfasten the screws which maintain the cable, coming from the LIC11, and unplug it.
- On the end of the cable install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

012

Go to Step 016 on page 2-75.

013

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

014

Go to Step 017 on page 2-75.

015

Go to Step 023 on page 2-76.

016

- Enter "No" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
- The "Diagnostic Active Status" window is displayed. Then an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Go to Step 017.

017

The cable between the LIC11 and the LCBB is faulty. Order a new one, exchange it, and when it is done go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

018

- Enter "No" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
- The "Diagnostic Active Status" window is displayed. Then an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Go to Step 019.

019

- The LIC11 is defective.
- Using the "Cancel" key, return to the "Maintenance Options" window, select the "Replace the Resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LIC11 replacement. After the LIC11 replacement, continue with the next bullet.
- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Install the wrap plug PN 58G9425 at the rear of the LIC11.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

020

Call your support for assistance.

021

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".

(Step **021** continues)

021 (continued)

- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****022**

Call your support for assistance.

023

- Plug the cable in the LCBB and secure it using the screws.
- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".

Is initialization successful?**Yes No****024**

Go to Step 026

025

Go to Step 028

026

- On the "Warning" window, click on "OK".
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the **all** LCB part replacement of your FRU list (LCPB or LCEB) and after the replacement, continue with the next bullet.
- Wait until you have seen messages saying 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' displayed on the service processor screen then continue.
- Return to the "Maintenance Options" window, by clicking on "OK" on the "Resource Selector" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".

Is initialization successful?**Yes No****027**

Call your support for assistance.

028

- On the "Warning" window, click on "OK".
- Using the "Cancel" and "Leave" keys, return to the "Resource Selection Options for Maintenance" window,
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the LCB and click on "OK".
- On the next "Resource Selector" windows, select the LCB and click on "OK".

Is the "Maintenance Options" window displayed?**Yes No****029**

Call your support for assistance.

030

- On the "Maintenance Options" window, select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

031

Call your support for assistance.

032

- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Perform Diagnostic on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" then, click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done a "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

033

Call your support for assistance.

034

- Using the "Cancel" key, return to the "Maintenance Options" window.
 - Initialize and remove from the concurrent mode all the resources previously set in that mode using the following steps for each one:
 - Select the "Initialize the resource" option to reinitialize the FRU.
 - Follow the instructions on the "Warning" windows and click on "OK" when prompted.
 - The "Maintenance options" window is displayed.
 - Select "Remove the resource from the concurrent mode" option and click on "OK".
 - On the "Warning" window, click on "OK".
 - On the "Resource selector" window, click on "Cancel".
 - Return to the "Resource Selection Options for Maintenance" window.
 - Click on "Cancel" key.
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128
-

3746-950 ESCA MAPs

MAP 2700: 3746-950 Permanent ESCA Problem

Symptom Explanation	Conditions That Could Cause This Symptom
ESCA reported problem Host reporting error on Host/3746-950 fiber optic link	<ul style="list-style-type: none"> • ESCP • ESCC • Fiber optic

001

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the 3746-950 on which you want to work.
- According to the status of the 3746-950, run diagnostic on the suspected ESCP/ESCC using either "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39 or "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16.

Does the diagnostic run error-free?

Yes No

002

Exchange the faulty element (ESCP or ESCC). Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

003

Run the manual assurance test (MAT) using the specific wrap plug installed in the ESCC. According to the status of the 3746-950, use either "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16 if the 3746-950 is set in Online mode, or "MAP 2990: How to Run 3746-950 Specific Diagnostics" on page 3-41 if the 3746-950 is set in Offline mode.

Does the diagnostic run error-free?

Yes No

004

Exchange the faulty ESCC. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

005

Go to "MAP 2730: 3746-950 ESCA Activation Problem" on page 2-81.

MAP 2710: 3746-950 Any Intermittent ESCA Problem

Symptom Explanation	Conditions That Could Cause This Symptom
ESCA reported problem Host reporting error on Host/3746-950 fiber optic link	<ul style="list-style-type: none"> • ESCP • ESCC • Fiber optic

001

You are here because a host system or connected node indicated an error on the 3746-950 host fiber optic link or you have been leaded here under the guidance of the *Enterprise System Connection Link Fault Isolation ZZ22-9473* manual.

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the 3746-950 on which you want to work.
- A according to the status of the 3746-950 (offline or online), run diagnostic on the ESCP suspected using either "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39 or "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16.

Does the diagnostic run error-free?

Yes No

002

Exchange the faulty element (ESCP or ESCC). Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

003

Run the manual assurance test (MAT) using the specific wrap plug installed in the ESCC fiber optic position. According to the status of the 3746-950, run MAT diagnostic on the ESCC suspected using either "MAP 2990: How to Run 3746-950 Specific Diagnostics" on page 3-41 if the 3746-950 is set in Offline mode, or "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16 if the 3746-950 is set in Online Mode.

Does the MAT diagnostic run error-free?

Yes No

004

Exchange the faulty ESCC. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

005

Perform the optical power measurement.

- Use the *Problem Determination Procedures, Maintenance Information for Enterprise Systems Connection Links*, SY27-2597.
- To do this you must to set the specific ESCC to transmit offline sequence, using the following procedure from the service processor.
 - From the "3746-9x0 Menu", click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the ESCP on which you want the measurement. Then click on "OK".
 - On the "ESCON configuration Lines" window, select "Options" (in the action bar). Then select the "Manage ESCC status" option..
 - On the "ESCC status Management" window, select the "Transmit offline sequence".
- Return or refer to the *Enterprise System Connection Link Fault Isolation ZZ22-9473* manual to continue the problem determination.

MAP 2720: 3746-950 Bit Error Rate Validation

Symptom Explanation	Conditions That Could Cause This Symptom
ESCA reported problem Host reporting error on Host/3746-950 fiber optic link	<ul style="list-style-type: none"> • ESCP • ESCC • Fiber optic

001

You are here under the guidance of the *Enterprise System Connection Link Fault Isolation ZZ22-9473* manual.

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
 - On the "MOSS-E View" window, double click on the 3746-950 on which you want to work.
 - On the "3746-9x0 Menu" window, click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management-Resource Selector" window, select the desired ESCP then click on "OK".
 - The "ESCON Configuration-Lines" window is displayed.
 - Click on the "Options" (in the action bar). Then click on the "Manage ESCC status" option.
 - The "ESCC Status Management" window is displayed.
 - Look the bit error count displayed for the ESCC.
 - This bit error count is reset every five minutes and, if the maximum count value (15) is reached, an SRC is generated. If the maximum count is reached before the five minutes the counter stays at that value until the reset.
 - Record the bit error rate counter.
 - Click on the "Refresh" (in the action bar) then click on the "Permanent Refresh" option.
 - Wait five minutes.
 - Record the new bit error rate counter.
 - Click on the "Refresh" (in the action bar). Then click on the "Stop Permanent Refresh" option.
 - Click on the "Options" (in the action bar). Then click on the "Return" option.
 - On the "ESCON Configuration-Lines" window, click on the "Options" (in the action bar). Then click on the "Exit" option.
 - On the "Confirmation" window, click on "OK".
 - Return to the "3746-9x0 Menu" window using the "Cancel" key.
 - Return or refer to the *Enterprise System Connection Link Fault Isolation ZZ22-9473* manual to continue the problem determination.
-

MAP 2730: 3746-950 ESCA Activation Problem

Symptom Explanation	Conditions That Could Cause This Symptom
ESCA activation problem Host reporting ESCA enable problem	<ul style="list-style-type: none"> • ESCP • ESCC • Fiber optic • Host system

A host system cannot enter in communication with the 3745 via the 3746-950 ESCA.

001

If you are not logged ON the service processor console, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.

- On the "MOSS-E View" window, double click on the 3746-950 on which you have the problem.
- The "3746-9x0 Menu" is displayed.
- Double click on the "Configuration Management" option.
- Double click on the "Manage ESCON Processors" option.
- On the "ESCP Management Resource Selector" window, select the desired ESCP. Then click on "OK".
- The "ESCON Configuration Lines" window is displayed.
- Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
- The following "ESCC Status Management" window is displayed.

ESCC Satus Management

Options Refresh Help

ESCP 2240 Configuration from ESCP

ESCC 0: 2240 Present: YES

ESCC 1: 2272 Present: NO

ESCC 0 Status: ENABLED

ESCC 1 Status:

Request to change ESCC 0 status:

Request to change ESCC 1 status:

o Enable

o Enable

o Transmit offline sequence

o Transmit offline sequence

o Disable

o Disable

Fiber status IN = IDLE CHARACTERS

Fiber status IN =

Fiber status OUT = ENABLE OBTAINED

Fiber status OUT =

Control unit link address

Control unit link address

(CNTLUNIT LINK):

(CNTLUNIT LINK):

Bit error rate counter:

Bit error rate counter:

- Select the "enable" option.
- Click on the "Options" (in the action bar). Then select the "Send request and save" option.
- A "confirmation" window is displayed, click on "OK".
- A "Warning" window inform you that the ESCP configuration is saved, click on "OK".
- Click on "Refresh"(in the action bar). Then select "Permanent Refresh" (no further action is possible from this screen). The screen is refreshed with the last status.
- When the "enable" is complete the "ESCC x Status" line displays : ENABLED.
- Click on "Refresh" (in the action bar). Then select "Stop permanent refresh".

(Step 001 continues)

001 (continued)

Is the "ESCC x Status" line displaying: **ENABLED**?

Yes No

002

Go to Step 004

003

- The ESCC is enabled. Return to the "MOSS-E View" window.
- Go to "CE Leaving Procedure" on page 4-53 to return the machine to the customer. If the problem persists contact your support.

004

Is the "fiber status IN" with **LIGHT OFF** indication displayed?

Yes No

005

Go to Step 007

006

Suspect a problem in the neighbor. Refer to *Problem Determination Procedures, Maintenance Information for Enterprise Systems Connection Links* SY27-2597.

007

Is the "fiber status In" with **OFFLINE SEQUENCES** indication displayed?

Yes No

008

Go to Step 010

009

Check the indication displayed on the "fiber status **OUT**". Then take the appropriate action described in the following table.

Fiber Status OUT indication	Action to Perform
ESCP EMITS OLS	Suspect a problem in the neighbor. Refer to <i>Problem determination Procedures, maintenance Information for Enterprise Systems Connection Links</i> SY27-2597.

010

- The fiber status **IN** indicates: ESCC DOWN, NO INFO.
- Check the indication displayed on the "fiber status **OUT**". Then take the appropriate action described in the following table.

Fiber Status OUT indication	Action to Perform
ESCP FORCED OLS	Suspect a problem in the ESCC. Go to "Run Diagnostics" on page 1-4 to run diag on the suspected FRU.
ESCC ERROR / NO INFO	Suspect a problem in the ESCC, then in the ESCP Go to "Run Diagnostics" on page 1-4 to run diag on the suspected FRUs.

(Step 010 continues)

010 (continued)

If you have already changed the ESCC and the ESCP, call your support for assistance.

3746-950 LAN MAPs

MAP 2750: 3746-950 Permanent Service Processor Link Problem

Symptom Explanation	Conditions That Could Cause This Symptom
Service processor not accessible digit present Console Message	<ul style="list-style-type: none"> • Service processor • CBSP cassette • TIC3 cassette • Service Processor Access Unit • Loop

001

Is there a panel code displayed on the 3746-950 control panel?

Yes No

002

Go to "3746-950 Control Panel Symptoms" on page 1-14.

003

Using the control panel code displayed on the 3746-950 control panel, go to "3746-950 Control Panel Codes" on page 1-15 and perform the action required.

Is your problem solved?

Yes No

004

Go to Step 006

005

Restart your application.

006

– Run the service processor link restart test as follows:

1. Set the service mode to maintenance.
 - a. Press the 'Service' key until the number '1' is displayed in the service window.
 - b. Press the 'Validate' key.
2. Start the test as follows:
 - a. Press the 'Function' key until the number '6' is displayed in the function window.
 - b. Press the 'Validate' key.
3. On the display, note the control panel code and perform the required action using the following table.

Control Panel Code	Action
05B0B0FD	Go to Step 007
05B0B0FE	TIC3 already active. User error
05B0B0FF	Microcode error call your support
Any other panel code	If the panel code displayed is NOT the same in step 3 go to "3746-950 Control Panel Codes" on page 1-15 and perform the action required. Otherwise exchange the CBSP.

007

(Step 007 continues)

007 (continued)

On the display, note the value of the 'Console not accessible' window.

Is there a value displayed?

Yes No

008

Connection established successfully. Press the 'Exit' pushbutton on the 3746-950 control panel, 00000000 must be displayed.

009

Is the displayed value permanently ON?

Yes No

010

- The 3746-950 is trying to establish a link with the service processor and the values are changing.
- According to the progress of the retries some value are displayed. These value are:
 - '*': Physical link not active
 - '\$': Disconnected at SSA level
 - 'A': 'OK' frame received on 'Hello' frame
 - 'C': Connected at DLC level
 - 'D': Disconnected sent by the service processor
 - 'E': Internal error
 - 'F': 'Hello' frame sent
 - 'G': Ring failure
 - 'I': Inserted
 - 'N': Inserting on LAN or retrying insertion
 - 'R': Link reset
 - '5': Congestion of CBSP during general IML
- When the connection or the retry is not possible a fixed value is displayed.
- Go to Step 011.

011

In the following table, locate the character displayed in the 'service processor not accessible' digit and perform the appropriate action.

Service Processor Not Accessible Digit Value	Action
*	Physical link not active. if not already done, note the control panel code and go to "3746-950 Control Panel Codes" on page 1-15 Otherwise call your support structure.
\$	Call your support structure.
B	Permanent beaconing. Refer to <i>Token-Ring Network, Problem Determination Guide</i> SX27-3710.
C	Call your support structure.
G	Ring failure (see your LAN manager).
H	Exchange the TIC3 of the CBSA
L	Your 3746-950 is not connected to the LAN. Check the 3746-950 LAN cable connection on the TIC3 and on the service processor access unit.
T	A physical link is established but there is no answer from the service processor. Suspect a microcode problem and contact your support.
U	TIC3 is unplugged. Replug the TIC3 cassette, run the service processor link restart again, if the same digit code is displayed exchange the TIC3.
U	Suspect a microcode problem and contact your support structure.

MAP 2760: 3746-950 TRP LAN Problem

Symptom Explanation	Conditions That Could Cause This Symptom
Unable to activate or deactivate a ring. Errors occur while ring is running. Console Message	<ul style="list-style-type: none"> • TRP • TIC3 • ring • Ethernet Bridge • Ethernet Bridge Connection Box




Figure 2-10. 3746 Model 9x0 TRP LAN

Notes:

1. The multiaccess enclosure can be connected to TIC3s of the same or different TRP.
2. One TIC3 of the multiaccess enclosure can be a TIC3 of the CBSTRP.

001

**You are here because there is a problem on a LAN connected to a TRP.
Are there two LANs connected on the same suspected TRP?**

Yes No

002

Go to Step 010 on page 2-87

003

Have the two LANs a problem?

Yes No

004

Is there a Ethernet Bridge connected to the suspect Token-Ring LAN?

Yes No

005

(Step 005 continues)

005 (continued)

Is there a multiaccess enclosure connected to the suspect Token-Ring LAN?

Yes No

006

Go to Step 047 on page 2-90

007

Go to Step 035 on page 2-89

008

Go to Step 038 on page 2-89

009

Go to Step 054 on page 2-91.

010

Is there a Ethernet Bridge connected to the suspect Token-Ring LAN?

Yes No

011

Is there a multiaccess enclosure connected to the suspect Token-Ring LAN?

Yes No

012

Go to Step 026 on page 2-88

013

Go to Step 023 on page 2-88

014

You are here because there is a problem on a Ethernet LAN connected to a TRP.

Check that all the cables are properly plugged in:

- The Ethernet bridge connection box,
- The Ethernet Bridge
- The TIC3 of the 3746.

Everything OK?

Yes No

015

Correct the problem

016

Are the Ethernet Bridge powered ON.

Yes No

017

Check the power cable connection
(Step **017** continues)

017 (continued)

Is the problem corrected?

Yes No

018

Go to Step 073 on page 2-92.

019

Problem solved. Return the machine to the customer, go to "CE Leaving Procedure" on page 4-53.

020

Is there a yellow LED, or number displayed on the Ethernet Bridge?

Yes No

021

Go to Step 070 on page 2-92.

022

Refer to the *8229 Bridge Manual*, GA27-4025 to investigate the problem.

023

Check the status of the multiaccess enclosure using the *Multiaccess Enclosure Installation and Maintenance*, manual.

Are all LEDs OK?

Yes No

024

Continue problem determination of the multiaccess enclosure with the *Multiaccess Enclosure Installation and Maintenance*, manual.

025

Go to Step 070 on page 2-92.

026

You are here because there is a problem on a Token-Ring LAN connected to a TRP.

- Check that all the cables are properly plugged to the ring, and in the TIC3 of the 3746.

Everything OK?

Yes No

027

Correct the problem

028

From the service processor run the SAT on the suspected TIC3 coupler. Refer either to "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39 to run diagnostic in offline mode or to "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16 to run diagnostic in concurrent mode.

Does the diagnostic run error-free?

Yes No

029

(Step 029 continues)

029 (continued)

Exchange the faulty FRU. Go to “3746-950 Maintenance Using a FRU list” on page 1-28.

030

Run the manual assurance test (MAT) using the specific wrap plug installed in the TIC3. According to the status of the 3746-950 use either “MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode” on page 3-16 if the 3746-950 is set in Online mode, or “MAP 2990: How to Run 3746-950 Specific Diagnostics” on page 3-41 if the 3746-950 is set in Offline mode.

Does the MATs diagnostic run error-free?

Yes No

031

Exchange the faulty FRU. Go to “3746-950 Maintenance Using a FRU list” on page 1-28.

032

Run diagnostic on the token ring processor. Refer either to “MAP 2980: How to run 3746-950 Diagnostic in Offline Mode” on page 3-39 to run diagnostic in offline mode or to “MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode” on page 3-16 to run diagnostic in concurrent mode.

Is the diagnostic run error-free?

Yes No

033

Exchange the faulty FRU. Go to “3746-950 Maintenance Using a FRU list” on page 1-28.

034

You can suspect a problem on the link. Perform the problem determination on the ring using the *Token-Ring Network, Problem Determination Guide SX27-3710*, or call your support for assistance.

035

Check the status of the multiaccess enclosure using the *Multiaccess Enclosure Installation and Maintenance*, manual.

Are all LEDs OK?

Yes No

036

Continue problem determination of the multiaccess enclosure with the *Multiaccess Enclosure Installation and Maintenance*, manual.

037

Go to Step 047 on page 2-90

038

You are here because you suspect a problem on a Ethernet LAN connected to a TRP.

- Check that all the cables are properly plugged in the Ethernet bridge connection box, in the Ethernet Bridge, and in the TIC3 of the 3746.

Everything OK?

Yes No

039

Correct the problem

040

(Step **040** continues)

040 (continued)

Are the Ethernet Bridge powered ON.

Yes No

041

Check the power cable connection

Is the problem corrected?

Yes No

042

Go to Step 073 on page 2-92.

043

Problem solved. Return the machine to the customer, go to "CE Leaving Procedure" on page 4-53.

044

Is there a yellow LED, or number displayed on the Ethernet Bridge?

Yes No

045

Go to Step 049.

046

Refer to the *8229 Bridge Manual*, GA27-4025 to investigate the problem.

047

You are here because you suspect a problem on a Token-Ring LAN connected to a TRP.

- Check that all the cables are properly plugged to the ring, and in the TIC3 of the 3746.

Everything OK?

Yes No

048

Correct the problem

049

From the service processor run the SAT on the suspected TIC3 coupler. Refer either to "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39 to run diagnostic in offline mode or to "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16 to run diagnostic in concurrent mode.

Does the diagnostic run error-free?

Yes No

050

Exchange the faulty FRU. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

051

Run the manual assurance test (MAT) using the specific wrap plug installed in the TIC3. According to the status of the 3746-950 use either "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16 if the 3746-950 is set in Online mode, or "MAP 2990: How to Run 3746-950 Specific Diagnostics" on page 3-41 if the 3746-950 is set in Offline mode.

(Step **051** continues)

051 (continued)

Does the MATs diagnostic run error-free?

Yes No

052

Exchange the faulty FRU. Go to “3746-950 Maintenance Using a FRU list” on page 1-28.

053

You can suspect a problem on the link.

- If you are investigating on Ethernet LAN problem run test on the Ethernet Bridge using the *8229 Bridge Manual*, GA27-4025. If the Ethernet Bridge is error free call your support for assistance.
- If you are investigating on multiaccess enclosure problem run test on the multiaccess enclosure using the *Multiaccess Enclosure Installation and Maintenance*, manual. If the multiaccess enclosure is error free call your support for assistance.
- If you are investigating on a Token-Ring LAN problem, perform the problem determination on the ring using the *Token-Ring Network, Problem Determination Guide* SX27-3710. If you do not solve your problem call your support for assistance.

054

Are there two Ethernet Bridge connected to the suspect TRP?

Yes No

055

Are there a multiaccess enclosure connected to the suspect TRP?

Yes No

056

Go to Step 070 on page 2-92.

057

Go to Step 067 on page 2-92

058

The two LANs are Ethernet LANs.

- Check that all the cables are properly plugged in the Ethernet bridge connection box, in the Ethernet Bridge, and in the TIC3 of the 3746.

Everything OK?

Yes No

059

Correct the problem

060

Are the Ethernet Bridge powered ON.

Yes No

061

Check the power cable connection

Is the problem corrected?

Yes No

062

(Step **062** continues)

062 (continued)
Go to Step 073.

063

Problem solved. Return the machine to the customer, go to "CE Leaving Procedure" on page 4-53.

064

Is there a yellow LED, or number displayed on the Ethernet Bridge?

Yes No

065

Go to Step 070.

066

Refer to the *8229 Bridge Manual*, GA27-4025 to investigate the problem.

067

Check the status of the multiaccess enclosure using the *Multiaccess Enclosure Installation and Maintenance*, manual.

Are all LEDs OK?

Yes No

068

Continue problem determination of the multiaccess enclosure with the *Multiaccess Enclosure Installation and Maintenance*, manual.

069

Go to Step 070

070

Run diagnostic on the token ring processor. Refer either to "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39 to run diagnostic in offline mode or to "MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode" on page 3-16 to run diagnostic in concurrent mode.

Is the diagnostic run error-free?

Yes No

071


Exchange the faulty FRU. Go to "3746-950 Maintenance Using a FRU list" on page 1-28.

072

You can suspect a problem on the link.

- If you are investigating on a Token-Ring LAN problem, perform the problem determination on the ring using the *Token-Ring Network, Problem Determination Guide* SX27-3710.
 - If you are investigating on Ethernet LAN problem run test on the Ethernet Bridge using the *8229 Bridge Manual*, GA27-4025. If the Ethernet Bridge is error free call your support for assistance.
 - If you are investigating on multiaccess enclosure problem run test on the multiaccess enclosure using the *Multiaccess Enclosure Installation and Maintenance*, manual. If the multiaccess enclosure is error free call your support for assistance.
-

073



Fuse Location on ac outlet distribution box

- On the ac outlet distribution box:
 - Fuse F1 controls the range of connectors J1 to J4
 - Fuse F2 controls the range of connectors J5 to J8.
- Check if other units are connected to the same range of connectors than the suspected unit.

Are there other units connected to the same range than the suspected unit?

Yes No

074

Go to Step 083 on page 2-94.

075

Check that the other units have their power ON/OFF switch to ON.

Are other units powered ON?

Yes No

076

Go to Step 078

077

Suspect a power problem in the Ethernet Bridge. Refer to the *8229 Bridge Manual*, GA27-4025 to investigate the problem.

078

Check the corresponding fuse.

Is the fuse OK?

Yes No

079

- Switch to OFF all the units controlled by this fuse.
- Disconnect the power cord of the Ethernet Bridge.
- Exchange the defective fuse.
- Switch ON all the units controlled by this fuse.
- Reconnect the power cord of the Ethernet Bridge.

(Step **079** continues)

079 (continued)

Is the fuse blown again?

Yes No

080

Problem solved go to "CE Leaving Procedure" on page 4-53.

081

- Suspect a power problem in a unit powered through the ac outlet distribution box.
 - Switch to OFF all the units controlled by this fuse.
 - Exchange the fuse.
 - Switch one by one the units controlled by this fuse to identify the unit which has a problem.
 - Once you have identified the faulty unit continue with Step 090.
-

082

Suspect the ac wall socket.

083

Check the corresponding fuse.

Is the fuse OK?

Yes No

084

- Disconnect the power cord of the Ethernet Bridge.
- Exchange the defective fuse.
- Reconnect the power cord of the Ethernet Bridge.

Is the fuse blown again?

Yes No

085

Problem solved go to "CE Leaving Procedure" on page 4-53.

086

Suspect a power problem in the Ethernet Bridge. Refer to the *8229 Bridge Manual*, GA27-4025 to investigate the problem.

087

Are all other units installed in the controller rack powered ON?

Yes No

088

Suspect the ac wall socket.

089

Suspect a power problem in the Ethernet Bridge. Refer to the *8229 Bridge Manual*, GA27-4025 to investigate the problem.

090

According to the defective unit type select, the action to be performed.

Unit Type	Action
Service Processor, Display, Optical Disk	Refer to "Service Processor Problem Determination" in the corresponding <i>Service Processor Installation and Maintenance</i> manual.
Network Node Processor	Refer to the <i>Network Node Processor Installation and Maintenance</i> manual according to the network node processor type to investigate the problem.
Modem	Refer to the following modem documentation: <ul style="list-style-type: none"> • For IBM 7855, refer to the <i>7855 Modem Model 10 Guide to Operation</i>, GA33-0160 • For IBM 7857, refer to the <i>IBM 7857 Guide to Operation</i>, GA13-1839 • For IBM 7858, refer to the <i>IBM 7858 Professional Modem Guide to Operation</i>, GA13-1981 • For other modem, refer to the appropriate documentation.
Ethernet Bridge	Refer to the <i>8229 Bridge Manual</i> , GA27-4025.
Multiaccess Enclosure	Refer to the <i>Multiaccess Enclosure Installation and Maintenance</i> , manual.

MAP 2770: 3746-950 Duplicate Token Ring Local Address

Symptom Explanation	Conditions That Could Cause This Symptom
3746-950 has the same token ring local address as another unit on the ring.	

001**Are you installing the 3746-950?****Yes No****002**

- There is another unit already in the ring with the same address. Determine which unit it is and change its token ring local address.
- Press the 'General IML' button on the 3746-950 control panel.

003**Do you want to keep the 3746-950 token ring local address?****Yes No****004**

- Return to the service processor console.
- Click on "Remove", on the window displayed.
- Remove the 3746-950 installation diskette from the service processor.
- Press on "Standby" key on the 3746-950 control panel.
- Reinstall the 3746-950 starting from step "Verifying the 3746-950 Code Level" in chapter "Installing and connecting the 3746-950 to the Service Processor" of the *IBM 3746 Nways Multiprotocol Controller Model 950, Installation Guide*, SY33-2107.

005

- Change the address of the other device already on the ring. Refer to its installation documentation.
 - Press the 'General IML' button on the 3746-950 control panel.
 - Return to the *IBM 3746 Nways Multiprotocol Controller Model 950, Installation Guide*, SY33-2107 step 2 of the paragraph "Configuring the Service Processor".
-

3746-950 CLP MAPs

MAP 2800: 3746-950 All the Lines of CLP Have a Problem


Symptom Explanation	Conditions That Could Cause This Symptom
All lines of CLP have problem Line activation problem on all the lines of one or more CLPs	<ul style="list-style-type: none"> One or more Processor unplugged or failing CLP

The hardware can connect four adjacent LICs to two adjacent CLPs. This hardware connection allows the CLPs to operate in standard mode or backup mode depending upon the option defined in the MOSS-E table.


The Backup Mode is only possible between two adjacent positions

CLP Position	Line Addresses	Attached LIC Position	CLP Backup Position
07G-A1-H	2112-2175	07N-A1 G and H	07G-A1 K
07G-A1-K	2176-2239	07N-A1 J and K	07G-A1 H
07G-A1-M	2240-2303	07N-A1 L and M	07G-A1-P
07G-A1-P	2304-2367	07N-A1 N and P	07G-A1-M
07E-A1-D	2368-2431	07M-A1 C and D	07E-A1-F
07E-A1-F	2432-2495	07M-A1 E and F	07E-A1-D
07E-A1-H	2496-2559	07M-A1 G and H	07E-A1-K
07E-A1-K	2560-2623	07M-A1 J and K	07E-A1-H
07E-A1-M	2624-2687	07M-A1 L and M	07E-A1-P
07E-A1-P	2688-2751	07M-A1 N and P	07E-A1-M
07D-A1-D	2752-2815	07L-A1 C and D	07D-A1-F
07D-A1-F	2816-2879	07L-A1 E and F	07D-A1-D
07D-A1-H	2880-2943	07L-A1 G and H	07D-A1-K
07D-A1-K	2944-3007	07L-A1 J and K	07D-A1-H
07D-A1-M	3008-3071	07L-A1 L and M	07D-A1-P
07D-A1-P	3072-3135	07L-A1 N and P	07D-A1-M

CLP in Backup Mode



CLP in Standard Mode



001

- Before continuing it is necessary to check if the suspected CLP has a backup CLP and if the LICs normally under the control of the suspected CLP are now under the control of the backup CLP.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Configuration Management" option.
 - Double click on the "Define Backup CLP" option.
 - The following "CLP Backup" window is displayed.

Processor Backup

Select a processor:

Processor Type	Primary Processor	Backup Processor	Automatic Fallback	Fallback State	Switchback Requested	
CLP	2112	2176	no	no	no	1
CLP	2176	2112	no	yes	no	2
CLP	2240		no	no	no	3
CLP	2304		no	no	no	3

Notes:

- 1** and **2** These lines indicates that the CLP line addresses range from 2112 and from 2176 can be backup for each other.
 - 2** This line with a "yes" in the fallback state column indicates that the primary processor (2176) is controlling the LICs of the backup processor (2112).
 - 3** These lines indicate that the CLPs have no backup.
- Note if the suspected CLP is backed up by another one, then click on the "Cancel" key.

Does the suspected primary CLP have a backup CLP with a "Yes" in the fallback state column?


Yes No

002

Test the suspected CLP. Go to Step 004 on page 2-99

003

The resources of the suspected CLP are under the control of the backup CLP.



Test the CLP which does the backup. Go to Step 004 on page 2-99.

004

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the processor for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?**Yes No****005**

- Check that the customer stopped traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Go to Step 004.

006

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?**Yes No****007**


- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143 for procedure).
- Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28.

008

Call your support for assistance.

MAP 2810: 3746-950 Problem on a Group of ARCs

Symptom Explanation	Conditions That Could Cause This Symptom
All the lines of the same ARC group have a problem.	<ul style="list-style-type: none"> One or more ARCs failing LCPB LCEB or LCEE problem



001

Is the 3746-950 set in Offline mode?

Yes No

002

Go to Step 004.

003

- To set the 3746-950 in Online, mode follow these steps.
 - Double click on the 3746-950 icon.
 - On the "3746-9x0 Menu" window, click on the "Problem management" option.
 - Click on the "Set 3746-9x0 Online/Offline option".
 - On the "Set 3646-9x0 Online/Offline" window, click on "Yes".
 - On the next "Set 3746-9x0 Online/Offline" window click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK".
- Start a general IML in order to set the 3746-950 in Online mode.
- At completion of the IML, the 3746-950 icon must be green.

Go to Step 004.

004

Did you arrive here using a FRU list, or a SRC sequence number?

Yes No

005

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, click on the 3746-950 on which you want to work.
- The "3746-9x0 Menu" window is displayed.
- Click on the "Problem Management" option.

(Step **005** continues)

005 (continued)

- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 006

006

- Check that the customer stopped the traffic on the suspected ARCs.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Locate the line connection box (LCBB or LCBE) housing the suspected defective group of ARCs.
- Locate the suspected ARC group in the LCB.

Is there only one ARC present in the suspected ARC group?

Yes No

007

Go to Step 017 on page 2-102.

008

- On the next "Resource Selector" windows, select the ARC of the ARC group for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

009

- Check that the customer stopped the traffic on the suspected ARC.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 008

010

- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC SAT" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

011**Have you already changed this ARC?**

Yes No

012

(Step 012 continues)

012 (continued)

- Using the "Cancel" key return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the ARC replacement. After the ARC replacement, continue with Step 010 on page 2-101

013

Go to Step 032 on page 2-104.

014

Have you already changed this ARC?

Yes No

015

Go to Step 032 on page 2-104.

016

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

017

- On the next "Resource Selector" windows select one ARC of the ARC group which has not been yet set in concurrent mode and click on "OK".

Is the "Maintenance Options" window displayed?

Yes No

018

- Check that the customer stopped the traffic on the suspected ARCs.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Then go to Step 017.

019

Have you put all the suspected ARCs of the ARC group in concurrent mode?

Yes No

020

- On the "Maintenance Options" window, click on "Cancel".
- On the "Resource Selector" window, click on "Cancel".
- On the "Concurrent Mode Confirmation" window, click on "Leave".
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- Go to Step 017.

021

- Unscrew the knobs on the suspected ARCs and unplug all the suspected ARCs except **one**, from the LCBB or LCBE. (Note carefully the position of each ARC in the LCB).
- (Step 021 continues)

021 (continued)

- Go to Step 022.

022**You need to select again the ARC installed in the LCB**

- Return to the "Maintenance Options" window and click on "Cancel".
- On the "Resource Selector" window, click on "Cancel".
- On the "Concurrent Mode Confirmation" window, click on "Leave".
- On the "Resource Selection Options for Maintenance" window, select the "Via the Active CDF-E" option and click on "OK".
- On the next "Resource Selector" windows select the ARC of the ARC group which is install in the LCB and click on "OK".
- Go to Step 023.

023

- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC SAT" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

024**Have you already changed this ARC?**

Yes No

025

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the ARC replacement. After the ARC replacement, return to the "Maintenance Options" window and continue with Step 023

026

- Reinstall in the LCB all the ARCs removed.
- Go to Step 032 on page 2-104.

027**Is there another ARC of the suspected ARC group to test?**

Yes No

028**Have you already changed an ARC during this procedure?**

Yes No

029

(Step 029 continues)

029 (continued)

- Reinstall in the LCB all the ARCs removed.
- Go to Step 032.

030

Problem has been identified and solved. Plug all the ARCs unplugged, then go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

031

- Unplug the tested ARC. Then plug the next ARC of the ARC group.
 - Go to Step 022 on page 2-103.
-

032

- Problem is not an ARC problem.
 - If you have already tested the LCB components call your support for assistance.
 - Otherwise using the "Cancel" key return to the "3746-9x0 Menu".
 - Click on the "Problem Management" option.
 - Double click on the "Perform Maintenance" option.
 - On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
 - On the "Resource Selector" window select the LCB that you want to test.
 - Go to "3746-950 FRU list for exchange" on page 1-54 and select the LCB component and continue the procedure.
-

MAP 2820: 3746-950 Problem on a LIC11

Symptom Explanation	Conditions That Could Cause This Symptom
All the lines on LIC11 have a problem.	<ul style="list-style-type: none"> • LIC11 • Cable between LIC11 and LCPB • LCPB • LCEB • CLP

001

Is the 3746-950 set in Offline mode?

Yes No

002

Did you arrive here using a FRU list, or a SRC sequence number?

Yes No

003

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, click on the 3746-950 on which you want to work.
- The "3746-9x0 Menu" window is displayed.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 004

004

- On the "Resource Selector" window, select the LIC11 for concurrent maintenance, click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

005

- Check that the customer stopped the traffic on the suspected LIC11.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 004

006

Go to Step 008 on page 2-106.

007

Go to Step 042 on page 2-110

008

(Step 008 continues)

008 (continued)

- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LIC11.
- Unfasten the screws which maintain the cable coming from the LCBB on the rear of the LIC11 and unplug the cable.
- On the rear of the LIC11 install the wrap plug PN 58G9425.
- Check if the two LEDs are ON.

Are the both LEDs of wrap plug ON?**Yes No****009**

Go to Step 013.

010

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****011**

Go to Step 014.

012

Go to Step 019 on page 2-107.

013

- Enter "No" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
- The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Go to Step 014.

014

- The LIC11 is defective.
- Using the "Cancel" key, return to the "Maintenance Options" window, select the "Replace the Resource" option and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LIC11 replacement and after the LIC11 replacement, continue with the next bullet.

(Step **014** continues)

014 (continued)

- Wait until 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Install the wrap plug PN 58G9425 at the rear of the LIC11.
- Check if the two LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

015

Call your support for assistance.

016

- Enter "Yes" on the information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

017

Call your support for assistance.

018

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

019

- Click on "Cancel".
- Replug the cable coming from the LCBB on the rear of the LIC11 and secure it.
- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LCBB connected to this LIC11.
- **On the LCBB** unfasten the screws which maintain the cable coming from LIC11 and unplug it.
- On the end of the cable install the wrap plug PN 58G9425.
- Check if the two LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

020

Go to Step 024 on page 2-108.

021(Step **021** continues)

021 (continued)

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

022

Go to Step 025.

023

Go to Step 026.

024

- Enter "No" on the "Information Required" window and click on "OK".
 - The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
 - The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window remind you to remove the wrap plug.
 - Unplug the wrap plug if not already done and click on "OK".
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 025.
-

025

The cable between the LIC11 and the LCBB is faulty. Order a new one, exchange it, and when it is done go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

026

- Plug the cable in its LCBB, and secure it using the screws.
- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

027

- Display the list of suspected FRU(s) (see "Display the FRU List After a Diagnostic Failure" on page 1-143).
- Select the FRU with the highest fault probability.
- Continue with Step 029 on page 2-109.

028

(Step 028 continues)

028 (continued)
Go to Step 034.

029

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue.
- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

030

Is there another FRU in your FRU list?

Yes No

031

Call your support for assistance.

032

Go to Step 029.

033

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

034

- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

035

- Display the list of suspected FRU(s) (see "Display the FRU List After a Diagnostic Failure" on page 1-143).
- Select the FRU with the highest fault probability.
- Continue with Step 037 on page 2-110.

036

All diagnostics are error free. The problem can be intermittent. Call your support for assistance.

037

(Step **037** continues)

037 (continued)

- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LCEB replacement. After the LCEB replacement, continue.
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

038**Is there another FRU in your FRU list?**

Yes No

039

Call your support for assistance.

040

Go to Step 037.

041

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

042

- Double click on the 3746-950 icon.
- The "3746-9x0 Menu" is displayed.
- Click on the "Problem Management" option.
- Double click on the "Perform Offline Diagnostics" option.
- The "Diagnostics" window is displayed, select the "specific Adapter" and the "No" wrap options. Then click on "Start".
- On the next window select the processor which has the suspected LIC11, then click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

043

- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143).
- Select the FRU with the highest fault probability.

Is this FRU the CABM?

Yes No

044

- Exchange the FRU, go to Chapter 4, "3746-950 FRU Exchange" on page 4-1. (Step **044** continues)

044 (continued)

- Using the "Cancel" key return to the "Diagnostics" window.
- The "Diagnostics" window is displayed, select the "specific Adapter" and the "No" wrap options. Then click on "OK".
- On the next window select the processor which has the suspected LIC11, then click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free?**Yes No****045**

Go to Step 049.

046

Problem solved. Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

047

Go to Step 054

048

All diagnostics are error free. The problem can be intermittent. Call your support for assistance.

049**Is there another FRU in your FRU list?****Yes No****050**

Call your support for assistance.

051**Is this FRU the CABM?****Yes No****052**

Go to Step 044 on page 2-110.

053

Go to Step 054

054

- Return to the "Problem management" window.
- Double click on the "Perform Specific Diagnostics" option.
- On the "Diagnostic Control Monitor" window, select the option:
 - "Run diagnostics for a specific hardware resource"
- Then click on "OK".
- On the "Resource Selector" window, select the LIC11 that you want to test, then click on "OK".
- On the next "Resource Selector" window, select again the LIC.
- On the "Test and Running Option Selection" the resource desired is displayed with "LIC11 MAT" (Manual Assurance Test) option preselected, click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LIC11.

(Step **054** continues)

054 (continued)

- Unfasten the screws which maintain the cable coming from the LCBB on the rear of the LIC11.
- On the rear of the LIC11 install the wrap plug PN 58G9425.
- Check if the two LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

055

Go to Step 065 on page 2-113.

056

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

057

- Using the "Cancel" key return to the "Diagnostic Control Monitor" window.
- Go to Step 066 on page 2-113.

058

- Replug the cable on the rear of the LIC11.
- Return to the "Resource Selector" window.
- On the "Resource Selector" window, select the LIC11 that you want to test. Then click on "OK".
- On the next "Resource Selector" window, select again the LIC.
- On the "Test and Running Option Selection" the resource desired is displayed with "LIC11 MAT" (Manual Assurance Test) option preselected. Click on "OK".
- An "Information Required" window is displayed asking you to install a wrap plug.
- Locate the LCBB connected to this LIC11.
- **On the LCBB** unfasten the screws which maintain the cable coming from LIC11 and unplug it.
- On the end of the cable install the wrap plug PN 58G9425.
- Check if the two LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

059

Go to Step 063 on page 2-113.

060

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.

(Step 060 continues)

060 (continued)

- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

061

Go to Step 064.

062

Go to Step 071 on page 2-114.

063

- Enter "No" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
- The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Using the "cancel" key return to the "3746-9x0 Menu".
- Go to Step 064.

064

The cable between the LIC11 and the LCBB is faulty. Order a new one, exchange it, and when it is done go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

065

- Enter "No" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
- The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Using the "Cancel" key return to the "Diagnostic Control Monitor" window.
- Go to Step 066.

066

- The LIC11 is defective.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the LIC11 replacement. After the FRU replacement, wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Diagnostic Control Monitor" window, select the "Run diagnostic for a specific hardware resource" option, then click on "OK".
- On the "Resource Selector" window, select the LIC11 that you want to test. Then click on "OK".
- On the next "Resource Selector" window, select again the LIC.
- On the "Test and Running Option Selection" window the resource desired is displayed with "LIC11 MAT" (Manual Assurance Test) option preselected. Click on "OK".
- An "Information Required" window is displayed asking you to install a wrap plug.
- Locate the LIC11.

(Step **066** continues)

066 (continued)

- Unfasten the screws which maintain the cable coming from the LCBB on the rear of the LIC11.
- On the rear of the LIC11 install the wrap plug PN 58G9425.
- Check if the two LEDs are ON.

Are the both LEDs of wrap plug ON?

Yes No

067

Call your support for assistance.

068

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds. Then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

069

- Using the "Cancel" key return to the "3746-9x0 Menu".
- Call your support for assistance

070

- Using the "Cancel" key return to the "3746-9x0 Menu".
 - Go to Step 015 on page 1-127.
-

071

- Plug the cable in its LCBB, and secure it using the screws.
- Return to the "Resource Selector" window.
- On the "Resource Selector" window, select the LCB that you want to test. Then click on "OK".
- On the next "Resource Selector" window, select again the LIC.
- On the "Test and Running Option Selection" the resource desired is displayed.
- Select the "LCBB SAT1" option, click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

072

- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143).
- Select the FRU with the highest fault probability.
- Go to Step 074 on page 2-115.

073

(Step 073 continues)

073 (continued)

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

074

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue.
- Return to the "Resource Selector" window.
- Select the LCB that you want to test and click on "OK".
- On the next "Resource Selector" window, select again the LIC.
- On the "Test and Running Option Selection" the resource desired is displayed.
- Select the "LCBB SAT1" option, click on "OK".
- The "Diagnostic Active Status" window is displayed. Then when the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

075**Is there another FRU in your FRU list?**

Yes No

076

Call your support for assistance.

077

Go to Step 074.

078

- Return to the "Resource Selector" window.
- On the "Resource Selector" window, select the LCB that you want to test. Then click on "OK".
- On the next "Resource Selector" window, select again the LCB.
- On the "Test and Running Option Selection" the resource desired is displayed.
- Select the "LCBB SAT2" option, click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

079

- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143).
- Select the FRU with the highest fault probability.
- Go to Step 081.

080

All diagnostics are error free. The problem can be intermittent. Call your support for assistance.

081

- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue.
- Return to the "Resource Selector" window.

(Step 081 continues)

081 (continued)

- On the "Resource Selector" window, select the LCB that you want to test. Then click on "OK".
- On the next "Resource Selector" window, select again the LCB.
- On the "Test and Running Option Selection" the resource desired is displayed.
- Select the "LCBB SAT2" option, click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

082

Is there another FRU in you FRU list?

Yes No

083

Call your support for assistance.

084

Go to Step 081 on page 2-115.

085

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

MAP 2830: 3746-950 Problem on a LIC12

Symptom Explanation	Conditions That Could Cause This Symptom
Line on LIC12 has a problem.	<ul style="list-style-type: none"> LIC12 CLP

001

Is the 3746-950 set in Offline mode?

Yes No

002

Did you arrive here using a FRU list, or a SRC sequence number?

Yes No

003

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, click on the 3746-950 on which you want to work.
- The "3746-9x0 Menu" window is displayed.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 004

004

- On the "Resource Selector" windows, select the LIC12 for concurrent maintenance. Click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

005

- Check that the customer stopped the traffic on the suspected LIC12.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option. Click on "OK".
- Go to Step 004

006

Go to Step 008.

007

Go to Step 019 on page 2-119

008

(Step **008** continues)

008 (continued)

- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 MAT" option and click on "OK".
- A "Diagnostic Active Status" window is displayed then an "Information Required" window prompts you to install a wrap plug.
- Locate the LIC12 that you want tested on the 3746-950.
- Unfasten the screws which maintain the cable at the rear of LIC12 and unplug the cable from the LIC12.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

009

- Using the "Cancel" key, return to the "Maintenance Options" window, select the "Replace the Resource" option, and click on "OK".
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with Step 013 on page 2-119.

010

- If you have installed the wrap plug according to the type of connection continue with Step 012.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps plugs?

Yes No

011

- Using the "Cancel" key return to the "Maintenance Options" window.
- Go to Step 008 on page 2-117 to run the diagnostic again using the other wrap plug.

012

- Reconnect and secure the cable at the rear of LIC12.
- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "3746-9x0 Menu" window.

All the diagnostics are error free. The problem can be intermittent. Call your support for assistance.

013

(Step **013** continues)

013 (continued)

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
- On the "Confirmation" window, click on "OK".
- Continue with Step 014.

014

- On the "Maintenance Options" window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 MAT" option and click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is Complete an, "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window ask you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

015

Call support for assistance.

016

- If you have installed the wrap plug according to the type of connection continue with Step 018.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps?

Yes No

017

- Using the "Cancel" key return to the "Maintenance Options" window.
- Go to Step 014 to run the diagnostic again using the other wrap plug.

018

- Reconnect and secure the cable at the rear of LIC12.
- Using the "Cancel" key, return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
- Follow the instructions on the "Warning" windows and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "Resource Selection Options for Maintenance" window.
- Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128

019

(Step **019** continues)

019 (continued)

- Double click on the 3746-950 icon.
- The "3746-9x0 Menu" is displayed.
- Click on the "Problem Management" option.
- Double click on the "Perform Offline Diagnostics" option.
- The "Diagnostics" window is displayed, select the "specific Adapter" and the "No" wrap options. Then click on "Start".
- On the next window select the processor which has the suspected LIC12 and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

020

- Exchange the LIC12 go to Chapter 4, "3746-950 FRU Exchange" on page 4-1.
- Return to the "Diagnostics" window.
- The "Diagnostics" window is displayed, select the "specific Adapter" and the "No" wrap options. Then click on "OK".
- On the next window select the processor which has the suspected LIC12, then click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

021

All the diagnostics are error free. The problem can be intermittent. Call your support for assistance.

022

Problem solved. Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

023

Run the LIC12 MAT diagnostic using a wrap plug.

- Using the "Cancel" key return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Specific Diagnostics" option.
- Continue with Step 024.

024

- On the "Diagnostic Control Monitor" window, select the "Run diagnostics for specific hardware resource" option and click on "OK".
- On the next "Resource Selector" windows, select the LIC12 resource and click on "OK".
- On the "Test and Running Option Selection" window the "LIC12 MAT" is preselected click on "OK".
- A "Diagnostic Active Status" window is displayed then an "Information Required" window prompts you to install a wrap plug.
- Locate the LIC12 that you want tested on the 3746-950.
- Unfasten the screws which maintain the cable at the rear of LIC12 and unplug the cable from the LIC12.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

(Step 024 continues)

024 (continued)

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

025

- Using the "Cancel" key, return to the "Diagnostic Control Monitor" window.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with Step 029.

026

- If you have installed the wrap plug according to the type of connection continue with Step 028.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps plugs?

Yes No

027

- Using the "Cancel" key return to the "Diagnostic Control Monitor" window.
- Go to Step 024 on page 2-120 to run the diagnostic again using the other wrap plug.

028

- Reconnect and secure the cable at the rear of LIC12.

All the diagnostics are error free. The problem can be intermittent. Call your support for assistance.

029

- Wait until the 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' messages are displayed on the service processor screen, then continue.
 - Continue with Step 030.
-

030

- On the "Diagnostic Control Monitor" window, select the "Run diagnostics for a specific hardware resource" option and click on "OK".
 - On the next "Resource Selector" windows, select the LIC12 resource and click on "OK".
 - On the "Test and Running Option Selection" window the "LIC12 MAT" is preselected click on "OK".
 - A "Diagnostic Active Status" window is displayed then an "Information Required" window prompts you to install a wrap plug.
 - At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35
- (If you do not know which kind of connection you have, install either one of these wraps).**
- Enter "Yes" on the "Information Required" window and click on "OK".
 - The "Diagnostic Active Status" window is displayed. When the test is Complete an, "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window ask you to remove the wrap plug.
 - Unplug the wrap plug and click on "OK".

(Step 030 continues)

030 (continued)

- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

031

Call support for assistance.

032

- If you have installed the wrap plug according to the type of connection continue with Step 034.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps?

Yes No

033

- Using the "Cancel" key return to the "Diagnostic Control Monitor" window.
- Go to Step 030 on page 2-121 to run the diagnostic again using the other wrap plug.


034

- Reconnect and secure the cable at the rear of LIC12.
 - Using the "Cancel" key, return to the "3746-9x0 Menu" window.
 - Problem solved. Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.
-

MAP 2840: 3746-950 CLP Fallback Problem

Symptom Explanation	Conditions That Could Cause This Symptom
Fallback operation failed on one or two LICs	<ul style="list-style-type: none"> LIC11 or 12 CLP Board

The fallback operation give the LIC control from one CLP to the CLP backup.



You are here because a problem was detected during the fallback operation. One or two LICs of the primary CLP have not been successfully controlled by the backup CLP.

001

Is the problem present on all the LICs previously controlled by the primary CLP?

Yes No

002

Suspect a problem on the LIC which failed to fallback. Exchange it, go to "3746-950 Maintenance Using a FRU list" on page 1-28

003

Was there only one LIC controlled by the primary CLP?

Yes No

004

Suspect a problem on the CLP which failed to fallback. Exchange it, go to "3746-950 Maintenance Using a FRU list" on page 1-28

005

Suspect a problem on the LIC which failed to fallback. Exchange it, go to "3746-950 Maintenance Using a FRU list" on page 1-28

MAP 2850: 3746-950 Activate/Deactivate Line Problems or Line Errors on CLP

001

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the 3746-950 icon.
- On the "3746-9x0 Menu", click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".
- Go to Step 002.

002

Is the problem reported on LIC12 line?

Yes No

003

Go to Step 013 on page 2-125.

004

- On the "Resource Selector" window, select the LIC12 for concurrent maintenance, then click on "OK".
- On the next "Resource Selector" window, click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

005

- Check that the customer stopped traffic on the suspected LIC12.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 004

006

- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 SAT" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

007

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

008

- Using the "Cancel" key return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 MAT" option and click on "OK".
- A "Diagnostic Active Status" window is displayed then an "Information Required" window prompts you to install a wrap plug.
- Locate the LIC12 that you want tested on the 3746-950.
- Unfasten the screws which maintain the cable at the rear of LIC12 and unplug the cable from the LIC12.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window asks you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

009

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

010

- If you have installed the wrap plug according to the type of connection continue with Step 012.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps plugs?

Yes No

011

Go to Step 008 to run the diagnostic again using the other wrap plug.

012

- Reconnect and secure the cable at the rear of LIC12.
- Go to Step 019 on page 2-126.

013

- On the "Resource Selector" window, select the LIC11 (address range) associated with the ARC that you want to test and click on "OK".
- On the following "Resource Selector" window, select the "ARCs" corresponding to the address range.
- On the two next windows, select the suspected ARC and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

(Step **013** continues)

013 (continued)

Is the "Maintenance Options" window displayed?

Yes No

014

- Check that the customer stopped traffic on the suspected ARC.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 013 on page 2-125

015

- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC SAT" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

016

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

017

- Click on "Cancel" to return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC MAT" and click on "OK".
- When the "Information Required" window is displayed, disconnect the ARC cable from the DTE, DCE, or cable and install the wrap plug according to the ARC type (see "Shipping Group Tools" on page A-2).
- Enter "Yes" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window prompts you to remove the wrap from the ARC cable, and reconnect the ARC previously removed. Click on "OK" when it is done.
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

018

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

019

- Click on "Cancel" to return to the "Maintenance Options" window.
- (Step 019 continues)

019 (continued)

- On this window, select the "Initialize Resource" option and click on "OK".
 - On the "Warning window" click on "OK".
 - Select the "Remove the Resource from the Concurrent Mode" option and click on "OK".
 - On the "Resource Selector" window, click on "Cancel".
 - The "Resource Selection Options for Maintenance" window is displayed. Click on "Cancel".
 - Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128 and perform the procedure.
 - If the problem persists, call your support for assistance.
-

MAP 2860: 3746-950 All the Lines of LCBE Have Problem

Symptom Explanation	Conditions That Could Cause This Symptom
All the lines installed on the same LCBE have problem	<ul style="list-style-type: none"> • LCEE • LCPE

001**Is the 3746-950 set in Offline mode?**

Yes No

002**Did you arrive here using a FRU list, or a SRC sequence number?**

Yes No

003

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, click on the 3746-950 on which you want to work.
- The "3746-9x0 Menu" window is displayed.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 004.

004

- Check that the customer stopped the traffic on the lines of the suspected LCBE and associated LCBB.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- On the "Resource Selector" window, select the LCBB associated with the suspected LCBE for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

005

- Check that the customer stopped the traffic on the lines of the suspected LCBE and associated LCBB.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window select the "Via the active CDF-E" option and click on "OK".
- Go to Step 004

006

- Return to the "Maintenance Options" window.
- (Step **006** continues)

006 (continued)

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed, with the number of errors.

Is the diagnostic error-free ?

Yes No

007

Go to Step 010.

008

Go to Step 016 on page 2-130.

009

Go to Step 025 on page 2-131.

010

- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143)
- Go to Step 011.

011

- If you are here for the first time select the FRU with the highest fault probability. Otherwise select the next FRU not already tested.
- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with the next bullet.
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" then click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is done an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed, with the number of errors.

Is the diagnostic error-free ?

Yes No

012**Is there another FRU to exchange?**

Yes No

013

Call your support for assistance.

014(Step **014** continues)

014 (continued)

Go to Step 011 on page 2-129.

015

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

016

- Return to the "Maintenance Options" window.
- On the window displayed select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

017

Go to Step 019.

018

All the diagnostics are error free. The problem can be intermittent. Call your support for assistance.

019

- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143)
 - Go to Step 020.
-

020

- If you are here for the first time select the FRU with the highest fault probability. Otherwise select the next FRU not already tested.
- Using the "Cancel" key, return to the "Maintenance Options" window and select the "Replace the Resource" option.
- A "Confirmation" window is displayed.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with the next bullet.
- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the Resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" then click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed, with the number of errors.

Is the diagnostic error-free ?

Yes No

021

(Step **021** continues)

021 (continued)

Is there another FRU to exchange?

Yes No

022

Call your support for assistance.

023

Go to Step 020 on page 2-130.

024

Go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

025

- Double click on the 3746-950 icon.
- The "3746-9x0 Menu" is displayed.
- Click on the "Problem Management" option.
- Double click on the "Perform Offline Diagnostics" option.
- The "Diagnostics" window is displayed, select the "specific Adapter" and the "No" wrap options. Then click on "OK".
- On the next window select the CLP which has the LIC11 with the suspected LCBE, then click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

026

- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143)
- Go to Step 028.

027

All the diagnostics are error free. The problem can be intermittent. Call your support for assistance.

028

- If you are here for the first time select the FRU with the highest fault probability. Otherwise select the next FRU not already tested.
- Go to Chapter 4, "3746-950 FRU Exchange" on page 4-1 for the FRU replacement. After the FRU replacement, continue with the next bullet.
- Wait until 'alarm xxxx FRU unplugged', and 'alarm xxxx FRU plugged' are displayed on the service processor screen (if you have changed CLP, or LIC11) then continue.
- Return to the "Diagnostics" window.
- The "Diagnostics" window is displayed, select the "specific Adapter" and the "No" wrap options. Then click on "OK".
- On the next window select the CLP which has the LIC11 with the LCBE suspected and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

(Step **028** continues)

3746-950 MAPs

028 (continued)

Is the diagnostic error-free?

Yes **No**

029

Is there another FRU to exchange?

Yes **No**

030

Call your support for assistance.

031

Go to Step 028 on page 2-131.

032

Go to "MAP: 3746-950 Ending Procedure In Offline Mode" on page 1-126.

Service Processor MAPs

MAP 2950: LAN Problem on LAN Attached to the Service Processor

Symptom Explanation	Conditions That Could Cause This Symptom
Unable to activate or deactivate a ring Errors occur while ring is running No connection with the service processor	<ul style="list-style-type: none"> Service processor or network node processor LAN adapter Ring Service processor access unit 3746-950 TIC3 or CBSP




Figure 2-11. LAN attached to the Service Processor

Notes:

1. The network node processor is an optional feature which is present only when APPN is installed. A backup network node processor can also be present. Until four network node processor can be installed on the same LAN.
2. The LAN can be made of two service processor access units (8228).
3. Only 37XX units can be connected on the LAN when APPN is installed.

001

You are here because there is a problem on the LAN attached to the service processor. The following links can be impacted (one or more):

- 3746-950/MOSS-E link
- 3746-950/APPN link (if present)
- MOSS-E/APPN link (if present)

Is the problem permanent?

Yes No

002

(Step **002** continues)

Service Processor MAPs

002 (continued)

Go to Step 017 on page 2-135.

003

Does the problem appear on all units connected to the service processor?

Yes No

004

Is the problem only on a 3746-950

Yes No

005

On the following list, select the unit on which you have a problem:

The problem is on

3745 or 3746-900

Action

Restart problem determination using one of the following manuals:

- The *IBM 3745 Communication Controller Models 130 to 17A, Maintenance Information Procedures*, SY33-2070 manual for 3745 model 130 to 17A or
- The *IBM 3745 Communication Controller Models 210 to 61A, Maintenance Information Procedures*, SY33-2054 manual for 3745 model 210 to 61A or
- The *IBM 3746 Expansion Unit Model 900*, SY33-2116 manual for 3746-900.

Network Node Processor

Perform problem determination on the appropriate network node processor using the *Network Node Processor Installation and Maintenance* manual.

006

Go to Step 012 on page 2-135.

007

Is the service processor powered ON ?

Yes No

008

Power ON the service processor.

Is the service processor powered On?

Yes No

009

Go to the appropriate *Service Processor Installation and Maintenance* manual, chapter "Service Processor Problem Determination".

010

Problem solved.

011

- Check that the service processor LAN cables are correctly connected at the rear of the service processor.
- Check that the LAN cables are correctly connected to the service processor access unit.
- If everything is correct go to chapter "Service Processor Problem Determination" in the corresponding *Service Processor Installation and Maintenance* manual.

012

On the 3746-950 control panel check the status of the "Service Processor Not Accessible" digit.

Is the "Service Processor Not Accessible" digit present?

Yes No

013

Is there a panel code displayed on the 3746-950 control panel?

Yes No

014

You have a 3746-950/APPN link problem, go to "MAP 2960: 3746-950/APPN Link Problem" on page 2-138.

015

Go to "3746-950 Control Panel Codes" on page 1-15.

016

Go to "MAP 2750: 3746-950 Permanent Service Processor Link Problem" on page 2-84.

017

You are here because you have transient errors on the service processor LAN .

Does the problem appear on all units connected to the service processor?

Yes No

018

Go to Step 020.

019

- Check that the service processor LAN cable is correctly connected at the rear of the service processor.
 - Check that all the LAN cables are correctly connected in the service processor access unit.
 - Do the problem determination on the ring using *Token-Ring Network, Problem Determination Guide* SX27-3710.
 - If you do not identify the problem call your support.
-

020

Is the problem only on a 3746-950?

Yes No

021

The problem is on:

3745 or 3746-900

Action

Restart problem determination using one of the following manuals:

- The *IBM 3745 Communication Controller Models 130 to 17A, Maintenance Information Procedures*, SY33-2070 manual for 3745 model 130 to 17A or for 3746-900 attached
- The *IBM 3745 Communication Controller Models 210 to 61A, Maintenance Information Procedures*, SY33-2054 manual for 3745 model 210 to 61A or for 3746-900 attached.
- The *IBM 3746 Expansion Unit Model 900*, SY33-2116 manual for 3746-900.

Network Node Processor

Perform problem determination on the network node processor using the appropriate *Network Node Processor Installation and Maintenance* manual.

022

Go to Step 023.

023

Using the service processor check the errors logged.

- Go to the service processor console and if your are not already logged ON, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the service processor icon.
- On the "Service Processor Menu" Click on the "Problem Management" option.
- Double click on the "Display Alarms" option.
- The "Display Alarms" window is displayed.
- On this window, search if you have alarm matching with one of the following list:
 - 0611
 - 0614
 - 061A
 - 061F
 - 0621
 - 062A
 - 062D
 - 062E
 - 062F
 - 06A1
 - 06A4
 - 06AA
 - 06AF
 - 06B1
 - 06BA
 - 06BD
 - 06BE
 - 06BF
 - 06CD

Is there any alarm matching?

Yes No

024

- Check that the service processor LAN cables are correctly connected at the rear of the service processor
- Check that the LAN cables are correctly connected to the service processor access unit.
- If that not solve the problem do the problem determination on the ring using *Token-Ring Network, Problem Determination Guide SX27-3710*.
- If you do not identify the problem call your support.

025

Select the alarm in the following table and perform the action required.

Alarm	Action
0611 0614 061A 062D	Suspect the MOSS-E service processor adapter card. To exchange the MOSS-E service processor adapter card, see chapter "Service Processor FRU Exchange" in the corresponding <i>Service Processor Installation and Maintenance</i> manual.
061F 0621 062A 062E 062F	<ul style="list-style-type: none"> • Check that the service processor LAN cables are correctly connected at the rear of the service processor and in the service processor access unit. If that not solve the problem continue with the next bullet. • Suspect the MOSS-E service processor adapter card. To exchange the MOSS-E service processor adapter card, see chapter "Service Processor FRU Exchange" in the corresponding <i>Service Processor Installation and Maintenance</i> manual.
06A1	Suspect the network node processor LAN adapter card. To exchange the LAN network node processor adapter card, see the <i>Network Node Processor Installation and Maintenance</i> manual.
06A4	Link lost between the network node processor and the 3746-900. Go to "MAP 2960: 3746-950/APPN Link Problem" on page 2-138.
06AA 06BD	Suspect the network node processor LAN adapter card. To exchange the LAN network node processor adapter card, see the <i>Network Node Processor Installation and Maintenance</i> manual.
06AF 06B1 06BA 06BE 06BF	<ul style="list-style-type: none"> • Check that the network node processor LAN cables are correctly connected at the rear of the network node processor and in the service processor access unit. If that not solve the problem continue with the next bullet. • Suspect the network node processor LAN adapter card. To exchange the LAN network node processor adapter card see the <i>Network Node Processor Installation and Maintenance</i> manual.
06CD	Microcode update incomplete. There is a microcode discrepancy between the network node processor and the service processor.

MAP 2960: 3746-950/APPN Link Problem

Symptom Explanation	Conditions That Could Cause This Symptom
Unable to activate or deactivate a port Errors occur while ring is running No session between the APPN and the 3746-950	<ul style="list-style-type: none"> • Network node processor or network node processor LAN adapter • Ring • Service processor access unit • APPN




Figure 2-12. LAN attached to the Service Processor

Notes:

1. The network node processor is an optional feature which is present only when APPN is installed. A backup network node processor can also be present. Until four network node processor can be installed on the same LAN.
2. The LAN can be made of two service processor access units (8228).
3. Only 37XX units can be connected on the LAN when APPN is installed.

001

You are here because you suspect a link problem between the APPN and the 3746-950.

Using the service processor check the errors logged.

- Go to the service processor console and if your are not already logged ON, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the service processor icon.
- On the "Service Processor Menu" Click on the "Problem Management" option.
- Double click on the "Display Alarms" option.
- The "Display Alarms" window is displayed.
- On this window, search if you have alarm matching with one of the following list:
 - **06A1**
 - **06A4**
 - **06AA**
 - **06AF**

(Step **001** continues)

001 (continued)

- 06B1
- 06BA
- 06BD
- 06BE
- 06BF

Is there any alarm matching?

Yes No

002

Perform problem determination on the network node processor using the appropriate *Network Node Processor Installation and Maintenance* manual.

003

Select the alarm in the following table and perform the action required.

Alarm	Action
06A1	Suspect the network node processor LAN adapter card. To exchange the LAN network node processor adapter card, see the appropriate <i>Network Node Processor Installation and Maintenance</i> manual.
06A4	Link lost between the network node processor and the 3746-900. Suspect the network node processor LAN adapter card. To exchange the LAN network node processor adapter card, see the appropriate <i>Network Node Processor Installation and Maintenance</i> manual.
06AA 06BD	Suspect the network node processor LAN adapter card. To exchange the LAN network node processor adapter card, see the appropriate <i>Network Node Processor Installation and Maintenance</i> manual.
06AF 06B1 06BA 06BE 06BF	<ul style="list-style-type: none"> • Check that the network node processor LAN cables are correctly connected at the rear of the network node processor and in the service processor access unit. If that not solve the problem continue with the next bullet. • Suspect the network node processor LAN adapter card. To exchange the LAN network node processor adapter card, see the appropriate <i>Network Node Processor Installation and Maintenance</i> manual.

Chapter 3. How to Run Diagnostics

3746-950 Diagnostic Description

The 3746-950 diagnostics are composed of:

- **The basic assurance tests (BATs)** which are of two types:
 - **BATs** which are located in the EEPROM of each processor
 - **Loaded BATs** which are on the service processor disk.

They test the common part of the processor (microprocessor, bus, storage, DSI and switch bus adapter).

- **The specific assurance tests (SATs)** which are located on the service processor disk and loaded as required in the processor to test TIC3, ESCC, CS, SAS Bus and interfaces.

- **The manual assurance tests (MATs)** which are located on the service processor disk and loaded as required in the processor to test part of the 3746-950. These diagnostics prompt the CE to perform specific operations such as, plug, unplug, install wrap, and so on. They run under the control of the DCM.

Both BATs and SATs use the self-test capabilities of the 3746-950 modules.

They report the errors via the SRCs on the service processor console when the link to the service processor is operational. BATs of the CBSP report errors on the 3746-950 panel when the link to the service processor is not operational.

3746-950 Diagnostics Invocation

Table 3-1 (Page 1 of 3). 3746 Model 950 Diagnostics Available				
Area tested	Diagnostics Available	Invoked Function	From	Results
ARC	SATs	Selective resource Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (note 2)
	MATs	Selective resource	Service Processor (Note 4)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
CBSP	BATs and Loaded BATs (note 1)	Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		CBSA IML with diags IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (note 2)
CLP	BATs and Loaded BATs (note 1) SAT1 / SAT2 (note 5)	Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (note 2)
CS	Assurance tests	Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	
ESCC	SATs	Selective resource Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (note 2)
	MATs	Selective resource	Service Processor (Note 4)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
ESCP	BATs and Loaded BATs (Note 1)	Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	
OP Panel	CBSP BATs	Specific adapter (CBSA) Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		CBSA IML with diags IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)
	3746-950 Panel test	Panel test	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)

Table 3-1 (Page 2 of 3). 3746 Model 950 Diagnostics Available

Area tested	Diagnostics Available	Invoked Function	From	Results
LCPB	SATs	Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)
LCPB + LCPE + ARC Interface	SATs	Selective resource Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)
LIC11	CLP SAT2	Selective resource Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)
	MATs	Selective resource	Service Processor (Note 4)	SRC Error displayed on 3746-950 control panel or alarm on service processor
LIC12	SATs	Selective resource Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)
	MATs	Selective resource	Service Processor (Note 4)	SRC Error displayed on 3746-950 control panel or alarm on service processor
MAE (SIE, SAC, System Card)	Firmware	MAE Selective IML Whole 3746-950	Service Processor (Note 6)	MAE errors do no generate a SRC error displayed on 3746-950 control panel
		IML with diags	3746-950 control panel	MAE errors do not generate a SRC error displayed on 3746-950 control panel
	Firmware Operational Diagnostics	Select Device to test Diags	Service Processor (Note 7)	Error displayed on service Processor
SL	Assurance tests	Whole 3746-950 Specific adapter	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	
	SATs MATs	Selective resource	Service Processor (Note 4)	

Service Processor MAPs

Table 3-1 (Page 3 of 3). 3746 Model 950 Diagnostics Available

Area tested	Diagnostics Available	Invoked Function	From	Results
SPS	CBSP BATs	Specific adapter (CBSA) Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		CBSA IML with diags IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)
TIC3	SATs	Selective resource Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (note 2)
	MATs	Selective resource	Service Processor (Note 4)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
TRP	BATs and Loaded BATs (Note 1)	Specific adapter Whole 3746-950	Service Processor (Note 3)	SRC Error displayed on 3746-950 control panel or alarm on Service Processor
		IML with diags	3746-950 control panel	
3746-950 link to service processor	Connection detection	Service Processor Link Restart CBSA IML without diags CBSA IML with diags IML without diags IML with diags	3746-950 control panel	SRC Error displayed on 3746-950 control panel (Note 2)

Notes:

- These tests cannot be run separately.
- If no SRC is displayed on the 3746-950 front panel, go to "MAP 2620: 3746-950 Control Panel Problem" on page 2-36.
- These diagnostics are invoked from the service processor console by selecting:
 - Either 'Perform Offline diagnostics' (off-line mode) for:
 - Specific adapter
 - Whole 3746-950
 - Or 'Perform maintenance' (concurrent mode) for:
 - Specific adapter
 - Selective resource
 in the 'Problem management' menu.
- These diagnostics are invoked from the service processor console by selecting either "Perform Maintenance" (concurrent mode) or "Perform specific diagnostics" (Offline mode).
- These diagnostics are invoked from the service processor console by selecting either "Perform Offline Diagnostics" or "Perform specific diagnostics" (Offline mode).
- These diagnostics are invoked from the service processor console only when the MAE is connected to the 3746-950 via an SIE/SAC cable. Otherwise these diagnostics are not available.
 - For the whole 3746-950 select successively:
 - 'Problem Management'
 - 'Perform Offline diagnostics' (off-line mode)
 - 'Whole 3746-950'
 - For MAE Selective IML select successively:
 - 'Multiaccess Enclosure (MAE) Management'

- 'MAE Selective IML'
7. For more detail about MAE area tested and diagnostic invocation refer to the *Multiaccess Enclosure Installation and Maintenance*, manual manual.

IML with Diags

- Reset CBSP
- BATs test the CBSP, SPS, OP Panel and TIC3 and the connection to the service processor.
- IML the CBSP from the service processor
- Run the loaded BATs
- Load the CBSP environment from the service processor
- The CBSP resets the CS and the other processors via the SPS card.
- From the service processor, load and run the SATs on the TIC3 of the CBSP which is not connected to the service processor.
- The VPD of the CS is collected via the service logic bus.
- Assurance tests test the CS and the SAS bus.
- BATS are run on all other processors, then initialized.
- When processors are initialized, they send their VPD via the CS.

- The operational code is loaded in each processor. Then the VPD of the attached coupler is sent to the CBSP and resource status table (RST) and the configuration data file extended (CDFE) is updated.
- SATs are loaded and run on couplers
- Operational code is loaded in each coupler
- IML ends.

Action of IML with Diags on MAE

When the MAE is connected via a SIE/SAC cable to a 3746-950 the following happens:

- Via the SPS and SIE/SAC link the MAE is reset.
- MAE firmware tests the MAE subsystem card.
- MAE operational code is loaded.
- SAC diagnostics are run.
- A frame is exchanged from MAE to 3746-950 Switch.




Figure 3-1. Parts of 3746-950 Tested by IML With Diagnostics or Whole 3746-950 Offline Diagnostics

Service Processor MAPs




Figure 3-2. Parts of 3746-950 Tested by CLP SATs




Figure 3-3. Parts of 3746-950 Tested by LIC11 MAT




Figure 3-4. Parts of 3746-950 Tested by LIC12 SAT




Figure 3-5. Parts of 3746-950 Tested by LIC12 MAT




Figure 3-6. Parts of 3746-950 Tested by LCBB SAT1

Service Processor MAPs




Figure 3-7. Parts of 3746-950 Tested by LCBB SAT2




Figure 3-8. Parts of 3746-950 Tested by ARC SAT and ARC MAT




Figure 3-9. Parts of 3746-950 and MAE Tested by MAE Selective IML

CBSA IML With Diagnostics:

- Reset CBSP.
- BATs test the CBSP, SPS, OP Panel and TIC3 and the connection to the service processor.
- IML the CPSP from the service processor
- Run the loaded BATs
- Load the CBSP environment from the service processor
- From the service processor load and run the SATs on the TIC3 of the CBSP which is not connected to the service processor.

The 3746-950 is now in standby.

Other Adapter IML With Diagnostics:

- Reset the adapter.
- BATS are run on the processor of the selected adapter and initialized.
- When the processor is initialized, it sends its VPD via the CS.
- The operational code is loaded in the processor. Then the VPD of the attached coupler is sent to the CBSP and resource status table (RST), and the configuration data file extended (CDF-E) is updated.
- SATs are loaded and run on couplers.
- Operational code is loaded in each coupler.
- IML ends.

3746-950 Concurrent Maintenance

The 3746-950 allows concurrent maintenance. Concurrent maintenance lets you isolate a resource from a system while the system is operating, without impacting the operations of the other resources. After the resource has been isolated from the rest of the system, it can be tested and replaced if necessary. When the problem is corrected the resource is given back to the system. Concurrent maintenance is initiated by the operator and has two aspects: concurrent diagnostics and concurrent repair.

Concurrent Diagnostics

Product characteristics which allow you to run concurrent diagnostics are as follow:

- The distributed structure of the processors and couplers with the capability of a selective re-IML or selective resource.
- The service bus circulating from the CBSA to the processors, and the CS which allows you to collect test results.

Concurrent Repair

Concurrent repair is made possible by the hot-pluggable capability of 3746-950 FRUs: processors, couplers, and the SPS. The hot-pluggability is made possible by the following characteristics:

- The cassette pins are of variable length; the longer pins being used for the ground.
- The vendor technology logic (VTL) layer as a protection between the CMOS-2 and the external signals.
- The ability of the 'coupler presence' signal to de-gate the bus drivers on the processor and to control the coupler power via the processor microcode.
- In addition, the state of any 3746-950 resource reflected in the CDF-E includes the 'present' or 'not present' state. When the resource is present the status 'available' or 'unavailable' is given. The resource is set to

not available when it is in concurrent maintenance.

Concurrent Mode Activation Procedure

The procedure to put a processor in 'concurrent' mode for maintenance is given here as an example. A similar procedure applies for the other FRUs:

- The lines controlled by the processor are deactivated from the host.
- From the service processor, the 'concurrent' mode is entered for the processor. The monitoring of the processor via the 'sanity frames' is stopped. At the same time, the processor is checked for no active lines (a processor is only accepted in 'concurrent' if no lines are active).

When a processor is set to 'concurrent' mode, all the associated underlying resources (example: couplers) are also set to 'concurrent' mode, except if the processor has a backup (since the backup processor continues to work with these resources).

- Unplug the cassette processor.

The processor- presence monitoring task in the CBSP detects that the processor is unplugged and an alarm is displayed on the service processor console.

- Plug the new processor in.

The processor-presence monitoring task in CBSP detects the processor being plugged in. The processor VPDs are read and an alarm is displayed. The processor state in the CDF-E is set to 'concurrent' mode.

- According to the type of processor, the diagnostics for that processor must be run.
- The resource is initialized (IMLed).
- From the service processor console, the command, quit 'concurrent' mode, is given for the processor.
- The lines are reactivated from the host.

How to Run the 3746-950 Control Panel Test

This test can be run without stopping the customer's application.

It is not a sequential test and can be cancelled at any time by pressing the 'Exit' key.

Notes:

1. Any inactivity lasting about 60 seconds during the control panel test results in the test being automatically cancelled. The panel returns to operational mode.
2. During this test the control panel's audible alarm sounds for each action.

'special character': Can be described as when every possible segment of the window is lit.



1. Set power to local:
 - a. Press the 'Power Control' key until '3' is displayed in the power control window.
 - b. Press the 'Validate' key.
If the above action cannot be performed, go to step 11.
2. Set service mode to maintenance.
 - a. Press the 'Service mode' key until the number '1' is displayed in the service window.
 - b. Press the 'Validate' key.
If the above action cannot be performed go to step 11.
3. Set 'Function' to panel test:
 - a. Press the 'Function' key until '5' is displayed in the function window.
 - b. Press the 'Validate' key.
If the above action cannot be performed go to step 11.

On the display, All 10 'special character' is displayed.

If the pattern is not identical for each of the 10 special characters, go to step 11.

Note: If the panel test code detects an error the SRC is stacked but not displayed on the

panel. Therefore, if the link with the service processor is operational, the SRC will be sent to the MOSS-E.

4. Press the 'Function' key.

On the display, the 'Function' window 'special character' will be displayed. Repetitive action will scroll through the 'Function' and 'Code' windows sequentially and wrap around.

If this does not occur, go to step 11.

5. Press the 'Service mode' key.

On the display, the 'Service mode' window 'special character' is displayed. Repetitive action will scroll through the 'Service mode' and 'Power Control' windows and wrap around.

If this does not occur, go to step 11.

6. Press the 'Power Control' key.

On the display, the 'Service processor not accessible' window 'special character' is displayed. Repetitive action will scroll through the 'All channels disabled' 'Service processor not accessible' windows sequentially and wrap around.

If this does not occur, go to step 11.

7. Press the 'Start' key.

On the display, '8' is displayed in the 'Function' window, and the ready or standby LEDs will light if not already ON. (ready and standby LEDs can not be ON at the same time).

If this does not occur, go to step 11.

8. Press the 'Standby' key.

The display is completely blank.

If this does not occur, go to step 11.

9. Press the 'Exit' key.

On the display, the 'Power Control' (3) and 'Service Mode' (1) are displayed indicating that the test is complete, and that the control panel has returned to operational mode.

If this does not occur, go to step 11.

10. **The control panel test is complete. No error has been detected. Ignore step 11**

11. Go to "MAP 2620: 3746-950 Control Panel Problem" on page 2-36.

How to run the 3746-950 Service Processor Link Restart

1. Set the 'service mode' to 'maintenance':
 - a. Press the 'Service mode' key until the number '1' is displayed in the service window.
 - b. Press the 'validate' key.
2. Start the test as follows:
 - a. Press the 'Function' key until the number '6' is displayed in the function window.
 - b. Press the 'validate' key.
3. Observe the display and note the value of the SRC displayed:
 - a. **05B0B0FD**: Request sent
 - b. **05B0B0FE**: Request rejected (TIC3 resource already active, operator error)
 - c. **05B0B0FF**: Request not received (time out, CBSP failure).
4. On the display, note the value of the 'Service processor not accessible' window.
The value can be:
 - ' ': Console accessible, the link is established
 - '*': Physical link not active
 - '\$': Disconnected at SSA level
 - 'A': 'OK' frame received on 'Hello' frame
 - 'B': Permanent beaconing
 - 'C': Connected at DLC level
 - 'D': Disconnected
 - 'E': Internal error
 - 'F': 'Hello' frame sent
 - 'G': Ring failure
 - 'H': Hardware error
 - 'I': Inserted
 - 'L': Lobe wire fault or Lobe media fault
 - 'N': Inserting on LAN or retrying insertion
 - 'R': Link reset
 - 'T': Time out retries exhausted
 - 'U': TIC3 unplugged.
 - '5': Congestion of CBSP during general IML (transient problem)
5. If the 'Service processor not accessible' window is not blank, note the control panel code displayed on the 3746-950 front panel (if one appears). Then go to "3746-950 Control Panel Codes" on page 1-15 and follow the procedure, or go to "MAP 2750: 3746-950 Permanent Service Processor Link Problem" on page 2-84
6. Press the 'exit' key to quit this function.

MAP 2970: How to run 3746-950 Diagnostic in Concurrent Mode

Only diagnostic on **processor, coupler, LICxx, LCPx, LCEx, or ARCxx** can be run in concurrent mode.

Note

When an multiaccess enclosure (MAE) is connected to the 3746-950 via an SIE/SAC cable an MAE selective IML can be performed in concurrent mode using the procedure described in "MAP 3000: How to Run the Selective IML on the Multiaccess Enclosure" on page 3-47.

Important

There is no diagnostic for the TIC3 of the CBSP in position 07N-A1-F1, and for SIE.

001

- You should be logged ON on the service processor console. If not, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- On the "MOSS-E View" window, double click on the 3746-950 icon.
- On the "3746-9x0 Menu", click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window select the "Via the active CDF-E" and click on "OK".
- Go to Step 002.

002

In the following table, find the FRU you want to test and go to the step indicated.

Select FRU	Go to
ARC	Step 052 on page 3-24
CBSP/CBSP2/CBSP3	Step 003
CLP/CLP3	Step 074 on page 3-27
ESCC/ESCC2	Step 007 on page 3-17
ESCP/ESCP2/ESCP3	Step 021 on page 3-19
LCEB	Step 117 on page 3-36
LCEE	Step 117 on page 3-36
LCPB	Step 117 on page 3-36
LCPE	Step 117 on page 3-36
LIC11	Step 092 on page 3-32
LIC12	Step 108 on page 3-35
TIC3	Step 034 on page 3-21
TRP/TRP2/TRP3	Step 042 on page 3-22

003

- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- In order to set the CBSP to concurrent mode, make sure there is no traffic on the CBSP. So stop the APPN.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Network Node Processor (NNP) Management" option.
 - On the following "Network Node Processor (NNP) Management" window, double click on the "Manage Control Points on NNPs" option.

(Step 003 continues)

003 (continued)

- On the "Manage Control Points (CP) on NNP" window, in the "Options" select the CP to stop (CP/NNP-A or CP/NNP-B), then click on the "Stop CP" option.
- Click on "OK", then continue with Step 004.

004

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- On the three following "Resource Selector" windows, select the CBSP and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the "CBSP" and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

005

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

006

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

007

- On the next three "Resource Selector" windows, select the ESCC and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window displayed?

Yes No

008

Go to Step 010

009

Go to Step 015 on page 3-18

010

- Check that the customer stopped the traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Perform the following steps to disable the ESCC:
 - Return to the "3746-9x0 Menu".
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".

(Step **010** continues)

010 (continued)

- The "ESCON Configuration Lines" window is displayed.
- Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
- The "ESCC Status Management" window is displayed.
- Select the "disable" option.
- Click on the "Options" (in the action bar). Then select the "Send request and save" option.
- A "confirmation" window is displayed. Click on "OK".
- A "Warning" window informs you that the ESCP configuration is saved. Click on "OK".
- Click on "Refresh"(in the action bar). Then select "Permanent Refresh" (no further action is possible from this screen).
- When the "disable" is complete the "ESCC x Status" line should display: DISABLED. It should **not** display: ENABLED.

Is the "ESCC x Status" line displaying: ENABLED?

Yes No

011

- Click on "Refresh"(in the action bar). Then select "Stop permanent refresh".
- Click on the "Options" (in the action bar). Then select the "Return" option.
- On the "ESCON Configuration lines" window, click on "Options" and on "Exit".
- On the "Confirmation" window click on "OK".
- On the "ESCP Management Resource Selector" window, click on "Cancel".
- The "3746-Menu" is displayed.
- Select the "problem Management" option.
- Double click on the "Perform maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".
- On the next three "Resource Selector" windows, select the ESCC and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

012

Call you support for assistance.

013

Go to Step 015

014

- The state of the ESCC or ESCP does not allow you to set the ESCC in concurrent mode to test it.
- Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for ESCC or ESCP replacement.

015

Do you want to run MAT diagnostics (Diagnostics with WRAP plug)?

Yes No

016

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed with "ESCC SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Go to Step 018 on page 3-19.

017

- Select the "Perform Diagnostics on the resource" option and click on "OK".
 - The "Test and Running Option Selection" window is displayed with "ESCC SAT" preselected.
 - Select the "ESCC MAT" option and click on "OK".
 - When the "Information Required" window is displayed, remove the optical fiber cable and install the wrap plug PN 5605670. Refer to "Exchange an ESCC/ESCC2" on page 4-31 to unplug the fiber optic cable.
 - Enter "YES" and click on "OK".
 - The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
 - On the ESCC coupler remove the wrap plug that you have installed and reconnect the fiber optic cable previously removed.
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 018.
-

018**Is the diagnostic error-free ?****Yes No****019**

Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for ESCC replacement.

020

Go to Step 047 on page 3-23.

021

- On the next three "Resource Selector" windows, select the ESCP and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?**Yes No****022**

Go to Step 024.

023

Go to Step 031 on page 3-20.

024

- Check that the customer stopped the traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Perform the following steps to disable the ESCC:
 - Return to the "3746-9x0 Menu".
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
 - The "ESCON Configuration Lines" window is displayed.
 - Click on the "Options" (in the action bar), then select the "Manage ESCC Status" option.
 - The "ESCC Status Management" window is displayed.
 - Select the "disable" option.
 - Click on the "Options" (in the action bar). Then select the "Send request and save" option.

(Step **024** continues)

024 (continued)

- A "confirmation" window is displayed. Click on "OK".
- A "Warning" window informs you that the ESCP configuration is saved, click on "OK".
- Click on "Refresh"(in the action bar). Then select "Permanent Refresh" (no further action is possible from this screen).
- When the "disable" is complete the "ESCC x Status" line should display: DISABLED. It should **not** display: ENABLED.

Is the "ESCC x Status" line displaying: ENABLED?

Yes No

025

- Click on "Refresh"(in the action bar). Then select "Stop permanent refresh".
- Click on the "Options" (in the action bar). Then select the "Return" option.
- On the "ESCON Configuration lines" window, click on "Options" and on "Exit".
- On the "Confirmation" window, click on "OK".
- On the "ESCP Management Resource Selector" window, click on "Cancel".
- The "3746-Menu" is displayed.
- Select the "problem Management" option.
- Double click on the "Perform maintenance" option.
- On the "Resource selection options for maintenance" window, select the "Via the active CDF-E" option, then click on "OK".
- On the next three "Resource Selector" windows, select the ESCP and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

026

Call your support for assistance.

027

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

028

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

029

Go to Step 047 on page 3-23.

030

- The state of the ESCC or ESCP does not allow you to set the ESCP in concurrent mode to test it.
- Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for ESCC or ESCP replacement.

031

(Step 031 continues)

031 (continued)

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

032

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

033

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

034

- On the "Resource Selector" window, select the coupler for concurrent maintenance and click on "OK".
- On the next two "Resource Selector" windows, select the coupler and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

035

- Check that the customer stopped the traffic on the suspected coupler.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".
- Go to Step 034.

036**Do you want to run MAT diagnostics (Diagnostics with WRAP plug)?**

Yes No

037

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed with "TIC3 SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Go to Step 039 on page 3-22

038

- Select the "Perform Diagnostics on the resource" option and click on "OK".

(Step **038** continues)

038 (continued)

- The "Test and Running Option Selection" window is displayed with "TIC3 SAT" preselected.
 - Select the "TIC3 MAT" option and click on "OK".
 - When the "Information Required" window is displayed, remove the LAN cable on the suspected TIC3 and install the wrap plug PN 6165899.
 - Enter "W" and click on "OK".
 - The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
 - On the TIC3 coupler, remove the wrap plug that you have installed and reconnect the LAN cable previously removed.
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 039
-

039

Is the diagnostic error-free ?

Yes No

040

Go to "3746-950 Maintenance Using a FRU list" on page 1-28 for TIC3 replacement.

041

- Click on "Cancel" to return to the "Maintenance Options" window.
 - Go to Step 124 on page 3-37.
-

042

- On the next three "Resource Selector" windows, select the TRP and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

043

- Check that the customer stopped the traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".
- Go to Step 042.

044

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected, then click on the "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test the number of errors is indicated by an arrow.

(Step 044 continues)

044 (continued)

Is the diagnostic error-free ?

Yes No

045

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

046

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

047

- Return to the "Maintenance Options" window using the "Cancel" key.
- Select "Initialize the resource" option click on "OK".
- On the "Warning" window, click on "OK".
- Enable the ESCC.
 - Simultaneously press the Ctrl/Esc keys.
 - On the "Window List" window, double click on the "3746-9x0 Menu" option.
 - Click on the "Configuration Management" option.
 - Double click on the "Manage ESCON Processors" option.
 - On the "ESCP Management Resource Selector" window, select the desired ESCP and click on "OK".
 - The "ESCON Configuration Lines" window is displayed.
 - Click on the "Options" (in the action bar). Then select the "Manage ESCC Status" option.
 - The "ESCC Status Management" window is displayed.
 - Select the "enable" option.
 - Click on the "Options" (in the action bar). Then select the "Send request and save" option.
 - A "confirmation" window is displayed, click on "OK".
 - A "Warning" window informs you that the ESCP configuration is saved, click on "OK".
 - Click on the "Options" (in action bar). Then select the "Return" option.
 - On the "ESCON Configuration lines" window, click on "Options" and on "Exit".
 - On the "Confirmation" window, click on "OK".
 - On the "ESCP Management Resource Selector" window, click on "Cancel".
 - The "3746-9x0 Menu" is displayed.
- Return to the "Maintenance Options" window.
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- The "Resource Selection Options for Maintenance" is displayed.

Have you another resource to test?

Yes No

048

The diagnostic runs error-free. If you ran the test to diagnose a problem, go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128 before you return the machine to the customer. Then call your support.

049

Is the next resource a processor, coupler, LICxx, LCPx, LCEx, or ARCxx?

Yes No

050

Go to "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39.


051

Service Processor MAPs

- Return to the "3746-9x0 Menu" using the "Cancel" key.
- On the "3746-9x0 Menu" click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".

Go to Step 002 on page 3-16.

052



Do you want to run MAT diagnostics (Diagnostics with WRAP plug)?

Yes No

053

- On the "Resource Selector" window, select the LIC11 (address range) associated with the ARC that you want to test and click on "OK".
- On the next "Resource Selector" windows select the "ARCs" corresponding to the address range and click on "OK".

Is the ARC that you want to test is alone in its ARC group?

Yes No

054

Check with your customer the lines speed connected to the ARCs of this ARC group.

Is there a line speed higher than 64 Kbps?

Yes No

055

Go to Step 057.

056

- Ask your customer to deactivate **all** the lines of this ARC group.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- When **all** the lines have been deactivated go to Step 057.

057

- On the next two "Resource Selector" windows, select the suspected ARC and click on "OK".
(Step **057** continues)

057 (continued)

- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?**Yes No****058**

- Check that the customer stopped traffic on the suspected ARC.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 057 on page 3-24

059

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed with "ARC SAT" preselected. Click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Go to Step 067 on page 3-26

060

- On the "Resource Selector" window, select the LIC11 (address range) associated with the ARC that you want to test and click on "OK".
- On the next "Resource Selector" windows, select the "ARCs" corresponding to the address range and click on "OK".

Is the ARC that you want to test is alone in its ARC group?**Yes No****061**

Check with your customer the lines speed connected to the ARCs of this ARC group.

Is there a line speed higher than 64 Kbps?**Yes No****062**

Go to Step 064.

063

- Ask your customer to deactivate **all** the lines of this ARC group.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- When **all** the lines have been deactivated go to Step 064.

064

- On the next two "Resource Selector" windows select the suspected ARC and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

(Step **064** continues)

064 (continued)

Is the "Maintenance Options" window is displayed?

Yes No

065

- Check that the customer stopped traffic on the suspected ARC.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".
- Go to Step 064 on page 3-25

066

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed with "ARC SAT" preselected.
- Select the "ARC MAT" option and click on "OK".
- When the "Information Required" window is displayed, disconnect the ARC cable, from the DTE or DCE. At the end of the ARC cable, install the wrap plug according to the ARC type (see "Shipping Group Tools" on page A-2).
- Enter "Yes" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window prompts you to remove the wrap plug from the ARC cable and reconnect the ARC cable previously removed. Click on "OK" when it is done.
- The "Diagnostic Active Status" window is displayed with the number of errors.
- Go to Step 067



067

Is the diagnostic error-free ?

Yes No

068

Is the ARC you tested an ARC assembly B? (with a detachable cable at the rear)?



Yes No

069

(Step **069** continues)

069 (continued)

- Display the list of suspected FRUs (see “Display the FRU List After a Diagnostic Failure” on page 1-143 for procedure).
- Once you have the FRU list, go to “3746-950 Maintenance Using a FRU list” on page 1-28 for FRU replacement.

070

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "ARC MAT", then click on "OK".
- When the "Information Required" window is displayed, disconnect the cable at the rear of the ARC and install the wrap plug according to the ARC type you are testing (see “Shipping Group Tools” on page A-2).
- Enter "YES" and click on "OK".
- The "Diagnostic Active Status" window is displayed, and when the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window prompts you to remove the wrap from the ARC cable, and reconnect the cable previously removed at the rear of the ARC. Click on "OK" when it is done.
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****071**

- Display the list of suspected FRUs (see “Display the FRU List After a Diagnostic Failure” on page 1-143 for procedure).
- Once you have the FRU list, go to “3746-950 Maintenance Using a FRU list” on page 1-28 for FRU replacement.

072

- The cable at the rear of the ARC is defective.
- Order a new cable and change it.

073

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

074

Ask your customer to stop the traffic on the suspected CLP. If APPN/IP is installed, deactivate the ports concerned (refer to “Activate/Deactivate a Resource Via CCM” on page 1-139), then continue the procedure from here.

Have you more than one CLP on the 3746-950?**Yes No****075**

Go to Step 087 on page 3-31.

076


The hardware can connect four adjacent LICs to two adjacent CLPs. This hardware connection allows the CLPs to operate in standard mode or backup mode depending upon the option defined in the MOSS-E table.

Service Processor MAPs


The Backup Mode is only possible between two adjacent positions

CLP Position	Line Addresses	Attached LIC Position	CLP Backup Position
07G-A1-H	2112-2175	07N-A1 G and H	07G-A1 K
07G-A1-K	2176-2239	07N-A1 J and K	07G-A1 H
07G-A1-M	2240-2303	07N-A1 L and M	07G-A1-P
07G-A1-P	2304-2367	07N-A1 N and P	07G-A1-M
07E-A1-D	2368-2431	07M-A1 C and D	07E-A1-F
07E-A1-F	2432-2495	07M-A1 E and F	07E-A1-D
07E-A1-H	2496-2559	07M-A1 G and H	07E-A1-K
07E-A1-K	2560-2623	07M-A1 J and K	07E-A1-H
07E-A1-M	2624-2687	07M-A1 L and M	07E-A1-P
07E-A1-P	2688-2751	07M-A1 N and P	07E-A1-M
07D-A1-D	2752-2815	07L-A1 C and D	07D-A1-F
07D-A1-F	2816-2879	07L-A1 E and F	07D-A1-D
07D-A1-H	2880-2943	07L-A1 G and H	07D-A1-K
07D-A1-K	2944-3007	07L-A1 J and K	07D-A1-H
07D-A1-M	3008-3071	07L-A1 L and M	07D-A1-P
07D-A1-P	3072-3135	07L-A1 N and P	07D-A1-M

CLP in Backup Mode



CLP in Standard Mode



Continue with Step 077.

077

- Before continuing it is necessary to check if the suspected CLP has a backup CLP and if the LICs normally under the control of the suspected CLP are now under the control of the backup CLP.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Configuration Management" option.
 - Double click on the "Define Backup CLP" option.
 - The following "CLP Backup" window is displayed.

Processor Backup

Select a processor:

Processor Type	Primary Processor	Backup Processor	Automatic Fallback	Fallback State	Switchback Requested	
CLP	2112	2176	no	no	no	1
CLP	2176	2112	no	yes	no	2
CLP	2240		no	no	no	3
CLP	2304		no	no	no	3

Notes:

1. **1** and **2** These lines indicate that the CLP line addresses range from 2112 and from 2176 can be backup for each other.
 2. **2** This line with a "yes" in the fallback state column indicates that the primary processor (2176) is controlling the LICs of the backup processor (2112).
 3. **3** These lines indicate that the CLPs have no backup.
- Note if the suspected CLP is backed up by another one, then click on the "Cancel" key.

Does the suspected primary CLP have a backup CLP with a "Yes" in the fallback column?


Yes No

078

Go to Step 086 on page 3-31.

079

The resources of the suspected CLP are under the control of the backup CLP.



Test of the suspected CLP without its LIC(s) attached

- Using the "Cancel" key, return to the "3746-9x0 Menu" window.
 - Click on the "Problem Management" option.
- (Step **079** continues)

Service Processor MAPs

079 (continued)

- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- On the "Resource Selector" window, select the processor for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

080

- Check that the customer stopped traffic on the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Go to Step 079 on page 3-29.

081

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?

Yes No

082

- Display the list of suspected FRUs (see "Display the FRU List After a Diagnostic Failure" on page 1-143 for procedure).
- Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

083

- Using the "Cancel" key return to the "Maintenance Options" window.
- Select the "Initialize the resource" option to reinitialize the FRU and click on "OK".
- Follow the instructions on the "Warning" window and click on "OK" when prompted.
- The "Maintenance options" window is displayed.
- Select "Remove the resource from the concurrent mode" option and click on "OK".
- On the "Warning" window, click on "OK".
- On the "Resource selector" window, click on "Cancel".
- Return to the "3746-9x0 Menu" window.

Now you must test the CLP with its attached LIC(s).

- Ask the customer to stop traffic on the LIC(s) associated with the suspected processor.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- When the traffic is stopped, click on the "Configuration Management" option on the "3746-9x0 Menu" window.
- Double click on the "Define Backup CLP" option.
- The "CLP Backup" window is displayed.
- Select the suspected CLP and click on the "Switchback" key.
- On the "Confirmation" window, click on "OK".
- Wait for alarm "Switchback successful" and click on "OK".

(Step **083** continues)

083 (continued)


- Click on "cancel" to return to the "3746-9x0 Menu" window.
- Select the "problem Management" option.
- Double click on the "Perform maintenance" option.
- On the next "Resource Selector" windows, select the suspected CLP for concurrent maintenance, by clicking on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on "Start".
- A "Specific Adapter" window is displayed. Select the processor and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration.
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostic error-free ?**Yes No****084**

- Display the list of suspected FRUs. See "Display the FRU List After a Diagnostic Failure" on page 1-143.
- Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

085

- The suspected CLP has been tested with its attached LICs. It is error free.
- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

086**The suspected CLP has no CLP backup.**

- Click on the "Cancel" key. You return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 087.

087(Step **087** continues)

087 (continued)

- On each of the three "Resource Selector" windows, select the processor for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

088

- Check that the customer stopped traffic on the suspected CLP.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".
- Go to Step 074 on page 3-27

089

- Select the "Perform Diagnostics on the resource" option and click on "OK".
- A "Diagnostics" window is displayed. Check that the "Specific Adapter" and "no wrap" options are selected. Then click on the "Start".
- A "Specific Adapter" window is displayed. Select the "CLP" and click on "OK".
- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration. (This diagnostic testing for the CLP and the attached LIC(s), LCB(s), LCBE(s) and ARC(s) can take up to one hour depending on the 3746-950 configuration).
- At the end of the test, the number of errors is indicated by an arrow.

Is the diagnostics error-free ?

Yes No

090

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

091

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

092

- On the "Resource Selector" windows, select the LIC11 for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

093

- Check that the customer stopped the traffic on the suspected LIC11.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" and click on "OK".

(Step 093 continues)

093 (continued)

- Go to Step 092 on page 3-32

094

- On the window displayed select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" then, click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LIC11.
- Unfasten the screws which maintain the cable coming from the LCBB on the rear of the LIC11 and unplug the cable.
- On the rear of the LIC11 install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?**Yes No****095**

Go to Step 105 on page 3-34.

096

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****097**

Go to Step 106 on page 3-34.

098

- Click on "Cancel".
- Replug the cable coming from the LCBB on the rear of the LIC11 and secure it.
- On the "Maintenance Options" window select the "Perform Diagnostics on the resource" option, and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC11 MAT" then, click on "OK".
- An "Information Required" window is displayed prompting you to install a wrap plug.
- Locate the LCBB.
- Unfasten the screws which maintain the cable on the LCBB and unplug this cable from the LCBB.
- On the end of the cable install the wrap plug PN 58G9425.
- Check if the both LEDs are ON.

Are the both LEDs of wrap plug ON?**Yes No****099**

Go to Step 103 on page 3-34.

100

(Step 100 continues)

100 (continued)

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window prompts you to remove the wrap plug.
- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed, then when the test is complete an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window remind you to remove the wrap plug.
- Unplug the wrap plug if not already done and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

101

Go to Step 104.

102

Go to Step 107.

103

- Enter "No" on the "Information Required" window and click on "OK".
 - The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
 - The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window remind you to remove the wrap plug.
 - Unplug the wrap plug if not already done and click on "OK".
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 104.
-

104

The cable between the LIC11 and the LCBB is faulty. Order a new one, exchange it, and when it is done go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128.

105

- Enter "No" on the "Information Required" window and click on "OK".
 - The "Diagnostic Active Status" window is displayed few seconds, then the "Information Required" window informs you that the wrap test is not running. Click on "OK".
 - The "Diagnostic Active Status" window is displayed, then an "Information Message" gives the test result. Click on "OK".
 - A "Diagnostic Warning" window remind you to remove the wrap plug.
 - Unplug the wrap plug if not already done and click on "OK".
 - The "Diagnostic Active Status" window is displayed with the number of errors.
 - Go to Step 106.
-

106

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

107

- Reconnect and secure the cable to the LCBB.
- (Step 107 continues)

107 (continued)

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

108

- On the "Resource Selector" window, select the LIC12 for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

109

- Check that the customer stopped the traffic on the suspected LIC12.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 108

110

- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 SAT" option and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

111

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

112

- Using the "Cancel" key, return to the "Maintenance Options" window.
- On this window, select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LIC12 MAT" option and click on "OK".
- A "Diagnostic Active Status" window is displayed then an "Information Required" window prompts you to install a wrap plug.
- Locate the LIC12 that you want tested on the 3746-950.
- Unfasten the screws which maintain the cable at the rear of LIC12 and unplug the cable from the LIC12.
- At the rear of the LIC12 install the wrap plug according to the type of connection that you have.
 - Wrap plug PN 58X9354 for X.21
 - Wrap plug PN 58X9349 for V.35

(If you do not know which kind of connection you have, install either one of these wraps).

- Enter "Yes" on the "Information Required" window and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete, an "Information Message" gives the test result. Click on "OK".
- A "Diagnostic Warning" window prompts you to remove the wrap plug.

(Step 112 continues)

Service Processor MAPs

112 (continued)

- Unplug the wrap plug and click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?

Yes No

113

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

114

- If you have installed the wrap plug according to the type of connection continue with Step 116.
- Otherwise continue this procedure.

Did you run the LIC12 MAT diagnostic using the two wraps plugs?

Yes No


115

Go to Step 112 on page 3-35 to run the diagnostic again using the other wrap plug.

116

- Reconnect and secure the cable at the rear of LIC12.
- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124 on page 3-37.

117



To test the LCPB, LCEB, LCPE, or LCEE select the LCBB associated

- On the "Resource Selector" window, select the LCBB for concurrent maintenance and click on "OK".
- Once the resource is set to concurrent mode, a "Maintenance Options" window is displayed.

Is the "Maintenance Options" window is displayed?

Yes No

118

- Check that the customer stopped the traffic on the suspected LIC11.
- If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.

(Step 118 continues)

118 (continued)

- Return to the "3746-9x0 Menu".
- Select the "Problem Management" option.
- Double click on the "Perform Maintenance" option.
- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
- Go to Step 117 on page 3-36.

119

- Return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT1" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****120**

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

121

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Select the "Perform Diagnostics on the resource" option and click on "OK".
- The "Test and Running Option Selection" window is displayed.
- Select the "LCBB SAT2" and click on "OK".
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free ?**Yes No****122**

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

123

- Click on the "Cancel" key to return to the "Maintenance Options" window.
- Go to Step 124.

124

- If you have run a test using a WRAP plug, remove the WRAP and reconnect the cable (if not already done).
- Select "Initialize the resource" option and click on "OK".
- On the "Warning" window, click on "OK".
- Select "Remove the resource from the concurrent mode" and click on "OK".
- On the "Resource selector" window, click on "Cancel".
- The "Resource Selection Options for Maintenance" is displayed.

(Step 124 continues)

Service Processor MAPs

124 (continued)

Have you another resource to test?

Yes No

125

The diagnostic runs error-free. If you ran the test to diagnose a problem, either go to "MAP: 3746-950 Ending Procedure in Concurrent Mode" on page 1-128 before you return the machine to the customer or call your support.

126

Is the next resource a processor, coupler, LICxx, LCPx, LCEEx, or ARCxx?

Yes No

127

Go to "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39.

128

- On the "Resource Selection Options for Maintenance" window, select the "Via the active CDF-E" option and click on "OK".
 - Go to Step 002 on page 3-16.
-

MAP 2980: How to run 3746-950 Diagnostic in Offline Mode

Ask the customer to stop all the traffic on the 3746-950. If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.

When the 3746-950 is set in Offline Mode, it is faster to start all the diagnostics than to start a selected diagnostic on a specific resource. Nevertheless, do not forget that when the 3746-950 has a CLP with an LIC11 attached test duration time can increase up to one hour according to the number of ARCs installed.

001

Have you more than one CLP installed on the 3746-950?

Yes No

002

Go to Step 004.

003

Before starting this procedure see if CLP(s) are set in standard or backup mode in order to know what will be tested during the Offline procedure. Go to "MAP: 3746-950 CLP Backup or Standard Mode Setting" on page 1-135 to check the CLP status and change it if necessary. Then return here to continue with Step 004.

004

- You should be logged ON on the service processor console. If not go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- Set the 3746-950 in Offline mode (if it is not already) as follows:
 - Double click on the 3746-950 icon.
 - The "3746-9x0 Menu" is displayed.
 - Click on the "Problem Management" option.
 - Double click on "Set 3746-9x0 Online/Offline option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - on the next "Set 3746-9x0 Online/Offline" window, click on "OK".
- If you set the 3746-950 in Offline mode in the previous step perform a general IML. Otherwise go to Step 006.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Operation Management" option.
 - Double click on the "Perform General IML" option.
 - A "Perform General IML" is displayed, click on "OK".
 - On the next "Perform General IML", click on "YES" to perform an IML without diagnostics.
 - A normal 3746-950 IML is terminated when 00000000 is displayed on the control panel and the ready LED is ON. In case of a problem during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

Does the ready LED come ON?

Yes No

005

Record the code displayed on the control panel and go to "3746-950 Control Panel Codes" on page 1-15.

006

- Return to the "3746-9x0 Menu" window.
- Click on the "Problem Management" option.
- Double click on "Perform Offline Diagnostics" option.
- The "Diagnostics" window is displayed. Select the "Whole 3746-950" and the "No wrap" options and click on "Start".

(Step **006** continues)

006 (continued)

- The "Diagnostics" window is displayed again and the "Elapsed time" is incremented during test duration (see "Note:").
- At the end of the test the number of errors is indicated by an arrow.

Is the diagnostic error-free?

Yes No

007

Go to "Display the FRU List After a Diagnostic Failure" on page 1-143. Once you have the FRU list, go to "3746-950 Maintenance Using a FRU list" on page 1-28 for FRU replacement.

008

- No error detected. Set the 3746-950 in Online mode.
 - Return to the "3746-9x0 Menu" window using the "Cancel" key.
 - Click on the "Problem Management" option.
 - Double click on "Set 3746-9x0 Online/Offline option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK".
- Start a general IML.
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Operation Management" option.
 - Double click on the "Perform General IML" option.
 - When the 3746-950 has terminated its IML and the ready LED is ON, continue with the next bullet.
- Return to the "MOSS-E View" window.

Go to "CE Leaving Procedure" on page 4-53 to return the machine to the customer. If the problem persists contact your support.

Note: If a diagnostic timeout occurs when you have started the diagnostic on the "Whole 3746-950" with "No wrap" option, restart once the diagnostic. If diagnostic timeout is again displayed contact your support.

MAP 2990: How to Run 3746-950 Specific Diagnostics

Ask the customer to stop all the traffic on the 3746-950. If APPN/IP is installed, deactivate the ports concerned (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here. These diagnostics must be run in **Offline Mode**.

This MAP only allows you to run either the **MAT diagnostic on a specific coupler (ESCC, TIC3) or diagnostics on the service logic (SAS Bus)**.

For all other diagnostics, use the "MAP 2980: How to run 3746-950 Diagnostic in Offline Mode" on page 3-39.

001

- You should be logged ON on the service processor console. If not, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- Set the 3746-950 in Offline mode (if it is not already) as follows:
 - Double click on the 3746-950 icon.
 - The "3746-9x0 Menu" is displayed.
 - Click on the "Problem Management" option.
 - Double click on the "Set 3746-9x0 Online/Offline Option".
 - On the "Set 3746-9x0 Online/Offline" window, click on "YES" or "NO" according to the current setting.
 - On the next "Set 3746-9x0 Online/Offline" window, click on "OK".
- If you set the 3746-950 in Offline mode in the previous step perform a general IML. Otherwise go to Step 003
 - Return to the "3746-9x0 Menu" window.
 - Click on the "Operation Management" option.
 - Double click on the "Perform General IML" option.
 - A "Perform General IML", click on "YES" to perform an IML without diagnostics.
 - A normal 3746-950 IML is terminated when 00000000 is displayed on the control panel and the ready LED is ON. In case of problem during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking.

Is the ready LED come ON?

Yes No

002

Record the code displayed on the control panel and go to "3746-950 Control Panel Codes" on page 1-15.

003

- Return to the "3746-9x0 Menu".
- Click on the "Problem Management" option.
- Double click on the "Perform Specific Diagnostics" option.
- On the "Diagnostic Control Monitor" window, select the option that you want.
 - If you select "Run diagnostics for a specific hardware resource", go to Step 004.
 - If you select "Run diagnostics for the Service Bus", go to Step 007 on page 3-42.

004

- On the "Resource Selector" window, select the resource and click on "OK".
- On the next "Resource Selector" window, select the resource again.
- On the "Test and Running Option Selection" the selected resource is displayed with "MAT" (Manual Assurance Test) preselected. Click on "OK".
- A "Diagnostic Active Status" window is temporary displayed.
- When the "Information Required" window is displayed:
 - Remove the cable at the rear of the ESCC or TIC3.
 - Install the wrap plug on the rear of the coupler (PN 6165899 for TIC3 and PN 5605670 for ESCC).

(Step **004** continues)

Service Processor MAPs

004 (continued)

- Press "W" and click on "OK".
- Click on the "Cancel" key to return to the "Maintenance Options" window.
- The "Diagnostic Active Status" window is displayed. When the test is complete an "Information Message" gives the test result. Click on "OK".
- On the coupler, remove the wrap plug that you have installed and reconnect the cable previously removed.
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error-free?

Yes No

005

Go to "MAP: 3746-950 in Offline Mode" on page 1-114 for FRU exchange.

006

You suspected a problem on a coupler and the diagnostic is error free. Call your support for assistance.

007

- The "Service Bus Group Selection" window is displayed.
- Select the "PRC SL" option, then click on "OK".
- On the "Resource Option Selection" window, select the "All Resources" option and click on "OK".
- On the "Test and Running Options Selection" window, select the "SAS BUS SAT" option, then click on "OK".
- A "Diagnostic Active Status" window is displayed.
- When the test end, an "Information Message" window is displayed. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error free?

Yes No

008

- Click on "Cancel" to return to the "Diagnostic Control Monitor" window.
- Select the "Run diagnostics for the Service Bus" option, then click on "OK".
- The "Service Bus Group Selection" window is displayed.
- Select the "PRC SL" option, then click on "OK".
- On the "Resource Option Selection" window, select the "All Resources" option and click on "OK".
- On the "Test and Running Options Selection" window, select the "SAS BUS MAT" option, then click on "OK".
- A "Diagnostic Active Status" window is displayed briefly. Then the first "Information required" window is displayed, prompting you to perform tasks on the 3746-950. Perform all the tasks following the prompts. Refer to "3746-950 Service Logic Cabling" on page 3-44 to locate the different components.

Is the diagnostic error free?

Yes No

009

- If the problem is a connectic problem correct it or exchange the suspected FRU. Go to "MAP: 3746-950 in Offline Mode" on page 1-114 for FRU exchange.

010

Go to Step 011.

011

(Step 011 continues)

011 (continued)

- Click on "Cancel" to return to the "Diagnostic Control Monitor" window.
- Select the "Run diagnostics for the Service Bus" option, then click on "OK".
- The "Service Bus Group Selection" window is displayed.
- Select the "CS SL" option, then click on "OK".
- On the "Resource option Selection" window, select the "All Resources" option, then click on "OK".
- The "Test and Running Option Selection" window is displayed with the "CS SERVICE BUS SAT" option preselected. Click on "OK".
- A "Diagnostic Active Status" window is displayed.
- When the test end an "Information Message" window is displayed, click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error free?

Yes No

012

- Go to "Display the FRU List After a Diagnostic Failure" on page 1-143.
- Once you have the FRU list go to "MAP: 3746-950 in Offline Mode" on page 1-114 to exchange the faulty FRU.

013

- Click on "Cancel" to return to the "Diagnostic Control Monitor" window.
- Select the "Run diagnostics for the Service Bus" option, then click on "OK".
- The "Service Bus Group Selection" window is displayed.
- Select the "PRC SL" option, then click on "OK".
- On the "Resource Option Selection" window, select the "Specific Resource" option and click on "OK".
- A "Resource Selection" window is displayed, with all the processors.
- Select a processor of the resource list (except the CBSP) not yet tested, then click on "OK".
- The "Test and Running Option Selection" window is displayed with the "PROC. SVRC. BUS SAT" option preselected. Click on "OK".
- A "Diagnostic Active Status" window is displayed.
- When the test end, an "Information Message" window is displayed. Click on "OK".
- The "Diagnostic Active Status" window is displayed with the number of errors.

Is the diagnostic error free?

Yes No

014

Go to Step 012.

015**Have you tested all the processors of your machine?**

Yes No

016

Go to Step 013.

017

- Using the "Cancel" key return to the "3746-9x0 Menu".
- You suspected a problem in the service logic and the diagnostics are error free. Call you support for assistance

3746-950 Service Logic Cabling




Figure 3-10. Stand Alone Service Bus (SASB) Routing with Basic Board Only




Figure 3-11. Stand Alone Service Bus (SASB) Routing with one Expansion Board

Service Processor MAPs




Figure 3-12. Stand Alone Service Bus (SASB) Routing with two Expansion Boards

MAP 3000: How to Run the Selective IML on the Multiaccess Enclosure

Important

For specific device diagnostic of the device of the multiaccess enclosure refer to the *Multiaccess Enclosure Installation and Maintenance*, manual manual.


001

- You should be logged ON on the service processor console. If not, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
- Ask the customer to stop the traffic on "all" the Multiaccess Enclosure.
- Be sure that all the MAE resources has been deactivated using CCM (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139).
- On the Service Processor select the "3746/9x0 Menu".
- Click on the "Multiaccess Enclosure (MAE) Management".
- Double click on the "Perform Maintenance on MAE".
- The following window is displayed:




Click on "Yes".

- The following window is displayed:



Click on "OK".


- You should first received an alarm message saying: "MAE Concurrent Maintenance in Progress".
- Click on "OK".
- Wait until the "MAE Link" icon is red.
- Return to the "Multiaccess Enclosure (MAE) Management" window.
- Double click on the "Selective IML on MAE".
- The following window is displayed:



Click on "Yes".

- The following window is displayed:

Service Processor MAPs



Click on "OK".

- You should first received an alarm message saying: "MAE Selective IML in Progress".
- Click on "OK".
- Wait until you received an alarm message saying: "MAE IML Complete", then click on "OK". The icon "MAE Link" should be green.

Did you receive "MAE IML complete"?

Yes No

002

There is a problem on the MAE or the link between the 3746-950 and the MAE. Refer to the *Multiaccess Enclosure Installation and Maintenance*, manual to start problem determination.

003

No problem detected.

Chapter 4. 3746-950 FRU Exchange

Use this chapter once you know what FRU to exchange. You should use all its sections, from front to back, to learn:

- Where the FRU is physically located
- How to exchange FRUs properly

Exchange Precautions

1. Most of the 3746-950 FRUs can be exchanged in concurrent maintenance. Thus, it is **VERY IMPORTANT** that these procedures be followed when replacing any FRU in the machine.
2. The control panel has voltage present even with the machine 'Power OFF'.
3. Be sure that the 3746-950 is 'power OFF' before replacing any FRUs, except for hot-pluggable FRUs.
4. **Before starting FRU exchange, make sure the involved area has been disabled by the customer.**
5. The 3746-950 contains cards that are sensitive to electrostatic discharge (ESD). Use the ESD kit and store all cards in their protective packaging when you are not actually exchanging them.
6. Procedures for exchanging FRUs are listed on the next pages, use the list in alphabetical order leading to the correct page. **Important. Do not disassemble or attempt to remove FRUs from the 3746 until you have read "General and Product Safety Information" on page xxi.**

VERY IMPORTANT

BEFORE ANY FRU EXCHANGE


BE SURE THAT THE REQUIRED AREA HAS BEEN DISABLED

IF NOT, GO TO START PAGE AND FOLLOW THE APPROPRIATE PROCEDURE

List of 3746-950 FRUs

ACPW	Use "Exchange an ACPW" on page 4-11.
Air Filter	Use "Exchange an Air Filter" on page 4-10.
ARC	Use "Exchange an ARC" on page 4-13
Board	Use "Exchange a Board" on page 4-15.
CBSP/CBSP2/CBSP3	Use "Exchange a CBSP/CBSP2/CBSP3" on page 4-16.
CLP/CLP3	Use "Exchange a Processor Other than the CBSP (CLP/CLP3, ESCP/ESCP2/ESCP3 or TRP/TRP2/TRP3)" on page 4-33
Control Panel	Use "Exchange the Control Panel" on page 4-18.
CS	Use "Exchange a Connectivity Switch" on page 4-19.
CSCE	Use "Exchange a CSCE" on page 4-21.
DCDC for Processor	Use "Exchange DCDC of Processor" on page 4-22.
DCSW	Use "Exchange a Connectivity Switch DCDC" on page 4-23.
DCDP	Use "Exchange the Power Distribution DCDP" on page 4-25.
DCPW	Use "Exchange a DCPW" on page 4-27.
Enclosure	Use "Exchange an Enclosure (Basic or Expansion)" on page 4-29.
ESCC/ESCC2	Use "Exchange an ESCC/ESCC2" on page 4-31.
ESCP/ESCP2/ESCP3	Use "Exchange a Processor Other than the CBSP (CLP/CLP3, ESCP/ESCP2/ESCP3 or TRP/TRP2/TRP3)" on page 4-33.
Fan Drawer	Use "Exchange a Fan Drawer" on page 4-32.
LCEE	Use "Exchange a LCEE" on page 4-34.
LCEB	Use "Exchange a LCEB" on page 4-36.
LCPB	Use "Exchange a LCPB" on page 4-38.
LCPE	Use "Exchange a LCPE" on page 4-40.
LIC (11 or 12)	Use "Exchange a LIC (Type 11 or 12)" on page 4-42.
SIE	Use "Exchange an SIE" on page 4-43.
SPD1	Use "Exchange an SPD1" on page 4-44.
SPD2	Use "Exchange an SPD2" on page 4-45.
SPS	Use "Exchange an SPS" on page 4-46.
TIC3	Use "Exchange a TIC3" on page 4-49.
TIC3 of CBSP/CBSP2/CBSP3	Use "Exchange a TIC3 associated With the CBSP" on page 4-47.
Transformer	Use "Exchange a Transformer" on page 4-50.
TRP/TRP2/TRP3	Use "Exchange a Processor Other than the CBSP (CLP/CLP3, ESCP/ESCP2/ESCP3 or TRP/TRP2/TRP3)" on page 4-33.


3746-950 FRU Physical Locations



FRONT View

Figure 4-1. 3746 Model 950

B-A1	Connectivity switch
E	Processors
F	Fans
G	Processors and SPS
H	Power Distribution DCDP
J	Backup ACPW or DCPW
K	Basic ACPW



REAR View

Figure 4-2. 3746 Model 950

B-B1	Connectivity switch
B-B2	Connectivity switch DC/DC
M	Couplers and SPD2
N	Couplers and SPD1
P	Transformer if backup ACPW installed
Q	Transformer
R	EPO

3746-950 Basic Board Locations




Figure 4-3. Basic Board O7G-A1 Locations (Processor side)




Figure 4-4. Basic Board O7N-A1 Locations (Coupler side)

- **1** TIC3 or ESCC/ESCC2 sockets
- **2** SPD1 location
- **3** LIC11 or LIC12 sockets
- **4** CBC
- **5** CBC, TIC3 or ESCC/ESCC2 sockets

Basic Enclosure

PRC Side Location Board 07G		Coupler Side Location Board 07N	
		SPD1	A1-A
CSCE	A1-B		
SPS	A1-D		
		CBC	A1-E
CBSP2	A1-F	TIC3	A1-F
		Coupler (4)	A1-G
Processor (1)	A1-H	Coupler (3)	A1-H
		Coupler (2)	A1-J
Processor (1)	A1-K	Coupler (3)	A1-K
		Coupler (2)	A1-L
Processor (1)	A1-M	Coupler (3)	A1-M
		Coupler (2)	A1-N
Processor (1)	A1-P	Coupler (3)	A1-P
Dummy	A1-Q	Not Used	A1-Q

*Figure 4-5. Basic board component location***Notes:**

1. (1) Processor CLP/CLP3, TRP/TRP2/TRP3, ESCP/ESCP2/ESCP3, or SIE
2. (2) LIC11, LIC12, TIC3 or ESCC/ESCC2
3. (3) LIC11, LIC12, TIC3
4. (4) CBC, LIC11, LIC12, TIC3, or ESCC/ESCC2

3746-950 Expansion Board Locations




Figure 4-6. Expansion Board 07D-A1 or 07E-A1 Locations (Processor side)




Figure 4-7. Expansion Board 07L-A1 or 07M-A1 Locations (Coupler side)

- **1** TIC3 or ESCC/ESCC2 sockets
- **2** SPD2 location
- **3** LIC11 or LIC12 sockets

Expansion Enclosure 1

PRC Side Location Board 07E		Coupler Side Location Board 07M	
		SPD2	A1-A
CSCE	A1-B		
		Coupler (2)	A1-C
Processor (1)	A1-D	Coupler (3)	A1-D
		Coupler (2)	A1-E
Processor (1)	A1-F	Coupler (3)	A1-F
		Coupler (2)	A1-G
Processor (1)	A1-H	Coupler (3)	A1-H
		Coupler (2)	A1-J
Processor (1)	A1-K	Coupler (3)	A1-K
		Coupler (2)	A1-L
Processor (1)	A1-M	Coupler (3)	A1-M
		Coupler (2)	A1-N
Processor (1)	A1-P	Coupler (3)	A1-P
Dummy	A1-Q	Not Used	A1-Q

Expansion Enclosure 2

PRC Side Location Board 07D		Coupler Side Location Board 07L	
		SPD2	A1-A
CSCE	A1-B		
		Coupler (2)	A1-C
Processor (1)	A1-D	Coupler (3)	A1-D
		Coupler (2)	A1-E
Processor (1)	A1-F	Coupler (3)	A1-F
		Coupler (2)	A1-G
Processor (1)	A1-H	Coupler (3)	A1-H
		Coupler (2)	A1-J
Processor (1)	A1-K	Coupler (3)	A1-K
		Coupler (2)	A1-L
Processor (1)	A1-M	Coupler (3)	A1-M
		Coupler (2)	A1-N
Processor (1)	A1-P	Coupler (3)	A1-P
Dummy	A1-Q	Not Used	A1-Q

Figure 4-8. Expansion Board Component Location

Notes:

1. (1) Processor CLP/CLP3, TRP/TRP2/TRP3, ESCP/ESCP2/ESCP3, or SIE
2. (2) LIC11, LIC12, TIC3, or ESCC/ESCC2
3. (3) LIC11, LIC12, TIC3

3746-950 Front Side Details




Figure 4-9. 3746-950 Front Side

3746-950 Rear Side Details





Figure 4-10. 3746-950 Rear Side

Exchange an Air Filter

No special precautions are needed to exchange an air filter.

1. Locate the air filter **1** at the front of the machine using Figure 4-9 on page 4-8.
2. Push the air filter through the holes of the cover **2** and remove it.
3. Insert the new air filter with the arrow pointing up.
4. Return to the step in the MAP you were performing.



Front View

Figure 4-11. 3746-950 Air Filter Replacement

Exchange an ACPW

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.


If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

Note

When the basic ACPW is disconnected, the 3746-950 power ON is no longer possible even if the backup ACPW/DCPW is connected.

1. Locate the ACPW that you have to exchange using Figure 4-9 on page 4-8.
2. If the machine has its:
 - **Ready LED ON**, go to step 3.
 - **Otherwise**, go to step 7.
3. Check if there is **another** ACPW or DCPW in your 3746-950. If yes, go to step 5. If not, proceed with the next step.
4. The machine has its **Ready LED ON** and does not have **another** ACPW or DCPW.
 - a. Press the 'standby' key on the control panel to put the machine in standby mode.
 - b. Go to step 7.
5. There is **another** ACPW or DCPW in your 3746-950.
6. Activate the maintenance switch.
 - a. Open the front cover and locate the lever of the maintenance switch on the DCDP. **1**
 - b. Pull the lever outwards.

This will prevent the main -48v dropping and stop the power monitoring.
7. If not already done, switch the main circuit breaker CB1 OFF, on the ACPW that you exchange. **2**



8. Unplug the J1 connector from that ACPW.
9. At the rear of the machine loosen the four screws which secure the transformer cover plate.
10. Remove the transformer cover plate.
11. Unplug the power cord from the J2 connector of the ACPW that you want to remove. **3**
12. Check that on the transformer there is no voltage between TB1 position 1 and TB1 positions 2, 3, or 4.
13. On TB1 and TB2 disconnect all wires coming from the ACPW **4** and note their position.

TB1 Position	Voltage
1	
2	200 V
3	220 V
4	240 V

14. If you exchange the basic ACPW, unplug connectors J11 and J12 from the rear of the DCDP.
Or for the backup ACPW, unplug connectors J9 and J10 from the rear of the DCDP.
15. Remove the screw holding the ACPW. **5**
16. Disconnect the two ground straps coming from the ACPW. **6**
17. At the front of the machine, remove the two screws holding the power box. Slide the ACPW out.

Note

When you remove the basic ACPW, if the backup ACPW is installed, you have to remove the bracket. **7**


FRU Exchange

To install the new ACPW:

- On the rear of the new ACPW, check that connector J2 is accessible.

This connector must be on the left if you install a basic ACPW, and on the right if you install a backup ACPW.

- Using the screw **8** move the plate **9** to the right if you install a basic ACPW, and to the left if you install a backup ACPW.



- Perform steps 17 to 6 in reverse order.
- Return to the step in the MAP you were performing.




Figure 4-12. Rear of the 3746-950

Exchange an ARC

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Locate the ARC that you have to exchange.
2. Identify which ARC assembly that you have to exchange see Figure 4-13.






Figure 4-13. ARC Assembly Identification


3. For an ARC assembly A continue with step 4, for an ARC assembly B go to step 8 on page 4-14
4. Loosen the two knobs **1** which secure the ARC in the line connection box (LCB).




5. Remove the ARC from the line connection box.
6. Unplug the ARC cable:
 - From the DTE or DCE or from a DTE or DCE cable if it is an ARC type ARC1C, ARC1D, ARC3C, or ARC3D.
7. **Install the new ARC:**
 - a. Perform the previous steps, 6 to 4 in reverse order.
 - b. Return to the step in the MAP you were performing.

FRU Exchange

8. Loosen the two screws **A** which secure the the ARC cable on the ARC.



9. Loosen the two knobs **B** which secure the ARC in the line connection box (LCB).



10. Remove the ARC from the line connection box.

11. Install the new ARC:

- Perform the previous steps, 10 to 8 in reverse order.
- Return to the step in the MAP you were performing.

Exchange a Board

Important


Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.


1. If the machine has its:
 - **Ready LED ON**, go to step 2.
 - **Otherwise**, go to step 4.
2. Press the 'standby' key.
3. When the machine is in standby mode with its **Standby LED ON** go to the next step.
4. Switch OFF the main circuit breaker CB1 **1** of the ACPW and, if installed, of the second ACPW/DCPW.



5. Locate the enclosure where you have to exchange the board using Figure 4-9 on page 4-8.
6. From the front of the machine, remove the internal covers to gain access to the CSCE cassette.
7. **WARNING: Use the ESD kit and procedures.**
8. Remove CSCE and all the PRC cassettes (plus SPS cassette for the basic board) from

the enclosure. (See the CSCE, SPS and PRCs exchange procedure for details).

9. From the rear of the machine, remove the internal cover to gain access to the SPD1 or SPD2 cassette according to the board enclosure that you want removed.
10. Unplug the SPD1 or SPD2 and all coupler cassettes, but do not remove them from the enclosure. (See the SPD1 or SPD2 and coupler exchange procedure for details).
11. Remove the screws holding the board on the enclosure. **2**
12. Remove the board. **3**



13. Install the new board using the screws previously removed.
14. Insert the PRCs, CSCE cassettes, and SPS cassette for basic board, previously removed in the enclosure. Slide them firmly in until they stop clicking.
15. From the rear of the machine, slide SPD1 or SPD2 and all the couplers firmly in until they stop clicking.
16. Switch ON the main circuit breaker CB1 **1** of the ACPW and, if installed, of the second ACPW/DCPW.
17. Return to the step in the MAP you were performing.

Exchange a CBSP/CBSP2/CBSP3

In this manual CBSP is the generic name for CBSP, CBSP2, or CBSP3.

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. From the service processor, return to the "MOSS-E VIEW" window and double click on the service processor icon.
2. On the "Service Processor Menu" window, click on the "Configuration Management" option. Then double click on the "Manage 3745/3746-9x0 Installation/removal" option.
3. On the "Controller Installation" window, select the machine by clicking on the serial number of the machine for which you are called and click on "repair".
4. On the "Repair Actions for 3746-9x0" window, select the "Change 3746-9x0 CBSP" option and click on "OK".
5. The "Controller Repair Message" window is displayed. Perform the following steps before clicking on "OK".
6. Locate the CBSP cassette using Figure 4-9 on page 4-8.
7. **WARNING: Use the ESD kit and procedures.**
8. If there is a cable plugged in the front of the CBSP, remove the bracket, and unplug the cable.
9. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.
10. Exchange the FRU suspected:
 - If the FRU is the complete processor cassette, exchange it and continue with the next step.
 - If the FRU is the DCDC of the processor refer to "Exchange DCDC of Processor" on page 4-22 to exchange it. Then continue on next step.
11. Insert the CBSP into the enclosure and slide it firmly in until it clicks (locks in).
12. If there was a cable in front of the CBSP, plug it again and secure it with the bracket previously removed.
13. Normally after CBSP insertion, an CBSP hardware initialization phase is started which should terminate with **05282805** displayed at the 3746-9x0 control panel. In case a problem occurs during this phase, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds).
 - If **05282805** is displayed:
 - a. Return to the "Controller Repair Message" window and click on "OK".
 - b. Continue with the displayed instruction of the "Controller Repair Message".
 - c. If the **standby LED** is **ON**, press the 'start' key on the 3746-9x0 control panel to continue. An IML is started. A normal IML is terminated by **00000000** displayed on the 3746-9x0 control panel. In case a problem occurs during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds).
 - If **00000000** is displayed:
 - a. Return to the "Controller Repair Message" window and click on "OK".
 - b. Continue with the displayed instruction of the "Controller Repair Message".
 - c. Return to the step in the MAP you were performing.
 - If you do not obtain **00000000**
 - a. Suspect a problem in other part of the machine.
 - b. Remove the CBSP that you have installed and reinstall the previous CBSP (using the previous steps 7 to 11)
 - c. Return to the "Controller Repair Message" window and click on "OK".
 - d. Return to the step in the MAP you were performing.
 - If **05282805** is not displayed:
 - a. Record the displayed control panel code.
 - b. Remove the CBSP that you have installed and reinstall the previous CBSP (using the previous steps 8 to 12), and return to the step in the MAP you were performing.




Figure 4-14. 3746 Model 9x0 CBSP Cassette

Exchange the Control Panel

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Open the control panel gate
2. Loosen the 4 screws of the control panel cover. **1**
3. **WARNING: Use the ESD kit and procedures.**
4. If you exchange:
 - The operator panel **2**: Go to step 5.
 - The keyboard display card **6**: Go to step 6.
5. Operator panel:
 - a. Disconnect connectors **3** and **4**.
 - b. Remove the 4 screws **5** and the operator panel.
 - c. To install the new operator panel, perform this procedure in reverse order.
 - d. From the 3746-950 control panel, run the 3746-950 control panel test (see "How to Run the 3746-950 Control Panel Test" on page 3-14).
 - e. Do not forget to put the 3746-950 in its initial power control mode (remote or local) if you have modified it.
6. Keyboard display card:
 - a. Disconnect connectors **4**.
 - b. Remove the five screws **7** and the keyboard display card.
 - c. To install the new keyboard display card, perform this procedure in reverse order.
7. From the 3746-950 control panel, run the 3746-950 control panel test (see "How to Run the 3746-950 Control Panel Test" on page 3-14).
8. Return to the step in the MAP you were performing.




Figure 4-15. 3746-950 Control Panel Cards

Exchange a Connectivity Switch

Important


Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:


- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.


1. If the machine has its:
 - **Ready LED ON**, go to step 2.
 - **Otherwise**, go to step 4.
2. Press the 'standby' key.
3. When the machine is in standby mode with its **standby LED ON**, go to step 4.



4. Locate the connectivity switch using Figure 4-10 on page 4-9.
5. At the rear of the machine remove the two internal covers **5** to gain access to the CS. (Left side)




6. Unplug connectors, from the back of the CS in the following order, J01, J03 and J04. **2**
7. At the front of the machine, remove the two internal covers **6** to have access to the CS (right side).



8. **WARNING: Use the ESD kit and procedures.**
9. Unplug the processor cables (number depending on the configuration). **3**
10. Remove the two screws holding the CS. **4**

FRU Exchange

11. Pull the CS out of the machine (be careful not to damage the cables).
12. Install the new CS and secure it with the screws. **4**
13. Plug the processor cables previously removed. **3**
14. Install the covers previously removed **6**.
15. At the rear of the machine, reconnect the cables in the following order:
 - The power cable J04
 - The service bus J01
 - The control cable J03. **2**
16. Install the covers previously removed **5**.
17. Return to the step in the MAP you were performing.



Rear Side

Figure 4-16. 3746-950 Connectivity Switch

Exchange a CSCE

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. If the machine has its:
 - **Ready LED ON**, go to step 2.
 - **Otherwise** go to step 4.
2. Press the 'standby' key.
3. When the machine is in standby mode with its **Standby LED ON**, go to the next step.
4. Switch OFF the main circuit breaker CB1 **1** of the ACPW and, if installed, of the second ACPW/DCPW.
5. Locate the CSCE using Figure 4-9 on page 4-8.
6. Remove the internal cover (2 screws) to have access to the CSCE. **1**
7. **WARNING: Use the ESD kit and procedures.**
8. Unfasten the top and bottom screws holding the CSCE cassette in the enclosure, but do not pull the CSCE cassette out of the enclosure.
9. Remove the two internal covers **2** to have access to the CS.
10. Unplug the processor cables coming from the CSCE cassette from the CS. **3**
11. Pull the CSCE out of the enclosure.
12. To install the new CSCE cassette, perform this procedure in reverse order.
13. Switch the main circuit breaker(s) CB1 ON.
14. Return to the step in the MAP you were performing.




Figure 4-17. 3746-950 CSCE Cable Connection to the Connectivity Switch (CS)

Exchange DCDC of Processor

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Once you have removed the processor cassette perform the following steps.
2. Remove the two screws on the cassette cover and open it. **1**
3. Remove the two screws fixing the DC/DC on the cover. **2**
4. Unlatch the DC/DC cable connector and unplug it. **3**
5. Exchange the DC/DC
6. Fix the new DC/DC on the PRC cassette cover using the screws **2**, plug its cable connector **3**, and close the cassette with screws. **1**
7. Insert the new PRC into the enclosure and slide it firmly in until it clicks (locks in).
8. Return to:
 "Exchange a CBSP/CBSP2/CBSP3" on page 4-16
 or to "Exchange a Processor Other than the CBSP (CLP/CLP3, ESCP/ESCP2/ESCP3 or TRP/TRP2/TRP3)" on page 4-33 in order to reinstall the processor.




Figure 4-18. 3746-950 Processor DC/DC

Exchange a Connectivity Switch DCDC

Important


Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:


- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.


1. If the machine has its:
 - **Ready LED ON**, go to step 2.
 - **Otherwise**, go to step 4.
2. Press the 'standby' key.
3. When the machine is in standby mode with its **standby LED ON**, go to step 4.



4. Locate the connectivity switch DCDC using Figure 4-10 on page 4-9.
5. From the rear of the machine remove the two internal covers **5** to have access to the CS (left side).



6. **WARNING: Use the ESD kit and procedures.**
7. Unplug the DCDC cable from J4 on the back of the CS. **2**
8. Unplug the power connector J1 from the DCDC. **3**
9. Remove the two screws maintaining the DCDC. **4**
10. Pull the DCDC out of the machine.
11. Install the new DCDC and secure it with the two screws. **4**
12. Plug the DCDC cable into the J4 connector of the CS.
13. Plug the power connector into J1 on the DCDC.
14. Install the covers previously removed **5**.
15. Return to the step in the MAP you were performing.



Rear Side

Figure 4-19. 3746-950 Connectivity Switch and DCDC

Exchange the Power Distribution DCDP

Important


Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. If the machine has its:
 - **Ready LED ON**, go to step 2.
 - **Otherwise**, go to step 4.
2. Press the 'Standby' key.
3. When the machine is in standby mode with its **Standby LED ON**, go to the next step.
4. Switch OFF the main circuit breaker CB1 **1** of the ACPW and, if installed, of the second ACPW/DCPW.



5. Locate the DCDP using Figure 4-9 on page 4-8.
6. At the rear of the machine, loosen the screws which secure the transformer cover plates.
7. Remove the transformer cover plates.
8. Unplug all the cables present from the DCDP connectors labeled (J8, J9, J10, J11, J12).
9. At the front of the machine, unplug all the cables present from the DCDP connectors labeled (3745, J1, J2, J3, J4, J5, J6, J7).
10. Disconnect the two ground straps located on the left side from the DCDP.
11. Remove the two screws holding the DCDP. **4**
12. Pull the DCDP out of the machine.
13. Return to the step in the MAP you were performing.

To install the new DCDP:

1. Perform this procedure (steps 10 to 5) in the reverse order.
2. Return to the step in the MAP you were performing.




Figure 4-20. 3746-950 Power Distribution Box DCDP Front and Rear View

Exchange a DCPW

Important

Check that the 'Power Control' display is set to local (3) on the control panel.


If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. If the machine has its
 - **Ready LED ON**, go to step 2.
 - **Otherwise**, go to step 3.
2. Activate the maintenance switch.
 - a. Open the front cover and locate the lever of the maintenance switch on the DCDP. **1**
 - b. Pull the lever outwards.

This will prevent the main -48v from dropping and will stop the power monitoring.
3. Locate the DCPW that you have to exchange using Figure 4-9 on page 4-8.



4. Switch the main circuit breaker CB1 OFF at the DCPW. **2**
5. Switch the -48 Volts DC source circuit breaker OFF or ask the customer to do so..
6. Attach a warning label directly to the circuit breaker indicating that "power must not be applied".
7. Disconnect the power supply cable from the customer junction box.
8. At the rear of the machine, loosen the four screws which secure the cover plate.
9. Remove the cover plate.
10. Check that on the rear TB of the DCPW there is no voltage **3** between the black and red wire.
11. Disconnect the black and the red wire from the DCPW. **3**
12. Unplug connectors J9 and J10 from the rear of the DCDP.
13. Remove the screw holding the DCPW. **4**
14. At the front of the machine, unplug the J1 connector and remove the two screws holding the power box. Slide the DCPW out.

To install the new DCPW, perform this procedure in the reverse order.

- Return to the step in the MAP you were performing.




Figure 4-21. 3746-950, Rear of DC Power Box

Exchange an Enclosure (Basic or Expansion)

Important


Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.


If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. If the machine has its:
 - **Ready LED ON**, go to step 2.
 - **Otherwise** go to step 4.
2. Press the 'standby' key.
3. When the machine is in standby mode with its **Standby LED ON**, go to the next step.
4. Switch OFF the main circuit breaker CB1 **1** of the ACPW and, if installed, of the second ACPW/DCPW.



5. Locate the enclosure that you want removed using Figure 4-9 on page 4-8.
6. From the front machine:
 - a. Remove the internal covers to have access to the CSCE cassette.
 - b. **WARNING: Use the ESD kit and procedures.**
 - c. Remove the CSCE, SPS, and all the PRC cassettes from the enclosure. (See the CSCE, SPS and PRCs exchange procedure for details).

- d. Disconnect the two ground straps from the enclosure. **3**



Front View

7. From the rear of the machine:
 - a. Remove the internal cover to gain access, to the SPD1 cassette if you change the basic enclosure, or to the SPD2 cassette if you exchange the expansion enclosure.
 - b. Unplug all the cables from the SPD1 or SPD2 cassette.
 - c. Unplug all cables from the coupler cassettes. (See "Exchange an ESCC/ESCC2" on page 4-31 and "Exchange a TIC3" on page 4-49)
 - d. If you exchange the basic enclosure: remove the SPD1 and all the coupler cassettes from the enclosure (see the SPD1 and coupler exchange procedure for details).
If you exchange the expansion enclosure: Remove the SPD2 and all the coupler cassettes from the enclosure (see SPD2 and coupler exchange procedure for details).
 - e. Remove the 8 screws which secure the enclosure. **4**
8. Pull the enclosure out from the machine.


Installation Procedure

1. From the rear of the machine:

- Insert the new enclosure in the machine.
- Secure it with screws previously removed. **4**
- Connect the two ground wires to the enclosure. **3**
- Insert the SPD1 or the SPD2 and all the coupler cassettes previously removed and slide them firmly in until they stop clicking.
- Reconnect the cable on SPD1 or SPD2 cassette and on each coupler cassette.
- Reinstall the internal covers.

2. From the front of the machine:

- Reconnect the cable on the enclosure board.
 - Insert the PRCs, the SPS and the CSCE cassettes previously removed and slide them firmly in until they stop clicking.
 - Reconnect the CSCE cable to the CS.
 - Reinstall the internal covers.
3. Switch ON the main circuit breaker CB1 **1** of the ACPW and, if installed, of the second ACPW/DCPW.
4. Check that the **Standby LED** comes ON, without any alarm.
5. Return to the step in the MAP you were performing.



Rear View

Figure 4-22. 3746-950 Enclosure Installation

Exchange an ESCC/ESCC2

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

Note

Exchange ESCC **only** by ESCC and ESCC2 **only** by ESCC2.

1. Locate the coupler cassette using Figure 4-10 on page 4-9.
2. Remove the cable located on the ESCC/ESCC2 using the following procedure.
 - **WARNING: Use the ESD kit and procedures.**
 - Loosen the screws **1**

- Remove the cover **2**
- Loosen the screws **3**
- Slide the bracket **4** upwards, and
- Unplug the ESCA cable **5**

3. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.
4. Exchange the coupler cassette.
5. Insert the new coupler cassette into the enclosure and slide it firmly in until it clicks (locks in).
6. Remove the protection of the ESCC/ESCC2 light.
7. Replace the removed cable.
 - Plug the ESCA cable **5** into the cassette.
 - Slide the bracket **4** downwards
 - Secure the screws **3**
 - Install the removed cover **2** and secure it with screws **1**.
8. Return to the step in the MAP you were performing.




Figure 4-23. 3746-950 ESCC Coupler

Exchange a Fan Drawer

Warning

You have only two minutes to exchange a fan drawer

Do not forget that the drawer assembly contains 2 fans. If the fan monitor detects a multiple fan error, the 3746-950 is automatically powered OFF after two minutes.

1. Locate the fan drawer you have to exchange using Figure 4-9 on page 4-8.
2. Unfasten the two screws holding the drawer. **1**
3. Remove the connectors from the drawer. **2**
4. Exchange the drawer and reconnect the connectors
5. Fasten the two screws holding the drawer
6. Return to the step in the MAP you were performing.




Figure 4-24. 3746-950 Cooling Units

Front Side




Figure 4-25. 3746-950 Fan Drawers Location

Exchange a Processor Other than the CBSP (CLP/CLP3, ESCP/ESCP2/ESCP3 or TRP/TRP2/TRP3)

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

Note

Exchange ESCP **only** by ESCP, ESCP2 **only** by ESCP2, and ESCP3 **only** by ESCP3.

Exchange CLP **only** by CLP, and CLP3 **only** by CLP3.

Exchange TRP **only** by TRP, TRP2 **only** by TRP2, and TRP3 **only** by TRP3.

1. Locate the PRC cassette (CLP, ESCP/ESCP2 or TRP/TRP2) using Figure 4-9 on page 4-8.
2. **WARNING: Use the ESD kit and procedures.**
3. If you change a TRP, and if there is a cable plugged in the front of the TRP, remove the bracket and unplug the cable.
4. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.

5. Exchange the FRU suspected:

- If the FRU is the complete processor cassette, exchange it and continue with the next step.
- If the FRU is the DCDC of the processor, refer to "Exchange DCDC of Processor" on page 4-22 to exchange it then continue on next step.

6. Insert the PRC into the enclosure and slide it firmly in until it clicks (locks in).

7. If you changed a TRP and if there was a cable in front of the TRP, plug it again and secure it with the bracket previously removed.

8. Return to the step in the MAP you were performing.




Figure 4-26. 3746-950 Cassette Processor

Exchange a LCEE

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Locate the line connection box.
2. Loosen the screws which secure the cable to the line connection box base (LCBB) **2**.
3. Remove the cable
4. Loosen the screws which secure all the ARC(s) into the LCEE.
5. Remove the ARC(s) and note their position in the LCEE.





Figure 4-27. Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)



6. Insert a screwdriver under the panel of the LCPE to remove it.

7. Loosen the 4 screws **3** which secure the LCPE **4** into the line connection enclosure expansion (LCEE).
8. Remove the LCPE from the LCEE.
9. Loosen the 4 screws which secure the LCEE **5**.
10. Remove the LCEE.
11. Install the new LCEE using the screw previously removed **5**.
12. Install the LCPE previously removed **4**.
13. Secure it using the 4 screws **3**.
14. Install the cover.
15. Plug the cable to the line connection box base and secure it **2**.
16. Reinstall all the ARC(s) in their previous positions and secure them.
17. Return to the step in the MAP you were performing.




Figure 4-28. LCPE into the LCEE

Exchange a LCEB

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Locate the line connection box.
2. If there is a line connection box expansion:
 - Loosen the screws which secure the cable coming from the line connection box expansion **2**
 - Remove the cable.
3. Loosen the screws which secure the cable coming from the LIC **1**.
4. Remove the cable
5. Loosen the screws which secure all the ARC(s) into the LCEB.
6. Remove the ARC(s) and note their position in the LCEB.





Figure 4-29. Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)



7. Insert a screwdriver under the panel of the LCPB to remove it.

8. Loosen the 4 screws **3** which secure the LCPB **4** into the line connection enclosure base (LCEB).
9. Remove the LCPB from the LCEB.
10. Loosen the 4 screws which secure the LCEB **5**.
11. Remove the LCEB.
12. Install the new LCEB using the screw previously removed **5**.
13. Install the LCPB previously removed **4**.
14. Secure it using the 4 screws **3**.
15. Install the cover.
16. Plug the cable coming from the LIC and secure it **1**.
17. Plug the cable coming from the line connection box expansion and secure it (if present) **2**.
18. Reinstall all the ARC(s) in their previous position and secure them.
19. Return to the step in the MAP you were performing.




Figure 4-30. LCPB into the LCEB

Exchange a LCPB

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Locate the line connection box.
2. Loosen the screws which secure the cable coming from the LIC **1**.
3. Remove the cable.
4. If there is a line connection box expansion:
 - Loosen the screws **2** which secure the cable coming from the line connection box expansion
 - Remove the cable





Figure 4-31. Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)



5. Insert a screwdriver under the panel of the LCPB to remove it.

6. Loosen the 4 screws **3** which secure the LCPB **4** into the line connection box base (LCBB).
7. Remove the LCPB from the LCBB.
8. Insert the new LCPB **4** into the LCBB.
9. Secure it using the 4 screws previously removed **3**.
10. Install the new cover provided with the LCPB.
11. Stick the new IBM logo on the new cover.
12. Plug the cable coming from the LIC and secure it **1**.
13. Plug the cable coming from the line connection box expansion (if present) and secure it **2**.
14. Return to the step in the MAP you were performing.




Figure 4-32. LCPB into the LCEB

Exchange a LCPE

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

Note

The LCPE that you received is shipped with a new cable. You **must** exchange them both at the same time.

1. Locate the line connection box.
2. Loosen the screws **2** which secure the cable coming from the LCPE to the LCPB.
3. Remove the cable





Figure 4-33. Line Connection Enclosure Base (LCEB) and Line Connection Enclosure Expansion (LCEE)



4. Insert a screwdriver under the panel of the LCPE to remove it.
5. Loosen the 4 screws **3** which secure the LCPE **4** into the line connection enclosure expansion (LCEE).
6. Remove the LCPE from the LCEE.
7. Insert the new LCPE **4** into the LCEE.
8. Secure it using the 4 screws previously removed **3**.
9. Install the new cover provided with the LCPE.
10. Stick the new IBM logo on the new cover.
11. Install the new cable provided between the LCPE and LCPB and secure it using the screws **2**.
12. Return to the step in the MAP you were performing.




Figure 4-34. LCPE into the LCEE

Exchange a LIC (Type 11 or 12)

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Locate the LIC cassette using Figure 4-10 on page 4-9.
2. **WARNING: Use the ESD kit and procedures.**
3. Loosen the screws which secure the cable.
4. Remove the cable.
5. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.
6. Exchange the LIC cassette.
7. Insert the new LIC cassette into the enclosure and slide it firmly in until it clicks (locks in).
8. Replace the removed cable, then tighten the screws.
9. Return to the step in the MAP you were performing.




Figure 4-35. 3746-950 LIC11 Coupler




Figure 4-36. 3746-950 LIC12 Coupler

Exchange an SIE

Important


Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.


If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. You should be logged ON on the service processor console. If not, go to "Console Use for maintenance" on page 1-1 for logging ON and return here.
2. Ask the customer to stop the traffic on "all" the Multiaccess Enclosure.
3. Be sure that all the MAE resources has been deactivated using CCM (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139).
4. On the Service Processor select the "3746/9x0 Menu".
5. Click on the "Multiaccess Enclosure (MAE) Management".
6. Double click on the "Perform Maintenance on MAE".
7. The following window is displayed:



Click on "Yes".

8. The following window is displayed:



Click on "OK".

9. You should first received an alarm message saying: "MAE Concurrent Maintenance in Progress".
10. Click on "OK".
11. Wait until the "MAE Link" icon is red.
12. Power OFF the MAE.
13. Locate the SIE cassette using Figure 4-9 on page 4-8. The SIE cassette can be in any processor (PRC) position.
14. **WARNING: Use the ESD kit and procedures.**
15. Loosen the screws which secure the cable.
16. Unplug the cable.
17. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.
18. Exchange the FRU suspected.
19. Insert the SIE cassette into the enclosure and slide it firmly in until it clicks (locks in).
20. Plug the cable previously removed.
21. Secure the cable with the screws.
22. Power ON the MAE.
23. Return to the step in the MAP you were performing.




Figure 4-37. 3746-950 SIE Cassette

Exchange an SPD1

Important


Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. If the machine has its:
 - **Ready LED ON**, go to step 2.
 - **Otherwise** go to step 4.
2. Press the 'standby' key.
3. When the machine is in standby mode with its **Standby LED ON** go to the next step.
4. Switch OFF the main circuit breaker CB1 **1** of the ACPW and, if installed, of the second ACPW/DCPW.



5. Locate the SPD1 cassette that you have to exchange using Figure 4-10 on page 4-9.
6. Remove the internal cover plate (4 screws) to have access to the SPD1.

7. **WARNING: Use the ESD kit and procedures.**

8. Unplug all the cables from the front of the SPD1 cassette.
9. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.
10. Exchange the SPD1 cassette.
11. Insert the new SPD1 cassette in the enclosure and slide it firmly in until it clicks (locks in).
12. Plug in the cables previously removed.
13. Install the cover plate previously removed in step 5.
14. Return to the step in the MAP you were performing.




Figure 4-38. 3746-950 SPD1 Cassette

Exchange an SPD2

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Locate the SPD2 cassette that you have to exchange using Figure 4-10 on page 4-9.
2. Remove the internal cover plate (4 screws) to have access to the SPD2.




Figure 4-39. 3746-950 SPD2 Cassette

3. **WARNING: Use the ESD kit and procedures.**
4. Unplug cables (in this order: J1, J2 and J5) from the front of the SPD2 cassette.
5. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.
6. Exchange the SPD2 cassette.
7. Insert the new SPD2 cassette in the enclosure and slide it firmly in until it clicks (locks in).
8. Plug in the cables (in this order J5, J2 and J1) previously removed.
9. Install the cover plate previously removed in step 5.
10. Return to the step in the MAP you were performing.

Exchange an SPS


Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.



1. If the machine has its:

- **Ready LED ON**, go to step 2.
- **Otherwise**, go to step 3.

2. The **ready LED** is **ON**.

a. Activate the maintenance switch if not already done.

- Open the front cover and locate the lever of the maintenance switch on the primary power box. **1**
- Pull the lever outwards.

This will prevent the main 48v from dropping and will stop the power monitoring.

b. Locate the SPS cassette on the basic board using Figure 4-9 on page 4-8.

c. **WARNING: Use the ESD kit and procedures.**

d. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.

e. Insert the new SPS into the enclosure and slide it firmly in until it clicks (locks in).

f. Return to the step in the MAP you were performing.

3. The **Ready LED** is **NOT ON**.

a. Locate the SPS cassette on the basic board using Figure 4-9 on page 4-8.

b. **WARNING: Use the ESD kit and procedures.**

c. Using the labels on the doors for reference, press the two unlocking buttons and pull the cassette out.

d. Insert the new SPS into the enclosure and slide it firmly in until it clicks (locks in).

e. Return to the step in the MAP you were performing.

Exchange a TIC3 associated With the CBSP

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. If the machine has its:

- **Standby LED blinking**, go to step 3.
- **Standby LED ON**, press the 'Start' key on the 3746-950 control panel and continue according to the **Ready LED** status.
- **Ready LED ON**, go to step 2.
- **Ready LED blinking**, go to step 3.

2. The **Ready LED** is **ON**.

- From the service processor, return to the "MOSS-E VIEW" window and double click on the service processor icon.
- On the "Service Processor Menu" window, click on the "Configuration Management" option. Then double click on the "Manage 3745/3746-950 Installation/Removal" option.
- On the "Controller Installation" window, select the machine by clicking on the serial number of the machine for which you are called and click on "repair".
- On the "Repair Actions for 3746-950" window, select the "Change 3746-950 CBSA TIC3" option and click on "OK".
- The "Controller Repair Message" window is displayed. Perform the following steps before clicking on "OK".
- Locate the TIC3 cassette using Figure 4-10 on page 4-9.
- WARNING: Use the ESD kit and procedures.**
- Using the labels on the doors for reference, loosen the screws which secure the cable.
- Remove the cable.
- Press the two unlocking buttons and pull the cassette out.
- Exchange the TIC3 cassette.

- Insert the new TIC3 into the enclosure and slide it firmly until it clicks (locks in).

m. Replace the removed cable, then tighten the screws.

n. Do a service processor link restart from the 3746-950 control panel.

- Select function 6.
- Press the 'Validate' key.
- If you are not able to perform the preceding two steps, the problem is not in the TIC3. Remove the TIC3 that you have installed and reinstall the previous TIC3 (using the previous steps h to i). Then return to the step in the MAP you were performing.
- If you are able to start the service processor link restart check the control panel code and perform the specified action:

Panel code Action

05B0B0FD Return to the "Controller Repair Message" window and click on "OK". Then go to the next bullet.

05B0B0FE Suspect a microcode problem. Call your support.

05B0B0FF Suspect a microcode problem. Call your support.

Other Code Suspect a problem in other part of the machine. Remove the TIC3 that you have installed and reinstall the previous TIC3 (using the previous steps h to m). Return to the "Controller Repair Message" window and click on "Cancel". Then return to the step in the MAP you were performing.

- On the "Controller Installation" window, click on "Save".
- A new window prompts you to install the installation diskette in the service processor. When it is done click on "OK".
- A "Controller Saving Message" is displayed. Remove the diskette and click on "OK".
- The "Controller Installation" window is again displayed. Click on "Cancel".

- Return to the step in the MAP you were performing.

3. The **Standby LED** or the **Ready LED** is **blinking**

- From the service processor, return to the "MOSS-E VIEW" window and double click on the service processor icon.
- On the "Service Processor Menu" window, click on the "Configuration Management" option. Then double click on the "Manage 3745/3746-950 Installation/Removal" option.
- On the "Controller Installation" window, select the machine by clicking on the serial number of the machine for which you are called and click on "repair".
- On the "Repair Actions for 3746-950" window, select the "Change 3746-950 CBSA TIC3" option and click on "OK".
- The "Controller Repair Message" window is displayed. Perform the following steps before clicking on "OK".
 - Locate the TIC3 cassette using Figure 4-10 on page 4-9.
- WARNING: Use the ESD kit and procedures.**
- Using the labels on the doors for reference, loosen the screws which secure the cable.
 - Remove the cable.
 - Press the two unlocking buttons and pull the cassette out.
- Exchange the TIC3 cassette.
 - Insert the new TIC3 into the enclosure and slide it firmly until it clicks (locks in).
- Replace the removed cable, then tighten the screws.
- Do a service processor link restart from the 3746-950 control panel.
 - Select function 6.
 - Press the 'Validate' key.
 - If you are not able to perform the preceding two steps, the problem is not in the TIC3. Remove the TIC3 that you

have installed and reinstall the previous TIC3 (using the previous steps h to m). Then return to the step in the MAP you were performing.

- If you are able to start the service processor link restart, a general IML is started. A normal IML must be terminated by 00000000 displayed on the control panel and the ready LED ON after about 3 minutes. If the **standby LED** is **ON**, press the 'start' key to end the IML. In case a problem occurs during IML, a code is displayed on the control panel. This code can be flashing or steady (more than 60 seconds) while the ready LED is blinking. According to the control panel code displayed perform the specified action:

Panel code Action

00000000 Return to the "Controller Repair Message" window and click on "OK". Then go to the next bullet.

Other code Suspect a problem in other part of the machine. Remove the TIC3 that you have installed and reinstall the previous TIC3 (using the previous steps h to i). Return to the "Controller Repair Message" window and click on "Cancel". Then return to the step in the MAP you were performing.

- On the "Controller Installation" window, click on "Save".
- A new window prompts you to install the installation diskette in the service processor. When it is done click on "OK".
- A "Controller Saving Message" is displayed. Remove the diskette and click on "OK".
- The "Controller Installation" window is again displayed, click on "Cancel".
- Return to the step in the MAP you were performing.

Exchange a TIC3

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.

1. Locate the coupler cassette using Figure 4-10 on page 4-9.

2. **WARNING: Use the ESD kit and procedures.**

3. Loosen the screws which secure the cable.

4. Remove the cable.

5. Using the labels on the doors for reference, press the two unlocking buttons and pull out the cassette.

6. Exchange the TIC3 cassette.

7. Insert the new TIC3 cassette into the enclosure and slide it firmly in until it clicks (locks in).

8. Replace the removed cable, then tighten the screws.

9. Return to the step in the MAP you were performing.




Figure 4-40. 3746-950 TIC3 Coupler

Exchange a Transformer

Important

Check that the 'Power Control' display is set to local (3) on the control panel.

If not, do the following:

- Press the 'Power Control' key until (3) is displayed in the power control window.
- Press the 'Validate' key.

If the state of the machine does not allow you to display or to change the 'Power control' mode, continue with the following procedure.


Note

Two persons are necessary to move a transformer.

To exchange a transformer, you must first remove its associated ACPW.

1. Locate the transformer that you have to exchange and its associated ACPW, using Figure 4-9 on page 4-8 and Figure 4-10 on page 4-9.
2. If the machine has its:
 - **Ready LED ON**, go to step 3.
 - **Otherwise**, go to step 7.
3. Check if there is **another** ACPW or DCPW in your 3746-950.
If yes, go to step 6.
If not, proceed with the next step.
4. Press the 'Stand-by' key.
5. When the machine is in standby mode with its **Standby LED ON**, go to step 7.
6. Activate the maintenance switch.
 - a. Open the front cover and locate the lever of the maintenance switch on the DCDP. **1**
 - b. Pull the lever outwards.

This will prevent the main -48v from dropping and will stop the power monitoring.



7. Switch the main circuit breaker CB1 OFF at the 3746-950 primary power box **associated** with the transformer that you exchange. **2**
8. Unplug the J1 connector from the ACPW.
9. At the rear of the machine loosen the four screws which secure the transformer cover plate.
10. Remove the transformer cover plate.
11. Unplug the power cord from the J2 connector of the ACPW associated with the transformer that you want to remove. **3**
12. Check that on the transformer there is no voltage between TB1 position 1 and TB1 position 2, 3, or 4.
13. On TB1 and TB2, disconnect all wires coming from the ACPW **4** and note their position.
14. **If** you are exchanging the transformer of the basic ACPW, unplug connectors J11 and J12 from the rear of the DCDP.
For the backup ACPW, unplug connectors J9 and J10 from the rear of the DCDP.
15. Remove the screw holding the ACPW. **5**
16. Disconnect the two ground straps coming from the ACPW. **6**
17. At the front of the machine, remove the two screws holding the power box. Slide the ACPW out.

Note

When you remove the basic ACPW, if the backup ACPW is installed, you have to remove the bracket. **7**

18. Unscrew the two screws which secure the transformer to the frame.
19. At the rear of the machine, disconnect the two ground wires from the transformer.

20. Remove the two screws securing the transformer.
 21. At the front of the machine, slide the two bars **8** shipped with the new transformer into the brackets of the transformer that you want to remove.
 22. Install the other two bars **9** using the U-brackets **10** and secure them with screws and nuts as shown.
 23. At the rear of the machine, install the two latches **11** over the brackets of the transformer.
 24. Secure the latches with screws and nuts.
 25. Slide the transformer out (weight 34 kgs) to the rear of the machine.
- To install the new transformer,
1. Perform steps 21 to 24 to install the new transformer on the bars.
 2. Slide the transformer into the machine (from the rear to the front).
 3. Perform steps 20 to 6 of the procedure in reverse order.
 4. Return to the step in the MAP you were performing.




Figure 4-41. 3746-950 Transformers




Figure 4-42. 3746-950 Transformer Handling

CE Leaving Procedure

The maintenance package has determined that the 3746-950 is ready to be returned to normal operation.

- On the "MOSS-E VIEW" window, double click on the service processor icon.
- The "Service Processor Menu" window is displayed.
- Click on the "Configuration Management" option.
- Double click on the "Manage Remote Operations" option.
- On the "Remote Operation Management" window, select the "Remote operations authorization" option and click on "OK".
- On the "Remote Support Facility" window, select the two following options:
 - "Enable Remote Support Facility"
 - "Generate alerts"
 and click on "OK".
- Click on "Cancel" to return to "Service Processor Menu", then click on "Function" and "Exit" to return to the "MOSS-E View" window.
- On the "MOSS-E VIEW" window, click on "Program" in the action bar.
- Click on "Log off MOSS-E".

You should use the following list to ensure that the machine is in suitable condition for customer operation and that call information is recorded.

1. Replace any cables removed.
2. Do all actions that apply in the following list:

If You Have

Had the whole configuration

Disabled some channels

Put the 3746-950 Offline

Been working on the 3746-950 in current maintenance mode on processors or couplers.

What You Should Do

Ask the customer to IPL.

Ask the customer

- To re-enable them from the host.

Put the 3746-950 to online mode if not already done.

Use the CDF-E display function to check that the replaced/tested FRUs are available or active if not already done.

3. If you deactivate a resource via CCM do not forget to reactivate it (refer to "Activate/Deactivate a Resource Via CCM" on page 1-139), then continue the procedure from here.
4. Replace all covers and close the doors.
5. Leave the machine in a **safe** condition.
6. Record the actions taken and the FRUs replaced during the call.
7. Return parts to the stock room.

Appendix A. Maintenance Aids

Special Tools

Maintaining the 3746-950 requires using tools in addition to those in the IBM service representative's tool kit. The tools needed include:

General Purpose Tools

Tool	Qty	Part Nbr.
PT2-220 V	1	1749268
or		
PT2-110 V	1	1749269
PT3-220 V	1	6406001
or		
PT3-110 V	1	6406000
PT3-TPAM Acc. kit	1	83X9300
TPLM	1	1749290
Display	1	1749270
Digital voltmeter	1	8309874
	or	8496278
EIA breakout panel	1	453637
Oscilloscope	1	
either		
Tektronix 454**	459559	
Tektronix 475**	453215	
Tektronix 2235**	6428880	
Tektronix 2465 A**	8309847	
High voltage probes	2	453698

ESD kit

Part Name	Part Nbr.
ESD kit	6428316
This kit contains:	
ESD mat	6428274
Wristband (small size)	6428167
(large size)	6428169
ESD ground cord	6428166

Shipping Group Tools

The following tools are shipped with the 3746-950:

Tool	Qty	Part Nbr.
ESCON Wrap Plug	1	5605670
TIC-3 Wrap Plug	1	6165899
Filler (dummy card)	1	2733278
LIC11 Wrap Plug	1	58G9425
LIC12 Wrap Plug for X.21	1	58X9354
LIC12 Wrap Plug for V.35	1	58X9349

Wrap plugs for testing ARCs and cables (These wrap plugs must be installed on ARC cables)

ARC V.35 DTE Wrap Plug	1	61F4527
ARC V.35 DCE Wrap Plug	1	61F4526
ARC V.24 DTE Wrap Plug	1	61F4523
ARC V.24 DCE Wrap Plug	1	61F4522
ARC V.24 DCE/DTE 3745 Wrap Plug	1	61F4525
ARC V.35 DCE 3745 Wrap Plug	1	61F4528
ARC V.35 DTE 3745 Wrap Plug	1	61F4578
ARC X.21 DTE Wrap Plug	1	61F4530
ARC X.21 DCE Wrap Plug	1	61F4529
ARC X.21 DCE/DTE 3745 Wrap Plug	1	65X8927

ARC Wrap plug for ARC assembly B (These wrap plugs must be installed at the rear of the ARCs)

ARC V.24 Wrap Plug	1	58G5660
ARC V.35 Non 3745 Wrap Plug	1	58G5661
ARC V.35 DTE 3745 Wrap Plug	1	58G5658
ARC V.35 DCE 3745 Wrap Plug	1	58G5659
ARC X.21 Wrap Plug	1	58G5662

Service Processor Group Tools

The following tool is shipped with the service processor:

Tool	Qty	Part Nbr.
Integrated modem Wrap Plug	1	74F4508

Controller Expansion Group Tools

The following tool is shipped with the IBM controller rack containing the service processor and/or the network node processor

Tool	Qty	Part Nbr.
Spare fuse	2	58G5782

Appendix B. 3746 Model 950 Bibliography

Customer Documentation for the 3746 Model 950








Table B-1 (Page 1 of 4). Customer Documentation for the 3746 Model 950		
This customer documentation has the following formats:		
		
Finding Information		
3745 Models A and 3746 Books All of the books in the 3745 Models A and 3746 library are available on the CD-ROM that contains the Licensed Internal Code (LIC) for the machine.		
Preparing for Operation		
	GA33-0400	IBM 3745 Communication Controller All Models¹ IBM 3746 Expansion Unit Model 900 IBM 3746 Nways Multiprotocol Controller Model 950 Safety Information² Provides general safety guidelines.
Evaluating and Configuring		
	GA33-0180	IBM 3745 Communication Controller Models A and 170³ IBM 3746 Nways Multiprotocol Controller Models 900 and 950 Overview Gives an overview of connectivity capabilities within SNA, APPN, and IP networking.
	GA27-4234	IBM 3745 Communication Controller Models A² IBM 3746 Nways Multiprotocol Controller Models 900 and 950 Planning Series: Overview, Installation, and Integration Provides information for: <ul style="list-style-type: none"> • Overall 3746 planning • Installation and upgrade scenarios • Controller and service processor network integration • Related MOSS-E and CCM worksheets for these tasks.
	GA27-4235	IBM 3745 Communication Controller Models A² IBM 3746 Nways Multiprotocol Controller Models 900 and 950 Planning Series: Serial Line Adapters Provides information for: <ul style="list-style-type: none"> • Serial line adapter descriptions • Serial line adapter line weights and connectivity • Types of SDLC support • Configuring X.25 lines • Performance tuning for frame-relay, PPP, X.25, and NCP lines. • ISDN adapter description and configuration.

Table B-1 (Page 2 of 4). Customer Documentation for the 3746 Model 950



GA27-4236

IBM 3745 Communication Controller Models A²
IBM 3746 Nways Multiprotocol Controller
Models 900 and 950

Planning Series:
Token Ring and Ethernet

Provides information for:

- Token-ring adapter description and configuration
- Ethernet adapter description and configuration.



GA27-4237

IBM 3745 Communication Controller Models A²
IBM 3746 Nways Multiprotocol Controller
Models 900 and 950

Planning Series:
ESCON Channels

Provides information for:

- ESCON adapter descriptions
- ESCON configuration and tuning information
- ESCON configuration examples.



GA27-4238

IBM 3745 Communication Controller Models A²
IBM 3746 Nways Multiprotocol Controller
Models 900 and 950

Planning Series:
Physical Planning

Provides information for:

- 3746 and MAE physical planning details
- 3746 and MAE cable information
- Explanation of installation sheets
- 3746 plugging sheets.



GA27-4239

IBM 3745 Communication Controller Models A²
IBM 3746 Nways Multiprotocol Controller
Models 900 and 950

Planning Series:
Management Planning

Provides information for:

- Overview for 3746
- 3746 APPN/HPR, IP router, and X.25
- NetView Performance Monitor (NPM), remote consoles, and RSF
- MAE APPN/HPR management.



GA27-4240

IBM 3745 Communication Controller Models A²
IBM 3746 Nways Multiprotocol Controller
Models 900 and 950



Planning Series:
Multiaccess Enclosure Planning

Provides information for:

- MAE adapters details
- MAE ESCON planning and configuration
- ATM and ISDN support.

Table B-1 (Page 3 of 4). Customer Documentation for the 3746 Model 950


	GA27-4241	IBM 3745 Communication Controller Models A² IBM 3746 Nways Multiprotocol Controller Models 900 and 950
		Planning Series: Protocols Description
		Provides information for: <ul style="list-style-type: none"> • Overview and details about APPN/HPR and IP.
	On-line information	IBM 3745 Communication Controller Models A² IBM 3746 Nways Multiprotocol Controller Models 900 and 950
		Planning Series: Controller Configuration and Management Worksheets
		Provides planning worksheets for ESCON, Multiaccess Enclosure, serial line, and token-ring definitions.
Operating and Testing		
	SA33-0356	IBM 3746 Nways Multiprotocol Controller Model 950
		User's Guide²
		Explains how to: <ul style="list-style-type: none"> • Carry out daily routine operations on Nways controller • Install, test, and customize the Nways controller after installation • Configure user's workstations to remotely control the service processor using: <ul style="list-style-type: none"> – DCAF program – Telnet client program – Java Console support.
	On-line information	Controller Configuration and Management Application Provides a graphical user interface for configuring and managing a 3746 APPN/HPR network node and IP Router, and its resources. It is also available as a stand-alone application, using an OS/2 workstation. Defines and explains all the 3746 Network Node and IP Router configuration parameters through its on-line help.
	SH11-3081	IBM 3746 Nways Multiprotocol Controller Models 900 and 950
		Controller Configuration and Management: User's Guide²
		Explains how to use CCM and gives examples of the configuration process.
	GA33-0479	IBM 3745 Communication Controller Models A IBM 3746 Nways Multiprotocol Controller Models 900 and 950
		NetView Console APPN Command Reference Guide
		Explains how to use the RUN COMMAND from the NetView S/390 Program and gives examples.

Table B-1 (Page 4 of 4). Customer Documentation for the 3746 Model 950		
Managing Problems		
	On-line information	<p>Problem Analysis Guide</p> <p>An on-line guide to analyze alarms, events, and control panel codes on:</p> <ul style="list-style-type: none"> • IBM 3745 Communication Controller Models A³ • IBM 3746 Nways Multiprotocol Controller Models 900 and 950.
	SA33-0175	<p>IBM 3745 Communication Controller Models A³ IBM 3746 Expansion Unit Model 900 IBM 3746 Nways Multiprotocol Controller Model 950</p> <p>Alert Reference Guide</p> <p>Provides information about events or errors reported by alerts for:</p> <ul style="list-style-type: none"> • IBM 3745 Communication Controller Models A³ • IBM 3746 Nways Multiprotocol Controller Models 900 and 950.
<p>¹ Models 130 to 61A. ² Documentation shipped with the 3746-950 ³ 3745 Models 17A to 61A.</p>		

Service Documentation for the IBM 3746 Model 950

Table B-2 (Page 1 of 3). Service Documentation for the 3746 Model 950

This service documentation has the following formats:









	SY33-2107	<p>IBM 3746 Nways Multiprotocol Controller Model 950 Installation Guide¹</p> <p>Provides instructions for installing or relocating the Nways Controller.</p>
	SY33-2108	<p>IBM 3746 Nways Multiprotocol Controller Model 950 Service Guide¹</p> <p>Provides procedures for isolating and fixing the IBM 3746-950 problems.</p>
	SY33-2115	<p>IBM 3745 Communication Controller Models A² IBM 3746 Expansion Unit Model 900 IBM 3746 Nways Multiprotocol Controller Model 950 Service Processor Installation and Maintenance³ (Based on the 7585, 3172, 9585, or 9577)</p> <p>Provides information on installing and maintaining the service processor based on PS/2 Types 7585, 3172, 9585, or 9577. Can be for systems with micro-code that has up to and including EC D46130 (any level) installed.</p>
	SY33-2120	<p>IBM 3745 Communication Controller Models A³ IBM 3746 Expansion Unit Model 900 IBM 3746 Nways Multiprotocol Controller Model 950 Service Processor Installation and Maintenance⁴ (Based on the 7585, 3172, or 9585)</p> <p>Provides information on installing and maintaining the service processor based on PS/2 Types 7585, 3172, or 9585. Can be for systems with microcode EC F12380 or higher installed.</p>
	SY33-2125	<p>IBM 3745 Communication Controller Models A³ IBM 3746 Expansion Unit Model 900 IBM 3746 Nways Multiprotocol Controller Model 950 Service Processor Installation and Maintenance⁴ (Based on 6275)</p> <p>Provides information on installing and maintaining the service processor based on PS/2 Type 6275. Can be for systems with microcode EC F12380 or higher installed.</p>
	SY33-2118	<p>IBM 3746 Nways Multiprotocol Controller Models 900 and 950 Multiaccess Enclosure Installation and Maintenance⁴</p> <p>Provides information on installing and maintaining the Multiaccess Enclosure (MAE).</p>










Table B-2 (Page 2 of 3). Service Documentation for the 3746 Model 950		
	SY33-2124	<p>IBM 3746 Nways Multiprotocol Controller Models 900 and 950</p> <p>Multiaccess Enclosure Installation and Maintenance⁴ (Starting from EC F12430 and Above)</p> <p>Provides information on installing and maintaining the Multiaccess Enclosure (MAE). For systems with microcode EC F12430 or higher installed.</p>
	SY33-2112	<p>IBM 3746 Nways Multiprotocol Controller Models 900 and 950</p> <p>Network Node Processor Installation and Maintenance³ (Based on the 7585 or 3172)</p> <p>Provides information on installing and maintaining the network node processor based on the PS/2 Type 7585 or 3172.</p>
	SY33-2126	<p>IBM 3746 Nways Multiprotocol Controller Models 900 and 950</p> <p>Network Node Processor Installation and Maintenance³ (Based on 6275)</p> <p>Provides information on installing and maintaining the network node processor based on the PS/2 Type 6275.</p>
	SY33-2127	<p>IBM 3745 Communication Controller Models A³ IBM 3746 Expansion Unit Model 900 IBM 3746 Nways Multiprotocol Controller Model 950</p> <p>Service Processor and Network Node Processor⁴ Service User's Guide</p> <p>Provides information on installing and maintaining the operational code on service processor, or network node processor. Can be for systems with microcode EC F12380 or higher installed.</p>
	SY33-2117	<p>IBM 3746 Nways Multiprotocol Controller Models 900 and 950</p> <p>External Cable Reference⁴</p> <p>Provides references to console and line cables used for connecting the IBM 3746 Models 900 and 950.</p>
	S135-2015	<p>IBM 3746 Nways Multiprotocol Controller Models 900 and 950</p> <p>Parts Catalog⁴</p> <p>Provides reference information for ordering parts for the IBM 3746 Models 900 and 950.</p>
	S135-2014	<p>IBM Controller Expansion</p> <p>Parts Catalog</p> <p>Provides reference information for ordering parts for the controller expansion attached to the IBM 3745 Models A², and 3746 Models 900 and 950.</p>
CD-ROM Bibliography		
	ZK2T-8214	<p>IBM Networking Softcopy Collection Kit</p> <p>Allows service manuals consulting via CD-ROM viewer. EMEA version.</p>

Table B-2 (Page 3 of 3). Service Documentation for the 3746 Model 950		
	ZK2T-8187	IBM Networking Softcopy Collection Kit Allows service manuals consulting via CD-ROM viewer. US version.
<p>¹ Documentation shipped with the 3746 Model 950</p> <p>² 3745 Models 17A to 61A</p> <p>³ Documentation shipped with the processor</p> <p>⁴ Documentation shipped with the 3746 Models 900 and 950</p>		

Related Signal Converter Products Information

The following publications relate to IBM signal converter products and are currently available:

- *7861 Description and Planning Guide*, GA33-0122.
- *7861 Setup, User's Guide, and Problem Determination*, SA33-0123.
- *7861 Maintenance Information and Parts Catalog*, SY33-2062.
- *7868 Guide to Operation*, GA33-0134.
- *5822-10 Guide to Operation*, GA33-0118.
- *5822-18 Guide to Operation*, GA33-0136.
- *Link Problem Determination Aid*, SY33-2064.
- *Power Supply and Telecommunication Connections*, GA33-0054.
- *7855 Guide to Operation*, GA33-0160.
- *IBM 7857 Modem, Guide to Operation*, GA13-1839.
- *IBM Asynchronous/SDLC V.32 Modem/A: Installation, Operation, and Problem Determination Guide*, SA27-3955.

World Wide Web

You can access the latest news and information about IBM network products, customer service and support via the internet, at the Universal Resource Locator (URL):

<http://www.networking.ibm.com>

Glossary

ac. alternating current

ACPW. AC power (box)

AFD. airflow detector

alarm. A message sent to the MOSS console. In case of an error a reference code identifies the nature of the error.

alert. A message sent to the host console. In case of an error a reference code identifies the nature of the error.

AMD. air moving device

APPN. advanced peer-to-peer networking

ARC. active remote connector

ARC1A1. ARC V.24 DCE attachment with 5 meter tethered cable

ARC1A2. ARC V.24 DCE attachment with 15 meter tethered cable

ARC1B. ARC V.24 DTE attachment with 15 meter tethered cable

ARC1C. ARC V.24 DCE 3745 interface with 5 meter tethered cable

ARC1D. ARC V.24 DTE 3745 interface with 5 meter tethered cable

ARC1E. ARC V.24 3174 AEA interface (1)

ARC1F. ARC V.24 3174 PCA EIA interface (1)

ARC2A. ARC V.25 autocall interface with 5 meter tethered cable

ARC2C. ARC V.25 autocall interface 3745 with 5 meter tethered cable

ARC3A1. ARC V.35 DCE attachment with 5 meter tethered cable

ARC3A2. ARC V.35 DCE attachment with 15 meter tethered cable

ARC3B. ARC V.35 DTE attachment with 15 meter tethered cable

ARC3C. ARC V.35 DCE 3745 interface with 5 meter tethered cable

ARC3D. ARC V.35 DTE 3745 interface with 5 meter tethered cable

ARC4A1. ARC X.21 DCE attachment with 5 meter tethered cable

ARC4A2. ARC X.21 DCE attachment with 15 meter tethered cable

ARC4B. ARC X.21 DTE attachment with 15 meter tethered cable

ARC4C. ARC V.21 DCE 3745 interface with 5 meter tethered cable

ARC4D. ARC V.21 DTE 3745 interface with 5 meter tethered cable

ARC5A. Reserved

ARC5B. Reserved

ARC5C. ARC RS-422 3708 interface (or RJ-11 connection) (1)

ARC5D. ARC RS-422 IBM Cabling System interface (1)

ARC6A. ARC V.25 autocall interface with 15 meter tethered cable

ARC6C. ARC V.25 autocall 3745 interface with 15 meter tethered cable

BA. basic access

BAS. basic board

BATS. basic assurance tests

BER. box event record

BLPU. basic level packaging unit

BMI. bit multiplex interface

box event record (BER). Information about an event detected by the controller. It is recorded on the disk/diskette and can be displayed on the operator console for event analysis.

bps. bits per second

BSC. binary synchronous communication

BSI. bus synchronism interface

C. Celsius

C&SM. customer and service information

CA. channel adapter

cache. A high-speed buffer storage that contains frequently accessed instructions and data; it is used to reduce access time.

CB. circuit breaker

CBA. controller bus adapter

CBC. controller bus coupler

CBR. circuit burst request

CBSA. controller bus and service adapter
(CBSP+CBC+TIC3)

CBSP. controller bus and service processor

CBTRA. controller bus and token-ring adapter
(TRP+CBC+TIC3)

CBTRM. cable terminator (IOC and DMA buses)

CCITT. Comite Consultatif International Telephonique
et telegraphique

CCU. central control unit

CDF. configuration data file (3745)

CDF-E. configuration data file extended (37CS)

CE. customer engineer

CEPT. Comite Europeen des Postes et Telecommuni-
cations

CLA. communication line adapter (CLP+LICnn)

CLDP. controller load/dump program

clear channel. Mode of data transmission where the data passes through the DCE and network, and arrives at the receiving communication controller (for example, the IBM 3745) unchanged from the data transmitted. The DCE or network can modify the data during transmission because of certain network restrictions, but must ensure the received data stream is the same as the transmitted data stream.

CLP. communication line processor

CMIP. common management interface protocol

CNM. communication network management

CP. 1.communication processor 2.control program
3.circuit protector 4.control point

CPLR. coupler

CPN. customer problem number

CPx. FRU name of circuit protector

CRC. cyclic redundancy check character

CS. connectivity switch

CSA. common subassembly

CSB. connectivity switch bus

CSC. connectivity switch cable

CSCE. connectivity switch cable extension

CSM. centralized support module

CSP. central service point

CSS. control subsystem (3745)

CTDA. configuration target device (processor) address

dc. direct current

DCAF. Distributed Console Access Facility (licensed
program)

DCCS. DC to connectivity subsystem

DCE. data circuit-terminating equipment

DCDP. DC distribution and protection (box)

DCM. diagnostic control monitor

DCPW. DC power box

DICO. DMA IOC connection card

DM. distribution manager

DMA. direct memory access

DS. data storage

DSB. data storage bus

DSI. data storage interface

DSM. data storage manager

DSS. data storage interface for SBA

DSU. data service unit (DCE-like for high-speed com-
munication lines)

DTE. data terminal equipment

EC. engineering change

EE. extended edition	initial program load (IPL). The initialization procedure that causes the 3745 control program to commence operation.
EIA. Electronic Industries Association	IO. input/output
EPO. emergency power-off	IOC. input/output control
EPROM. eraseable PROM	IOCB. input/output control bus
ESCA. ESCON adapter	IPL. initial program load
ESCC. ESCON coupler	IRAM. instruction random access memory
ESCON*. Enterprise Systems Connection	ISO. International Organization for Standardization
ESCP. ESCON processor	kbps. kilobits per second
ESD. electrostatic discharge	LA. line adapter
EXP. expansion enclosure	LAN. local area network
EXP1. first expansion enclosure	LCB. line connection box
EXP2. second expansion enclosure	LED. light-emitting diode
FCS. frame check sequence	LIC. line interface coupler
FRU. field-replaceable unit	LICx. FRU name of line interface coupler type x (3745)
HCS. Hardware Central Service	LLC. logical link control
HDLC. high-level data link control	LS. local storage
hex. hexadecimal	LSA. link service architecture
host processor. (1) A processor that controls all or part of a user application network. (2) In a network, the processing unit in which the access method for the network resides. (3) In an SNA network, the processing unit that contains a system services control point (SSCP). (4) A processing unit that executes the access method for attached communication controllers. Also called <i>host</i> .	LSCT. LIM software configuration table
HPPB. high-performance parallel bus	LSM. local storage manager
HSC. hardware support center	LSSD. level-sensitive scan design (total hardware latches chain collection)
HSF. hardware service facility	LU. logical unit
Hz. Hertz	MAC. medium access control
IBM service representative. An individual in IBM who performs maintenance services for IBM products or systems.	MAE. Multiaccess enclosure
IEEE. Institute of Electrical and Electronics Engineers	MAP. maintenance analysis-procedure
IML. initial microcode load	MAU. multistation access unit
initial microcode load (IML). The process of loading the microcode into a scanner or into MOSS.	MB. megabyte; 1 048 576 bytes
	MCF. microcode fix
	MCL. microcode change level
	MES. miscellaneous equipment specification
	MG. motor generator

MI. maskable interrupt

microcode. A program, that is loaded in a processor (for example, the MOSS processor)

MLA. MOSS LAN adapter

MMIO. memory mapped input/output

maintenance and operator subsystem (MOSS). The part of the controller that provides operating and servicing facilities to the customer's operator and the IBM service representative.

MOSS. maintenance and operator subsystem (3745)

MOSS-E. maintenance and operator subsystem extended (37CS)

NA. network addressable

NCP. Network Control Program

NDM. netview distribution manager

NetView. An IBM licensed program used to monitor a network, manage it, and diagnose its problems.

Network Control Program (NCP). An IBM licensed program that provides communication controller support for single-domain, multiple-domain, and interconnected network capability.

NMI. non-maskable interrupt

NMVT. network management vector transport

NNP. network node processor

NODA. next origin device (processor) address

NPM. NetView performance monitor

NTDA. next target device (processor) address

OEMI. original equipment manufacturer's interface

OLT. online test

online tests. Testing of a remote data station concurrently with the execution of the user's programs (that is, with only minimal effect on the user's normal operation).

OSI. open system interconnect

PA. primary access

PBC. packet burst control

PBG. packet burst grant

PCR. 1.pico-processor command register 2.power check reset

PICA. process and intertask communication architecture

PMH. problem management hardware

PN. part number

PNL. control panel

POR. power-ON reset

PP. pico-processor

PPB. primary power box

PPC. PowerPC (system card of MAE)

PRC. processor

PRDA. packet request device (processor) address

PROM. programable read-only memory

PS. power supply

PSI. packet switch interface

PSN. public switched network

PTCE. product-trained CE

PTF. program temporary fix

PTT. Post, Telephone and Telegraph (agency)

PU. physical unit

RETAIN. Remote Technical Assistance Information Network

RNR. receiver not ready

RPL. remote program load

RPO. remote power-off

RSC. remote service center

RSF. remote support facility

RVX. stands for RS232, RS422, V.24-35, X.21-2x connections

SAC. switch adapter card

SATS. specific assurance tests

SBA. switch bus adapter

SBI. switch bus interface

SC. switch control

SDLC. synchronous data link control

SIE. switch interface extender

SL. service logic

SNA. Systems Network Architecture

SNMP. Simple network management protocol

SPD1. signal and power distribution type 1

SPD2. signal and power distribution type 2

SPDL. signal and power distribution card in LCB

SPS. service and power support

SQL. structured query language

SRC. system reference code

SSA. system service architecture

SSCP. system services control point

STCn. signal transfer card n

SSS. subsystem support service

Systems Network Architecture (SNA). The description of the logical structure, formats, protocols, and operational sequences for transmitting information through a user application network. The structure of SNA allows the users to be independent of specific telecommunication facilities.

TB. terminator block

TDM. time division multiplexing

TDR. technical data record

TERC. terminator card

TIC1. token-ring interface coupler type 1 (3745) running at speed of 4 Mbits

TIC2. token-ring interface coupler type 2 (3745) running at speed of 4 or 16 Mbits

TIC3. token-ring interface coupler type 3 (37CS) running at speed of 4 or 16 Mbits

time out. The time interval allotted for certain operations to occur.

TPS. two-processor switch

TR. token-ring

TRA. token-ring adapter (TRP+TIC3)

TRFM. transformer

TRP. token-ring processor

TRS. transmitter/receiver subassembly

UEPO. unit emergency power-off

URSF. universal remote support facility

UTP. Unshielded twisted pair cable

V. volt

V.24. CCITT V.24 recommendation

V.25. CCITT V.25 recommendation

V.28. CCITT V.28 recommendation

V.35. CCITT V.35 recommendation

VPD. vital product data

VTAM*. Virtual Telecommunications Access Method

VTL. vendor technology logic

W. watt

X.21. CCITT X.21 recommendation

X.25. CCITT X.25 recommendation

YZxxx. wiring diagram

Tell Us What You Think!

**3746 Nways Multiprotocol Controller
Model 950
Service Guide**

Publication No. SY33-2108-04

We hope you find this publication useful, readable, and technically accurate, but only you can tell us! Your comments and suggestions will help us improve our technical publications. Please take a few minutes to let us know what you think by completing this form. If you are in the USA, you can mail this form postage free or fax it to us at 1-800-253-3520. Elsewhere, your local IBM branch office or representative will forward your comments or you may mail them directly to us.

Overall, how satisfied are you with the information in this book?	Satisfied	Dissatisfied
	<input type="checkbox"/>	<input type="checkbox"/>

How satisfied are you that the information in this book is:	Satisfied	Dissatisfied
Accurate	<input type="checkbox"/>	<input type="checkbox"/>
Complete	<input type="checkbox"/>	<input type="checkbox"/>
Easy to find	<input type="checkbox"/>	<input type="checkbox"/>
Easy to understand	<input type="checkbox"/>	<input type="checkbox"/>
Well organized	<input type="checkbox"/>	<input type="checkbox"/>
Applicable to your task	<input type="checkbox"/>	<input type="checkbox"/>

Specific comments or problems:

Please tell us how we can improve this book:

Thank you for your comments. If you would like a reply, provide the necessary information below.

Name	Address
------	---------

Company or Organization	
-------------------------	--

Phone No.	
-----------	--




Fold and Tape

Please do not staple

Fold and Tape



NO POSTAGE
NECESSARY
IF MAILED IN THE
UNITED STATES



BUSINESS REPLY MAIL

FIRST-CLASS MAIL PERMIT NO. 40 ARMONK, NEW YORK

POSTAGE WILL BE PAID BY ADDRESSEE

Design & Information Development
Dept. CGF/Bldg. 656
International Business Machines Corporation
PO BOX 12195
RESEARCH TRIANGLE PARK NC 27709-9990



Fold and Tape

Please do not staple


Fold and Tape



Part Number: 29H4706



Printed in the United States of America
on recycled paper containing 10%
recovered post-consumer fiber.



SY33-2108-04



29H4706

