

TELEVISION TECHNICAL BULLETIN

MODELS DV5161H

SYMPTOM Set occasionally goes to standby. Problem can sometimes be very intermittent.

CAUSE D602 going high resistance intermittently.

ACTION Replace D602, using the part number given below.

<u>REF NO</u>	<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>PRICE CODE</u>
D602	Diode	RH-DX0507BMZZ	AB