

Sony Service Company - Technical Services
 A Division of Sony Electronics Inc.
 Sony Drive, Park Ridge, New Jersey 07656

Model: SDP-505ES, SDP-777ES

No. 482

Subject: SERVICING IC406/503

Date: April 29, 1996

Symptom
 (**)

IC NE657N (8-759-927-57), referenced IC504 (SDP-505ES) and IC503 (SDP-777ES) is no longer available, it is necessary to perform the following modification when this part needs servicing.

Solution: SDP-505ES:

1. Remove IC406 (NE657N), C414/C514 (1UF, 50V), C419/C519 (10UF, 25V) from the Analog Board.
2. Add a jumper wire between the negative leads of C414 & C419 as well as between C514 & C519.

SDP-777ES:

1. Remove IC503 (NE657N), C525/C535 (1UF, 50V), C301/C302 (10UF, 50V) from the Main Board.
2. Add a jumper wire between the negative leads of C535 & C301 as well as between C525 & C302.

