Canon

Service Information

Copyright Canon (UK) Limited

Model : **Network Printer Board-F1**
Network Multi PDL Printer Board-H1 ← ①
Network Multi PDL Printer Board-K1

Ref. No. : 99-OIPD0-B0037-01

Date : June 4, 1999

Approved by : *Shinya Kishimoto*

REVISED   99-OIPD0-B0037 : Additional Information

Location : SYSTEM SOFTWARE

Subject : PATCH FILE 52726.PS & 52726.EFI ← ① RELEASE

Reason : Defect Modification

Patch file 52726.ps(file size = 60,602 bytes) and 52726.efi (file size = 81932 bytes) ← ① was released to modify the defect that the PDL Board reboots if data is printed when the username has 64 bytes or more under the Novell NDS environment in Network Printer Board-F1 v1.0/1.01a and Network Multi PDL Printer Board-H1/K1 v1.0

Resolution:

Increased the number of acceptable user characters to 520.

Installation Notes :

= For Network Printer board-F1 and Network Multi PDL Board-H1
1. Download the 52726.ps to the print or direct queue with Firey Downloader
2. Reboot the system.
3. Print the configuration page and check that "NET.04.14.99" is printed out in Update Information on the configuration page.
4. From the NDS client login to the network as one of the existing users.
5. Print a Job.

= For Network Printer board-K1 ← ①
1. Select "Setup" at Boot up screen.
2. Install the Software through the parallel port.
3. Download the file 52726.efi with PDL Downloader.
4. Exit Setup and reboot.
5. Print the configuration page and check that "52726" is printed out in Update Information on the configuration page.
6. From the NDS client login to the network as one of the existing users.
7. Print a job.

Remark :

1. ~~This patch file cannot be used in Networ k Printer Board -K1. We ha ve requested EF I to create a patch file for Netwo k Printer Board K1 currentl y.~~
2. Althou gh the sa me defect occurs in Netwo k Multi PDL Board -D1/E1, it will be modified in Version 2.