

# Changes from CX23887-14Z to CX23887-15Z

## Product Bulletin

**Products Affected:** CX23887-14Z and CX23887-15Z

Conexant Systems, Inc. is committed to offering its valued customers quality products. To ensure that commitment, Conexant from time to time, must evaluate the features and cost-effectiveness of its current product lines.

Please note the following changes from CX23887-14Z to CX23887-15Z:

- ◆ A Silicon change was made to correct a link training compatibility problem with PCIe 2.0 chipsets that prevents the CX23887-14Z from enumerating in a PCI Express 2.0 slot.
- ◆ The Rev ID has been incremented from 0x0F (CX23887-14Z) to 0x0E (CX23887-15Z).

Samples of the CX23887-15Z will be available in December, 2007, while production quantities will be supported in March, 2008.

*NOTE:*

Although we will continue to support the CX23887-14Z, the CX23887-15Z will be the production version of the device and is recommended for all new designs.

Conexant appreciates and values our business relationship and looks forward to your continued interest in its products. While we regret any inconvenience this announcement may cause, we are eager to supply your future requirements with our world class quality product lines. If you should have any questions, please call your nearest Conexant Sales Office.