

GPA Group plc

PAGE	DATE	CODE	PAGE	DATE	CODE	PAGE	DATE	CODE
CHAPTER 78 TAB			78-34-00	CONFIG 1	CONT.	78-36-00	CONFIG 2	
EXHAUST			123	JAN 20/99	R07	101	SEP 20/98	R01
EFFECTIVE PAGES			124	JAN 20/99	R03	102	SEP 20/98	R01
SEE LAST PAGE OF LIST FOR			125	JAN 20/99	R07	103	SEP 20/98	R01
NUMBER OF PAGES			126	JAN 20/99	R07	104	MAY 28/03	R01
			127	JAN 20/99	R07	105	MAY 28/06	R02
			128	BLANK		106	MAY 28/06	R02
			78-34-00	CONFIG 2		107	JAN 28/05	R02
78-CONTENTS			101	SEP 20/98	R01	108	JAN 28/05	R02
1	SEP 28/99	RGUI	102	SEP 20/98	R01	109	JAN 28/05	R02
R 2	MAY 20/09	RGUI.1	103	SEP 20/98	R01	110	JAN 28/05	R02
R 3	MAY 20/09	RGUI.1	104	SEP 20/98	R01	111	JAN 28/05	R02
R 4	MAY 20/09	RGUI.1	105	SEP 20/98	R01	112	JAN 28/05	R02
78-FAULT CODE INDEX			106	SEP 20/98	R01	113	JAN 28/05	R02
1	SEP 20/08	R03	107	SEP 20/98	R01	114	JAN 28/05	R06
2	SEP 20/08	R04	108	SEP 20/98	R01			
3	SEP 20/08	R03	109	SEP 20/98	R01			
4	SEP 20/08	R03	110	JAN 20/99	R01			
5	SEP 20/08	R04	111	JAN 20/99	R01			
6	BLANK		112	JAN 28/01	R03			
78-11-00			113	JAN 20/99	R01			
101	SEP 20/94	R01	114	JAN 20/99	R01			
102	SEP 20/94	R01	115	JAN 20/99	R01			
78-31-00			116	JAN 20/99	R01			
101	JUN 15/86	R02	117	JAN 20/99	R01			
102	JUN 15/86	R02	118	JAN 20/99	R01			
103	MAY 20/98	R01	119	JAN 20/99	R01			
104	JUN 15/84	R01	120	JAN 20/99	R01			
105	JUN 15/84	R01	121	JAN 28/03	R01			
106	JUN 20/97	R01	122	JAN 28/03	R01			
78-34-00 CONFIG 1			123	JAN 28/03	R01			
101	SEP 20/98	R07	124	JAN 28/03	R01			
102	SEP 20/98	R01	125	JAN 28/03	R01			
103	SEP 20/98	R01	126	JAN 28/03	R01			
104	SEP 20/98	R01	127	JAN 28/03	R01			
105	SEP 20/98	R01	128	JAN 28/03	R01			
106	SEP 20/98	R01	129	JAN 28/03	R01			
107	SEP 20/98	R01	130	JAN 28/03	R01			
108	SEP 20/98	R01	131	JAN 28/03	R02			
109	JAN 20/99	R01	132	BLANK				
110	JAN 20/99	R01	78-36-00	CONFIG 1				
111	JAN 20/99	R07	101	SEP 20/98	R07			
112	JAN 20/99	R01	102	SEP 20/98	R01			
113	JAN 20/99	R07	103	SEP 20/98	R01			
114	JAN 20/99	R05	104	MAY 28/03	R03			
115	JAN 20/99	R07	105	SEP 20/98	R07			
116	JAN 20/99	R04	106	JAN 28/05	R01			
117	JAN 20/99	R01	107	JAN 28/05	R01			
118	JAN 20/99	R01	108	JAN 28/05	R01			
119	JAN 20/99	R01	109	JAN 28/05	R01			
120	JAN 20/99	R01	110	JAN 28/05	R01			
121	JAN 20/99	R07	111	JAN 28/05	R01			
122	JAN 20/99	R03	112	JAN 28/05	R01			
			113	JAN 28/05	R07			
			114	BLANK				

R = REVISED, A = ADDED OR D = DELETED  
 F = FOLDOUT PAGE  
 32  
 MAY 20/09

**D633N632**

CHAPTER 78  
 EFFECTIVE PAGES  
 R PAGE 1  
 LAST PAGE

## CHAPTER 78 - EXHAUST

TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
FAULT ISOLATION	78-FAULT CODE INDEX	1	ALL
<u>EXHAUST</u>	78-00-00		
<u>COLLECTOR/NOZZLE</u>	78-10-00		
TURBINE EXHAUST SYSTEM	78-11-00		
Component Location		101	ALL
Component Index			
Component Location			
<u>THRUST REVERSER</u>	78-30-00		
THRUST REVERSER SYSTEM	78-31-00		
Component Location		101	ALL
Component Index			
Component Location			

# 78-CONTENTS

CHAPTER 78 - EXHAUST

TABLE OF CONTENTS

<u>Subject</u>	Chapter Section <u>Subject</u>	<u>Page</u>	<u>Effectivity</u>
THRUST REVERSER CONTROL SYSTEM	78-34-00		
Component Location		101	CONFIG 1 [*]
Component Index			
Component Location			
Fault Isolation			
Rev Thrust Selected With REV Amber REV ISLN Light and REV ISLN VAL EICAS Message (Fig. 106)		115	
REV ISLN Lgt/REV ISLN VAL EICAS Msg Displayed After T.O. (Fig. 110)		121	
REV ISLN Lgt/REV ISLN VAL EICAS Msg Displayed During Rev Thrust (Fig. 112)		125	
REV ISLN Light and REV ISLN VAL EICAS Message Displayed only when Eng(s) are Shut Down and Hyd Pumps are off. Reversers are Stowed (Fig. 114)		127	
REV ISLN Light On and EICAS REV ISLN VAL Message Displayed during Rev Thrust and on the Ground (Fig. 113)		126	
REV ISLN Light On and EICAS REV ISLN VAL Message Displayed After T.O. and After Landing or After T.O. and After Eng Shutdown With Hyd. Pumps Off (Fig. 111)		123	
T/R Deployed, Reverse Thrust Could Not Be Advanced Beyond Idle (Fig. 103)		110	
T/R Did Not Deploy Isolation Valve Opened (Fig. 107)		117	
T/R Operation Slow (Fig. 109)		119	
T/R Partially Deployed (Fig. 104)		111	
T/R Remained Deployed (Fig. 108)		118	

## 78-CONTENTS

CHAPTER 78 - EXHAUST

TABLE OF CONTENTS

<u>Subject</u>	<u>Chapter Section Subject</u>	<u>Page</u>	<u>Effectivity</u>
Thrust Reverser Remained Fully or Partially Deployed with REV Green or Amber Light On and with REV ISLN Light On and REV ISLN VAL EICAS Message (Fig. 105)		113	
[*] AIRPLANES WITHOUT SYNC-LOCKS			
Component Location		101	CONFIG 2 [*]
Component Index			
Component Location			
Fault Isolation			
(L,R) REV ISLN VAL EICAS Msg During Reverse Thrust (Fig. 109)		126	
(L,R) REV ISLN VAL EICAS Msg. (Fig. 107)		121	
"(L,R) REV ISLN VAL" EICAS Message Displayed only When Eng(s) are Shut Down and Hyd Pumps are Off. Reversers are Stowed. (Fig. 104)		112	
Fwd Thrust Selected. REV Green or REV Amber Shown. Fwd Thrust Levers Could Not Move Fwd (Fig. 110)		127	
FWD Thrust Selected. No REV Amber. No REV Green. FWD Thrust Lever Could Move FWD. Time to FWD Thrust to Slow (Fig. 106)		119	
REV Selected. REV Amber or No REV Amber. No REV Green. REV Thrust Lever Could Not Move To Full REV. (Fig. 105)		113	
T/R Deployed, Reverse Thrust Could Not Be Advanced Beyond Idle (Fig. 103)		111	
T/R Sync Lock Does Not Unlock (Fig. 111)		130	
Time to REV Thrust Too Slow (Fig. 108)		124	

## 78-CONTENTS

CHAPTER 78 – EXHAUST

TABLE OF CONTENTS

<u>Subject</u>	<u>Chapter Section Subject</u>	<u>Page</u>	<u>Effectivity</u>
[*] AIRPLANES WITH SYNC-LOCKS			
THRUST REVERSER POSITION INDICATING SYSTEM	78-36-00		
Component Location		101	CONFIG 1 [*]
Component Index			
Component Location			
Fault Isolation			
Amber REV Did Not Display, Green REV Did With T/R Fully Deployed (Fig. 104)		105	
Amber REV Remained Displayed After Full Reverse Was Reached (Fig. 103)		104	
T/R Stowed, Amber REV Remained Displayed (Fig. 105)		106	
Thrust Reverser Position Indication System Problem (Fig. 106)		113	
[*] AIRPLANES WITHOUT SYNC-LOCKS			
Component Location		101	CONFIG 2 [*]
Component Index			
Component Location			
Fault Isolation			
Amber REV Did Not Display, Green REV Did With T/R Fully Deployed (Fig. 104)		105	
Amber REV Remained Displayed After Full Reverse Was Reached (Fig. 103)		104	
T/R Stowed, Amber REV Remained Displayed (Fig. 105)		107	
Thrust Reverser Position Indication System Problem (Fig. 106)		114	
[*] AIRPLANES WITH SYNC-LOCKS			

## 78-CONTENTS

FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
78 34 XA --	(01=L,02=R) Reverser deploy problem was encountered by the flight crew which is not covered by the fault code diagrams.	SSM 78-34-01, SSM 78-34-02, SSM 78-36-01
78 34 XB --	(01=L,02=R) Reverser stow problem was encountered by the flight crew which is not covered by the fault code diagrams.	SSM 78-34-01, SSM 78-34-02, SSM 78-36-01
78 34 XC --	(01=L,02=R) REV ISLN VAL and REV ISLN lgt display problem was encountered by the flight crew which is not covered by the fault code diagrams.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 114, FIM 78-36-00/101, Fig. 106 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 107, FIM 78-36-00/101, Fig. 106
78 34 01 --	(01=L,02=R) Rev thrust lever could not be moved to rev thrust from rev idle. REV green was displayed.	FIM 78-34-00/101, Fig. 103, Block 1
78 34 02 --	(01=L,02=R) Engine REV amber in view with rev selected. No REV green indication. Rev lever would not move to full reverse.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 104, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 105, Block 1
78 34 03 --	(01=L,02=R) Engine would not reverse. REV ISLN light was on. EICAS msg: REV ISLN VAL displayed.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 106, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 105, Block 1
78 34 04 --	(01=L,02=R) Engine would not go to rev thrust. REV amber display missing. Rev thrust lever would not move to rev position.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 107, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 105, Block 1

EFFECTIVITY

ALL

## 78-FAULT CODE INDEX

R03

 Page 1  
 Sep 20/08

FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
78 34 05 --	(01=L,02=R) Engine time from rev to fwd thrust too slow, ____ sec.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 110, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 106, Block 1
78 34 06 --	(01=L,02=R) Engine stuck in rev. REV green displayed and fwd thrust levers could not be advanced.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 108, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 110, Block 1
78 34 07 --	(01=L,02=R) Engine stuck in full rev. REV ISLN lgt is on. EICAS msg: REV ISLN VAL displayed. Fwd thrust levers could not be advanced.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 105, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 110, Block 1
78 34 08 --	(01=L,02=R) Engine stuck in rev. REV ISLN lgt on. EICAS msg: REV ISLN VAL displayed. Fwd thrust lever could not be advanced.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 105, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 110, Block 1
78 34 09 00	EICAS msg L REV ISLN VAL displayed.	FIM 78-34-00/101, Fig. 107, Block 1, FIM 78-34-00/101, Fig. 109, Block 1
78 34 10 00	EICAS msg R REV ISLN VAL displayed.	FIM 78-34-00/101, Fig. 107, Block 1, FIM 78-34-00/101, Fig. 109, Block 1

EFFECTIVITY

ALL

## 78-FAULT CODE INDEX

R04

Page 2  
Sep 20/08

FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
78 34 11 00	EICAS msg REV ISLN VAL displayed and REV ISLN lgt on after takeoff.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 110, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 107, Block 1
78 34 12 00	EICAS msg REV ISLN VAL displayed and REV ISLN lgt on after takeoff and after landing. Msg and lgt norm in rev.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 111, Block 1
78 34 12 00	EICAS msg L(R) REV ISLN VAL displayed and REV ISLN light on during rev thrust.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 112, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 109, Block 1
78 34 14 00	EICAS msg REV ISLN VAL displayed and REV ISLN lgt on, on ground and during rev thrust.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 113, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 109, Block 1
78 34 15 00	EICAS msg REV ISLN VAL displayed and REV ISLN lgt on during all operations. Rev thrust is normal.	WITHOUT THRUST REVERSER SYNC LOCKS; Replace L(R) thrust reverser isolation detect relay K10358 (K10359)(WDM 78-36-11, WDM 78-36-21). If fault persists, check circuit between D2148 pin 28 and D4336 (D4256) pin 4. Repair as required.
78 34 16 --	(01=L,02=R) Engine was slow to reach reverse, _____ sec.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 109, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 108, Block 1

EFFECTIVITY

ALL

## 78-FAULT CODE INDEX

R03

 Page 3  
 Sep 20/08



FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
78 34 17 --	(01=L,02=R) Engine rev thrust lever (difficult, unable) to select rev position.	FIM 78-34-00/101, Fig. 103, Block 1
78 34 18 00	EICAS msg REV ISLN VAL displayed and REV ISLN lgt on with eng(s) shutdown and hyd pumps off. Reversers were stowed.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 114, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 107, Block 1
78 34 19 00	EICAS msg REV ISLN VAL displayed and REV ISLN lgt on after takeoff and after eng shutdown with hyd pumps off. Reversers were stowed.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 111, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-34-00/101, Fig. 107, Block 1
78 34 20 00	AIRPLANES WITHOUT SYNC LOCKS; EICAS msg L(R) REV ISLN VAL displayed (as a GROUND FAULT) when electrical power was applied to the airplane.	Clear the REV ISLN VAL message (FIM 31-41-00/101, Fig. 109). Open and close the applicable thrust reverser (AMM 78-31-00/201). Examine the EICAS for the L(R) REV ISLN VAL message. If the message does not show, no corrective action is necessary. If the message shows, do the corrective action for FIM 78-34-00/101, Fig. 106A, Block 1.
78 36 01 --	(01=L,02=R) Engine REV amber displayed with rev selected. Reverse lever could be moved toward full reverse.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-36-00/101, Fig. 103, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-36-00/101, Fig. 103, Block 1

EFFECTIVITY

ALL

## 78-FAULT CODE INDEX

R03

Page 4  
Sep 20/08

FAULT CODE	LOG BOOK REPORT	FAULT ISOLATION REFERENCE
78 36 02 --	(01=L,02=R) REV amber did not display. REV green did display during reverse thrust.	WITHOUT THRUST REVERSER SYNC LOCKS; FIM 78-36-00/101, Fig. 104, Block 1 WITH THRUST REVERSER SYNC LOCKS; FIM 78-36-00/101, Fig. 104, Block 1
78 36 03 --	(01=L,02=R) Engine REV amber display remained after fwd thrust selected. FWD thrust levers could be advanced.	FIM 78-36-00/101, Fig. 105, Block 1
78 36 04 --	(01=L,02=R) Engine REV amber displayed (steady, momentary) during fwd thrust.	FIM 78-36-00/101, Fig. 105, Block 1
78 36 05 --	(01=L,02=R) Engine REV amber blinks on and off every 5 seconds during fwd thrust.	FIM 78-36-00/101, Fig. 106, Block 1

EFFECTIVITY

ALL

## 78-FAULT CODE INDEX


R04

 Page 5  
 Sep 20/08

TURBINE EXHAUST SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
EXHAUST COLLECTOR - COMMON NOZZLE		2	415KL,425KL, AFT LATCH ACCESS PANEL	78-11-04

Turbine Exhaust System - Component Index  
Figure 101




E46845


**78-11-00**

R01

Page 101  
Sep 20/94



AFT LATCH ACCESS PANEL



COMMON NOZZLE EXHAUST COLLECTOR

(A)

Turbine Exhaust System - Component Location  
Figure 102

EFFECTIVITY	ALL
-------------	-----

78-11-00

R01


Page 102  
Sep 20/94

216139



THRUST REVERSER SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	REFERENCE
ACTUATOR - L ENGINE FAN C-DUCT HYDRAULIC OPENING	6	2	415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-31-25
ACTUATOR - R ENGINE FAN C-DUCT HYDRAULIC OPENING	6	2	425AL,426AR, FAN C-DUCT AND THRUST REVERSER	78-31-25
ACTUATOR - L ENGINE T/R HYDRAULIC LOCKING	3	2	415JL,416HR,415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-31-26
ACTUATOR - R ENGINE T/R HYDRAULIC LOCKING	3	2	425JL,426HR,425AL,426AR, FAN C-DUCT AND THRUST REVERSER	78-31-26
ACTUATOR - L ENGINE T/R HYDRAULIC NONLOCKING	3	4	415GL,415HL,416FR,416GR,415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-31-26
ACTUATOR - R ENGINE T/R HYDRAULIC NONLOCKING	3	4	425AL,425GL,425HL,426AR,426FR,426GR, FAN C-DUCT AND THRUST REVERSER	78-31-26
CASCADE SEGMENTS - L ENGINE	3	16	415AL,416AR, FAN C-DUCT AND THRUST REVERSER, TRANSLATE COWL	78-31-05
CASCADE SEGMENTS - R ENGINE	3	16	425AL,426AR, FAN C-DUCT AND THRUST REVERSER, TRANSLATE COWL	78-31-05
COWL - THRUST REVERSER TRANSLATING	3	2	415AL,416AR, FAN C-DUCT AND THRUST REVERSER, LEFT ENGINE	78-31-23
	3	2	425AL,426AR, FAN C-DUCT AND THRUST REVERSER, RIGHT ENGINE	78-31-23
DOORS - L ENGINE T/R BLOCKER	3	12	415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-31-24
DOORS - R ENGINE T/R BLOCKER	3	12	425AL,426AR, FAN C-DUCT AND THRUST REVERSER	78-31-24
LATCH - L ENGINE, FAN C-DUCT	3	5	415KL, T/R ACCESS DOOR	78-31-00
LATCH - R ENGINE, FAN C-DUCT	3	5	425KL, T/R ACCESS DOOR	78-31-00
LINKS - DRAG, L ENGINE BLOCKER DOOR	3	12	415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-31-27
LINKS - DRAG, R ENGINE BLOCKER DOOR	3	12	425AL,425AR, FAN C-DUCT AND THRUST REVERSER	78-31-27
REVERSER - FAN C-DUCT AND THRUST (HALVES)	3	2	LEFT ENGINE	78-31-20
	3	2	RIGHT ENGINE	78-31-20
TUBING - L ENGINE T/R ROTARY FLEX SHAFT AND	3	4	415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-31-26
TUBING - R ENGINE T/R ROTARY FLEX SHAFT AND	3	4	425AL,426AR, FAN C-DUCT AND THRUST REVERSER	78-31-26

Component Index  
Figure 101



**78-31-00**



**CENTER AND UPPER NONLOCKING HYDRAULIC ACTUATOR DISCONNECT INTERFACE**

(A)

**LOWER LOCKING HYDRAULIC ACTUATOR DISCONNECT INTERFACE**


(B)

**Component Location  
Figure 102 (Sheet 1)**

EFFECTIVITY	ALL
-------------	-----


**78-31-00**

217118



FAN C-DUCT AND THRUST REVERSER  
(TRANSLATING COWL DEPLOYED)

(C) FROM SHT 1



HYDRAULIC ACTUATOR ARRANGEMENT


Component Location  
Figure 102 (Sheet 2)

EFFECTIVITY	
	ALL


78-31-00

R01

Page 103  
May 20/98




(E) FROM SHT 1



UPPER NONLOCKING HYDRAULIC ACTUATOR  
(FLEXSHAFT SHOWN DISCONNECTED)

(F)



CENTER NONLOCKING HYDRAULIC ACTUATOR  
(FLEXSHAFT SHOWN DISCONNECTED)

(G)


Component Location  
Figure 102 (Sheet 3)

EFFECTIVITY	
	ALL

78-31-00


127698





**LOWER LOCKING HYDRAULIC ACTUATOR**

(H) FROM SHT 3



**FAN C-DUCT (UNDERSIDE)**

(I) FROM SHT 1


Component Location  
Figure 102 (Sheet 4)

EFFECTIVITY	ALL
-------------	-----

**78-31-00**

R01

Page 105  
Jun 15/84



FAN C-DUCT OPENING ACTUATOR

(J) FROM SHT 2

Component Location  
Figure 102 (Sheet 5)

EFFECTIVITY	
	ALL

**78-31-00**

R01

Page 106  
Jun 20/97

THRUST REVERSER CONTROL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ACTUATOR - L ENGINE, THRUST REVERSER FEEDBACK	3	2	415AL,416AR, AT THRUST REVERSER LOCKING ACTUATOR	78-34-06
ACTUATOR - R ENGINE, THRUST REVERSER FEEDBACK	3	2	425AL,426AR, AT THRUST REVERSER LOCKING ACTUATOR	78-34-06
CABLE - L ENGINE THRUST REVERSER FEEDBACK	4	2	433AL, STRUT CONTROL DRUM ACCESS, 415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-34-03
CABLE - R ENGINE THRUST REVERSER FEEDBACK	4	2	STRUT CONTROL DRUM ACCESS, 443AL, STRUT CONTROL DRUM ACCESS, 425AL, 426AR, STRUT CONTROL DRUM ACCESS	78-34-03
CIRCUIT BREAKER - L ENGINE T/R CONT, C1482 R ENGINE T/R CONT, C1483	5	1	FLT COMPT, P11 11D12	*
LEVER - (FIM 76-11-00/101) THRUST, M985		1	11B30	*
RELAY - (FIM 31-01-36/101) SYS NO. 1 AIR/GND, K199 L ENG T/R STOW, K26 L T/R DISAGREE, K10234 L T/R HYD ISLN VALVE, K10236		1		*
RELAY - (FIM 31-01-37/101) SYS NO. 2 AIR/GND, K203 R ENG T/R STOW, K27 R T/R DISAGREE, K10235 R T/R HYD ISLN VALVE, K10237		1		*
SENSOR - L ENGINE, L T/R AUTO RESTOW PROXIMITY, S10105	1	1	415AL, LEFT FORWARD BULKHEAD, AT LH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SENSOR - L ENGINE, R T/R AUTO RESTOW PROXIMITY, S10108	1	1	416AR, RIGHT FORWARD BULKHEAD, AT RH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SENSOR - R ENGINE, L T/R AUTO RESTOW PROXIMITY, S10105	1	1	425AL, LEFT FORWARD BULKHEAD, AT LH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SENSOR - R ENGINE, R T/R AUTO RESTOW PROXIMITY, S10108	1	1	426AR, RIGHT FORWARD BULKHEAD, AT RH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SENSOR - (FIM 78-36-00/101) L ENGINE, LH SLEEVE DEPLOY PROX, S166 L ENGINE, RH SLEEVE DEPLOY PROX, S167 R ENGINE, LH SLEEVE DEPLOY PROX, S166 R ENGINE, RH SLEEVE DEPLOY PROX, S167				
SWITCH - (FIM 26-21-00/101) L ENGINE FIRE, S37 R ENGINE FIRE, S38				
SWITCH - L T/R CONT, S134	5	1	FLT COMPT, P10, THRUST LEVER ASSY M985	*

\* SEE WDM EQUIPMENT LIST

 Thrust Reverser Control System - Component Index  
 Figure 101 (Sheet 1)

 EFFECTIVITY  
 AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**

CONFIG 1

R07

Page 101

Sep 20/98

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
SOLENOID - L ENG T/R ISOLATION VALVE	2	1	434AL, ISOLATION VALVE V106	*
SOLENOID - R ENG T/R ISOLATION VALVE	2	1	444AL, ISOLATION VALVE V107	*
SWITCH - (FIM 78-36-00/101) L T/R HYD PRESS, S330 R T/R HYD PRESS, S331				
SWITCH - R T/R CONT, S135	5	1	FLT COMPT, P10, THRUST LEVER M985	*
UNIT 1 - (FIM 32-09-00/101) PROXIMITY SWITCH ELECTRONICS, M162				
VALVE - L ENGINE, THRUST REVERSER DIRECTIONAL CONTROL	3	1	432AL	78-34-01
VALVE - L ENGINE, T/R ISOLATION, V106	2	1	434AL	78-34-05
VALVE - R ENGINE, T/R ISOLATION, V107	2	1	444AL	78-34-05
VALVE - R ENGINE, THRUST REVERSER DIRECTIONAL CONTROL	3	1	442AL	78-34-01




\* SEE WM EQUIPMENT LIST

Thrust Reverser Control System -Component Index  
Figure 101 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 102  
Sep 20/98

R01



Component Location  
Figure 102 (Sheet 1)

51945

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS


**78-34-00**

CONFIG 1


R01

Page 103

Sep 20/98



ENGINE STRUT HYDRAULIC  
 BAY ACCESS DOOR,  
 434AL (LEFT ENGINE),  
 444AL (RIGHT ENGINE)  
 SEE (D)



LEFT OR RIGHT ENGINE T/R ISOLATION VALVE

NOT USED

(C)

(D)

Thrust Reverser Control System - Component Location  
 Figure 102 (Sheet 2)

EFFECTIVITY  
 AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**


CONFIG 1

Page 104

Sep 20/98



R01

H64-306



LEFT OR RIGHT ENGINE T/R FEEDBACK ACTUATOR HYDRAULIC

(E) FROM SHT 1



Thrust Reverser Control System - Component Location  
Figure 102 (Sheet 3)


EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 105  
Sep 20/98

R01

ENGINE CONTROL STRUT  
DRUM AND FEEDBACK  
CABLE INTERFACE

SEE (G)




FAN C-DUCT AND  
THRUST REVERSER  
415AL(L ENG,OUTBD)  
416AR(L ENG,INBD)  
425AL(R ENG,INBD)  
426AR(R ENG,OUTBD)

SEE (H)

STRUT DRUM  
ACCESS PANEL  
433AL(L ENG,OUTBD)  
433GL(L ENG,INBD)  
443GL(R ENG,INBD)  
443AL(R ENG,OUTBD)

ENGINE CONTROL  
STRUT DRUM (REF)



T/R FEEDBACK CABLE

THRUST REVERSER  
HINGE ACCESS DOOR  
415BL(L ENG,OUTBD)  
416BR(L ENG,INBD)  
425BL(R ENG,INBD)  
426BR(R ENG,OUTBD)

ENGINE CONTROL STRUT DRUM AND FEEDBACK CABLE INTERFACE

T/R  
HINGE  
ACCESS  
DOOR  
(REF)


L OR R  
T/R FEEDBACK  
CABLE

T/R FEEDBACK  
ACTUATOR/  
CABLE  
INTERFACE

SEE (I)

FAN C-DUCT AND THRUST REVERSER

(H)



(G)

LOWER LOCKING  
HYDRAULIC  
ACTUATOR  
(REF)

T/R FEEDBACK  
CABLE

LEFT T/R  
FEEDBACK  
ACTUATOR

T/R FEEDBACK ACTUATOR/CABLE INTERFACE

(I)

Component Location  
Figure 102 (Sheet 4)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

78-34-00



CONFIG 1

Page 106

Sep 20/98


R01





THRUST LEVERS

0



AIRPLANES WITH TITANIUM THRUST LEVERS

P

Component Location  
Figure 102 (Sheet 5)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS



78-34-00

CONFIG 1

R01

Page 107

Sep 20/98



AIRPLANES WITH TITANIUM THRUST LEVERS

(R)

Component Location  
Figure 102 (Sheet 6)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS



**78-34-00**

CONFIG 1

Page 108

Sep 20/98

R01



FLOW CONTROL VALVE LOCATION

(A)

Flow Control Valve Location  
Figure 102 (Sheet 7)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS


**78-34-00**

CONFIG 1  
Page 109  
Jan 20/99

R01

T/R DEPLOYED, REVERSE THRUST COULD NOT BE ADVANCED BEYOND IDLE

**PREREQUISITES**  
NONE



T/R Deployed, Reverse Thrust Could Not Be Advanced Beyond Idle  
Figure 103

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
 CONFIG 1  
 Page 110  
 Jan 20/99


R01

**T/R PARTIALLY  
DEPLOYED**

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
HYDRAULIC POWER IS ON (AMM 29-11-00/201)




T/R Partially Deployed  
Figure 104 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 111  
Jan 20/99

R07

FROM SHEET 1  
(BLOCK 2)



T/R Partially Deployed  
Figure 104 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 112  
Jan 20/99


R01

T/R REMAINED FULLY OR PARTIALLY DEPLOYED WITH "REV" GREEN OR AMBER LIGHT ON AND WITH "REV ISLN" LIGHT ON AND "REV ISLN VAL" EICAS MESSAGE

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B30,11D12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)




Thrust Reverser Remained Fully or Partially Deployed with REV Green or Amber Light On and with REV ISLN Light On and REV ISLN VAL EICAS Message  
Figure 105 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 113  
Jan 20/99

R07

FROM SHEET 1  
(BLOCK 2)



Thrust Reverser Remained Fully or Partially Deployed with REV Green or Amber Light On and with REV ISLN Light On and REV ISLN VAL EICAS Message  
Figure 105 (Sheet 2)

EFFECTIVITY \_\_\_\_\_  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
 CONFIG 1  
 Page 114  
 Jan 20/99

R05




REV THRUST SELECTED  
WITH "REV" AMBER  
"REV ISLN" LIGHT  
AND "REV ISLN VAL"  
EICAS MESSAGE

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B30,11D12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)




Rev Thrust Selected With REV Amber REV ISLN Light and REV ISLN VAL EICAS Message  
Figure 106 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 115  
Jan 20/99

R07

FROM SHEET 1  
(BLOCK 4)



Rev Thrust Selected With REV Amber REV ISLN Light and REV ISLN VAL EICAS Message  
Figure 106 (Sheet 2)


EFFECTIVITY \_\_\_\_\_  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 116  
Jan 20/99

R04

**T/R DID NOT DEPLOY  
WITH ISOLATION VALVE  
OPENED**

**PREREQUISITES**  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
NO ELECTRICAL POWER (AMM 24-22-00/201)  
NO HYDRAULIC POWER (AMM 29-11-00/201)



T/R Did Not Deploy Isolation Valve Opened  
Figure 107


EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 117  
Jan 20/99

R01

**PREREQUISITES**  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
NO ELECTRICAL POWER (AMM 24-22-00/201)  
NO HYDRAULIC POWER (AMM 29-11-00/201)

**T/R REMAINED DEPLOYED**



T/R Remained Deployed  
Figure 108


EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 118  
Jan 20/99

R01

**PREREQUISITES**  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
THRUST REVERSER IS DEACTIVATED (AMM 78-31-00/201)

**T/R OPERATION SLOW**




T/R Operation Slow  
Figure 109 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 119  
Jan 20/99

R01



T/R Operation Slow  
Figure 109 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
 CONFIG 1  
 Page 120  
 Jan 20/99

R01


**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
HYDRAULIC POWER (AMM 29-11-00/201)  
THRUST REVERSER STOWED

**WARNING:** FAILURE TO DEACTIVATE THRUST REVERSER FOR GROUND MAINTENANCE COULD RESULT IN INADVERTENT THRUST REVERSER OPERATION WITH POSSIBLE INJURY TO PERSONNEL AND/OR DAMAGE TO EQUIPMENT.

"REV ISLN" LGT/"REV ISLN VAL" EICAS MSG DISPLAYED AFTER T.O.




REV ISLN Lgt/REV ISLN VAL EICAS Msg Displayed After T.O.  
Figure 110 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 121  
Jan 20/99

R07

FROM SHEET 1  
(BLOCK 3)



REV ISLN Lgt/REV ISLN VAL EICAS Msg Displayed After T.O.  
Figure 110 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 122  
Jan 20/99

R03




"REV ISLN" LIGHT ON AND EICAS "REV ISLN VAL" MESSAGE DISPLAYED AFTER T.O. AND AFTER LANDING OR AFTER T.O. AND AFTER ENG SHUTDOWN WITH HYD. PUMPS OFF

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
HYDRAULIC POWER (AMM 29-11-00/201)  
THRUST REVERSER STOWED

**WARNING:** FAILURE TO DEACTIVATE THRUST REVERSER FOR GROUND MAINTENANCE COULD RESULT IN INADVERTENT THRUST REVERSER OPERATION WITH POSSIBLE INJURY TO PERSONNEL AND/OR DAMAGE TO EQUIPMENT.




REV ISLN Light On and EICAS REV ISLN VAL Message Displayed After T.O. and After Landing or After T.O. and After Eng Shutdown With Hyd. Pumps Off  
Figure 111 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 123  
Jan 20/99

R07

FROM SHEET 1  
(BLOCK 2)



REV ISLN Lgt/REV ISLN VAL EICAS Msg Displayed After T.O. and After Landing.  
Figure 111 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS


**78-34-00**  
 CONFIG 1  
 Page 124  
 Jan 20/99

R03

**PREREQUISITES**  
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)

"REV ISLN" LGT/"REV ISLN VAL" EICAS MSG DISPLAYED DURING REV THRUST

**WARNING:** FAILURE TO DEACTIVATE THRUST REVERSER FOR GROUND MAINTENANCE COULD RESULT IN INADVERTENT THRUST REVERSER OPERATION WITH POSSIBLE INJURY TO PERSONNEL AND/OR DAMAGE TO EQUIPMENT.



REV ISLN Lgt/REV ISLN VAL EICAS Msg Displayed During Rev Thrust  
Figure 112


EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 125  
Jan 20/99

R07

"REV ISLN" LIGHT ON  
AND EICAS "REV ISLN  
VAL" MESSAGE DIS-  
PLAYED DURING REV  
THRUST AND ON THE  
GROUND

**PREREQUISITES**  
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)



REV ISLN Light On and EICAS REV ISLN VAL Message Displayed  
during Rev Thrust and on the Ground  
Figure 113

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**  
CONFIG 1  
Page 126  
Jan 20/99


R07

"REV ISLN" LIGHT AND "REV ISLN VAL" EICAS MESSAGE DISPLAYED ONLY WHEN ENG(S) ARE SHUT DOWN AND HYD PUMPS ARE OFF. REVERSERS ARE STOWED.

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
THRUST REVERSER STOWED



REV ISLN Light and REV ISLN VAL EICAS Message Displayed only when Eng(s) are Shut Down and Hyd Pumps are off. Reversers are Stowed.

Figure 114

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-34-00**

CONFIG 1

R07

Page 127

Jan 20/99

H72375

THRUST REVERSER CONTROL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
ACTUATOR - L ENGINE, THRUST REVERSER FEEDBACK	3	2	415AL,416AR, AT THRUST REVERSER LOCKING ACTUATOR	78-34-06
ACTUATOR - R ENGINE, THRUST REVERSER FEEDBACK	3	2	425AL,426AR, AT THRUST REVERSER LOCKING ACTUATOR	78-34-06
CABLE - L ENGINE THRUST REVERSER FEEDBACK	4	2	433AL, STRUT CONTROL DRUM ACCESS, 415AL,416AR, FAN C-DUCT AND THRUST REVERSER	78-34-03
CABLE - R ENGINE THRUST REVERSER FEEDBACK	4	2	STRUT CONTROL DRUM ACCESS, 443AL, STRUT CONTROL DRUM ACCESS, 425AL, 426AR, STRUT CONTROL DRUM ACCESS	78-34-03
CIRCUIT BREAKER - L ENG SYNC-LOCK, C4472	5	1	FLT COMPT, P6 6C12	*
R ENG SYNC-LOCK ALTN, C4474		1	6D12	*
CIRCUIT BREAKER - R ENG SYNC-LOCK, C4470		1	FLT COMPT, P11 11K32	*
T/R CONT ALTN R, C1483		1	11D12	*
T/R CONT L, C1482		1	11K33	*
T/R CONT R, C4471		1	11B30	*
DIODE (FIM 31-01-36/101) SUPPR, R10398				*
DIODE (FIM 31-01-37/101) SUPPR, R10399				*
LEVER - (FIM 76-11-00/101) THRUST, M985				*
MODULE - (FIM 31-01-36/101) TIME DELAY, M10004		1		*
MODULE - (FIM 31-01-37/101) TIME DELAY, M10010		1		*
RELAY - (FIM 31-01-36/101) L ENG T/R STOW, K26		1		*
SYNC-LOCK, K10725		1		*
SYS NO. 1 AIR/GND, K167		1		*
SYS NO. 1 AIR/GND, K199				
RELAY - (FIM 31-01-37/101) HIV PWR SENSE, K10724		1		*
R ENG T/R STOW, K27		1		*
SYNC-LOCK, K10726		1		*
SYNC-LOCK PWR SENSE, K10723		1		*
SYS NO. 1 AIR/GND, K10201		1		*
SYS NO. 2 AIR/GND, K203				

\* SEE THE WDM EQUIPMENT LIST

 Thrust Reverser Control System - Component Index  
 Figure 101 (Sheet 1)

 EFFECTIVITY  
 AIRPLANES WITH SYNC-LOCKS

**78-34-00**

CONFIG 2

R01

Page 101

Sep 20/98

H59915

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
SENSOR - (FIM 78-36-00/101) L ENGINE, LH SLEEVE DEPLOY PROX, S166 L ENGINE, RH SLEEVE DEPLOY PROX, S167 R ENGINE, LH SLEEVE DEPLOY PROX, S166 R ENGINE, RH SLEEVE DEPLOY PROX, S167				
SENSOR - L ENGINE, L T/R AUTO RESTOW PROXIMITY, S10105	1	1	415AL, LEFT FORWARD BULKHEAD, AT LH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SENSOR - L ENGINE, R T/R AUTO RESTOW PROXIMITY, S10108	1	1	416AR, RIGHT FORWARD BULKHEAD, AT RH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SENSOR - R ENGINE, L T/R AUTO RESTOW PROXIMITY, S10105	1	1	425AL, LEFT FORWARD BULKHEAD, AT LH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SENSOR - R ENGINE, R T/R AUTO RESTOW PROXIMITY, S10108	1	1	426AR, RIGHT FORWARD BULKHEAD, AT RH THRUST REVERSER LOCKING ACTUATOR	78-34-07
SOLENOID - L ENG T/R ISOLATION VALVE	2	1	434AL, ISOLATION VALVE V106	*
SOLENOID - R ENG T/R ISOLATION VALVE	2	1	444AL, ISOLATION VALVE V107	*
SWITCH - L T/R CONT, S134 (SYNC-LOCK)	5	1	FLT COMPT, P10, THRUST LEVER ASSY, M985	
SWITCH - R T/R CONT, S135 (SYNC-LOCK)	5	1	FLT COMPT, P10, THRUST LEVER ASSY, M985	
SWITCHES - (FIM 22-32-00/101) L T/R CONT, S21 (ISOLATION VALVE) R T/R CONT, S22 (ISOLATION VALVE)				
SWITCHES - (FIM 26-21-00/101) L ENGINE FIRE, S37 R ENGINE FIRE, S38				
SWITCHES - (FIM 78-36-00/101) L T/R HYD PRESS, S330 R T/R HYD PRESS, S331				
SYNC-LOCK, L ENGINE THRUST REVERSER	6	1	416AR	78-31-26
SYNC-LOCK, R ENGINE THRUST REVERSER	6	1	426AR	78-31-26
UNIT 1 - (FIM 32-09-00/101) PROXIMITY SWITCH ELECTRONICS, M162				
VALVE - L ENGINE, THRUST REVERSER DIRECTIONAL CONTROL	3	1	432AL	78-34-01
VALVE - R ENGINE, THRUST REVERSER DIRECTIONAL CONTROL	3	1	442AL	78-34-01
VALVE - L ENGINE, T/R ISOLATION, V106	2	1	434AL	78-34-05
VALVE - R ENGINE, T/R ISOLATION, V107	2	1	444AL	78-34-05


\* SEE THE WDM EQUIPMENT LIST

Thrust Reverser Control System - Component Index  
Figure 101 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 102  
Sep 20/98


R01



FAN C-DUCT AND THRUST REVERSER  
415,416AR (LEFT ENGINE)  
425AL,426AR (RIGHT ENGINE)  
SEE (A)


TRANSLATING COWL (REFERENCE)  
SEE (B)

LEFT OR RIGHT ENGINE T/R FEEDBACK ACTUATOR  
SEE (E) SHEET 3



FAN C-DUCT AND THRUST REVERSER

(A)



TRANSLATING COWL (REFERENCE)

(B)

Component Location  
Figure 102 (Sheet 1)

51945


EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**


CONFIG 2  
Page 103  
Sep 20/98

R01





ENGINE STRUT HYDRAULIC  
BAY ACCESS DOOR,  
434AL (LEFT ENGINE),  
444AL (RIGHT ENGINE)  
SEE (D)



NOT USED

(C)

LEFT OR RIGHT ENGINE T/R ISOLATION VALVE

(D)

Thrust Reverser Control System - Component Location  
Figure 102 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS


**78-34-00**

CONFIG 2

Page 104



Sep 20/98

R01



LEFT OR RIGHT ENGINE T/R FEEDBACK  
ACTUATOR HYDRAULIC

(E) FROM SHT 1



LEFT OR RIGHT ENGINE  
T/R DIRECTIONAL CONTROL VALVE

(F)

Thrust Reverser Control System - Component Location  
Figure 102 (Sheet 3)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**

CONFIG 2

R01


Page 105

Sep 20/98

H60017

ENGINE CONTROL STRUT  
DRUM AND FEEDBACK  
CABLE INTERFACE


SEE (G)



FAN C-DUCT AND  
THRUST REVERSER  
415AL (LEFT ENGINE OUTBOARD)  
416AR (LEFT ENGINE INBOARD)  
425AL (RIGHT ENGINE INBOARD)  
426AR (RIGHT ENGINE OUTBOARD)

SEE (H)

STRUT DRUM  
ACCESS PANEL  
433AL (LEFT ENGINE OUTBOARD)  
433GL (LEFT ENGINE INBOARD)  
443GL (RIGHT ENGINE INBOARD)  
443AL (RIGHT ENGINE OUTBOARD)



T/R FEEDBACK CABLE

ENGINE CONTROL  
STRUT DRUM  
(REFERENCE)

THRUST REVERSER  
HINGE ACCESS DOOR  
415BL (LEFT ENGINE OUTBOARD)  
416BR (LEFT ENGINE INBOARD)  
425BL (RIGHT ENGINE INBOARD)  
426BR (RIGHT ENGINE OUTBOARD)

ENGINE CONTROL STRUT DRUM AND FEEDBACK CABLE INTERFACE

T/R  
HINGE  
ACCESS  
DOOR  
(REFERENCE)

L OR R  
T/R FEEDBACK  
CABLE

T/R FEEDBACK  
ACTUATOR/  
CABLE  
INTERFACE

SEE (I)

FAN C-DUCT AND THRUST REVERSER

(H)

(G)

LOWER LOCKING  
HYDRAULIC  
ACTUATOR  
(REFERENCE)

T/R FEEDBACK  
CABLE

LEFT T/R  
FEEDBACK  
ACTUATOR

T/R FEEDBACK ACTUATOR/CABLE INTERFACE

(I)

Component Location  
Figure 102 (Sheet 4)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS



78-34-00

CONFIG 2


Page 106

Sep 20/98

R01



THRUST LEVERS  
0



AIRPLANES WITH TITANIUM THRUST LEVERS  
P

Component Location  
Figure 102 (Sheet 5)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS



**78-34-00**

CONFIG 2

Page 107

Sep 20/98

R01



AIRPLANES WITH TITANIUM THRUST LEVERS

(R)



Component Location  
Figure 102 (Sheet 6)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 108  
Sep 20/98

R01

H60085



Thrust Reverser Control System - Component Location  
Figure 102 (Sheet 7)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**



CONFIG 2

R01

Page 109

Sep 20/98

H60102



FLOW CONTROL VALVE LOCATION

(A)

Flow Control Valve Location  
Figure 102 (Sheet 8)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**

CONFIG 2


Page 110

Jan 20/99

R01

T/R DEPLOYED, REVERSE THRUST COULD NOT BE ADVANCED BEYOND IDLE

**PREREQUISITES**  
NONE



T/R Deployed, Reverse Thrust Could Not Be Advanced Beyond Idle  
Figure 103

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS


**78-34-00**  
CONFIG 2  
Page 111  
Jan 20/99

R01



"(L,R) REV ISLN VAL" EICAS MESSAGE DISPLAYED ONLY WHEN ENG(S) ARE SHUT DOWN, HYD PUMPS ARE OFF AND REVERSERS ARE STOWED

**PREREQUISITES**  
MAKE SURE THESE CIRCUIT BREAKERS ARE OPEN:  
11B29, 11D11  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
THRUST REVERSER IS DEACTIVATED (AMM 78-31-00/201)



(L,R) REV ISLN VAL EICAS Message Displayed Only When Eng(s) Are Shut Down and Hyd Pumps Are Off. Reversers Are Stowed.  
Figure 104

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 112  
Jan 28/01


R03

REV SELECTED. REV AMBER OR NO REV AMBER. NO REV GREEN. REV THRUST LEVER COULD NOT MOVE TO FULL REV.

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
6C12,6D12,11B29,11B30,11D11,11D12,11K32,11K33

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
THRUST REVERSER IS RETRACTED




REV Selected. REV Amber or No REV Amber. No REV Green.  
REV Thrust Lever Could Not Move to Full REV.  
Figure 105 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 113  
Jan 20/99

R01

FROM SHEET 1  
(BLOCK 3)




REV Selected. REV Amber or No REV Amber. No REV Green.  
REV Thrust Lever Could Not Move to Full REV.  
Figure 105 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 114  
Jan 20/99

R01




REV Selected. REV Amber or No REV Amber. No REV Green.  
REV Thrust Lever Could Not Move to Full REV.  
Figure 105 (Sheet 3)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 115  
Jan 20/99

R01

FROM SHEET 3  
(BLOCK 7)




REV Selected. REV Amber or No REV Amber. No REV Green.  
REV Thrust Lever Could Not Move to Full REV.  
Figure 105 (Sheet 4)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 116  
Jan 20/99

R01




REV Selected. REV Amber or No REV Amber. No REV Green.  
REV Thrust Lever Could Not Move to Full REV.  
Figure 105 (Sheet 5)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 117  
Jan 20/99

R01

FROM SHEET 5  
(BLOCK 11)



REV Selected. REV Amber or No REV Amber. No REV Green.  
REV Thrust Lever Could Not Move to Full REV.  
Figure 105 (Sheet 6)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 118  
Jan 20/99


R01

FWD THRUST SELECTED.  
NO REV AMBER  
NO REV GREEN  
FWD THRUST LEVER  
COULD MOVE FWD.  
TIME TO FWD THRUST  
TOO SLOW.

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,6C12,6D12,11D11,11D12,11K32,11K33

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
FWD THRUST LEVER FULLY AFT  
REV THRUST LEVER FULLY FWD AND DOWN  
THRUST REVERSER IS RETRACTED



FWD Thrust Selected. No REV Amber. No REV Green. FWD Thrust Lever Could Move FWD.  
Time to FWD Thrust Too Slow.  
Figure 106 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS


**78-34-00**  
CONFIG 2  
Page 119  
Jan 20/99

R01



FROM SHEET 1  
(BLOCK 2)

FROM SHEET 1  
(BLOCK 11)



FWD Thrust Selected. No REV Amber. No REV Green. FWD Thrust Lever Could Move FWD.  
Time to FWD Thrust Too Slow.  
Figure 106 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 120  
Jan 20/99


R01

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
6C12, 6D12, 11B29, 11B30, 11D11, 11D12,  
11K32, 11K33

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
HYDRAULIC POWER IS OFF (AMM 29-11-00/201)  
ENG FIRE SWITCH IS IN THE NORMAL POSITION  
REVERSE THRUST LEVER IS FORWARD AND DOWN

1 (L, R) REV ISLN VAL EICAS MESSAGE DISPLAYED.



1 "(L, R) REV ISLN VAL" STATUS OR ADVISORY MESSAGE DISPLAYED. NO ADVISORY MESSAGE WITH THE ENGINES SHUTDOWN OR HYDRAULICS OFF.


(L, R) REV ISLN VAL EICAS Message Displayed.  
Figure 107 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 121  
Jan 28/03

R01

FROM SHEET 1  
(BLOCK 2)




(L, R) REV ISLN VAL EICAS Message Displayed.  
Figure 107 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 122  
Jan 28/03

R01



(L, R) REV ISLN VAL EICAS Message Displayed.  
Figure 107 (Sheet 3)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS


**78-34-00**  
CONFIG 2  
Page 123  
Jan 28/03

R01

**PREREQUISITES**

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
THRUST REVERSER IS DEACTIVATED (AMM 78-31-00/201)

TIME TO "REV" THRUST TOO SLOW.




Time to REV Thrust Too Slow.  
Figure 108 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 124  
Jan 28/03

R01



Time to REV Thrust Too Slow.  
Figure 108 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 125  
Jan 28/03


R01

(L,R) REV ISLN VAL  
EICAS MSG DURING  
REVERSE THRUST

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE OPEN:  
11B29,11D11

MAKE SURE THAT THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
THRUST REVERSER IS DEACTIVATED (AMM 78-31-00/201)  
REVERSE THRUST LEVER IS FORWARD AND DOWN



(L,R) REV ISln Val EICAS Msg During Reverse Thrust  
Figure 109

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 126  
Jan 28/03


R01

FWD THRUST SELECTED.  
REV GREEN OR REV  
AMBER SHOWN. FWD  
THRUST LEVERS COULD  
NOT MOVE FWD.

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE OPEN AND ATTACH DO-NOT-CLOSE TAGS:  
11B30,11D12,11K33

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
THRUST REVERSER IS DEACTIVATED (AMM 78-31-00/201)  
THRUST REVERSER IS EXTENDED  
REV THRUST LEVERS FORWARD AND DOWN  
FIRE SWITCH AT NORMAL POSITION



Fwd Thrust Selected. REV Green or REV Amber Shown.  
Fwd Thrust Levers Could Not Move Fwd.  
Figure 110 (Sheet 1)


EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 127  
Jan 28/03

R01



FROM SHEET 1  
(BLOCK 2)




Fwd Thrust Selected. REV Green or REV Amber Shown.  
Fwd Thrust Levers Could Not Move Fwd.  
Figure 110 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 128  
Jan 28/03

R01

FROM SHEET 2  
(BLOCK 5)



Fwd Thrust Selected. REV Green or REV Amber Shown.  
Fwd Thrust Levers Could Not Move Fwd.  
Figure 110 (Sheet 3)


EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 129  
Jan 28/03

R01

**T/R SYNC-LOCK DOES NOT UNLOCK**

**PREREQUISITES**  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)




T/R Sync Lock Does Not Unlock  
Figure 111 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**  
CONFIG 2  
Page 130  
Jan 28/03

R01



T/R Sync Lock Does Not Unlock  
Figure 111 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-34-00**

CONFIG 2



R02

Page 131

Jan 28/03

L02639





FUEL CONTROL PANEL, M73 (REF)

(A)

Component Location  
Figure 102 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS


**78-36-00**

CONFIG 1


Page 102

Sep 20/98

R01




ENGINE STRUT HYDRAULIC  
BAY ACCESS DOOR  
434AL (L ENG)  
444AL (R ENG)  
L OR R T/R ISOLATION  
VALVE (REF)  
SEE (B)




FAN C-DUCT AND  
THRUST REVERSER  
415AL (L ENG OUTBD)  
416AR (L ENG INBD)  
425AL (R ENG INBD)  
426AR (R ENG OUTBD)

L OR R ISOLATION  
VALVE PRESSURE SWITCH  
S330 OR S331



LOWER LOCKING  
HYDRAULIC ACTUATOR  
SEE (C)

LOWER LOCKING  
HYDRAULIC  
ACTUATOR (REF)



SLEEVE DEPLOY  
PROXIMITY SENSOR  
S166 OR S167

LOCK LEVER  
ARM (REF)  
SEE (D)

FEEDBACK  
LEVER (REF)

SENSOR TARGET  
(REF)


FEEDBACK  
ACTUATOR (REF)

LH LOWER LOCKING HYDRAULIC  
ACTUATOR (RH SIMILAR)  
(C)

L OR R T/R ISOLATION VALVE (REF)  
(B)

LOWER LOCKING  
HYDRAULIC  
ACTUATOR (REF)

SLEEVE ACTUATOR  
UNLOCKED PROXIMITY  
SENSOR S164 OR S165



SENSOR TARGET  
(REF)

LOCK LEVER  
ARM (REF)

LOCK LEVER ARM  
(D)

56066

Component Location  
Figure 102 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

78-36-00

CONFIG 1


R01

Page 103

Sep 20/98

**PREREQUISITES**  
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29, 11B30, 11D11, 11D12  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)

AMBER REV REMAINED  
DISPLAYED AFTER FULL  
REVERSE WAS REACHED



Amber REV Remained Displayed After Full Reverse Was Reached  
Figure 103

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**  
CONFIG 1  
Page 104  
May 28/03

R03



AMBER REV DID NOT  
DISPLAY, GREEN  
REV DID WITH T/R  
FULLY DEPLOYED



**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11D11,11D12,11B29,11B30

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)

1 DO THIS PROCEDURE: PSEU  
BITE PROCEDURE (FIM 32-09-03/  
101, FIG. 103, BLOCK 1).  
WAS THE PROBLEM CORRECTED?

YES

21 PUT THE AIRPLANE IN  
SERVICE.

NO

22 REMOVE PSEU M162  
(AMM 32-09-04). REMOVE L (R)  
EICAS COMPUTER M10181 (M10182)  
(AMM 31-41-02).  
EXAMINE THE CIRCUIT FROM  
CONNECTOR D3210E (D3210A)  
PIN 12A TO CONNECTORS D321B  
PIN F3 AND D321D PIN F12 OR  
D319D PIN F12 AND D319B PIN F3  
(WDM 78-36-11,-21). REPAIR  
THE PROBLEMS THAT YOU FIND.  
INSTALL EICAS COMPUTER AND  
PSEU.

Amber REV Did Not Display, Green REV Did with T/R Fully Deployed  
Figure 104

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**

CONFIG 1

R07

Page 105

Sep 20/98


**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
 1 > 11K6, 11K33; 2 > 11B30, 11K12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
 ELECTRICAL POWER IS ON (AMM 24-22-00/201)

**CAUTION:** DO NOT TOUCH THE PSEU CARD BEFORE YOU DO THE PROCEDURE FOR DEVICES THAT ARE SENSITIVE TO ELECTROSTATIC DISCHARGE. ELECTROSTATIC DISCHARGE CAN CAUSE DAMAGE TO PSEU CARD.

**T/R STOWED, AMBER REV REMAINED DISPLAYED**



- 1 > AIRPLANES WITHOUT ETOPS
- 2 > AIRPLANES WITH ETOPS


T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**  
CONFIG 1  
Page 106  
Jan 28/05

R01

H67675




T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**  
CONFIG 1  
Page 107  
Jan 28/05

R01

FROM SHEET 2  
(BLOCK 4)



T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 3)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS


**78-36-00**

CONFIG 1  
Page 108  
Jan 28/05

R01

D34470

FROM SHEET 2 (BLOCK 22)      FROM SHEET 3 (BLOCK 6)



T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 4)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**

CONFIG 1

R01

Page 109

Jan 28/05

H67693

FROM SHEET 3  
(BLOCK 25)

NO

**9** IS THE COMBINED CIRCUIT AND SENSOR RESISTANCE FOR THE ACTUATOR LOCK PROX SENSOR CIRCUIT LESS THAN 16 OHMS PIN TO PIN, AS MEASURED FROM THESE PSEU CONNECTORS AND PINS: (TEST THE CIRCUIT BY PLACING OHMMETER PROBE ON ONE PIN AND THE OTHER OHMMETER PROBE ON THE OTHER PIN.)

LEFT ENGINE (WDM 78-36-11)

PSEU CONNECTOR	PSEU PINS
D3210E	A9 TO B9 LEFT SLEEVE C9 TO D9 RIGHT SLEEVE

RIGHT ENGINE (WDM 78-36-21)

PSEU CONNECTOR	PSEU PINS
D3210A	A9 TO B9 LEFT SLEEVE C9 TO D9 RIGHT SLEEVE

NO

**49** USING AN OHMMETER, ISOLATE THE HIGH RESISTANCE PORTION OF THE ACTUATOR UNLOCK PROX SENSOR CIRCUIT:

1. VERIFY THAT THE RESISTANCE OF THE ACTUATOR LOCK PROX SENSOR AS MEASURED FROM CONNECTOR D41520P (LEFT) OR D41522P (RIGHT), BETWEEN PINS 1 AND 3 IS 8 TO 11 OHMS (TYPICAL) (WDM 71-51-11, SHEET 4)
2. THE RESISTANCE OF THE PROX SENSOR LINES LESS THE PROX SENSOR (THE DIFFERENCE BETWEEN THE PROX SENSOR CIRCUIT RESISTANCE AS MEASURED IN BLOCK 10 AND THE PROX SENSOR RESISTANCE AS MEASURED ABOVE) IS 2 TO 5 OHMS.

REPLACE THE NECESSARY PARTS TO REDUCE THE COMBINED LINE AND SENSOR RESISTANCE TO LESS THAN 16 OHMS

YES

**10** IS THE CIRCUIT RESISTANCE ON THE SENSOR LINE MORE THAN 20 MEGOHMS OF RESISTANCE TO GROUND? TEST THE CIRCUIT BY PLACING AN OHMMETER PROBE ON THESE PINS AND THE OTHER PROBE ON A GROUND:

**NOTE:** DISCONNECT THE PROXIMITY SENSOR FROM THE SENSOR LINE PRIOR TO TEST.

LEFT ENGINE (WDM 78-36-11)

PSEU CONNECTOR	PSEU PINS
D3210E	A9 LEFT SLEEVE B9 LEFT SLEEVE C9 RIGHT SLEEVE D9 RIGHT SLEEVE

RIGHT ENGINE (WDM 78-36-21)

PSEU CONNECTOR	PSEU PINS
D3210A	A9 LEFT SLEEVE B9 LEFT SLEEVE C9 RIGHT SLEEVE D9 RIGHT SLEEVE

NO

**50** EXAMINE THE SENSOR LINE CIRCUIT. REPAIR THE PROBLEMS THAT YOU FIND (WDM 78-36-11, -21).

YES

SEE SHEET 6  
(BLOCK 11)

T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 5)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**  
CONFIG 1  
Page 110  
Jan 28/05

R01

FROM SHEET 5 (BLOCK 10)      FROM SHEET 2 (BLOCK 23)

YES                                  NO

**11** IS THE CIRCUIT RESISTANCE ON THE PSEU TO EICAS CIRCUIT MORE THAN 20 MEGOHMS OF RESISTANCE TO GROUND? TEST THE CIRCUIT BY PLACING AN OHM-METER PROBE ON THESE PINS AND THE OTHER PROBE ON A GROUND:

**NOTE:** TURN EICAS OFF. DISCONNECT THE LINE TO BE TESTED FROM EICAS AND THE PSEU.

LEFT ENGINE (WDM 78-36-11, SHT 1)

<u>PSEU CONNECTOR</u>	<u>PSEU PINS</u>
D3210E	A12 E12
<u>LEFT EICAS CONNECTOR</u>	<u>LEFT EICAS PIN</u>
D319B	F3 G3
<u>RIGHT EICAS CONNECTOR</u>	<u>RIGHT EICAS PIN</u>
D321B	F3 G3

RIGHT ENGINE (WDM 78-36-21, SHT 2)

<u>PSEU CONNECTOR</u>	<u>PSEU PINS</u>
D3210A	A12 E12
<u>LEFT EICAS CONNECTOR</u>	<u>LEFT EICAS PIN</u>
D319D	F12 F14
<u>RIGHT EICAS CONNECTOR</u>	<u>RIGHT EICAS PIN</u>
D321D	F12 F14

NO

**51** LOCATE AND CORRECT THE UNSERVICEABLE INSULATION ON THE PSEU TO EICAS REV AMBER INDICATION WIRE (WDM 78-36-11, WDM 78-36-21).

YES


**52** REPLACE THE PSEU, M162 (AMM 32-09-03/401).

T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 6)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**  
CONFIG 1  
Page 111  
Jan 28/05

R01



T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 7)

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**  
 CONFIG 1  
 Page 112  
 Jan 28/05

R01




**THRUST REVERSER  
POSITION INDICATION  
SYSTEM PROBLEM**

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
THRUST REVERSER IN STOWED POSITION (AMM 78-31-00/  
201)



Thrust Reverser Position Indication System Problem  
Figure 106

EFFECTIVITY  
AIRPLANES WITHOUT SYNC-LOCKS

**78-36-00**

CONFIG 1

R07

Page 113

Jan 28/05

H67770

THRUST REVERSER CONTROL SYSTEM

COMPONENT	FIG. 102 SHT	QTY	ACCESS/AREA	AMM REFERENCE
CIRCUIT BREAKER - L ENG T/R IND, C1480 R ENG T/R IND, C1481	1	1 1	FLT COMPT, P11 11D11 11B29	* *
COMPUTER - (FIM 31-41-00/101) L EICAS, M10181 R EICAS, M10182				
RELAY - (FIM 31-01-36/101) L 30 SEC AFTER STOW COMMAND, K10712				
RELAY - (FIM 31-01-37/101) R 30 SEC AFTER STOW COMMAND, K10713				
SENSOR - L ENGINE, LH SLEEVE ACTUATOR LOCK PROXIMITY, S164	2	1	415AL, LH THRUST REVERSER LOCKING ACTUATOR	*
SENSOR - L ENGINE, LH SLEEVE DEPLOY PROX, S166	2	1	415AL, LH THRUST REVERSER LOCKING ACTUATOR	*
SENSOR - L ENGINE, RH SLEEVE ACTUATOR LOCK PROXIMITY, S165	2	1	416AR, RH THRUST REVERSER LOCKING ACTUATOR	*
SENSOR - L ENGINE, RH SLEEVE DEPLOY PROX, S167	2	1	416AR, RH THRUST REVERSER LOCKING ACTUATOR	*
SENSOR - R ENGINE, LH SLEEVE ACTUATOR LOCK PROXIMITY, S164	2	1	425AL, LH THRUST REVERSER LOCKING ACTUATOR	*
SENSOR - R ENGINE, LH SLEEVE DEPLOY PROX, S166	2	1	425AL, LH THRUST REVERSER LOCKING ACTUATOR	*
SENSOR - R ENGINE, RH SLEEVE ACTUATOR LOCK PROXIMITY, S165	2	1	426AR, RH THRUST REVERSER LOCKING ACTUATOR	*
SENSOR - R ENGINE, RH SLEEVE DEPLOY PROX, S167	2	1	426AR, RH THRUST REVERSER LOCKING ACTUATOR	*
SWITCH - (FIM 22-32-00/101) L T/R CONT, S23 (INDICATION) R T/R CONT, S24 (INDICATION)				
SWITCH - L T/R HYD PRESS, S330	2	1	434AL, L T/R ISOLATION VALVE	*
SWITCH - R T/R HYD PRESS, S331	2	1	444AL, R T/R ISOLATION VALVE	*
TIME DELAY - (FIM 31-01-36/101) L T/R ISLN VLV, M10440				
TIME DELAY - (FIM 31-01-37/101) R T/R ISLN VLV, M10439				
UNIT - (FIM 32-09-00/101) PROX SW ELEX, M162				

\* SEE THE WDM EQUIPMENT LIST

 Thrust Reverser Position Indicating System - Component Index  
 Figure 101

 EFFECTIVITY  
 AIRPLANES WITH SYNC-LOCKS



**78-36-00**

CONFIG 2

R01

Page 101

Sep 20/98



FUEL CONTROL PANEL, M73 (REF)

(A)


Component Location  
Figure 102 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS


**78-36-00**

CONFIG 2  
Page 102  
Sep 20/98

R01




ENGINE STRUT HYDRAULIC  
BAY ACCESS DOOR  
434AL (L ENG)  
444AL (R ENG)  
L OR R T/R ISOLATION  
VALVE (REF)  
SEE (B)




FAN C-DUCT AND  
THRUST REVERSER  
415AL (L ENG OUTBD)  
416AR (L ENG INBD)  
425AL (R ENG INBD)  
426AR (R ENG OUTBD)

L OR R ISOLATION  
VALVE PRESSURE SWITCH  
S330 OR S331



LOWER LOCKING  
HYDRAULIC ACTUATOR  
SEE (C)

LOWER LOCKING  
HYDRAULIC  
ACTUATOR (REF)



SLEEVE DEPLOY  
PROXIMITY SENSOR  
S166 OR S167

LOCK LEVER  
ARM (REF)  
SEE (D)

FEEDBACK  
LEVER (REF)

SENSOR TARGET  
(REF)


FEEDBACK  
ACTUATOR (REF)

LH LOWER LOCKING HYDRAULIC  
ACTUATOR (RH SIMILAR)  
(C)

L OR R T/R ISOLATION VALVE (REF)  
(B)

LOWER LOCKING  
HYDRAULIC  
ACTUATOR (REF)

SLEEVE ACTUATOR  
UNLOCKED PROXIMITY  
SENSOR S164 OR S165



SENSOR TARGET  
(REF)

LOCK LEVER  
ARM (REF)

LOCK LEVER ARM  
(D)

56066

Component Location  
Figure 102 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**

CONFIG 2


R01

Page 103

Sep 20/98

AMBER REV REMAINED  
DISPLAYED AFTER FULL  
REVERSE WAS REACHED

**PREREQUISITES**  
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29, 11B30, 11D11, 11D12  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Amber REV Remained Displayed After Full Reverse Was Reached  
Figure 103

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 104  
May 28/03


R01

AMBER REV DID NOT  
DISPLAY, GREEN  
REV DID WITH T/R  
FULLY DEPLOYED

**PREREQUISITES**

MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11D11,11D12,11B29,11B30

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Amber REV Did Not Display, Green REV Did with T/R Fully Deployed  
Figure 104 (Sheet 1)


EFFECTIVITY  
AIRPLANES WITH THRUST REVERSER  
INDICATION CIRCUIT PRE-SB 78-039

**78-36-00**  
CONFIG 2  
Page 105  
May 28/06

R02

AMBER REV DID NOT  
DISPLAY, GREEN  
REV DID WITH T/R  
FULLY DEPLOYED

**PREREQUISITES**  
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11D11, 11D12, 11B29, 11B30  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)



Amber REV Did Not Display, Green REV Did with T/R Fully Deployed  
Figure 104 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH THRUST REVERSER  
INDICATION CIRCUIT POST-SB 78-039

**78-36-00**  
CONFIG 2  
Page 106  
May 28/06

R02

**PREREQUISITES**


MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:

- 1 ▷ 11K6, 11K33; 2 ▷ 11B30, 11K12

MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)

**CAUTION:** DO NOT TOUCH THE PSEU CARD BEFORE YOU DO THE PROCEDURE FOR DEVICES THAT ARE SENSITIVE TO ELECTROSTATIC DISCHARGE. ELECTROSTATIC DISCHARGE CAN CAUSE DAMAGE TO PSEU CARD.

**T/R STOWED, AMBER REV REMAINED DISPLAYED**



- 1 ▷ AIRPLANES WITHOUT ETOPS
- 2 ▷ AIRPLANES WITH ETOPS


T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 1)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 107  
Jan 28/05

R02






T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 2)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 108  
Jan 28/05

R02




T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 3)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 109  
Jan 28/05

R02

FROM SHEET 2 (BLOCK 22)      FROM SHEET 3 (BLOCK 6)




T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 4)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 110  
Jan 28/05

R02

FROM SHEET 3  
(BLOCK 25)



T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 5)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 111  
Jan 28/05

R02

FROM SHEET 5 (BLOCK 10)      FROM SHEET 2 (BLOCK 23)

YES

NO

**11** IS THE CIRCUIT RESISTANCE ON THE PSEU TO EICAS CIRCUIT MORE THAN 20 MEGOHMS OF RESISTANCE TO GROUND? TEST THE CIRCUIT BY PLACING AN OHM-METER PROBE ON THESE PINS AND THE OTHER PROBE ON A GROUND:

**NOTE:** TURN EICAS OFF. DISCONNECT THE LINE TO BE TESTED FROM EICAS AND THE PSEU.

LEFT ENGINE (WDM 78-36-11, SHT 1)

<u>PSEU CONNECTOR</u>	<u>PSEU PINS</u>
D3210E	A12 E12
<u>LEFT EICAS CONNECTOR</u>	<u>LEFT EICAS PIN</u>
D319B	F3 G3
<u>RIGHT EICAS CONNECTOR</u>	<u>RIGHT EICAS PIN</u>
D321B	F3 G3

RIGHT ENGINE (WDM 78-36-21, SHT 2)

<u>PSEU CONNECTOR</u>	<u>PSEU PINS</u>
D3210A	A12 E12
<u>LEFT EICAS CONNECTOR</u>	<u>LEFT EICAS PIN</u>
D319D	F12 F14
<u>RIGHT EICAS CONNECTOR</u>	<u>RIGHT EICAS PIN</u>
D321D	F12 F14

NO

**51** LOCATE AND CORRECT THE UNSERVICEABLE INSULATION ON THE PSEU TO EICAS REV AMBER INDICATION WIRE (WDM 78-36-11, WDM 78-36-21).

YES


**52** REPLACE THE PSEU, M162 (AMM 32-09-03/401).

T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 6)

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 112  
Jan 28/05

R02



T/R Stowed, Amber REV Remained Displayed  
Figure 105 (Sheet 7)


EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 113  
Jan 28/05

R02

**THRUST REVERSER  
POSITION INDICATION  
SYSTEM PROBLEM**

**PREREQUISITES**  
MAKE SURE THESE CIRCUIT BREAKERS ARE CLOSED:  
11B29,11B30,11D11,11D12  
MAKE SURE THE AIRPLANE IS IN THIS CONFIGURATION:  
ELECTRICAL POWER IS ON (AMM 24-22-00/201)  
THRUST REVERSER IN STOWED POSITION (AMM 78-31-00/  
201)



Thrust Reverser Position Indication System Problem  
Figure 106

EFFECTIVITY  
AIRPLANES WITH SYNC-LOCKS

**78-36-00**  
CONFIG 2  
Page 114  
Jan 28/05

R06