

4730 Series Accessories

CW Sensor Probe Interconnects (without data adapter)

41-2A	Sensor/Probe Interconnecting Cable (5ft.)(M/M)
41-2A/10	Sensor/Probe Interconnecting Cable (10ft.)(M/M)
41-2A/20	Sensor/Probe Interconnecting Cable (20ft.)(M/M)
41-2A/50	Sensor/Probe Interconnecting Cable (50ft.)(M/M)
41-2A/100	Sensor/Probe Interconnecting Cable (100ft.)(M/M)

CW Sensor Adapters

95000601A	Adapter 50 Ohm N/75 Ohm N(M/F) (2520, 4200A, 4220A and 4300)
95109001A	Sensor Data Adapter (Smart Sensor 4230A, 5230, 9230)
95109101A	Data Adapter with Cable (5ft)
95109101A	Data adapter with cable instead of 41-2A
95109102A	Data Adapter with Cable (10ft)