

SERVICE INFORMATION

GP 605 / GP555 / GP605P

SERV INFO	PRODUCT	TYPE	DESC./SYMPTON	DATE ISSUED
K1-000003-01	GP605	Mech	Error Code (E063)	6/4/99
K1-000007-02	GP605	C.Q.	Updating the image adjustment basic procedure	15/4/99
K1-000009-UK2	GP605	Mech.	Retrofit modification	29/06/99
K1-000011-UK3	GP605	Retrofit	Jamming	02/07/99
K1-000014-01	GP605	C.Q.	Faint / Blank Copies	28/04/99
K1-000016-uk1	GP605	Elec.	Retrofit – Possible short circuit	09/06/99
K1-000018-01	GP605	Mods	Paper Jams	09/06/99
K1-000020-UK2	GP605	Mech	Original jams	28/06/99
K1-000022-01	GP605	Elec	Eprom Upgrade Version 10	30/07/99
K1-000024-01	GP605	Manual	Additions to Service Manual FY8-13FD-000	27/07/99
K1-000026-01	GP605/555	Mech	Jamming ADF	03/03/00
K1-000028-01	GP555	Differ	Introducing the GP555	15/09/99
K1-000029-01	GP605P	Differ	Differences between GP605 & GP605P	04/10/99
K1-000031-01	GP605	Bugs	Eprom upgrade to Version 21	15/09/99
K1-000035-01	GP605/555	Mech	Document Jams	03/12/99
K1-000037-01	GP605/555	Mech	ADF Reverse flapper stuck open	28/02/00
K1-000039-02	GP605/555/ GP605P	C.Q.	Uneven image in halftones	03/04/00
K1-000041-UK2	GP605/555/ GP605P	Elec/ (Retrofit)	Electrical short	28- 06/00
K1-000043-01	GP605/555	Elec	Eprom Upgrade to Ver.32/30	
K1-000049-01	GP605/555	Mech	Modification	27/04/00
K1-000050-01	GP605/555	Mech	ADF Jamming	11/04/00
K1-000053-02	GP605/555	C.Q.	Faint copies	13/10/00
K1-000055-01	GP605/555	Elec	Extra jam codes	29/1/02
K1-000058-01	GP605/555/ GP605P	Mainten.	Toner blockage	29/09/00

SERV INFO	PRODUCT	TYPE	DESC./SYMPTON	DATE ISSUED
K1-000060-01	GP605/555/ GP605P	C.Q.	Black dots	29/09/00
K1-000062-01	GP605/555	Bugs	Eprom upgrade IPver 33.01 ADF-Y ver10.01	20.03.01
K1-000066-01	GP605/555/ GP605P	Mech	Feint Copies	04/01/01
K1-000068-01	GP605/555/ GP605P	Bugs	Eprom Upgrade to MFC ver 33.03	02/03/01
K1-000070-01	GP605/555/ GP605P	CQ	Low life of separation corona wire	25/05/01
K1-000072-UK1	GP605/555/ GP605P	Mech	Corona Wire Modifications	07/03/01
K1-000075-01	GP605/555/ GP605P	Error code	E001	02/03/01
K1-000077-01	GP605/555/ GP605P / iR8500	Parts	Drum Compatibility	25/05/01
K1-000079-01	GP605/555/ GP605P	Mech	Improvement of Durability of ADF Hinge	19/03/02
K1-000081-01	GP605/555/ GP605P	Mech	Error Code E014 due to Fixing Motor Failure	19/03/02
K1-000083-01	GP605/555/ GP605P	Mech	Preventing Damage to the Pre- Last Original Sensor	04/07/02
K1-000084-01	GP605/555/ GP605P	Mech	Change in install procedure	16/01/03
END				