AII-SY- MODEL: GP605 / PS Printer Board-F1 SUBJECT: Device auto-configuration function under Win 95 The device auto-configuration feature of the PS Board-F1 Win 95 driver, that should automa discover what accessories are attached to the GP605 via IP or IPX protocols, does not func correctly when used with certain IP address ranges. An error occurs indicating that the devic cannot be located. This should only occur if the second octet of the IP address is 3-digit xxx.100.xxx.xxx (i.e; second octet is between 100-255) If any problems are experienced with the auto-config function, the options installed on the GI (Finisher, Side Paper Deck) will need to be manually set in the driver properties. When updated software is issued this bug will be corrected.	1011 —				AL INFORMA
SUBJECT: Device auto-configuration function under Win 95 The device auto-configuration feature of the PS Board-F1 Win 95 driver, that should automa discover what accessories are attached to the GP605 via IP or IPX protocols, does not func correctly when used with certain IP address ranges. An error occurs indicating that the device cannot be located. This should only occur if the second octet of the IP address is 3-digit xxx.100.xxx.xxx (i.e; second octet is between100-255) If any problems are experienced with the auto-config function, the options installed on the GP (Finisher, Side Paper Deck) will need to be manually set in the driver properties.					ATI-SY-
The device auto-configuration feature of the PS Board-F1 Win 95 driver, that should automa discover what accessories are attached to the GP605 via IP or IPX protocols, does not func correctly when used with certain IP address ranges. An error occurs indicating that the device cannot be located. This should only occur if the second octet of the IP address is 3-digit xxx.100.xxx.xxx (i.e; second octet is between100-255) If any problems are experienced with the auto-config function, the options installed on the GI (Finisher, Side Paper Deck) will need to be manually set in the driver properties.	MODEL:	GP605 / PS Printe	r Board-F1		
discover what accessories are attached to the GP605 via IP or IPX protocols, does not funct correctly when used with certain IP address ranges. An error occurs indicating that the device cannot be located. This should only occur if the second octet of the IP address is 3-digit xxx.100.xxx.xxx (i.e; second octet is between100-255) If any problems are experienced with the auto-config function, the options installed on the GP (Finisher, Side Paper Deck) will need to be manually set in the driver properties.	SUBJECT:	Device auto-configu	iration func	ction unde	er Win 95
If any problems are experienced with the auto-config function, the options installed on the GI (Finisher, Side Paper Deck) will need to be manually set in the driver properties.	discover what ac correctly when u cannot be located	cessories are attached to the sed with certain IP address d. This should only occur it	e GP605 via IP ranges. An erro f the second oct	or IPX proto or occurs indi	cols, does not funct cating that the devic
(Finisher, Side Paper Deck) will need to be manually set in the driver properties.					
When updated software is issued this bug will be corrected.	• •	-	-	-	
	When updated so	oftware is issued this bug wi	ll be corrected.		

_

.