

SERVICE BULLETIN

BULLETIN NUMBER: SB-0029
REVISION: 1-0-0
DATE: April 2007

PRODUCT DESCRIPTION: MT-4 Base Control Module

DE REFERENCE / CO: CO 6287

PRODUCTS EFFECTED: CI-BC-4E-00 (prior to s/n 10190)

SYMPTOMS: Trouble changing channels with tone remote adaptor from a non-Telex/Vega tone remote.

CAUSE: The jumpers JU125 & JU126 that add a delay to the AUX PTT i/p's are incorrectly labelled on PCB # 50138-03.

SOLUTION: Ignore the jumper indicators on the PCB for JU125 & JU126 and follow the board layout in the manual

PARTS REQUIRED: IM55-002

PROCEDURE: Follow instructions in Instruction Manual IM55-002

RETURN REQUESTS: Please contact the service department to obtain an RMA number and shipping instructions at 1-800-664-4066 or service@danelec.com

REVISION HISTORY:	Revision	Date	Description
	1-0-0	Apr 07	First Release