

SERVICE BULLETIN

BULLETIN NUMBER: SB-0055
REVISION: 1-0-0
DATE: MAR-2012

PRODUCT DESCRIPTION: Firmware Flashing Software v1.7.0.0 for UDB Flash Memory Replacement

DE REFERENCE / ECO: CO 6730

PRODUCTS AFFECTED: **Model Number(s):**
MT-4E Family and UIC Products

CAUSE / SYMPTOMS: Product manufactured after November 30, 2011 is not compatible with flashing firmware revisions below v1.7.0.0.

SOLUTION: Customers are advised to download the most recent version of the flashing firmware.

Navigate to the Daniels website (www.danelec.com) and download the latest bundle.

RETURN REQUESTS: To obtain an RMA number and shipping instructions, please contact Daniels service department at 1-800-664-4066 or service@danelec.com.

REVISION HISTORY:	Rev	Date	Description
	1-0-0	Mar 2012	First Release