

EPM2000 User's Guide Addendum

FAQ

- *Why doesn't the instrument indicate an invalid ratio when Channel A, Channel B, or both channels are overranging?*

If either or both channels are overranging while the instrument is in ratio mode, the ratio reading will be invalid. This is a known bug for instruments containing firmware Version 4.32 or earlier. If an accurate ratio reading is desired, prevent overranging by making sure enough headroom is available on the ranges selected for the individual channels.

Important: *Please update your manual with this added information.*

Customer Service Dept.
Molelectron Detector, Inc.