

## **New Firmware Information**

### **MCU 1.03, 3-18-2011**

\* Adds support for the K144RFLK pll lock board.

### **MCU 1.02, 9-30-2010**

\* MCU sleeps during receive to eliminate spurs.

### **MCU 1.01, 7-13-2010**

\* Increased shut-down temperature to ~75 C (was ~60C).

### **MCU 1.00, 1-28-2010**

\* Initial production release.