

SUBJECT : ERRATA FOR SERVICE MANUAL

The following changes must be made in the Service Manual:

Section 2 CHARACTERISTICS

page 2-4	* Max. Base Line Instability		
	Jump	0.1 div or 1 mV must be 0.2 div or 1 mV	
page 2-5	* Trigger sensitivity		
	≤ 10 MHz	≤ 0.8 div must be ≤ 1 div	
page 2-11	* Resistance		
	Accuracy	(25%+25) must be (2.5%+25)	
page 2-11	* Diode test		
	Accuracy must be	$\pm (2\% + 5)$	
	Voltage accuracy	$\pm (0.5\% + 5)$	applies for voltage measurement
	Measurement current	0.5 mA must be: 0.5 mA typically	

page 2-23 **ACCESSORIES**

PM9080/001 is not furnished with the instrument, but is optional.

Section 4 PERFORMANCE VERIFICATION PROCEDURE

Page 4-8 **14/15/16/17 Trigger sensitivity channel A & B (14 and 15 not for model 91)**

Add the following remark:

The verified limits include the trigger sensitivity and the trigger voltage level error.