

# FTK200 Optical Fiber Test Kit

**Users Guide** 

1568082 April 2000 © 2000 Fluke Corporation. All rights reserved. Printed in USA. All product names are trademarks of their respective companies.

#### LIMITED WARRANTY AND LIMITATION OF LIABILITY

Each Fluke product is warranted to be free from defects in material and workmanship under normal use and service. The warranty period is one year and begins on the date of shipment. Parts, product repairs, and services are warranted for 90 days. This warranty extends only to the original buyer or end-user customer of a Fluke authorized reseller, and does not apply to fuses, disposable batteries, or to any product which, in Fluke's opinion, has been misused, altered, neglected, contaminated, or damaged by accident or abnormal conditions of operation or handling. Fluke warrants that software will operate substantially in accordance with its functional specifications for 90 days and that it has been properly recorded on non-defective media. Fluke does not warrant that software will be error free or operate without interruption.

Fluke authorized resellers shall extend this warranty on new and unused products to end-user customers only but have no authority to extend a greater or different warranty on behalf of Fluke. Warranty support is available only if product is purchased through a Fluke authorized sales outlet or Buyer has paid the applicable international price. Fluke reserves the right to invoice Buyer for importation costs of repair/replacement parts when product purchased in one country is submitted for repair in another country.

Fluke's warranty obligation is limited, at Fluke's option, to refund of the purchase price, free of charge repair, or replacement of a defective product which is returned to a Fluke authorized service center within the warranty period.

To obtain warranty service, contact your nearest Fluke authorized service center to obtain return authorization information, then send the product to that service center, with a description of the difficulty, postage and insurance prepaid (FOB Destination). Fluke assumes no risk for damage in transit. Following warranty repair, the product will be returned to Buyer, transportation prepaid (FOB Destination). If Fluke determines that failure was caused by neglect, misuse, contamination, alteration, accident, or abnormal condition of operation or handling, including overvoltage failures caused by use outside the product's specified rating, or normal wear and tear of mechanical components, Fluke will provide an estimate of repair costs and obtain authorization before commencing the work. Following repair, the product will be returned to the Buyer transportation prepaid and the Buyer will be billed for the repair and return transportation charges (FOB Shipping Point).

THIS WARRANTY IS BUYER'S SOLE AND EXCLUSIVE REMEDY AND IS IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. FLUKE SHALL NOT BE LIABLE FOR ANY SPECIAL, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES OR LOSSES, INCLUDING LOSS OF DATA, ARISING FROM ANY CAUSE OR THEORY.

Since some countries or states do not allow limitation of the term of an implied warranty, or exclusion or limitation of incidental or consequential damages, the limitations and exclusions of this warranty may not apply to every buyer. If any provision of this Warranty is held invalid or unenforceable by a court or other decision-maker of competent jurisdiction, such holding will not affect the validity or enforceability of any other provision.

> Fluke Corporation P.O. Box 9090 Everett, WA 98206-9090 U.S.A.

Fluke Europe B.V. P.O. Box 1186 5602 BD Eindhoven The Netherlands

11/99

# **Table of Contents**

#### Title

#### Page

| ▲Safety Information                       | iv |
|---|----|
| Cleaning Fiber Connections                | iv |
| Introduction                              | 1  |
| Contacting Fluke                          | 2  |
| Unpacking                                 | 2  |
| Features                                  | 4  |
| Measuring Optical Power                   | 8  |
| Setting a Reference for Loss Measurements | 10 |
| Measuring Optical Power Loss              | 12 |
| Memory Functions                          | 14 |
| Saving and Reviewing Measurements         | 14 |
| Replacing Saved Measurements              | 14 |
| Deleting Saved Measurements               | 14 |
| Maintenance                               | 15 |
| Battery Replacement                       | 15 |
| Accessories and Replacement Parts         | 16 |
| Calibration and Service                   | 17 |
| FM150 Fiber Meter Specifications          | 17 |
| FS150 Fiber Source Specifications         | 18 |

| Appendix A: Using the Serial Port     | 21 |
|---------------------------------------|----|
| Appendix B: Using Data-LINK™ Software | 23 |
| Appendix C: Glossary                  | 29 |

# List of Figures

#### Figure

Title

#### Page

| 1. | Standard Equipment          | . 3  |
|----|-----------------------------|------|
|    | FM150 Fiber Meter Features  |      |
|    | Display Features            |      |
|    | FS150 Fiber Source Features |      |
| 5. | Measuring Optical Power     | 9    |
|    | Setting a Reference         |      |
| 7. | Measuring Loss              | . 13 |
|    | Battery Replacement         |      |
|    |                             |      |

# List of Tables

#### Table

#### Title

#### Page

| 1. | FM150 Fiber Meter Features        | 5 |
|----|-----------------------------------|---|
|    | Accessories and Replacement Parts |   |
|    | Pin Assignments for Serial Cable  |   |
|    | Report Header Information         |   |

# ▲ Safety Information

# 

To avoid possible eye damage caused by hazardous radiation:

- Never look directly into optical output connectors. Some sources produce invisible radiation that can permanently damage your eyes.
- Do not open the case, except to change the battery; no user-serviceable parts are inside.

#### Caution

To avoid false test results, replace the battery as soon as the low battery indicator (BAT) appears.

# **Cleaning Fiber Connections**

Always clean the fiber ends before making connections. Use any of the following:

- Lint-free swabs or wipes moistened with isopropyl alcohol
- Pre-moistened swabs or wipes approved for use on fiber connectors

Canned air approved for use on fiber connectors is also useful for dislodging contamination. Protect all connectors with dust caps when not in use.

# **Optical Fiber Test Kit**

#### Introduction

The FTK200 Optical Fiber Test Kit is used to measure optical power and optical power loss at 850 nm, 1300 nm, 1310 nm, and 1550 nm. This test kit includes the FM150 Fiber Meter (also referred to as "the meter"), which has the following features:

- Measures optical power loss of multimode or singlemode fibers.
- Measures output power from optical sources such as network interface cards or optical test equipment.
- Displays output power measurements in dBm or µW.
- Operates for up to 30 hours on a single 9 V alkaline battery. Automatic power-down feature helps conserve battery power.

- Displays remaining battery life.
- Designed to use the optional ToolPak<sup>™</sup> Meter Hanging Kit from Fluke.
- Saves up to 500 measurements for each wavelength.
- Serial port lets you print measurements on a serial printer or upload measurements to a PC.
- Data-LINK<sup>™</sup> software runs on a PC to let you upload measurements from the meter, view measurements, add header information to create test reports, and save and print reports.
- Data-LINK lets you capture live data from the meter for optical power stability tests.

The FTK200 Kit also includes a Fluke FS150 Fiber Source, which provides light for multimode testing at 850 nm and 1300 nm. For testing singlemode fiber, Fluke offers the optional LS-1310/1550 Laser Source.

The instructions in this guide assume you are using the FS150 source included. For other optical sources, refer to the manufacturer's instructions.

# **Contacting Fluke**

Visit Fluke's Web site at www.fluke.com.

To order accessories, receive operating assistance, or get the location of the nearest Fluke distributor or Service Center, call:

- USA: 1-888-99-FLUKE (1-888-993-5853)
- Canada: 1-800-363-5853
- Europe: +31-402-678-200
- Japan: +81-3-3434-0181
- Singapore: +65-738-5655
- Anywhere in the world: +1-425-356-5500

# Unpacking

The equipment listed below and shown in Figure 1 is included with the FTK200 Kit. If anything is missing or damaged, contact the place of purchase immediately.

- FM150 Fiber Meter (with 9 V battery installed)
- ST adapter cap (with dust cap) for FM150 Fiber Meter
- FS150 Fiber Source (with 9 V battery and dust cap installed)
- ST adapter cap (with dust cap) for FS150 Fiber Source
- 2 ST/ST 3 ft (1 m) 62.5 µm multimode patch cords
- 1 ST/ST 1 ft (0.3 m) 62.5 μm multimode test jumper
- 1 ST/ST adapter (singlemode quality)
- Data-LINK PC utility diskette
- RS-232 PC interface cable
- 2 recording pads
- FTK200 Optical Fiber Test Kit Users Guide
- Warranty registration card
- Hard carrying case

#### Optical Fiber Test Kit Unpacking




Figure 1. Standard Equipment

afz02f.eps.

# Features

Figures 2 and 3 and Table 1 describe the meter's features. Figure 4 describes the features of the FS150 Fiber Source included in the kit.




Figure 2. FM150 Fiber Meter Features

#### Table 1. FM150 Fiber Meter Features

| Item       | Description   |  |
|------------|---|--|
| 1          | On/off key. Hold down ① to turn the meter on. The automatic power-down feature, which turns the meter off if no keys are pressed for 5 minutes, is enabled when you turn the meter on. To disable this feature, turn the meter off; then hold down ① until <b>P</b> is displayed.   |  |
| (2)<br>(3) | Press receipt to save the current measurement in non-volatile memory. Press receipt briefly to view or replace a saved measurement. Hold down receipt to send stored measurements to a PC or serial printer. See "Memory Functions" and Appendices A and B for details. To clear from memory all saved measurements for the current wavelength, hold down receipt and receipt together until <b>HELD</b> appears. |  |
| 4          | Toggles the meter between power (dBm) and loss (dB) measurements. Loss readings are compared to the stored reference level. Hold down $\frac{dB}{dBM}$ until <b>HELD</b> appears to change the measurement units to $\mu W$ .   |  |
| 5          | Press (REF) briefly to display the reference value for the currently selected wavelength. Hold down (REF) to store a new reference value for the displayed wavelength.  |  |
| 6          | LCD display. See Figure 3 for details.  |  |
| 7          | Serial connector for printing to a serial printer or uploading saved measurements to a PC.  |  |
| 8          | Removable adapter cap with an ST connector for connecting to multimode or singlemode patch cords.   |  |
| 9          | Changes the wavelength to be measured. To see the percentage of battery life remaining, hold down $\lambda$ until <b>HELD</b> appears.  |  |
| (10)       | Used in recall mode to scroll through saved measurements.   |  |




Figure 3. Display Features




Figure 4. FS150 Fiber Source Features

# Measuring Optical Power

Optical power is the output power produced by a source such as an optical network interface card or optical test equipment. You can measure power at a source or at the end of a fiber link.

To measure optical power, proceed as follows:

1. Verify that the meter and source are set to the proper wavelength. Let the source warm up for two minutes, if necessary.

- 2. Clean all fiber ends.
- 3. Make the connections shown in Figure 5.
- Verify that the meter is in the power measurement mode. The measurement unit should be dBm. If necessary, press (<sup>dB</sup>/<sub>dEm</sub>) to change the measurement unit to dBm. To change the unit to μW, hold down (<sup>dB</sup>/<sub>dEm</sub>) until HELD appears on the display.
- 5. Read the power measurement.

#### **Optical Fiber Test Kit** Measuring Optical Power




Figure 5. Measuring Optical Power

afz04f.eps

# *Setting a Reference for Loss Measurements*

Setting a reference lets the meter automatically subtract from loss measurements the losses due to patch cords. The loss for a fiber under test is automatically calculated as the difference between the reference loss and the loss with the fiber inserted.

For the most accurate test results, you should set the reference at these times:

- Anytime you start using a different optical source for loss measurements
- Anytime you change the patch cord used on the meter or source.

#### Note

For the most accurate test results, set the reference at the beginning of each day using the patch cords and wavelength settings you will use for testing.

The meter stores a separate reference value for each wavelength. The reference values are not affected when you turn the meter off or change the battery.

To view the reference for the selected wavelength, press  $\ensuremath{\left[ n \ensuremath{\tiny EP} \ensuremath{\right]}}$  briefly.

To set a reference, proceed as follows:

- 1. Set the source to the wavelength you will use for testing. Let the source warm up for two minutes.
- 2. Select two known-good patch cords of the same type as the fiber to be tested. Select one known-good adapter of the appropriate type. Clean all fiber ends.
- To set the reference, hold down ref until HELD appears on the display. The loss reading should then change to 0 dB. The last digit may vary slightly because of fiber movement and minor variations in the output power of the source.
- 5. If you are testing with more than one wavelength, change the meter and source to the new wavelength, then repeat step 4.




Figure 6. Setting a Reference

afz05f.eps

# Measuring Optical Power Loss

Optical power loss is the light energy lost through the fiber, adapters, splices, and other components in a fiber link. The loss for a fiber under test is automatically calculated as the difference between the loss with the fiber inserted and the reference loss. (See Figures 6 and 7.)

To measure loss, proceed as follows:

1. Verify that the meter and source are set to the proper wavelength. Let the source warm up for two minutes, if necessary.

#### Note

The patch cords used for loss measurements should be the same patch cords used to set the reference at the wavelength you are testing. If the patch cords have been disconnected from the meter or source since the reference was set, set the reference again before measuring loss.

- 2. Clean all fiber ends.
- 3. Set a reference, if necessary. (See the previous section "Setting a Reference for Loss Measurements" for details.)
- 4. Make the connections shown in Figure 7.

#### Note

The additional test jumper used during loss measurement ensures that the loss you measure includes the fiber to be tested and the connections at both ends of the fiber.

- Verify that the meter is in the loss measurement mode. If so, the unit of measurement will be dB. If it is not, press <sup>(dB)</sup>/<sub>(dBm)</sub>.
- 6. Read the loss measurement.




Figure 7. Measuring Loss


# **Memory Functions**

The FM150 Fiber Meter lets you save loss and power measurements in non-volatile memory. Saved measurements are not lost when you change the battery. You can save up to 500 measurements for each wavelength. You can send the measurements directly to a serial printer or upload them to a PC. Refer to the Appendix for more information on connecting to a printer or PC.

#### Saving and Reviewing Measurements

To save the current reading, press well. The reading is saved in the next available memory location, which is briefly displayed. You can also use the test results pad included with the meter to record the storage location number, fiber identification, file name, and comments about the results.

To review saved measurements, press  $\lambda$  to select the desired wavelength; then press  $\frown$ . The highest memory location used is alternately displayed with its contents. Use  $\blacktriangle$   $\checkmark$  to scroll through the memory locations.



#### **Replacing Saved Measurements**

You can save a new measurement in any memory location, as follows:

- 1. Press <sup>man</sup>; then use ▲ ▼ to select the memory location you want to change.
- 2. Hold down the wey until **HELD** appears. The meter then switches to measurement mode.
- 3. Make a new loss or power measurement; then press

#### **Deleting Saved Measurements**

To delete all measurements saved for the currently selected wavelength, hold down both real and real until HELD appears.

To delete all saved measurements, delete the measurements for each wavelength.

### Maintenance

Clean the case with a soft cloth dampened with water or a mild detergent. Do not use solvents or abrasive cleansers.

Always cover the connector with the dust cap when not using the meter.

Do not open the case (except to replace the battery). No user-serviceable parts are inside.

#### **Battery Replacement**

Replace the battery in the FM150 Fiber Meter when **BAT** appears at the top of the display. Refer to Figure 8.

Replace the battery in the FS150 Fiber Source when the light in the power switch blinks or does not turn on. Refer to Figure 8.




Figure 8. Battery Replacement

#### Accessories and Replacement Parts

Table 2 shows the accessories and replacement parts available from Fluke for the FTK200 Optical Fiber Test Kit.

| Table 2. Accessories and Replacement Parts |
|--|
|--|

| Description                             | Fluke Model or<br>Part Number |
|---|-------------------------------|
| Recording pads, pack of 10              | NF410                         |
| ToolPak™ meter hanging kit              | TPAK                          |
| ST adapter cap for FM150 Fiber Meter    | 1568277                       |
| ST adapter cap for FS150 Fiber Source   | 1568292                       |
| ST/ST 62.5 $\mu$ m multimode patch cord | FOC-ST/ST                     |
| ST/SC 62.5 $\mu$ m multimode patch cord | FOC-ST/SC                     |
| ST/ST 62.5 $\mu$ m short test jumper    | NF230                         |
| ST/ST adapter                           | NF300SM                       |
| SC/SC adapter                           | NF310SM                       |

#### Table 2. Accessories and Replacement Parts (cont.)

| Description  | Fluke Model or<br>Part Number |
|--|-------------------------------|
| LS-1310/1550 Laser Source                                | LS-1310/1550                  |
| RS-232 PC interface cable,<br>9-pin to 3-conductor plug  | 1568303                       |
| Battery door for FM150 Fiber Meter or FS150 Fiber Source | 1568289                       |
| Users guide, English                                     | 1568082                       |
| Mode d'Emploi, français                                  | 1568094                       |
| Manuale d'Uso, italiano                                  | 1568156                       |
| Bedienungs-Handbuch, Deutsch                             | 1568100                       |
| Manual de Uso, español                                   | 1568139                       |
| Manual do Usuário, português                             | 1568142                       |
| Users guide, Simplified Chinese                          | 1568121                       |
| Users guide, Japanese                                    | 1568117                       |

#### Calibration and Service

Have the meter calibrated at an authorized Fluke Service Center every 12 months. For service, contact an authorized service center. To locate the nearest service center, contact Fluke as described at the beginning of this guide.

| Detector type                          | Germanium  |
|--|--|
| Calibrated wavelengths                 | 850 nm, 1300 nm, 1310 nm, and 1550 nm  |
| Measurement range                      | +6 dBm to -50 dBm  |
| Resolution                             | 0.01 dB  |
| Loss and power<br>measurement accuracy | ±0.25 dB at 25 °C and -10 dBm  |
| Temperature range                      | Operating: 0 °C to +50 °C; Storage: -30 °C to +60 °C                           |
| Humidity range                         | Operating: 0 to 95 % RH, non-condensing  |
| Battery type and life                  | 9 V alkaline (NEDA 1604A or IEC 6LR61); 30 hours typical with alkaline battery |
| Low battery indication                 | BAT appears on the display.  |
| Display                                | 4-digit LCD display  |

# FM150 Fiber Meter Specifications

#### FM150 Fiber Meter Specifications (cont.)

| Memory                   | Stores up to 500 measurements for each wavelength. Measurements are stored in non-volatile memory, which is retained when power is off or the battery is changed. Memory contents can be uploaded to a PC or sent directly to a serial printer. |
|--------------------------|---|
| Serial port<br>connector | 3.5 mm, 3-conductor phone jack  |
| Certifications           | CE  |
| Dimensions               | 3.2 in x 5.8 in x 1.5 in (8.1 cm x 14.7 cm x 3.8 cm)  |
| Weight                   | 8.6 oz (244 g)  |

# FS150 Fiber Source Specifications

| Light source  | Light source Infrared LED |  |
|---|---------------------------|--|
| Wavelength 850 nm ±30 nm; 1300 nm -10 nm/+50 nm           |                           |  |
| Output power -20 dBm nominal into 62.5 µm multimode fiber |                           |  |
| Connector ST  |                           |  |

#### FS150 Fiber Source Specifications (cont.)

| Stability              | ±0.1 dB per 8 hours at 25 °C   |
|------------------------|--|
| Battery type and life  | 9 V alkaline (NEDA 1604A or IEC 6LR61); 30 hours typical with alkaline battery |
| Low battery indication | Blinking LED in power switch   |
| Temperature range      | Operating: 0 °C to 50 °C; Storage: -20 °C to +70 °C                            |
| Humidity               | Up to 90 % RH  |
| Certifications         | CE   |
| Dimensions             | 3.2 in x 5.6 in x 1.5 in (8.1 cm x 14.2 cm x 3.8 cm)                           |
| Weight                 | 7.2 oz (204 g)   |

# Appendix A Serial Communications

#### Using the Serial Port

The serial port on the FM150 Fiber Meter lets you send saved measurements to a PC or a serial printer.

The interface cable provided is configured for serial communication with a PC. An adapter might be required for connecting directly to a serial printer. Table 3 gives the pin assignments for the serial cable. Refer to your printer's documentation for the printer's serial port pin assignments.

Table 3. Pin Assignments for Serial Cable

| Phone Plug<br>Conductor | Pins on 9-pin<br>Connector | Signal        |
|-------------------------|----------------------------|---------------|
| Tip                     | 7                          | Clear to Send |
| Ring                    | 2                          | Transmit Data |
| Sleeve                  | 5                          | Ground        |

The data protocol for the serial port is 1200 baud, 8 data bits, 1 stop bit, no parity, and XON/XOFF data flow control.

#### Sending Measurements to a Printer

To send measurements directly to a serial printer, proceed as follows:

- 1. Turn on the FM150 Fiber Meter and the printer.
- 2. If necessary, set the printer to the data protocol given under "Using the Serial Port" in this appendix. Refer to the documentation for your printer for its configuration instructions.
- 3. Use the RS-232 interface cable provided (with an adapter, if necessary) to connect the meter to the printer.
- 4. On the meter, press when to enter the recall mode; then hold down when until **HELD** appears. All measurements stored for all wavelengths are transmitted to the printer. When all measurements are transferred, **HELD** disappears.

#### Sending Measurements to a PC

To send measurements to a PC, use the Data-LINK  $^{\rm TM}$  software provided with the meter.

For instructions on installing and using Data-LINK, see the Appendix "Using Data-LINK Software" in this manual.

# Appendix B Using Data-LINK Software

#### Introduction

Data-LINK<sup>™</sup> software lets you do the following:

- Upload stored power and loss measurements from a Fluke FM150 Fiber Meter to a PC.
- Add header information to test results to create fiber test reports.
- Use a PC to monitor and capture live power or loss measurements from an FM150 Fiber Meter.

# System Requirements

To install and use Data-LINK software, you need the following:

- A 386-, 486-, or Pentium-based personal computer or laptop computer
- 4 MB RAM (minimum)
- Microsoft Windows® operating system
- A 1.44 MB 3.5 in floppy disk drive
- A 9-pin serial communication port on the PC

# Installing Data-LINK Software

- 1. Quit all applications in the Windows operating system.
- 2. Insert Data-LINK disk 1 into the floppy disk drive.
- 3. Click Start on the Windows desktop; then click Run....
- 4. Click **Browse**, select the floppy disk drive; then click **Setup.exe**.
- 5. Click **Open** then **OK** to start the installation process.
- Follow the instructions displayed by the Data-LINK software. When the installation is complete, click OK.

# Running Data-LINK Software

To run Data-LINK, click **Start** on the Windows desktop, click **Programs**; then click the Data-LINK icon.

# *Connecting the FM150 Fiber Meter to a PC*

- 1. Use the RS-232 PC interface cable included with the meter to connect the meter's serial port to a 9-pin serial port on the PC. Note which PC port number is used (Com 2, for example).
- 2. At the top of the Data-LINK window, click Settings.
- In the Communication Settings dialog box, select the PC Com port connected to the fiber meter; then click OK.

# Uploading and Saving Test Results

- 1. At the top of the Data-LINK window, click the File menu; then click Receive Stored Report.
- 2. Turn on the FM150 Fiber Meter by holding down (<sup>①</sup>) until **P** appears.
- 3. Press where the recall mode; then hold down where until **HELD** appears on the display. In a few seconds, test results will begin to appear in the Data-LINK window on the PC.
- When all of the test results are transferred, the Data-LINK Receive Report window changes from Receive Report to Report Complete. Click OK to close the Receive Report window. Turn off the meter to save battery life.

- 5. Enter the desired header information for the test results, as described in Table 4.
- 6. To save the results, click File then click Save As Report or Save As Data.

**Save As Report** saves the results as a fiber test report file (.fbr) that you can open later in Data-LINK.

**Save As Data** saves the results as a comma-separated value file (.csv), which can be opened in most spreadsheet applications.

#### Note

Data-LINK does not open .csv files.

7. In the Save dialog box, select a location for saving the results; then click **Save**.

#### **Table 4. Report Header Information**

| Field    | Description  |  |
|----------|--|--|
| Company  | Name of the organization where testing was performed.                    |  |
| Operator | Name of the operator who did the testing.                                |  |
| Location | Location of the fibers tested.   |  |
| Cable #  | Cable identification for the fibers tested.                              |  |
| Fibers   | From: The end of the fiber link where the fiber optic source was placed. |  |
|          | To: The end of the fiber link where the FM150 Fiber Meter was placed.    |  |
| Date     | You can enter the date of testing to replace the default current date.   |  |
| Time     | You can enter the time of testing to replace the default current time.   |  |

# **Capturing Live Measurements**

Capturing live measurements helps you automatically record the stability of optical signal power over time.

- 1. Connect the meter to a PC and to the optical signal to be measured.
- If you need to capture more than 4 minutes of data, turn on the meter by holding down 

   until P appears on the display. This disables the automatic powerdown feature until the meter is turned off and on again.
- 3. Set the meter up to measure output power (dB) at the correct wavelength. Verify that the meter is measuring as expected.
- 4. At the top of the Data-LINK window, click **File**; then click **Capture Live Data**.

- In the Capture Live Data window, click File; then click Start Capture. Select a sampling interval; then click OK.
- 6. In the Save Captured Data window, enter a file name and directory for saving the data; then click **OK** to begin collecting data. The word "CAPTURING" blinks in the Capture Live Data window while data is being captured.

The Capture Live Data window displays the measurements as shown on the meter. Data-LINK software saves the measurements at the interval you specified.

7. To stop capturing data, click the File menu; then click End Capture.

The captured data is saved as a comma-separated value file (.csv), which can be opened by most spreadsheet applications.

# **Opening and Printing Reports**

To open a previously saved Data-LINK fiber test report (file extension .fbr), proceed as follows:

- 1. At the top of the Data-LINK window, click the File menu; then click **Open**.
- 2. Select the directory where the test report is saved, click on the report; then click **Open**.

#### Note

If a Data-LINK file does not open, it has probably been corrupted or is not a valid Data-LINK file.

#### **Printing Single Reports**

To print one report, open the report; then click the File menu; then click **Print**. Select the desired print options; then click **OK**.

#### **Printing Multiple Reports**

- 1. Click the File menu; then click Batch Print.
- 2. In the Batch Print dialog box, select the reports you want to print as follows:
  - To select a block of reports for printing, click on the first report in the block; then hold down the Shift key and click on the last report in the block.
  - To select non-sequential reports for printing, hold down the Ctrl key and click on the desired reports.
- 3. Click **Open**. In the Print dialog box, select the desired print options; then click **OK**.

# Appendix C Glossary

# Adapter

A device used to mate fiber connectors of the same or different styles.

### Attenuation

A loss of optical power due to losses in the fiber itself or in connections between fibers.

### Core

The light-conducting central portion of an optical fiber.

### dBm

A unit of power (in decibels), assuming a reference of 1 mW (1/1000 of a watt).

### Insertion loss

Loss of optical power caused by adding a connector, adapter, splice, or other optical component to a fiber path.

### Launch cable

A fiber patch cord used to couple an optical source to a fiber.

# Macrobending losses

Light losses due to large-radius bends in a fiber, such as bends made during installation.

# Microbending losses

Light losses due to microscopic imperfections in a fiber.

# Multimode fiber

Fiber with a relatively large core (50  $\mu$ m or more) that offers many paths, or modes, for propagation of light.

# Optical power

Optical power measured at a source or the end of a fiber and expressed in microwatts ( $\mu$ W) or in decibels with reference to one milliwatt (dBm).

# Receive cable

A fiber patch cord used to couple a fiber to an optical receiver.

# SC connector

Subscription Channel Connector. An optical connector that originated in Japan and provides push-pull connections, low loss, and low backreflection.

# Singlemode fiber

Fiber with a small core (8  $\mu m$  to 10  $\mu m)$  that offers just one path, or mode, for propagation of light.

# ST connector

Straight-Tip Connector. A popular fiber connector originally developed by AT&T.

# Test Jumper

A short patch cord used when testing a fiber link.