

The G1000 Documentation Update Kit for the Diamond DA40 (P/N K00-00178-01) contains all of the documents that were updated as a result of the release of G1000 system software version 0369.07.

The following table itemizes both the updated documentation contained in Kit K00-00178-01 (see “P/N” column) and the corresponding document part numbers to be replaced (see “Replacement for P/N” column):

Item No.	P/N	Title	Replacement for P/N
1	190-00363-02	G1000 Pilot’s Guide for the Diamond DA40	190-00363-01
2	190-00380-02	G1000 Engine Indication System Pilot’s Guide for the Diamond DA40	190-00380-01
3	190-00381-02	G1000 Multi Function Display Pilot’s Guide for the Diamond DA40	190-00381-01
4	190-00459-01	G1000 Documentation Update Kit Instructions for the Diamond DA40	190-00459-00

- **Items 1 through 3** should be inserted in the G1000 Pilot’s Guide binder.
- **Item 4** represents this document and does not need to be inserted in the G1000 Pilot’s Guide binder, nor does it need to be kept on the G1000-equipped aircraft.



NOTE: These items are meant to replace the documents whose part numbers are listed under table column entitled “Replacement for P/N”. In said column, “N/A” indicates that the document included in the update kit either is new—and thus is an addition to the G1000 Pilot’s Guide documentation—or is not designed to be part of the G1000 updated Pilot’s Guide binder documentation.