

## S E R V I C E N O T E

SUPERSEDES:

NONE

**HP MODEL 1310B X-Y DISPLAY**  
**ALL SERIAL PREFIXES**  
**ARCING/BREAKDOWN OF PA CONNECTOR**

High voltage arcing can contribute to the breakdown of the post accelerator connector.

When servicing the instrument or replacing a CRT a small amount of high voltage grease, (HP Part Number 8500-0059\*), should be applied to the mating surfaces of the PA connector. This will prevent arcing from the connector.

\*Dow corning 5 compound™

I/NS/WN

11/81-08/BL



**FOR MORE INFORMATION, CALL YOUR LOCAL HP SALES OR SERVICE OFFICE** or East (201) 265-5000 ● Midwest (312) 255-9800 ● South (404) 955-1500 ● West (213) 970-7500 or (415) 968-9200; **OR WRITE**, Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. **IN EUROPE, CALL YOUR LOCAL HP SALES or SERVICE OFFICE OR WRITE**, Hewlett-Packard S.A., 7, rue du Bois-du-Lan, P.O. Box, CH-1217 MEYRIN 2 - Geneva, Switzerland. **IN JAPAN**, Yokogawa-Hewlett-Packard Ltd., 9-1, Takakura-cho, Hachioji-shi, Tokyo, Japan 192.