

MANUAL CHANGES

MANUAL IDENTIFICATION

Model Number: 8447B
Date Printed: January 1971
Part Number: 08447-90006

This supplement contains important information for correcting manual errors and for adapting the manual to instruments containing improvements made after the printing of the manual.

To use this supplement:

Make all ERRATA corrections

Make all appropriate serial number related changes indicated in the tables below.

Serial Prefix or Number	Make Manual Changes	Serial Prefix or Number	Make Manual Changes
1145A	1		

► NEW ITEM

► ERRATA

Page 8, paragraph 49:

Change step 3 to read "Move the 10 dB attenuator from 8447B OUTPUT to INPUT"

CHANGE 1

Page 20, Table 5, Change to read:

2	5000-7891	SIDE COVER-BLUE GRAY
5	5060-0708	TOP COVER-BLUE GRAY
8	08447-00011	PANEL:FRONT (STANDARD)-LIGHT GRAY
8	08447-00012	PANEL:FRONT (OPTION 001)-LIGHT GRAY
8	08447-00013	PANEL:FRONT (OPTION 010)-LIGHT GRAY
8	08447-00014	PANEL:FRONT (OPTION 011)-LIGHT GRAY
9	5000-0710	BOTTOM COVER-BLUE GRAY

Add the following:

2	5000-8766	SIDE COVER-OLIVE GRAY
5	5060-8553	TOP COVER-OLIVE GRAY
8	08447-00034	PANEL:FRONT (STANDARD)-MINT GRAY
8	08447-00035	PANEL:FRONT (OPTION 001)-MINT GRAY
8	08447-00036	PANEL:FRONT (OPTION 010)-MINT GRAY
8	08447-00037	PANEL:FRONT (OPTION 011)-MINT GRAY
9	5000-8569	BOTTOM COVER-OLIVE GRAY

NOTE

Manual change supplements are revised as often as necessary to keep manuals as current and accurate as possible. Hewlett-Packard recommends that you periodically request the latest edition of this supplement. Free copies are available from all HP offices. When requesting copies quote the manual identification information from your supplement, or the model number and print date from the title page of the manual.