Agilent PNA Microwave Network Analyzers

Application Note 1408-15

Banded Millimeter-Wave Measurements with the PNA






Table of Contents

Introduction	3
System Configuration	4
System Operation	
Configuring millimeter-wave modules	
Configuring external synthesizers1	
Operational notes14	
Power control14	4
Power leveling1	5
Expected output power1	5
IF BW selection1	5
Resolution of frequency source1	5
Multiple channels1	5
System Calibration	6
Choosing the right calibration technique10	6
Loading and checking calibration definition file1	
Configuration #1: Two T/R modules20	
Configuration #2: One T/R & one T modules2	
Application Examples	4
Example #1: Antenna measurements24	
Example #2: Pulsed measurements	
Example #3: Materials measurements2	
Appendix A: Creating Your Own Waveguide Calibration Kit Definition	
Appendix B: Performing Calibrations	4
SmartCal, 2-port34	4
SmartCal, 1-port3	
Unguided Calibration, Thru Response3	9
Appendix C: Caring for Waveguide Interfaces4	1
Appendix D: Supplemental Data42	2

Introduction

Millimeter-wave is becoming more common as measurement needs are pushed beyond 110 GHz, to 220 GHz, 325 GHz, and even 1 THz! Applications include on-wafer device characterizations as well as various types of materials measurements.

The PNA series network analyzers can be configured for wide dynamic range reflection and transmission measurements of components at millimeter-wave frequencies. Two types of millimeter-wave solutions are available from Agilent Technologies:

- One solution is the N5250A network analyzer. With 1.0mm coaxial test port connectors, this solution provides single, continuous measurement sweeps from 10 MHz to 110 GHz.
- 2. The other solution is based on banded millimeter-wave test head modules with waveguide (WG) interfaces. System configuration differs depending on frequency range of interest.

The objective of this application note is to provide detailed information on the banded millimeter-wave solutions. This includes system configurations, system operation, system calibration, and some typical measurement examples. This note applies to the following product numbers within the PNA series: E8362B, E8363B, E8364B, and E8361A.

System Configuration

Figure 1 shows two types of banded millimeter-wave systems. These system configurations include the VNA2 waveguide (WG) test head modules from Oleson Microwave Laboratory (OML).




Figure 1. Two banded millimeter-wave systems: (a) one without external synthesizers, and (b) one with external synthesizers.

Each banded millimeter-wave configuration includes four components.

- 1. The receiver
- 2. The N5260A test set controller
- 3. Two waveguide test head modules
- 4. Two external synthesizers. These may not be necessary for lower frequency bands, but they are recommended for operations above 110 GHz and are required for operations at or above 220 GHz.

Table 1 shows configuration details per frequency range.

Table 1. Banded millimeter-wave configurations.

System Configurations	WR-15 50 – 75 GHz	WR-12 60 – 90 GHz	WR-10 75 – 110 GHz	WR-08 90 – 140 GHz	WR-06 110 – 170 GHz	WR-05 140 – 220 GHz	WR-03 220 – 325 GHz
Receiver	Any PNA series with Options 014, 080, 081, UNL, and H11 • E8362B, 10 MHz to 20 GHz • E8363B, 10 MHz to 40 GHz • E8364B, 10 MHz to 50 GHz • E8361A, 10 MHz to 67 GHz						
Test Set Controller	N5260A ¹						
Test Head Modules	N5260AW15	N5260AW12	N5260AW10	N5260AW08	N5260AW06	N5260AW05	N5260AW03
External Synthesizers				Recommended: E8257D with Option 520 (Qty of 2; one for RF and one for LO)			Required: E8257D with Option 520 (Qty of 2; one for RF and one for LO

• 8121-1221 x4 RF and LO 3.5 mm Cable (N5260A to test modules, front)

^{1.} Each N5260A includes:

^{• 85105-60030} x2 Bias Cable (N5260A to test modules, front)

^{• 85105-60033} x4 IF Signal Cable (N5260A to test modules; SMA, front)

 ⁰⁸⁵⁰³⁻⁶⁰⁰⁵¹ x1 Test Set Interface Cable (PNA to N5260A, rear)

^{• 8120-1839} x4 IF Signal Cable (N5260A to PNA; BNC, rear)

 ⁵⁰⁶¹⁻⁹⁰³⁸ x2 RF and LO SMA Cable (PNA to N5260A, rear)

¹²⁵⁰⁻²⁶⁰⁴ x4 SMA Right Angle Adapter (not required, use only if needed with 8121-1221 cables)

Without external synthesizers (Figure 1a), the RF and LO signals needed for the frequency up-conversion in the WG test head modules are provided via the PNA rear panel. This configuration may be economical, but it is not suitable for higher frequencies because of the higher harmonic multipliers needed for both the RF and LO signals.

With external synthesizers (Figure 1b), the RF and LO signals are supplied by the two PSG signal generators, each with Option 520 (20 GHz).

In both cases, the signals are up-converted and down-converted in the WG test heads and then passed onto the PNA receiver for data processing and display. When external synthesizers are added, the following cables are also needed¹:

- 5 x BNC (2 for 10 MHz connections and 3 for Trigger connections)
- 2 x 3.5mm (for RF and LO connections)
- 1 x GPIB (for connection between external synthesizers)
- 1 x GPIB-to-USB converter, Agilent 82357A (for connection between the PNA and external synthesizer)

Banded millimeter-wave solutions are configured using WG millimeter-wave test head modules from Oleson Microwave Laboratory (OML). Two series of WG test head modules are available from OML; they are referred to as "VNA1" and "VNA2."

- OML "VNA2" waveguide test head modules are compatible with the PNA series (E836xB and E8361A, each with Options 014, 080, 081, UNL, and H11). OML "VNA2" waveguide test head modules that are currently used in 8510 systems must be upgraded before they can be used with the PNA series. Please contact OML, Inc. for details.
- OML "VNA1" waveguide modules can often be found with 8510 systems, but are not compatible with the PNA series unless they are upgraded to "VNA2" modules. Please contact OML, Inc. for details of upgrade, or visit OML, Inc. at www.omlinc.com.

Band	Frequency range of operation	Agilent part number	OML model number
WR-15	50 – 75 GHz	N5260AW15	V15VNA2-T/R
WR-12	60 – 90 GHz	N5260AW12	V12VNA2-T/R
WR-10	75 – 110 GHz	N5260AW10	V10VNA2-T/R
WR-08	90 – 140 GHz	N5260AW08	V08VNA2-T/R
WR-06	110 – 170 GHz	N5260AW06	V06VNA2-T/R
WR-05	140 – 220 GHz	N5260AW05	V05VNA2-T/R
WR-04	170 – 260 GHz	_	V04VNA2-T/R
WR-03	220 – 325 GHz	N5260AW03	V03VNA2-T/R

Table 2. Available OML "VNA2-T/R" test heads with Agilent part numbers and OML model numbers.

^{1.} Cables are purchased separately.

OML VNA2 waveguide test head modules are available in transmission/reflection (T/R) and transmission (T) configurations. Each Agilent part number, N5260AWxx, includes a pair of T/R test head modules and the respective WG calibration kit. Figures 2 and 3 show the simplified block diagrams of an OML VNA2 T/R test head module and a T test head module, respectively. Other combinations of test head modules may be available from Agilent Technologies; as an example, one T/R and one T modules. Please contact your local Agilent Technologies representative for more detail.




Figure 2. Simplified block diagram of an OML T/R test head module.





Figure 3. Simplified block diagram of an OML T test head module.

Different combination of test head modules covering the same frequency range can be used together, but will result in different available parameters. Table 3 shows details of the possible combinations. A full "S-parameter" test set requires two T/R modules. One T/R module and one T module will result in a "T/R" test set where only one transmission measurement and one reflection measurement are possible.

	Port 1	Port 2	Available Parameters	Comments
Combination #1 (Figure 4a)	T/R module	T/R module	S11, S21, S12, S22	Both ports 1 and 2 can supply stimulus to DUT
Combination #2 (Figure 4b)	T/R module	T module	S11, S21	Only port 1 can supply stimulus to DUT

If S12 and S22 are needed for combination #2, two approaches are possible:

- 1. Reverse the DUT to measure the reverse parameters.
- Reconfigure the test head modules by placing the T/R module on port 2 and the T module on port 1. This approach requires a calibration before measurements can be made.





(b)

Figure 4. Two combinations of test head modules: (a) Two T/R modules, and (b) one T/R module (left) and one T module.

System Operation

This section describes how to operate the banded millimeter-wave system. System operation includes creating a configuration for each set of millimeter-wave modules, calibrating the system, and taking measurements.

Figures 5 and 6 illustrate the front and rear panel connections of the system. Rear panel connections are slightly different if external synthesizers are used (Figure 6b). For details on system installation, please refer to the N5250A Network Analyzer Systems Installation Guide, part number N5250-90001.




Figure 5. Front panel connections of the N5260A millimeter-wave controller to the waveguide test head modules.




Figure 6. Rear panel connections: (a) without external synthesizers, and (b) with two PSGs as external synthesizers. Connection between the PNA and a PSG must be done via USB/GPIB Interface (Agilent 82357A), and PNA *Trig OUT* must go to *Trig IN* of RF synthesizer.

System setup procedure has been greatly simplified due to extensive enhancements made to the PNA firmware. The following steps show how to create a configuration for each set of millimeter-wave modules. For multiple frequency bands, one configuration is needed for each band.

Configuring millimeter-wave modules:

Before proceeding to the front panel of the PNA, please make sure the rear panel connection of the system is completed as illustrated in Figure 6a, and the N5260A millimeter-wave controller has been turned on.

- 1. System > Configure > Millimeter Module Config..., this brings up display (a) as shown in Figure 7.
- 2. Click on *Module Config*, this brings up display (b).
- Click on *New*, this brings up display (c), and enter the name of configuration. It is best for the name to be descriptive and representative of the frequency band. (The example shows "60 to 90 GHz".)
- 4. Click OK. This brings up display (d). Enter values of the frequency range and the values of the multipliers, both RF and LO. Multiplier values can be obtained either from the labels on the test head modules, or from Table 4 below. Click Save when done.

Table 4. RF and LO harmonic multipliers of each frequency range.

				LO frequency	
	Frequency range	RF frequency	RF harmonic	range \pm IF	LO harmonic
Band	of operation (GHz)	range (GHz)	multiplier	offset (GHz)	multiplier
WR-15	50 – 75	12.5 to 18.8	N = 4	10.0 to 15.0	M = 5
WR-12	60 - 90	10.0 to 15.0	N = 6	12.0 to 18.0	M = 5
WR-10	75 – 110	12.5 to 18.4	N = 6	9.3 to 13.8	M = 8
WR-08	90 - 140	7.5 to 11.7	N = 12	11.2 to 17.5	M = 8
WR-06	110 – 170	9.1 to 14.2	N = 12	11.0 to 17.0	M = 10
WR-05	140 - 220	11.6 to 18.4	N = 12	14.7 to 18.1	M = 12
WR-04	170 – 260	8.5 to 13.0	N = 20	12.1 to 18.6	M = 14
WR-03	220 – 325	12.2 to 18.1	N = 18	12.2 to 18.1	M = 18

5. To apply a configuration, highlight the configuration, and then click on Activate Selected Config. This brings up display (e), click OK and the PNA will exit and restart with the new configuration, as shown in Figure 8. This step may take a minute.




Figure 7. Steps necessary to create a millimeter-wave module configuration. The example shows a frequency band of 60 to 90 GHz.




Figure 8. PNA operating in newly created millimeter-wave band configuration.

Configuring external synthesizers:

External synthesizers can be added to any banded millimeter-wave configuration at anytime. Before proceeding to the PNA front panel,


- · make sure the rear panel connection of the system is completed as illustrated in Figure 6b
- turn on the N5260A millimeter-wave controller
- turn on both external synthesizers and set the GPIB address of each unit via its front panel as illustrated in Figure 6b:

Utility > GPIB/RS-232 LAN > GPIB address

Enter **19** (for the RF unit) and **18** (for the LO unit) Press softkey *Enter*

Proceed to the PNA front panel to configure the external synthesizers.

- 1. System > Configure > External Source Config..., this brings up display (a) as shown in Figure 9.
- 2. Click on *Add*, this brings up display (b). Enter "Source Name" and then use the drop-down menu to select the "Source Type" of "AGPSG" (only Agilent PSG Series are supported, please see **Operational Notes** for details). Click *OK*. (The example shows the "Source Name" as "PSG RF 19" to indicate that the synthesizer to be used is the PSG series, the unit is intended for the RF signal, and the GPIB address is 19.)
- This brings up display (c). With the source name "PSG RF 19" highlighted, click on Hardware List (BNC) and then update the "GPIB Address" to make sure it is in agreement with the setup (the address is 19).
- 4. Click on *Add* (this time to add the LO source). This brings up display (d). Enter "Source Name" and then use the drop-down menu to select the "Source Type" of "AGPSG." Click *OK*. (The example shows the "Source Name" as "PSG LO 18" to indicate that the synthesizer to be used is the PSG series, the unit is intended for the LO signal, and the GPIB address is 18.)
- 5. This brings up display (e). With the source name "PSG LO 18" highlighted. Click on *Hardware List (BNC)* and then update the "GPIB Address" to make sure it is in agreement with the setup (this time, the address is 18). Click *OK*. You have now completed configuring the external synthesizers.






Figure 9. Steps necessary to configure and apply external synthesizers.

Now apply the external synthesizers to the active configuration:

- System > Configure > Millimeter Module Config..., this brings up display (f) of Figure 9. (This example shows the "Selected Module" as "220 to 325 GHz".)
- 7. Click on Use External Sources, and then use the drop-down menu to select the "RF" and "LO" under "External Source Select." Click OK when done. (As you can see, all sources you have configured will appear under each drop-down menu. This is why it is important to make the "Source Name" descriptive. Otherwise, it maybe difficult to figure out each one.)

Operational Notes

Power control

Power control is not available when operating at banded millimeter-wave frequencies. Although one appears to be able to vary power under **Channel > Power... > Test Port Power**, in reality, it makes no difference at the waveguide interface because (1) the amplifiers inside the test head modules are designed to operate at saturation (see Figure 2), therefore, increasing the RF Test Port Power in the PNA results in no change at the waveguide interface; (2) the RF and LO outputs from the rear panel of the PNA are coupled off before the splitter or any control mechanism, thus, providing no control for power.

Without external synthesizers, the RF and LO signals are provided by the PNA's rear panel (Option H11). These values vary over a wide range; the typical values are shown in Table 5.

Table 5. Typical values of the RF and LO outputs from the rear panel of the PNA.

Rear Panel LO power (typical)				
1.7 GHz to 20 GHz	–16 to –7 dBm			
Rear panel RF powe	r for E8362B (typical)			
1.7 GHz to 20 GHz	–16 to –5 dBm (at –5 dBm test port power ¹)			
Rear panel RF powe	r for E8363B/E8364B (typical)			
1.7 GHz to 10 GHz	–12 to –2 dBm (at –5 dBm test port power ¹)			
10 GHz to 16 GHz	–8 to 0 dBm (at –5 dBm test port power ¹)			
16 GHz to 20 GHz	—1 to +5 dBm (at –5 dBm test port power ¹)			

With external synthesizers, the PSG sources are remotely controlled by the PNA. The PNA downloads the frequency list to each PSG (E8257D with Option 520) and the output is set to 0 dBm for each frequency point.

How do we know if the heads are driven with sufficient power?

The ALC loops inside the N5260A millimeter-wave controller are in place to guarantee sufficient RF power is available at the test heads to drive them (see Figure 10).




Figure 10. Simplified block diagram of N5260A millimeter-wave controller.

 Test port power has to be at a high enough level such that the "Drop Cal" does not occur. If Drop Cal occurs, then the power out of the rear panel RF connector will drop by about 15 dB.

Power leveling

Power leveling is not available when operating at banded millimeter-wave frequencies. (Please see *Power control* in this document for more information.)

Expected output power

For each test head module shipped, OML ships along a plot of its output power vs. frequency at the waveguide interface. These values vary depending on the frequency band of interest.

IF BW selection

For optimal performance at millimeter-wave frequencies, it is recommended that the IF BW be no wider than 1 kHz, preferably 10 Hz. Otherwise, traces can be noisy.

Resolution of frequency source

Only Agilent PSG sources are supported. Because frequency up-conversions done in the test heads require high harmonic multipliers (higher multipliers for higher frequency bands, see Table 4 for details), it is necessary for external synthesizers to have precision to sub-Hz resolution level. If 1-Hz resolution sources are used, errors can propagate resulting in sizable frequency errors.

Frequency resolution of the PSG Series (CW) is 0.001 Hz. PNA 1st IF = 8.333333... MHz IF = N*rf +/- M*LO

Example:

RF = 110 GHz (measurement frequency of WR-10) N = 6 (from Table 4) rf = RF / N = 110 GHz / 6 rf = 18.333333333... GHz (frequency of external RF source) M*L0 = IF + N*rf M*L0 = 8.333333... MHz + 110 GHz = 110008333333.333... Hz M = 8 (from Table 4) L0 = 110008333333 Hz / 8 L0 = 13751041666.625 Hz (frequency of external LO source)

As you can see, due to the unique value of the PNA 1st IF, the values needed for the external RF and LO synthesizers are most likely never to be whole numbers. Therefore, it is necessary for external synthesizers to have sub-Hz resolution in order to yield an accurate PNA 1st IF.

Multiple channels

Using multiple channels is not supported when operating in external synthesizer configuration. This is primarily because when switching from one channel to the next, the PNA has to download all the necessary information to the PSGs before starting a sweep. Timing differences between channel switching (within the PNA) and signals within the trigger chain (outside the PNA) could result in erroneous data collection for the trace being swept.

System Calibration (error-correction)

Choosing the right calibration technique

Applicable calibration techniques depend on the system (hardware) configuration. Table 6 shows the available calibration techniques for two possible system configurations: one with two T/R modules, and the second with one T/R module and one T module. Depending on the technique chosen, the calibration interface on the PNA may be different.

Table 6. Combination of test head modules and applicable calibration techniques.

		System conf	Calibration interface			
		Configuration #1 ¹	Configu	iration #2 ²		
	(5	Two T/R modules S-parameter test set)	(transmiss	e and one T module ion/reflection test set)	SmartCal (guided calibration)	Unguided calibration
OPEN Response	1	S11 OR S22	1	S11		1
SHORT Response	1	S11 OR S22	1	\$11		1
THRU Response	1	S21 OR S12	1	S21		1
1-Port Reflection	1	S11 OR S22	1	S11	1	1
Full SOLT 2-Port	1	S11, S21, S12, S22		•	✓	1
Full TRL 2-Port	1	S11, S21, S12, S22	-		1	1

1. See Figure 4a.

2. See Figure 4b.

Each N5260AWxx includes a pair of T/R test head modules (configuration #1) and the respective WG calibration kit. With this, the setup would allow for measurements of S11, S21, S12 and S22. Plus, full 2-port calibration is possible with SOLT, and TRL.

Note

Setting System Z₀ to 1- Ω : When performing *Unguided* calibration with waveguide interface, the user must manually set the System Z₀ to 1- Ω to match the waveguide kit. This is because *Unguided* calibration uses System Z₀ during calibration computation. Whereas, SmartCal uses the Z₀ defined by the connector definition and is applied automatically during calibration.

System > Configure > System Z0

Enter a value of 1 for waveguide, then click OK.

With configuration #2, although the setup only allows for measurements of S11 and S21, the user can perform either 1-port calibration for S11, or thru response calibration (normalization) for S21, or *append* the latter calibration to the previous thus creating one calset for both traces within one measurement channel¹. Here are the steps to append two calibrations:

- With trace S11 active, perform 1-port calibration using SmartCal, then click Save As User CalSet to finish
- With trace S21 active (in the same channel), while the 1-port calibration is selected, perform response calibration (or normalization) using Unguided Cal, then click *Save As User CalSet* to finish but make sure the selected calset is the same one as the currently active 1-port cal click *Save* to complete
- As the final step, the Calibration Wizard will then ask if appending this calibration to the existing one is desired, as shown in Figure 11, simply click *OK* to confirm. Once finished, the same calset will cover both calibrations, 1-port for S11 and thru response for S21. This way, when you click on S11, the status bar (located on the bottom of the display) shows C 1-Port, and when you click on S21, it shows C Response.

Confirm apper	nd calset.		×
You have cho Confirm?	osen to append th	is calibration to	calset: CalSet_1.
	OK DK	Cancel]

Figure 11. Appending a calibration to an existing CalSet.

Each WG calibration kit from OML comes with the following standards and a floppy disk loaded with the calibration definition file formatted for the PNA:

- Precision Terminations, Fixed Loads, qty 2
- Precision (flush) Shorts, qty 2
- Precision Insert A (line1), Null Shim
- Precision Insert B (line2), ¼ Offset Shim
- Adjustable Load
- Precision Section

Loading and checking calibration definition file

Each PNA is shipped with calibration definition files from Agilent calibration kits. For non-Agilent calibration kits such as the WG calibration kits from OML, the user must first load the file and then check to make sure all the items are in order. (The user can also choose to create his own WG cal kit file if desired. Refer to Appendix A for details.)

Calibration > Advanced Modify Cal Kit ... > Import Kit ...

Use dropdown menu to select "3 ½ Floppy (A:)" Highlight the file to be imported, and click **Open**

Once the file is loaded, it will appear on the list of *Installed Kits* as shown in Figure 12. Highlight the file of interest, (The example shows *V05_OML*.) and click Edit Kit ... in order to view the kit definition. On this page, you can see all the standards (and combinations) as defined for this particular WG calibration kit.

Edit PNA Cal Kits Open Save As Restore Defaults	Edit Kit Identification Kit Number 37 Kit Description OML WR-05 (6 Band) Universal Calibration Kit Connectors Description: WR-05 Waveguide Add or Edit Family: Change Family
Interest Kit. Save As Inter New Finit to File. Inter New Inter New File New Finit to File. Inter New Inter New Inter New Inter New Finit to File. Inter New Inten	ID Standard Description 10 Shott-Null Skim G-Band Shott (75 +05:65) 2 Shott-Null Skim G-Band Shott (75 +05:65) 3 Shott-Null Skim G-Band Shott (75 +05:65) 5 Load VI Offest Sim G-Band Shott (75 +05:65) 6 Band TA Que to Not (75 +05:65) Load VA Offest 6 Band TA Que to Not (75 +05:65) Load 1:00" 8 Load VA Offest G-Band TA Que to Not (75 +05:65) Load 1:00" 9 Load Shott-Null Skim G-Band TA Que to Not (75 +05:65) Load 1:00" 10 Load Shott-Null Skim G-Band TA Que to Not (75 +05:65) Load 1:00" 112 Load Shott-Null Skim Connector Image Not (10) Image Not (10) 12 Load Shott-Null Skim Connector family WR G&Wavegude Image Not (10) Image Not (10) 13 Thru-Null Description WR G&Wavegude Image Not (10) Image Not (10) Image Not (10) 14 Thru-Null Description WR G&Wavegude Image Not (10) Image Not (10) Imag

Figure 12. Loading the calibration definition file and checking on the connector definition.

The examples in Figure 14 show the standards and class assignments for both TRL and SOLT. These are defined as shown in Table 7. Figure 15 shows examples of the details of each standard definition.

	Class Assignments	Class Label	Selected Standards
TRL	TRL THRU	THRU	Thru + Null Shim
	TRL REFLECT	REFLECT	Flush Short
	TRL LINE/MATCH	LINE	Thru + 1⁄4 Offset Shim
SOLT	S11A, S22A	OPENS	Short + Null Shim
	S11B, S22B	SHORTS	Short + 1⁄4 Offset Shim
	S11C, S22C	LOADS	Flush Fixed Load
	FWD TRANS	THRU	Thru

Table 7. Standards and class assignments of TRL and SOLT calibrations.

Thru-reflect-line (TRL) calibration:

Setting test port reference plane

Two selections are available for setting the test port reference plane; *Thru Standard* or *Reflect Standard* (see Figure 13). If a flush short is used for the reflect standard, then select the "Reflect Standard" for the "Test port Reference Plane". A flush short provides a much more accurate phase reference than a thru standard.

Short-open-load-thru (SOLT) calibration:

Adjustable load

Although an adjustable load is shipped in each WG calibration kit from OML, this standard is not ideal for millimeter-wave frequencies because mechanical tolerances make obtaining repeatable results difficult. Plus, adjustable loads are best if step sizes can be varied from large to small as one tries to trace out circles on a smith chart. Given the frequency ranges of these calibration kits, it would be very challenging to produce repeatable results. Therefore, fixed loads are used for the load standards for SOLT.

Offset load

Offset load is available in the PNA with firmware 6.0. Using offset load can result in a more accurate calibration than with broadband load, but it does require extra connections. A typical offset load requires two known offsets along with a load element. As such, one connection is made using the *first offset with the load*, and the other one is made using the *second offset with the load*. Figure 13 shows a definition of an offset load.

Loads			×
Identification	3 Label	Offset Load	_
Standard ID			_
Load Description	WR-03 Waveguid	e load	
- Frequency Range -		Connector	
Min 173580	MHz		
Max 347159	MHz	WR-03 Waveguide	<u> </u>
-Load Type	Arbitrary	Complex Impedance	
C Fixed Load	C Impedance	Real 50	
C Sliding Load	Offset Load	lmag 0	
Delay Characteristic	8		
Delay 0	pSec	Loss ()	Gohms/s
Z0 1	ohms		
- Diffset Load Definitio	n		
First Offse	t Standard Thru+N	lull Shim 💌	
Second Offse	t Standard Thru+1	/4 Offset Shim 💌	
	d Standard Load		
Clear	ОК	Cancel Apply	Help

Figure 13. Example of an offset load definition.




Figure 14. Examples of TRL and SOLT class assignments.

	Shorts
1	Identification Standard ID 1 Label
dit Kit	Short Description G-Band Flush Short (S-05)
Identification Kit Number 37 Kit Name 100510011	Frequency Range Connector
Kit Description OML W/R-05 (G Band) Universal Caliburon Kit Connectors Class Assignments	Min 115696 MHz WR-05 Waveguide
Description: WR-05 Waveguide dd or Edit Family. Edit	Short Characteristics L0 H(e-12) L2 0 H(e-33)/Hz^2 L0
Change Family D Standard Description	L1 0 H(e-24)/Hz L3 0 H(e-42)/Hz^3 Delay Characteristics
Short G-Band Short [S-05] Short+Null Shim G-Band Short [S-05 +0S-05] Short + 0.100" Null S	Z0 I Colar Colors
ShortHail Short - Constant -	20 1 ohm
6 Load+Null Shim G-Band Fixed Load [T-05 + D5-00]	Shorts
9 Load Sliding G Band Sliding Load [AL-05] 10 Load Sliding+Null Shim G-Band Sliding Load [AL-05 + OS-05] Sliding Load +	Standard ID Label Short-NULSIAM
12 Load Sliding+1/4 Off G-Band 1/4 Offset Sliding Load [AL-05 + 051/4-05] 13 Thru G-Band Thru	Standard ID Label ShottAulliShm Shott Description G-Band Shott [S-05 + 0S-05] Short + 0.100" Null St
4 Thru+Null Shim G-Band Thru (OS-05) Null Shim 6 Thru+1/4 Offset Shim G-Band 1/4 Offset Thru (OS1/4-05) 1/4 wave Offs	Frequency Range Connector
Add., Edit., Delete Delete All	Min 115696 MHz WR-05 Waveguide
	Max 231392 MHz
OK Cancel Help	Short Characteristics
	L0 0 H(e-12) L2 0 H(e-33)/Hz ⁻²
	L1 0 H(e-24)/Hz L3 0 H(e-42)/Hz ^o 3
	Velay 8,475 pSec Loss 0 Gohms/s
	20 1 ohms
	Clear OK Cancel Apply Help
	Clear UK Cancel Apply Help

Figure 15. Examples of standards definitions. Key parameters to check included Min and Max of Frequency Range, as well as Delay and Z_0 .

Configuration #1: Two T/R Modules (S-parameter test set)

With a full 2-port calibration, this configuration allows one to measure all four S-parameters (S11, S21, S12, S22). Full 2-port calibrations are available in either TRL or SOLT. These calibrations are available under *SmartCal* (guided) or *Unguided* calibrations on the PNA under *Calibration Wizard*.

Note

TRL calibration

TRL only requires four steps. It requires one reflect standard for each test port, one thru and one line (a section with a defined length).

- The reference must be established by the SHORT (reflect) standard.
- The impedance selected must be LINE Z₀.

These are the default settings when using *SmartCal*. When using *Unguided* calibration, the user must check to confirm these settings, as well as setting system Z_0 to 1- Ω (**System** > **Configure** > **System** Z_0).

SOLT calibration

SOLT requires seven steps, three more steps than TRL! It requires three standards for each test port, and one thru.

Unknown Thru is available, but only with SOLT. Since SOLT takes more steps and is less accurate than TRL, the only time you should consider performing SOLT calibration is to benefit from an Unknown Thru. One such situation may be where the test heads are restricted from movement (such as bolted down to avoid cable movements); in such a case, an Unknown Thru would be very useful as it would eliminate the need to move them. Another example is when the test port cables are at 90 degrees, preventing a straight thru from being connected. When SOLT is needed, using offset load (instead of fixed load) will result in a more accurate calibration. This may require you to modify a cal kit definition as well as performing more connections during the actual calibration.

Example #1:WR-12, 60 to 90 GHzEquipment:E8364B with Options 014, UNL, 080, 081, H11N5260A test set controllerWR-12 (60 to 90 GHz) T/R test heads modulesSetup:IF BW: 100 HzNumber of Points: 201Calibration:Channel 1: SmartCal, 2-port, Flush Thru, TRL

For 2-port calibrations in waveguide, SmartCal defaults to TRL with Flush Thru. Figure 16 shows that the system dynamic range is better than 90 dB and trace noise is better than ± 0.10 dB.




Figure 16. WR-12, 60 to 90 GHz, Flush Thru TRL calibration results.

Configuration #2: One T/R module and one T module (T/R test set)

This configuration allows you to measure only two S-parameters (S11 and S21). For simultaneous corrected measurements of both parameters, one can perform a 1-port calibration for trace S11 and then append the thru response calibration (or normalization) performed for trace S21; thus, resulting in one calset for both traces.

1-port calibrations are available under SmartCal (guided) or unguided calibrations, while Thru Response calibrations (or normalization) are only available under unguided calibrations (see Table 6).

Example #2:	WR-05, 140 to 220 GHz
Equipment:	E8364B with Options 014, UNL, 080, 081, H11
	N5260A test set controller
	WR-05 (140 to 220 GHz) T/R and T test head modules
	E8257D with Options 520 and UNR (Qty of 2)
Setup:	IF BW: 10 Hz
	Number of Points: 201

For the frequency range of 140 to 220 GHz, Figure 17 compares dynamic range and Figure 18 compares trace noise (for S21). In both cases, using Agilent PSG Series as external synthesizers to improve performance. For dynamic range, the improvement was up to 10 dB on average; for trace noise, it went from less than 0.05 dB around 220 GHz to practically non-existence!




Figure 17. WR-05, 140 to 220 GHz, T/R and T modules. Dynamic range comparison between measurements made with external synthesizers and without.






Figure 18. WR-05, 140 to 220 GHz, trace noise comparison between measurements made with external synthesizers (right) and without (left). Both plots have the same scale, 0.10 dB per division.

Example #3:	WR-03, 220 to 325 GHz
Equipment:	E8364B with Options 014, UNL, 080, 081, H11
	N5260A test set controller
	WR-03 (220 to 325 GHz) T/R and T test head modules
	E8257D with Options 520 and UNR (Qty of 2)
Setup:	IF BW: 10 Hz
	Number of Points: 201

For the frequency range of 220 to 325 GHz, Figure 19 compares dynamic range and Figure 20 compares trace noise (for S21). Similar to the previous example (WR-05), using Agilent PSG Series as external synthesizers do improve performance in both cases. However, the improvement for this higher frequency range is much more significant. For dynamic range, the improvement was up to 20 dB on average; for trace noise, it went from less than 0.20 dB around 300 GHz to less than 0.02 dB – that's an improvement of at least ten times!








Figure 20. WR-03, 220 to 325 GHz, trace noise comparison between measurements made with external synthesizers (right) and without (left). Both plots have the same scale, 0.20 dB per division.

Application Examples

Example #1: Antenna measurements

Below are two examples of antenna configurations. For more details, please refer to the *Agilent Antenna Test – Selection Guide*, literature number 5968-6759E or visit our web site at **www.agilent.com/find/antenna**




Figure 21. PNA banded millimeter-wave solution applied to *indoor* antenna measurements. The transmit side (left) uses an OML T/R module, and the receive side (right) uses the OML Dual T module. Dual T modules are ideal for measuring both vertical and horizontal polarities of the antenna.




Figure 22. PNA banded millimeter-wave solution applied to *outdoor* antenna measurements. The transmit side (left) uses an OML T/R module, and the receive side (right) uses the OML Dual T module. Dual T modules are ideal for measuring both vertical and horizontal polarities of the antenna.

Example #2: Pulsed measurements

In a banded millimeter-wave configuration, the pulse modulator can be applied to the RF signal coming from either the front of the N5260A millimeter-wave controller or the rear of the PNA. In either case, a dual output pulse generator (Agilent 81110A) will be needed to provide a pulse drive to the modulator as well as the B gate of the PNA. Measurements of point-in-pulse and pulse profiling have been performed for V-band (50 to 75 GHz) and W-band (75 to 110 GHz).

Figure 23 shows the pulse modulator (Agilent Z5623AH81) being placed between the front of the N5260A millimeter-wave controller and the test head module. Since this pulse modulator is unidirectional, this is connected to the port 1 path only. In this configuration, the modulator takes the CW signal coming out of the front of the N5260A and provides a pulsed-RF signal going into the test head module of port 1 and it will in turn deliver a pulsed-RF stimulus to the device-under-test (DUT).




Figure 23. Pulsed the RF signal coming from the front of the N5260A millimeter-wave controller.

Figure 24 shows the pulse modulator being placed between the PNA and the N5260A millimeter-wave controller. In this configuration, the modulator takes the CW signal coming out of the rear panel of the PNA and provides a pulsed-RF signal going into the N5260A millimeter-wave controller. Although the pulse modulator is unidirectional, this configuration will provide a pulsed-RF signal to both ports 1 and 2 because any input into the millimeter-wave controller will be delivered to both ports 1 and 2 due to the presence of the switch inside the controller. Figure 25 compares measurement results of pulse profiling at 100 GHz, and there is no difference whether the signal is pulsed in the front or the rear.




Figure 24. Pulsed the RF signal coming from the rear of the PNA.




Figure 25. Results of pulse profiling measurements at 100 GHz by pulsing the RF signal from the front of the N5260A as well as from the rear of the PNA.

Example #3: Materials measurements

Figure 26 shows one example configuration of materials measurement in W-band, 75 to 110 GHz. This application requires two W-band waveguide horns and alignment of the test heads in order to transmit and receive test signals. In addition, using the measurement software shown requires two T/R test heads (an S-parameter setup). For more details, please visit our web site at **www.agilent.com/find/materials**




Figure 26. Using materials measurement software and Free Space Calibration technique to perform materials measurements in millimeter-wave. Insert shows measurement software interface.

Appendix A: Creating Your Own Waveguide (WG) Calibration Kit Definition

- 1. Calibration > Advanced Modify Cal Kit > Insert New
- 2. Enter "Kit Name" and "Kit Description" and then click on "Add or Edit" to enter connector information (Figure 27)

Edit Kit × Identification Kit Number Z Kit Name My Dwn WG Kit Kit	Enter "Kit Name" and "Kit Description." ("Kit Name" will appear on the list of "installed kits" next time you click
Connectors Description: Add or Edit Family: Family Change Family	on "Advanced Modify Cal Kit".)
D Standard Description	
Add Edit Delete Delete All	Click on "Add or Edit" to enter connector information

Figure 27. Enter calibration kit name.

3. Enter "Connector Family," "Frequency Range" (Min. frequency = Cutoff frequency), 1 for "Z0;" select "No Gender," and "WAVEGUIDE" (Figure 28)




Figure 28. Enter connector (WG) description.

4. Click **OK**. This returns to the "Edit Kit" page (name of the page is shown on the upperleft corner of the dialog box). Click "Add" to start adding standards (Figure 29).

	Edit Kit Xi Identification Kit Number 3 Kit Name My Own WG Kit Kit Description Creating my own WG cal kit
Clicking OK (on the "Add or Edit Connector" page) returns to the "Edit Kit" page and the connector information appears.	Consectors Class Assignments Class Assignments SOLT Edit SOLT Edit
	ID Standard Description
Click "Add" to start adding standards	Add Edit Delete Delete All OK Cancel Help

Figure 29. Completed connector description, and start adding standards.


5. For waveguide, the best calibration technique may be thru-reflect-line (TRL). There is almost no reason to use SOLT since TRL is more accurate and SOLT requires more steps. Thus, for TRL or its variation such as line-reflect-line (LRL), you may want to add the following standards:

TRL	THRU	Thru (0 delay)
	REFLECT	Flush Short (0 delay)
	LINE	Thru with offset (a known delay)
LRL	LINE 1	Thru with offset 1 (a known delay)
	REFLECT	Flush Short (0 delay)
	LINE 2	Thru with offset 2 (a different known delay)

However, if SOLT is needed, offset load can be used in place of fixed load. Using offset load will result in a more accurate calibration than with broadband load, and below are the standards needed:

SOLT	Short	Flush Short
	Open	Flush Short and Offset
	Offset Load	Load with Offset 1 (a known delay)
		Load with Offset 2 (a different known delay)
	Thru	Thru (0 delay)

Select a standard by clicking on it, the example shows SHORT (Figure 30, left). This brings up the "Shorts" page. The key parameters to note are the frequency range, the delay value if applicable, and the value of Z0 (Figure 30, right). Click OK when done, and this returns to the "Add Standard" page. Repeat this step until all standards have been added. Figure 31 shows adding a THRU standard.






	Thru/Line/Adapter 🗵
1	Identification Standard ID 2 Label THRU Thru Description Insertable thru standard
	Frequency Range Min 7000 Max 18000
	Delay Characteristics pSec Loss 0 Gohms/s Z0 1 ohms 0
Add Standard	Connectors
Select the type of standard to be adde	Pot WG X-band Pot WG X-band
C OPEN	
C SHORT	
C LOAD	Clear QK Cancel Apply Help
• THRU	
C DATA BASED STANDARI	Cancel Help

Figure 31. Adding a THRU standard.

Once you have added at least one fixed load and two offsets of different length, you can then define an offset load. Figure 32 shows the "Loads" page, and the default of this page is "Fixed Load." When "Offset Load" is selected, the "Offset Load Definition" area becomes active and you must use the dropdown menu to select each standard element. The "Delay Characteristics" area then becomes inactive because this is applicable for "Fixed Load."





6. After all standards have been added, click OK on the "Add Standard" page to return to the "Edit Kit" page. All the standards that have been added should appear in the table (Figure 33, left). Now, under "Class Assignments", use the drop down menu to select "TRL" (or "SOLT") and then click on Edit. This brings up the "Class Assignments" page, Figure 33 (right) shows "Class Assignments" for TRL. For each "Class" selected, highlight the standard on the left, and then click on the ">>" button in the middle, to move the standard to the right under "Selected Standards."




Figure 33. Assigning standards to class TRL.

Edit Kit Identification Kit Number 2 Kit Name My Dwn WG Kit Kit Description Connectors Description WG X-band Add or Edit Panily. WG X-band Change Family.	Class Assignments
ID Standard Description 1 SHORT WG X-band short 3 LOAD WG X-band load	
3 LUAD Wa X-band Ioad 2 Diffeet LOAD WG X-band Ioad 2 THRU 4 THRU 1/4 Offset Insertable thru standard Add Edk Delete	My Oum WGE Kit: Modify SOLT Collibration Class Assignments Calibration Kit Class C stata C STIA C STIB C STIB C STIC Link FWD TRANS, PWD MATCH, Help Expanded Calibration (applies to reflection classes) Mathematical tradeble S STIC LOAD
0.6	Unselected Standards Unselected Standards Unselected Standards Selected Standards Unselected Standards Selected Standards

Figure 34. Assigning standards to class SOLT (with Offset Load).

7. Click **OK** when done to return to the "Edit Kit" page, and then click **OK** again to return to the "Edit PNA Cal Kits" page. At this point, you should be able to see the kit that you just created under the list of "Installed Kits" (Figure 35).

0	pen Save	As Restore Defaults
	Import K	it Save As Insert New Print to File
ID	Kit Name	Description
1	85052B	3.5 mm with sliding load
2	85052D	3.5 mm Calibration Kit
3	My Own WG Kit	Creating my own WG cal kit
4	85033D/E	3.5 mm Calibration Kit
5	85052C	3.5 mm SOLT/TRL Calibration Kit
6	85056A	2.4 mm with sliding load
7	85056D	2.4 mm Calibration Kit
8	85056K	2.4 mm/2.92 mm with Broadband Load
9	85056K01	2.4 mm/2.92 mm with Sliding Load
10	85058B Databa	
11	85058E Databa	
12	85058BP Polyno.	
13		1.85 mm Economy (Reduced Accuracy)
14	85059A Data-ba.	
15	85059AP Polyno.	
16	85038A	7-16 Calibration Kit
17	85050B	APC 7 with sliding load
		dit Kit Delete ^ v

Figure 35. Calibration kit file created, done!

8. Congratulations! You are now ready to calibrate in waveguide.

Appendix B: Performing Calibrations

I. SmartCal, 2-port calibration

- 1. Calibration > Calibration Wizard ...
- 2. Select *SmartCal (GUIDED Calibration)*, then click *Next*> (Figure 36, top)
- 3. Select Cal Type, click Next> (Figure 36, middle)
- 4. Use dropdown menu and then the scroll bar to select the DUT connectors (Figure 36, bottom). Also, use dropdown menu to select the available calibration kit based on the selected DUT connectors. Notice, the default *Cal Method* is *2-Port*, *Defined Thru*, TRL. Plus, if "Modify Cal" is not selected, then steps shown in Figure 37 will be skipped. Click *Next*>

Calibration Wizard: Begin Calibr © [SmatCal (GUIDED Calibration): C UNGUIDED Calibration (Respon C Use Electronic Calibration (ECal	Use Mechanical Standards nse, 1-port, 2-port): Use Mechanical Standards Select calibration preferences.
	Save Preferences. Don't show this page again.
Select Guided D	Albration Type (Mechanical Standards)
Cal Type Selecti 2 Port Cal 1 Port Cal	
	Kack Next> Cancel Help
Use dropdown menu to select DUT connectors.	Guided Calibration: Select DUT Connectors and Cal Kits Connectors Cal Kits DUT Port 1 WR-03 Waveguide WR-03 Waveguide V03_AL_03
C Selecting "Modify Cal" will show steps in Figure 36.	Modify Cal OPTINNAL Solve [Modify Cal] to change the Cal Method and/or standards used for the selected cal kits. (Back Next> Cancel Hep

Figure 36. Select SmartCal and DUT connectors.

5. Having selected "Modify Cal" allows you to change the *Cal Type*. Figure 37 (top) shows *Cal Type: TRL*, you can click *Mod Stds*, and then use the dropdown menu on the right to select a different cal type. Figure 37 (middle) shows the selection of *SOLT*. Clicking *OK* returns you to the previous screen, and this time it shows the *Cal Type: SOLT* (Figure 37, bottom).

Modify Cal	X
Thru Calibration Options (Cal Type: TRL)	
Thru Cal Method Thru #1 1-2 Defined Thru Mod Stds	
Defined Thru	
Flush Thru Unknown Thru Adapter Removal	
	· · · · · · · · · · · · · · · · · · ·
	< Back Next> Cancel Help
View/Modify Properties of Cal for P	
Select 2-Port calibration type	Advanced
Defined Thru	Calibration type TBL View/Modify
Defined Thru	TRUMPING TRUE
	SOLT Select View/Modify to preview the standards to be measured.
a second s	sector rewriteday to provide all alles to be included.
	OK Cancel Help
Modify Cal	X
	Iptions (Cal Type: SOLT)
	Thru Cal Method
Thru #1 1-2	
	< Back Next> Cancel Help

Figure 37. Changing Cal Type.

6. The calibration has now begun. As shown on the upper-left corner of each screenshot (Figure 38), the 2-port, Flush Thru, TRL calibration includes four steps. The example shown here is based on using an OML cal kit.

Step 1 of 4: Port 1, Short Step 2 of 4: Port 2, Short Step 3 of 4: Port 1, THRU + NULL Shim, Port 2 Step 4 of 4: Port 1, THRU + 1/4 Offset Shim, Port 2

$\langle \rangle$		
Guided Calibration Step 1 of 4	PORT 2	×
PORT 1 SHO Connect G-BAND FLUSH SHOR		Measure Done
Select [Measure] when connections have been made.		
	< <u>B</u> ack <u>N</u> ext >	Cancel Help
Guided Calibration Step 2 of 4		×
PORT 2 SH		Done
Select [Measure] when connections have been made.	< <u>₿</u> ack <u>N</u> ext>	Cancel Help
Guided Calibration Step 3 of 4		Measure
Connect G-BAND THRU [OS-05] NULL SH Select [Measure] when connections have been made.	IM between port 1 and port 2	Done
	< Back Next >	Cancel Help
Guided Calibration Step 4 of 4		
PORT 1 THRU+1/4 OFFS Connect G-BAND 1/4 OFFSET THRU [0S1/4-0 between port 1 and Select [Measure] when connections have been made.	5] 1/4 WAVE OFFSET NULL SHIM	Done
	KBack Next>	Cancel Help

Figure 38. Steps of the 2-port, Flush Thru, TRL calibration (using an OML cal kit).

7. Congratulations! You have just completed a 2-port, Flush Thru, TRL calibration.

Alternatives:

Using an OML calibration kit, performing an SOLT calibration with Offset Load would require 9 steps:

Step 1 of 9: Port 1, Short + NULL Shim Step 2 of 9: Port 1, Short + ¹/₄ Offset Shim Step 3 of 9: Port 1, THRU + NULL Shim, Load Step 4 of 9: Port 1, THRU + ¹/₄ Offset Shim, Load Step 5 of 9: Port 2, Short + NULL Shim Step 6 of 9: Port 2, Short + ¹/₄ Offset Shim Step 7 of 9: Port 2, THRU + NULL Shim, Load Step 8 of 9: Port 2, THRU + ¹/₄ Offset Shim, Load Step 9 of 9: Port 1, Port 2

Using an OML calibration kit, performing an SOLT calibration with fixed Load would require 7 steps:

Step 1 of 7: Port 1, Short + NULL Shim Step 2 of 7: Port 1, Short + 1/4 Offset Shim Step 3 of 7: Port 1, Load Step 4 of 7: Port 2, Short + NULL Shim Step 5 of 7: Port 2, Short + 1/4 Offset Shim Step 6 of 7: Port 2, Load Step 7 of 7: Port 1, Port 2

II. SmartCal, 1-port calibration

- 1. Calibration > Calibration Wizard ...
- 2. Select SmartCal (GUIDED Calibration), then click Next> (Figure 39, top)
- Select Cal Type. Notice on the right that you can choose either Port 1 or Port 2 as the test port for the 1-port calibration. Then, click Next> (Figure 39, middle)
- 4. Use dropdown menu and then the scroll bar to select the DUT connectors (Figure 39, bottom). Also, use dropdown menu to select the available calibration kit based on the selected DUT connectors. Notice, the *Cal Method* here is simply *1-Port*. Plus, if "Modify Cal" is not selected, then steps shown in Figure 40 will be skipped. Click *Next>*

Calibration Wizard: Begin Calibration
SmartCal (GUIDED Calibration)
UNGUIDED Calibration (Response, 1-port; 2-port): Use Mechanical Standards Select calibration preferences.
C Use Electronic Calibration (ECal) Not sure about preferences? Assistance is available in the online Help.
Save Preferences. Don't show this page again.
<beck next=""> Cancel Hep</beck>
Select Guided Calibration Type (Mechanic 2) X Cal Type Selection 2 Port Cal Port Cal Configuration Select 1st Port Select 1st
Guided Calibration: Select DUT Connectors and Cal Kits
Use dropdown menu to select DUT connectors. Selecting "Modify Cal" will show steps in Figure 39."
< <u>B</u> ack <u>N</u> ext > Cancel Help

Figure 39. Select SmartCal and DUT connectors.

5. Having selected "Modify Cal" allows you to look at the screens shown in Figure 40. However, in the case of 1-port calibrations, you are limited to SOL calibration only. Thus, clicking on "Modify Cal" does not offer you additional selection. Your *Cal Type* remains as *One Port*.

lodify Cal	X	
- Thru Calibration Options (Cal Type: 1-Port) Thru Cal Method		
Port 1 V One Port V Mod Stds		
	· · · · · · · · · · · · · · · · · · ·	
	< <u>Back</u>	
View/Modify Selections of Cal Standa	rds for this Cal	×
Select 1-Port calibration type	Advanced	
One Port	Calibration type One Port View/Modify	
	Select View/Modify to preview the standards to be measured.	
and the second		
	OK Cancel Help	

Figure 40. Viewing *Modify Cal* displays.

6. The calibration has now begun. As shown on the upper-left corner of each screenshot (Figure 41), the 1-port calibration includes three steps. The example shown here is based on using a OML cal kit.

Step 1 of 3: Port 1, Short + Null Shim Step 2 of 3: Port 1, Short + 1/4 Offset Shim Step 3 of 3: Port 1, Load

Guided Calibration Step 1 of 3 PORT 1 PORT 2 I I I I I I I I I I I I I I I I I I I	×
PORT 1 SHORT+NULL SHIM Connect G-BAND SHORT [S-05 +0S-05] SHORT + 0.100" NULL SHIM to port 1	Done
Select [Measure] when connections have been made.	
< Back, Next >	Cancel Help
Guided Calibration Step 2 of 3	×
PORT 1 SHORT+1/4 OFFSET SHIM Connect G-BAND 1/4 OFFSET SHORT (S-05+ 0S1/4-05) SHORT+ 1/4 WAVE NULL OFFSET SHIM to port 1	Done
Select [Measure] when connections have been made.	
< <u>B</u> ack <u>N</u> ext >	Cancel Help
Guided Calibration Step 3 of 3 PORT 1 PORT 2 1 1 0 2	×
PORT 1 LOAD Connect G-BAND FLUSH FIXED LOAD [T-05] to port 1	Measure Done
Select [Measure] when connections have been made.	
≪ <u>B</u> ack <u>N</u> ext⇒	Cancel Help

Figure 41. Steps of the 1-port calibration.

7. Congratulations! You have just completed a 1-port calibration.

Alternative:

Using an OML calibration kit to perform a 1-port SOL calibration with Offset Load would require 4 steps:

Step 1 of 4: Port 1, Short + NULL Shim Step 2 of 4: Port 1, Short + 1/4 Offset Shim Step 3 of 4: Port 1, THRU + NULL Shim, Load Step 4 of 4: Port 1, THRU + 1/4 Offset Shim, Load

III. Unguided Calibration, Thru Response

1. Calibration > Calibration Wizard ...

- 2. Select UNGUIDED Calibration, then click Next> (Figure 42, top)
- 3. For Unguided calibration, the user must select the calibration kit because the default (or the kit last used) is often not what you want. Click on View/Select Cal Kit (Figure 42, middle) and then use the scroll bar to select the calibration kit of choice (Figure 42, bottom). Click OK.

Calibration Wizard: Begin Calibration	×
O SmartCal (GUIDED Calibration): Use Mechanical Standards	
 UNGUIDED Calibration (Response, 1-port, 2-port): Use Mechanical St 	andards Select calibration preferences.
O Use Electronic Calibration (ECal)	Not sure about preferences? Assistance is available in the online Help.
	Save Preferences. Don't show this page again.
< <u>B</u> ack	<u>N</u> ext > Cancel Help
Select Calibration Type for Mechanical Standard	ds 🗵
Cell Type Selection Personse Confi 2 Port Solt 1 Port Solt TRL Response	guration Selected Cal Kit: 850368/E TypeN (75) Calibration Kit Characterization: < (type) View/Select Cal Kit
	Cancel Help
Select Cal Kit	×
Choose class type C SOLT classes TRL classes Edit Class Assignments	ID Kit Name Description 28 Q11644A Q-band Waveguide SOLT/TRL Calibration 29 R11644A R-band Waveguide SOLT/TRL Calibration 30 U11644A U-band Waveguide SOLT/TRL Calibration 31 V11644A V-band Waveguide SOLT/TRL Calibration 32 W11644A V-band Waveguide SOLT/TRL Calibration 33 V10_AL_10_R6 O/fl. WR-10_Cali /R, SjN V10-AL-10 34 V3_AL_03 O/fl. WR-03 (J Band) Universal Calibration
	OK Cancel Help

Figure 42. Select *Unguided* calibration, and calibration kit of choice.

4. This returns to the previous page, and the *Cal Kit* information has been updated (Figure 43, top). Make sure *Response* is highlighted on the left. (If not, click on it once.) Click *Next*> to start the *Response* calibration.

Seler Cal 2 F 1 F TR

Your *Response* calibration selection will be different depending on your active trace. If the active trace is S11, then you will see the standard selection for *Reflection Response*, as those shown in Figure 43 middle. If the active trace is S21, then the standard selection are those for *Transmission Response*, as those shown in Figure 43 bottom.

ct Calibration Type for Mecl	hanical Standards	×	
Type Selection	Response Configuration Gelected Cal Kit: V03_AL_03 OML WR-03 (J Band) Universal Calibration Characterization: < type> View/Select Cal Kit		
	< <u>₿</u> ack <u>N</u> ext> Cancel He	lp	
Port 1 (S Short Cal Kit 34	echanical Standards II] Shot Uffset VM3_AL_03_0ML_WFt-03 (J Band) Universal Response: Select a standard (Back 11000)		Xormalize
Port 2 - F	echanical Standards fort 1 (S21) Isolation Control (Control (Contro) (Contr		I × Show Prompts Normalize
	< <u>Back</u> Mext>	Cancel	Help

Figure 43. Response calibration and associated standard selection for Reflection Response and Transmission Response.

5. Congratulations! You have just completed a Response calibration.

Appendix C: Caring For Waveguide (WG) Interfaces

A clean surface at millimeter-wave is much more important than at lower frequencies because any debris on its surface can potentially be added to the measurement distorting the measurement results.

Caring for WG interfaces is not difficult. Dirt and dust can be removed using the following items:

- Isopropyl Alcohol 99.5%
- Lint-free cloth
- Pressurized air for dust removal

To remove dirt on the surface, simply put a few drops of the Isopropyl Alcohol on the Lint-free cloth and then gently wipe the surface.

To remove dust, simply spray the pressurized air on the surface.

Appendix D: Supplemental Data

As can be seen in Figures 17 through 20, using external synthesizers for higher frequency ranges, such as 140 to 220 GHz (WR-05) and 220 to 325 GHz (WR-03), can improve dynamic range up to 10 dB and 20 dB, respectively, as well as improving trace noise. Below, figures 44 through 46 show that the PSG series used as external synthesizers do not make any difference with or without Option UNX, ultra-low (close-in) phase noise. We chose to focus our comparison in the frequency range of 220 to 325 GHz only because if there is any noticeable difference, it would easily appear at this frequency range than at a lower one. In the comparison, either both PSG units have Option UNX, or they both do not.

In the case of trace noise, both transmission (S21) and reflection (S11) have remained very low regardless of Option UNX. They are less than ± 0.0300 dB in the worst case; above 290 GHz in the case of S21, and above 305 GHz in the case of S11.

Based on these measurement results, we are no longer including Option UNX on the PSG configurations when used as external synthesizers.




Figure 44. S21 trace noise comparison between measurements made with external synthesizers with and without Option UNX, ultra-low (close-in) phase noise.

S21, Dynamic range




Figure 45. S21 dynamic range comparison between measurements made with external synthesizers with and without Option UNX, ultra-low (close-in) phase noise.




Figure 46. S11 trace noise comparison between measurements made with external synthesizers with and without Option UNX, ultra-low (close-in) phase noise.

Web Resources

For additional literature and the latest product information, visit our Web sites:

PNA Series Network Analyzers www.agilent.com/find/pna

Antenna measurements www.agilent.com/find/antenna

PSG Signal Generators www.agilent.com/find/psg

Test and measurement accessories www.agilent.com/find/accessories



www.agilent.com/find/emailupdates

Get the latest information on the products and applications you select.

Agilent Direct

www.agilent.com/find/agilentdirect

Quickly choose and use your test equipment solutions with confidence.



www.agilent.com/find/open

Agilent Open simplifies the process of connecting and programming test systems to help engineers design, validate and manufacture electronic products. Agilent offers open connectivity for a broad range of systemready instruments, open industry software, PC-standard I/O and global support, which are combined to more easily integrate test system development.

www.agilent.com

Agilent Technologies' Test and Measurement Support, Services, and Assistance

Agilent Technologies aims to maximize the value you receive, while minimizing your risk and problems. We strive to ensure that you get the test and measurement capabilities you paid for and obtain the support you need. Our extensive support resources and services can help you choose the right Agilent products for your applications and apply them successfully. Every instrument and system we sell has a global warranty. Two concepts underlie Agilent's overall support policy: "Our Promise" and "Your Advantage."

Our Promise

Our Promise means your Agilent test and measurement equipment will meet its advertised performance and functionality. When you are choosing new equipment, we will help you with product information, including realistic performance specifications and practical recommendations from experienced test engineers. When you receive your new Agilent equipment, we can help verify that it works properly and help with initial product operation.

Your Advantage

Your Advantage means that Agilent offers a wide range of additional expert test and measurement services, which you can purchase according to your unique technical and business needs. Solve problems efficiently and gain a competitive edge by contracting with us for calibration, extra-cost upgrades, out-of-warranty repairs, and onsite education and training, as well as design, system integration, project management, and other professional engineering services. Experienced Agilent engineers and technicians worldwide can help you maximize your productivity, optimize the return on investment of your Agilent instruments and systems, and obtain dependable measurement accuracy for the life of those products.

United States:	Korea:	
(tel) 800 829 4444	(tel) (080) 769 0800	
(fax) 800 829 4433	(fax) (080) 769 0900	
Canada:	Latin America:	
(tel) 877 894 4414	(tel) (305) 269 7500	
(fax) 800 746 4866	Taiwan:	
China:	(tel) 0800 047 866	
(tel) 800 810 0189	(fax) 0800 286 331	
(fax) 800 820 2816	Other Asia Pacific	
Europe:	Countries:	
(tel) 31 20 547 2111	(tel) (65) 6375 8100	
Japan:	(fax) (65) 6755 0042	
(tel) (81) 426 56 7832	Email: tm_ap@agilent.com	
(fax) (81) 426 56 7840	Contacts revised: 09/26/05	

For more information on Agilent Technologies' products, applications or services, please contact your local Agilent office. The complete list is available at:

www.agilent.com/find/contactus

Product specifications and descriptions in this document subject to change without notice.

© Agilent Technologies, Inc. 2005, 2006 Printed in USA, March 14, 2006 5989-4098EN

