

Agilent AN 369-5 Multi-frequency C-V Measurement of Semiconductors

Application Note

Agilent E4980A and 4284A Precision LCR Meters

Introduction

Parameters such as the capacitance of the oxide layer (Cox) and the density of substrate impurities (Nsub) that are required in the evaluation of the manufacturing process of MOS type semiconductors can be derived by using measured C-V characteristics. To make an accurate evaluation of these processes, precise C-V measurements are required. Such measurements entail the following difficulties.

Difficulties

- 1. There is no single instrument that can make C-V measurements from low to high frequencies.
- It is difficult to compensate for the additional errors that occur when cable extensions or a prober are used.
- 3. The accuracy and reliability of the DC bias voltage are not sufficient to perform repeatable C-V measurements.

In the following discussion we will show how C-V measurements are performed with the E4980A and 4284A solving these problems.

Solutions Offered by the E4980A and 4284A

1. Wide Frequency Range Measurements from 20 Hz to 2 MHz.

The program listing shown in the appendix was used to measure the C-V characteristics at 10 kHz, 100 kHz, and 1 MHz of the MOS device whose characteristics are shown in Figure 1.

Thus, the E4980A and the 4284A can single-handedy perform C-V measurements in both the low and high frequency ranges. This allows it to measure high-loss devices (semiconductors on large diameter wafers, etc.), which are difficult to measure at 1 MHz, at low frequencies (10 kHz, 100 kHz, etc.).




Figure 1. Multi-frequency C-V characteristics of a semiconductor

2. Compensation Functions for Cable Extensions and Probers.

In order to test semiconductor devices on a wafer, an extension cable and a prober are required. (See Figure 2.) The extension cable and the prober cause additional errors that greatly influence the test value. The E4980A and 4284A's 2m/4m Cable Length Operation function with 16048D/E test leads, Option 006 for 4284A, minimizes additional errors caused by using 2m/4m extension cables. The E4980A and 4284A's open/short/load compensation functions minimize errors caused by a prober. This powerful compensation function ensures highly accurate C-V measurements even when a prober is used.

3. Highly Accurate Internal Bias

Insufficient accuracy and stability of the bias voltage applied to a device prevents accurate C-V measurements. The E4980A and 4284A ensure the application of a stable bias voltage with a maximum accuracy of 0.1% (Option 001). This minimizes measurement errors due to bias voltage errors.

Conclusion

The E4980A and 4284A feature a wide frequency range, powerful compensation functions, and highly accurate bias characteristics. This versatility of the meter guarantees highly accurate C-V measurements, and higher efficiency in the evaluation of semiconductor processes. Because the E4980A and 4284A can perform all of the low and high frequency C-V measurements singlehandedly, it will greatly contribute to the lowering of capital costs.




Figure 2. Extension cable and prober

Table 1. E4980A Option 001 DC Bias Capability

Range	Resolution	Accuracy*
±0 to 5 V	330 μV	± 0.1% + 2 mV
±5.001 to 10 V	1 mV	$\pm 0.1\% + 2 \text{ mV}$
±10.002 to 20 V	2 mV	$\pm 0.1\% + 2 \text{ mV}$
±20.005 to 40 V	5 mV	$\pm 0.1\% + 2 \text{ mV}$

^{*}This can only be used when the test signal level is < 2 Vrms

Table 2. E4984A Option 001 DC Bias Capability

Range	Resolution	Accuracy*
±0.000 to 5 V	1 mV	± 0.1% + 1 mV
±4.002 to 8 V	2 mV	$\pm 0.1\% + 2 \text{ mV}$
±8.005 to 20 V	5 mV	$\pm 0.1\% + 5 \text{ mV}$
±20.01 to 40 V	10 mV	$\pm 0.1\% + 10 \text{ mV}$

^{*}This can only be used when the test signal level is < 2 Vrms

Appendix. Sample Program

```
! ****** Agilent 4284A C-V MEASUREMENT SAMPLE PROGRAM ******
 20
 30 GCLEAR
 40 PRINT CHR$(12)
                                                ! CLEAR DISPLAY
 50 DIM C(3,128),Cn(3,128),Vbias(128)
 60
    REAL Datab(1:513) BUFFER
210 GOSUB Corr
 220 PRINT "CONNECT OUT AND PRESS CONTINUE"
 230 PAUSE
 240 PRINT CHR$(12)
                                              ! CLEAR DISPLAY
! HOLD TIME = 10sec
 250 Holdtime=10
 260 Delaytime=.1
                                               ! DELAY TIME = 100msec
 770 Vbias(1)=-5
                                                ! START BIAS VOLTAGE
                                               ! 100mV BIAS STEP
 280 Vstep=.1
290 OUTPUT @Ad; "TRIG:DEL %EVAL$ (Delaytime)
                                                ! SET DELAY TIME
 300 OUTPUT @Ad; "BIAS: STATE ON"
                                                ! BIAS ON
 310 Freq$(1)=" 1MHz"
 320 Freq$(2)=" 100KHz"
 330 Freq$(3)=" 10KHz"
 340 FOR I=1 TO 3
      OUTPUT @Ad; "FREO" & Freq$ (I)
                                                ! FREQUENCY SETTING
 350
      OUTPUT @Ad; "BIAS: VOLT "&VAL$ (Vbias(1))
 360
                                                ! SET START BIAS VOLTAGE
      PRINT TABXY(5,15); "HOLD TIME 10SEC"
 370
      WAIT Holdtime
                                                ! HOLD TIME
 380
      PRINT TABXY(5,15); "MEASURING at "&Freq$(I)
 390
 400
      FOR J=1 TO 101
      OUTPUT @Ad;"TRIG"
 410
                                                ! TRIGGER 4284A
 420
      IF J=101 THEN 450

Vbias(J+1)=Vbias(J)+Vstep ! CHANGE BIAS VOLTAGE

OUTPUT @Ad; "BIAS: VOLT "&VAL$ (Vbias(J+1)) ! SET BIAS VOLTAGE
 430
 440
 450 NEXT J
 460
      RESET @Dummv
 470
      RESET @Buff
      OUTPUT @Ad;"MEM:READ? DBUF" ! READ BUFFER
TRANSFER @Pat TO @Dummy;COUNT 6,WAIT ! TRANSFER HEADER
 480
 490
 500
       TRANSFER @Pat TO @Buff; COUNT 101*4*8+1 , WAIT ! TRANSFER DATA
      FOR J=1 TO 101
        C(I,J)=Datab(J*4-3)
 530 NEXT J
      IF MAX(C(*))=0 THEN Err
                                                ! CHECK IF MAX C VALUE IS 0
    FOR J=1 TO 101
        Cn(I,J)=C(I,J)/MAX(C(*))
                                                ! NORMALIZE C VALUE
 570 ! PRINT Cn(I,J) ! PRINT NORMALIZED C VALUE
      NEXT J
     OUTPUT @Ad; "MEM:CLE DBUF; FILL DBUF"
                                                ! CLEAR DATA IN BUFFER
      PRINT CHR$(12)
 600
                                                ! CLEAR DISPLAY
 610 NEXT I
 620 OUTPUT @Ad; "BIAS: STATE OFF"
                                                ! BIAS OFF
 630 GOSUB Plotting
 640 GOTO Ending
 650 !
 670 ! THE FOLLOWINGS ARE FOR PLOTTING THE MEASUREMENT DATA TO CRT.
 680 !
 690 Plotting:DEG
                                                ! SET ANGLE UNIT TO DEGREE
 700 GRAPHICS ON
 710 VIEWPORT 8.150.17.100
                                              ! PLOT NUMBERS AND LABELS
 720 WINDOW 0,100,0,100
 730 I.DTR 0
 740 LORG 2
 7SO CSTZE 4
 760 MOVE 50.15
 770 LABEL "BTAS (V)"
 780 MOVE 8,23
 790 LABEL "-5.0"
 800 MOVE 54,23
 810 LABEL "0"
 820 MOVE 94.23
 830 LABEL "5.0"
 840 MOVE 5,28
```

```
850 LABEL "0.0"
860 MOVE 5,98
870 LABEL "1.0"
880 MOVE 75,5
890 LABEL " 1MHz"
900 MOVE 75,10
910 LABEL "100kHz"
920 MOVE 75,15
930 LABEL " 10kHz"
940 MOVE 88.5
950 DRAW 98 ,5
960 LINE TYPE 8
970 MOVE 88 .10
980 DRAW 98 ,10
990 LINE TYPE 3
1000 MOVE 88,15
1010 DRAW 98.15
1020 LINE TYPE 1
1030 LDTR 90
1040 MOVE 3.55
1050 LABEL "Cap/Cox"
1060 LDIR 0
1070 MOVE 5,28
1080 LABEL "0.0"
1090 MOVE 5.98
1100 LABEL "1.0"
                                                  ! END PLOT NUMBERS AND LABELS
1110 !
1120 VIEWPORT W3,125,40,100
                                                  ! DRAW AXES
1130 FRAME
1140 WINDOW -5.5.0.1
1150 AXES 1,.2,-5,0
                                                  ! END DRAW AXES
1160 !
1170 FOR I=1 TO 3
                                                  ! PLOT DATA
1180 MOVE Vbias(1),Cn(I,1)
1190 FOR J=2 TO 101
1200 DRAW Vbias(J), Cn(I,J)
1210 NEXT J
1320 LINE TYPE 3
1230 IF I=1 THEN LINE TYPE 8
1240 NEXT I
                                                 ! END PLOT DATA
1250 LINE TYPE 1
1260 RETURN
1270 !
1280 Corr:! ********* SUBROUTINE FOR CORRECTION **********
1290 ! THE FOLLOWINGS ARE FOR PERFORMING OPEN/SHORT COMPENSATION.
1300 !
1310 OUTPUT @Ad; "DISP: PAGE CSETUP"
                                                 ! GO TO CORRECTION SETUP PAGE
1320 OUTPUT @Ad; "CORR:LENG O; METH SING"
                                                 ! CABLE LENGTH Om, SINGLE COMPEN MODE
1330 OUTPUT @Ad; "CORR:SPOT1:FREQ 1MAHz; STAT ON"
                                                 ! SPOT FREO 1 = 1MHz
1340 OUTPUT @Ad; "CORR:SPOT2:FREQ 100KHz; STAT ON"
                                                 ! SPOT FREO 2 = 100kHz
1350 OUTPUT @Ad; "CORR:SPOT3:FREQ 10KHz; STAT ON"
                                                 ! SPOT FREO 3 = 10kHz
1360 OUTPUT @Ad. "CORR.LOAD.STAT OFF"
                                                 I LOAD COMPEN OFF
1370 PRINT "OPEN COMPENSATION"
1380 PRINT TABXY(5.15): "PRESS CONTINUE"
1390 PAUSE
1400 PRINT TABXY(5,15);" "
1410 OUTPUT @Ad: "CORR: SPOT1: OPEN"
                                                 ! PERFORM OPEN COMPEN AT SPOT FREO 1
1420 OUTPUT @Ad; "CORR:SPOT2:OPEN"
                                                 ! PERFORM OPEN COMPEN AT SPOT FREO 2
1430 OUTPUT @Ad; "CORR:SPOT3:OPEN"
                                                 ! PERFORM OPEN COMPEN AT SPOT FREQ 3
1440 OUTPUT @Ad; "*OPC?"
                                                 ! CONFIRM OPEN MEASUREMENT COMPLETED
1450 ENTER @Ad;A$
1460 OUTPUT @Ad; "CORR:OPEN:STAT ON"
                                                 ! OPEN COMPEN ON
1470 PRINT CHR$(12)
                                                  ! CLEAR DISPLAY
1480 PRINT "SHORT COMPENSATION"
1490 PRINT TABXY(5,15); "PRESS CONTINUE"
1500 PAUSE
1510 PRINT TABXY(5,15):" "
1520 OUTPUT @Ad; "CORR:SPOT1:SHOR"
                                                 ! PERFORM SHORT COMPEN AT SPOT FREO 1
1530 OUTPUT @Ad; "CORR: SPOT2: SHOR"
                                                 ! PERFORM SHORT COMPEN AT SPOT FREQ 2
1540 OUTPUT @Ad; "CORR:SPOT3:SHOR"
                                                 ! PERFORM SHORT COMPEN AT SPOT FREO 3
1550 OUTPUT @Ad; "*OPC?"
                                                 ! CONFIRM SHORT MEASUREMENT COMPLETED
1560 ENTER @Ad;A$
1570 OUTPUT @Ad; "CORR:SHOR:STAT ON')
                                                 ! SHORT COMPEN ON
1580 OUTPUT @Ad; "DISP: PAGE MEAS"
                                                 ! GO TO MEASUREMENT PAGE
1590 PRINT CHR$ (12)
1600 RETURN
1610 !
1630 Err:PRINT "C-V MEASUREMENT WAS FAILED."
```

www.agilent.com

Remove all doubt

Our repair and calibration services will get your equipment back to you, performing like new, when promised. You will get full value out of your Agilent equipment throughout its lifetime. Your equipment will be serviced by Agilent-trained technicians using the latest factory calibration procedures, automated repair diagnostics and genuine parts. You will always have the utmost confidence in your measurements.

Agilent offers a wide range of additional expert test and measurement services for your equipment, including initial start-up assistance onsite education and training, as well as design, system integration, and project management.

For more information on repair and calibration services, go to

www.agilent.com/find/removealldoubt



Agilent Email Updates

www.agilent.com/find/emailupdates Get the latest information on the products and applications you select.



www.agilent.com/find/quick

Quickly choose and use your test equipment solutions with confidence.

Product specifications and descriptions in this document subject to change without notice.

© Agilent Technologies, Inc. 2006, 2000 Printed in USA, October 2, 2006 5950-2953

