



In This Manual

- 1. Introduction
- 2. Performing Easy Tests
- 3. Data Display and Management
- 4. Modifying Application Test Definitions
- 5. Using Classic Test Environment
- 6. Creating Your Test Definitions
- 7. Advanced Definitions and Operations
- 8. Miscellaneous Operations



Notices

© Agilent Technologies 2005, 2006

No part of this manual may be reproduced in any form or by any means (including electronic storage and retrieval or translation into a foreign language) without prior agreement and written consent from Agilent Technologies, Inc. as governed by United States and international copyright laws.

Manual Part Number

B1500-90041

Edition

Edition 1, September 2005 Edition 2, May 2006

Agilent Technologies, Inc. 395 Page Mill Road Palo Alto, CA 94303 USA




In This Module

- New Features
- EasyEXPERT
- To Perform Easy Application Test
- User Interface
- Modular Mainframe
- SCUU/GSWU
- ASU
- B2200 Switch Control
- Desktop EasyEXPERT
- 415x Setup File Converter

🔆 Agilent Technologies

Note:



The B1500A has many exciting new features and capabilities.

New Features

- EasyEXPERT software
 - Application test environment (> 150 algorithms)
 - Classic test environment 415x like setup
 - Quick test environment multiple test execution
 - · Semi-auto prober control and B2200 switch control
- Modular mainframe
 - MFCMU for C-V sweep
 - HPSMU, HRSMU, MPSMU for I/V sweep/sampling
- SMU CMU Unify Unit (SCUU)/Guard Switch Unit (GSWU)
 - · switching effortlessly between IV and CV measurement
- Atto Sense/Switch Unit (ASU)
 - · 100 aA level low current measurement
- · Touch-screen, knob, and softkeys
 - optional USB keyboard, mouse, and stylus pen


Agilent Technologies

The EasyEXPERT software

- •Task-oriented, "top-down" approach to device characterization
- Multiple test execution
- ·Automatic measurement, auto-analysis functions
- •Test sequencing without programming
- Application Library (>150 algorithms)
- •Categorized and organized


•Easy-to-use

- 415x setup file converter program
- Versatile Modular Mainframe
- •Flexible & Expandable (10 slots)
- •Multiple SMU types
- •Atto-sense and Switch Unit (ASU)
- Multi-Frequency CMU
- •SMU CMU Unify Unit for IV/CV Probing
- •4.2 Amp Ground Unit
- **Convenient User Interface**
- •Touch screen operation (with optional stylus pen)
- ·Contextual softkeys & knob control
- •Optional USB keyboard & mouse



Instead of setting up the instrument hardware, the EasyEXPERT software focuses on the real task at hand for the engineer ---device characterization. All that you need to do is to connect the instrument to the device terminals as shown in the EasyEXPERT test parameters area.

The EasyEXPERT software also provides the classic test mode that allows the 4155/4156 like measurement setup operation.



Step 1: Click Application Test tab.

Step 2: Select one or more technology categories, and select a desired test from the list of tests associated with the selected technology categories.


Step 3: Change the setup parameters (Device parameters and Test parameters) if you want.

Step 4: Connect DUT, and click the Start button. The B1500A starts the selected test.

Step 5: Analyze the measurement result data displayed on the Data Display window automatically opened after the test.

The measurement result record is automatically stored in the internal hard disk drive when the Auto Recode mode is ON.

<section-header><section-header><list-item><list-item><list-item><list-item><list-item><list-item><list-item><list-item>




The following modules and accessories are available for the B1500A:

•B1520A CMU: 1 kHz to 5 MHz CV capability (1 slot)

•B1511A MPSMU: 100 mA/100 V force capability, 10 fA/0.5 mV measurement resolution (1 slot)
•B1517A HRSMU: 100 mA/100 V force capability, 1 fA/0.5 mV measurement resolution (1 slot)
•B1510A HPSMU: 1 A/200 V force capability, 10 fA/2 mV measurement resolution (2 slots)
•N1301A-100/102: SMU CMU unify unit (SCUU) & cable assembly

•N1301A-200/201/202: Guard switch unit (GSWU) & cable assembly


•E5288A ASU: 0.1 fA/0.5 mV measurement resolution with support for IV/CV switching The ASU (Atto sense/switch unit) can be used with the HRSMU calibrated with it. The SCUU can be used with the CMU (slot N), SMU (slot N-1), and SMU (slot N-2). The GSWU can be used with the SCUU.



You have a very hard time switching between CV and IV measurements (you may actually devote separate probe stations to CV and IV just to avoid having to change cables). In addition, great care has to be taken when cabling to a capacitance meter to insure that all of the capacitance measurements are properly compensated. The SCUU removes all of these worries and makes connection simple and easy. In addition, the B1500A software automatically takes care of the multiplexing based upon the type of algorithm selected from the front panel.

To install the SCUU near the manipulators/positioners, use the N1301A-102 SCUU cable.

To realize accurate capacitance measurement, use the N1301A-200/201/202 GSWU & cable.



The GSWU must be connected to the outer conductors of the manipulators/positioners connected to the Force1/CMUH and Force2/CMUL connectors of the SCUU. And the GSWU control cable must be connected between the GSWU and the SCUU.

When the SMU paths are available for the manipulators/positioners, the GSWU opens between the outer conductors. However, when the MFCMU paths are available, the GSWU connects them together to make the return path of measurement current. This will reduce the signal path impedance. And this is effective for the accurate capacitance measurement.


By using the EasyEXPERT software, cable length between the CMU and the SCUU is automatically detected, and the GSWU switch control is automatically performed. Also, capacitance error compensation is also automatically performed if the compensation data are available.

The GSWU is effective for

reducing the residual inductance of the measurement cable
stabilizing the residual inductance when measurement cable distance is changed (moved) It's roughly 1/10 to 1/30 when used with two 80 cm cable.

Note:


When the SMU paths are available for the manipulators/positioners, the outer conductors must be open because they must be connected to the SMU guard terminals that must be always open.



The high-resolution SMU (HRSMU) has an innate 1 fA & 0.5 mV measurement resolution. The optional ASU extends the HRSMU measurement resolution to 0.1 fA.

The ASU has another feature, built-in switching capability. It can switch between the SMU and an auxiliary input (AUX input, two BNC).

If the Agilent 4284A LCR meter is connected to the AUX inputs, the ASU can switch between the low current and CV measurements. Then connect a wire between the CMU return terminals of ASUs to make the return path of measurement current. This is effective for accurate capacitance measurement. However, you need to perform capacitance compensation by yourself.



Agilent B2200A/B2201A switching matrix can be controlled by B1500A/EasyEXPERT via GPIB. EasyEXPERT provides the Switching Matrix Operation Panel for interactive control of B2200 independent from the test execution mode of B1500. And switch setup can be saved to a classic test setup data. In the classic test, the switch setup is sent to B2200 when a measurement start button is clicked.


B1500A/EasyEXPERT also provides the semi-auto prober control script. The semi-auto prober can be controlled without programming. The prober control script supports the die move operation by using the following first three procedures in the repeat measurement setup and adds the subsite move operation by using the Subsite procedure in the quick test setup.

Prober control script:

- Start procedure
- Iteration procedure

•Final procedure

Subsite procedure




The Desktop EasyEXPERT software provides the following additional advantages to the B1500A, allowing you to minimize the amount of offline tasks performed on B1500A and increase the working ratio for measurements.

•Allows B1500A to be controlled from an external computer via GPIB while online.


•Allows test setup to be created on an external computer while offline.

•Allows data analysis to be performed on an external computer while offline.

To start Desktop EasyEXPERT, see Module 8.



To control the B1500A, you can reuse the 4155/4156 setup file (.MES file) by converting the .MES file to the EasyEXPERT setup file (.XTS file). The file conversion can be done by the SetupFileConverter.exe file. To execute the file conversion, see Module 8.



In This Module

- To Turn on/off B1500A
- To Launch EasyEXPERT
- To Specify/Create Workspace
- To Perform Application Test
- To Save/Recall Your Test Setup
- To Export/Import Your Preset Group
- To Export/Import Test Record
- To Perform Quick Test
- To Control B2200 Switching Matrix
- To Manage Data Display Window

Agilent Technologies


This section explains the above tasks. You will understand how to launch B1500A/EasyEXPERT, how to perform application test and quick test, and how to create your test setups and preset groups.



The Standby button works to turn on the B1500A when it is turned off. When the B1500A is turned on, the Standby button works to terminate the EasyEXPERT software, Windows, and turn off the B1500A.


After the B1500A is turned on, log on Windows.

The default user is Agilent B1500 User with no password.



After logging on, click Start EasyEXPERT button to launch the EasyEXPERT software.

If you do not see the Start EasyEXPERT button, double click the Start EasyEXPERT icon to open the Start EasyEXPERT window.



After launching the EasyEXPERT, you will see one of the above screens.

Case 1: If this is the first time to launch the EasyEXPERT

The LCD displays the EasyEXPERT main screen.

Case 2: If the B1500A has one workspace only

Select Yes, and click OK if you use the existing workspace.

The EasyEXPERT main screen is displayed.

Select No, and click Next if you want to create a new workspace.

See next slide.

Case 3: If the B1500A has some workspaces (more than one)

Select workspace you want to use, and click Continue.


The EasyEXPERT main screen is displayed.

If you create workspace, check the Create a new Workspace radio button, and click Continue.

To create a public workspace, check the *Allow other users to access this workspace* box. The public workspace can be used by all users.

To create a private workspace, delete the check from the *Allow other users to access this workspace* box.

Workspace is the space created in the Agilent B1500A's internal hard disk drive, and is used to store the test setup, measurement result data, and so on. The workspace can be created and allocated for each user.



Enter the workspace name and click OK to create/rename the workspace.

If you want to create a public workspace, check the *Allow other users to access this workspace* box.

The public workspace can be used by all users.

If you want to create a private workspace, delete the check from the *Allow other users to access this workspace* box.

Eatopary +	Help About This Instrument About This Test	_	文 mon, help 전 산 종 臣· Hold Roo Pint Options			
ter Market	Aglent CaryOGERT Help '4-4' Occurr linit calegoia	s from the left a So	B Agilent introdu Using E Classic Applica Functio Eulit - in B Applica Eulit - in B Applica S Precaut B http://v	500 Online Help E1500 Online H tion syDCPERT Test Definition tion Test Definit	Agilent B1500A/EasyEXPER Online Help - Snecknin: - Stoin JacKMEE - Show Jack Money - Show Jack Money - Show Jack Money - Show Date - Show	
Reg Seter	p Name D	te.	Count	Device ID	Remarks	

Online Help is available for the B1500A and EasyEXPERT. Select Help > Agilent EasyEXPERT Help menu to display the online help window. The online help provides the following information.


•Introduction describes overview, front view, rear view, and measurement units of the Agilent B1500A.

•Using EasyEXPERT provides the reference information of the Agilent EasyEXPERT software.


•Function Details explains the measurement functions of the B1500A with EasyEXPERT.

•Built-in Programming Tool provides the reference information of the built-in function, read out functions, and script programming statements.

•If You Have a Problem describes the problem solving information, the B1500A system maintenance information, and the error messages.



To know about the application test, click the (i) icon. This icon displays the message box that explains the application test definition. This function will help you to know what is and how to use the application test.



When you set a test condition of application test, you do not need to use keyboard. You can select the value from the typical values as shown below.

•Click the entry field of a setup parameter by using the touch screen or the mouse. This displays the typical values for the specified parameter on the softkeys.

•Select one of the softkeys.

Also you can use the following manner.

•Point the entry field of a setup parameter by using the mouse.


•Right click the mouse to display the popup menu.

•Click the Select menu to display the typical values for the specified parameter.

•Select one from the typical values.


Note:

The typical values are defined in the test definition. And you can change the values by using the Define typical values window opened by clicking the Typical Values button on the Test Specification screen of the Test Definition window. For the Test Definition window, see Module 4.



When you need to enter numeric characters in an entry field, you will see the icon at the right side of the entry field. This icon opens the Numeric KeyPad. You can use this screen keypad instead of the USB keyboard.

When you need to enter alphabetic characters in an entry field, you will see the icon at the right side of the entry field. This icon opens the On Screen Keyboard. You can use this screen keyboard instead of the USB keyboard.



Step 1: Click Application Test tab.


Step 2: Select one or more technology categories, and select a desired test from the list of tests associated with the selected technology categories.

Step 3: Change the setup parameters (Device parameters and Test parameters) if you want.


Step 4: Connect DUT, and click the Single button. The B1500A starts the selected test. After the test, the test result data is displayed on the Data Display window. And the Test Result Editor is also displayed on the lower left area of the B1500 screen. See the next page.

Step 5: Analyze the measurement result data.

The measurement result record is automatically stored in the internal hard disk drive.



The Test Result Editor provides the following GUI to set a flag and remarks to the test result record. Set the flag and remarks to the test record. •Save button and Delete button Divides test records into groups, Save and Delete. Test records in Save-group are always listed in the lower area of the EasyEXPERT main screen. Test records in Delete-group can be listed when Results > Filter > Show Deleted Data is checked. Flags buttons The following buttons are available. You can set one of the following flags. Important ! Button Sets the important flag (!) to the test result record. Valid # button Sets the valid flag (#) to the test result record. Questionable ? Button Sets the questionable flag (?) to the test result record. •Remarks field You can enter characters into this field. The characters will be recorded as the Remarks value of the test result record. OK button Applies the setup on the Test Result Editor, and closes this dialog box.




The test result records are listed in the test record list area. The area also lists the following data. •Append measurement data marked with ...

•Deleted data marked with * if Results > Filter > Show Deleted Data is checked

•Test name defined in the application test definition if Results > Filter > Expand Application Test Results is checked

If Results > Filter > Show All Append Data is checked, all append data will be listed and the symbol will be changed to A for the data obtained by the Append measurement or S for the data obtained by the Single measurement.



The EasyEXPERT provides three execution modes, Single, Append, and Repeat.


Single button triggers a single measurement.

Append button triggers an append measurement. The measurement results will be appended to the Data Display window that shows the previous measurement results. The Data

Display window can have maximum 10 layers for displaying measurement results.

Repeat button opens the Repeat Measurement Setup dialog box used to set the repeat measurement condition. To perform the repeat measurement, see Module 7.

To abort measurement, click Stop button that appears instead of the Single button.



The test setups you create or modify MUST be saved in a preset group (My Favorite Setup).


To save the setup, click the Save button.

To recall the setup, click the Recall button.

You can organize the setups by using the My Favorite Setup button.

To select the available preset group, use the field below the My Favorite Setup button. In the above example, the Demo group is selected and listed in the My Favorite Setup list.

To rename, duplicate, or delete the setups, and to add, rename, duplicate, delete, import, or export the preset group, use the function of the My Favorite Setup button menu or the Organize Preset Group dialog box shown in the next page.



This dialog box is opened by selecting the Organize Preset Group function of the My Favorite Setup button menu, and is used to organize the preset group.

•Preset Group List

Lists the preset groups saved in the workspace. The Add, Rename, Duplicate, Delete, Import, and Export buttons are available to organize the preset groups.

•Copy

Sets the operation of the >> button and the << button. They work as Copy when this check box is checked, and as Move when this check box is blank.

•>>

Copies or moves the preset setup selected in the left Preset Group box to the right Preset Group box.

•<<


Copies or moves the preset setup selected in the right Preset Group box to the left Preset Group box.

•Close

Closes the Organize Preset Group dialog box.

Preset Group


Lists the preset setups saved in the preset group. The Select All, Unselect All, Rename, Duplicate, and Delete buttons are available to select or organize the setups saved in the preset group.



You can export/import your preset group.

To export the present preset group, click the My Favorite Setup button, select Export, and specify the folder and the name of the preset group to export.

To import the preset group, click the My Favorite Setup button, select Import, and specify the preset group to import.



To export the test result record, specify the data records and select the Transport Data > Export As xxxx menu.

You can save the data records as an EasyEXPERT file, a CSV file, a XML spreadsheet file, or a XML file created by using the specified XML style sheet.

You can import the data record exported as the EasyEXPERT file or the XML spreadsheet file.

To import the file, select the Transport Data > Import... Then the Test Result Import dialog box is opened. On the dialog box, select the file to import.

You can read by using a text editor or a spreadsheet software as shown above. This example reads a test record exported to a CSV file.

Exercise 1


Perform Application Test.

- **1.** Open Vth gmMax test definition in the CMOS library.
- 2. Change the setup (SMU, output value, etc.)
- 3. Create your preset group, and save your setup.
- 4. Connect device (MOSFET).
- 5. Perform Application Test.

Time to complete: 5 minutes.



Note:




For all class exercises, you need the 28-pin dual in line socket which comes standard with the 4145 fixture (16058A) or the 4156 fixture (16442A/B). Either fixture works fine.

With the 16442A/B fixture, note that there are two SMU numbering schemes....3 SMUs with force and sense, or six SMUs with force only. For this class example we will use the six (6) SMU scheme.


To mount the MOSFET, the leads must be re-arranged into a straight line as shown.

IMPORTANT:


The MOS FET is highly sensitive to electrostatic damage. Touching the bare leads will definitely destroy the device. The device comes with a special shorting wire attached. Bend the leads the way you want, insert the device in the socket, and then remove the shorting wire. The wire has a tab. Just grab the tab and pull straight out. The wire will spiral out as you pull.



Note:



Note:



Step 1: Click Quick Test tab.

Step 2: Select the Preset Group.

Step 3: Mark (check) the test setups to be executed while the Quick Test is executed.


Step 4: Connect DUT, and click the Single button. The B1500A starts the selected tests from top to bottom in the list.

After the test, the test result data is displayed on the Data Display window. And the Test Result Editor is also displayed on the lower left area of the B1500 screen.

Step 5: Analyze the measurement result data.

The measurement result record is automatically stored in the internal hard disk drive.

The softkeys placed right side of the LCD are used to trigger a single measurement of the associated test.



This dialog box is opened by selecting the Organize Preset Group function of the My Favorite Setup banner menu, and is used to organize the test preset group.

•Preset Group List

Lists the preset groups saved in the workspace. The Add, Rename, Duplicate, Delete, Import, and Export buttons are available to organize the preset groups.

•Copy

Sets the operation of the >> button and the << button. They work as Copy when this check box is checked, and as Move when this check box is blank.

•>>

Copies or moves the preset setup selected in the left Preset Group box to the right Preset Group box.

•<<

Copies or moves the preset setup selected in the right Preset Group box to the left Preset Group box.

•Close

Closes the Organize Preset Group dialog box.

Preset Group

Lists the preset setups saved in the preset group. The Select All, Unselect All, Rename, Duplicate, and Delete buttons are available to select or organize the setups saved in the preset group.

Exercise 2


Perform Quick Test.

- 1. Open or create your preset group.
- 2. Edit your preset group as you want (changing the test execution order etc.).
- 3. Save your preset group.
- 4. Connect device (MOSFET).
- 5. Perform Quick Test.


Time to complete: 5 minutes.

🗧 Agilent Technologies

Note:



Note:



Step 1: Click Switching Matrix button to open the Switching Matrix Operation Panel.

Step 2: Enter the switch setup name.

Step 3: Define the switch setup by using the matrix on the operation panel window. Label can be set to input ports and output channels.

Step 4: Click the Apply Switch Setup button to send the switch setup to the B2200 switching matrix.

Note:

Before clicking this button, connect the B2200 to the B1500 via GPIB, and set the configuration. To set the configuration, see Module 8.

The switch setups you create or modify MUST be saved in a preset group.


To save the setup, click the Save button.

To recall the setup, click the Recall button.

You can organize the setups by using the Preset List button.

To select the available preset group, use the field below the Preset List button. In the above example, the DemoSW group is selected and listed in the Preset List list.

To rename, duplicate, or delete the setups, and to add, rename, duplicate, or delete the preset group, use the function of the Preset List button menu or the Organize Preset Group dialog box shown in the next page.



This dialog box is opened by selecting the Organize Preset Group function of the Preset List button menu, and is used to organize the switch preset group.

•Preset Group List

Lists the preset groups saved in the workspace. The Add, Rename, Duplicate, and Delete buttons are available to organize the preset groups.

•Copy

Sets the operation of the >> button and the << button. They work as Copy when this check box is checked, and as Move when this check box is blank.

•>>

Copies or moves the preset setup selected in the left Preset Group box to the right Preset Group box.

•<<

Copies or moves the preset setup selected in the right Preset Group box to the left Preset Group box.

•Close

Closes the Organize Preset Group dialog box.

Preset Group

Lists the preset setups saved in the preset group. The Select All, Unselect All, Rename, Duplicate, and Delete buttons are available to select or organize the setups saved in the preset group.

My Favorite Setup					
Preset Group: Domi		I In Lat			
Setup Name	Switch Setup				
15 1to7	Typest to Carrent My Farette Group	AL I			
15.100	OWENE 1 2 3 4 5 5 7 8 7 28 13 32 Apply Surl	a find and			
	Chair (0)	ch Solup			
	Input: Labol All	-1			
-					
	[SHUB2040#] 『				
	Бинзи Г фффффффф .				
	INN				
Flag Setup Name					
Vth gmMax Id-Vd					
Timp (dvd (dvg3	5000 M2 7 000000000000				
Timp Idvd Idvp2 Timp Idvd Idvp					
Tring ided ideg	SMINH r 000000000000				

Switch setups can be saved in the preset group for test setups.

Click the Export to Current My Favorite Group button. The switch setup will be converted to a classic test setup and saved in the My Favorite Setup group opened in the main screen.

To select the available preset group, use the Preset Group field. In the above example, the Demo group is selected and listed in the quick test setup list.

To duplicate, import, or export the preset group, use the function of the My Favorite Setup banner menu or the Organize Preset Group dialog box shown in the next page.

Exercise 3


Add switch setup to test preset group.

- 1. Create a switch setup.
- 2. Create your switch preset group, and save your setup.
- **3.** Add the switch setup to your test preset group.
- 4. Save your test preset group.

Time to complete: 5 minutes.



Note:



The Data Display Properties window is used to set the default setting of the Data Display window. This window is opened by selecting the Data Display > Default Data Display Properties... menu of the main screen.

The Effective Area is used to select the area effective when the Data Display window is opened, and provides the following check box.

•X-Y Graph: Check this box to enable the X-Y Graph area.


•Grid ON: Check this box to display the grid in the X-Y Graph.

•List Display: Check this box to enable the List Display area.

•Parameters: Check this box to enable the Parameters area.

The Graph Color area is used to set the color map of the Data Display window. You can change the color of the graph background, text, graph grid, and line. The color palette is opened by clicking the pattern of the item.

The Graph Trace Color area is used to set visibility, color, and thickness of the data traces Y1 to Y8 plotted in the graph.



The Data Display Manager is used to control the appearances of the Data Display windows. This window is opened by selecting the Data Display > Manage Data Display... menu of the main screen.

The Data Display Window Order area lists the Setup Name of the Data Display windows opened. The list items from top to bottom correspond to the windows from front to back in the screen image.

The Minimized Data Displays area lists the Setup Name of the Data Display windows minimized. The Data Display Window Configuration area provides the following radio buttons and a check box to change the appearances of the Data Display windows. All functions are available for the opened windows. See following slides for the display examples.

•Keep Setup: Keeps the present configuration of the Data Display windows.


•Tiling: Resize and collate the data display windows such that they fill up the entire screen.

•Stacking: Resize and collate the data display windows so that they overlap slightly with an offset.


•Overlaying: Resize, overlap, and make transparent the data display windows so that multiple graphs can be viewed and superimposed on one another.

The following check box must be checked to apply the same graph scale to all graphs.


•Apply same scale to all graph




This is a display example of Tiling.



This is a display example of Stacking.



This is a display example of Overlaying.



When some Data Display windows are opened, the following Windows menu functions are useful.

Tiling

Tiles all Data Display windows on the screen.


Stacking

Stacks all Data Display windows on the screen.

Overlaying

Overlays all Data Display windows on the screen. Then the position, window size, and visibility of the most front window are applied to all windows on the screen.

The background of the X-Y Graph area is cleared except for the most back window.




In This Module

- Data Display window
- Graph Analysis Tools
- Data Status
- To Change Graph/List/Display Setup
- To See Print Preview
- To Print Display Data
- To Copy Graph Plot/List Data
- To Save Analysis Result
- To Use Preview Window

Agilent Technologies

This section describes the above topics. You will understand how to use analysis tools, how to change display setup, and how to print/export test result.




The Data Display window is opened after measurement automatically, or by clicking the Data Display button. And the window is used to display measurement data and analyze the data.

The Show X-Y Graph icon displays/hides the X-Y Graph Plot area. This is the same as the View > X-Y Graph menu.


The Show List Display icon displays/hides the List Display area. This is the same as the View > List Display menu.

The Show Parameters icon displays/hides the Parameters area. This is the same as the View > Parameters menu.



The Data Display window provides marker, cursors, and lines for analyzing test result data. Marker is used to read measurement data and draw a tangent line. Cursors are used to read the cursor position and draw a normal line, gradient line, or regression line. The cursor/marker position data is displayed top of the graph plot area.


Clicking Y axis can select the Y axis effective for the analysis tools. On the graph, left axis is always Y1 axis. And the right axis is selectable from Y2 to Y8 axes.



When a line is displayed, the line information can be displayed in the graph plot area.

The Show Line Information icon displays/hides the line information. This is the same as the View > Line Information ON/OFF menu.

The Show Graph Legend icon displays/hides the graph legend. This is the same as the View > Graph Legend ON/OFF menu.



If the append measurement is performed, the data display layer is added to the Data Display window. In this example, the Data Display window has three layers.


Use the icons shown above to organize the data display layers.

Switch Display Mode icon switches the mode, overwrite or append.

In the overwrite mode, the data is displayed in a new Data Display window.

In the append mode, the data is displayed on a new display layer in the present Data Display window.

The Data Display window can hold up to 10 display layers. And the earliest layer over 10 will be automatically deleted. The Hold this layer icon is available when the window holds at least two layers. If this icon shows the standing pin, the layer will be held. If this icon shows the laid pin, the layer can be deleted. Double clicking the tab gives the same result as this icon.



Graph control:

Auto Scale icon changes graph scale to fit the trace in the graph automatically for the Choose Active Y Axis.

Zoom In icon zooms the data graph in. This enlarges the trace in the graph. Then the center of zooming will be the cursor position.

Zoom Out icon zooms the data graph out. This reduces the trace in the graph.

Graph Setup icon opens the Graph Setup dialog box used to change the graph axis setup.

Choose Active Y axis icon selects the Y axis that is effective for the analysis tools (marker control and auto scaling).

Marker control:

Marker ON/OFF icon enables or disables the marker.


Interpolation ON/OFF icon enables or disables the interpolation function of measurement data. You can read the interpolation data between two actual measurement points.

Marker Skip icon moves the marker to the next measurement curve that is added by the VAR2 variable.

Marker Maximum icon moves the marker to the maximum measurement point.

Marker Minimum icon moves the marker to the minimum measurement point.

Marker Search icon opens the Direct Marker/Cursor dialog box used to specify the coordinate values to move the marker.




Line control:

Line 1 State icon enables or disables line 1 and its function: normal, gradient, tangent, or regression.

Line 2 State icon enables or disables line 2 and its function: normal, gradient, tangent, or regression.

Cursor to Marker icon moves the cursor to the marker position.

Adjust Gradient icon is available when a regression line is active. Clicking this icon enables the rotary knob and the mouse wheel to increase/decrease the gradient of the line. Clicking this icon again, clicking the rotary knob, or clicking the mouse wheel disables this function.



To enable maker, click the Marker ON/OFF icon, or select the Marker > Marker ON/OFF menu.


To enable the Line 1, click Line 1 icon and select one of the line mode. Or select the Line > Line 1 ON/OFF menu and select one of the line mode.

To enable the Line 2, click Line 2 icon and select one of the line mode. Or select the Line > Line 2 ON/OFF menu and select one of the line mode.

If you enable the Normal line, two cursors are available. The cursors specify the points that the line passes through.

If you enable the Gradient line, a cursor is available. The cursor specifies the point that the line passes through.


If you enable the Regression line, two cursors are available. The cursor specify the measured data used to draw the regression line.



Enable the Normal line by clicking the Line 1 (or Line 2) icon and Normal.

Move cursors to draw the line. The line passes through the cursor points.

To move the cursor, you can use the Cursor To Marker icon. The cursor will move to the marker point.




Enable the Gradient line by clicking the Line 1 (or Line 2) icon and Gradient.

Move the cursor to specify the point that the line passes through. And click the Adjust Gradient icon.


Use the rotary knob or the marker scroll button to adjust the gradient of the line.

To move the cursor, you can use the Cursor To Marker icon. The cursor will move to the marker point.



Enable the Tangent line by clicking the Line 1 (or Line 2) icon and Tangent.


Move marker to draw the line. The tangent line will pass through the marker point.



Enable the Regression line by clicking the Line 1 (or Line 2) icon and Regression.

Move cursors to specify the region of the measurement data used for the regression calculation.

To move the cursor, you can use the Cursor To Marker icon. The cursor will move to the marker point.




If measurement unit detects any status while measurement, the status code is recorded with the measurement data. In this example, a SMU detected the compliance condition in the drain channel, so the status code C is put just before the Idrain value.

SMU status code:

- C: Compliance
- T: Other channel compliance
- X: Oscillation
- V: Overflow

MFCMU status code:

- U: Unbalance
- D: I/V amp saturation
- V: Overflow



The Graph Properties dialog box is used to set the following setting of the selected Data Display window. This dialog box is opened by clicking the Properties... button in the X-Y Graph Plot area or by selecting the Edit > Graph Properties... menu of the Data Display window.

The Grid ON check box in the Effective Area is used to display the grid in the X-Y Graph.

The Graph Color area is used to set the color map of the Data Display window. You can change the color of the graph background, text, graph grid, and line. The color palette is opened by clicking the pattern of the item.

The Graph Trace Color area is used to set visibility, color, and thickness of the data traces Y1 to Y8 plotted in the graph.

	Data Status
st Display Properties	Physical Unit
Display IF Data Status IF Physical Unit	Example: C -1.2345 V
Number Format Figure Format (with Unit Prefix)	
C Scientific Notation	Example: -1.23456789012345E-003 A
OK Cancel Apply	

This dialog box is used to set the data display format in the List Display area. This dialog box is opened by clicking the Properties... button in the List Display area or by selecting Edit > List Display Properties... menu of the Data Display window.

Display:

Check the following check box to add the data status or the physical unit to data. Unchecking the box removes it.

•Data Status: Adds or removes the status code before data.

•Physical Unit: Adds or removes the physical unit after data.

Number Format:

Selects the data display format from the following formats.

• Engineering Format (with Unit Prefix):

Data display with arithmetic point, SI prefix, and unit. Example: -1.2345 mA

Scientific Notation:

Data display with arithmetic point, exponential part (E, +/- sign, and three-digit number), and unit. Example: -1.23456789012345E-003 A

(Phote	ly Seba	p				1
x Y Graph						
		223	120	400 Miler		Phinait
	X:	Name: Voite	Scale:	(1 V	Max: W [2 V	
E.	¥1:	Schuer .	· Des	* 8.8.04	W (685 U.K.	
	Y2:	lam .	S (Day	· [-170.95	i pesta	<u> </u>
	12	- Bau	(a) from	will bevonte	W braue	
0	¥3.	[toan	<u>*</u>] [Log		M] [5 mA	×
	isplay		* koa	Parameters		
			¥ (1.00	Parameters	(1) (5 mA	N.
List D	lisplay 			Parameters AM C (12)	18441 1114	
List D	isplay 	u <u>see</u>	Ip. (Part)	Parameters	18441 1114	Roser
List D		u <u>seer</u>	The Proof	Parameters AM C (12)	18441 1114	
List D		d <u>Broke</u> Igone Isauroe Idae Indos	Tipe (Post)	Parameters AM C (12)	18441 1114	
List D	Suplay F F F F F	Agator Agator Agator Adamon	The Proof	Parameters AM C (12)	18441 1114	

This dialog box is used to change the graph scale and data displayed in the Data Display window.

The X-Y Graph area sets the X axis and Y axis of the X-Y Graph Plot area.

•Name: Name of variable to plot on the X axis


•Scale: Linear or Log

•Min: Minimum value of the specified axis

•Max: Maximum value of the specified axis

The List Display area selects the variables to be listed in the List Display area. Up to 20 variables can be set.

The Parameters area selects the variables to be listed in the Parameters area. Up to 20 parameters can be set.



The Data Display window provides the File > Print Preview... function to show the print preview. This is an example of the print preview.

•Select the File > Print Preview menu to open the Print Preview dialog box.

•Set the Print Range, Data to print, and Scaling.

•Click Preview button. The Print preview window is displayed.

Print Print Range	Save in: 🙆 IV Decuments	
	My Procest Decisioners	
Data to print (주 gurrent Data Display (^ 실l opened Data Display	Desinos My Decumenta	
Scaling	Ny Consult	
E Keep Aspect Balto	Hy Telefork He rame	· Sava
Next Cancel	Save as type: Bines in Mines th Protected Of Insta	aye Final 31 Canes age Canal Tanta Fanti Frati Alama
		if, or png format

The Data Display window provides the display image output capability to a printer or a file.

Before printing, connect a printer to the B1500A via the parallel interface or the LAN, and set up it by using the Add Printer Wizard of Windows. After that, do following.

•Select the File > Print menu to open the Print dialog box.

•Set the Print Range, Data to print, and Scaling.

•Click Next button.

•Select the printer, and set the Properties.

•Click OK button.

You can export the display image to a file as shown below.

•Select the File > Save Image As... menu to open the Save Image As... dialog box.

•Select the format (file type) from Save As Type menu.

•Enter the file name.

•Click Save button.


The file can be imported by the graphics software that supports the exported file type. The EasyEXPERT supports the following types.

•bmp: Bitmap image

•emf: Enhanced metafile

•gif: GIF image

•png: PNG image



You can copy graph image to the clipboard, and paste it to a word processing software. In the above example, the graph image is pasted to the WordPad.

This is an example of the copy and paste operation.

•Select the Edit > Copy Graph menu on the Data Display window.

•Select the Edit > Paste menu on the WordPad.

FI	IN TRACE VARIAN		PHI - Agilant EngEXPE				
12	particular and a state	Marker Cursi				Pacto to N	.
	Copy Grad	6		12 10 19 X-1 00	篇·號·照前日	Γαδιθιυ ΙΝ	lotepad
	flat Copy List		a nati			x	-
100	y G Copy Para	meters		P. p Untitle	rd - Hutepad		2
	Api Graph Pro	perties		0000	SR Format View Help		
		Properties		1rdex	Vgate Vsource vdrafin	subs idrafn ps 100 m 0 v 404 fa -1#3.4	14 25
1.4	TO BE AND ADDRESS OF ADDRESS			and the second	-450 mV 0 V	100 my 0 y 404 fa -1#3.4 100 my 0 y -7.79 pa	+81.55 85
	Lilling of		1	all	-100 MV 0 V -555 MV 8 V	100 m 0 v -7.75 pA 100 m 0 v -7.75 pA 100 m 0 v -7.714 pA 100 m 0 v -7.117 pA 100 m 0 v -7.41 pA 100 m 0 v -7.41 pA	2. 290000000000 p5 -000 0000000000 p5
	11940			10040	-100 mV 0 V	188 8 8 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-1,0600000000000 ps -810,00000000000 Ps
	1	1	1		-200 MV 0 V	100 WV 0 V	-810,000000000008 #1
1.2	2.	/	/		-150 ev 0 v -100 ev 0 v	100 mV 0 V -7,909 pA 100 mV 0 V -6,075 pA	-1.73999999999999 pt 2.52 85
		1	/	lió	-30 mm 0 4 100 mm		and and
1.00						0 v	
	107	1	/	15	0 V 0 V 100 W	0 v	
30.	10 a	1	/	12	0 V 0 V 100 mV 50 mV 0 V 100 mV 100 mV 0 V 105 mV	0 v 47,457 p4 82,02 0 v 44,878 pA 46,38 0 v 48,295 pA 494,74 0 v 48,295 pA 494,74	Personal ps
10	10 a 20a	1	/	1500 1400 1400 1400 14	0 V 0 V 100 mv 50 mv 0 V 100 mv 100 mv 0 V 100 mv 150 mv 0 V 100 mv	0 v 47.437 p4 12.03 0 v 44.873 p4 46.38 0 v 46.295 p4 434.7 0 v 46.345 p4 1.030 0 v 47.990 p4 42.431 0 v 46.445 p4 4.030	21 13000000000 2 8 2 9 800000000 2 9 99999999 2 1000000000 2 100000000000
10	Ada	/	/	11/101/1	0 V 0 V 100 mv 50 mv 0 V 100 mv 100 mv 0 V 100 mv 150 mv 0 V 100 mv	0 v 47.437 p4 12.03 0 v 44.873 p4 46.38 0 v 46.295 p4 434.7 0 v 46.345 p4 1.030 0 v 47.990 p4 42.431 0 v 46.445 p4 4.030	21 13000000000 2 8 2 9 800000000 2 9 99999999 2 1000000000 2 100000000000
10	Ada	a jak (as 1910		141114		0 v -7,47 pa 82,07 0 v -4,273 pa -5,187 0 v -4,275 pa -5,147,0 0 v -4,275 pa -1,47,0 0 v -4,285 pa -1,47,0 0 v -4,185 pa -2,427 0 v -4,186 pa -4,180 0 v -4,186 pa -4,186 0 v -4,186 pa -4,1	Notocontent as pa notocontent as notocontents as noto
町中	Ada	e Jok Geo Hoo	- 19: 400-775		0 v 0 v 100 mv 100 mv 0 v 100 mv	0 v 47,457 pa 12,01 0 v 44,573 pa 46,585 0 v 44,573 pa 44,73 0 v 44,573 pa 44,75 0 v 44,575 pa 42,475 0 v 44,585 pa 42,475 0 v 44,555 pa 42,475 0 v 44,555 pa 44,145 0 v 44,555 pa 44,145 0 v 44,555 pa 44,145 0 v 44,555 pa 42,095 0 v 44,555 pa 42,555 0 v	Proceedings as PS PS PS PS PS PS PS PS PS PS
日本の	Ada				0 v 0 v 100 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	Antonomount as PE antonomount As antonomount ps PE Base antonomount ps PE antonomount ps PE anto
	190 190 190 190 190 190 190 190 190 190	Iber		1 11 4 100 - 10 -	0 v 0 v 100 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m 10 m	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	Antonomount as PE antonomount As antonomount ps PE Base antonomount ps PE antonomount ps PE anto
	Ada			11 11 11 11 11		$\begin{array}{cccccccccccccccccccccccccccccccccccc$	00000000000000000000000000000000000000
		100 T		11 11 11 11 11	0 V 0 V 100 m 100 m 0 V 100 m 100 m	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	00000000000000000000000000000000000000
	Han Han (out o locate (of your) your (you)				0 v 0 v 100 m 100 m 100 m 100 m	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0000000000 ps PS PS 0000000000 ps PS PS PS PS PS PS PS PS PS PS
		100 T			0 v 0 v 100 m 50 m 0 v 100 m 150 m 0 v 100 m 150 m 0 v 100 m 150 m 0 v 100 m 100	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	00000000000000000000000000000000000000
					9 0 0 100 mc 100 mc 0 100 mc 100 mc 0 100 mc 1150 mc 0 100 mc 1150 mc 0 100 mc 1151 mc 100 mc 100 mc 110 mc 100 mc 100 mc 11 mc 100 mc 100 mc 110 mc 100 mc 100 mc 110 mc 100 mc 100 mc 110	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	00000000000000000000000000000000000000
	146 (4 per per 147) (4 per 240 per 147) (4 per 240 per 147) (4 per 240 per 147) (4 per 240 per 147) (5 per 240 pe		F G H		9 v 0 v 100 m 100 m 0 v 100 m 110 m 0 v 100 m 100 m 100 m 100 m	Constraints Constrai	00000000000000000000000000000000000000
	1/40 1 0.64 page - 62 1 page - 62 1 -200 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500 1 -500		* 0 H		0 v 0 v 100 ms 0 v 0 v 100 ms 150 ms 0 v 100 ms 100 ms 100 ms	Constraints Constrai	00000000000000000000000000000000000000
1 2 3 4 5 5 6 1 2 3 4 5 5 7	(d) (d) <td></td> <td>P 0 H</td> <td></td> <td>0 v 0 v 100 m 100 m 0 v 100 m 1150 m 0 v 100 m 1150 m 0 v 100 m 1150 m 0 v 100 m 100 m 0 m 100 m 10</td> <td>Constraints Constraints Constrai</td> <td>00000000000000000000000000000000000000</td>		P 0 H		0 v 0 v 100 m 100 m 0 v 100 m 1150 m 0 v 100 m 1150 m 0 v 100 m 1150 m 0 v 100 m 100 m 0 m 100 m 10	Constraints Constrai	00000000000000000000000000000000000000
	refu refu <td< td=""><td></td><td>100 eV 100 eV 100 eV 100 eV 100 eV 100 eV 100 eV 100 eV 100 eV</td><td></td><td>9 0 0 100 mg 9 0 0 100 mg 155 mg 0 100 mg 12 100 mg 100 mg 101 mg 100 mg 100 mg 11 mg 100 mg 100 mg 12 mg 100 mg 100 mg 12 mg 100 mg 100 mg 13 mg 100 mg 100 mg 13 mg 100 mg 100 mg 140 mg 100 mg 100 mg 150 mg 100 mg 100 mg 150 mg 100</td><td>Constraints Constraints Constrai</td><td>00000000000000000000000000000000000000</td></td<>		100 eV 100 eV 100 eV 100 eV 100 eV 100 eV 100 eV 100 eV 100 eV		9 0 0 100 mg 9 0 0 100 mg 155 mg 0 100 mg 12 100 mg 100 mg 101 mg 100 mg 100 mg 11 mg 100 mg 100 mg 12 mg 100 mg 100 mg 12 mg 100 mg 100 mg 13 mg 100 mg 100 mg 13 mg 100 mg 100 mg 140 mg 100 mg 100 mg 150 mg 100 mg 100 mg 150 mg 100	Constraints Constrai	00000000000000000000000000000000000000
	Mini- Mini- <td< td=""><td></td><td>P</td><td></td><td>0 v 0 v 100 m 50 m 0 v 100 m 150 m 0 v 100 m 150 m 0 v 100 m 100 m</td><td>Constraints Constraints Constrai</td><td>00000000000000000000000000000000000000</td></td<>		P		0 v 0 v 100 m 50 m 0 v 100 m 150 m 0 v 100 m 150 m 0 v 100 m 100 m	Constraints Constrai	00000000000000000000000000000000000000
	refu refu <td< td=""><td></td><td>100 mV 100 mV</td><td></td><td>9 v 0 v 0 v 100 ms 9 v 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 100 ms 100 ms 100 ms 100 ms</td><td>0 0 </td><td>00000000000000000000000000000000000000</td></td<>		100 mV 100 mV		9 v 0 v 0 v 100 ms 9 v 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 100 ms 100 ms 100 ms 100 ms	0 0	00000000000000000000000000000000000000
	100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100		P 0 M 1997 # 0 M 1997 # 0 M 100 eV 100 eV		9 v 0 v 0 v 100 ms 9 v 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 155 m 0 v 100 ms 100 ms 100 ms 100 ms 100 ms 100 ms	0 0	00000000000000000000000000000000000000
	Adva Description 0.01 page - Sec page - Sec 0.01 page - Sec page - Sec page - Sec 0.01 page - Sec page - Sec page - Sec page - Sec 0.01 page - Sec 0.01 page - Sec 0.01 page - Sec		* 0 * imm am top av top av t		0 v 0 v 100 ms 100 ms 0 v 100 ms 100 ms 0 v 100 ms 100 ms 100 ms 100 ms 100 ms 100 ms <td>Constraints Constraints Constrai</td> <td>00000000000000000000000000000000000000</td>	Constraints Constrai	00000000000000000000000000000000000000
123455789101111111	Adds Adds <th< td=""><td></td><td>P Q H 1970 # 1970 # 1970 # 100 eV 100 eV 100 eV 100 eV 100 eV</td><td></td><td>9 y m 0 y 100 m 150 m 0 y 100 m 100 m 100 m 100 m</td><td>0 0 </td><td>00000000000000000000000000000000000000</td></th<>		P Q H 1970 # 1970 # 1970 # 100 eV 100 eV 100 eV 100 eV 100 eV		9 y m 0 y 100 m 150 m 0 y 100 m 100 m 100 m 100 m	0 0	00000000000000000000000000000000000000
	Adva Description 0.01 page - Sec page - Sec 0.01 page - Sec page - Sec page - Sec 0.01 page - Sec page - Sec page - Sec page - Sec 0.01 page - Sec 0.01 page - Sec 0.01 page - Sec		P Q H 1970 # 1970 # 1970 # 100 eV 100 eV 100 eV 100 eV 100 eV		0 v 0 v 100 ms 100 ms 0 v 100 ms 100 ms 0 v 100 ms 100 ms 100 ms 100 ms 100 ms 100 ms <td>0 0 </td> <td>00000000000000000000000000000000000000</td>	0 0	00000000000000000000000000000000000000

You can copy the data list to the clipboard, and paste it to a word processing software. In the above example, the data list is pasted to the Notepad.

This is an example of the copy and paste operation.


•Select the Edit > Copy List menu on the Data Display window.

•Select the Edit > Paste menu on the Notepad.

You can save the data as a text file, and read it by using a spreadsheet software. Data elements are separated by a tab.

Note:

As same as the Copy List function, the Copy Parameter function is used to copy the data in the Parameter area.



To leave the graph modification information such as scaling, marker, cursor, and line on the graph, select the File > Update Test Result menu.

You can see the all information when you open the graph again. Note that the modification information will be destroyed if you did not do it.

To save the graph image as a file, select the File > Save Image As... menu. You can save the image as a bmp, emf, gif, or png file.

Exercise 4


Use the analysis tools.

- 1. Use your test setup and perform measurement as shown in Exercise 1.
- 2. Enable marker and draw line. Try it for all line types.
- **3.** Copy/paste/save data list, and open it by using a spreadsheet software (optional, if you can).
- 4. Save analysis condition. Re-open the test record.
- 5. Export your test record. And import it.

Time to complete: 10 minutes.

Agilent Technologies

Note:




The Data Display window provides the File > Print... function to print the graph image. However, you may want to set the graph title and change the line style. Then use the Preview window. The Preview window is used to see and print the graph image you modified.

Select the View > Open Preview Window to open the Preview window and the Preview Settings dialog box. And use the Preview Settings dialog box to set the title of graph, X axis, and Y axis, and change the line style. To change the color and thickness, use the Color and Thickness dialog box opened by clicking the Color and Thickness... button.

Clicking OK button in the Preview Settings dialog box applies the modification to the Preview window and closes the dialog box.

Note:

The graph image in the Preview window cannot be saved.



This example is result of the changes shown in the previous page.

Line style was changed as shown above. The titles are set as follows.

- Graph title: ID-VG Characteristics
- X axis title: Gate Voltage
- Y1 axis title: Drain Current
- Y2 axis title: Transconductance
- Y3 axis title: Drain Current

Also color of line1 was changed to red, and thickness of trace was changed.

To change the setup again, open the Preview Settings dialog box by selecting the View > Preview Settings... menu.

Exercise 5


Use the Preview window.

- 1. Use your test record used in Exercise 4.
- 2. Change the graph image as you want.
 - Add graph title and change axis title.
 - Change line style
 - Change color and thickness
- 3. Print the graph image if a printer is available.

Time to complete: 5 minutes.




Note:




Modification Overview

- 1. Open an application test definition to be modified
- 2. Open test definition editor
- 3. Save the definition as your test definition
- 4. Modify the definition as you like
- 5. Resave and close the definition
- 6. Export your test definition
- 7. To Use Built-in Functions
- 8. To Use Auto Analysis Function in Test Contents

Agilent Technologies



Click a test definition in Library list area, and click Select button to open the test definition. For example, open Vth gmMax.



Click Library and select Open Definition of This Test... to open the test definition editor.

e the definit	ion as	vour def	inition (e	x: Trna v	th)			
					,			
C We protect								
Save Ctrl+		Teef Gubant					-	102112
Close		100.000001						
Constraint and Constr	y. (1425)		Description:	alanguagetter lang- 'a'' Yi's groups all that rought				
10.000	The VE			(Real) INSTITUTE AND ADDRESS OF BUILDING ADDRESS OF BUILDING ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS A		ann anns	MIRT	
	es (C)regren ries)	Abectation are even to	5 Sheer den	(11) MIREPSERUM. 481			1997	8
Devis Farm	autors Definition		AM	and the last	Frap	erties	_	
Name	Defaul							
i. Interfa	100	Press alors	PET.					
C 14	100 m		1					
in Joy				1.5				
- (1848	Maria I	d Wite-dearre						
Test Parame	ure Definition							10
Background	A Chapan Fed.	Auto (\$1500 East Differ)	Bints. Diar		wi	-	and in	and it
Harren	Type:	Default:	Ownerlytics:		Align: X	¥1	width	Eats
r" jiste		- Delton	Electronical State		8 (m)	Miles .	Rine .	ar n
* Jinura		- Concision	· Karina annua (m)		19 (41)	#5P97 .	1. (e)	
C Date	Marchale	- point	 Dian terretal (M) Butterneta terretal SM 		10 100 H	NO.4	No.	
r Nation		- Lan ev	· Deserves terres an		or from	Night I	No.	
		All see out	When you works		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	No.	BC	

After changing test name, save as new name (ex. Trng vth). Saving the definition changes the window title to the new test name. Window title will be changed from Vth gmMax to Trng vth in this example.

	- vun	y 100	t Defin					
						_		
hang	e defa	ult value	s, and ac	dd paran	netei	rs (e	x: Pcoi	np_d)
Tropath							-75%	
te mile Teat Spiicficatur		net cursuit]						
lest Information								1
Calegory	0400		Qencription	Allegate Option large-	100			
Test Name	7110.455			(Wat)		11221022	and the second second	
juon	Compan Held	PT I BIRTY AND THE I	apres- que	100010481948.00/ (IP)107087849205.00	76.01 1.04M/859 07/2+	CARLINALES.	PMERE	
beater Parame	ders Definition			-	P	oper first	100	1
			Abl	orres Classifier		Hin		This area sets the
Name:	Default	Description	ter.		- 10		ida -niv 📕	properties of the
e ba	-	Ridertangth				piges:		
c [ng	-014 vr	Riften men				Resolution	2411 C	specified parameter.
r (tans	M21.0 Au	#[Tampenture				Dence Values		•Min
						Theory Concerns	- Distant	•Max
fost Paramete					-	_		•Digits
Background	2.9 ogan Fadd	ALTER ALTER AND AND ADDRESS	Rivers. Quar	-	ALC: 1	Denes 🔄	W	•Resolution
Alamet Contract	Fape:	Osfault:	Description:	ate terreral	Align: X	•;	Widds Ext:	
r buint		- 22.0 MA	Current Producer for S	Locations terrorial		A DOWN	9.5 E U	·Unit
· Dragtes		SHORT	• -	and the second se	-	10 m	1)- 1)r	•Typical Values
r Jacobra	· later	-10.	· Hassowerst hoat for			ALC: NOT		•Symbols
r Date Time	Millionate (·	14	8 × 10	AD	<u>x x x</u>	
ar brane, e	Minutes -	-Barrow	· Pasar strategies for	Part Samuel	a shu	• • That	the str	
			ine () i				-	

On the Test Specification tab screen, you can add new parameters or change parameter settings. The above example adds the Pcomp_d test parameter.

For example:

Name=Pcomp_d, Type=Numeric, Default=1 mV, Description=Power compliance for drain terminal, Align=check, X=550, Y=120, Width=80, Ext=uncheck

Properties: Min=1 mW, Max=100 mW, Digits=4, Resolution=1 mW, Unit=W

For Align, X, Y, and Width values, see the values of the entry fields for the same terminal. For example, Pcomp_d must be put between Vd and Subs entry fields.


Typical Values... button opens a dialog box used to define the typical values used for the selections of the parameter value in the Application Test mode. For example, set 1 mW to 10 mW in 1 mW step.

Symbols... button opens a dialog box used to map a numeric value to a string. For example, Value=1 and Symbol=ON are set, typing ON enters 1, and typing 1 enters ON. The value must satisfy the Min, Max, Digits, and Resolution settings. The value and the symbol must be one by one. The definition is effective only for the parameter.

o Modify '	Test Definition
omouny	
hanne or set t	est parameters (ex: Pcomp_d)
nunge of set to	cor parameters (ex. i comp_a)
Ingeth	
n 199	
Tell Southstore Tell Carteria	
in in o e	😕 🔛 💭 🔶 🕰
Marker Barrier Charles	
	I/V Sweep Setep Name: C
Selection Internet Debets	Dama Sata Measurement Tercar Tercari Sata Davier Sata
a can be the	NAME INTO A CARA BARANCE
Local Variables Defini *	Name Visits at ASC/
BLOCH VARIABLES DETING *	Direction State a bing
IF Integline="ESORT" Integline = "MANUA	Mean(Mag: UREAR * Ad- Mark (UREARY) * Valued
AddPactor = 1	Mage (splits from)
SISE IF IntegTime="M IstagNods = "FLC" AddFactor = 1	Mega valiveritata 🕷
SIGE IF Integline*L Integline = "FGC"	No of Stage (MAT A
Addractor = 16 ELSE IF IntegTime**A	Perr Comp Rolling #
Integlide = "AUTO" AddFactor = 6	Thinks
END IF	Hadd Profiles . Delays (white
Vth gemas	Wane: I Name: Mode: Source: Compliance:
Auto Analysis	partemente Misteres
	Sala-San gilan allan alla gilan alla sala alla sala alla sala sala s
	A CONTRACTOR OF A CONTRACTOR O

On the Test Contents tab screen, you can change the test execution flow (program flow), measurement conditions, display setup, and so on.

To add the Pcomp_d parameter to the measurement setup, click the Vth_gmmax line in the program list. Then I/V Sweep setup editor is displayed. In the editor, display the Measurement Setup tab screen. And enter Pcomp_d to Pwr Comp entry field.



Next, display the Display Setup tab screen. And change the Y axis Max values. For example, add /, 1, and 0 at the last of entry field to change the Max value to 1/10.

P LOOP TO ALLO COMMENT DO DEDE	
Encid Variables Definition statement	
Encid Variables Definition statement	
Les Add Technology Add Stretcher Vanishier Vanishier Vanishier	
String Variable	
Variables Definit	
*** Integration 7 Name inform at Value 1 at Description Function of 42 factor	
Integrane stort	
Variables Yes	and
Angeliefe - 1 No are used	n the
t 17 Telegities" Name Fr. H Value F R Description For square H message box	
Integrates - It	•
staglide = "AUTO" Melactor = 6	

On the Test Contents tab screen, add program lines in the test execution flow. In this section, the following lines are inserted between the Vth_gmmax line and the Auto Analysis line.

Message

IF Yes=0

END


END IF

This will open the message box after the measurement is completed and before the auto analysis is performed.

At first, the variables used in the message box. For example, Yes and No variables are defined. Click Local Variables Definition line to display the local variable list shown above. And define the variables.

Example:

Name=Yes, Value=0, Description=User response Name=No, Value=0, Description=User response




Next, click the Message line in the program list. The editor change the display as shown above.


- 1. Enter the message.
- 2. Enter the button name.
- 3. Select the variable used to keep the status of the button.
- 4. Repeat 2 and 3 for all buttons you want to add.

dd branching	(ex: auto a	nalysis is p	erformed	l if Yes button is press		
Togeth						
ar bactoria Test Centeria						
	0 00	ADDED COMMENT	A			
ragion Consisters [Applement Text] Analy	Our Sat Heaterna			100		
But Seat	If stateword			<u> 191</u>		
	Condition Expression					
IF Integrime* SHOPF -2 Integrides = "WANTA. Addraruz: -8 ELGE IF Integrimes"M Integrides - "FLC" Addractor = 1 ELGE IF Integrimes"L Integrides - "FLC" Addractor = 16 ELGE IF Integrimes"L Integrides - "AllO" Addractor = 6 H for the former"L Harman IF Respire Jacob Addractor = 1 IF Respire Jacob Addractor = 1 IF Respire Jacob Addractor = 1 Jacob Jacob Jacob Addractor = 1 Jacob Jacob Jacob Addractor = 1 Jacob Jacob Jac	The lines ter the test if No is clicked.					

At last, insert the branching lines. The example above terminates the test execution if the No button is clicked on the Message box, without performing auto analysis.




This is the example image when the Message box is displayed on the screen after the measurement is completed.




This slide shows an example of using the Variable Inspector for debugging. Confirm whether the correct values are passed to the variables properly.

Set the break point, and click the Run button. After the program is paused, click the Inspect button. The Variable Inspector is displayed. You can check the values by using the variable display fields. The field can be displayed by using the Add XXXX Variable button. XXXX will be Numeric, Vector, String, or Module.



After you create your test definition, save the definition and close the Test Definition editor.

Click File > Close. Confirm Test Definition Save dialog box is opened. Click Yes to save your test definition and continue the close operation. The Confirm Test Definition Overwrite dialog box is opened. Click OK to overwrite your test definition.



The test definition can be exported as the EasyEXPERT test definition file format or XML file format. And the file can be imported to the EasyEXPERT later.

Exercise 6


Modify test definition.

- 1. Select Vth gmMax test definition and open it.
- 2. Modify it as shown in page 4-6 to 4-11.
- 3. Save it as Trng vth, and perform test.
- 4. Add program lines to start Id-Vd test by Yes button.
- 5. Save it as Trng vth2, and perform test.
- 6. Export it, and import it.

Time to complete: 10 minutes.

Agilent Technologies

Note:



Modification example for step 4. ! ***** Analysis ***** Message If Yes=1 Auto Analysis END IF ! ***** Id-Vd ***** Message If Yes=1 Id-Vd END IF

Setup example of the first message box: Message=Do you want to perform auto analysis? Button 1: Label=Yes, Selected=Yes Button 2: Label=No Setup example of the second message box: Message=Do you want to perform Id-Vd measurement? Button 1: Label=Yes, Selected=Yes Button 2: Label=No


To Use Built-in Functions

Absolute value:	abs(A)
Averaging:	avg(A), mavg(A,B)
Data conversion:	string(A), value(A)
Difference:	delta(A)
Differentiation, integration:	diff(A,B), integ(A,B)
Exponent, logarithm:	exp(A), lgt(A), log(A)
Maximum, minimum:	max(A), min(A)
Reading data :	getNumericData(A), getVectorData(A)
Square root:	sqrt(A)
Trigonometric function:	acos(A), asin(A) , atan(A), atan2(A,B), cos(A), sin(A), tan(A)
	Agilent Technologies

The EasyEXPERT software provides the built-in functions to calculate the display data and parameter and to get the test result data. The built-in functions can be used in the user function and analysis function of the test setup, and in the test execution flow of the test contents. For details of the functions, see User's Guide or online help.

The following functions are also available.

at(A,B), at(A,B,C), ceil(A), cond(A,B,C,D), dim1Size(A), dim2Size(A), floor(A), index(A,B), isValid(A), setDeviceId(A), storeAt(A,B,C,D), substring(A,B,C), swmToModule(A)



This is an user function setup example. This example uses the diff function to calculate gm values and the max function to get the maximum gm value.

Also, the getVectorData and getNumericData functions are used in the test execution flow to get the test result data.

To Use Read Out Functions

Marker index value:	@MI
X coordinate value:	@MX, @CX
Y coordinate value:	@MY, @MYn, @CY, @CYn
Regression line parameter:	@L1C0, @L2C0
Line slope:	@L1G, @L1Gn, @L2G. @L2Gn
Line X intercept:	@L1X, @L2X
Line Y intercept:	@L1Y, @L1Yn, @L2Y, @L2Yn
Intersection of lines:	@IX, @IY, @IYn
	n: integer. 1 to 8.
	Agilent Technologies

The EasyEXPERT software provides the read out functions to read the marker position, cursor position, line slope, line intercept, and so on. The read out functions can be used in the analysis function of the test setup.

	example
Troy idig Auto Ana	201
na may	All Miles
Test Souchstan Test Contents Test Guit	4
KY30866 KV4 CV3046	
Proper Component Applement Text Ane	
Status Date Date	Cherrel Setue Massimum Setue Research (1712)
To car Pada	Wser Fullclive
A Cuty Cut Pade	Add
Local Variables Defini .	c in with stations
Message 15 Texal	r (2796 🖬 1 🕑 796(27) 👔
IdVe	
Kato Analysis Nessage	
IF Yes=1 YG = gatTectorDa	
ID = getVectorDe GN = getVectorDe	Audyois Function
VTH + getHumerLo GM_NAE = getVect	LANCE THE CONTRACT OF AN
Bieplay, Yth and Auto Analysis	Name: Unit; Definition:
ESD 1F	u jas War There W
END BLOCK	
	Vth = @L1X

This is an analysis function setup example. This example uses the @L1X function to get the X intercept value of the line 1.

alysis: Auto	Analysis		
	C Trop to by Auto Area		2.58
	The resp. That Sourcestan		1112122
Line 1	TTE prove proved	52	
LINE	Auto Exploy Data Deglay		
Line 2	Antevini Sutup Control Angean Companient Application Test App	and Once Test I the alterna	
	4		S Interpolation Made
Marker	Selection Inter Depts	Aber 1	A44
Warker	Conv Cat Parts	P Ender C Normal C Gradiest - # Targest C Regression	H 3
	Local Variables Defini	First Past Past Part Condition	
	BLOCH. Message		
	IF Tex=1 IdVo	P X Y Caurdrule P Duta Candition GIVI-GIVI_IVI	
	Auto Analysis Message	Aller 2	1
	IF Yes=1 VG = gatVectorDa	The I'm	- Area
	TD = getVectorDs ON = getVectorDs	- Ford Paul Charter Charter Charter	
	VTH = getHumeric GM_MAX = getVect	P X V Decidenale P Data Candition	
	Bigulay, Uth and Boto Scalasia	n n n	
	END IF	# SYCercitude # Date Confilms	
	END BLOCK		
		Marker F Dutte	
		Contract M * M F Attar M*	

The Auto Analysis statement provides the setup editor used to set up the automatic analysis function. When a measurement finishes, the function automatically draws lines, a marker, or both on the X-Y Graph of the Data Display window.

You can set up two lines and one marker for the automatic analysis function by using the setup editor.

In the Line 1 and Line 2 areas, you can set up the lines to be drawn.

In the Marker area, you can set up the marker.

The above example draws the tangent line for the Y1 data at the maximum GM point.

	1	
© 105		202
	Notice Tel Carteria Tel	
	Tracing Tests Data Degree	Interpolation
	feel Situp Cardini m (importent) Applement Teal Augus	Case Ter! Hundresse
5	Next Date Dates	Electronistics Node
- Selar		Finally Type Channel C Gadent - F Targent - C Repression
		PertPart Processing & Day Condition
81.	cal Variante Defini *	Candidans (In- H + (In-Hm) - H + Adm - H + (In-H)
	1***** Integration T IF Integrime="SHORT"	Second Part # x + Cardenate # cura Candidan Line 1 setup
	IntegHode = "HANDA AddFactor = 1	
	List IF IntegTime"M IstagNods = "FLC" AddFactor = 1	Max 2
	ELAE IF IntegTime*L IntegNode = "Fic"	e name e name e gadate e tagende en lagendes.
	Addraster = 16	Feel Pool P. S.V. Exectedes P. Exta Condition
	Integlinde - "AUTO" AdoFactor = 6	R B C B
	END IF	# x V Construits # Bala Condition Line 2 Setup
	Tab general	n <u>n</u> n <u>n</u>
	Auto Analysis D BLOCK	Marker setup
	1	Condition # * # E Afor #* #

The auto analysis capability allows you to display/move the marker/line on the data graph automatically after measurement. The above example is the Vth gmMax test definition.

To add the auto analysis operation to your test definition, open your test definition and do the procedure shown above (1 to 5). The Auto Analysis component can be added to your definition.

Interpolation Mode

Check this box to enable the interpolation mode. You can position marker between measurement points.

Line 1, Line 2

This area sets the line 1 or line 2 automatically displayed and moved to the specified position after the measurement.

Check Enable box to enable the line.

For Type, select a line type, Normal, Gradient, Tangent, or Regression.

For Axis, select the axis effective for the line.

In First Point and Second Point, specify the cursor points used to draw line.

In Gradient, specify the slope of the Gradient line.

	Interpolation	Vite parker Text Societants Text Contents Text or 12
		Tel Southstor Tel Lamens Tel of
vitana Mindar		Addis Brazily Date Date Digitie
and the second se	Const Text, Headlevens	Proper Company Approxim Ter Appres
	ale I	
-	17 Endts TigH r Nortal C Gadeet # Target C Represent III -	1 mm
	TextPaint P vir Corrients # Data (andress	and the second s
	Canaditana (2011) 🖬 1 (2011) 🖬 1 🖬 1 👘	BLOCE .
100	Second Plant # x v cavedwate # cuta cavettere Line 1 setup	IF InterTime-"DECRT"
=		AddPactor = 2
	Alter 2	IstagNoda = "PLC"
	Charles Charles Charles Charles Charles	\$158 IF InterTime"L
	Fiel Pail F 5 V Excelosite F Esta Condition	Addraster = 16
		IntegNode - "AUTO"
-		AddFactor = #
	formed Panel # 31 Y Conventions # Data Convention Line 2 setup	KND IF
	* The body of the	END IN THE PARTY OF
	# x y Coordinate # Eatle Condition LINE Z SETUP	END IF The Sector I-V Every
-	Date: Constant of Tanget of Represent III Provide Conduct of Tanget of Represent III Provide Conduct of Tanget of Represent IIII Provide Conduct of Tanget of Represent IIIII Provide Conduct of Tanget of Represent IIIIIIIIII Provide Tanget of Tanget of Represent IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Local Varies Estint * Local Varies Estint * 1***** Insequation T 1****** Insequation T 1* Reserve * Totegrime** Totegrime** LangMode * *252* AddPactor * 1***** Totegrime** Integrime** Integrime** Integrime**

Marker

This area sets the marker automatically displayed and moved to the specified position after the measurement.


Check Enable box to enable the marker.

For Condition, enter a variable name and a condition expression to specify where you want the marker to display.

For After, check this box to enable the additional condition. And enter a second variable and condition expression. This sets up a search start condition for finding specified point.

For example, you can specify the following expressions to search for a measurement point that satisfies the first condition after the second condition is satisfied.

Condition: [DGM] = [MAX(DGM)*0.01] [x] After [DGM] = [MAX(DGM)]



In the Vth gmMax test definition, the user functions and analysis functions are defined to use the auto analysis function. See the previous slide. The analysis function enables the line 1 for the Y1 data and displays the tangent line at the X-coordinate that takes the maximum gm value.

The following user function is used to calculate the gm value.

Gm = diff(Idrain, Vgate)

The following user function is used to get the maximum gm value.

gmMax = max(gm)

The following analysis function is used to get the Von value. The readout function @L1X gives the X intercept value of the line 1.

Von = @L1X

The following analysis function is used to calculate the Vth value.

 $Vth = Von - (Vd^*Polarity/2)$

Where, Polarity is -1 for P-ch MOSFET or 1 for N-ch MOSFET.


	L In Mail
	- / 1 8
Tet Grad	
Test Angelas Gener Test Hereinenen	
Dutts Salag Name Backs, VO and Targer Line	-
Turk K.Y.Graph	
Add Development	(married
	- 8
r vi. (10	- 8
u AS [m. ∃[mm. ∃]k ≣[mm	
arDa	
ortin Met Display Parameters	
	(Trans
	and an analysis of the second

The test setup performs measurement and displays the test result as defined in the channel setup, measurement setup, and display setup. And the test result data will be stored to the test record.


In addition to the default test result display, you can make additional data display by using the Display Data Setup statement. The statement provides the user interface as same as the Display Setup of the Classic Test or the Test Output of the test definition. The above example displays the ID-VG/GM-VG curves, GM_MAX and VTH values, and tangent line by using the extra Data Display and Auto Analysis function. See next slide.

Note:

The additional display data cannot be saved to the data record. However only the last display data can be saved if the Test Output is not defined in the test definition.



This is a test result example displayed on the Data Display window.



By the default setting, the results of the tests defined in your test definition are displayed on the Data Display window and are stored to the data record.


You can control the data display of the tests by using the Data Display Control statement. Insert the statement, and remove the check from the Enable Data Display box to disable the data display.


You can control the data storage of the tests by using the Data Store Control statement. Insert the statement, and remove the check from the Enable Creating Test Result Record box to disable the data storage.

This function is not available for the following data. The data output is always enabled.

·Data output set to the Test Output of the test definition

•Data output of the last test setup if the Test Output is not set






To use the classic test mode, click the Classic Test tab. And select the execution mode. The following modes are available.

•I/V Sweep: For X-Y characteristics measurement of I or V.


•I/V-t Sampling: For time-Y characteristics measurement of I or V.

•C-V Sweep: For DC bias-impedance characteristics measurement.

•Switching Matrix Control: For B2200 switching matrix control.



This section explains how to perform I/V sweep measurement. You will perform the above tasks to execute the I/V sweep measurement.



Click the I/V Sweep icon and open the setup editor. Then click the Channel Definition tab to display the channel definition screen.

•Enter the Setup Name for the test setup to be defined on the setup editor.

•List SMUs used for source output or measurement, and set the following parameters.

•Unit: SMU name or number


•V Name: Variable name for the voltage measurement or source data

•I Name: Variable name for the current measurement or source data

•Mode: Source output mode, V (voltage), I (current), VPULSE (voltage pulse), IPULSE (current pulse), or COMMON (ground)

•Function: Source output function, VAR1 (primary sweep), VAR2 (secondary sweep), VAR1' (synchronous sweep), CONST (constant)


V Name and I Name are used to specify the parameters displayed on the Data Display window. The display parameters are selected on the Display Setup tab screen.



You can read measurement data by using the Data Display window. Parameters displayed on the window are selected on the Display Setup tab screen. If you enter the variable name in the V Name, I Name, Time Stamp Name, and/or Index Name entry fields, you can choose the variables as the display parameters.

•The time stamp is the time the measurement is started for each measurement point.


•The index is the index number for each measurement data.



The Measurement Setup tab screen is used to set the source output value and timing parameters.


At the VAR1 area, you set the primary sweep source output.

- •Unit: SMU name or number
- •Name: Variable name of source output
- •Direction: Single (start to stop) or Double (start to stop to start)
- •Linear/Log: Linear sweep or Log sweep
- •Start: Source output start value
- •Stop: Source output stop value
- •Step: Source output incremental step value
- •No of Step: Number of sweep steps
- •Compliance: SMU compliance value
- •Pwr Comp: SMU power compliance value



At the VAR2 area, you set the secondary sweep source output.

- •Unit: SMU name or number
- •Name: Variable name of source output
- •Start: Source output start value
- •Stop: Source output stop value
- •Step: Source output incremental step value
- •No of Step: Number of sweep steps
- •Compliance: SMU compliance value
- •Pwr Comp: SMU power compliance value




At the VAR1' area, you set the synchronous sweep source output.

- •Unit: SMU name or number
- •Name: Variable name of source output
- •Offset: B value of the above formula.
- •Ratio: A value of the above formula.
- •Compliance: SMU compliance value
- •Pwr Comp: SMU power compliance value

The VAR1' output is expressed by the following formula.

VAR1' output = A \times (VAR1 output) + B



At the SMU Pulse area, you set the SMU pulse timing parameter and the pulse base value.

•Unit: SMU name or number

•Period: Pulse period

•Width: Pulse width

•Base: Pulse base value

Only a SMU can be set to the pulse source.

A easu	rement Setu	nb				Ċ
a Sen June re	Carnel brian Pressentent Set		en Treplane	-	Q	I/V-t Sampling
XY.Suma	VARS NAME	VAR2	WARL ¹	Court: 0	* (a)(a)	
10	wit Second	m 2010.0.00 m	Unit: Units in	Device ID:	Contraction of the local division of the loc	
114	Name: 10		Rame: 11.0 m	lect)	- Photos	C-V Sweep
Sampling	Oirection: Tryin	2	omet 💷 📕	The Party Party of the Party of	ettag+	e i oncep
	timear/long: Ltd.A.	2	Natio: 1	Variat The Ball	0	
CV Sveep	stare (r y	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		and a second sec		
	570gt [1.000 V	# 2.0000 V		30		
	stage: 00 m		and the second s	1 III		
	No of Step: 31 Compliance: 20.001 ma	10 P	Period 11.1 co	* vergentes).		
	Pair Compt 201	N 2010	With Line B	100		
	Timing	AP* 4	Base: DV B	4	-	
		Delay: [1]	Carlot State State State and and Area Area and	- Minds		
	Constants	construction (all	* Bererp Continue at Ann .	etatus an an		
	that V Name	I Name Mr	de Source Compliant	and and the second		
	SURVEHM milling	10 10	MINY MILITERE			
				LV Sweep nu		
					(w)	
Plag S		Date	Count Device ID	Renarka	(5)	
0 1	ing v62	8/15/2005-4:03:30			10	
ä	18 V8 18 V8	8/15/2005 4:03:30 8/15/2005 4:03:29			-	
0	V0_grimax	8/15/2005 4:03:17	PM 2			
	ing vth2 Vth_gmmas	8/15/2005 4:03:03 8/15/2005 4:02:51			- 11	
0	ing vth2	8/15/2005 3:01:14				

At the Constants area, you set the SMU constant output.

•Unit: SMU name or number


•V Name: Variable name for the voltage measurement or source data

•I Name: Variable name for the current measurement or source data

•Mode: Source output mode, V (voltage), I (current), VPULSE (voltage pulse), IPULSE (current pulse), or COMMON (ground)

•Source: SMU output value

•Compliance: SMU compliance value



At the Timing area, you set the source output and measurement timing.

•Hold: Source output hold time. Time after the measurement trigger until starting delay time.

•Delay: Measurement start delay time. Time after the hold time until starting measurement.

When a SMU forces pulse, the delay time is ignored. Source output and measurement timing will be controlled by the pulse width and pulse period.

C-V Sweep
C-V Sweep
C-V Sweep
C-V Sweep
C-V Sweep
CONTINUE AT ANY
STOP AT ANY ABNOR
-Range overflow
-
-SMU compliance
-SMU oscillation

This field sets the sweep abort function.

When this field is CONTINUE AT ANY, the sweep measurement is not aborted.

When this field is STOP AT ANY ABNORMAL, the sweep measurement will be aborted when one of the following conditions is detected.

•Measurement range overflow

•SMU compliance

•SMU oscillation

Pik Deb Dallar P	irement Set	~P				UV-t
2 4	() 1/V Sweep	Setup Name		1	0	Sampling
S LY Sured	Carol Letas Helevenert 5		tup	Comet (0	1 000	
10	we become		Unit: MANNE	Farge	Contraction of the local division of the loc	
3 114	Name: 11	10 11	Name: 10.0 g		T Plantalli	Not available when
Sarying	Orestine: Topic	2	offsets 11 -	incommunity and in the local division of the local dintere division of the local division of the local divisio	-	
- B	timesr/log: Lbill.M.	2	Rade: 1	Variout	R.	a pulse source is use
CV Sweep	Still Range Setup					
	Measurement Range			10 Yet	1.00	
				E 101		
	Unit: Name	c Hole: Range:	Range Change Rule: Kale	in the second se		
	L DATES B		ET PAL NYSE	1 14		
	 (14)(244. m)(2 (24)(244. m)(3) 		BY R.G. BANKE	- i - ii		
	r buise whe		TRY ALL LINES			
	Provide These		AND CONTRACTOR OF THE	A South Street	· · · · · · · · · · · · · · · · · · ·	
				Ting Javid		
				125	1	
	-	Class		Tra		
	1			Sampleg		
	Setup Name Timo Id-Vd	Dife 8/15/2005 7:37:43 PE	Count Device ID	Remarka	-9	
	Ting Id-Vd	8/15/2005 7:36:24 99			121	
10	Ting vth2	8/15/2005 4:03:30 79	2		1.0	
	Timg vth2 Timg vth2	8/15/2005 4:03:03 Ph 8/15/2005 3:01:14 Ph			_	
0	Timg vth2	#/15/2005 2:53:11 Ph	1		_	
	Timg vth2	8/15/2005 2:33:30 PB				

The Range button opens the SMU Range Setup dialog box. The dialog box is used to set the measurement ranging mode. This button is not available when a pulse source is used.

•Unit: SMU name or number

•Name: Variable name for the measurement data

•Mode: Ranging mode, AUTO, LIMITED, or FIXED

•Range: Range value

•Range Change Rule: BY FULL RANGE, GO UP AHEAD, or UP AND DOWN AHEAD

•Rate: Value used for range changing. See the following formula.

For the AUTO or LIMITED, SMU automatically selects the minimum range that covers the measurement value, and performs the measurement by using the range. For the limited auto ranging, the instrument does not use the range lower than the specified range value. For example, if you select the 100 nA limited auto ranging, the instrument never uses the 10 nA range and below.

BY FULL RANGE performs normal auto ranging operation.

For the GO UP AHEAD and UP AND DOWN AHEAD rules, specify the *Rate* value, 11 to 100, which fixes the boundary of the ranging. The ranging occurs when the measurement data goes across the *boundary* values shown below.

go up boundary = present measurement range \times Rate / 100

go down boundary = present measurement range \times Rate / 1000

The go down boundary is available only for the UP AND DOWN AHEAD rule.

Pik Into Jam	surement Setup	I/V-t
No No	Connel Educe Television State (Trag Hole Educe)	Sampling
Ever and Every a	Likewar / Long 1362.44 N Redic: 0 400 Water: 10 400 100 400 100	Not available when a pulse source is use
	Name Name Colspan="2" Name Colspan="2" Setup Name Colspan="2" Time 164-V6 Colspan="2" Colspan="2" Time 164-V6 Colspan="2" Colspan="2" Colspan="2" Colspan="2" Colspan="2" Colspan="2" Colspan="2"	

The ADC/Integ button opens the A/D Converter & Integration Time Setup dialog box. The dialog box is used to select the ADC for each SMU and set the integration time for each ADC (high resolution or high speed). This button is not available when a pulse source is used.

A/D Converter:

•Unit: SMU name or number

•Name: Variable name of the measurement data

•ADC: ADC type, HR ADC (high resolution) or HS ADC (high speed)

Integration Time:

•Mode: AUTO, MANUAL, or PLC. Rule to decide the integration time. For details, see online help or User's Guide.

•Factor: Coefficient for the reference value of the integration time.

•Auto Zero: Auto Zero function ON or OFF. For HR ADC.

leasu	irement <mark>Set</mark> up	Ÿ
Ten Turne In	Senag Rases: [Trop line Council Info: Processing Rases: [Trop line Council Info: Procesing Rases: [Trop line Council Info: Processing Rases: [Trop li	I/V-t Sampling
Dive Sarying	VALUE VALUE <th< th=""><th></th></th<>	
CH Sweet	Afreen of Satury Channel Bettings	
	Vinit: VRame: Solicis R; 6400 Filter; DALL: 0* mil/0* mil/0* 2 01 2 DALL: 0* mil/0* mil/0* 2 01 2 DALL: 0* mil/0* mil/0* 2 01 2 DALL: 0* mil/0* mil/0* 0 1 1 Solution mil/0* 0 1 1 1 Solution mil/0* 0 1 1 1 Solution mil/0* 0 1 1 1	
	Wait Take Control	
	Tartier 5 2 2 Company Wate 1 2 Company Wate 1 2 Company Wate 1 2 Company Wate 1 2 Company and 2 Comp	
	0	

The Advanced button opens the Advanced Setup dialog box. The dialog box is used to set the SMU filter and SMU series resistor settings, and set the wait time.

Channel Settings:

•Unit: SMU name or number

•V Name: Variable name for the voltage measurement or source data

•I Name: Variable name for the current measurement or source data

•Series R: SMU series resistor NONE or 1MOHM (1000000 ohm)

•SMU Filter: SMU filter ON or OFF

Wait Time Control:

•Factor: Coefficient for the reference value of the wait time. For details, see online help or User's Guide.

After Measurement Settings:

•Bias Hold after Measurement: Bias hold function ON or OFF.

•Output Value after Measurement: Source output value after measurement. START (sweep start value), STOP (sweep stop value), SOURCE (sampling output source value), or BASE (sampling output base value)

Function Se	un						IV Sweep
	Display Help O and Drug Present Set User Function **** **** **** **** Date -Me	en version has a series of the	a/source da	ta	Const. () Device III Performente IIII IIII IIII IIII Vito patitas Vito patitas	Car Car Car Car Car Car Car	IV-t Sampling C-V Sweep
	g Setup Name Ting Sampling Ting Id-Vd Vth gmMax Vth gmMax Ting Id-d Idvg2 Ting Id-d Idvg2	Date 4/11/2006 6:30:59 PH 4/11/2006 5:27:34 PH 4/7/2006 12:49:35 PH 4/7/2006 12:49:35 PH 3/31/2006 9:21:40 PH 3/31/2006 9:19:56 PH	Count Device ID	Remarks		I	

Click the Function Setup tab to display the User Function/Analysis Function setup screen. The user functions can be displayed on the X-Y Graph Plot, List Display, and Parameters area of the Data Display window. Up to 20 functions can be set.

Name: Function name

Unit: Unit of the function

Definition: Definition of the function. The following identifiers can be used.

-Variables for the measurement/output data used in this test

-Functions defined in the above lines

-Local variables passed from the application test that calls this test as a component -Built-in functions and global variables

For details, see online help or User's Guide.

Note:

The Apply button performs calculation of the definition in this screen. If this button is clicked when the Data Display window associated with this test has been opened, the display is also updated. The associated Data Display window will be the Data Display window that displays the last measurement data or that is recalled at last.

unction Setup		(P)
The Data Disp	ay Telep Dinfo Seecep Comel Setup (Nessurement Setup (Nessure Setup (Davies	I/V-t Sampling
Conc for Apr	Uber Farches	C-V Sweep
N COL		
Switching Mattie	Analysis true the	
	Name voic publicities and the state of the s	•
	Data calculation -Measurement data/source data	•7
	-Read out function -Built-in function, etc.	-
Tr Tr	Name Date Count Device ID Remarks A ng Gangling 4(11/2006 5:20:59 FM 11 1	
4 Vt	n gmMax 4/7/2006 12:49:05 PM 3 n gmMax 4/7/2006 12:45:09 PM 1	

The analysis functions can be displayed on the Parameters area of the Data Display window. Up to 20 functions can be set.

Name: Function name

Unit: Unit of the function

Definition: Definition of the function. The following identifiers can be used.

-Variables for the measurement/output data used in this test

-Functions defined in the above lines

-Local variables passed from the application test that calls this test as a component


-Built-in functions and global variables

-Read out functions

For details, see online help or User's Guide.

Note:

The Apply button performs calculation of the definition in this screen. If this button is clicked when the Data Display window associated with this test has been opened, the display is also updated. The associated Data Display window will be the Data Display window that displays the last measurement data or that is recalled at last.



Click the Auto Analysis Setup tab to display the auto analysis setup screen. The auto analysis capability allows you to display/move the marker/line on the data graph automatically after measurement. The above example displays marker at Vd=1 V point and draw a tangent line for this point.

Interpolation Mode: Check this box to enable the interpolation mode. You can position marker between measurement points.

Line 1, Line 2: This area sets the line 1 or line 2 automatically displayed and moved to the specified position after the measurement. Check Enable box to enable the line.

For Type, select a line type, Normal, Gradient, Tangent, or Regression.

For Axis, select the axis effective for the line.

In First Point and Second Point, specify the cursor points used to draw line.

In Gradient, specify the slope of the Gradient line.

Marker: This area sets the marker automatically displayed and moved to the specified position after the measurement. Check Enable box to enable the marker.

For Condition, enter a variable name and a condition expression to specify where you want the marker to display.

For After, check this box to enable the additional condition. And enter a second variable and condition expression. This sets up a search start condition for finding specified point.

For example, you can specify the following expressions to search for a measurement point that satisfies the first condition after the second condition is satisfied.

Condition: [DGM] = [MAX(DGM)*0.01] [x] After [DGM] = [MAX(DGM)]

Note:

The Apply button performs calculation of the definition in this screen. If this button is clicked when the Data Display window associated with this test has been opened, the display is also updated. The associated Data Display window will be the Data Display window that displays the last measurement data or that is recalled at last.

splay Setup	lay July	1/V-t
5 IV Second	Selay Name: 11-2 11-2 Selay Name: 11-2 11-2 Selay Name: 11-2 11-2 Selay Name: 11-2 11-2 Selay Name: 11-2 Selay Name: 11-2 Selay Name: 11-2 Selay Name: 11-2	Sampling
A construction to the same line sam	Name:	C-V Sweep
	List Singlay Parameters -	
	Add Add Image: Second	
Reg St	top Name Date Count Device ID Remarks A sold Vid 4/11/2006 5/27/34 PM B	


Click the Display Setup tab to display the display setup screen. The X-Y Graph area is used to set the X axis and Y axis of the X-Y Graph Plot area in the Data Display window.

•Name: Name of variable to plot on the X axis


•Scale: Linear or Log

•Min: Minimum value of the specified axis

•Max: Maximum value of the specified axis



The List Display area selects the variables to be listed in the List Display area of the Data Display window. Up to 20 variables can be set.



The Parameters area selects the variables to be listed in the Parameters area of the Data Display window. Up to 20 parameters can be set.

The Data Disp	day Help Option Second	U/V-t
0	Nor Graph Name: Scale: Misc Mac P X: PT X Prop. X PT N PT N P Sector Disc.	Sampling
	* VL [1 K] A40 X [1 K] [1 K] [1 K] [1 K] * VL [1 K] [1 K] [1 K] [1 K] [1 K] [1 K] [1 K] [1 K] [1 K] * VL [40, 0] [1 K] [1 K] [1 K] [1 K]	C-V Sweep
Surfictions Matter		My Favorite Setup
	Isis Exception Parameters With parking C FP Mith FP FP C FP FP FP FP	Preset Group name Use this field to select preset group
	Hame Date Count Device ID Remarks A Interpretation 4111/2006 5127:34 594 8 4	

The test setups you create MUST be saved to the internal hard disk drive as "My Favorite Setup". To save the setup, click the Save button.

To recall the setup, click the Recall button.

You can organize the setups by using Preset Group. In the above example, the Demo group is selected and listed in the "My Favorite Setup".

To create a new preset group, click the My Favorite Setup button to display the function menu, and select Add New Preset Group.


To select the available preset group, use the field below the My Favorite Setup button.




You can export/import your preset group.

To export the present preset group, click the My Favorite Setup button, select Export, and specify the folder and the name of the preset group to export.


To import the preset group, click the My Favorite Setup button, select Import, and specify the preset group to import.




Note:



This is a test result example displayed on the Data Display window.



This section explains how to perform I/V-t sampling measurement. You will perform the above tasks to execute the I/V-t sampling measurement.



Click the I/V-t Sampling icon and open the setup editor. Then click the Channel Definition tab to display the channel definition screen.

•Enter the Setup Name for the test setup to be defined on the setup editor.

·List SMUs used for source output or measurement, and set the following parameters.


•Unit: SMU name or number

- •V Name: Variable name for the voltage measurement or source data
- ·I Name: Variable name for the current measurement or source data
- •Mode: Source output mode, V (voltage), I (current), or COMMON (ground)
- •Time Stamp Name: Variable name for the time stamp data
- •Index Name: Variable name for the data index

You can read measurement data by using the Data Display window. Parameters displayed on the window are selected on the Display Setup tab screen. If you enter the variable name in the V Name, I Name, Time Stamp Name, and/or Index Name entry fields, you can choose the variables as the display parameters.

•The time stamp is the time the measurement is started for each measurement point.

•The index is the index number for each measurement data.



Click the Measurement Setup tab to display the setup screen for the sampling timing parameters and the SMU source output parameters. At the Sampling Parameter area, you set the following sampling timing parameters.

Linear/Log:

Sampling mode. LINEAR for linear sampling. LOG10, LOG25, LOG50, LOG100, LOG250, or LOG500 for logarithmic sampling. For the logarithmic sampling, the number after LOG indicates the number of measurement data in a decade. For example, LOG10 mode is used to get 10 data/decade.

For the log sampling, the B1500A holds only the data that can be plotted on the log scale in the same distance as close as possible. Only the held data is counted in the number of measurement result data.


For the linear sampling with Interval < 2 ms, if the total measurement time runs over the specified time Interval \times No of Samples, the sampling measurement will be stopped even if the number of measurement result data is less than the specified No of Samples.

Interval:

Interval of the sampling, in seconds. 0.002 to 65.535 s, 0.001 s resolution.

Interval < 0.002 s in 0.00001 s resolution is also available for the linear sampling. It must satisfy the following formula. For details, see online help or User's Guide.

Interval \geq 0.0001 + 0.00002 $\,\times\,$ (number of measurement channels-1)



No of Samples:

Number of samples. Integer. 1 to the following value.

For linear: 100001 / (number of measurement channels)

For logarithmic: 1 + (number of data for 11 decades)

Total Sampling Time:

This field just displays the total sampling time that is the time from the measurement start time for the first point to the end of sampling measurement. It does not include the hold time.

Total Sampling Time = Interval \times No of Samples

Output Sequence:

Source output sequence. SIMULTANEOUS or SEQUENTIAL.

Hold Time:

Time since the Source value output until the first sampling point, in seconds. 0 to 655.35 s, resolution 0.01 s.

The following values are also available for Interval < 0.002 s. |Hold Time| will be the time since the sampling start until the Source value output.

-0.09 to -0.0001 s, resolution 0.0001 s.

Base Hold Time:

Hold time of the Base value output until the Source value output, in seconds. 0 to 655.35 s, resolution 0.01 s.

Ap //Y 1 Stampins of Jepp Teamwork Talaci Jepp Teamwork Talaci Jepp Teamwork Linear/Gog: J.F.C.M. Interval [27 = No of Samples: [24] rid Samples Time: [25] Output Segments [25]	Soling Name: [Trig tarang care bene] Ann waves bene] (Deck tenue) 2] 8] 8] 8] 9]	Fainger ADC / ADC / ADS / ADS / Period III:	9	I/V-t Sampling C-V Sweep
Hold Time: 100 Rane Hold Time: 2 + Hanks V Name: 110	a B	Compfance:	• •	C V Sweep
SMU (Constant output setup	Un pola Un pola Un pola	×	
· · · · · · · · · · · · · · · · · · ·	antianta att V Numei 11 Att att Normalia Att att Normalia SIMU (Att att att att att att att att att att	Image: Second	All and V Research Model Research Resea	All and V Name(Na

At the Constants area, you set the SMU constant output.

•Unit: SMU name or number

•V Name: Variable name for the voltage measurement or source data

•I Name: Variable name for the current measurement or source data

•Mode: Source output mode, V (voltage), I (current), or COMMON (ground)

•Base and Source: SMU output value


•Compliance: SMU compliance value

Base value is available for all output channels for the SIMULTANEOUS mode and the last source channel for the SEQUENTIAL mode.

	urement Setup	(tr.
		I/V-t
lie Duta Di	O[1/V I Samphin Selag Name: Trig Let unit #	Sampling
AV Suppl	Channel Serce These ensemt Serce Function Serce Function Serce Functional Ser Serce Functional Serce Funcing Serce Functional Serce Functiona	
	Seepling Parameter	
() IPH	Linearities (2007 - Bevice - B	
Sampling	No of Samples: [11]	
CYlese	Total Grandma Daw Di B	
	Stillings Step	
1	11/2	
	The local sectors and the sect	
Subday Matrix	Vinit: Name: Mode: Famps: Kamp: Clamps Falls: Falls:	
	Verilie Name: Mode: Kange: Kange Change Chan	
	Vinit: Name: Mode: Famps: Kamp: Clamps Falls: Falls:	
	Veilie Name: Mode: Kange Nange Change Rade: Note: PortEHM Will Brand Port Port Port Port Port Port Port Port	
	Venit: Narm: Mode: Kange Range Change fade: Kate: P (2015)98 a) (2 10 2 10 10 10 10 10 10 10 10 10 10 10 10 10	
	Veilie Name: Mode: Kange Nange Change Rade: Note: PortEHM Will Brand Port Port Port Port Port Port Port Port	
	Venic Name Hole. Kange Range Change Inde. Note: Unit of the Provide State of the Provide Stat	
Rag	Visit Name Mode Kange Kange Kange Kange [Introlline] Introlline] Introlline] Introlline] Introlline] Fixed range mode Introlline] Chute Count Device 10	
Here	Vinit Name Mode Kange Kange Change falle Note: If Instantion Instantinstantinsteantion Instantion	
Matrix	Visit Name Node: Name (Introl intelling) (Intelling) (Intelling) (Intelling) Fixed range mode (Intelling) Class (Intelling) Class (Count) Count Device 1D Remarka (Intelling)	

The Range button opens the SMU Range Setup dialog box. For details of the dialog box, see page 5-13.

If the range changing occurs during measurement, the SMU may not complete measurement within the sampling interval. So use FIXED range if the sampling interval is top priority and the resolution/sensitivity is second priority.



Click the Function Setup tab to display the User Function/Analysis Function setup screen.

The user functions can be displayed on the X-Y Graph Plot, List Display, and Parameters area of the Data Display window. Up to 20 functions can be set.

•Name: Function name

•Unit: Unit of the function

•Definition: Definition of the function. The following identifiers can be used.

•Variables for the measurement/output data used in this test

•Functions defined in the above lines

·Local variables passed from the application test that calls this test as a component

•Built-in functions and global variables

For details, see online help or User's Guide.

The analysis functions can be displayed on the Parameters area of the Data Display window. Up to 20 functions can be set.

Name: Function name

•Unit: Unit of the function

•Definition: Definition of the function. The following identifiers can be used.

·Variables for the measurement/output data used in this test


•Functions defined in the above lines

·Local variables passed from the application test that calls this test as a component

•Built-in functions and global variables

•Read out functions

For details, see online help or User's Guide.



Click the Display Setup tab to display the display setup screen. The X-Y Graph area is used to set the X axis and Y axis of the X-Y Graph Plot area in the Data Display window.

•Name: Name of variable to plot on the X axis


•Scale: Linear or Log

•Min: Minimum value of the specified axis


•Max: Maximum value of the specified axis

The List Display area selects the variables to be listed in the List Display area of the Data Display window. Up to 20 variables can be set.


The Parameters area selects the variables to be listed in the Parameters area of the Data Display window. Up to 20 parameters can be set.




Note:



This is a test result example displayed on the Data Display window.



This section explains how to perform C-V sweep measurement. You will perform the above tasks to execute the C-V sweep measurement.



Click the C-V Sweep icon and open the setup editor. Then click the Channel Definition tab to display the channel definition screen.

•Enter the Setup Name for the test setup to be defined on the setup editor.

•List units used for source output or measurement, and set the following parameters.


•Unit: MFCMU/SMU name or number

- •V Name: Variable name for the voltage measurement or source data
- ·I Name: Variable name for the current measurement or source data
- •Mode: Source output mode, V (voltage), I (current), or COMMON (ground)
- •Time Stamp Name: Variable name for the time stamp data
- •Index Name: Variable name for the data index

You can read measurement data by using the Data Display window. Parameters displayed on the window are selected on the Display Setup tab screen. If you enter the variable name in the V Name, I Name, Time Stamp Name, and/or Index Name entry fields, you can choose the variables as the display parameters.

•The time stamp is the time the measurement is started for each measurement point.

•The index is the index number for each measurement data.



The Measurement Setup tab screen is used to set the source output and timing parameters.

At the C-V area, you set the DC bias output of the MFCMU.

•V Name: Variable name of the MFCMU output

•Model: MFCMU measurement mode. Primary and secondary measurement parameters. Select one from the following four models.

•Cp-G: Parallel capacitance (F) and Conductance (S)

•Cp-D: Parallel capacitance (F) and Dissipation factor

•Cs-Rs: Series capacitance (F) and Series resistance (onµ)

•Z-Th: Impedance ($o\eta\mu$) and Phase (degree)

•C/Z Name: Variable name of the primary measurement parameter, C or Z

•G/D/R/Th Name: Variable name of the secondary measurement parameter, G, D, R, or Th

•Direction: Sweep direction, single (start to stop) or double (start to stop to start)

•Start: Source output start value

·Stop: Source output stop value

•Step: Source output incremental step value

•No of Step: Number of sweep steps


vieasu	rement Set	tup						
(4) The Dataset - Yel way of the Dataset -	C V Senser Owned land Mathematics C V Mathematics C V News K Mathematics Field K Mathematics Field C Name Fig S Raines Fig S Raines Fig Singer Table 1 Singer Table 1 Nonger Fill 1 Nonger Fill 1 Nonger Fill 1 Nonger Fill 1	E Color Field Field	H Ram H Ram H Leve Ta teory (1)	the first of the f		Try Harden State Try Harden S		
	tup Name ng CV ng CV	Dete 8/17/2005 12:43:32 PM 8/17/2005 12:42:53 PM		Device ID	Renarka	-	19	
	ng CV ng CV ng CV	8/17/2005 12:41:58 PH 8/17/2005 12:40:35 PM 8/17/2005 12:40:35 PM 8/17/2005 12:29:31 PM	18 17					

At the Signal Source area, you set the MFCMU output frequency and oscillator level.

•Frequency List: MFCMU output frequency

•F Name: Variable name of MFCMU output frequency

•AC Level: MFCMU oscillator level, 10 mV to 250 mV, 1 mV resolution



At the Integration Time area, you set the integration time of the impedance measurement by the MFCMU.

•Mode: AUTO or PLC. Rule to decide the integration time. For details, see online help or User's Guide.

•Factor: Coefficient for the reference value of the integration time.

At the Timing area, you set the source output and measurement timing.

•Hold: Source output hold time. Time after the measurement trigger until starting delay time.

•Delay: Measurement start delay time. Time after the hold time until starting measurement.

The Sweep [] status field sets the sweep abort function.

When this field is CONTINUE AT ANY, the sweep measurement is not aborted.

When this field is STOP AT ANY ABNORMAL, the sweep measurement will be aborted when one of the following conditions is detected.

•Measurement range overflow

•MFCMU error

•SMU compliance

•SMU oscillation

Neasu	rement <mark>Se</mark> tup	Ö
a ten funo re	CV Severe Links Force Setup Severe Track	I/V-t Sampling
	V Name: Try Trippancy List: Add States and S	C-V Sweep
	Barge [10.00 / B] Bergeration Time B Factors [2 B Control (100 / B) Control (100 / B) <t< th=""><th></th></t<>	
	Conte V Name: I Name: Mode: Bource: Compliance: These are no forms to deploy to this area. SMU output setup	
	buth Date Count. Device ID Remarka 1 mg CV 6(17/2005 12-43) 20 HP 30 9	
	mg CV m(1/2003 tr 2/2/3149 16 mg CV n(1/2/003 tr 2/2/2/3149 16 mg CV 6(1/2/005 tr 2/2/60 244 15 mg CV 6(1/2/005 tr 2/2/6 54 14	

At the Constants area, you set the SMU constant output.

•Unit: SMU name or number


•V Name: Variable name for the voltage measurement or source data

•I Name: Variable name for the current measurement or source data

•Mode: Source output mode, V (voltage), I (current), or COMMON (ground)

•Source: SMU output value

•Compliance: SMU compliance value



Click the Function Setup tab to display the User Function/Analysis Function setup screen.

The user functions can be displayed on the X-Y Graph Plot, List Display, and Parameters area of the Data Display window. Up to 20 functions can be set.

•Name: Function name

•Unit: Unit of the function

•Definition: Definition of the function. The following identifiers can be used.

·Variables for the measurement/output data used in this test

•Functions defined in the above lines

·Local variables passed from the application test that calls this test as a component

•Built-in functions and global variables

For details, see online help or User's Guide.

The analysis functions can be displayed on the Parameters area of the Data Display window. Up to 20 functions can be set.

•Name: Function name

•Unit: Unit of the function

•Definition: Definition of the function. The following identifiers can be used.

•Variables for the measurement/output data used in this test


•Functions defined in the above lines

·Local variables passed from the application test that calls this test as a component

•Built-in functions and global variables

•Read out functions

For details, see online help or User's Guide.



Click the Display Setup tab to display the display setup screen. The X-Y Graph area is used to set the X axis and Y axis of the X-Y Graph Plot area in the Data Display window.

•Name: Name of variable to plot on the X axis

•Scale: Linear or Log

•Min: Minimum value of the specified axis

•Max: Maximum value of the specified axis

The List Display area selects the variables to be listed in the List Display area of the Data Display window. Up to 20 variables can be set.

The Parameters area selects the variables to be listed in the Parameters area of the Data Display window. Up to 20 parameters can be set.

egencies by range gencies by	echan resum	Boreline * One factory specified frequencies (Default) Open factores Produces * specify for a calibration frequencies (Default) Open factores Produces * specify for a calibration frequencies (Default) Open factores Produces * specify for a calibration frequencies (Default) Open factores Produces * specify for a calibration frequencies (Default) Open factores Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration frequencies (Default) Node Produces * specify for a calibration for a calibration for a calibration for a calibrat
and a state of a state	20 minute * Specify frequencies by range advance * Specify frequencies by range advance * Specify frequencies by range miller Masket Minute Masket Minute Masket Minute Masket Minute Masket	Bordian * Specify first of califications frequencies Model 10-10 W Open Correction Model 10-10 Specify frequencies by range W Short Correction Model 10-10 Water Model 10-10 Model 10-10 Model 10-10 Water Model 10-10 Model 10-10 Model 10-10 Model
Capacitance (17) Canditance (17)	Adverse Advers	Advanced P Load Correction Maximum P Spon Correction Maximum P Spon Correction Maximum P Spon Correction Maximum P Spon Correction Maximum P Load Correction Maximum
Capacitance	Advance- Material Material Advance- Advance- Material Material Advance- Material Material Advance- Material Material Materia	Bardian Pages Rance (17) Bardian Pages Rance (17) Pages Rance (17) Pages Ran
stort tudarence manifes by range in the store of the stor	Adverses advers	Nordar Using Control of C
apprendes by range State I Technologies by range State I Tec	Adverses	Microsome Second Colorence Second Colorence Machine Microsome Machine Second Colorence Machine Microsome Machine Second Colorence Machine Microsome Machine Machine Machine Machine Machine Machine Machine
ngaandes by range Inductance (7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ection Peacers Peace	Short Career, Short Masters. Second
agametes by range Benindance (7 400 1) Benindance (7 400 1) Beni	ection means * Specify frequencies by range Karb Map Head for any	9 Open Correction Material Party frequencies to range Material 9 Short Correction Material State Material 9 Short Correction Material State Material 9 Short Correction Material Material Material 11 Long Correction Material Material Material 12 Long Correction Material Material Material 12 Long Correction Material Material Material
B State III	nthen Name. Adjected	P Sout Correction Materia South Correction South Correcti
Base Base Base Base Base Base Base Base	nthen Praises.	P. Short Correction Materia State Materia Materia P. Losd Correction Masses Materia Materia Materia P. Losd Correction Masses Materia Materia Materia
I scale I I I I I I I I I I I I I I I I I I I	etten Prazer	P Short Correction Materia Ma
	The Note of the State of the St	F Lord Correction Insure: Ins
Resistance Grann	riter Nearen Atlantic	tool Correction Heasen Advance Advanc
	vites Nexus. Matrix	F tool Correction Brance. Adviced Optime. 26 Canal
PLC Hode Factor: [13]	Abient	Association of Carol
DK David		
		9 Photo Supported to a second se
		Advanced Ontions
and Ontions	Advanced Options	Auvanced Options
nced Options	Advanced Options	
-1		Advanced Options

The MFCMU is equipped with the error correction function used to realize accurate impedance measurements. The correction function minimizes the effects of the error elements in the extension cables and the DUT interface such as manipulator and probe card.

•Phase compensation: Corrects phase error caused by extending measurement cables.

•Open correction: Corrects for stray admittance. Effective for high impedance measurements.

•Short correction: Corrects for residual impedance. Effective for low impedance measurements.

•Load correction: Corrects any error by using the working standard (load standard).

Click the Calibration button to open the Calibration window. And click the CMU calibration tab on the window to perform the compensation and correction data measurement.


•To measure the phase compensation data, open the measurement terminals at the end of the device side and click the Measure... button.

•To measure the open correction data, open the measurement terminals at the end of the device side and click the Measure... button.


•To measure the short correction data, connect the measurement terminals together at the end of the device side and click the Measure... button.

•To measure the load correction data, connect the load standard that has the reference value or calibration value. Then, click the Measure... button.

For details of the error correction (CMU calibration) and the Advanced Options, see online help or User's Guide. The Advanced Options window is used for the compensation/correction data measurement setup.



Note:



This is a test result example displayed on the Data Display window.



This section explains how to define the switch setup for B2200 Switching Matrix.

File Data Disc	ilay Help			Setu	p Nan	ne				
AL	🙆 Switching Matrix	Control	Setup Ham	e en pe				F Com		1.17
and and a state	Connection Operation: In	ne out	outs:	AN	Delet	el 110e	Open	Court	0	1991
0	P Open Al 💌	-	H	н		н	1	Device 1	ID:	
	C Settle Setur 200	and a second	10 P	(H)	H	H [10+		Hallen	atta Belape	
-	Cane tange Main		10			a een		Care .		-
E Corsoner	Oper Output	- 1		AD .	91- 8	1 1000	1	» *		
	C Open Dout . 19		1014 A	8	All A		-	11.7		_
Switching Hathy	-Open All		.50	A0	20	-BE	M	2		
		7		.		-M		25-11	•	
	Switch Sotu						ккк			
	-Switch Setu					-171	BBK	出版		
	-Close Range		To		v Qutr			Vite prof	. 1	
	-Close Range -Open Output		To	specify	y Outp				Hav I	
	-Close Range -Open Output -Open Range					ut Ch				
	-Close Range -Open Output		To : o speci			ut Ch		W may		
	-Close Range -Open Output -Open Range					ut Ch		"	 	
Teg 5	-Close Range -Open Output -Open Range	T	o speci	fy Inpu		ut Ch t		I Content		
• T	-Close Range -Open Output -Open Range -Open Input	Dele 4/11/200	o speci	fy Inpu	ıt Por	ut Ch t	annel	I Content	-14	
T	-Close Range -Open Output -Open Range -Open Input	Date 4/11/200 4/12/200	o speci 6 6:10:59 P 6 5:27:34 P 12:49:05 P	fy Inpu Count 4 11 4 8 4 3	ıt Por	ut Ch t	annel	I Content	-14	
	-Close Range -Open Output -Open Range -Open Input	Date 4/11/200 4/7/2000 4/7/2000	o speci	fy Inpu Count 4 11 4 3 4 1	ıt Por	ut Ch t	annel	I Content	-14	

This setup screen is used to create the relay control setup (switch setup) for Agilent B2200A/B2201A Switching Matrix.

To send the switch setup to B2200, click the Single button. Before doing this, you have to establish the GPIB connection to B2200 by using the Switching Matrix tab screen of the Configuration window. See Module 8.

This screen provides the following GUI.

Add: Adds a setup row for relay connection.

Delete: Deletes the setup row. To select the setup row, use the left radio button.

Up: Moves the selected setup row upward.

Down: Moves the selected setup row downward. The setup row provides the following entry fields.

Operation: Relay control operation. Open All, Switch Setup, Close Range, Open Output, Open Range, or Open Input. See the next page.

Input: B2200 input port number or label. Available for the Switch Setup, Close Range, and Open Input operations.

Outputs: B2200 output channel number or label. Four entry fields are available for the Switch Setup and Open Output operations to specify the output channels. Two entry fields are available for the Close Range and Open Range operations to specify the range of output channels.

Rule: Relay connection rule. BBM or MBBR.

•BBM: Breaks the previous connection and then makes the new connection for the specified outputs.


•MBBR: Makes the new connection and then breaks the previous connection for the specified outputs.

Operation and number of Outputs





Operation	Description	Number o Outputs
Open All	Opens all relays.	0
Switch Setup	Makes the connection from the specified input port to the specified output channels. Up to four output channels can be specified at once.	4
Close Range	Makes the connection from the specified input port to the specified output channels. They are between two channels given by the Outputs fields.	2
Open Output	Opens the relays connected to the specified output channels. Up to four output channels can be specified at once.	4
Open Range	Opens the relays connected to the specified output channels. They are between two channels given by the Outputs fields.	2
Open Input	Opens the relays connected to the specified input port.	0

Note:




Note:






This section explains how to create your test definition. You will perform the above tasks to create the definition.



Test definition consists of test specification, test contents, and test output setup. The test specification contains test name, description, device parameters, and test parameters. The parameters will be the variables used to pass the test conditions to the test execution flow or test setup defined in the test contents. Especially for the test parameters, you can specify the position of entry field for each parameter. You can see the entry fields when the main screen displays this application test setup. The test contents are the core of the test definition. You will define the local variables, test execution flow, and test setup. You can define the test setup by selecting application tests, classic tests, or my favorite setup, and entering the test conditions.

The test output setup is optional. If you need the test result output (test result display and record) of the test definition, declare the variables (analysis parameters) and define the display parameters. See "If You Define Application Test Output".

You can use the device parameters, test parameters, and analysis parameters in the test execution flow (program flow) of the test contents without declaration of local variables.



Test contents are the test execution flow (program flow), and is the core of the test definition. In the test contents, the following elements can be defined.


- Local variables
- •Program components
- •Application tests
- •Classic tests
- •My Favorite setup
- Analysis components
- •Miscellaneous components

•Device parameters defined in the test specification

•Test parameters defined in the test specification

•Analysis parameters defined in the test output

The program is executed from top to bottom in the test execution program list.



To start test definition, open the test definition editor.

Select the Application Test tab, click the Library button, and select the Define New Test... function. The test definition editor will be opened. See next slide.

<section-header><text>

The test definition editor provides three tabs, Test Specification, Test Contents, and Test Output. At first define the test specification. Click the Test Specification tab.

In the Test Information area:

•Click the right button in the Category field to specify the category the new test definition belongs.

•Enter the Test Name.

•Select the Icon that will be displayed on the list area below the Library button of the main screen. It is the image file used to select the test definition. See previous slide.

•Enter the Description of the test.

In the Device Parameters Definition area:

•Click Add button to display the entry fields for the parameter.

•Set the Name, Default value, and Description for the parameter. When you add a parameter, you will see the entry fields at the Properties area. The area shows you the properties (minimum value, maximum value, number of effective digits, resolution, and unit) for the device parameter or the test parameter specified by the radio button put on the left of the parameter name.

For the Typical Values... button and the Symbols... button, see online help or User's Guide.

fine Test Specification
-
Test Selections Test Services Test Galaxy
Text Tolewalker Cutoperg.
Text Base, Intellat
Jose gene. Que
Service Personellers Definition Properties
Name: Default: Description: To add a device parameter, press the [Add] butters in this area. Set properties of parameter
Test Persenters Defeation
Resigned Roots Dar An Door Dar
Name: Type: Dafaidt: Denziption: Align:X: V: Width Est:
To add a first parameter, prices the (Add) halfon in this area.

In the Test Parameters Definition area:

•Select the Background that will be displayed on the application test setup area of the main screen. Usually it is the image that shows the device connections.

•Set the Name, data type, Default value, and Description for the parameter. When you add a parameter, you will see the entry fields at the Properties area. The area shows you the properties (minimum value, maximum value, number of effective digits, resolution, and unit) for the device parameter or the test parameter specified by the radio button put on the left of the parameter name.


•Set the X, Y, and Width values to specify the position of entry field displayed on the application test setup area.

•Check the Aligh box to set the X origin of entry field to the left edge of the entry field. Uncheck this box to set it to the left edge of the parameter name placed left next to the entry field.

•Check the Ext box. The entry field will be put on the Extended Test Parameters dialog box that is displayed by clicking the Extended Setup button on the application test setup area of the main screen.

fication								
Troy kind king							1	
File Help Tell Spachaton Tell Co Heat Information	ritaria (that Output)							
Cutegory: Think		Exectiption	The approximation of the second	B-W Car	dento a	130-16	_	1.
Test Barners Trug die	100		PERSONAL PRIME	10,000,000				
how Diving	an Neo Aperical Solo	fandietterin Bease- One						
Device Parameters Def	failtine .				Properties	<u> (</u>		- 11
Name	Default: D	Add	need lines in					
r [est		ul tria						
c pair at	11 NP	riliv time						
Test Parameters Defini	them :				-			- 73
Background (CPUp	en Harlingters (school	Execution Research Quar		445	[Dente]		1.100	-
Name: Typ		Description		liger X.	Ψ1	with	6 Ed	1. ·
in proclamat Mar		Rizeen kat einaan t	and the state of the second state	1.141	No	With .	N.	
e protingen aller		Eleven stat restate fo		1. 685		¥342	10	
L Buck town With	to be been a service of the service	Efter entrys for star	And a state of the state of the state	(*)++)	10×	100	80	15
in Mon vorant mile	and allowed	Rillion and states of	-	12	100	No.	10	1
				P 84	4044	8,010	10 C	
· BULTER BA		Eliterate of steas for a Eliterate vertage for gets	and a second	10. Co.		1.1.1.1.1.1.1		

This example sets: Category: TRNG (newly created) Test Name: Trng idvd idvg Icon: IdVg.bmp Device parameters: Hold and Delay Background: Vth_gmmax.PNG Test parameters: Drain, Gate, Source, Subs IdVd_Vdstart, IdVd_Vdstop, IdVd_step, IdVd_Vgstart, IdVd_Vg_nop, IdVd_Vgstep IdVg_Vdout, IdVg_Vgstart, IdVg_Vgstop, IdVg_Vgstep Vsub, Vs, Icomp, Igcomp Entry field properties: 80 (width) x 30 (distance in vertical direction)



This is a result example of the test specification setup shown in the previous slide.

Contract File Help	a/ala
The Sectors Tel Sectors Tel Context	O ™ Attain connent to the second
	Care Set Metabolis (in Prote Set)
button	
The second second	
Local Variables Defini s BLOCK END BLOCK	
	No Parameter Settings
Specify the line	
to insert element or edit	Define the setup necessary
	ior the ingringited element
or edit	for the highlighted element

Define the test contents as shown below:

•Click the Test Contents tab.

•Click the Local Variable Definition line to highlight the line. The right open space displays the Local Variables Definition statement setup editor.


•Define the local variables used in this test execution flow (program flow).

•Click the line that an element has to be inserted.

•Click an element of Program Component, Application Test, Analysis, Classic Test, or Miscellaneous tab menu.

•Click the Insert button of the Edit tab menu. The element will be inserted between the highlighted line and the next line.

•Repeat this to create the test execution flow.



Available elements are shown above. The Program Component provides the typical program statements such as IF, LOOP, FOR, and so on. They are used to control the test execution flow. The Application Test, Classic Test, and My Favorite are used to define the test setup/test condition. The Analysis provides the elements used to control auto analysis function and data display. And the Miscellaneous provides other useful elements. For details of elements, see online help or user's guide.

Burnet	
File Help Two Souchcases Teld Santents Two do	set -
1	Local Variables Definition statement
Laterbas	Add Numuni Add Letter Add Libreg Add Highur Senistice Senistice Senistice Senistice
2	Nanevic Variable
The second second	Name: [1211 m Value: 1 B Description:
Local Variables Defini	Vector Variable
BLOCK END BLOCK	Name [075 B Court] B Description
END BLOCK	# Ansign Linear Values FROM 1 B TO 1
	C Assign Linear Values FROM
	Skring Variable
	Name: 5711 M Value: M Description
	Muslada Variabia
	Name Fill a Description

Add Numeric Variable button displays the Numeric Variable area that provides the following fields.

•Name: Numeric variable name

•Value: Initial value of the variable

•Description: Additional information for the variable

Add Vector Variable button displays the Vector Variable area that provides the following fields.

•Name: Vector variable name. Two dimensional array.

·Count: Number of elements, or array size

•Description: Additional information for the variable

This area also provides the following radio button used to specify how to set the initial value of the array data automatically.

• Assign Linear Values FROM [value of first element] TO [value of last element]

If *Count*>1, this sets *first value* + (*N*-1) x (*last value-first value*)/(*Count*-1) to the *N*-th element. If *Count*=1, this sets *first value*(=*last value*) to the element.

Assign Linear Values FROM [value of first element] STEP [step value]

This sets *first value* + (*N*-1) x *step* to the *N*-th element.

Add String Variable button displays the String Variable area that provides the following fields.

•Name: String variable name

•Value: Initial value of the variable

•Description: Additional information for the variable

Add Module Variable button displays the Module Variable area that provides the following fields.

•Name: Module variable name

•Description: Additional information for the variable

	_								
Contract File Help				-		-		a/018	
go 4	Test Santants Two Curr	h O	۲				A reader		
Local Var Ridor END BLOCK	isblee Defini -		•Bloo •Inse •Delo •Cop •Cut •Pas	ert ete Y	elect	-			

The Edit tab provides the following buttons:

•Block Selection/Line Selection toggle button selects the edit target selection mode. In the line selection mode, clicking line just selects the line. In the block selection mode, clicking line selects the block the line belongs.


•Insert button inserts the specified element between the highlighted line and the next line.

•Delete button deletes the highlighted line.

•Copy button copies the highlighted line to the clipboard.

•Cut button moves the highlighted line to the clipboard.

•Paste button inserts the line in the clipboard between the highlighted line and the next line.



The Debug tab menu provides the following buttons:


•Run button starts the debug (executes the test flow). During execution, the label changes to Pause. Clicking Pause button pauses the execution, and changes the label to Run that is used to continue the debug (execution).

•Abort button aborts the debug (execution).

•Step button executes the highlighted line of the test flow. Clicking the button repeatedly continues the execution by a line.

•Break button sets/releases the break point. For the break point, this button releases the break point from the highlighted line. Program execution will break at the break point automatically.

•Inspect button is available when the debug (execution) is paused or breaked. This button opens the Variable Inspector used to monitor value of device parameters, test parameters, analysis parameters, local variables, or system variables.



The Variable Inspector is displayed by clicking the Inspect button after the program is paused, and is used to monitor or change the value of the device parameters, test parameters, analysis parameters, local variables, or system variables. For the vector variables, only data monitor is available. The Variable Inspector provides the following buttons to add the variable monitor area.


- Add Numeric Variable
- Add Vector Variable
- · Add String Variable
- Add Module Variable

The following functions are available for the menu displayed by clicking the banner of the variable monitor area.

•Up: This button shifts the variable monitor area upward.

•Down: This button shifts the variable monitor area downward.

•Remove: This button deletes the variable monitor area.



In the test execution flow (program flow), you can use the following variables.

·Local variables defined in the test contents

•Device parameters defined in the test specification

•Test parameters defined in the test specification

·Analysis parameters defined in the test output

You need to declare the variables used in the test contents definition by using the Local Variables Definition. You can use the device parameters, test parameters, and analysis parameters without declaration of local variables.


You can read the value of parameters/variables used in the Application Test setup or Classic Test setup defined in a test contents. To do so, use the External Variables Setup dialog box or built-in functions. The read values can be used for the calculation of test result and the display and record of calculation result. See "If You Define Application Test Output".

Trong Khiel Khieg Film Hielp		100
Save Ctrl+S Close		
Poper Concert (Appart Tot) Appart	ann Ind (Horizena) (Schools Midd) ICK Maleenaat	
- Ener Ind - Bank	Cardions Test Refeatives Serve	2
Local Variables Defini . BLOCK IdVa	Construction of the instrument of the second	
Nessage IF Tes=0 END END IF	Table Table Table	itter Dererte
1dVg END BLOCK	A Section	an track data
	- (OK OHM


After you create your test definition, save the definition and close the Test Definition editor.

Select File/Close menu. Confirm Test Definition Save dialog box is opened. Click Yes to save your test definition and continue the close operation.


If the same file name exists, the Confirm Test Definition Overwrite dialog box is opened. Click OK to overwrite your test definition.




The test definition can be exported as the EasyEXPERT test definition file format or XML file format. And the file can be imported to the EasyEXPERT later.



Note:



This is a test result example displayed on the Data Display window.



If you want to get the output of the application definition, define analysis parameters and set display parameters in the Test Output tab screen. See the following pages.

You can read the value of parameters/variables used in the Application Test setup or Classic Test setup defined in a test contents. To do so, use the External Variables Setup dialog box or built-in functions. The read values can be used for the calculation of test result and the display and record of calculation result.

	1. Define analysis 2. Set display para	
ring kolid koligit ir Help		
t Specification Test Containing Test Guttant	Define Autom Resmeter) → Opens Analysis Paramete
K Y Graph	March 1997 A March 1997	Definition window
Name Sub	SAN Devi San Mar	(see next slide).
and the second se	the second secon	(See liext slide).
9 ¥ [14	🕑 (ava.varat 🕱 (ava.varat 🕱	
c AF ≥ Ne → Ne ≥ Ne	 International and international and internatindex and international and international and international and	
r vi la si lan	2 14 1 1 4 1 2 13 2 13 2 1	
r vi la si lan		

The test output setup is optional. If you need the test result output (test result display and record) for this application test, declare the variables (analysis parameters) and define the display setup.

At first, declare the analysis parameters:

•Check the Define own Output Parameters box.

•Click the Define Analysis Parameters... button. The Analysis Parameter Definition window is opened.

•Declare the analysis parameters. See next slide.

•Click the Close button.

•Set the display parameters. See below.

The X-Y Graph area is used to set the X axis and Y axis of the X-Y Graph Plot area on the Data Display window.

•Name: Name of variable to plot on the X axis


•Scale: Linear or Log

•Min: Minimum value of the specified axis

•Max: Maximum value of the specified axis

The List Display area selects the variables to be listed on the List Display area of the Data Display window. Up to 20 variables can be set.

The Parameters area selects the variables to be listed on the Parameters area of the Data Display window. Up to 20 parameters can be set.



Declare the analysis parameters as shown below:

At the Vector Parameters area or the Scalar Parameters area:

•Click the Add button.

•Enter the Name, Unit, and Description of the parameter.

For the sweep output/measurement data, use the vector parameter.

For the spot output/measurement data, use the scalar parameter.

For the data given by the max() and min() built-in function, use the vector parameter.

In this example, VG, ID, and GM are the vector parameter and VTH is the scalar parameter. GM_MAX is the vector parameter because the max() built-in function is used to calculate this value.

Troy Khell	Second and					-/0
	ter Test Contains Test	NO DELLA COMPANY		Deline Arabana Kara	osten	
X Y Craph				INTE WAS	-	
9 X 7 Y) 7 Y2	1200	kole • Dor • Dor • Dor	2 (13	Max		
1.7	and the second sec	- - 	Parameters [Att] c [cm c [50]		-	


This example sets:

X-Y Graph: ID-VG plot for Y1-X graph and GM-VG plot for Y2-X graph

List Display: VG, ID, and GM

Parameters: GM_MAX and VTH

All parameters must be declared by using the Analysis Parameter Definition window shown in the previous slide or displayed on the last data display.



To read the value of variables used in an Application Test setup or a Classic Test setup, make a mapping table between the test setup internal variables and the external variables which mean the local variables, device parameters, test parameters, and analysis parameters defined in the test contents.

To open the External Variable Setup window from a classic test setup:

•Specify the classic test.

•Click the Display Setup tab.

•Click the Assign to external variables... button.

To open the External Variable Setup window from an application test setup:

•Specify the application test.

•Click the Assign to external variables... button.

External Variable Setup Variable assignments External variable: C VTH Vth Vth	lable assignments		
Variable assignments Add Delete Up Down External variable: Measurement data:	lable assignments		
External variable: Measurement data:	Add Delete Up Down		in anonyminering
		Add	
C VTH I Vth	External variable: Measurement data:		External variab
	C VTH I Vth		VTH
C GM_MAX 💌 GmNax 💌	r GM_MAX 💌 GmMax 💌		GM_MAX
	C VG ▼ Vgate ▼		VG
C ID 💌 Idan 💌	c ID 🔹 Idan 💌		D
C (GM 🔄 (gm 💌	c GM 💌 (pm 💌		GM

This example makes the mapping table between the test setup internal parameters and the analysis parameters.

•Define VTH, GM_MAX, VG, ID, and GM as the analysis parameters.

•Set these analysis parameters to the display parameters.

•Open the External Variable Setup dialog box.


•Match VTH with the internal parameter Vth.

•Match GM_MAX with the internal parameter gmMax.


•Match VG with the internal parameter Vgate.

•Match ID with the internal parameter Idrain.

•Match GM with the internal parameter gm.



This is a result example of the test output setup shown in the previous pages.



This example shows another way to read the value of the internal variables (Vg, Id, gm, gmMax, and Vth). In this example, you do not use the mapping table but use the getVectorData and getNumericData built-in functions. The functions can be used to read the value of parameters displayed on the last data display.

To read the value:

•Define VG, ID, GM, GM_MAX, and VTH as the analysis parameters.

•Set these analysis parameters to the display parameters.

•Insert the ASSIGN statements to add the formula shown above.

ents					
Tring kiled kilegi					2/5
File Help Test SoveRation Test Janta	etta Tue Output				ATT210
		ADDER COMM	ри ене (Марала)	-	
Rogan Corporent (ARTSR			(anterest and a		
1 100 100 100 100 100 100 100 100 100 1		landage Ny IGE Definitr'i Ny Tonis	UNING!		1
Dev DA	-				
Local Variables BLOCK The same TF Yes-1 10Yg VG = getTect CK getTect VR,RVA = get VCU = getTuct END IF	torData torData torData tvettop maridba	teer Paraguenea			
Nessage 1F Tes=1			Labert	Selected	
18VA END IF Norrape		Bufford 3	[** <u>#</u>	[in _	
END BLOCK		Bullon 2	N	ju <u>.</u>	
		Button 3			

This example sets the following test flow:

Local Variables Definition ! Defiles Yes variable

BLOCK

Message ! Do you perform Id-Vg measurement?

IF Yes=1

IdVg ! Classic test setup for Id-Vg measurement

VG=getVectorData("Vg")

ID=getVectorData("Id")

GM=getVectorData("gm")

GM_MAX=getVectorData("gmMax")

VTH=getNumericData("Vth")

END IF

Message ! Do you perform Id-Vd measurement?


IF Yes=1

IdVd ! Classic test setup for Id-Vd measurement


END IF

Message ! Click OK to display VTH and GM_MAX values and end the test

END BLOCK



This is a result example of the test output setup shown in the previous pages.



In This Module

- To Control External GPIB Devices
- To Call Execution Files
- To Perform Repeat Measurements
- Prober Control Script



To Control	External GPIB Devices
Miscellaneous: (GPIB I/O
Write String	to send a string command to GPIB device
Write Value	to send a command to GPIB device
Read String	to read a string value from GPIB device
Read Value	to read a numeric value data from GPIB device
Read List	to read a vector data from GPIB device
Read STB	to read status byte of GPIB device
GP-IB Control	Group Execution Trigger
	Device Clear
	Go To Local
	Local LockOut
	Agilent Technologies

You can control external GPIB devices from the EasyEXPERT by using the GPIB I/O statement. The GPIB I/O statement provides the write/read functions shown above. Select a write function and enter the necessary parameters to send a command to the GPIB device. Select a read function and enter the necessary parameters to read response from the GPIB device. For details, see online help or User's Guide.

The followings are the GPIB Control functions.

•Group Execution Trigger: Sends a trigger to the specified GPIB device.

•Device Clear: Sends a device clear to the specified GPIB device.

•Go To Local: Returns the specified GPIB device to the local state.

•Local LockOut: Locks the specified GPIB device.

Note:

Before starting, enable System Controller. See Module 8. Also establish the GPIB connection with the external GPIB devices.

Agilent B2200 contro	ol example
To send command	© Texit(2200
	File Holp Test Specification Test Statestis Test Output
	19210 Newsyn Constant Data Store
rogramming image:	Pagent Gargerett Appendix Test Anne State Test Mandenian
RST	C Real Day C Real Day C Real Ltd. C Real 175
OUT:FUNC ACON	S tea include of the Carteria
enters "SMU1" to StringPort)	Local Variables Defini . Comptoniston Cheves Char Contained Classication Thype
OUT:SYMB:PORT {0},"{1}"	dpih("Mrita") dpih("Write") Write Value
OUT:SYMB:PORT? {0}	Spibl "Hrits" Addees: [7] # Terminator: [7-01] *
eads string data)	Spik("Meite") Opib("Read") Format: [#2vTAMM.Over.UL(2)(1)]
)PC?	Spint "Read" 2 Value 2 Server 1 Value 2 Server
eads operation complete flag)	Color Velent) Value 2 Darie S Value 4 S
nters "OUT1" to StringCh)	opini "Heite" i opini "Bead") Volue 1 N (0)
OUT:SYMB:CHAN {0},{2},"{1}"	dpib('#rite') Value 1 → {0}
OUT:SYMB:CHAN? {0},{2}	Value 2 → {1}
eads string data))PC?	Value 3> {2}
reads operation complete flag)	Value 4 → {3}

This slide shows an example setup of the GPIB I/O statement. This is a component of the test contents used to control the Agilent B2200 switching matrix.

This example uses the Write Value function to send the following command to the B2200.

:ROUT:SYMB:CHAN {0},{2},"{1}"

where, {0} is CardNo, {1} is StringCh, and {2} is ChanNo.

The followings are the reference of the setup editor.

•Address: GPIB address of the device

•Terminator: EOI, LF, CR/LF, LF+EOI, CR/LF+EOI, or NONE (no terminator)

•Format: Command (header and parameters) sent to the device

•Value 1: Value for {0}

•Value 2: Value for {1}

•Value 3: Value for {2}

•Value 4: Value for {3}


{0}. {1}, {2}, and {3} are variable available in the Format field only.

Note:

Use double quotes to enter a string to a local variable by using the Assign statement.

Agilent B2200 contro	ol example	
Fo read data	Fireff1200	-/0
	Test Specification: Test 20/dat/s Test 0/dp/r	
	07510 Neurope Constanting Constant	
rogramming image:	Program Conserver 1 Appendix Terril Ansavel Cases Terril Housewood	
RST	Thead States C Read States C Read States	
ROUT:FUNC ACON	GP III Carest	
enters "SMU1" to StringPort) ROUT:SYMB:PORT {0},"{1}"	BLOCK Traper	
ROUT:SYMB:PORT? {0}	Cplb("#cjb") Sciple("#cjb") Sciple("#cjb") Addman" [2] B Thread [1]	_
eads string data)	Spibi "Heits" Address: [2] B Threed: [10] B Spibi "Heits" Spibi "hast" Sting Datato	
DPC?	Colles (*#rite*) Colles (*Read)) Length To Read: [17] Length Actually Read: [17971	3
eads operation complete flag)	StringCh + "5071" Opib ('Veita') Terminator (7-00) Terminator (Term	•
enters "OUT1" to StringCh)	Color Televis	
ROUT:SYMB:CHAN {0},{2},"{1}"	dpik("Hrite") Gpik("Read")	
ROUT:SYMB:CHAN? {0},{2}	END BLOCK GENERAL	
reads string data) OPC?		
reads operation complete flag)	-	

This example uses the Read String function to read the response from the B2200. This example reads the :ROUT:SYMB:CHAN? query command response. The result (ReturnCh value) must be OUT1.



You can call the execution file (EXE file) from the EasyEXPERT. Use the Command Execution statement and define the setup editor as shown in this example.

•Command Filename: Execution file name (command name)

•Argument: Command parameter or argument

•Write Type: String or List (vector data)

•Read Type: String, Value (numeric data), List (vector data), or None (no read data)

If you specify Write String, enter the string sent to the command.

If you specify Write List, enter the name of vector variable sent to the command, and specify the format of data element sent to the command. See next slide.

In the Read String/Value/List area, specify the variables used to receive execution result and output data. There is no entry field for Read Type: None.

•Result: Numeric variable name. Used to store the execution result.


•Value: Numeric variable name for Read Value, or vector variable name for Read List. Used to store the returned data.

•String: String variable name. Used to store the returned data.

•Length Actually Read: Numeric variable name. Used to store the byte length of the returned data.

The above example calls the sleep.exe file used to insert the wait time for program execution. The WAIT value must be defined in msec. After the normal command execution, the sleep.exe returns 1 for Value and 0 for Result. The sleep.exe file is stored in the following folder.

C:\Program Files\Agilent\B1500A\EasyEXPERT\Utilities



The Format field is used to specify the data format of List (vector variable). The strings shown in the above example can be defined in the Format field.

In the strings, the list data index is mandatory. The character length and format identifier are omissible. Then the length is not limited, and the format G is set.

C or c: Circulation

D or d: Decimal numeral

E or e: Exponential notation

F or f: Fixed point

G or g: General

N or n: Numeric

P or p: Percent

R or r: Round trip

X or x: Hexadecimal numeral

For the format, see online help or manual of the Agilent T&M Programmers Toolkit.


Exercise 12

Try to improve your test definition as you want.

- To Use Built-in Functions
- To Use Read Out Functions
- To Control External GPIB Devices
- To Call Execution Files



Note:



Repeat measurement is performed as shown in this flowchart. The status is a response returned by the start/iteration procedure. The Count is the accumulated number of test executions. They are the stop condition of the repeat measurement.

The repeat measurement stop function is enabled by the following check boxes.

Counter reaching to

•Procedure return condition

If the first box is checked and the limit value is specified, the repeat measurement will be stopped if Count >= limit. To perform the repeat measurement, set the limit value more than the number of devices under test or remove check from this box.

If the second box is checked, the repeat measurement will be stopped if status is not 0.

When the second box is checked, the device ID automatic setup function is available and is enabled/disabled by using the following check box. The function enters the device_id value to the Device ID of the test result record. The device_id is a response returned by the start/iteration/subsite procedure.

Automatically fill in Device ID

The Repeat Measurement Setup dialog box provides the following action buttons.

•Run: Starts repeat measurement.

•Abort: Stops repeat measurement immediately.

•Cancel: Closes the Repeat Measurement Setup dialog box.

Start/Iteration/Final Procedure:

Enter the full path name of the procedure. For example, enter as follows.

C:\Program Files\Agilent\B1500\EasyEXPERT\Utilities\ProberControl\suss\Start_suss.exe Arguments:

Enter the options of the procedure. See the following pages describing about procedures. For example, enter -a GPIB0::5::INSTR -I C:\temp\prb.log.

If you use the sub die move operation (subsite procedure), the flowchart must be changed. See page 7-18.

Trag yer (Trag y	Device Parameters Next Statistic Next Statistic Sector Sector Sector Tring yn r2 Tring yn r2 Tring yn r2 Specify ProberType. Or specify driver for your prober in CustomProber. Select Select	Werder Farzenetters Forder Farzenetters Werder Type: Werder Type: Trag yn: Ford Farzenetters Trag yn: Forder Housenetters Trag yn: Forder Housenetters Specify Prober Type: Save Trag yn: Specify Prober Type. Or specify driver for your prober in CustomProber. Birth Sector Trag yn: Select	Device Parameters Notified Notified Notified Device Parameters Image	Device Parameters Notadify Device Parameters Tring gr Tring gr Tring gr Specify ProberType. Or specify driver for your prober in CustomProber. Tring gr Tring gr Specify ProberType. Or specify driver for your prober in CustomProber. Tring gr Tring gr Or specify driver for your prober in CustomProber. Tring gr	Image: Select	Overlog Parameters Text Parameters Te	Device Parameters State Tel Parameters Tel Paramete	Beschaft Device Parameters Next State Device Parameters Next State Device Parameters Beschaft Device Parameters	Weeker Parametere Weeker Parametere <t< th=""></t<>
Percent State Ford Percentations Forder Stype Unterpret Forder Stype Forder Stype Unterpret Forder Stype Forder Stype Tring gen r2 Specify Prober Type. Or specify driver for your prober in CustomProber. Tring gen r2 Select	Percent Statistic Ford Percentences Extendent Statistic Visitivity Extendent Statistic Percent Statistic Visitity Extendent Statis Percent Stati	Image of a standard Image of a stand	Productivel Fund Hard Baddadin Fund Hard	Productivel Forder Type: Count: Forder Type: Productively Forder Type: Save Prog on 7 Save Save <th>training and training and t</th> <th>received adds adds adds received adds received adds received</th> <th>Terderer Type: Terderer Type: Terderer Type: Specify Prober Type: Or specify driver for your prober in CustomProber.</th> <th>New Signal Stadality Ford Personalizers Enderstanding Untrary Ford Personalizers Enderstanding Untrary Ford Personalizers Enderstanding Tring gen Enderstanding Enderstanding Tring gen Save Save Tring gen Save Save Tring gen Specify ProberType. Untrary Tring gen Or specify driver for your prober in CustomProber. Enderstanding State Select Select</th> <th>Besteled Besteled <td< th=""></td<></th>	training and t	received adds adds adds received adds received	Terderer Type: Terderer Type: Terderer Type: Specify Prober Type: Or specify driver for your prober in CustomProber.	New Signal Stadality Ford Personalizers Enderstanding Untrary Ford Personalizers Enderstanding Untrary Ford Personalizers Enderstanding Tring gen Enderstanding Enderstanding Tring gen Save Save Tring gen Save Save Tring gen Specify ProberType. Untrary Tring gen Or specify driver for your prober in CustomProber. Enderstanding State Select Select	Besteled Besteled <td< th=""></td<>
Notation Restantion Boardient Restantion	Notación Bradadión Brochemiere Forde Presendence Resention for for Presidenti for the presention of the present of the presention of the presention of the presention o	Windows Extended former	Notedation Forder Type: Texted Bits House Disclose Forder Type: Texted House Tring grs Control Prober Type: Save Tring grs Specify Prober Type: Or specify driver for your prober in CustomProber. Tring grs Select	Notified Indexembers Extended Sector Boundary Indexembers Extended Sector Boundary Indexembers Indexembers Indexembers Extended Sector Indexector <th>Baladry Extended to the second to the se</th> <th>Terd Presentedors Terd Presente</th> <th>Teleformer Telefo</th> <th>Notedity Ford Bersonders Brandwith Browne Browne Brown</th> <th>Bestadding Eventering Bestadding E</th>	Baladry Extended to the second to the se	Terd Presentedors Terd Presente	Teleformer Telefo	Notedity Ford Bersonders Brandwith Browne Browne Brown	Bestadding Eventering Bestadding E
State Forder Type Tring ym Tring ym Tring ym Save Specify ProberType. Save Tring ym Specify driver for your prober in CustomProber. State Subout the second sec	State Image:	With Y Wet Breambers Restance Restance We Remembers	State Image: Select Defendence: Count. Defendence: Count. <td< th=""><th>Browner Text Parameter Reference Transger Text Parameter Reference Transger Text Parameter Reference Transger Save Save Specify ProberType. Or specify driver for your prober in CustomProber. Reference Transger Select Select</th><th>Browner First Baranders Extraction Sector Browner First Baranders Extraction Sector Browner Extraction Sector Image of the sector Browner Extractin</th><th>Teel Prometers Teel Prometers Teel Prometers Teel Prometers Save Specify ProberType. Or specify driver for your prober in CustomProber.</th><th>Ted Baranders Ted Baranders Ted Barander Ted Barander</th><th>With and a strength Extended State Ubrary Forder Type: Trag gen P Save Specify ProberType. Save Or specify driver for your prober in CustomProber. Save Specify Select Select</th><th>Image: Specify ProberType. Save Trag ge: Tra</th></td<>	Browner Text Parameter Reference Transger Text Parameter Reference Transger Text Parameter Reference Transger Save Save Specify ProberType. Or specify driver for your prober in CustomProber. Reference Transger Select Select	Browner First Baranders Extraction Sector Browner First Baranders Extraction Sector Browner Extraction Sector Image of the sector Browner Extractin	Teel Prometers Teel Prometers Teel Prometers Teel Prometers Save Specify ProberType. Or specify driver for your prober in CustomProber.	Ted Baranders Ted Baranders Ted Barander Ted Barander	With and a strength Extended State Ubrary Forder Type: Trag gen P Save Specify ProberType. Save Or specify driver for your prober in CustomProber. Save Specify Select Select	Image: Specify ProberType. Save Trag ge: Tra
Ubin Text Parameters Extended Notari Tring gen Prober Type Image Notari Tring gen Save Specify Prober Type. Or specify driver for your prober in CustomProber. Select Select	Ubin Text Parameters Extended Montal Tring gm Interference Interference Tring gm Contended Montal Interference Tring gm Save Interference Specify ProberType. Or specify driver for your prober in CustomProber. Interference State Interference Interference Interference Save Interference	Iterary Text Baranehers Iteraries Tring gn Involver Type: Involver Type: Tring gn Contended Meeting Involver Type: Tring gn Specify Prober Type. Save Tring gn Or specify driver for your prober in CustomProber. Involver Tring gn Select Involver	Iterary Test Parameters Extended Meeters Tring yer Control Parameters We Excercite Meeters Tring yer Control Parameters We Parameters Tring yer Control Parameters We Parameters Specify ProberType. Or specify driver for your prober in CustomProber. We Parameters Select Select We Parameters We Parameters	Iterary Test Parameters Extended Mediat Tring gen Casada Mediatal Important Tring gen Casada Mediatal Important Contended eder Save Important Specify ProberType. Or specify driver for your prober in CustomProber. Important Tring gen Select Important	Iteration Iteration Iteration	Ted Parameters	Ter Brevenders Ter Brevenders Prober Type: Specify Prober Type. Or specify driver for your prober in CustomProber.	Ubin Text Presenders Februarde Medican Tring gn Februarde Medican Image: Annual Medican M	I Unity Text Parameters Februarie Heater Tring yn Text Parameters Februarie Heater Tring yn Extra Heater Internet Heater Tring yn Extra Heater Extra Heater T
Utberary Tend Parameters Extensional Sectors Her Remains Sectors Tring ym Contender Hootest Image: Annual Hootest Image: Annual Hootest Tring ym Contender Hootest Image: Annual Hootest Image: Annual Hootest Tring ym Contender Hootest Image: Annual Hootest Image: Annual Hootest Tring ym Contender Hootest Image: Annual Hootest Image: Annual Hootest Tring ym Contender Hootest Image: Annual Hootest Image: Annual Hootest Tring ym Contender Hootest Image: Annual Hootest Image: Annual Hootest Tring ym Specify ProberType. Or specify driver for your prober in CustomProber. Image: Annual Hootest Tring ym Select Image: Annual Hootest Image: Annual Hootest Tring ym Select Image: Annual Hootest Image: Annual Hootest	Utburget Tend Parameters If a formation before Tring gen r Image: Control of Cont	Warener Rest Rest Rest Tring gin Product Hype: Saturation Headmanth Income Tring gin Constant Headmanth Income Income Tring gin Constant Headmanth Income Income Tring gin Specify ProberType. Save Save Tring gin Specify ProberType. Income Income Tring gin Select Select Income Tring gin Select Income Income	Uttary Tend Parameters Retreaction Sectors We presente betrage Tring gen Product Houses Tring gen Tring gen Control Houses Tring gen Tring gen Specify ProberType. Save Tring gen Specify ProberType. Save Tring gen Or specify driver for your prober in CustomProber. We house Select Select Select	Literary Text Parameters Restance Restance <t< th=""><th>Brand Frank Decision Frank Decision Frank Decision Tring gin Image: All control of the co</th><th>Teel Parameters Teel P</th><th>Terd Parameters Product Type: Contraction Houses Contraction Houses Contraction</th><th>Utwary Tend Parameters Extended Series Her Parameter Beland Tring print Contrader Savedin Honotext Marceler Tring print Savedin Honotext Savedin Honotext Savedin Honotext Tring print Savedin Honotext Savedin Honotext Savedin Honotext Tring print Specify ProberType. Savedin Honotext Savedin Honotext Tring print Specify ProberType. Savedin Honotext Savedin Honotext Tring print Specify driver for your prober in CustomProber. Savedin Honotext State Savedin Honotext Savedin Honotext</th><th>Utter arg First Parameter Kenter Extended Metage Her Parameter Kenter Tring gen 7 Prober Type Image Parameter Kenter Image Parameter Kenter Tring gen 7 Save Image Parameter Kenter Image Parameter Kenter Tring gen 7 Save Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify driver for your prober in CustomProber. Image Parameter Kenter Tring gen 7 Select Image Parameter Kenter</th></t<>	Brand Frank Decision Frank Decision Frank Decision Tring gin Image: All control of the co	Teel Parameters Teel P	Terd Parameters Product Type: Contraction Houses Contraction	Utwary Tend Parameters Extended Series Her Parameter Beland Tring print Contrader Savedin Honotext Marceler Tring print Savedin Honotext Savedin Honotext Savedin Honotext Tring print Savedin Honotext Savedin Honotext Savedin Honotext Tring print Specify ProberType. Savedin Honotext Savedin Honotext Tring print Specify ProberType. Savedin Honotext Savedin Honotext Tring print Specify driver for your prober in CustomProber. Savedin Honotext State Savedin Honotext Savedin Honotext	Utter arg First Parameter Kenter Extended Metage Her Parameter Kenter Tring gen 7 Prober Type Image Parameter Kenter Image Parameter Kenter Tring gen 7 Save Image Parameter Kenter Image Parameter Kenter Tring gen 7 Save Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify Prober Type. Image Parameter Kenter Image Parameter Kenter Tring gen 7 Specify driver for your prober in CustomProber. Image Parameter Kenter Tring gen 7 Select Image Parameter Kenter
Ting yn r Specify ProberType. Or specify driver for your prober in CustomProber. Select	The gent The ge	Ting yn r Ting yn r	Trag ger Trag Setup Namer Trag S	Tring gen Tring gen	Ting gn Ting gn Tin	Probertype: Calific Normality Custometrype: Custometrype: Cust	Product Type: Carde Mental Control of the State of the St	Trag yn T Specify ProberType. Or specify driver for your prober in CustomProber.	Ting yn r Ting yn r Specify ProberType. Or specify driver for your prober in CustomProber.
Trag yer (Trag y	Tring per Tring	Tring gin Tring gin	Tring yer (Tring	Tring gen Tring Tring gen Tring	Trans gen Trans gen	Custometry prober Type. Or specify driver for your prober in CustomProber.	Product rype Custower rype Specify Prober Type. Or specify driver for your prober in CustomProber.	Trang year Trang	Tray gen Tray g
Ting yn Ting Y	Tring yn Tri	Tring grit Tring	Tring ym Custometrotact Tring ym Custometrotact Tring ym Save Specify ProberType. Save Or specify driver for your prober in CustomProber. Save State Save State Save State Save Tring ym Save Specify ProberType. Or specify driver for your prober in CustomProber. State State State State Tring ym State Tring ym Date	Tring ym Constant House	Tring ger Tring ger	Contractive termine termine Contractive termi	Specify ProberType. Or specify driver for your prober in CustomProber.	Ting yn Ting yn Ting yn Ting yn Ting yn Ting yn Ting yn Ting yn Ting yn Specify ProberType. Or specify driver for your prober in CustomProber.	Trag yn Trag y
Tray yes Specify ProberType. Or specify driver for your prober in CustomProber.	Trag yer Specify ProberType. Or specify driver for your prober in CustomProber.	Custometrodere Vender Laterner Fireg per fi Save Trong per fi Save Specify ProberType. Save Or specify driver for your prober in CustomProber. Bit Vill Select Bit Vill Select Bit Vill	Trag yn 7 Specify ProberType. Or specify driver for your prober in CustomProber.	Trag yn 7 Specify ProberType. Or specify driver for your prober in CustomProber.	Tray ger (Tray g	Contractivities: Protocological and and a second seco	Specify ProberType. Or specify driver for your prober in CustomProber.	Image: First period Image: First period Image: First period Save Specify ProberType. Image: First period Or specify driver for your prober in CustomProber. Image: First period Image: First period Image:	Tray yn r Specify ProberType. Or specify driver for your prober in CustomProber.
Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber. Select True pro Select True pro Select True pro Select True pro Select True pro Select True pro Select True pro Select True pro Select Selec	Specify ProberType. Or specify driver for your prober in CustomProber. Select Fing Setup Neme Fing Setup Neme Date Coart. Device 1D Remets	Specify ProberType. Save Or specify driver for your prober in CustomProber. Image: All the second s	Specify ProberType. Or specify driver for your prober in CustomProber.	Save Specify ProberType. Or specify driver for your prober in CustomProber.	Save Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Save Specify ProberType. Or specify driver for your prober in CustomProber.
Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber. Select Tray yr. Select Tray yr. Tray yr. Select Tray yr. Tray yr. Tray yr. Tray yr. Select Tray yr. Tray yr. Select Tray yr. Tray yr. Select	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Save Or specify driver for your prober in CustomProber. Image: Seture Market State Seture Market State Image: Seture Market State	Specify ProberType. Or specify driver for your prober in CustomProber.	T Specify ProberType. Or specify driver for your prober in CustomProber.	T Save Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.
Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber. Tray problem Select Select Select	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.	Specify ProberType. Or specify driver for your prober in CustomProber.
Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber. Select They Setup Neme Dete Coart. Detes	Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber.	Or specify driver for your prober in CustomProber.
Tragen Select	Trong print Select Select	Treg pro- Select Select Defer Count Device ID Remarks	Tring particular and the second secon	Tring parts and the second sec	Tring and Select Select			Trong print Statement Line Select	Trage and a second seco
Trange And Select	Trans Pan Select	Select Date Coast Device 1D Remarks	Trong program Difference Difference Select Difference Difference Flag Selap Name Date Count. Device 1D	Trong program Difference Difference Select Difference Difference Flag Selap Name Date Count. Device 1D	Select		97 2 2007 gen	States 2 Select	Select
Select	Select	Setter Land Setlect Setter Land Setlect Plag Setup Name Date Count Device ID	Image Select Image Image <t< th=""><th>Image Select Image <t< th=""><th>Select</th><th></th><th>2 DiMogen</th><th>Select 2 Date open</th><th>Select 2 Data see</th></t<></th></t<>	Image Select Image Image <t< th=""><th>Select</th><th></th><th>2 DiMogen</th><th>Select 2 Date open</th><th>Select 2 Data see</th></t<>	Select		2 DiMogen	Select 2 Date open	Select 2 Data see
1000 R	BOOR	Plag Setup Nerve Date Count Device ID Remarks	Plag Setup Name Date Count Device ID Remarks	Plag Setup Name Date Count Device ID Remarks	1000 x x x x x x x x x x x x x x x x x x		Calaat		
1000 R	BOOR	Plag Setup Nerve Date Count Device ID Remarks	Plag Setup Name Date Count Device ID Remarks	Plag Setup Name Date Count Device ID Remarks	1000 x x x x x x x x x x x x x x x x x x				
noe	non	Plag Setup Name Date Count Device ID Remarks	move w Flag Setup Name Date Count Device ID Remarks	move w Plag Setup Name Date Count Device ID Remarks	noe				
					Plag Setup Name Date Count Device ID Remarks				
									That Setup Name Date Count Device ID Remarks
All the second sec			skrgvd 3/7/2006 9:92:37 PM 2			lag Sebap Name Date Count Device ID Remarks	lag Sebap Name Date Count Device ID Remarks		DLOUT_1.2 1/2/2005 6/4/5/04 1
sdvgvd 3/7/2006 9:92:37 PM 2					. Idvgvd 3/7/2006 9:99:37 PM 2	Ing Sebup Name Date Count Device ID Remarks	Ing Sebup Name Date Count Device ID Remarks	IN-OUT-1-7 3/7/2006 6:43:40 PM 1	
SWH-open 3/7/2006 4:45:49 PM 1	sdvgvd 3/7/2006 9:99:37 191 2 SWM-open 3/7/2006 4:45:49 PM 1	SWM-open 3/7/2006 4:45:49 PM 1			SWM-open 3/7/2006 4:45:49 PM 1	Isry Name Date Count Device ID Remarks IN-OUT-1-7 3/7/2006 6-43:-40 PM 1	Ing Setup Name Date Count Device ID Remarks IN-0017-1-7 3/7/2006 6-43:40 PM 1	IN-CRUT-1-7 3/7/2006 6-43:40 PM 1 shtypei 33/7/2006 6-43:40 PM 2 SWM-open 32/7/2006 4:55:47 PM 1	ubygvd 3/7/2006 4:99:37 PM 2 SWM-open 3/7/2006 4:45:49 PM 1
SWR-open 3/7/2006 4:45:49 PM 1 1d-Vd 3/7/2006 4:45:45 PM 1	skygvd 3//2006 9:99:32 PM 2 SVM-open 3/2/2006 9:95:45:49 PM 1 16-V-Vd 3/2/2006 9:54:51 PM 1	SWM-open 3/7/2006 4:45:49 PM 1 Id-vd 3/7/2006 4:45:45 PM 1	Id-Vid 3/7/2006 4:45:45 PM 1	Id-Vd 3/7/2006 4:45:45 PM 1	SWM-open 3/7/2006 4:45:49 PM 1 Id-Vd 3/7/2006 4:45:45 PM 1	Ing Sebup Name Date Count Device ID Remarks IN-CUT-1-7 3//2006 6-43:40 PM 1 idxyrd 3//2006 6:98:22 PM 2 SWM-open 3/7/2006 4:45:49 PM 1 Id-Vd 3/7/2006 4:45:49 PM 1	Ing Setup Name Date Count Device ID Remarks 1 IN-CUT-1-2 1//2006 6:43:40 PM 1	IN-0x01-1-7 3/7/2006 6-43-40 PM 1 stkypvd 3/7/2006 6-43-40 PM 2 SWM-open 3/7/2006 4145-49 PM 1 16-V-0d 3/7/2006 4145-49 PM 1	shqyvi 33/7/2006 9195:32 PM 2 SWM-opm 3/7/2006 9195:32 PM 1 1d-Vid 37/72006 9195:45 PM 1
SWH-open 3/7/2006 4:45:49 PH 1	ishqed 3//2006.999:37 (M 2 SWM-spen 3//2006.41:51:49 (M 1 Id-Vid 3//2006.41:51:49 (M 1	SWIN-open 3/7/2006 4:45:49 PM 1 Id-Vd 3/7/2006 4:45:45 PM 1	1d-Vd 3/7/2006 4:45:45 PM 1	1d-Vd 3/7/2006 4:45:45 PM 1	SWM-open 3/7/2006 4:45:49 PM 1 Id-Vd 3/7/2006 4:45:45 PM 1	Ing Sebup Name Date Count Device ID Remarks IN-CUT-1-7 3//2006 6-43:40 PM 1 idxyrd 3//2006 6:98:22 PM 2 SWM-open 3/7/2006 4:45:49 PM 1 Id-Vd 3/7/2006 4:45:49 PM 1	Ing Setup Name Date Count Device ID Remarks IN-CUT-1-7 1//2006 6:43:40 PM 1 Idryped 3//2006 6:45:40 PM 1 SWM-open 3//2006 6:45:40 PM 1 Idryped 3//2006 6:45:54 PM 1 Idryped 3//2006 4:45:45 PM 1 Idryped 3//2006 4:45:45 PM 1	IN-00/T-1-7 1/7/2006 6-43-40 PM 1 ubtyped 3/7/2006 6-99-37 PM 2 SWM-open 3/7/2006 4-95-49 PM 1 Id-Vid 3/7/2006 4-95-45 PM 1	shtged 3//2006.999:37 (M 2 SWM-spen 3//2006.41:51:49 M 1 Id-Vid 3//2006.41:51:49 M 1
		lag Sebap Name Date Count Device ID Remarks	lag Sebap Name Date Count Device ID Remarks	lag Sebap Name Date Count Device ID Remarks		Select			w = =
Statement St. State 10 Band					Sebup Name Date Count Device ID Remarks			B-007-1-7 w	
Fing Setup Name Count Device ID Remarks	Plag Setup Name Date Count Device ID Remarks	IN CRIT-1-2 3/3/2006 6-47-40 DM 1	IN-OLIT-1-7 3/7/2005 6:43:40 PM 1	IN-007-1-7 3/7/2006 6:43:40 PM 1		N			Flag Setup Name Date Count Device ID Remarks

If you do not use the sub die (subsite) move operation, skip this page.

Click Application Test tab and open the Subsite move test setup in the Utility category. On the Subsite move setup screen, specify ProberType (Cascade, Suss, or Vector) or driver for your prober in CustomerProber, and save it as a setup in your preset group (My Favorite Setup). Then you can use the setup for your quick test. See next page.

The Subsite move setup moves wafer chuck to the next subsite, reads device ID from the prober, and sets it to the Device ID of the test result record.

For more details of the test setup, open the Test Definition window.

In the Subsite move test definition, an execution file callProbeDvr.exe is used. This file is used to send Subsite_xxxx.exe to the prober specified by the prober_info.ini file and receive the response; status and device_id. The callProberDvr.exe has the following input/output parameters.

Input: Full path of Subsite xxxx.exe

Output: status; 0 (no error) or 1 (error)

Output: device_id

Note:

The callProberDvr.exe refers to the prober_info.ini file for the GPIB address and log file name. Do not set the Arguments of Subsite_xxxx.exe.


B	e Data Display Help				_
1	My Favorite Setup +				1
100	Preset Group: TITIG	2 -	1000	0	
lass: Tet Apple	Setup Name SWM-Ito7 if idvard Sabsite move It-6-Vd	Quick Treat			
a a	SWM-open	Repeat Measurement Setup			
1.4	5 IN-OUT-1-7	Repeat Procedures	5		10.04
3		Start Procedure:	1		1967
		C:\Program Files\Agilent\B1500\EasyEXPERT\Utilities 🛁	Browsem		-
		Arguments:			ideped
		Iteration Procedure:			
		C:\Program Files\Agilent\B1500\EasyEXPERT\Utilities	man 1		Salache mone
		Arguments:	Browse		
		Final Procedure:			3848
		C:\Program Files\Agilent\B1500\EasyEXPERT\Utilities	Browse		_
		Arguments:			210.04
		Automatically fill in Device ID			11776
3	Flag Setup Name IN-OUT-1-2	Repeat Stop Condition		-	IN-001
	idvgvd	Stop repeating by:	Run	- 15	17
Ĩ	SWM-open Td-Vd Idvavd		Abot		
	SWM-1to7	Procedure return condition	Cancel		

If you do not use the sub die (subsite) move operation, skip this page.

To perform the test with the sub die move operation, do as follows.

- 1. Add the Subsite move test setup to your preset group (My Favorite setup).
- 2. Set your preset group and test setups in the Quick Test tab screen.
- 3. Open the Repeat Measurement Setup dialog box.
- 4. Specify the procedures and the repeat measurement condition.
- 5. Start repeat measurement.

The Subsite move setup must be entered after measurements for a sub die.



Prober control script is sample program used for semi-automatic prober control. The Agilent EasyEXPERT can call the script by using the Repeat Measurement Setup window.

See page 7-9 to call the script and perform repeat measurement.

See page 7-14 for the prober information file.


See page 7-13 for the start procedure.

See page 7-15 for the iteration procedure.

See page 7-16 for the final procedure.

See page 7-17 for the subsite procedure.

To use the prober control script, specify the start/iteration/final procedure in the Repeat Measurement Setup dialog box (see page 7-9). And use the Subsite move test setup in your quick test to control sub die move. The Subsite move setup uses the subsite procedure for moving wafer chuck to the next subsite. See page 7-10 and 7-11.



To specify the start procedure in the Repeat Measurement Setup dialog box, enter the full path name of Start_xxxx.exe into the Start Procedure field.

After the repeat measurement is started, this procedure displays the Device ID Entry dialog box and waits for your input. On the dialog box, enter a string used for the prefix of device_id. After that, you will see the Start Confirmation dialog box that is used to confirm your wafer setup status. Load wafer and perform wafer alignment, then click OK on the dialog box. The procedure moves wafer chuck to the first probing position, checks the prober status, gets the X-Y coordinate of the probing position, and sets the wafer chuck to the UP position. At last, the procedure returns the response.


The status is 0 or 1. It is used for the EasyEXPERT repeat measurement stop function. When the Procedure return condition box is checked in the Repeat Measurement Setup dialog box, the repeat measurement will be stopped if status is not 0.

The device_id is a string for the Device ID of the test result record. When the Automatically fill in Device ID box is checked in the Repeat Measurement Setup dialog box, the device_id will be entered to the Device ID of the test result record.

If you use the subsite procedure, the flowchart must be changed. See page 7-18.

Note:

To ignore the Arguments, set the GPIB address and log file name in the prober_info.ini.



The prober information file is necessary to execute the prober control script. Before starting tests, open this file, edit it as you want, and overwrite it. The name must be prober_info.ini.

The prober_info.ini file stores the information shown below.

•Address: GPIB address of prober

•LogMode: Log file creation mode; True or False

•LogName: Log file name (full path)

•UseID: Device ID creation mode; True or False

•SubsiteInfo: Set always False. This is just a place holder.

•WaferInfo: Set always False. This is just a place holder.


•ID: Ignore this variable. This is just a pass parameter.

If the procedures specify the -a option, the Address value is not used.

If the procedures specify the -l option, the LogName value is not used.

To create a log file, set LogMode=True.

To use the prefix:coordinate format for the device_id value, set UseID=True. If UseID=False, the device_id value will be coordinate, not prefix:coordinate. The prefix will be the value entered in the Device ID Entry dialog box that is opened by Start_xxx.exe. This function is available when the Automatically fill in Device ID check box is checked.



To specify the iteration procedure in the Repeat Measurement Setup dialog box, enter the full path name of Iterator_xxxx.exe into the Iteration Procedure field.


The procedure is called after the measurement is completed for a die. This procedure sets wafer chuck to the DOWN position, moves it to the next probing position, checks the prober status, gets the X-Y coordinate of the probing position, and sets the wafer chuck to the UP position. At last, the procedure returns the response.

The status is 0 or 1. It is used for the EasyEXPERT repeat measurement stop function. When the Procedure return condition box is checked in the Repeat Measurement Setup dialog box, the repeat measurement will be stopped if status is not 0.

The device_id is a string for the Device ID of the test result record. When the Automatically fill in Device ID box is checked in the Repeat Measurement Setup dialog box, the device_id will be entered to the Device ID of the test result record.

If you use the subsite procedure, the flowchart must be changed. See page 7-18. Note:

To ignore the Arguments, set the GPIB address and log file name in the prober_info.ini.




To specify the final procedure on the Repeat Measurement Setup dialog box, enter the full path name of Final_xxxx.exe into the Final Procedure field.

The procedure is called after one of the stop condition is detected. This procedure sets wafer chuck to the DOWN position.

Note:

To ignore the Arguments, set the GPIB address and log file name in the prober_info.ini.



To realize sub die move operation, you need to define Subsite_xxxx.exe in your test definition and create your application test setup. However, you do not need to take care of this procedure by using the Subsite move test setup included in the application library. The Subsite move setup moves wafer chuck to the next subsite, reads device ID from the prober, and sets it to the Device ID of the test result record.

Open the Subsite move test setup and save it as a setup in your preset group (My Favorite Setup). Then you can use the setup for your quick test.

Note:


To use the Subsite move setup, set the GPIB address and log file name in the prober_info.ini. And ignore the Arguments for Subsite_xxxx.exe.

Note:

If you use a Suss prober, the number of Subsite move setups used in your quick test (die test) is important. It must be N-1; N is the number of subsites defined in the prober.


The status is 0 or 1. It is used for the EasyEXPERT repeat measurement stop function. When the Procedure return condition box is checked in the Repeat Measurement Setup dialog box, the repeat measurement will be stopped if status is not 0.

The device_id is a string for the Device ID of the test result record.




If you use the subsite procedure, change the flowchart as follows. On the page 7-9, replace the box A with the block A shown above. On the page 7-13 and 7-15, insert the box B shown above to the position B of the flowchart.





This module describes the above topics. You will understand what is the status indicator, what is the automatic data export function and the automatic data record function, how to perform selftest and calibration, how to perform SMU zero offset cancel, and so on.



Status indicator lets you know the status OFF or ON of the following functions. The indicators are placed at the bottom of the main screen.

SMU Zero OFF/ON: Shows the status of the SMU zero offset cancel function OFF or ON. Auto EXPORT OFF/ON: Shows the status of the automatic data export function OFF or ON. Auto Record ON/OFF: Shows the status of the automatic data record ON or OFF. The functions can be set to ON or OFF as shown in the following pages.

Eatopory +		
2 CHOS		Test Results Date Auto Esport
Nensty Nensty NeedSynal	Choose test categories from the left area.	w name automatic data expert to the specified storage device
Nansteph Reliability w		Ovelandern for Experit Folder nam :
Library -		Eldecuments and Settings(81588-set/34/2) and Agreene
20'Vg ("CI Ocose an application test object from the left area.	File Name * Default Format /* Custom Format [https://
		e.g., 'tetus name' ('tenne 10'(131) ; «_12_2006 «_34_06 PH)
(Carves		File Type
200		4 Test Result (EasyEXPERT format)
Cancel	F	Compressed Test Result (EasyEXPERT format)
Select All		r csv
Unselect All		C 395. Spread Short
Display Data Recall		C Using XSLT XM, Usin Unior File Path :
Fiber •		E Second
Transport Data	Export As Test Result	Kolmonian of Calquet Nine
Properties	Export As Compressed Test Result	Data Rocage
Tring Samp 	Export As XML Spread Short 8	Constitution automatic data record to the internal itsrage
Vth gmHa	Auto Export Setting	OK CONCEL
Trng idvd Trng idvd		*
		Hideold II antorior is ante 10

The automatic data export function and the automatic data record function can be enabled or disabled by using the Test Results Data Auto Export dialog box. This dialog box is displayed by selecting the Results > Transport Data > Auto Export Setting... menu.

The automatic data export function is used to export the test result data to the storage device you specify. You can specify the destination (storage device), exported file name, and file type. To set the automatic data export function to ON, check the Enable automatic data export to the specified storage device check box.

The automatic data record function is used to save the test result data to the internal HDD automatically. This function can be disabled (set to OFF) if the automatic data export function is enabled (set to ON). To set the automatic data record function to OFF, uncheck the Enable automatic data record to the internal storage device check box.

For more information, see online help or User's Guide.

ibra IU Ca	tion Ibration CNU Calbra	ton	_		
-	Calibration				
	Name	Full Range	Status	Notes	Select All
Ø	GNDU+ADC		PASS	1	
	SMU1:HP		PASS		Unselect All
	SMU2:HR		PASS		
	SMU3:HR	****	PASS		
	SMU4:HR	****	PASS		Start Calibration
ы	SMU5:HR	****	PASS		-
					Abot
					F Full Range
					Calibration
			☐ Enat	ole Auto Calibration	•
_					
					Close

The Calibration window is opened by clicking the Calibration button. The SMU calibration screen of this window is used to perform the calibration of SMUs. The list area of this screen lists Name, Full Range, and Status.

Name: Name of module. To select, check the left check box.

Full Range: For the high resolution SMU (HRSMU) connected to the atto sense/switch unit (ASU). Full range calibration on or off.

Status: Calibration status. Pass or fail.

Notes: Error information when calibration failed.

To perform the self-calibration, specify the modules, open the measurement terminals of the corresponding modules, and click the Start Calibration button.

Full Range Calibration:


For the HRSMU connected to the ASU. Enables or disables the full range calibration. If this box has been unchecked, the B1500 does not use the 1 pA range.

Enable Auto Calibration:

Enables or disables the auto-calibration capability. If this box has been checked (function ON), and the B1500 automatically starts calibration for all modules every 30 minutes if the output switches of all modules are off for 30 minutes.

NOTE:

To perform calibration correctly, open the measurement terminals. If auto-calibration is enabled, do not forget to open the measurement terminals or disconnect the device under test from the terminals after measurement.



The SMU Zero Cancel screen is used to perform the SMU zero offset current measurement and set the SMU zero offset cancel function.

This function subtracts the offset current from the current measurement raw data, and returns the result as the measurement data. This function is used to compensate the error factor (offset current) caused by the measurement path such as the measurement cables, manipulators, or probe card.

To enable this function, perform the following procedure.

1. Check the left box of the Name column to specify the module to enable this function.

2.Click the Measure... button to perform the zero offset current measurement and wait until the measurement is completed. The measurement data will be displayed in the appropriate cell.

3. Click the Close button to enable the zero offset cancel function.

To disable the function, uncheck the left box of the Name column, and click the Close button. Note:

The offset cancel is not available for measurement over 100 nA range. For 10 nA range measurement, the offset cancel is performed by using the 1 nA range offset value. For measurement by a range less than 10 nA, the offset value measured by each range is used.

For more information, see online help or User's Guide.

altration		99	
THU Collectore (1997 Dalaration)			
IT Open Correction	Magazina .		
E libert Correction	Heater-		
E Load Correction	Mission	Advanced Optimes	
22110000000000000000000000000000000000		Advanced Options for CHU Califoration	
IT Phase Compensation	Heatore	A codework A	Raference Standard Value
		5 Use factory specified frequencies (fields)	O Open Reference
		C Specify list of calibration frequencies	Model: CP-0
		000 1992	Capacitance: 17
			Conductance: [11
			Short Reference
		Table 1	
			Inductance: 1 H
		" Specify Deepsencies by range	Resistance: [FH
		* Specify frequencies by carge Start [100] B Stop [100]	
			Resistance: Torini
		Mart IIII B Stope IIII	Resistance: Today
		Mart Time	Hestitance: Print B Load Reference
		Mart IIII B Stope IIII	Resistance: [1 of an

The CMU Calibration screen is used to perform the measurement data correction of the multi frequency capacitance measurement unit (MFCMU). For the easy way, perform the phase compensation and the open correction at least. The check boxes left of the Open/Short/Load Correction and the Phase Compensation are effective after the corresponding measurement is performed.

Measure...: Opens a dialog box used to perform correction/compensation data measurement. To perform the measurement, follow the dialog box.

Advanced Options...: Opens the "Advanced Options for CMU Calibration" dialog box used to set the frequencies for the correction data measurement and the reference values of the working standard. See the next page.

To perform the open correction and the phase compensation, open the measurement terminals.

To perform the short correction, connect the measurement terminals together.

To perform the load correction, connect your load standard between the high terminal and the low terminal.

Advanced Options for CMU Calibration	
Frequency	Reference Standard Value
^{(*} Use factory specified frequencies (Default)	Open Reference
Specify list of calibration frequencies	Model: Cp-G
1 MHz	Capacitance: 0 F 📃
Add	Conductance: 0 5
	Short Reference
Delete Jorn Bet	Model: LS-RS
	Inductance: 0 H
← Specify frequencies by range	Resistance: 0 ohm B
Start: 1.00 B Stop: 5.000 B	Load Reference
Steps: 17 B Scale: 100 -	Model: LI-RS
	Inductance: 0 H
Integration Time	Resistance: 50 ohm
C Auto Mode 🕫 PLC Mode 🛛 Factor: 16 📓	
	OK Cancel

This dialog box is opened by clicking the Advanced Options... button, and is used to set the information required to measure the open/short/load correction data and the phase compensation data. This dialog box provides the following action button.

OK: Applies the setup changes and closes this dialog box.

Cancel: Cancel the setup changes and closes this dialog box.

Frequency: You can select the measurement frequency setup mode from the following modes.

Measurement frequency setup modes:

Default (Use factory specified frequencies): Usually, select this mode. Twelve points are automatically set. They are 1 k, 2k, 5 k, 10 k, 20 k, 50 k, 100 k, 200 k, 500 k, 1 M, 2 M, and 5 MHz.

Specifies by list: Select this mode when you want to set the frequencies independently. The frequency must be 1 kHz to 5 MHz. The number of frequencies must be 1 to 101. Click Add to open a dialog box, and enter the value. For the unnecessary value, highlight the value and click Delete.

Specifies by range: Select this mode when you want to set the frequencies sequentially and automatically. Specify the start frequency, the stop frequency, the number of steps, and the scale LINEAR/LOG. The start frequency must be less than the Stop value and at least 1 kHz. The stop frequency must be more than the Start value and no more than 5 MHz. The number of steps must be 2 to 1001.

NOTE:

If the device measurement frequency is not equal to the correction data measurement frequency, calculation will be performed automatically to get the correction data for the device measurement frequency, and the calculated correction data will be used for the data correction of the measurement data.

Advanced Options for CMU Calibration	
Frequency	Reference Standard Value
Use factory specified frequencies (Default)	Open Reference
C Specify list of calibration frequencies	Model: Co-G
1 MHz	Model: Cp-G 💌 Capacitance: 0 F
Add	Conductance: 0 5 B
	Short Reference
Delete Irom list	Model: LS-RS
	Model: LS-RS Inductance: 0 H
← Specify frequencies by range	Resistance: O ohm
Start: 1.00 B Stop: 5.000 B	Load Reference
Steps: 17 8 Scale: 100 *	Model: Ls-Rs
	Inductance: 0 H
Integration Time	Resistance: 50 ohm
C Auto Mode 🔅 PLC Mode 🛛 Factor: 16 📓	10 C C C
	OK Cancel

Integration Time area defines the integration time used for measuring phase compensation data or open/short/load correction data. The number of averaging samples (Mode=AUTO) or the averaging time (Mode=PLC) is set.

Mode: A/D converter operation mode, AUTO or PLC.

Factor: Factor for the initial value. For details, see online help or user's guide.

Advanced Options for CMU Calibration	
Frequency	Reference Standard Value
[®] Use factory specified frequencies (Default)	Open Reference
C Specify list of calibration frequencies	Model: Cp-G
1 MHz	Capacitance: 0 F
Add	Conductance: 0 5
	Short Reference
Delete Jorn list	Model: L4-RS
	Inductance: 0 H
C Specify frequencies by range	Resistance: O ohm
Start: 1.00	Load Reference
Steps: 17	Model: Ls-Rs
	Inductance: 0 H
Integration Time	Resistance: 50 ohm
C Auto Mode C PLC Mode Factor: 16	
	OK Cancel

Reference Standard Values area provides the following entry fields used to set the reference values of the open/short/load standard. If you use the standard, enter the reference values to the entry fields.

OPEN Reference: Capacitance and Conductance. If you do not use the reference, enter 0 in the both fields.

SHORT Reference: Inductance and Resistance. If you do not use the reference, enter 0 in the both fields.

LOAD Reference: Inductance and Resistance

Man Frame Modules Switching Matrix Event Log	
System Information	
Model Identification: 81500A Line Frequency: 50 EasyEXPERT Rev.: A.02.00.2006.0411 Firmware Rev.: A.03 Main Frame Diagnosis	
Item Status	1
☑ Trigger I/O ·····	
Digital I/O Touch Panel Switch Unselect All	1
Z LCD	
High Voltage LED	1
Measurement LED ····· Start Diagnosis	6
Pront Key	

The Configuration window is opened by clicking the Configuration button, and is used to display the system information and event log, as well as to perform diagnostics and self-test.

The Main Frame screen is used to display the system information and perform diagnostics.

Model Identification: Displays the instrument ID. B1500A.

Line Frequency: Sets the power line frequency, 50 Hz or 60 Hz.

EasyEXPERT Rev.: Displays the revision number of the EasyEXPERT.

Firmware Rev.: Displays the revision number of the B1500 firmware.

Main Frame Diagnosis: This area lists Item and Status.

Item: Name of diagnostics item. To select, check the left check box.

Status: Diagnostics status. Pass or fail.

To perform diagnostics, specify the items to perform and click the Start Diagnosis button. A dialog box is opened. Follow the dialog box to perform the diagnostics. Some items need your judgement, pass or fail. Also you will need to connect an adapter, press keys, check LEDs, and so on.

	uration						
and the local division of the local division	1000000000	odules Switching Hat	mx Event Log	_	_		
	Slot	Module Type	Name	Status	SCUU	Notes	
	11	B1500A	GNDU+ADC	PASS	13000	110/05	Select All
	1	B1510A	SMU1:HP	PASS			-
	3	B1510A	SMU2:HP	PASS			Unselect All
	5	B1517A	SMU3:HR	PASS			
	6	B1517A	SMU4:HR	PASS			
	7	B1520A	CMU1:MF	PASS			Start Self Test
							Recover Module
E							About
Acce	ssory (Configuration		-	1		
5	itatus L	ED: 01	×				
							1

The Modules screen is used to perform self-test of modules.

Slot: Slot number where the module is installed. To select, check the left check box.

Module Type: Module model number

Name: Module name

Status: Self-test status, Passed, Failed, Recovered, or ---- (self-test has not been performed)

SCUU: Specifies if the module is connected to the SCUU.

Notes: Error information when the module self-test failed.

To perform self-test, specify the modules, open the measurement terminals of the corresponding modules, and click the Start Self Test button.

Recover Module button is for the service use only. This button makes the failed modules respond again. This button does not solve the problem that causes the Failed status.

Status LED: Enables (ON) or disables (OFF) the status indicator (LED) of the ASU (Atto Sense and Switch Unit) and the SCUU (SMU CMU Unify Unit).

iguration	
Pame Modules Switching Natrix Event Log	12
Switching Matrix Type: R2200A Fento Leakage Switch MainFrame GPIB Address: 22 R Poll	Start Self Test
200A/B2201A Input Port Configuration Extended	Configuration +
SWM IN1: SWM IN1: SWM IN1: SWM IN1: SWM IN2: SWM IN1: SWM IN1: SWM IN3: SHU2:HP F SWM IN3: SHU2:HP F SWM IN1: SWM IN1: SWM IN1: SWM IN3: SHU2:HP SWM IN1: SWM IN3: SHU2:HP SWM IN1: SWM IN3: SHU3:HR F SWM IN5: SHU3:HR F SWM IN6: SWM IN1: SWM IN1:	Г сми

The Switching Matrix screen is used to establish the GPIB connection with Agilent B2200A/B2201A switching matrix and define the B2200A/B2201A input port connections.

Switching Matrix Type: Displays the type of the switching matrix. B2200A Femto Leakage Switch Mainframe, B2201A 14ch Low Leakage Switch Mainframe, or No Switching Matrix.

GPIB Address: Specifies the GPIB address of the B2200A/B2201A. 1 to 30.

Poll: Confirms if the B2200A/B2201A with the specified GPIB Address is connected to the B1500A.

Start Self Test: This button starts the B2200A/B2201A selftest.

SWM IN: SWM IN1 to SWM IN14 mean the B2200A/B2201A input ports 1 to 14 respectively. Enter the label used to specify the input port to the right entry field. The port name and the connected module name can be the label. : (colon) cannot be used.

If the Kelvin check box is checked, the coupled even number port is grayed out.

If the CMU check box is checked, the SWM IN14 is grayed out.

Kelvin: Check this box if this port is used for the Kelvin connection.

CMU: To perform capacitance measurement, check this check box and set SWM IN13 to CMU1:MF. And connect MFCMU to B2200A/B2201A Input 13 and 14. To perform capacitance compensation, see User's Guide.

Extended Configuration: This button opens the Extended Configuration dialog box.

onfiguration	
Man Frame Modules Switching Matrix Event Log General Information	
Switching Matrix Type: 82200A Fento Leakage Switch NanFrame	Start Self Test
Extended Configuration B Save As Hardware Profile B	Extended Configuration +
To save current configuration as Hardware Profile, Save	
 ○ No Compensation ③ Select DUT I/F: 16495F/G Cable: 16494A-001 ○ User Compensation Data File 	т сми т т сми
	Close

This dialog box is opened by clicking the Extended Configuration button in the Configuration window Switching Matrix screen.

Save as Hardware Profile is used to save the hardware profile that is the B2200A/B2201A hardware configuration and the measurement module connection. Click the Save button to save the present hardware profile. The hardware profile can be made for each workspace individually.

CMU Compensation is used to select the compensation mode of the capacitance measurement using the B2200A/B2201A. Click one of the radio buttons, No Compensation, Select, and User Compensation. For the capacitance compensation, see User's Guide.

• No Compensation:

Select this radio button if you do not need the capacitance compensation. The raw data without compensation is displayed and saved.

• Select:

Select this radio button to perform the capacitance compensation for the path from the B2200A/B2201A input ports to Agilent 16495F/G connector plate or Agilent B2220A probe card interface. The data after compensation is displayed and saved.

DUT I/F field is used to specify the model number of the path you use. The selections are the 16495F/G and B2220A.

Cable field is used to specify the model number of the cable from the B2200A/B2201A output to the DUT I/F. The selections are the 16494A/B/C-001/002/005. This mode cannot perform the capacitance compensation for the cables to positioner/manipulator or the probe card.

• User Compensation Data File:

Select this radio button to perform the capacitance compensation for the path from the B2200A/B2201A input ports to the end of positioner/manipulator or probe card. See User's Guide. The data after compensation is displayed and saved.

onfiguration						
tan Frame Nodules Swit	ching Matrix Event Log	_	_	_		1
Date/Time	Message	ID	Process	User	Host	•
4/12/2005 2:00:41 PM 4/12/2005 2:00:38 PM 4/12/2005 2:00:37 FM 4/12/2005 152:48 PM 4/12/2005 12:44:00 4/12/2005 12:44:00 4/12/2005 12:44:51 4/12/2005 12:14:57 4/12/2005 12:14:53 4/12/2005 12:14:52 4/12/2005 12:14:52 4/12/2005 12:14:52	Configuration query completed. Service started successfully. Service stopped successfully. Service started successfully. Service started successfully. Service started successfully. Configuration query completed. Service started successfully. Service started successfully. Service stopped successfully.	110001 102002 102002 102002 102002 102002 102002 102002 102002 102002 102002 102002 102002	StaDaemon StaDaemon AppSetup AppSetup StaUpd StaUpd StaDaemon StaDaemon StaDaemon StaDaemon StaDaemon StaDaemon StaDaemon	BL500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user B1500user	B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0 B1500A-0	
					Close	1

The Event Log screen displays the event log. Date/Time: Displays date and time of the event. Message: Event message ID: Process ID of the event Process: Process name User: User name. Windows login name. Host: Host name of the B1500

The Refresh button refreshes the event log.

onfiguration tan Frame Nodules ASU Sv	anna man I anna an		
ASU List	accound Machic Event Log		
Slot Module Type	Name	ASU Serial Number	ASU I/O Path
1 B1510A	SMU1:HP		
3 B1517A	SMU2:HR		
4 B1517A	SMU3:HR		
5 B1517A	SMU4:HR		
6 B1517A/E52	88A SMU5:HR/AS	* s/n mismatch	SMU
7 81511A	SMU6:MP		
8 B1511A	5MU7:MP		
9 B1511A	5MU8;MP		
10 B1520A	CMU1:MF		
* NOTE: The specifications a guaranteed for the exclusive and the HRSMU. So confirm	combination of the ASU the serial number of the	ASU I/O P	ath: 📃 👱
guaranteed for the exclusive	combination of the ASU the serial number of the	ASU I/O P	ath: 📃 👱

The ASU screen is available if the B1500A installs the HRSMU connected to the ASU (Atto Sense/Switch Unit), and shows the ASU information.

Slot: Slot number

Module Type: Type of module


Name: Module name or SMU name

ASU Serial Number: Serial number of the ASU connected to the HRSMU. This cell does not show the serial number if no ASU is connected or unpaired ASU is connected.

ASU I/O Path: ASU input to output connection, SMU or AUX

If the ASU I/O Path field is set to SMU, the ASU makes the path from the ASU Force input to the ASU output.

If the ASU I/O Path field is set to AUX, the ASU performs automatic switching in every test. The ASU makes the path from the AUX In input to the ASU output for the test without the HRSMU and makes the path from the ASU Force input to the ASU output for the test with the HRSMU.



The XSLT sample files are stored in the following folder. The files can be used as a XML style sheet file for exporting test data record.

C:\Program Files\Agilent\B1500A\EasyEXPERT\Utilities\XSLT

csv.xsl:

This file can be used to export test record in the format that uses a comma (,) as data separator.


This file is used to realize the Export As CSV... function.

tab-sv.xsl:

This file can be specified in the XML Style Sheet File Path field in the Export Using XSLT dialog box if you want to export a test record in the format that uses a tab as data separator.

xmlss.xsl:

This file can be used to export test record in the XML Spread Sheet format. This file is used to realize the Export As XML Spread Sheet... function.



To control external GPIB devices, the B1500A must be set to system controller. Exit the EasyEXPERT, and close the Start EasyEXPERT window. After that, launch the Agilent Connection Expert by clicking Start, All Programs, Agilent IO Library Suite, and Agilent connection Expert.

On the Agilent Connection Expert, change the GPIB configuration of the B1500A.

•Select GPIB0.

•Click Change Properties... button.

•Change GPIB address to 21 that is the typical address number for the system controller.

•Check System controller box.

•Click OK button.

•Reboot the B1500A.

100
-
Cancel
Erowse

To open the Start EasyEXPERT window, click Start > Programs > Start EasyEXPERT menu. The Option menu provides the functions used to open the following dialog box.

Gpib Configuration:

Select Online if the B1500A is connected to your computer and you want to control the B1500A via GPIB. Or select Offline.

EasyEXPERT Database:

Specify the EasyEXPERT Database path if you want to move the database to the other folder.


After that, click the Start EasyEXPERT button to launch Desktop EasyEXPERT.

Note:

Desktop EasyEXPERT supports most B1500A/EasyEXPERT functions. However, some functions are not supported on an external computers due to differences in hardware and so on.

Note:

For the installation procedure, see the readme file stored in the Desktop EasyEXPERT CD-ROM.



To convert the 4155/4156 setup file (.MES file) to the EasyEXPERT setup file (.XTS file), use SetupFileConverter.exe, and perform the following procedure. The SetupFileConverter.exe file is stored in the following folder.

C:\Program Files\Agilent\B1500A\EasyEXPERT\Utilities

1.Create your working folder (for example, C:\415xdata).

2.Copy your .MES files to this folder.

3.Copy SetupFileConverter.exe file to this folder.

4.Launch the DOS Prompt window.

5.Go to your working folder (for example, C:\> cd 415xdata).

6.Execute SetupFileConverter.exe as shown below.

Example:

C:\415xdata> SetupFileConverter.exe *.MES

All .MES files in your working folder will be converted to the EasyEXPERT setup file format. And the .XTS files will be created in this folder.

If you do not specify the parameter, help message will be displayed by executing the file. For more information, see the setup converter readme file, online help, or User's Guide.