

4275A-26

S E R V I C E N O T E

SUPERSEDES

HP 4275A Multi-Frequency LCR Meter

Serial Numbers: 0000J00000/9999J99999

Duplicate Service Notes: 4274A-30

Correct Power Transformer replacement

To Be Performed By: HP-qualified personnel

Situation:

A Replacement Power Transformer, P/N 9100-0870, listed in the Replaceable Parts Table of Service Manual, has no connectors. When replacing the power transformer, the connectors must be crimped to the transformer's leads. But even if the connectors are obtained, it is impossible to crimp the connectors to the transformer leads, outside of the factory. So, it is impossible to replace the transformer in the field if the above P/N is ordered.

Solution/Action:

The following assembly is now set up: (This assembly is the transformer with the connectors already crimped.) Order the following P/N instead of above P/N when replacing the power transformer.

Transformer Assembly: PN 04274-65001

DATE: 15 August 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

| | | |
|---------------|-----------------|-------------------------|
| AUTHOR: YO | ENTITY: 3355 | ADDITIONAL INFORMATION: |
|---------------|-----------------|-------------------------|

© 1991 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

