

S E R V I C E N O T E

SUPERSEDES: None

HP 4275A Multi-Frequency LCR Meter

Duplicate Service Notes: 4274A-31

Repair Method for A9 MPU Board

Situation:

The A9 MPU Board (04275-66549) has been obsoleted, because of a supply problem with the original ROM and RAM. The A9 board was redesigned, and the new A9 board (04275-66559) is now being used in the HP 4275A. This service note gives the repair method for each type A9 board.

Solution/Action:

1. Repair method for the 04275-66549 and -66559:

The repair strategy for the above board is board level repair. Order A9 board part number 04275-66559 for board replacement.

2. Repair method for a board with another part number (a prior part number board):

The repair strategy for the board is component level repair. If you cannot repair the board to the component level, or if you want to replace the board, order part number 04275-66559 for board replacement.

DATE: 25 December 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
YO	3301	