

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

4287A-05

S E R V I C E N O T E

Supersedes:
NONE

4287A RF LCR Meter

Serial Numbers: MY433xxxxx and above

Firmware Rev.02.01 was released.

Parts Required: None

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: HY PRODUCT LINE: WN
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2005
PRINTED IN U.S.A.



July 25, 2005

Situation:

New System Firmware for 4287A with Windows 2000 was released as Rev.02.01. This release was to make changes one invisible internal problem of the previous firmware, Rev.02.00.

Solution/Action:

The Rev.02.01 firmware is now available from the 4287A product page on Agilent.com. It is recommended to update the firmware to Rev.02.01 when you service 4287As shipped with the Rev.02.00 firmware, S/N MY43300413 through MY43300456.