

S E R V I C E N O T E

SUPERSEDES: None

4291A RF Impedance/Material Analyzer

Serial Numbers: JP3KA00193 / JP3KA00220 (revision 3.00)
 JP3KA00221 / JP3KA00245 (revision 3.01)

New firmware corrects some bugs on firmware revision 3.00 and 3.01

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N	Description	Qty.
04291-65013	Firmware Installation Kit, 3.02	1

Situation:

The firmware revision 3.00 has a bug that some softkey cannot be seen on softkey tree.
 The firmware revision 3.00 and 3.01 have a bug that current level is not set correctly.

Solution/Action:

Upgrade to firmware revision 3.02. Upgrade instruction is provided in the Upgrade Manual furnished with the kit.

DATE: October 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hour
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AUTHOR: YO	ENTITY: 3355	AGILENT RESPONSIBLE UNTIL: October 1996	
		ADDITIONAL INFORMATION: FQC369429 & 369438, PC033-39032	