

S E R V I C E N O T E

SUPERSEDES: NONE

HP 4291A RF LCR Meter

Serial Numbers: See Duplicate Service Notes Below

Modification to fix Internal Real Time Clock Delay trouble**Duplicate Service Notes:**

4286A-04	Serial Numbers:	JP1KA00101 / JP2KC00687
4291A-04	Serial Numbers:	JP1KA00101 / JP9KZ99999
4352A-01	Serial Numbers:	JP1KC00101 / JP9KZ99999
4395A-05	Serial Numbers:	JP1KE00101 / JP1KE00285
4396A-16	Serial Numbers:	0000J00000 / 9999J99999
4396B-06	Serial Numbers:	JP1KE00101 / JP1KE00407

To Be Performed By: HP-Qualified Personnel**Parts Required:**

HP P/N	Description	Quantity
0757-0465	Resistor 100kohm	1

Continued

DATE: July 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 1 Hour
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: KW	ENTITY: 3355	HP RESPONSIBLE UNTIL: July 2000	
		ADDITIONAL INFORMATION:	