								E31	02A	-03	
S	Е	R	V	Ι	С	Е	Ν	0	Т	Е	
							SUPERSE	EDES: Nor	ne		
4	4073A Ultra Advanced Parametric Tester										
Se	erial Nun	nbers:									
E. E.	3101A 3102A 3102L 3103A	JP0 JP0	0D00301 0A00000 0A00000 0A00000)/JP99Z)/JP99Z	99999 99999						
R	Rear door may rub off paint coat of PDU main switch.										
D	Duplicate Service Notes:										
E.	3101A-15 3102A-03 3103A-02	3									
To Be Performed By: Agilent-Qualified Personnel											
Pa	Parts Required: None										
Si	Situation:										
	If the floor of 4070 installation site is uneven and the cabinet is distorted, the rear door may rub off the paint coat of PDU main switch.										
Se	Solution / Action:										
R	Raise the rear left corner (rear door hinge side) by lowering the leveling foot.										
	DATE: January 2001										

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	INFORMAT	
AUTHOR: SY	ENTITY: 3300	ADDITIONAL INFORMATION:
© 2000 AGILENT TECHNOL	OGIES	

PRINTED IN U.S.A.



Agilent Technologies