

S E R V I C E N O T E

SUPERSEDES: NONE

3488A, 3488A OPT023 Switch/Control Unit

Serial Numbers: CN37143400/CN37143570 CN38140106/CN38140111

Potential problem concerned about transformer(9100-4784)

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

| P/N | Description | Quantity |
|-----------|-------------|----------|
| 9100-4784 | Transformer | 1 |

Situation:

Unexpected power supply related problems:
 Rating fuse always blows soon after powered on.
 Strange noise can be heard.

Solution/Action:

Check the transformer first. If it is marked "RT74590 9815", replace it with a new transformer. Service Inventory is not affected.

DATE: January 1999

ADMINISTRATIVE INFORMATION

| | | | |
|---------------------------------|---|---|---|
| SERVICE NOTE CLASSIFICATION: | | | |
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | <input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME | STANDARDS: | LABOR 1.0 Hours |
| LOCATION CATEGORY: | <input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER | SERVICE INVENTORY: | <input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | USED PARTS: | <input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT |
| AUTHOR: LB | ENTITY: F4Y5 | AGILENT RESPONSIBLE UNTIL: January 2001 | |
| | | ADDITIONAL INFORMATION: | |