

S E R V I C E N O T E

SUPERSEDES: 35665A-04

35665A Dual Channel Dynamic Signal Analyzer

Serial Numbers: 0000A00000 / 9999Z99999

**Recommended Replacement Floppy Drive,
Ribbon Cable and Dust Cover**

Situation:

The 3.5 inch floppy drive and its associated ribbon cable have been replaced with newer versions. They must both be replaced if the original floppy drive is being replaced. Also, if the original drive contains a plastic dust cover on the rear portion, this dust cover should be discarded, since the new floppy drive mechanism does not need this cover.

Solution/Action:

New part numbers have been setup to replace the floppy drive (A100) and its ribbon cable (W4). The new part numbers are:

A100	Floppy Drive	0950-3282	(old pn was 0950-2990)
W4	Ribbon Cable	8120-6241	

DATE: August 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
MJL	MSD	