

3588A-05A

S E R V I C E N O T E

SUPERSEDES: 3588A-05

HP 3588A Spectrum Analyzer

Serial Numbers: 3005A00100 / 3005A00749

Front panel modifications improve disk drive / front panel alignment

To Be Performed By: HP-Qualified Personnel

Parts Required:

HP Part No.	Description
03588-60214	Front Panel Assembly
03588-34311	Dress Plate
5080-8600	Exchange Disk Drive Assembly

Situation:

The disk drive eject button occasionally will not align properly with the front panel causing the disk drive to stick. The front panel assembly has been modified to accept the bezel that normally comes with the disk drive assembly.

Solution/Action:

Replace the front panel assembly, dress plate, and disk drive assembly with the part numbers listed above. Refer to the Disassembly/Assembly instructions in the service manual (Section II) for further information.

DATE: 07 October 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR:
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: DWH	ENTITY: A100	RESPONSIBLE ENTITY: A100	UNTIL: 01 November 1993
ADDITIONAL INFORMATION:			

