S E R V I C E N O T E

SUPERSEDES: NONE

5315A 100 MHz Universal Counter

Serial Numbers: 0000A00000 / 9999A99999

Duplicate Service Notes: None

Add Safety Warning to the Option 004 Oven Contained Oscillator Adjustments

To Be Performed By: Agilent-Qualified Personnel

Situation:

The 5315A Option 004 Oven Contained Oscillator adjustments require that the top and bottom covers be removed while power is still connected to the 5315A. As a result, line voltages are exposed which are dangerous and may cause injury if touched during the adjustment.

Solution/Action:

Add the following warning to the option 004 adjustment procedures, pages 5-9, paragraph 5-24, of the 5315A Operating and Service Manual, P/N 05315-90028. This warning has also been added to the Manual Change Sheet.

Continued

DATE: 05 DECEMBER 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
MDM	0200	5315A/B Operating and Service Manual, P/N 05315-90028

© 1991 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



WARNING

When power is applied to the 5315A and the top and bottom covers are removed, line voltages are exposed which are da gerous and may cause injury if touched.