

5335A-17C

S E R V I C E N O T E

SUPERSEDES: 5335A-17B

**HP 5335A Universal Frequency Counter**

**Serial Numbers:** 1928A00101 / 3131A14555

**Replacement of the 5335A Front End Schmitt Amplifiers**

**Situation:**

Instruments that were shipped before 1983 had A3 (or A12 for Option 040) U2 and U5 Schmitt Amplifiers that were superceded by more reliable parts. These were in turn replaced in 1991 with even newer parts. (Reference Service Notes 5335A-17 and 17A). This note is written to draw attention to several typographical errors in the previous Service Notes.

These errors are corrected in Installation Note 05335-90042. This note is included in Service Kit 05335-67003, which contains a pair of new Schmitt Amplifiers and instructions for modifying older units. Be sure that you have the latest edition of this note, which is February 1995. The cost of the modification is not covered by warranty because there are no units produced in 1991 that are still in warranty.

Other parts may be required depending upon the age of your unit, and whether or not it has been previously modified. See the Installation Note for complete details.

DATE: February 1995

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		
<b>MODIFICATION AVAILABLE</b>		
ACTION CATEGORY:	AGREEABLE TIME	<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> HP LOCATION	AVAILABLE UNTIL:
AUTHOR: CF	ENTITY: 0200	ADDITIONAL INFORMATION: