

S E R V I C E N O T E

SUPERSEDES: 6050A-01A

6050A Multiple Input Electronic Load Mainframe

Serial Numbers: 0000A00000 / 9999A99999

6050A Electronic Load Mainframe Fan Speed Adjustment

Duplicate Service Notes: 6051A-01B

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

- 0757-0427 1.5K ohm 1% 1/8W Resistor
- 0757-0317 1.33K ohm 1% 1/8W Resistor

Situation:

The fan speed adjustment in the 6050A mainframe has been eliminated. Do to the difficulty of the adjustment and special test equipment requirements NJD production engineering has discontinued the Fan speed adjustment.

Solution / Action:

Remove potentiometers R311 and R313 from the A1 GPIB board assembly. Install p/n 0757-0317 1.33K ohm resistor in component location R286. Install p/n 0757-0427 1.5K ohm resistor in component location R288.

DATE: July 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
BH	2100	

